

Fairbanks Morse Engine Division 701 Lawton Avenue Beloit Wisconsin 53511 608/364-4411

September 26, 1978

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Ill. 60137

Copies Is Patrion I alling H Theans The Ferry This J Pay

Attention: Mr. James G. Keppler, Director, Region III

Subject: Colt Industries-Fairbanks Morse Engine Division,

Emergency Diesel Generators
Possible Exhaust Rocker Arm Defect

Reference: Phone conversation reporting information contained below to U. S.

Nuclear Regulatory Commission, Mr. Bob Heichman by Mr. J. M. Moriarty of Colt Industries-Fairbanks Morse Engine Division on September 26, 1978

Gentlemen:

A 14-cylinder PC-2 powered engine genset to be delivered for installation at the Northeast Utilities Company's Millstone III site has been undergoing test in preparation for a customer witnessed 300-start qualification test. During this pre-contract test running an exhaust rocker arm failed making the engine inoperable until a new rocker arm was installed. The failure occurred on 9/20/78 and subsequent investigation shows the failure was caused by a stress riser from "fit up" grinding of the arm during assembly to the engine. The hand grinder "slipped or jumped" while the operating clearance was being provided and notched the underside of the arm subject to tensile stress during operation.

In this case, the stress level from operation increased by the factor from the grinding "notct," was high enough to cause the resulting fatigue crack. (No additional factor such as the defective material which was concurrent with the notch on the Beaver Valley rocker arm was required to initiate the fatigue crack because the notch was more severe.)

There is a possibility that such grinding defects exist in other rocker arms installed on delivered units (3 - Alabama Power and 2 - S. Carolina at the customer's site plus 2 - Beaver Valley and the other Millstone unit in storage at Beloit).

The only operating PC-2 units are at Alabama Power Co., Farley Nuclear Plant. We will contact Farley, advise them of this reportable incident and that an inspection/corrective action plan is being developed.

The South Carolina Electric & Gas Co., Summer Station PC-2 units have not been started up yet. We will notify them of this matter and inform them of our intended course of action as soon as it's established.

10

U. S. Nuclear Regulatory Commission September 26, 1973 Page 2

Those units still in Beloit will be inspected with appropriate change out, if necessary, prior to shipment.

We will keep you advised as we proceed on this matter.

Very truly yours,

whole years great " by

S. M. Moriarty
MANAGER UTILITY ALES

JMM: jc

cc: Mr. George Hairston Alabama Power Co. P. O. Drawer 470 Ashford, AL 36312

> Mr. Ronald B. Clary South Carolina Electric & Gas Co. P. O. Box 764 Columbia, South Carolina 29218

> Mr. George Buffington Stone & Webster Engineering Corp. P. O. Box 2325 Boston, Massachusetts 02107

Stone & Webster Engineering Corp.
P. O. Box 2325
Boston, Massachusetts 02107
Attention: Project Engineer For Duquesne J.O. 12241