CALCULATION TITLE PAGE

	T						PAGE 1		-1-
TEXAS UTILITIES	GE				SES - UNIT	NO.1 & 2	TOTAL NO.	OF PAGE	15- /2
CALCULATION TIT			bjective):					
GENERIC CALCULA	TION				0 5 20		A - NUC	LEAR ETY REI	ATER
		PARALLE	L :	5 10 13	156125				
								NUCLEA TY REL	
	7	CALCULATION		CURRENT	UMBER		OPT	TIONAL	
J. O. OR W.O NO.	DI	VISION & GROUP	·	CALC. NO			WORK P	ACKAGE	NO.
15454	NZ	(c)-	GB	NX - 24	2		N	/A	
REV. NO						SUPERSEDES			
REPARER(S)/DATE	(8)	REVIEWER(S)/D	ATE (S)	REVIEWE	R(S)/DATE(S)		OR REV. NO.	YES	RED (V)
T. Grwale		Kawai R.	2/0	RAHMAT	RADIZAGEN				
		10/16/		10/30	R.Cojez	0	NA	000	V
10/15/87		10/10/	01	1 1/	-/0/				14
		Kawai X.	142	1/	.001				
T. Cirwah				/	· 4. 20	1	0		1
1/21/88		1-21-8	18	/-	21-88	' '			
				DISTRIB	UTION				
				COPY					COPY
GROUP		NAME & LOCA	TION		UTICN		NAME & LOCA	ATION	COPT
			TION	COPY			NAME & LOCA	TION	SENT
FIRE FILE	.1 5	Rev	TION ision 245/1	COPY SENT			NAME & LOCA	TION	SENT
FIRE FILE	.1 5	Rev NICHOLSON	TION ision 245/1 C 4YL	COPY SENT OI1 2			NAME & LOCA	ATION	SENT
FIRE FILE ORIGINALS TO PROJECT FILE	. I S	Rev NICHOLSON R. CLER. CHOO	1710N ision 245/1 247L (5GE)	COPY SENT OI1 2			NAME & LOCA	TION	SENT

8803280307 880331 PDR ADOCK 05000445 E PDR

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION SHEET

0.65	CALCU	LATION IDENTIFICATION N	UMBER	
J.O. OR W.O. NO. 15454	DIVISION & GROUND NZ (C)			DDE PAGE
T				
I NDEX:-			PAC	E No.
TITLE				1
INDEX				2
REVISION	STATUS TA	73 CE		3
OBBCTIV	ε			4
METHOD				4.5
REFERENCE	23.			5
CONICLUSIO	No			5A
CALCULATI	ons		6	-28
ATTACKME		TELEPHONE MEM	OR ANDUM	1
		TEST EXPLANATION PHEIFIC SCIENTIF		15
	c>	1.0.c of UNIT 1	5-TINU ?	
		SHOWING CONDITION	OF SUPPORT	27
			-	72

40

42

010.65		CALCULAT	ION IDENTIFICATION N		
	OR W.O. NO.	DIVISION & GROUP	GENX-242	OPTIONAL TASK CODE	PAGE 3
		REVISION	STATUS TABLE		
REV	PAGE NO.	DE	SCRIPTION/REASO	N	
0	ALL	ORIGINAL I	SSUE		
1	A	REVISED TOTA	L SUPPORT N	30,	
	5	CORRECTEC SPE	ELLING FOR HY	DEAULIC.	
	M. T.				
	10.00				
		3			
		the section of the		*1	

▲ 5010.65 CALCULATION IDENTIFICATION NUMBER DIVISION & GROUP J.O. OR W.O. NO. CALCULATION NO. OPTIONAL TASK CODE PAGE 4 NZ(C) GENX-212 15454 REFERENC-1 OBJECTIVE: -MUCLEAR STANDARD NE-E-79 SECTION XI. 3.1 REDVIRES THAT PARFILLEL SMUBBER. SHALL NOT BE MUMATCHED IN OLDER TO PERFORM THEIR INTENDED FUNCTION. THE 11 REDVIRE MENTS OF MATCHED SNUBBERS ARE 13 a) THE DIFFERENTIAL LOST MOTION BETWEEN 15 ·TWO SNUBBERS SHALL NOT EXCEED 0.02 INCH. b) THE DIFFERENTIAL ACTIVATIONS. 19 20 SHALL NOT EXCEED 0,005 9 OR 50% OF 21 22 THE SMALLEST ACTIVATION LEVEL, THE 23 OBJECTIVE IS TO CHECK WHETHER THE SHUBBERS 24 MEET THE AROVE (a & b) CRITERIA. 25 METHOD :- aT LIST OF ALL THE SUPPORTS WHICH 26 27 HAVE PARALLEL SNUBBERZY IS OBTAINED (REFFERENCE - 2) FROM SITE, WITH SNUBBER MODEL NUMBER AND SERIAL NUMBER. TOTAL SUPPORTS ARE 235. BY A TEST DATA SHOWNG LOST MOTION & ACTIVATION LEVEL FOR EACH OF ABOVE SNUBBERS WERE OBTAINED FROM PACIFIC SCIENTIFIC, (REF-3) CYDIFFERENTIAL LOST MOTION & ACTIVATION LEVEL BETWEE! PAIR OF SNUBBERES

29

30

32 33

35

3 6

38 39

40 41

42

4.5 46

J.O. OR W.O. 110.	DIVISION & GROUP	GENX-242	OPTIONAL TASK CODE	PAGE 5

METHOD (CONT.).

21 22 23

USED IN EACH SUPPORT ARE CALCULATED

- d) DIFFRENTIAL MOTION IS COMPARED TO THE 0.02 IN MAXIMUM.
- COMPARED TO THE 0.005 G OR SOY, OF
 THE SMALLEST ALTIVATION LEVEL.

REFERENCES!-

1) HUCLEARL STANDARD NE-E-79 "MECHANICAL

AND HYDRAULIC SNUBBERS FOR MUCLEAR

APPLICATION" SEPTEMBER 1984.

- 2) INCOMING CORROSIONDANCE "CH-ICPI-825 DATED 5/13/87 JOB BOOK R 2.1.2.
- 3) INCOMING CORROSPONDANCE CH-1CPI-992.

▲ 5010 65

8

10

13

1.5

16

18

20

21

23

24

26

27 28 29

30

32

3.5

3 6

36

40

	CALCULAT	ION IDENTIFICATION N	UMBER	
J.O. OR W.O. NO.	DIVISION & GROUP	GENX- 7.42	OPTIONAL TASK CODE	PAGE 5 A

CONCLUSIONS :-

THE COMPAKISON OF LOST MOTION FOR MATCHED SNUBBERS SHOWED THAT THE DIFFERENTIAL LOST MOTION WAS WITH IN THE 0.02 IN LIMIT FOR ALL SUPPORTS. THE COMPARISON OF ACTIVATION LEVEL SHOWED THAT FOR 17 %. OF SUPPORTS. THE DIFFERSNITIAL ACTIVATION LEVEL EXCEEDED THE 0.0059 OR 4 OF SMALLEST ACTIVATION LEVEL HOWEVER APPENDIX XI.3.1 OF THE REF - STATES THAT "LOAD SHARING IS A STRONG FUNCTION OF MISMATCH OF LOST MOTION AND END FITTINGS CLEARANCE AND A LESSER FUNCTION OF MISMATCH OF ACTIVATION LEVEL AND RELEASE RATE! IT IS COMMON INDUSTRY PRACTICE TO MATCH ONLY THE CLEARANCE/ LOST MOTION OF SNUBBERS TO ENSURE THE PROPER LOAD SHAKING OF MULTIPLE SNUBBERS. (SEE PATACHMENT A) BASED ON THIS IT IS GNOWDED THAT MULTIPLE SNUBBERS ON PIPE SUPPORTS ON CPSES SATISHEY THE WAD SHARING CRITERIA OF REFERENCE-1.

42

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION SHEET

			N IDENTIFICA				
J.O. OR W.O. NO. 15454	N 3-CC)		CALCULATION SENX-Z	42	OPTIONAL TAS	K CODE PA	GE6
23×13×2= 2	596 PAI	RET	D SHO	BBE	25		
5UPPORT No	SNUBBER	MeDe	ACT	0	LOST	0 Ex02	REMARK
C5-1-106- 720-C42 K	9075	1/2	0:014	0.002	0.015	0.001	8 C
20-1-134-7 CG1K	15329	1/4	0.0122	0.004	3 0.020	0.005	0 · Ic
RH-1-5B-01	9737	1/2					84
RH-1-58-01	9720	1/2	Del.	etocl			
AF-1-096- 533K	17828	1	Del-	2+00	L		
AF-1-096-02 5-33K	0 19536	1/4	0.0165	0.002	0.015	0.002	o k
562K	10186	10		DELI	ETED		
4F-1-099-00 54316	14505	3	NA	11 86	0.015	0.002	
4F-1-099-00 533 K	24254	1	Dela	teel			
533 K	7 9832	1/2	0.015	0.00	5 0.017	0.007	
4F-1-099-09 543K	24249	1	0.006	0100	0.028	0.00	
FW1-1-092-70 562K	11717	10	gripping in	DELE	TEO.		
AF-1-059-70 562K	24186	L		Let	e.2		

5010.66	CALCUI	LATIO	N IDENTIFICA	TION NUM	BER		
15454	DIVISION & GROU		CALCULATION X-2		PTIONAL TASK	CODE	PAGE7
		RE		BBER	25		
5UPPORT	SNUGBER	HODEL	ACT LEVEL	0	HOTON	014	REMAR
AF-1-101-00 5 331C	7 28085	1/4	4.013	0.0	0.020	0.00	
51-1-051-02 C42K	9 17818	1	0,008	0,004	0.022	0.001	97名:**
31-1-037-013 842K	8380	3	NA		0.009	0,00	1
51-1-057-01 C42F	7 19038	1	0.006	0001	0.028	0.00	2
51-1-088-00 C42K	9 19044	1	0.006	0.001	0.026	0.00	9
51-1-058-01 C42K	8370	3	NA	-	0.016	0.006	
51-1-181-00: C41K	15063	10	0.007	0.007	0.028	0.00	50.005
51-1-306-02 C42F	28089	1/4	0.000	0.001	0.019	0.00	3
51-1-306-02. C42F	19043	1	0.008	0.00 1	0.017	0.009	9
51-1-304-02 C42K	19132	1	0.008	. 004	0.018	0.007	7
CH5K	18126	1	0.006	0.004	0.022	0.001	45 > 12 x10 00
RH-1-001-006	27950	3	7	elete	d		
C41K	4890	10		nolete	0		

RECEIPTED AND			ON IDENTIFIC				9
J.O. OR W.O. NO.	NZ-(C)	P	GENX-		OPTIONAL TAS	KCODE	PAGE 8
	PA	IRE	D SHO		RS		
SUPPORT	SNUBBER	MoDel	ACT LEVEL	0	LOST	AH	REAM
CHIC	27954	3	NA 0.005		0.016	0.002	1
24-1-002-012 641K	10762	10	0.011	0,00	2 0.010	0,010	
5221C	7378	3	DE	-5	TED		
2T-1-009-008 5221	10295	1	Del	2+2	d		
522F	21000	3	_0 e	le +	d.		
522K	107 30	3	NA		0.011	0.016	
522K	12344	1/2	0.009	0.00	2 0.017	0,002	
542K	16469	3	Del	etec	L		
C42K	7833	1/2	0.017	0.00	5 0.814	0.002	
3-1-001-015 C42K	8517	1/2		eted			
5-1-879-022 C42K	11390	1/2.	Dela	tod			
20-1-115-011 C74K		10	0.016	0.004	0.020	0.001	
CSIK		1	0.008	0.002	0.132	0.01	

	CALCU	LATIO	N IDENTIFICA	ATION NU	MBER			
J.O. OR W.O. NO.	DIVISION & GROUND A Z (()	P	CALCULATIO	The state of the s	OPTIONAL TASE	CODE	PAGE 4	
	PA	RE	D SHO	BBE	25			
SUPPORT	SNUBBER	HODER	ACT	0	LOST	0	REMAL	
CC-1-239-00	34442	1/4	0.012	0.0	0.026	0.00		
CC-1-212-00 CE3 K	12024	1	0.007	0,001	0.009	0.00	1	
CC-1-218-01	10782	1/4	0.012	0.002	0.013	0.00	3	
CC-1-2/5-012	19294	1/4		DE	LETED			
433K	205.8	3	0.003	0.00	0.026	0.0	00	
A43 K	10525	3	NA		0.014	0.00	2	
A43K	15987	3	NA		0.017	0.00	2	
CC-1-043-01	4298	10	0.015	0.0	0.010	0.001		
453K	8386	3	Del	etec	2			
CC-2-044-700 A43K	11724	10	0.018	0.004	0.02	0.003	5	
433F	1492	3	Del	2 + 0 cl	.			
522K	11997	3	NA	arang con	0.018	0.000	5	
532×	15950	3	NA		0.012	0.00	6	

	CALCU	LATIO	N IDENTIFIC	ATION NU	MBER		
J.O. OR W.O. NO.	DIVISION & GROU		CALCULATI		OPTIONAL TAS	K CODE	PAGE 10
	PA	RE	D SHO	BBE	25		
5UPPORT No	SNUBBER	MoDel	ACT	. A	LOST MOTION	DA	REMAN
RH-1-024-6	14517	3	NA		0.011	0.00	5
MS-1-074-01	8401	1/2	0.008	0.00	6 0.013	00.	4 30.005
MS-1-074-0 C521C	14 8373 8374	1/2	0.013	0.00	2 0.013	0100	
MS-1-151-02 C52K	10757	1/4		DE	ETED		
MS-1-151-03 C52K	19554	1/4		DE	ETED		
US-1-151-00	10378	1	De	leter	Q		
45-1-151-04 C52K	B107	1	De	2e+	od.		
45-1-150-0 C52K	35251	1/4	0.012	0.004	0.024	0.002	
US-1-150-0	35219	1/4	0.010	0.00	0.020	0.004	
US-1-344-00	24514	1	0.105	0.00	0.028	0.002	9.74000
US-1-345-0	9791	1/2	0.014	0.002	0.013	0.005	
45-1-028-0 533K	The second district of	1	0.008	0.0	0.023	0.002	
563K	NAME AND ADDRESS OF THE OWNER, TH	10	0.007	0.00	3 0.011	0.006	

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CALCUI	LATIO	N IDENTIFIC	ATION NUM	BER		
1.0. OR W.O. NO.	DIVISION & GROU		CALCULAT		OPTIONAL TAS	K CODE	PAGE 11
		COLUMN TO SERVICE SERV	D SH	THE REAL PROPERTY AND ADDRESS OF THE PARTY AND	25		
SUPPORT	SNUBBER	HOORE	ACT	0	LOST	014	REMORE
C92 K	12680	1	0.008		0.005	-	
C92K	3 10373 21792	1	De	leto	a		
FW-2-0944 SUZK	26961	3	SNOR	CHAN	TO STI2.	wt.	
51-2-051-419 C42K	15891	1	NA		0.020	0.00	7
51-2-051-41 E42K	20007	1	0.010	0.004	0.022	0.00	6 49>20.00
51-2-095-41 C4ZK	3 24649	3	0.005	0.001	0.028	0.00	2
C4216	13012	1	0.009	01002	0.013	0.01	7
51-2-087-41 C42K	20177	1	0.008	0.001	0.030	0.00	2
C42F	7 20183	1	0.009	0.001	0.038	0.016	
C41K	THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	3	NA NA		0.010	0.001	
C42K	THE RESERVE THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TWIND TWO IS NAMED IN COLUMN TWO IS NAMED IN COLUMN TWO IS NAMED IN	Γ	0.008	0.00	0.024	0,00	2 49746005
C42K	NAME AND ADDRESS OF THE OWNER, TH	11	SUPPOR	26798	PLETTE	2.47	7
C42F	16471	1	0.008	0.002	0.002	0.0	

			N IDENTIFICA		NAME AND ADDRESS OF THE OWNER, WHEN		10
J.O. OR W.O. NO.	NZ-(C)		CALCULATION - Z		TIONAL TASK	CODE	PAGE 12
	PAI	RET) SNO	BBER	S		
SUPPORT	SNUBBER	Holes	ACT	0	LOST	4	REMA
C4216	15190	10	0.010	0.002	0.020	0.0	
2441C	3789	3	NA		0.009	0.001	
CT-2-051- 40 C72K	8 12995	3	XIA 0007		0.013	0,013	
WP-2-030-4	14454	1	0.010	0.0.	0.026	0.006	
C42F	THE RESERVE AND ADDRESS OF THE PARTY OF THE	1	0.006	0.002	0.020	0.004	
CS-2-001-41	STATE OF THE OWNER, WHEN PERSON NAMED IN COLUMN 2 IS NOT THE OWNER, WHEN PERSO	1	0.006	0.001	0.011	0.017	
RC-2-052-42 C411K	19045	1	0.007	0.001	0.032	0.002	
C42K	THE RESERVE AND ADDRESS OF THE PARTY OF THE	1	0.007	0.001	0.030	8 002	
C5-2-079-41		T	0.007	0.002	0.028	0.002	
C42F	THE RESERVE THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	1.	0.005	0.005	0.026	0.004	1974
C76K	THE RESERVE AND ADDRESS OF THE PARTY OF THE	10	0.006	0.008 M.G.	0.028	0.002	0.005
26-2-115-431 C5414	15779	10	0.008	.008 N.G.	0.024	0.006	0.005
45-2-344-4. C52K	THE RESERVE AND ADDRESS OF THE PERSON NAMED IN	1	0.01	0.0	0.030	0.0	

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION SHEET

▲ 5010 85	CALCUI	ATIO	N IDENTIFIC	ATION NU	ARFR		
J.O. OR W.O. NO.	DIVISION & GROU	P		ON NO.	OPTIONAL TASK	CODE	PAGE 13
		RET	-	BBET	25		
5UPPORT	SNUBBER	Holder	ACT	0	LOST	AH	CEMAKK
MS-2-344-407	21124	1	0.005	0.005	0.028	0.004	9> × 0.015
5B-2-02-404 E 25K	21348	3	N.A. 0.005		0.007	0.017	
533F	15988	3	NA	NA	0.012	0.00	
4F-1-001-021 Y33K	13041	1	0.006	0.00	0.010	0.016	
533K	21812	1	0.008	0.00	2 0.024	0.0	
4F-1-096-041 543K	19540	1/4	0.0119	0.002	0.014	0.00	
4F-1-094-049	11808	1/2	0.013	0.00	0.008	0.008	
AF1-097-043 563F	14604	1	0.009	0.0	0.013	0,000	
553 F	28055	1/4	0.012	0.002	0.019	0.001	
533F	10287	1/2	0.007	0.006	0.012	0.003	49>46007 80.0058
AF-1-102-002 543K	8450	1/2	0.01	0.001	0.009	0.008	
BRX-044-008 453F	10448	1/2	0.01	0.002	0.015	0.005	
A33K	9232	3	De-	lete	d		

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION SHEET

			N IDENTIFICA					
J.O. OR W.O. NO.	DIVISION & GROU		GENX- 2		OPTIONAL TASE	CODE	PAGE 14	
		RET	D SHO	BBE	RS			
SUPPORT NO	SNUBBER	HODER	ACT LEVET	0	LOTTON	DIH	REMA	
A3316	15948	3	NA 0,006	-	01013	0.013		
CC 1-028-004 A33F	4798	35	0.0019	0.000	0.030	0.001		
53316	6451	35	0.0059	0.003	0.028	0.0	9>/2010	
533F	1/617	10	0.014	0.004	0.030	0.013		
CC1-043-015	15958	3	NA		0.013	0,001		
443F029	10717	10	0.012	0.00	0.024	0.001		
A33 F	11575	35	0.003	0.0	0.016	0.01		
533F	26539	3	0.003	0.00	0.026	0.002		
533 6	14710	10	0.010	0.00	0,028	0.0	4976x00	
S33F	14032	3	De	Lete				
E33F	2.325	为	0.017	0.00	2 0.013	0.0		
C42K	25038	14	0.014	0.0	0.017	0.0		
C53F	15359	1/4	0.014	0.00	0.018	0.005		

			N IDENTIFICA		-		1
1.0. OR W.O. NO.	NZ(C)		CALCULATIO		PTIONAL TASK	CODE	PAGE 15
	PAI	RET) SHO	BBER	25		
5UPPORT	SNUBBER	HODE	ACT LEVEL	4	LOST	AH	Remore
C53 F	10778	1/4	1 4 0 12	0,004	0.014	0.0	
CC1-218-007 CS3F	1079	1/4	0.013	0.004	0.014	0.0	
CC1-218-016 CS3K	28009	1/4	0.016	0.007	0.020	0.00	3
C53F	24117(8)	-	De	lete	d		
C53F	1690	3	0 e	Det	a cl		
C53K	16150	14	0.010	0.00	2 0.017	0.00	7
C53F	15385	14	0.015	0.00	0.016	0.005	5
CS3F	19990	1/4		DELE	2 78.0		
A75F	6138	3	D	elet	ed.		
A75F	21034	3	0.004	0.10	0.025	0.003	3
545F	2181	1/2	02	let	ed.	80. GO O	
552F	12988	3	NA		0.017	0.00	4
CS 1-242-708 A42F	12688	1	0.010	0.003	0:013	0.00	2

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION SHEET

▲ 5010.86	CALCUL	ATIO	N IDENTIFICA	TION NUMB	ER		
J.O. OR W.O. NO.	NZ (C)		CALCULATION X - 2		TIONAL TASK	CODE	PAGE 16
	PAI	RET	D SHO	BBE29	S		
5UPPERT No	SNUBBER	MoDel	ACT	0	HOTON	Q H	REMOR
553F	12999	3		eted			
553F	12470	-	De	detoc			
532F	13031	١	0.007	-	0.011	0.002	
C82F	12035	1	0.008	0.002	0.007	0.001	
C72K	10782	10	0.012	0.00 Z	0.027	0.002	
C52F	15103	10	0.007	0:002	0.024	0.002	
522F	26371	1/4	0.016	0.0	0.017	0.007	
522F	110173	3	NA	tion or the	0.008	0,001	
512K	14894	3	NA		0.008	0.003	
522×	14898	3	NA	renderen d	0.013	0.001	
C71-029- 023 C92F	18007	1/2	De	lete	2		
C92F	1 -0100	14	0.014	0.0	0.020	0.001	
C924	2040	14	0.014	0.004	0.016	0.001	

	CALCU	LATIC	N IDENTIFICA	UN NOITA	MBER		
J.O. OR W.O. NO.	DIVISION & GROU	P	CALCULATION GENY-		OPTIONAL TASI	KCODE	PAGE 17
	PA	RE	D SHO	-	25		
5UPPORT No	SNUBBER	HODER	ACT	0	TZOL	OH.	EEMAR
CT1-034-019 CB2K	9781	1/2	1 - 1 -	0.00	0.009	0.01	
C71-034-020 C8216	11372	1/2	0.017	0.00	3 0.015	0.00	3
CTI- 038-437 C42F	20327	1/4	0.015	0.00	3 0.015	0.003	5
CT1-002-003 532K	11978	3	NA	-	0.021	0,00	3
CT 1-007-007 522K		3	NA .		0.015	0.00	4
CT1-009-004 522K		1	0.007	0.00	0:011	0.00	4
S22K		3	NA		0.008	0.00	,
LT1-013-023 542K	NAME AND ADDRESS OF THE OWNER, WHEN PERSON AND ADDRESS OF THE OWNER, W	10	0.015	0.0	0.010	0.00	2
CB216	3291-3	3	THEORNA	STINGS	ens		
CT1-013-415		10	0.012	0.003	0.020	0.00	1 .
C52K	12019	3	NA NA		0.028	0.008	
C & 2 K	28861	3	0.004	0,001	0.018	0,002	
S4216		10	0.015	0.001	0.010	0.0	

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION SHEET

	CALCUL	ATIO	N IDENTIFICA	TION NU	MBER		
J.O. OR W.O. NO.	DIVISION & GROUND		GENX-2		OPTIONAL TASE	K CODE	PAGE 1.8
	PAI	RE	D SHO	BBE	25		
SUPPORT NO	SNUBBER	HOOSE	ACT	0	LOTTON	0	REMAR
S42K	9234	10	0.011	0.00	0.009	0,00	
532K	10770	3	NA	-	0.009	0.00	3
CT1-038-44 C52K	27599	1/4	0.016	0.0	0.025	0.00	2
C421C	3 19968	1/4	0.015	0.00 3	0.017	0.00	8
C92F	10358	1/2	lool	eta			
C 5216	12039	1	0.007	0.00	0.012	0.00	3
C92K	8375	1/2	Del	2 to a	4		
C82 K	28455	1/4		DEL	ETED		
CULF	10234	1	NA		0.008	0.00	5
CBLK	9819	1/2	0.013	0.003	0.012	000	3
CT1-049-01		1/4	10/4	0.003	0.017	0.00	3
CT1-049-40 CB2K		1/4	0.014	0.007	0.015	0.00	2
CT1-051-41.		3	NA		0.015	0.00 \$	

	CALCUL	ATIO	N IDENTIFICA	TION NU	MBER		10
1.0. OR W.O. NO. 15454	DIVISION & GROU	P	GENX-		OPTIONAL TASI	K CODE	PAGE 19
	PAI	RE	D SHO	BBE	RS		
SUPPORT No	SNUBBER	HODEL	ACT	0	LOST	AH	RENACO
CT1-051-416	14598	1	0.007	0.00	0.017	0.0	
CT1-051-417	14550	1	0.008	0.00	0.022	0.004	49>464
CT1-051-418 C72K	12313	1/2	0.008	0.00	0.012	0.006	9>/2008
CT1-051-419 C72F	14592	1	0.007	0.002	0.015	0.003	
CTI-054-433 C42K	16180	1/4		DEL	ETED		,
CT1-074-410	19980	?	- De	20+	2 d		
C424	12041	1.	0.008	0.0	0.009	0.005	-
C 52K	14572	1	0.009	01003	01015	0.004	
CT1-076-408	THE RESERVE AND ADDRESS OF THE PARTY OF THE	3	NA		0.025	0.001	
C72-	THE RESIDENCE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER, THE O	3	NA		0.021	0.00	
C 52K	12043	Г	De	let	ed.	3474 . 3T	
CT1- 097-414	THE RESERVE AND PERSONS ASSESSMENT AS	74	0.017	0.00	2 0.015	0.003	
CT1-117-412 CUZK	12354	1/2	0.009	0.003	0.011	0.005	-1

	CALCUL	ATIO	N IDENTIFICA		MBER		
J.O. OR W.O. NO. 15454	NZ (L)		GENX- 2		OPTIONAL TASK	CODE	AGE 20
	PAI	RE	D SHO	BBE	25		
5UPPORT	SNUBBER	Holes	ACT	0	LOST	4	REMAIL
CT1-117-415	24201	1	De		e cl		
CT1- 124- 419	12646	1	0.008	0.00	2 0.005	0.008	
C72K	6 5429	1/2	De	let	-ed		
DDZ - 003-49		3	0.003	0.0	0.020	0.00	
DOZ-0.3-45	7 20294	1	0.008	0.00	0.026	0.002	
DO2-000-48	7134	3	NA		0.014	0.004	
Do1-029-00 553F	11601	10	0.011	0.00	0.035	0.012	
Do1-035-00	ACCUPATION AND PARTY AND PARTY.	3	0:005	0100	0.029	0.002	
563F	1 1.000	35	0.0026	0.00	3 01025	0.014	3>2 ***
Do1-038-00	THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	3	NA		0.016	0.007	* 1
545K	SECURE AND ASSESSMENT OF THE PROPERTY OF THE PARTY OF THE	1/4	0.014	0.0	0.023	0.0	
Do1-058-001		3	NA 0.005		0.008	0.019	
Do1-070-00	THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE PERSON NAME	3	NA.		0.006	0.008	

	CALCUL	ATIO	N IDENTIFICA	TION NU	MBER		
J.O. OR W.O. NO.	NZ-CC)		GENX-2		OPTIONAL TASK	CODE	PAGE 21
	PAI	RET	D SHO	BBE	25		
5UPPORT No	SNUBBER	Hope	ACT	00	LOSTON	AH	eenark
DD1-003-098 5351C	20633	1	0.005	0100	0.026	0.002	97%.005
535K	12138	1/2		0.00	2.010	.001	
D01-071-001	11910	10	0.008	0.00	0.026	0.00	45> 1/2(0.008
503F	8850	35	0.0042	0.000	7 0.028	0.005	,
D01-071-000 S53K		10	0.012	0.001	0.031	0.005	
D01-069-00U	THE RESERVE OF THE PARTY OF THE	10	0.008	0.002	0.017	0.0	
505F	10755	3	NA	-	0.010	0.003	
565F		10	0.008	0.005	0.025	0.010	237 & 10.00g
C72K	16867	3	Del	e +	e d		
FW1-017-700 C42F	TALL SECTION AND DESCRIPTION AND DESCRIPTION ASSESSMENT OF THE PARTY O	35	0.0019	0.0018	3 0-014	0004	AS> 1/2 (0.00)
FW1-017-707 C72F		100	0.009	0.006	0.033	0.005	300058
FW1-017-709 C72K		100	0.0031	0.0003	0.038	0.008	
FY11-017-712 C72K	1420	100	0.004	0.00	0.030	0.005	

J.O. OR W.O. NO. 15454	DIVISION & GROU	P	CALCULATIO			CODE	PAGE 22
13444			GENX- 2		TIONAL TASK	CODE	AGE
	NAME AND ADDRESS OF THE OWNER, WHEN PERSON NAMED IN	-	D SHO	THE RESERVE THE PERSON NAMED IN	S		
	7~	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	5.10		1		
SUPPORT	SNUBBER	HODER	LEVEL	Δ	HOTTON	4	erm Ack
-W1-018-01	No	+	0.005	4	0,020	IH	+
CSLF	11580	35	0.005	0,0	0.018	0.002	
FW1-018-70	AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED I	+-	0.003		0.025		
C72K	1457	100	0.003	0.0	0.024	0.001	
FM1-018-70		1.	0.006		0.030		05>6 (0.0)
e72K	1424	/06	0.003	0.00	10:037	0.007	1
FW1-018-70	1455	1	0.004		0.020		
CTZK	1450	100		0.001	0.018	0.002	
FW1-019-70		100	0.0013		2.014		49 >0.002
C421C	8790	35	0.0014	0.0001	0,018	0.004	2
FW1-020-700		1.	0.0022		0.030		
C42F	1432	100	0.0041	0.0019	0.030	0.0	
FW1-095-011	14921	1-	NA		0.012		
CUZK	14922	3	NA	1.0	0.018	0.006	
FW1-095-70		1	8-006		0.025		
COZE	2/013	3	0.006	0.0	0.025	0.00	
FW1-095-70		2	NA	22 he	0.013	2.205	
CUZF	13005	3	NA		0.019	0.006	
=W1-096-700	The second secon	3	NA		0.022		
CUZE	21007	13	0.006		01022	0.00	1
Fx11-096-70		7	NA		0.025	0.011	
CUZK	16904	3	NA	America 1	0.014	0.011	Marin 1
FW1-090-70	THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE PERSON NAME	3	XA	a familiar o	0.018		
CUZK	12009	1	NA.	borriers,	0.028	0.01	
FW1-096-70	Name and Address of the Owner, where the Party of the Owner, where the Party of the Owner, where the Owner, which is the Owner, which	-	1	e ted)		
CELK	16943	3	Del	5 45 0	Markey 1 1 m		

	CALCUL	ATIO	N IDENTIFICA	TION NU	MBER		
J.O. OR W.O. NO.	NZ-(C)	-	GEN X-Z	COMP. CEDIMIZ.	OPTIONAL TASK	CODE	PAGE 23
	PAI	RET	5 5 NO	BBE	25		
SUPPORT No	SNUBBER	Holder	ACT	0	LOST	4	
FW1-096-705 CUZK	10714	10	0.009	0,00	0.023	0.0	9>8000
FN11-096-706	10052	10	0.012	0,00	2 0.008	0.0	
FW1-096-707 C62F	2/04/	3	Del	et-	ocl		
FN/1-097-040 CUZE	21044	3	De	le 1	rad		
FW1-097-701	14891	3	NA	Mark to t	0.008	0:01	
FW1-097-702	14900	10	0.009	0.00	7 0.009	0.012	497/2 (02)
FW1-097-705 CUZK	28416	3	0.005	0.00	2 0.022	0.00	43>2(0.00
FY.11-098-013	28848	3	0.007	0.00	0.016	0.00	
FW1-098-700 CUZK	2/003	3	0.008	0.00	0.017	0.010	
FX11-099-701	8357	3	NA	*	0.009	0.01	
E52F	13302	3	NA	-	0.012	0.005	
FW11-101-007 C5LK	16788	3	NA		0.018	01001	1
FY11-101-009	16870	3	NA.		0.013	0.005	

10.00 00.00	VISION & GROUP	_	CALCULATIO		PTIONAL TASK	CODE	PAGE 24
	Z-(C)		JENX-24			CODE	- AGE
	PAIR	ZET	2 240	BB ನ್	25		
SUPPORT	SNUBBER	HOORE	ACT	00	LOST	4	
FW1-101-700 CG2K	28555	3	0.002	0,00	0.022	0.006	
451-002-004 C72F	9629	35	0.003	0.0	0.012	0,002	
M51-002-00	7897	35	0,0033	0.001	0.010	0.001	
M31-602-008	7938		0.0045		0.036	01006	D5 7/2 (0-002
C7 LF MS1-002-013	7422	35	0.0048	0.001	0.030		-
C72K	7945	35	0.0017	0.000	0.020	0.003	-
M51-003-007 C72K	2072	100	0.004	0.002	0.024	0.011	今72,0014
M51-003-009	1428	100	0.0025	0.00/	0.035	0.005	092/20:00
MS1-003-010	141	100	0.0019	0,001	2 0.030	0.007	45)/2 (0.00
451-003-014 C72F	2078	100	0.005	0.00	0.027	0.007	
MS1-004-007	m 1108	35	0.0017	0.001	0.011	0.014	97/20.001
MS1-004-009	5 470	3 5	0.0035	0.000	0.014	0.009	
MS/- 028-018 533K	10133	T		le+	0		
MS1-070-003	15111	35	0.003	0.00	2 0.028	0.006	974.00

		-	N IDENTIFICA			-	70
1.0. OR W.O. NO.	NZ-CC)		GEN X- 242 -			CODE	PAGE Z 5
	Reservation of the Party of the	-	D SHO	the same of the same of	25		
SUPPORT NO	SUUBBER	HOORE	LEVEL	0	LOST HOTTON	4	8 EMARK
MS1-07/- 00		35	0.005	0.00	0.024		8 975.0
M51-073-01 C52F	20351	1/4	0.012	0.002	0.010	0.00	f .
MS1-150-02 C52F	34421	1/4	0.017	0.00	7 0.026	0.006	974.0
MS1-150-03 C52F	47 5	14	Dole	400			
431-150-05 e52K	13033	1	De	leta	ed		
M31-150-05	50) 522	14	0.011	0.00	0.003	0.0	
US/-150-05 C52F	HOSER ALL	1			, - '-		
MS1-150-06 C52F	19284	1/4	0.013	0.00	0.011	0.00	3
451-151-04 C52F	8911	1	De	Qet	e d		
C521C	2/892	1	De	let	e d	Total C	
572F	14035	3	NA	Lave vo	0.018	0.002	
451-240-00 572K	12903	10	0.010	0.00	0.025	0.005	
MS1-257-00 572 K	1 14796	3	NA	-	0.017	0.008	

			N IDENTIFIC				76	
1.0. OR W.O. NO.	NZW	- 1	GENX-ZAZ		OPTIONAL TASK CODE		PAGE Z6	
73 43 4	CONTRACTOR OF STREET	-	D SHO	-	25			
	,							
SUPPORT No	SUUBBER	HODE	LEVEL	0	HOTON	01	1 LEWAR	
451-274-001 572F	11755	10	10.013	0.00	0.030	0.0		
M51-344-00		1/2	1	0.0	02 0:017	0.0	06	
MS1- 345-00	NAME OF TAXABLE PARTY OF TAXABLE PARTY.	1/2		let	red			
RC1-097-001	7405	10	0.016	5.00	0.013	0,01	7	
RH 1-010-004 522K		1	De	le4	1		, ,	
211-016-700 522E	16925	3	NA	-	0.008	0.00	4	
271K	12908	3	NA	-	0.008	0.00	3	
222F	24245	1	- De	le t	red			
435F	NAME AND POST OF THE OWNER, THE O	L	0.008	0.00	0.009	0.00	1	
A35F	THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	1/4	0.016	0.000	0.014	0.00	8 49>40	
581-040-020 555K		3	NA		0.016	0.00	1	
581-060-028 555F	THE RESIDENCE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER, THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER,	3	NA		0.015	0.0	/	
F53F	12012	3	NA NA		0.019	0.01	1	

				TION NUMBE			
J.O. OR W.O. NO.	DIVISION & GROUP		GENX-ZA	and the second second	TIONAL TASK	CODE	AGE 2
	and the same of th	RET	D SHO	BBERS	5		
SUPPORT NO	SNUBBER	MoDer	ACT	Δ 67	HOTTON	DH	
511-029-05°		35	0.003	0.003	0.020		37/20:00
732F	4918	10	0.015	0.0	0.012	0.001	
511-031-071 53214	28437	3	0.001	0.003	0.018	0.004	37/20
C42F	14568	1	0.009	0.002	0.019	0.002	
511-072-00! 532F	27974	3	NA 0.005	-	0.018	0.008	
511-087-01 C42F	16487	3	NA		0.015	0. 4	
A32F	7 27616	1/4		DELE	rec .		
F33K	53 09	10	0.014	0.00	0.010	0.0	
F33F	5300	10		DELET	69		
A 33F	7/07	3	De	22 + 2	2		
F33F	5300	10	0.012	0.003	0.011	0.001	
5W1-011-02	7 7055	3	- D	elete	d		
5×11-012-02 = 33F		10	0.011	0.001	0:010	2,001	

	CALCUL	ATIO	N IDENTIFICA	TION NUM	BER				
J.O. OR W.O. NO.	A/Z (C)		CALCULATIO		PTIONAL TASK	CODE	CODE PAGE 28		
13737	PAI	or other Designation of the last of the la	D SHO		25				
SUPPORT	SNUBBR	HODER	ACT	0	NOT NO TO	Q.H			
5W1-012-026 F33F		3	XA		0.019	0.00			
5W1-013-005 A33F	7/20	3	NA		0.014	0.00			
VA 1-005-030 C7216	21831	1	0.008	0.003	0.026	0.002	5>4.00		
VAX-005-714 A73F	The second secon	3	NA		0.013	0.003			
MPX-542-000 ASSE	17797	1	0.009	0.003	0.021	0.001			
CC-1-RB-001-00.	NAME AND ADDRESS OF THE OWNER, OF TAXABLE PARTY.	1/4	0.017	0.00	0.009	0.009			
ec-1-R8-09-00 -3	-	1/4	0.014	0.004	0.020	0.018			
-3 -008		1,6		etoc					
-3 9A-0	The state of the s	1/4	0.011	0:005	0.017	0.003			
C-1-R8-004-019		1/4		DEL	ETED	Area .			
CS-1-R8-004-017	11375	1/4		DEI	ELED				
Do-1-DA-007-01		174	0.012.	0.006	0.022	0.006	370.005		
5W1-1-58-004B -020-3		1/4	0.013	0.004	0.015	0.002			

M-1-CPU-1949

15054- NZCO- GENX-242

Job Book
STONE & WEBSTER ENGINEERING CORPORATION Time 9:00 Q.m.
COMANCHE PEAK STEAM ELECTRIC STATION UNIT ' J.O. No. 15454 TELEPHONE MEMORANDUM Outgoing Outgoing
Between 7. GNWALA/S. ALLOS STEC and F. FEORICKSON OF PECIFIC SCIENTIF
Subject PARRELLEL SNUBBERS.
THE JOB BOOK NUMBER MUST BE PLACED IN UPPER RIGHT
SUIMARY
) T. Ginwala asked F. Fedrickson whether to Consider to les mo
at the pin in calculating differential lost motion of
0.02 as specified in muclear standard HE E7-9.
F. Fedsickson stated that the standard specifies.
differential lost motion of 0.02 and is appercuble or
to the last motion internal to the Snubber. Therefore
the talcrance shall not be considered.
9 5. Act imquired about the impact of exceeding the
differential activation level of 0.005 g specified in
Nucleul Standard.
F. Federekson repliced that the effect of differtal
activation level is not cartical & is not normally
matched for passalel smulbers.
Action Assigned:
COPIES TO: F. Fredrickson Pacific scientic KYChu TYChang S. Acc AWChan CButt T-Conval:
ZWrucke

(WED) 85.15. '87 13135 NO.19 PAGE 1

ATTRE - 3 174 544 NECO - OFNX- 242

Kin-Tech Division

Pg 10= 15

	5/13/27
DIVISION: Engineering	
DIVISION: Engineering	
TO: Sin Walla TELEPHONE COMPANY: Stone Wester TELECOPY	609-402-402
of PAGES: Cover Sheet + 3	
COMMENTS/SPECIAL INSTRUCTIONS:	
FAX NO TO CALL AS FOLLOWS: (714)520-7804	
OUR MACHINE IS A NEC NEFAX BIT I AUTOMATIC. NOT RECEIVE ALL THE PAGES, OR IF TRANSMITTAL	
CLEAR, PLEASE CALL ASAP THE OPERATOR AT EXT.	
FAX OPERATOR: Decial	

ATT- 12

15454 N& CO. GENY- 242

PAGE 2 OF E

1.0 PURPOSE

FROM PSCO ANH

19800 15

1.1 To assure compliance of production units of the Shock Arrestor Assembly with referenced drawings.

2.0 SCOPE

2.1 This test establishes both visual and functional characteristics which could be expected to vary through dimensional variation or improper assembly and adjustment.

3.0 REFERENCE DOCUMENTS

3.1 PSCo Drawings 1801107 and 1801117

4.0 EQUIPMENT

- 4.1 1801TF-2 Universal Shock Arrestor Tester
- 4.2 Holding Fixture 1801 HF-1
- 4.3 Holding Fixture 1801 HF-2
- 4.4 .0001 Dial Indicator

5.0 INDIVIDUAL TESTS

5.1 Examination of Product

- 5.1.1 Each unit shall be subjected to a dimensional examination to determine compliance with applicable Sales assembly drawing.
- 5.1.2 Each unit shall be visually inspected to assure completeness of assembly, freedom from burrs and sharp edges, alignment of parts, security of fasteners, and dimensional integrity.
- 5.1.3 Units shall be visually inspected for general appearance of plating, painting, freedom from nicks and damage of finishes.
- 5.1.4 Units shall be inspected to assure the accuracy and legibility of marking and identification.

6.0 FINAL FUNCTIONAL TESTS

- 6.1 Breakaway Friction Force (100 lbs. max.)
 - 6.1.1 Install unit in 1801 HF-1 Holding Fixture and the starting force in both the extension and retraction modes measured with a spring scale. Load measured shall not exceed 100 pounds. Starting

ROM PSCO ANH

(A)

0

(A)

ATT= 13

MEPORT NO. _____IT-535

PAGE _ 3 _ 0F _ 6

15451 47 \$ 0 . GENY-242

force shall be measured at three (3) positions throughout entire travel in both directions of extension and retraction. Approximate positions for force check are one (1) inch from either end and mid position. At each position the starting force shall not exceed 100 pounds.

6.2 Lost Motion (.040 max.)

6.2.1 Install the snubber on the 1801 HF-1 Fixture and adjust the dial indicator such that it will record movement at the clevis end of the snubber. With the snubber extended at approximately its midposition, hold the inertia mass stationary using hand pressure and apply a load of 120 lbs. to the snubber, zero out the indicator, and apply a reverse load of 120 lbs. to the snubber while maintaining hand pressure to prevent movement of the inertia mass. Relative movement noted on the dial indicator shall not exceed .040 inch.

6.3 Acceleration/Load Test

6.3.1 The unit shall be installed in the 1801 TF-2 Universal Shock Arrestor Tester with the unit extended approximately midway from full extension. The 1801 TF-2 Tester pressure gage shall be set for 130 PSI, which is equal to 13,750 lbs. load.

With the required pressure applied to the unit, the time as recorded by the timer for the snubber to extend 1" shall be .51 sec. minimum. This test shall be repeated by retracting the unit and again the minimum time recorded shall be .51 second.

ADDENDUM PA 10 0F 15 Rev. D

Final Inspection Check List
PSCo 1801107
1801117

Shock Arrestor

SCo	P.O.	No.	Date	
hop	Orde	r No.	Customer	
I.	Visu	al Examination (para	a. 5.1)	
	(a)	Dimensional (Actual	dim. listed on	Page 5 of 6)
	(b)	Workmanship		
Ι.		l Functional Tests		
				max.)(para. 6.1)
	(b)	Lost Motion (.040 m	max.)(para. 6.2).	Actual
	(c)	Acceleration/Load T (para. 6.3)	est (.51 sec. mi	in./1.000 travel)
		(10.0)		Actual Time
				Extending
		1,417,749		Retracting
			Inspector	
			Stamp	Date

NO. 6

15454 . NZC) - GENX - ZAZ

Kin-Tech Division

Pacific

COVER SHEET FOR PAX

DATE: 6-12-87

FROM: LEE CAMACHO DIVISION: KIN. TECH

TO: GIN WALLA

TELEPHONE (609) 482-4140
TELECOPY *(609) 482-4029

of PAGES: Cover Sheet + 4 COMMENTS/SPECIAL INSTRUCTIONS:

FAX NO TO CALL AS FOLLOWS: (714)520-7804

OUR MACHINE IS A NEC NEFAX BIT I AUTOMATIC. IF YOU DO NOT RECEIVE ALL THE PAGES, OR IF TRANSMITTAL IS NOT CLEAR, PLEASE CALL ASAP THE OPERATOR AT EXT. 314.

FAX OPERATOR: TIME: 9:00

FRI)06.12. '87 08:45

HO.6 PAGE 2

15454 NZG) - GENY - 242

REPORT NO. DR 1432

DATE 17 October 1977

DATA REPORT 1432

TEST EVALUATION OF PSA-10 SNUBBER
ON ECCENTRIC TYPE FIXTURE
(1801103-TF-2)

FROM



KIN-TECH DIVISION

A.	PREPARED rriaza Designer	0	ara		JE. Glauser Director of Engineering
	Designe				
	DATE	- By	APPO BY	PAGES AFFECTED	
	10-17-77	24-	thy		

ATT-8

154 54 N 2-CO GENY - 24 2 P4 13 0 F15 1 REPORT NO. DR 1432

0.05 NO. DR 1432

PAGE 1 0F 2

This test is intended to replace the acceleration test currently performed on PSA-10 Snubbers (1801-TF-2).

FROM PSCS ANH

The Eccentric Type Test Fixture consists of an eccentric shaft that fits the spherical bearing of the snubber and drives the snubber with a reciprocating motion. The shaft is driven by a constant torque gear motor through a roller chain drive. The sprocket at the gear motor rotates at 41 RPM and the sprocket at the eccentric shaft rotates at 76 RPM (1.85 ratio) when there is no load (snubber not installed). The sprocket at the eccentric shaft is mounted on a friction type clutch. When the snubber is installed, the gear motor attempts to drive it at 76 RPM, equal to .049 g's. The snubber tries to contain this reciprocating motion to less than .02g. The braking action of the snubber creates a difference in RPM of the eccentric shaft. This difference in RPM is an overload taken by the friction switch installed in the eccentric shaft. A counter records the rotation of the eccentric shaft, in conjunction with an internal timer which allows the tester to run for a preset amount of time (1 min or 30 sec).

The readings obtained are RPM and they can be translated into g's. The following results were obtained on a test run of 108 units and compared to their respective acceleration times.

Snubber Qty	RPM	AAT*	Percentage
7	20	1.03	6.48
8	23	.92	7.41
6	26	.89	5.56
3	28	.88	2.77
12	30	.81	11.11
11	32	.75	10.19
7	34	.71	6.48
11	36	.72	10.19
12	38	.70	11.11
16	40	.67	14.82
9	42	.65	8.33
		1	

PACIFIC SCIENTIFIC . KIN-TECH DIVISION

FROM PSCO ANN

15454 NECC) . GENX-242 PET - 3

REPORT NO. DR 1432

PAGE _ 2 OF 2

Snul	ber	Qty	RPM	AAT*	Percentage
	4	1	44	.62	3.7
	2		50	.53	1.85

*AAT = Average acceleration time of the extension and retraction cycle for the total number of snubbers in the same RPM group.

Based on the above, a value of 44 RPM will be used as an acceptable criteria, with the option of using the standard acceleration tester as an alternate test method for snubbers exceeding 44 RPM. It is also recommended that those units with readings below 20 RPM be inspected closely.

20 - 44 GOOD
20 - 44 - L.ok.

PACIFIC SCIENTIFIC . KIN-TECH DIVISION

1346 S. State College Blvd. Anaheim, Ca. 92803 (714) 774-5217

(5454.0211) GEN 4-248




FIG. 3 MODEL PSA 10

C. INMAN

INTEROFFICE CORRESPONDENCE 6 10227

TO: MAROLD MOSCOW	LOCATION	SUBJECT / REFERENCE / J.O. NO. 15% 5% 05"	-
FROM:	NYOC 36	PARALLEL SNUBBERS.	
T. GINWACA / S. ALI	136R		

MESSAGE: -

PLEASE REVIEW THE PATTACHED LIST OF PARRELEL SNUBBERSLAND INFORM US IF ANY OF THESE SNUBBERS ARE DELETED BY 5/15/87

7- Grand Syed A. Ali A140

The above toward sold you call NYO. Jave

green on please 5083

Anish 21/87

green on please 5083

Anish 21/87

SIGNATURE

TELEPHONE

CALCULATION SHEET

Pg 2 0 F 27

	CALCUI	LATIO	N IDENTIFICA	TION NUI	MBER	2.1.1	1
J.O. OR W.O. NO.	DIVISION & GROU	P	CALCULATIO	N NO.	OPTIONAL TASK	CODE	PAGE
23×13×2= 2	59B PAI	RET	PEOB	BBE	ED EXIST	T- DIFF	roceta
5UPPORT No	SNUGBER	HODER	Level G	46	HOTTON	AH	102-1
C5-1-106- 720-C42 K	9075	1/2				NOT IN HITS LISTINGS	1 2/10
CG2K	15323	1/4				NOT IN HITS LISTINGS	1010
RH-1-5B-01	9737	1/2	1-074	/		P36 5,14	1: 0.
RH-1-58-01	9720	1/2	1-074	/		P3E4 514	
AF-1-096- 533K	17925	1	0100	V		PSE 1190	54-1-25
AF-1-096-02 5 33 K	0 19536	1/4	0100		SNUSSEE MOD To RY	SA-1256 Mod.	
562K	10186	10	0100	/		PSE 1190	1610. SA-1-25
AF-1-095-00 54316	16505	3	OISD		SHUSSEE MOO' TO KY	54 1-187 MOD	
4F-1-099-00 533 K	17526	1	0120	/		PSE 1190	, 0103
533 K	7 9832 10309	1/2	0120		SHUSSEE MOO TO EZ	SA-1-187 Mod	. 0102
4F-1-099-03 543K	3 24269	1	0120	k	To Ky.	5A-1-167 Mad	, 0102
=W1-1-092-70 562K	0 11717	10	0120	/	NO. N. P.	PSE 1190	, 010: \$4.1.18
AF-1-054-70 5621C	24126	1	0125	/		CPPA 57,629	,0102

Ry 3 0 = 23

	CALCU	LATIC	ON IDENTIFICA	TION NU	MBER		
J.O. OR W.O. NO.	DIVISION & GROU	UP	CALCULATIO	ON NO.	OPTIONAL TASK	CODE	AGE 2
	PA	IRE	D SHU	BBE			
SUPPORT	SNUBBER	HODE	ACT LEVEL	4	LOST	Q.H	P: 01
AF-1-101-00 5 331C	7 28085	1/4			MOO. TO 12	541-16Z MOD	101:
51-1-051-02 C42K	17818	1	014			HOC 2999-I	. 6 10
51-1-037-01 8421C	2 8380	3	016		Moo Field	WPT 8425	5
51-1-047-0 C42F	17 19038	1	016		Meo Field	WP7 8425	,_ 0
51-1-099-00 C42K	19044	1	0170		V	PSM .1.	, 0 10
51-1-095-01 C42K	0 14919	3	0170		M.o	WP7_ MoD/	1013
51-1-181-00 C41F	15063	10	0176		Med Field	WPT 8380 MOD/-	, ; 0
51-1-30G-02 C42F	25099	1/4	018		Moo	WPT 8433 MoD, ST.	. 6 15
51-1-306-02 C42F	AND RESIDENCE OF THE PARTY OF T	1	018		Meo	WPT 8433 Moc/ST	12 10
51-1-304-02	19/32	1	018		M00	8433 Mw/5T	1 6:0
51-1-300-03 CH2K	AND DESCRIPTION OF THE PERSON	1	018		Mob.	WPT 8433 MoD/-	, 610
RH-1-001-000 CUIK	27948	3	013A	/		PSE 418	1 2 -02
24-1-001-01 C41K	THE RESERVE THE PERSON NAMED IN COLUMN 2 I	10	013A	/		PSE 418	, 4/0':

ATT-C

1687

MOD

16.10%

STONE & WEBSTER ENGINEERING CORPORATION

PS A C/ 27

CALCULATION SHEET w10 65 CALCULATION IDENTIFICATION NUMBER PAGE 3 J. O. OR W.O. NO. DIVISION & GROUP CALCULATION NO. OPTIONAL TASK CODE SHUBBERS COMMENTS PAIRED PRAR EXIST(V) DELETHO ACT HOORE C-37 PEAM = SNUBBER 5UPPORT LEVE HOTTON 4 0 105-AT No 9 C7 40 4 IN PH-1-601-009 14402 HOLD CHIIC 1 5 /5/2 013B 27954 24-1-002-012 WPT 10053 Moo 10 013B 10100 C41/6 10762 FIELD Moo CT-1-009-007 SA- 1-121 10751 =/ 6713 13 027 52216 10 7375 CT-1-009-008 10295 CPPA 16 027 10102 52214 54449 12742 54-1-121 15 CT-1-010-010 CPPA 21000 3 027 19 1 4 10'4 5225 54449 20 21004 SA-1-121 SHUBBER CT-1-007-010 SA-1-06 & 10790 MOD. 70 22 031 , 2 100 522K MOD ZX 107 47 23 SHUBBER CT-1-013 - 007 54-1-100 12344 NOO. 1/2 25 032 MOD 1210. 5221C TO 27 12357 26 27 CT-1-014-012 CPPA 16469 3 28 033 1610% 5421 54921 16513 29 CTI-039-428 KSK SA-1-16 9833 Meo. 31 035D CHZK 1 0 1012 MOD TO KSK 10350 32 CS-1-001-015 33 CPPA 8517 1/2 34 041 10101 CUZIC 54565 5518 35 CS-1-079-022 3 6 11390 PSE 1/2 16:102 0438 CYZK 265 11412 38 120-1-115-011 39 10431 PSM-1 WPT 8411 40 10 053 1731 16:0: C74K 11619 4: MOD. 120-1-018-051 42 20305 PSM . 1 -

10

24194

CH3D

--- C51K

44

45

CALCULATION SHEET

Pg 50F 27

	CALCUI	LATIO	N IDENTIFICA	TIONNE	JMBER	KIND II.	
J. O. OR W. O. NO.	DIVISION & GROU	P	CALCULATIO	N NO.	OPTIONAL TASK	CODE	AGE 4
	PAI	RE	Peos	BBE			
5UPPORT No	SNUBBER	Hoper	ACT LEVEL	4	HSTION LA	4	1-104
CC-1-259-007 C53K		1/4			Moo.	SA- 1-171 MOD.	1:10
CC-1- 212 - 005 CG3 E	12024	1	0550		KY Moo To Ky	SA-1-172 MOD	, (10%
CC-1-218-012 C53K	10752	1/4	0556		KX Mod. To Kx	MOD -	10.
CC-1-215-012 C53E	10739	1/4	059A	V	/	P 5E 640	5A-1-23
433K	24507	3	0628		M.a T. Rx	MOD	A STATE OF THE PARTY OF T
CE-1-010-005 A43K	10525	3	0628		Me 0 To , Sx	5A-1-16A MOD	, 102
A43K	15987	3	0628		Mod To Sx	SA-1-164 MOD	, c /5'.
CC-1-0113-017 A43K	4296	10	0628		MOD. TO EX	MOD	, c. 15°.
CC-1-156-002 A53K	8356	3	0648	/		CPPN 57666	1 6 10 °C
00-2-044-700							
- A43K	11765	10	066B		T A TELEF		1 16%
56-2-045-703	12950	7				CPPA	
- A33F	149200	3	0668		***	57664	11 110
522K		3	069		Mod Sx To Sx	SN-1-176 MOD	
532×	AND RESIDENCE OF THE PERSON OF	3	069		Meo Sx To Sx	5A-1-176 MOD	,: 10.

5010 65	CALCU	LATION	IDENTIFICA	TION NU	MBER	Pg 601	
J.O. OR W.O. NO.	DIVISION & GROU	JP	CALCULATIO	ON NO.	OPTIONAL TASK	CODE	AGE 5
	PA	IRET	PROB	BBE			
5UPPORT No	SNUGBER	HOOSE	LEVEL	0	LOST MOTTON IN	AH	PE72M
RH-1-024-0 522K	14513	3	070		Mod Sx To Sx	SA-1-177 MOD.	.010
MS-1-074-01	5 8400	1/2	075		Med KI To KI	MOD.	, 0 10
MS-1-074-0 CSZIC	14 8373	1/2	270		M.O K2 T. K2	541-201 Mod.	. 0102
MS-1-151-02 C52K	10750	1/4	076A	1		PSE 541	. 0/1:
MS-1-151-03 C5216		1/4	076B	1		PSE 1190	. 0/02 SA -1-24
MS-1-151-09	THE RESERVE OF THE PERSON NAMED IN	1	0768	/		PSE 1190	. 015.
45-1-151-04 C52K	3 8909	1	0768	/		PSG 1190	,010L
45-1-150-0. C52K		1/4	077		Mod Vsk To Ksk	5A-1-279 MOD	
45-1-150-0: C521C		1/4	770		Moo. To	SA-1-129 MOD	. 0 103
US-1-344-00	24214	1	077		MOO Ka To Ka	SA-1-229 MOD.	.0101
US-1-345-00 CSZF	9790	1/2	078		M.D. S. T. S.	M00	.0102
45-1-029-0 533K	AND DESCRIPTION OF THE PARTY OF	1	080B		Map.	5A-1-205 MOD	.0102
00-1-03y-00	THE RESERVE OF THE PARTY OF THE	10	1676		Mos	SA-1.212 MOD	,0102

CALCULATION SHEET

PG 70F2) ▲ 5010.65 CALCULATION IDENTIFICATION NUMBER PAGE 6 J. O. OR W.O. NO. DIVISION & GROUP CALCULATION NO. OPTIONAL TASK CODE 2THYMMOS PAIRED SHUBBERS PROS# DELITED E+IST.(J) ACT LOST PETCH = SNUBBER LEVEZ 5UPPORT 0 0 HOTTON 102-AT No 9 40 5 IN IH 12680 VA-1-005-016 54-1-217 Moa To C92 K 10196 MOD 180 12687 Rsx VA-1-005-018 10373 PSE 10 CAZK 180 840 ,01:2 21792 54-1-217 EW-2-094-404 12 15078 3 13 SUZK 101:2 26961 51-2-051-412 12700 CHZK ,0102 15891 51-2-051-413 20407 19 CYZK ,0102 20014 20 51-2-095-413 21 24649 22 3 CYZIC 18.02 24664 24 51-2-087-411 13012 25 C4215 10102 20250 26 27 51-2-087-4/2 20177 28 CYZK ,0.02 20196 51-2-087-417 20183 3 1 ,0102 CUZE 32 20640 33 51-2-690-403 4329 3 34 ,0102 ---- C41K. 6339 35 51-2-089-409 3 6 20646 37 CHZK ,0102 20617 38 51-2-088-410 39 482 11 40 ,0102 CUZK 605 41 51-2-306-426 42 16467 .2/02 43 C42F-__ 16471 45

			IDENTIFICA	TIONN	MBER		7
J.O. OR W.O. NO.	DIVISION & GROU	P	CALCULATIO	N NO.	OPTIONAL TASK	CODE	PAGE 7
	PAI	RET	- SH'>	BBE	25		
5UPPORT NO	SNUBBER	HODE	ACT LEVEL	0	LOST	O.H	PE12
RC-2-135-405 C4219	15195	10				,	,01
C441C	3799	3					. 51
CT-2-051- 40 C72K	24535	3					. 01
WP-2-030-4 C46K	16463	1					. 01
C42F	21817	1					.010
C5-2-001-41	15916	1					. 0/
RC-2-052-42 C4114	19054	1	は				,01
C42K	2 20187	1					.010
C5-2-079-41	21735	1					. 610
C42F	20424	1					,010
20-2-115-411 C7614	15809	10					,0/0
26-2-115-431 C5414	15779	10			# # # # # # # # # # # # # # # # # # #		,010
45-2-344-4. C52K	19/31	1		Total select			,010

J. O. OR W.O. NO.	DIVISION & GROU		N IDENTIFIC		·	KCODE	PAGE 8
					kalma e	Auf de les	
	PA	1125	Peost Peost	Doute			
SUPPORT NO	SNUBBER	HODER	1000	-	HOTTO	TH	105-1
MS-2-344-40	21124	1					,010
5B-2-023-404 E 25F	21348	3					,010
AF-1-001-017 533E	15984	3	AIIO		PENAGO SALIBORE BAZE	5543 Moo./57	.0/0
4F-1-001-021 Y33K	13041	1	OIIA		Revise o	PSM-1- 1742 MoD/-	.010
533K		1	0100		Mob. To Kx	MOD	, 016
AF-1-096-041 54316		1/4	000		SHOBBEE Mea To Ry	SA-1-25 MOD	. 015
4F-1-094-045	CATEGORIES, PRINCIPAL DE CONTRACTOR DE SANTAGRADA DE CONTRACTOR DE CONTR	1/2	0100		Moo. To Kx	SA-1-25	. 010
AF1-097-0019 563F	14604	1	0100		Moa To KZ	MOD	.010
A =-1-097-044 553 F		1/4	0100		SNUCCER Mob. To Rx	SA-1-156 MOD	2010
AF-1-090-03	10287	泛	010A		PEEP.		.0102
54316	8450	1/2	0103		Mos. To Ra	NOD	,0102
BRX-044-008 A 53 F	10537	1/2	090		/	PSC/1.0%	4,0102
A3315	9232	3	0628	~		CPPA 57.666	, 0/07 SA.1.16

CALCULATION SHEET

Page 100F 27

	CALCUL	ATIO	N IDENTIFICA	TION NUI	MBER		0
J.O. OR W.O. NO.	DIVISION & GROU	9	CALCULATIO	N NO.	OPTIONAL TASK	CODE	PAGE 9
	PAI	RET	PERSHU	BBE		TS ()	
5UPPERT HO	SNUBBER	HODER	LEVEL	40	HSTION TA	04	102-D
CC1-017-010 A3316	21018	3	061B		1	P==/4	,0103
A33F	4744	35	061A		/	P\$4-4-6618	
5331C	6451	3.5	061A		/	PSM-1-12	,000
533F	3 11611	10	061A		/	PSC/Y	,0102
C1-043-01	15955	3	0628		MeO To Ex	MOD	.0107
C(1-643-62)	10717	10	06ZB		/		,0102
A33 F	11574	35	0628		/	00%0	,0000
533A	76589	3	0610		SENT TO FIGUR VIA. Z.O.C. MERIN	,	,0103
533 F	14710	10	0628		/	P5C-1-06L	10103
533F	THE RESERVE AND ADDRESS OF THE PARTY OF THE	3	0610	1		182	,0102
E33F	20325	14	0616		SUPPT. TO BE REEVALUATE	PS4 1.03	,0102
C42K	25038	14	058		RENSED SAUGREE SAZE	PSM.1- 1442	,0102
C53F	Mark Conference of the Confere	1/4	0554		MOD. TO RY	SA-1-172 MOD	,0102

		-	N IDENTIFIC	ATION NU	MBER		0 = 27
J.O. OR W.O. NO.	DIVISION & GROU	P	CALCULATI	ON NO.	OPTIONAL TAS	K CODE P	AGE TO
	PAI	RE	PESLEM	BBE	25 conquestion con	2TC (\)	
SUPPORT No	SUUBBER	HODE	ACT LOVEL	7.18	HOTION		P672 N
C53 C	10778	1/4	0550		Mod. To Ex	MOD.	1010
CC1-215-007	10780	1/4	0550		MOD. TORX	5A-1-172	10102
CS31C	25069	1/4	0550		/	Psc-1-0550	F. 0107
CC1-240 -00	24117(B)	?	0558	~		PSE 541	54-1-17
C53F	16907	3	0569	~		PSE 640	. 010' SLI-174
C53K	3 16156	14	OSSB		/	P\$-1-058	2,0103
CS3F	15395	14	055 D		/	95M.1-	10100
CS3F	19940	1/4	0556	/		CPPA 57629	,0102 SA-1-171
A75F	0161	3	0637	1		PSE 840	,0102 SA-1-24
A756	2/034	3	0634		/	PSC-1-0634-6	,0102
545 F	2181	1/2	HOGI	1		Pse Acd	10101 SA-1-03
552F	12988	3	N068		1	PSC-1-N0684	,0102
251-242-70 A42F	12656	1	N019		1	PSC-1-NOIT-1	,0100

\$ 5010 65	CALCU	LATIO	N IDENTIFIC	ATION NIII		age 1.	20F27
J.O. OR W.O. NO.	DIVISION & GROU		CALCULATI		OPTIONAL TASK	CODE	AGE 11
	PA	IRE	D SHU	BBE	25 comment	3	
SUPPORT	SNUBBER	HSORE	LEVEL	0	LOST MOTTON	4	P=72H
553F	13000	3	NOIZ	-		840	,0102 SA-1-21
553F	12670	?	N066	/		PSE 840	SA-1.05
532F	13031	1	033		1	PSM-1-1593	.0102
C 52K	12035	1	037W		REVISED SAUDOER SIZE	PSM1. 0252	.0102
C72K	107 04	10	037W		SIZE SIZE	PSM-1-002	.0102
C52F	THE RESERVE OF THE PARTY OF THE	10	03700	144	Potential Mod.	SA/Y MOD	,0102
522 F		1/9	028		/		,0101
522F	THE R. P. LEWIS CO., LANSING, SALES	3	027		Mo NX	54-1-121 MOD	10102
52216		3	027		Peviseo Sweet Size	P=M 1-	,0102
522K		3	028		/	PSC/Y	10102
C71-029-023	NAME AND ADDRESS OF THE OWNER, WHEN PERSON ADDRESS OF THE OWNER, WHEN PERSON AND ADDRESS OF THE OWNER, WHEN	1/2	029K	-		P5€ 640	10102
C92F	24122	14	029M		Mod.	P\$M-1 0380	,0102
C924	COLUMN TWO IS NOT THE OWNER, THE PARTY OF THE OWNER, AND ADDRESS OF TH	14	029M		Mob. By Field	PSW.1.	,0102

	CA	LCULATIO	N IDENTIFIC	ATIONN	UMBER		
J.O. OR W.O. NO.	DIVISION &	ROUP	CALCULATI	ON NO.	OPTIONAL TAS	K CODE P	AGE 12
	7	PAIRE	PROBA	BBE	TES COMMENTES	274 (\.	
5UPPORT	SUUGA	HOOR HOOR	LEVEL		- HOTTON	No. at the	PERM .02-0
CT1-034-0 CB2F	19 978	1'/2	036		Moo To Rsk	SA-1-10	.010
CT1-034-0	11372	1/4	036		Mod. Te Rsk	5A-1-106	. 510
CTI-038-4	37 2032	1/4	035A		Med. To Esc	SA-1-208	. 610
CT 1-002-0 532/C	03 1197	13	031		Moo To Ry	SA.1.068	. 010
CT 1-007-0 522 K		3 3	031		Mao To RY	SA-1-068	. 0107
CT 1-009-00 522K	1299	- 11	027		Mod.	0551 10001.	.010
CT1-012-0 522K	1488	13	028		/		. 5101
671-013-0 542K		110	032		1	1381	,0107
CT 1-013-41	3291-	13	035A		1	PS 4 - 1 - 035A-6	,0101
CT1-013-4 C.62K	AND AND THE PARTY OF THE PARTY	10	035A		Moo To Ry		, 0 0 ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° °
CT 1=0 13 - 41	12019	15	035A	X > 14	Moa IN FIELD	PSM.1.145	.010:
CT1-013-41	CONTRACTOR OF THE PARTY OF THE	7 3	035 A		Moo To Rsk	54-1-708	, 0103
CT1-014-00 54215	CONTRACTOR OF THE PARTY OF THE	NAME AND ADDRESS OF THE OWNER, WHEN PERSON NAMED IN	033		+		,0103

\$010.65	CALCU	LATIO	N IDENTIFIC	ATION NU	MBER	P5 140	17 2 /
J.O. OR W.O. NO.	DIVISION & GROU		CALCULATI		OPTIONAL TAS	K CODE	PAGE 13
	PA	IRE	Plog #	BBE			
SUPPORT NO	SNUBBER	MoDel	LEVEL	40	MOTTON TH		102-A
S424	9234	10	033		Moo Field	PSM-1 0235 HoLD EF	, 510
CT1-014-014 532K	10709	3	033		1	PSW - 1-027	. 015
CT1-038-441	27599	1/4	035A		1	P\$6-1-035	, 0127
CT1-039-443	19965	1/4	0354		SEVISED SAN BOOKE SAILE	PSM-1-	,0100
C71-044-022 C92F	10358	1/2	29L	/		CPPA 57624	. 0101 SA-1-07
C 4216	12039	1	0291		1	PSM . 1 .	,010
C92K	8375	1/2	0291	-		CPPA 54938	,0107
C 52 K	28559	1/4	029N	/		3A-1-049 MOD	
C42F	10078	1	037B		1		,010:
CBLE	9519	1/2	03700		Mod To Rsk	54-1-265 MOD.	,0152
CB2K	The same of the sa	1/9	037W		Mas. To Psk	SA-1.765 Meo	,0102
C 52 K		1/4	037W		REVISED SALURAGER	P\$M+1- 0304	,0103
CT 1-051-415 C72K	16795	3	037W		1	PSM-1-	,0102

ATT-C

STONE & WEBSTER ENGINEERING CORPORATION 2 RZ

CALCULATION SHEET

Pg 15 OF 27 ▲ 5010.65 CALCULATION IDENTIFICATION NUMBER PAGE 14 J. O. OR W.O. NO. DIVISION & GROUP CALCULATION NO. OPTIONAL TASK CODE PAIRED CHHMMOS SHUBBERS EXIST (V) PROB # DELETED ACT LOST PIRH = SNUBBER LEVEL 5UPPORT Δ Δ MOTTON .02-AT NO 9 IN 5 NO CT 1-051-416 14598 0370 C7215 PSC/Y 101012 14409 CT1-051-417 14550 10 PSC/Y CTZK .0102 037W 14563 CT1-051-418 12313 12 037W 13 PSC/Y C72K .0102 12 3 52 CT1-051-419 15 14590 16 C72F 037W PSX/Y ,0/02 14592 CPPA .. CT1-054-433 16180 1/4 19 CUZK 0372 10102 54921 20 16181 SA-1-129 21 CT1-074-410 PSE 19980 22 CBZK 037W 1917 19963 23 SA-1-765 CT 1-075-406 PSK . 1 -24 12041 0264 PEVISED 037W 25 .010= CUZF SHURBAR 12042 26 P3M-1-27 CT1-074-404 14572 REVISED SWIESCE SHEE 5500 035A 10102 28 C 52K 14592 29 30 CT1-076-408 12017 035A 3 10102 3 1 C BZK 12020 32 CT1-077 -407 33 SA-1-708 12010 MOD. ,0102 035A To 34 C72F MOO RY 12015 35 CPPA CT1-097-403 3 6 12043 037W ,0102 37 C52K 1917 SA-1-265 12044 38 PSM = 1 = (NO ROLEASE DATE) CT1- 097-414 39 19942 HOLD 1397 14 037W ,0102 40 CYZK 9947 41 CT1-117-412 000 9 42 12354 037W 16 10102 CUZK 43 REVISED 12393 SIZE 44 45

5

STONE & WEBSTER ENGINEERING CORPORATION 242 ATT-C

J.O. OR W.O. NO.	DIVISION & GI		CALCULATIO		OPTIONAL TASK	CODE	AGE 15
			2 (4):15				
	P	AIRE	PROB#	BBE	916		
SUPPORT NO	SNUGBE	Moore	LEVEL	00	LOSTON	D. H.	105-V
CT1-117-41	5 1919		0370			PSE 1917	,0107
CTI- 124- 41	5 1244	11	035c		Mos To Vx	54-1- 166 Mos	,0102
C72K	8420	1/1	035<	~		CPPA 57666	1 5711.5
DDZ-003-45	2837	15					.0103
DOZ-0.3-48	2029	4 1					. 5/5%
D01-004-49 536F	3 7134	3					.0102
Do1-029-00 553F	1160		1670		Holp		
Do1-035-05 553X		8 3	1676		1	P3M 1-	,0102
563F	3 6990	35	1670		HOLD		,006
55314	16966	13	1676		1	PSU. 1.	. 0103
242K	2637	1 /4			SITE SCOPE PER CPPA 32947		.0102
Dol- 058-001	THE REAL PROPERTY AND PARTY AND PERSONS ASSESSMENT AND PARTY AND P	MARKET PROPERTY PROPERTY AND ADDRESS OF THE PERTY PROPERTY PROPERTY PROPERTY AND ADDRESS OF THE PERTY PROPERTY	167F		Hord		,0102
Do1-070-00	16971	131	167F	****	Houp		, 6 102

STONE & WEBSTER ENGINEERING CORPORATION CALCULATION

5010 65	211.011	1 4710	N (BENEVE	216111		Pg 170	
J.O. OR W.O. NO.	DIVISION & GROU	-	CALCULATIO		OPTIONAL TASE	CODE	AGE 1 6
	PA	IRE	PLOST			e tr	
5UPPORT	SNUBBER	HODEL	ACT	Dete	LOST HOTTON	4	PER.
DD1-003-09		1.1				PROB Nº NOT LISTED	,0/0
DD1-003-07 535K	12139	1/2				PROB. Nº	, 010
D01-071-00 563K	11910	10	1678		Hora		,0/0
563K	8881	35	167F		How		,000
D01-071-000 S53K	11425	10	167F		Hora		,012
D01-069-00 565K	12920	10	167 C	<	Horo		,015
565F	10750	3	167F		Horo		,010
565F	11626	10	167F		How		1012
EV/1-017-02 C72K	16888	3	007	/		PSE 2521	: DID
E42F	6 8374	35	007	73.00	1	Psi: - 5539	.004
E72 K	1458	100	007		1	PSM-1-	, 005
C72K	1426	100	007	#4 *I	Med By Field	PSM -1-	,005
FY11-017-712 C7216	1420	100	007		Moo Ay Field	Psm-1-1772	,005

ATT-C

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION SHEET

Pg 1805 27 ▲ 5010.55 CALCULATION IDENTIFICATION NUMBER PAGE 17 OPTIONAL TASK CODE DIVISION & GROUP CALCULATION NO. J.O. OR W.O. NO. COMMENTE SHUBBERS PAIRED EXIT(V) PROBE ACT LOST PETRH = MOTTON SNUGBER LEVEZ 5UPPORT Δ .02-NO 9 6 IN 114 40 PSM-1-EW1-018-016 11590 35 006 ,0062 C52F HOLD 11537 FW1-018-700 1454 PSC 1-006-1 , 0052 006 6 100 10 C721C 1457 S448644 Fr11-018-705 1433 SA . 1.165 12 To PZ 10052 100 13 MOD C72K 006 1424 14 FW1-018-709 1455 PSC-1-0064 . 0052 CTZK 100 16 006 1456 17 Fx11-019-701 PSM -1 -3788 18 35 ,0000 REVISED 19 C1:21 005 SHUOSER 4ZE 8790 20 FW1-020-700 PSM - 1-5457 1427 2 1 22 100 100,50 CYZE 008 1432 23 FW11-095-011 PSM 1-14921 Moz. 1555 BY 2010 25 CUZK ISZ FIELD 14922 26 PSM-1-FW11-095-700 7.1001 27 MOD 1220 3 CGZF 152 .0102 28 87 2/013 FILL 2 -FW1-095-701 30 13001 PSC/Y 3 15% 31 CGZF .010% 13005 32 FY11-096-700 POTEMINA 3 3 12026 PSM/Y MOD. 153 34 ,0102 CUZE 21007 35 Fx11-096-701 11984 12 153 3 ,010:-37 CGZK PREP 16904 38 P504 -1-F- x-11 - 090-702 12008 5252 REVISE SHUBBER SHZE 153 10102 CUZK 40 12009 Sibon 1 . 42 EV-11-096.704 16866 250 3 153 ,010-43 CELIC BE 1190 44 169110 45

STONE & WEBSTER ENGINEERING CORPORATION - GEN7 - 24.2

CALCULATION SHEET

5010.65	CALCU	LATIO	N IDENTIFICA	TION NU	MBER	1	
J.O. OR W.O. NO.	DIVISION & GROU	JP	CALCULATIO	N NO.	OPTIONAL TASK	CODE	AGE 18
	PA	IRET	PROB#	BEE		8	
5UPPORT	SNUBBER	HODEL	ACT	0	HOTTON	4	PL 2H
FW1-096-70	5 10709	10	153		1	PSM-1-	,010
FN11-096-7	10052	10	153		/	P54/Y	, 510
FW1-096-7 C62F		3	OIZD	-	•	PSE 1190	, 5103 SA-1-18
FN/1-097-09 CUZE	NAME AND ADDRESS OF THE OWNER, THE PARTY OF THE OWNER, THE PARTY OF THE OWNER, THE PARTY OF THE OWNER, THE OWN	3	154	-	-	P36 665	, 5 5
FW1-097-7 CG2K	14906	3	154		Mod To Qx	SA-1-211 Moo	.0107
FW11-097-7 662K	NAME AND ADDRESS OF TAXABLE PARTY.	10	154			PSM-1- 5473	,010
F4/1-097-70 C 402K	S 28401 28416	3	154		FIELD TO MoonFY	PSM -1-	1016:
Fy/1-095-01		3	155		Field To Moder	PSM -1 - 1567	,010
Fr11-093-70 CGZK	ASSESSMENT OF THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	3	155		1	PSC/Y	.0102
FY11-099-70 C6216	5357	3	152		Mod To Ry	SM-134 MOO	.0103
FV/1-100-7	13302	3	153		1		-10102
FV11-101-00	16805	3	154		Potential M60	PSM -1 -(Na 5342	10100
FY11-101-00 C52F	The second of th	تخ	154		-/	PSC/Y	,0102

CALCULATION SHEET

5010 65	CALCUL	ATION	IDENTIFICAT	TION NUMB	ER		10
J.O. OR W.O. NO.	DIVISION & GROU	P	CALCULATIO	. NO. OF	TIONAL TASK	CODE PA	AGE 19
	PAI	RET	PEOBA	BER Release			
5UPPORT	SNUBBER	HODER	LEVEL	0	LOSTON	AIH	102 -A
FW11-101-70 CG2K	28555	3	150		1	PSC/Y	,010
M51-002-000 C72F		35	002		Mob. BY FIELD	PSM-1-	,004
M5/-001-0	7938	35	002		1	PSM 1-	. 001
M51-002-0	The same of the sa	35	002		/	PSW-1-	,006
M51-002-0	THE RESERVE THE PERSON NAMED IN COLUMN 2 I	35	002		1		1006
MS1-003.0	MARKON AND DESCRIPTION OF THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	100	003		Hord		. 05.5
M51-003-00	1425	100	003		How		.005
MS1-003-01		100	003		HOLD		.00
W51-003-01	THE RESERVE THE PERSON NAMED IN COLUMN 2 IS NOT THE OWNER.	100	003		1		,005
MS1-004-0	8403	35	004		SAUSOSE ASSY TO BE ESPLACED	P5M-1-	1000
MS1-004-0	C TAXABLE PARTY AND PROPERTY OF THE PARTY OF	35	004		Hord		,006
MS1-029-0 533K	NAME AND ADDRESS OF TAXABLE PARTY.	1	0800	/		95E 301	.0102 SA-1-20
MS1-070-06	Commence of the last of the la	35	100			No 80000	,004

5

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION

CALCULATION

CALCULATION	SHEET	

5010 65	CALCU	LATIO	N IDENTIFICA	TION NU	_	Pg 210+	
J.O. OR W.O. NO.	DIVISION & GRO			-	OPTIONAL TASK	CODE	ACE ZC
	PA	IRE	PROB!	BBE			
5UPPORT	SNUBBER	HODER	LEVEL	0	TZ OLL OLL OLL OLL OLL OLL OLL OLL OLL OL	DH	PEL!
MS1-071- 00 THUK	10100	35	100			RECORD	,000
M51-073-01 C52F	3 19501 20351	1/4	078		/	P\$<-1-078-3	, 510
MS1-150-03	34421	1/4	077		IN PREP.		,010
MS1-150-03 C52F	4750	11	077	-		PSE 640	, 0 0
M31-150-05 e 52K		1	077	_		PSE 640	,010
M31-150-09 C52F	512	11	770		HOLD		, 510
45/-150-05 C52F	4 20039	1	077		1		,0)5
MS1-150-06 C52F	19254	1/4	017		/		, 910
451-151-04 C52F	8909	1	076B	V		P.SE	1010' SA-1-23
C 521C	21892	1	076B	V	,	1190	, 0/0' SA-1-23
MSI- 223-00 572E	14034	3	0230		1	PSM-1-	, 0103
451-240-00 572K	12919	10	023B		HOLD		10/55
451-257-00 572 F	1 14796	3	023A		MOD. BY FIELD	PSM-1-	, 5/5

	CALCU	LATIO	N IDENTIFICA	TION NU	MBER		1
J.O. OR W.O. NO.	DIVISION & GROU	P	CALCULATIO	N NO.	OPTIONAL TASK	CODE	AGE Z
	PA	IRE	Pension	BBE	RS COMMENT	<i>y</i>)	
5UPPORT	SNUBBER	Holder	ACT	00	LOTTON HOTTON	AH	PET.H.
H51-274-09	11753	10	0230		Mod. By Field	1585	,510:
M51-344-00	9118	1/2	077		/	950	1010
MS1-345-0	11355	1/2	078	/		PSE 665	. U10
161-097-00 CEUF	10813	10	053		Mor. Ex FIELD	P\$14-1-	, 0107
RH 1-010-00 522K	10771	1	070	-		PSE 1190	1010' SA-1-17
241-016-76 522F	16920	3	070		Mod To RZ	SA-1-177 Mag	.010
522K-00	CONTRACTOR OF THE PROPERTY OF	3	AITO		Mod. To Re	SA-1-131 Med	,010
222F		1	071A	~	POWER PROPERTY AND ADDRESS OF THE PARTY AND AD	CPPA 54853	10/02
51×-019-03 435F	12018	1	135 A		Pavises Supposes	PSM-1-	10100
A35K		1/4	1350		4		,0101
581-000-01 555K	NAME AND ADDRESS OF THE OWNER, TH	3	079E		1	PSM-1	,0100
555K	NAME OF TAXABLE PARTY.	3	079E		1		10105
F 53 F	NAME AND ADDRESS OF THE OWNER, WHEN	3	ISIB		/	PSC/1-515	2,0100

		ABER	TION NUM	N IDENTIFICA	ATION	CALCUL	
PACE Z	CODE	OPTIONAL TASK	N NO.	CALCULATIO		DIVISION & GROUP	J.O. OR W.O. NO.
)	TOPES CE	BELETE	Pe-BHU	RET	PAI	
PETH	4	LOST	00	ACT	HODEL	SNUBBER	5UPPERT No
,004	0125	1		7	35	10159	511-029-053 132F
, 5/5	P5M.1.	MOD. BY FIELD		0478	10	4918	732K
, 010		\		0476	3	28453	511-031-071 53214
11-1-	NOT SUE!	_		014	1	14565	511-051-015 C42K
,010		HOLD		069	3	27974	511-072-003 532F
1.010	NOT STRETCH PER. MASTER TRACK	_		016	3	14486	511-087-016 C42F
.0/0"	PSE 840		/	N035	1/4	25611	A32F
1010	P5M-1- 5556	Bevises Summer Size		067W	0	5308	F33K
, 010°	PSE 840		~	0675	10	5306	F33F
5010	PS€ 840		/	0675	3	7/07	5W1-004-011 A 33F
1010	64. 1-155 MOD	MOD. To		0685	0	5300	F33F.
, 0103 54-1-155	CPPA 54921		/	0688	3	7055	54/1-011-027 = 33K
,0102	P>=/Y	1		068W	10	5329	5×11-012-023

		CALCUL	ATIO	N IDENTIFICA	TION NUM	ABER	×	
J.O. OR W.O. NO.	DI	VISION & GROUP		CALCULATIO	N NO.	OPTIONAL TASK	CODE P	AGE Z
		PAI	RET		BBET			
5UPPORT NO		SNUBBER	HODE	LEVEL	00	LOTTON NOTON	AH	.02-
F33F	9	7/29	3	0680	*	MOD. FIELD	1273 ben: 1.	,010
5W1-013-00 A33F	5	7/20	3	06830		PENSED PENSED	PSW-1- 1573	, 0/9
VA 1-005-03 C7216	0	21831	1	180		PENISED SAUGGEL SALE	PSM -1-	, 5/5
VAX-005-7 A73F	16	16483	3	178A		PENISSID SHUBBAR SIZE	PSM-1-	, 610
MPX-542-0 ASSF	04	17797	1	N042		MOD BY FELD	PSu.1.	, 010
-3 -3	œ3	19511	1/4	055A		Mon. To Ry	5A-1-165 MOD	, 010
ec-1-RB-09-	اوه	25095	1/4	OSSD		1	PSc/1.055b	s, c/0
-3	٥8	Control of the last of the las	1/2	055A	/		95E 341	.010
CC-1-R8-039A	- 009		1/4	5075			NO RIGED	.010
CS-1-RB-004-0	014	20357	1/4	045T	-		P SE 1536	.010 SA-1-16
CS-1-RB-004-0 -Z	17	34459	1/4	0457	-	X-94-CE	PSE 1536	, 0/6: SA1.16
Do-1-DG-007-0	0.11	28642	1/4	5143	CAMPONE SE C.		No Barco	,010
51/-1-58-004	B	15413	1/4	5197	1 304		No Record	10/0

INTEROFFICE CORRESPONDENCE

HTI-C

18 250

TO ROMON RACELIS

ABZ.

SUBJECT / REFERENCE / J.O. NO. /545405

T. GIN WALL /S. ALI

3GK

PARALLEL SNUBBERS.

MESSAGE: -

PLEASE REVIEW THE ATTACHED LIST OF

CONUMITY

PARALLEL SNUBBERS LAND INFORM US IF ANY OF

THESE SNUBBERS ARE DELETED, BY 5/19/87

5/11/87

T-Ginual / Lynd A. Ali K 1140
SIJNATURE TELEPHON

REPLY:

AS OF THIS DATE 5/13/87 THERE
ARE ONLY (2) SUPPORTS THAT WERE
DELETED ON UNIT 2. SEE ATTACHED
LIST.

5/13/87

R. Racelis

36/6 TELEPHONE

STONE & WEBSTER ENGINEERING CORPORATION 15274. NEC) CENY- 24.

CALCULATION SHEET

Page 26 0 F 27 ▲ 5010 65 CALCULATION IDENTIFICATION NUMBER J.O. OR W.O. NO. DIVISION & GROUP PAGE 6 CALCULATION NO. OPTIONAL TASK CODE SHUBBERS PAIRED ACT LOST PETCH = SNUBBER LEVEL HOTTON 5UPPORT Δ 0 102-07 NO 9 NO 5 IN IH 12680 UA-1-005-016 C92 K 10152 12697 VA-1-005-018 10373 10 101: 2 CAZK 21792 EW-2-094-404 FUNCTION CHANGE 15078 3 STRUT SHUBBER 10 SUZK 10102 26961 51-2-05/24/2 12700 16 C42K 10102 17 15891 51-2-051-418 . 20407 19 EYZK ,0102 20014 20 21 51-2-095-413 24649 3 22 CYZIC 18.02 24604 23 51-2-087-411 24 13012 25 10:02 C4210 26 20250 51-2-087-412 27 20171 28 542K 10.02 201960 29 30 51-2-087-417 20183 3 1 10102 CHEES 32 20640 33 51-1-098-403 4329 3 34 10/02 SHEKE 4339 35 51-2-088-409 36 20646 37 CYZK 1 = 102 20617 38 MODIFICO 51-2-088-410 2-680-477 39 482 40 10102 CYZK 6005 41 16467 31-2-306-426 42 12/0% 43 C42E __ .. 16471 45

19

CALCULATION SHEET (5452 . NZCL) - GENX - 24 CALCULATION SHEET

J.O. OR W.O. NO.	DIVISION & GROU	P	CALCULAT	ON NO.	OPTIONAL TASK	CODE	PAGE
	PAI	RET) SHO	BBEN	25		
5UPPORT No	SNUBBER	Holes	ACT	0	LOST	AH	F= 102
CC-1-239-007 C53K	34442	1/4					, e
CC-1-212-005	12024	1					1.61
CC-1-218-012	10752	1/4					10
C634	19294	1/4					
433K	26507	3					101
A43K	16525	3					1,41
CC-1-043-611 A43K	15987	3					, , ,
CC-1-045-017 A43K	4294	10					1
CC-1-156-002 A 53K	8359	3					10
CC-5-8110-100	11724	10					10
433F	14920	3		LET	ED PORT),: 11
522K	11997	3					. : 11
532K	15950	3					, : 10

Enclosure 1 Page 1 of 5 October 10, 1985

TEXAS UTILITIES GENERATING CO. (TUGCO) COMANCHE PEAK STEAM ELECTRIC STATION

LARGE BORE FIELD WALKDOWN REPORT

Prepared By

J. Oliver

J. J. Oliver Field Walk Task Leader

Reviewed By

R. R. Wrucke

Project Engineer

Approved

R. P. Klause

Project Manager

9703020047 870218 PDR ADDCK 05000445 A PDR 00013-1545405-N1

INTRODUCTION

A sample verification of existing unit 1 as-built documentation for large bore Class 2 and 3 piping systems was performed in accordance with Project Procedure CPPP-5. The purpose of this effort was to establish sufficient confidence in the adequacy of dimensions and functions shown on the as-built drawings to support initiation of the pipe stress requalification effort. This report summarizes the findings and conclusions of the verification effort.

This walkdown does not (and was not intended to) verify TUGCO's as-built program. However, the results of this walkdown tend to indicate that the as-built program implemented by TUGCO is adequate. Verification of the as-built program is within the scope of the Construction Adequacy Program (Appendix B of Comanche Peak Response Plan and Issue-Specific Action Plans). Each revision to piping system as-built documentation, resulting from all project activities (including the Construction Adequacy Program) will be evaluated by SWEC for specific impact on the piping requalification effort and the need to revise the applicable pipe stress and support package.

SCOPE

Four unique samples were randomly selected to verify the following attributes:

- (a) Valve Location
- (b) Pipe Support Location
- (c) Pipe Support Function
- (d) Valve and Support Orientation

These attributes were selected because they have the greatest potential for impact on the pipe stress effort. Other less significant attributes exist, but the methods of verifying the above attributes (distance from elbows, tees, valves, supports, etc.) indirectly verify other attributes (e.g., dimensions and configurations).

The total population and sample size for each attribute is shown on Attachment 1. The sample sizes and accept/reject criteria were determined from SWEC Quality Assurance Directive (QAD) 7.11 Rev. A.

SWEC tolerances were established for each attribute. These tolerances are consistent with tolerances previously used by SWEC on other as-built programs. The tolerances also consider the sensitivity of the data to the pipe stress analyses.

SUMMARY OF RESULTS

Approximately 1800 manhours were expended, over a period of three weeks, to complete the physical walkdown.

The results of the fieldwalk follow:

- Valve Location -. Valve locations are adequately described.
 Seventy-nine of the 80 valves were found to be within SWEC tolerances. Valve number 1-8107A was determined to be outside SWEC required tolerances. (See Attachment A)
- Pipe Support Location Pipe support locations are adequately described. Of the two hundred supports sampled, 199 were within SWEC tolerances. Pipe Support Number CT-1-014-405-C82K was determined to be outside SWEC required tolerances. (See Attachment B)
- Pipe Support Function All 200 of the pipe support functions are adequately described.
- Valve And Support Orientation Valve and support orientations are not adequately described. One hundred-ninety of the 200 supports and valves sampled were within SWEC tolerances. The following discrepancies were observed:

Valve/Support Number	As-Built Dimension	SWEC Tolerance	Actual Dim. By SWEC	Diff of As-Built Vs Actual	See Attachment	
AF-1-101-027-S63R	5°-31'	±5°	0.30	5.2°	С	
CS-1-155-036-S42R	00 .	±5°	6.3°	6.3°	D	
CS-1-217-002-A42K	00	25°	6.2°	6.2°	· E	
CS-1-258-702-A53R	0°	±5°	6.70	6.70	F	
CT-1-010-008-S22K	00	±5°	6.0°	6.0°	G	
CT-1-122-002-S32R	00	±5°	6.10	6.10	H	
SW-1-037-007-J03R	0°	±5°	7.00	7.00	I	
CC-1-007-043-A63R	00	±5°	6.00	6.0°	J	
1AF-055	45°	±5°	55.0°	10.00	K	
1CH-073	60°	±5°	35.0°	25.0°	L	

During the conduct of the walkdown there were only 16 items that were inaccessible. These items were replaced with other items, using the same random sample selection process used for initial sample selection.

CONCLUSIONS

1. The as-built documentation of pipe support and valve orientation is adequate to initiate the stress requalification effort. However, the stress results cannot be finalized until appropriate corrective action relative to verification of valve orientation and the orientation of pipe supports fabricated with catalog components is implemented. All instances where supports were not oriented within SWEC tolerances involved catalog components (i.e., struts or snubbers). The catalog components' paddles were misaligned with the clamps. No cases of misalignment were observed with box frame type supports (i.e. no catalog components.)

NOTE: A review of the sub-populations (supports with and without catalog components) was made to verify that a sufficient number of supports without catalog components were sampled. More than 70 of these supports were verified and all were within tolerance. Therefore, sufficient samples were reviewed to support the conclusion that the concern is limited to supports with catalog components.

Upon investigation of the discrepancies identified, SWEC discovered that two of the out of tolerance situations were previously identified by the TUGCO As-Built Group but are currently not resolved by the project.

ACTION REQUIRED

- 1.1 Orientation of all ASME valves that could cause eccentric loading on the pipe (e.g. motor operated valves, but not gate valves) should be verified. This effort should begin as soon as possible to minimize the impact on the requalification effort. SWEC will oversee this effort on an auditing basis.
- 1.2 Orientation of ASME pipe supports fabricated with catalog components should be reverified to identify and resolve all situations which exceed specified tolerances. Resolution of this concern in many cases will require rework of the supports to properly align the clamp and strut/snubber end paddle. SWEC will oversee this effort on an auditing basis.
- 1.3 The valve and support orientation concern shall be resolved. Appropriate preventive action should be taken to assure that the final as-installed condition is not changed in the future (e.g. during maintenance activities).
- 1.4 All TUGCO As-Built Group identified items, that have not been resolved by NCR or drawing revision, should be reviewed to determine the cause and extent of this concern and appropriate corrective and preventive action should be implemented.
- 2. The project implemented the same As-Built Program for all Class 1 piping, High Energy Class 2 and 3 small bore piping and all Class 2 and 3 large bore piping. Since the same program was implemented, the results of the large bore walkdown can be considered representative for all of this piping, provided the corrective action to be implemented includes all Class 1 piping and high energy Class 2 and 3 small bore piping. For those lines which were not as built in accordance with the large bore As-Built Program, a walkdown shall be performed to establish sufficient confidence in the accuracy of dimensions and support functions shown on the latest design documents to initiate the small bore stress requalification.

ACTION

2.1 TUGCO should identify the small bore stress problems that were not as-built in accordance with the As-Built Program. 2.2 SWEC will perform a walkdown for the piping identified by TUGCO. This walkdown shall be similar to the program described in Project Procedure CPPP-5, and this report.

COMMENTARY

In addition to the specific conclusions identified above, some engineering inferences about the adequacy of the as-built documentation (to support stress requalification) can be made. These inferences are:

- 1. All installed components are appropriately reflected on the as-built documentation. The location of supports and valves were verified by measurement to the next component (e.g., support, valve, fitting) installed within the system. No components, within the Class 2 and 3 stress systems, were observed to be installed but not identified on the drawings.
- 2. The piping and support configuration (layout and geometry) are appropriately described on the drawings. The method of verifying valve and support location (distance from elbows, tees, valves, supports etc.) indirectly verified the piping system dimensions and configuration.

Although one of the four attributes did not meet the established acceptance criteria, it is not necessary to perform any additional walkdowns for large bore piping prior to initiation of pipe stress analysis. This decision was based on the following judgements:

- All attributes with significant impact on analyses have been walked down.
- 2. The Construction Assessment Program will fully assess the adequacy of as-built documentation against the construction tolerances. Changes to the as-built documentation that affect pipe stress analysis and support designs will be fully evaluated by SWEC on an ongoing basis.

LARGE BORE FIELD WALKDOWN

POPULATION AND SAMPLE SIZE/SELECTION

I. Population/Sample Size


ATTRIBUTE	TOTAL POPULATION		SAMPLE SIZE	Source of Total Population			Accept/ Reject
Valve Location	913		80	Note	1		1/2
Support Location	3042		200	Note	2		5/6
Support Function Valve and Support	8042		200	Note	2		5/6
Orientation	8955		200	Note	3		5/6


- NOTE 1 List of valves developed by SWEC from review of BRP Drawings in SWEC Scope.
- NOTE 2 "As-Built-LBH-PROB-RPT" Computer listing of Comanche Peak Large Bore Supports sorted by Stress Package, dated 6-20-85.
- NOTE 3 Combination of both lists identified in Notes 1 and 2 above.


II. Sample Selection


The specific samples were selected as follows:


- Consecutive numbers (from 1 to the population size) were assigned to each item listed in the appropriate index (Notes 1, 2 and 3).
- Four sets of numbers (one set for each attribute) were selected from a random number table.
- The item (valve or support) corresponding to the random number was selected for the walkdown.



































MISCELLANEOUS OBSERVATIONS FROM LARGE BORE WALKDOWN

The following conditions outside the scope of CPPP-5 were observed during the walkdown effort.

- 1. Pipe support CC-X-109-016-A65R is a voided support but is still installed in the field. This support does not appear on the hanger location drawing BRHL-CC-X-AB-041. Upon investigation, this support was requested to be removed via a memo dated May 22, 1979. SWEC walked down 8 of the 32 supports listed on this memo and all were found to be removed as requested.
- 2. The strut for support CC-1-116-002-F33R is stamped as CC-1-159-017-S53R. Reference BRHL-CC-1-FB-001.
- 3. Support SW-1-129-046-A43R is shown correct dimensionally but is incorrect pictorially on BRHL-SW-1-AB-005. The support is shown as being located east of the tee; actually, it is located west of the tee.
- 4. Support CC-1-033-005-S33K The bottom two bolts on the south baseplate are not in full contact with the baseplate.
- 5. Support CC-1-204-019-C53R A 3/4" Ø stainless steel line appears to be in contact with the strut. A rod hanger for the 3/4" Ø line is disconnected from the pipe in this area.
- 6. Support CC-1-011-007-A53R Loose jam nut on strut.
- 7. BRP-BR-X-AB-005B Rev. 11 Valve is identified as 1-8564A on piping drawing but is tagged as 1-8564B. Valve 1-8564B is tagged as 1-8564A.
- 8. Support CT-1-011-005-S22K Items 11 and 12 are tube steel per revision 2 of drawing; however, original items 2 and 10 (W8x20) are still installed.
- 9. Support CT-021-001-S22R Bearing is loose in strut paddle on clamp end.
- 10. Drawing BRP-MS-1-SB-045, revision 1, incorrectly shows the elevation of valve IPS-063 at 887'-45/16". The elevation should be 877'-45/16".

(largebore) #1

STONE & WEBSTER ENGINEERING CORPORATION

STONE & WEBSTER ENGINEERING CORPORATION - NEW YORK



ONE PENN PLAZA 250 WEST 34TH STREET NEW YORK, NEW YORK

ACORESS ALL CORRESPONDENCE TO HOUSE TO NEW YORK NEW YORK 10116

OCT 14 1985

"ELE*-ONE 2 2 222 4220 ** "ELE* 1427 CABLE ADDRESS STOREBENG NEW 100*

JOHN W. BECK

Mr. John W. Beck Vice President Texas Utilities Generating Company 400 North Olive, L.B. 81 Dallas, Texas 75201

October 10, 1985

J.O. No. 15454 CPO-52

FIPING AND SUPPORT REQUALIFICATION PROGRAM COMANCHE PEAK STEAM ELECTRIC STATION, UNIT NO. 1

Large Bore Field Walkdown Report

Enclosure 2 Miscellaneous Construction Discrepancies Observed

Enclosure I describes the results of the walkdown of large bore piping conducted by SWEC in accordance with Project Procedure CPPP-5. conclusions of this report indicate that generic concerns exist that require consideration by the Comanche Peak Response Team (CPRT) and TUGCO Quality Assurance (QA). These concerns are summarized as follows:

- The orientation of valves and supports in piping systems are not correctly documented in the as-built documents. Expeditious resolution of this concern is necessary to preclude negative impact on SWEC's stress regualification schedule.
- Some items requiring correction which were identified during the as-built program have not been resolved.

We believe, with the commitment to resolve the above issues, the as-built program documentation is adequate to initiate stress requalification.

Enclosure 2 describes some construction discrepancies (e.g., loose bolts, strut/pipe lack of clearance) observed by the walkdown team. These discrepancies were not evaluated as part of the walkdown effort, and therefore should be resolved by CPRT and QA.

R. P. Klause

Proje t Manager

RPK:bif attachment

cc: J. B. George (TUGCO) - 1/1

R. L. Cloud (RCLA) - 1/1

J. C. Finneran (TUGCO) - 1/1

T. Snyder (TERA) - 1/1

TEXAS UTILITIES GENERATING CO. COMANCHE PEAK STEAM ELECTRIC STATION



IMPACT OF CONSTRUCTION
DEVIATIONS ON STRESS
REQUALIFICATION PROGRAM

PDR ADOCK 05000445



STONE & WEBSTER

J.O.Nos. 15454/15616 Report No. 15454-N(C)-010

Job Book R4.8

IMPACT OF CONSTRUCTION DEVIATIONS ON STRESS REQUALIFICATION PROGRAM

COMANCHE PEAK STEAM ELECTRIC STATION UNITS 1 AND 2

Prepared for

Texas Utilities Generating Company

by

J. Henderson M. J. Shah

December 15, 1785

Project Engineer - Unit 1

Colorsus.

Project Engineer - Unit 2

Project Kanager

Stone & Webster Engineering Corporation Cherry Hill Operations Center Cherry Hill, New Jersey

TABLE OF CONTENTS

Section	<u>Title</u>	Page
	SUMMARY	ii
1.0	INTRODUCTION	1
2.0	PURPOSE	1
3.0 3.1 3.2	REVIEW METHODS DEVIATION REPORTS DETAILS OF THE REVIEW	2 2 2
4.0	RESULTS OF THE REVIEW	2
5.0	DISCUSSION OF RESULTS	3
6.0	CONCLUSIONS	6
7.0	REFERENCES	7
TABLE 1	SUMMARY OF DEVIATION REPORTS	
TABLE 2	SUMMARY OF ISSUES	
TABLE 3	LINEAR DIMENSION/LOCATION DEVIATIONS	
TABLE 4	MAGNITUDES OF PIPING/SUPPORTS LINEAR DIMENSION DEVIATIONS	
TABLE 5	MAGNITUDES OF SUPPORTS/RESTRAINT LOCATION DEVIATIONS	
ATTACHMENT 1	A TYPICAL DEVIATION REPORT	
ATTACHMENT 2	LOG OF DRs	
ATTACEMENT 3	EVALUATION SHEET	
ATTACHMENT 4	RESULTS OF THE REVIEW	

SUMMARY

Deviation reports (DRs) generated by the Evaluation Research Corporation (ERC) were evaluated by Stone & Webster Engineering Corporation (SWEC) for potential impact on SWEC's Stress Requalification Program (SRP) (Reference 7.1). Approximately 800 DRs related to the piping systems and supports were reviewed for this effort. The review confirmed the need to address clearances between piping and adjacent components/structures on a plantwide basis, as committed to in Section 7.2 of CPPP-6, Revision 2 (Reference 7.2). It also indicated the need to conduct a Hardware Validation Program (HVP), as recommended in Section 8 of L. S. Wigley's July 1986 report on Assessment of TUGCO's As-Built Documentation for Piping and Pipe Supports (Reference 7.3).

It was concluded that the concerns on clearances and other hardware problems do not impact the SWEC requalification program directly, and there is no need to change the stress requalification program or procedures to address the ERC-generated deviation reports on a specific or generic basis.

1.0 INTRODUCTION

The Construction Adequacy Program (CAP) is sponsored by the Comanche Peak Response Team (CPRT) of Texas Utilities Generating Company (TUGCO) to perform an independent reinspection of safety systems. Evaluation Research Corporation (ERC) has been contracted to perform this reinspection of the safety-related components on a sampling basis (Section 2.2 of Reference 7.4).

Each apparent construction deviation from the design drawing is identified by ERC and documented as a Deviation Report (DR).

The safety significance of these DRs in relation to reportability in accordance with 10CFR50.55(e) is continuously being evaluated by TUGCO. To determine the trends and adequacy of the sample size, ERC is also reviewing the DRs.

Concurrent with SWEC's Stress Requalification Program (SRP), TUGCO requested SWEC to evaluate independently the effects of the piping and pipe supports-related DRs on the SRP. SWEC was requested to develop a program to identify trends, if any, and make changes in the procedures, if necessary, to minimize the impact of these DRs when they are incorporated later into the as-built packages. Details of the SWEC program are as outlined in CPPP-18 (Reference 7.1).

2.0 PURPOSE

The purpose of this report is to describe the results, methods, and conclusions of SWEC's evaluation of the DRs for possible impact on the SRP. Deviations are categorized and discussed to identify the actions proposed. The review was limited to the ERC-DRs which were generated using following procedures:

- QI-019 Reinspection of Small Bore Pipe Supports (SBPS)
- QI-021 Reinspection of Piping System Bolted Joints/Material (PBOH)
- QI-025 Reinspection of Large Bore Pipe Configuration (LBCO)
- QI-026 Reinspection of Small Bore Pipe Configuration (SBCO)
- QI-027 Inspection Procedures for Large Bore Supports Rigid (LBSR)
- QI-029 Inspection Procedures for Large Bore Pipe Supports Nonrigid (LBSN)
- QI-048 Reinspection of Small Bore Welds/Material (SBWM)
- QI-049 Reinspection of Large Bore Piping Weld/Material (LBWM)
- QI-051 Reinspection of Whip Restraints (PWRE)
- QI-070 Reinspection of Tubing Welds/Material (TUWM)

3.0 REVIEW METHODS

This section describes details of the review methods used to evaluate the DRs for possible impact on the SRP. Section 3.1 addresses generation of the DRs by ERC, while Section 3.2 discusses the details of the review and the manner in which the review results were documented.

3.1 DEVIATION REPORTS (DRs)

The inspection procedures listed in Section 2.0 provide a set of criteria for inspection of various components of construction, defined as population groups. Inspections were performed on each of the population groups on a sampling basis and DRs were generated when the as-built condition deviated from the requirements of design drawings and specifications.

A typical DR is shown as Attachment 1 to this report. Like from the following population groups were reviewed to determine the impact on the SRP:

LBCO: Large Bore Piping Configuration SBCO: Small Bore Piping Configuration LBSR: Large Bore Pipe Supports - Rigid LBSN: Large Bore Pipe Supports - Monrigid

PWRE: Pipe Whip Restraints SBPS: Small Bore Pipe Supports

PBOM: Piping System Bolted Joints/Materials

TUWH: Tubing Welds/Materials

SBWH: Small Bore Piping Welds/Materials LBWH: Large Bore Piping Welds/Materials

3.2 DETAILS OF THE REVIEW

The DRs for each of the population codes were obtained from ERC and a file was created. A log of all DRs (filed in Job Book R4.25, SWEC Evaluation of ERC Deviation Reports) in a population code also was prepared (Attachment 2). Table 1 provides the number of DRs that were reviewed for each population code.

Each DR was reviewed and classified as Category A, B, or C. Category A DRs include the deviations that have a potential impact on the design of the piping system and/or pipe supports. Category B DRs are hardware-related and thus will not affect the qualification methodology for the piping/pipe supports analysis. Category C DRs are neither design-nor hardware-related and do not require further evaluation for impact on the SRP. A categorization of DRs for each population code is given in Table 1.

4.0 RESULTS OF THE REVIEW

Results of the review for each DR were documented in a form shown in Attachment 3. Types of issues identified as a result of the review of DRs for each population code are summarized in Attachment 4. Table 2 provides a summary of issues and the number of DRs for each population code.

5.0 DISCUSSION OF RESULTS

It can be seen from Table 1 that approximately two-thirds of the deviations are Category A, while approximately one-third of the deviations are Category B. The number of Category C deviations is insignificant. As explained earlier, Category B deviations are hardward-related and do not affect the input to the SEP. The majority of Category B deviations are Items 7 through 11 in Table 2 and include missing locking devices, missing washers, paint on spherical bearings, clamp halves not parallel, and gaps greater than the smallest shim in rear brackets of snubbers. Significance of these deviations on the construction adequacy of the piping and pipe support systems has been assessed by the ERC under its Construction Adequacy Program and recommendations have been used or will be made by ERC to correct these deviations identified as construction deficiencies. L. S. Wigley also has recommended a program called Eardware Validation Program (HVP) as a part of the assessment of TUGCO as-built documentation for piping and pipe supports (Reference 7.3). Therefore, Category B deviations are not addressed further in this report.

Category A deviations identified in Table 2 as Items 1 through 6 and Item 12 are discussed below in detail.

Item 1 Locations/Dimensions Out-of-Tolerance

These deviations relate to the linear dimensions of piping/pipe supports and locations of pipe supports. Linear dimensions relate to the configuration/geometry of piping systems and supports and, if significant, may affect the stress analysis results. Of 136 total deviations for this item, 109 deviations are in the area of linear dimensions, while 21 deviations are related to the support locations. The remaining 6 deviations are in the area of elevation and bend radii of piping systems.

Details of the number of deviations for linear dimensions, support/ restraint locations, and miscellaneous areas for various population groups are given in Table 3. Tables 4 and 5 provide details on the magnitudes of these deviations. Potential impact of these deviations on the stress analysis of piping systems is discussed below.

Linear Dimensions

In the piping configuration groups of LBCO and SBCO, 47 deviations out of a total of 50 deviations are less than 12 inches. These deviations in configuration of the piping represent small percentage changes in dimensions. Effects of these small changes on the stresses in piping systems and support loads would be small. Therefore, no further action is required to address these deviations.

The remaining 3 deviations (1 ft - 4 1/2 in. and 4 ft - 8 3/4 in. and 1 ft - 0 1/2 in.) are isolated cases and will be evaluated in the SRP.

In the pipe support/restraint population groups of LPSR, LBSW, SBPS, and PWRE, 50 out of a total of 59 deviations have linear dimension deviations of less than 3 in., six deviations (6 out of 59) are in the 3- to 6-in. range, and the remaining three deviations are between 7 in., 8 in., and

and 1 ft - 0 1/16 in. Fifty-six deviations less than 6 in. are related to bolt hole locations, base plate dimensions, pin-to-pin dimensions of struts, and geometry of support frame members being out of tolerances. These deviations represent small percentage changes in dimensions with no appreciable effects on the stress analysis results.

The other three deviations are as follows: 0 ft - 7 in. deviation is related to support I-beam located 7 in. above the required elevation. This changes the required rod length only and does not affect the design capacity of support components. The 8-in. deviation is in the required distance of 7 ft - 8 11/16 in. between the centerline of pipe and top of rear bracket of strut. This does not affect the capacity of support components adversely and thus is not significant. The remaining deviation of 1 ft - 0 1/16 in. is in the dimension between the centerline of tube steel support member and the the centerline of base plate. The ERC-SSE Group has reanalyzed the support with the revised geometry and found the support to be acceptable. Based on the above discussion, it is concluded that these deviations are insignificant and changes in the SRP are not required.

Support/Restraint Locations

Mine of the 21 DRs in this group are in the area of rupture restraints and thus do not affect the SRP. The remaining 12 DRs relate to the deviations in support locations. Ten of these deviations are less than 6 in., and two deviations are 9 in. and 9 1/8 in. These deviations are small and thus have no appreciable effect on the stress analysis of a piging system.

The remaining six deviations were in the areas of pipe elevations and bend radii with no adverse trend. Therefore, no impact on SRP is . . expected.

Item 2 Welds Missing, Undersized, or Underlength

A total of 113 deviations in this item were in the area of supports and restraints as shown in Table 2 and were related to the missing, undersized, or underlength welds.

The majority of these deviations were in the area of undersized welds (1/16 in. to 1/8 in.) over a small portion of the total welds length and thus would not reduce the overall strengths of the connections. It should be noted that the recent changes in the acceptance criteria of welds (Reference 7.6) allow 1/16 in. undersized weld for one-fourth of the weld length. This is based on computation of the reduced shear area due to undersized welds and limiting the reduction in the shear area percentage to reasonable values. Moreover, ERC has performed structural adequacy evaluation of the deviations for as-built weld configurations of individual supports/restraints and has concluded that support/restraint capacity is not affected significantly. Therefore, these deviations do not require further evaluation for impact on the stress requalification program.

Item 3 Clearance Violations

There were 82 deviations where small bore and large bore piping clearances were less than those required by the piping erection specification. The clearances are among pipe-to-pipe, pipe with wall penetration sleeves, and pipe with hangers, walls, handrails, etc. A final walkdown will be performed by SWEC at the completion of the stress requalification effort to verify that sufficient clearance exists between the piping systems and the adjacent structures (Section 7.2 of Reference 7.2). Therefore, no additional action is required.

Item 4 Anchor Bolt Violations

Of a total of 33 deviations in this item, 10 deviations were related to the depth of embedments being smaller than required, 9 deviations were in the area of minimum spacing requirements, and the remaining 14 were miscellaneous deviations. Embedment depths were shorter by a minimum of 0.125 in. for a required embedment of 6 1/2 in. to a maximum of 1.81 in. for a required embedment of 7 1/2 in. Spacing violations ranged from 0.125 in. of a required minimum of 5 5/8 in. to 4.75 in. for a required minimum spacing of 14 3/4 in. These violations have been evaluated by ERC on an individual basis using the reduced strengths of these bolts for smaller and overlapping shear cone capacities and found to be acceptable. Additionally, the number of cases is less than 5 percent with no adverse trend. Therefore, additional effort is not required in this area.

Item 5 Gaps in Connections and Supports

There were 25 deviations in pipe supports and 36 deviations in rupture restraints where either supports and piping had gaps which did not meet the design requirements or connections were not tight and mating surfaces did not bear at all locations.

A total of 25 DRs in pipe support population groups of LBSR and SBPS have gaps between piping and support frames/restraints which deviate from the required gaps by a minimum of ±1/32 in. to a maximum gap of +1/16 and -1/4 in. As a part of the SRP, the project has redefined the gap requirements for box frames and is reshimming the gaps to meet the revised requirements of Attachment 4-11 of CPPP-7 (Reference 7.5). Therefore, no further action is required to address these deviations.

The remaining 36 deviations are in the population group PWRE of rupture restraints. Since these deviations do not relate to the efforts of the SRP, they are not addressed further in this report.

Item 6 Richmond Inserts - Thread Engagement Less Than Minimum

There were a total of 28 deviations for pipe supports and restfaints where thread engagement in Richmond inserts or of bolts into nuts was less than minimum. A total of 18 deviations in pipe support population groups of LBSR and LBSN and 2 deviations for pipe rupture restraint (PWRE) are for the Richmond inserts where thread engagement, for 1 1/2-in.-diameter inserts are less than minimum of 3 1/8 in. The deviations range from 1/16 in. to 1 7/8 in. The remaining 8 deviations in

pipe rupture restraint population group PWRE have nuts which do not engage bolts fully. Capacities of these connections with thread engagement less than the minimum need to be established through analysis and/or testing. This issue is being addressed under the CPRT program for Issue ISAP V.b - Improper Shortening of Anchor Bolts in Steam Generator Upper Lateral Supports, and testing is planned. After the allowable capacities of these and other similar inserts are established through analysis/testing, structural adequacy of these connections should be evaluated to determine the need for any required modifications. No action is required at this time.

Item 12 Miscellaneous Deviations

Thirty-one out of 89 deviations in this category were related to either wrong items installed or missing items. These deviations are hardware-related and thus would be addressed under the HVP. The remaining 58 deviations relate to miscellaneous areas such as gap behind base plates (5), gouges due to grinding (4), angularity out of tolerance (4), gap between pipe and supports greater than tolerance (14), thread engagement in strut rods (9), and other miscellaneous items of specific nature. These deviations are small in number and do not have any generic implications on the stress requalification program. They also have been addressed by ERC on a specific basis and thus do not require any further action for the SRP.

6.0 CONCLUSIONS

Based on the discussion in Section 5.0, it is concluded that approximately one-third of the construction deviations are hardware related and should be corrected under the Eardware Validation Program. The other two-thirds of the deviations are related to six different items.

Item 1 is related to deviations in locations of supports and/or restraints and piping/supports linear dimensions out of specified tolerances. Magnitudes of deviations were evaluated, and it was concluded that the deviations do not show any trend and are not significant. Therefore, generic changes in the SRP are not required.

Item 2 is related to missing, undersized, and underlength welds where the majority of deviations were related to welds being undersized from 1/16 in. to 1/8 in. over a small portion of weld lengths. The overall strengths of these welds are not reduced significantly and therefore do not require a generic change in the SRP.

Item 3 is related to clearances between piping to piping and other components. A final walkdown will be performed by SWEC to resolve this item.

Item 4 is related to anchor bolts where the depth of embedments and the spacing did not meet the design requirements. These deviations have been evaluated and accepted by ERC using reduced strengths of the anchor bolts. There was also no adverse trend. Thus, no change in the SRP is required.

Item 5 relates to gaps in connections and gaps between piping and supports, and is being addressed by TUGCO as a part of the Hardware Validation Program.

Item 6 relates to inadequate thread engagement for Richmond inserts and is addressed as a part of the CPRT Issue Specific Action Plan (ISAP) V.b, where testing is planned to determine the capacities of inserts with inadequate thread engagement. No further action can be taken in the SRP at this time.

It is concluded, therefore, that there is no need to change the stress requalification program or procedures to address the ERC-generated deviation reports on a specific or generic basis.

7.0 REFERENCES

- 7.1 Comanche Peak Project Procedure CPPP-18, Procedure for Evaluation of ERC Deviation Reports, Revision 1, dated November 7, 1986
- 7.2 Comanche Peak Project Procedure CPPP-6, Pipe Stress/Support Requalification Procedure, Revision 2, dated April 18, 1986
- 7.3 Assessment of TUGCO As-Built Documentation for Piping and Pipe Supports, Final Report, dated July 2, 1986, L. S. Wigley
- 7.4 Safety Evaluation Report Related to the Operation of Comanche Peak Steam Electric Station, Units 1 and 2, NUREG-0797 Supplement No. 13, U.S. Nuclear Regulatory Commission, dated May 1986
- 7.5 Comanche Peak Project Procedure CPPP-7, Design Criteria for Pipe Stress and Pipe Supports, Revision 2, dated April 25, 1986
- 7.6 Visual Weld Acceptance Criteria for Structural Welding at Nuclear Power Plants, Revision 2, May 7, 1985, Nuclear Construction Issues Group, Southern Company Services, Birmingham, Alabama

TABLE 1
SUMMARY OF DEVIATION REPORTS

Population	No. of DRs	No. of		Category	
Code	Reviewed	Deviations	Ā	B	<u>c</u>
LBCO	61	74	64	10	0
SBCO	71	79	76	1	2
LBSR	154	174	96	67	11
LBSN	205	208	98	103	7
PWRE	212	225	136	88	1
SBPS	66	70	43	15	12
PBOM	11	11	4	6	1
TUWH	8	8	6	0	2
SBWM	1	1	1	0	0
LBWM	_3	_3	<u>·3</u>	_0	_0
Total	792	853	527	290	36
Percent		100	61.8	34.0	4.2

TABLE 2
SUMMARY OF ISSUES

Deviation					No. o	of DRs i	n Popul	ation					
Issue	Category	LBCO	SBCO	LBSR	LBSN	PWRE	SBPS	PBOH	TUMH	SBWH	LBWH	Total	Percent
1. Locations/dimen out of tolerance		23	33	20	20	30	10	0	0	0	0	136	16.0
Welds missing, sized, or under		0	0	26	. 34	36	21	0	5	1	0	113	13.2
3. Clearance viola	tions A	39	43	0	0	0	0	0	0	0	0	82	9.6
4. Anchor bolt vio	lations A	-	-	8	13	2	6	0	0	0	0	29	
	В	-	-	1	_	2	0	0	0	0	0	3	3.9
	С	-	-	0	-	1	0	0	0	0	0	1	3.9
Gaps in connect supports	ions and A	-	-	11	0	36	14	0	0	0	0	61	7.1
6. Richmond insert	s - A	-	_	13	5	9	0	0	0	0	0	27	
Thread engagement than the minimum				-	5	1	0	-		-	-	1	3.3
7. Locking devices missing	В	-	-	3	14	12	6	0	0	0	0	35	4.1
8. Washers missing covering boltho		-	-	0	0	26	0	0	, 0	0	0	26	3.0
9. Paint in spheric bearings for sm		-	-	16	25	0	2	0	0	0	0	43	5.0
10. Clamp halves not parallel	В	-	-	14	18	0	3	0	0	0	0	35	4.1

1802A-1545405-HC4

Deviation					No. o	f DR. i	n Popul	.tion					
Issue	Category LBCO SBCO	LBCO	SBCO	LBSR	LBSN	PWRE	PURE SBPS PBOM	PBOH	TIM	SBW	LBW	Total	Percent
11. Gaps > smallest shim	-		•	14	91	0	0	0	0	0	0	30	
for snubber	3	•	•	1	-	0	9	0	0	0	0	- 1	3.6
12. Miscellaneous devia-	<	2	0	18	26	33	2	4	-	0	•	80	
tions	60	10	-	19	30	37	4	9	0	0		107	26 9
	S	0	2	=	9	0	12	-	2	0	0	34	
		F	1	1	-	-	1	1	1	1	1	1	
TOTAL		14	19	174	208	225	70	=	80	-	3	853	

TABLE 3

LINEAR DIMENSION/LOCATION DEVIATIONS

	No. o	f Deviations in the A	rea of	
Population Group	Linear Dimensions	Support/Restraint Locations		Total DRs
LBCO	21	0	2	23
SBCO	29	0	4	33
LBSR	16	4	0	20
LBSN	15	5	0	20
PWRE	21	9	0	30
SBPS		_3	<u>o</u>	_10
Subtotal	109	21	6	136

Total: 136

TABLE 4

MAGNITUDES OF PIPING/SUPPORTS LINEAR DIMENSION DEVIATIONS

Population		Magnitudes	of Deviations	(Inches)	
Group	Total DRs	0-3	3-6	6-9	Greater Than 9
LBCO	21	15	5	1	0
SBCO	29	8	16	•	5 (Deviations of 1 ft - 4 1/2 in., 1 ft - 0 1/2 in., 0 ft - 10 in., 4 ft - 8 3/4 in. 1 ft - 0 in.)
LBSR	16	12	3	1	0
LBSN	15	11	2	1	1 (Deviation of 1 ft - 0 1/16 in.)
PWRE	21	20	1	0	0
SBPS		_7	_0	0	<u>o</u>
TOTAL	109	73	27	3	6

TABLE 5

MAGNITUDES OF SUPPORTS/RESTRAINT LOCATION DEVIATIONS

Population		Magnitudes o	f Deviations	(Inches)	
Group	Total DRs	0-3	3-6	6-9	Greater Than 9
LBCO	0	0	0	0	0
SBCO	0	0	0	0	0
LBSR	4	3	1	0	0
LBSN	5	1	2	2 (0'-	
PWRE	9	8	1	0,-9	1/8")
SBPS	_3	_3	0	<u>o</u>	<u>o</u>
TOTAL	21	15	4	2	0

ATTACEMENT 1

	A TYPICAL DEVIATION REPO	
	Commenche Peak Response Te. ERC Deviation Report (DR	
OR NUMBER	- ORIGINATOR -	DATE
I-M- 58CD . 026-1	10. d.	
DESTIFICATION OF ITE	Dain Char	9-29-35
WE +2-64-X-136-152-		CHII
		ONE THO F CONSEN
STATES AND LOCATION	1	
WASTE PRICESING LA	•	.VA 355 3555
		TUGGO DISTECTOR
ex occi	34 3 (1944)	TUGGO ENSPECTION DATE
157'-6"		TUGGO DISPECTION DATE
LOUISMAN (DICEPTE O	FECTIST ITEM NO.)	
1-025 ENO SET	ON 15.2 162, STATES IF THE	LINE IS LETS THAN ZOC"
pedation temp. A or	he wer minimum cutionice	INCLUDING NEWLYEN
אטן אל אפוניקאנינע	<u> </u>	
יצי שניוום כמודפאפון	דם דאב אפנטב צבינובביים	INT, THERE IS A
CLEREANCE OF YET	1/2 West BETWEEN THIS LINE	EANA ANGTHE Z IN LINE
WELL ATTON TO-THE	LUTION . IT STARTS AT THE	NOTE OF THE LILE
'T' DOW THE T	E AND BUNS POR 647", 3	
	T 45° ELBOW AND RULS FO	Z FL TH
HE SOUTHERN HO	الم مسلم عدم عمد حمد الم	-3-2",
מים סא חיבו	DENG (INC. DE TETTETEMEN AND	150077.70)
,		
district and the second		
166 0		
michely	8.29-85	
TRST LEVIEWER	DATE ORIGINAT	OR DATE
		3
ALD DE TESTA	O-(INCLUDE -USTIFICATION'AS AN	00777
01-020 Per.	o regimes a min. Elea	uauce & L -
- menden - 1140	ation Sur this Mana	are was not transton
dus DR is col	iel	
Complete and the complete of t		
SIEG ATTE		
71/C 75- V.SC	- () · 6 · 8 pm	
	A	7.77
SECOND REVIEWED	DATE ORIGINAT	OR DATE

COMANCHE PEAR . REVIEW OF ERC - DRs FOR SRP

	CATEGORY		TYPE OF	F DEVIATION	GENERIC RESOLUTION		
. NO.	A	BC	CODE	DESCRIPTION	ITEM	REMARKS	
					and the later of t		
	-						
			and the sales				
					- -		
	-	+ +					
	1						
	1						
				H. H. T.	NY III YE		
	1						
		1 1					
	1						
			1 1 7 1				
	-						
					A CATALON AND		
		-		-			
Management	1						
		l i					
		1	111-11				
	-						
	-	-	1				
					-		
						No.	
		1			1		

ATTACHIENT 3

COMANCHE PEAK STEAM ELECTRIC STATION PIPING - PIPE SUPPORTS ERC DEVIATION REPORT (DR) EVALUATION SHEET

DR No.		System	Berger de la		
Reference:					
BRP		BRH_			
BRHL		GHH			_
SWEC SRP Stress	Problem No.				
		O Unit 2	C Common		
	M-	S-			
Categorization:	(1) Deviation R	equires Drawing Change?	V	V-	
	(7) Detri arion A	ffacts CDD Calaulastan	**	No	-
Yes on Question	s (1) and (2)		C	-	_
Yes on Question	(2) Only		Category	В	0
,	lude justificatio				_
					_
					_
					_
				(Date	e)
Reviewed by:				(Date	•)

ATTACHMENT 4

RESULTS OF THE REVIEW

I.	Population Code IM-LBCO			
II.	Number and Category of DRs Reviewed	61		
	Category A 64 Category B 10	Category	C O Tota	1 74
III.	Issues Identified			
	Description	Numbers	Category	Item in Table 2
1.	Pipe to pipe clearance	18		3
2.	Linear dimension out of tolerance	10	A	1

		-	-	-
1.	Pipe to pipe clearance	18	- A	3
2.	Linear dimension out of tolerance	10	A	1
3.	Out-of-location to' rance	11	A	1
4.	Pipe-to-support clearance	10	A	3
5.	Pipe-to-conduit or cable tray clearance	5	A	3
6.	Pipe-to-sleeve clearance	4	A	3
7.	Valve installed backwards	3	В	12
8.	Material installed wrong or missing	2	A	12
9.	Elevation out of tolerance	2	A	1
10.	Flow element installed backwards	3	В	12
11.	ID problems	1	В	12
12.	Expansion joint out of tolerance	1	В	12
13.	Missing jam nut on tie bar	1	В	12
14.	Flow arrow on valve missing	1	В	12
15.	Pipe-to-wall clearance	2	A	3

RESULTS OF THE REVIEW

I. Population Code IM-SBCO

II. Number and Category of DRs Reviewed 71

Category A 76 Category B 1 Category C 2 Total 79

	Description	Numbers	Category	Item in Table 2
1.	Pipe-to-pipe clearance	27	- A	3
2.	Linear piping dimension out of tolerance	18	A	1
3.	Out-of-location tolerance	11	A	1
4.	Pipe-to-support clearance	7	A	3
5.	Valve clearance	4	A	3
6.	Pipe-to-sleeve clearance	3	A .	3
7.	Elevation out of tolerance	3	A	1
8.	Pipe-to-cable tray clearance	2	A	3
9.	Valve installed with flow arrow reversed	1	В	12
10.	Pipe bend greater than tolerance	-1	A	1
11.	Conflict in valve identification	1	С	12
12.	Missing identification	1	c	12

I.	Population Code	IS-LBSR			
II.	Number and Categ	ory of DRs Reviewed	154		
	Category A 96	Category B 67	Category C	11 Total	174

	Description	Numbers	Category	Item in Table 2
1.	Weld missing, undersized, or under- length	26	A	2
2.	Anchor bolt violations	8	- A B	4
3.	Member or plate out of tolerance	16	A	1
4.	Paint on spherical bearings	16	В	9
5.	Class halves out of parallelism	14	В	10
6.	Miscellaneous deviations	6 5 1	A B C	12
7.	Gaps between pipe and supports	11	A	5
8.	Thread engagement problems (strut assemblies) and nut threrads	1 7	A B	12
9.	Gap on brackets ≥ smallest shim	14	В	11
10.	Mark identification problems	8	С	12
11.	Wrong item installed	2 2	A B C	12
12.	Gap behind base plate	4	A	12
13.	Locking devices missing or broken	3	В	7
14.	Angularity out of tolerance	3	A	12
15.	Support locations out of tolerance	4	A	1
16.	Cotter pin broken, missing, etc	4	B	12
17.	Missing items	1	В	12
18.	Thread engagement - Richmond inserts	13	Α ,	6

- I. Population Code IS-LBSN
- II Number and Category of DRs Reviewed 205

Category A 98 Category B 103 Category C 7 Total 208

	Description	Numbers	Category	Item in Table 2
1.	Weld missing, undersized, or under- length	34	A	2
2.	Paint on spherical bearings	25	. 3	9
3.	Clamp halves out of parallelism	18	В	10
4.		16	B	11
5.	Anchor bolt violations	13 1 1	A B C	4 12 12
6.	Member or plate out of tolerance	15	A	1
7.	Miscellaneous devistions	7	A B	12 12
8.	Mark identification problems	. 9	B	12
9.	Wrong item installed	8 5 2	A B C	12 12 12
10.	Locking devices missing	10	В	7
, 11.	Thread engagement problems - Richmond inserts	5	A	6
12.	Missing items	4 2	A B	12 12
13.	Beveled washer missing (slope >1:20)	4	В	7
14.	Angularity out of tolerance	1 3	A B	12
15.	Support location out of tolerance	5	A	1
16.	Cotter pin broken, missing, etc	4	В	12
17.	Thread engagement problems - threaded rods	6	A	12

	Topication code 13	TWILE			
II.	Number and Category	of DRs Reviewed	212		
	Category A 137	Cat gory B	88 Category C	1 Total 226	
TTT	Tanuar 71			_	

	Description	Numbers	Category	Item in Table 2
1.	Welds missing, undersized, or under- length, wrong type or location	36	٨	2
2.	Gaps in bolted connections	26	A	5
3.	Members or place out of tolerance	21	A	1
4.	Identification missing	18	В	12
5.	Wrong or extra material installed, or missing materials	11 6	Â B	12
6.	Washers missing or do not cover hole	15	В	8
7.	Locking devices missing	12	В	7
8.	Gap between pipes and supports > tolerance	14	٨	12
9.	Beveled washers missing	iı	В	8
10.	Lack of full thread engagement	9	A B	6
11.	Shims do not cover 100 p :cent of mating surfaces	10	В	5
12.	Location out of tolerance	10	A	1
13.	Miscellaneous deviations	5	A B	12
14.	Cotter pin problems	5	В	12
15.	Anchor bolt violations	2 2 1	A B	4
16.	Shim stacks not welded	3	8-	12
17.	Gauges due to grinding	2	A	12
18.	Gap behind base plate	1	۸ ,	12

- I. Population Code IM-SBPS
- II. Number and Category of DRs Reviewed 66

 Category A 43 Category B 15 Category C 12 Total 70
- III. Issues Identified

	Description	Numbers	Category	Item in Table 2
1.	Gaps at deadweight supports	14	A	5
2.	Weld missing, undersized, or under- length	11	. A	2
3.	Identification problems	8	c	12
4.	Anchor bolt violations	6	A	4
5.	Support dimensions > tolerance	6	A	1
6.	Material missing or wrong	1 2 2	A B C	12
7.	Locking devices missing	6	В	7
8.	Location of support > tolerance	4	A	1
9.	clamp halves out of yarallelism	3	В	10
10.	Base plate has 1/4 indiameter x 1/4 in. holes	2	С	12
11.	Spherical bearing is painted	2	В	9
12.	Miscellaneous deviations	1	A B	12
13.	Thread engagement less than the minimum required (strut assembly)	1	В	12

- I. Population Code IM-PBOM
- II. Number and Category of DRs Reviewed 11

 Category A 4 Category B 6 Category C 1 Total 11

	Description	Numbers	Category	Item in Table 2
1.	Nuts are not tight	5	В	12
2.	Stud is not one thread higher than nut	2	. A	12
3.	Capscrews installed instead of stud	1	A	12
4.	Gasket wrong color code	1	A	12
5.	No identification on flange	1	С	12
6.	Gasket does not cover flange	1	В	12

I. Population Code SBWM

II. Number and Category of DRs Reviewed 1

Category A 1 Category B O Category C O Total 1

III. Issues Identified

Description Numbers Category Table 2
Undersized weld 1 A 2

I.	Population	Code IM	-TUWH				
II.	Number and	Category	of DRs Reviewed 8				
	Category A	6	Category B O Category	c	2	Total	8

	Description	Numbers	Category	Item in Table 2
1.	Undercut on welds	3	A	2
2.	Wrong identification of weld	2	c	12
3.	Undersized welds	2	A	2
4.	Gouges due to grinding	1	A	12

Ι.	Population	Code IM	LBWM				
II.	Number and	Category	of DRs Reviewed 3				
	Category A	3	Category B O Category	С	0	Total	3

	Description	Numbers	Category	Item in Table 2
1.	Rust on strinless steel pipe	1	A	12
2.	Gouging due to grinding	1	A	12
3.	Weld shrinkage	1	A	12

TABLE 1
SUMMARY OF DEVIATION REPORTS

Population	No. of DRs	No. of		Category	
Code	Reviewed	Deviations	Δ	В	<u>c</u>
LBCO	61	74	64	10	0
SBCO	71	79	76	1	2
LBSR)34	174	96	67	11
LBSN	205	208	98	103	7
PWRE	212	225	136	88	1
SBPS	66	70	43	15	12
PBOM	11	11	4	6	. 1
TUWM	8	8	6	0	2
SBWM	1	1	1	0	0
LBWM	_3	_3	_3		_0.
Total	792	853	527	290	36
Percent		100	61.8	34.0	4.2

CONSTRUCTION ASPORTS

LUCALITY CONSULTING

ENGINEERING

July 2, 1986

STONE & JEBSTER ENGINEERING JORPORATION



245 SUMMER STREET, BOSTON, MASSACHUSETTS

ADDRESS CAL CORRESPONDENCE TO P.O. BOX 1315. BOSTON. MA 02107

BOSTON
NEW YORK
CHERRY HILL N J
DENYER
HOUSTON
DALLAS
PORTLAND OREGON
RICHLAND WASHINGTON D C

1 1 - low 29.1

Mr. Larry D. Nace Vice-President, Engineering/Construction

Texas Utilities Generating Company Comanche Peak Steam Electric Station

Farm Road 56

Glen Rose, Texas 76043

Dear Larry:

ASSESSMENT OF TUGCO AS-BUILT DOCUMENTATION FOR PIPING AND PIPE SUPPORTS COMANCHE PEAK STEAM ELECTRIC STATION

During the Nuclear Regulatory Commission (NRC)/Texas Utilities Generating Company (TUGCO) public meeting held on October 2 and 3, 1985, in Granbury, Texas, the NRC Staff raised questions about the TUGCO program and the organizations involved in addressing the requirements in NRC IE Bulletin 79-14, Seismic Analysis for As-Built Safety-Related Piping Systems. Subsequent to the above meeting, questions regarding the adequacy of the as-built documentation have been raised during NRC Staff audits of the Stone & Webster Engineering Corporation (SWEC) stress requalification program effort.

In April 1986, TUGCO commissioned a task group to conduct an overall assessment of relevant activities associated with piping and pipe supports at Comanche Peak Steam Electric Station - Unit 1. The purpose of this assessment was to determine whether the existing programs are effective to ensure the adequacy and completeness of the as-built documents used in the stress requalification program being performed by SWEC.

Attachment (1) provides the final report of this assessment.

Please call me at (617) 589-8170 (Boston) if you have any questions.

Very truly yours,

Takk Group Leeder

Attachment: "Assessment of TUGCO As-Built Documentation for Piping and Pipe Supports," repor dated July 2, 1986.

cc: J.C. Finneran

J.E. Krechting

O.W. Lowe

T.G. Tyler

SWEC Internal CC:

W.A. Matson

E.J. Sisken

P. Dunlop

R.K. Westfahl

V.A. Hoffman

E.J. Brabazon

D.C. Foster

A.W. Chan

R.P. Klause

C.E. Watters

S. Feldman

R. Ackley

ASSESSMENT OF TUGCO AS-BUILT DOCUMENTATION FOR PIPING AND PIPE SUPPORTS

FINAL REPORT

TEXAS UTILITIES GENERATING COMPANY (TUGCO)
COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
UNIT 1

July 2, 1986

Prepared	DV: 97/1/201/1/
repares	M. P. Polacher - Principal Engr - Engr Mechanics
Prepared	R. A Baia F Lead Engr - Engr Mechanics
Approved	by: S. Wigley - Group Leader
	7

\$706+702+3

TABLE OF CONTENTS

Sect	tion Description	Page
KEY	ABBREVIATIONS/DEFINITIONS	
SUM	MARY	1
1.0	INTRODUCTION	2
2.0	PURPOSE	2
3.0	SCOPE	2
4.0	ATTRIBUTES	2
5.0	EXISTING PROGRAMS	3
6.0	DISCUSSION	8
7.0	o conclusions	13
8.	O RECOMMENDATIONS	14
9.	O REFERENCES	17
Ta	bles	
1 2	- Attributes - Responsibility Matrix	
Fi	igures	
1 2	- Organizational Interrelationships - Detailed Organizational Interrelationships	

Attachment

KEY ABBREVIATIONS/DEFINITIONS

ASME III - Section III of the American Society of Mechanical Engineers Code

BRH - Brown & Root Pipe Hanger Drawing

BRHL - Brown & Root Pipe Hanger Location Drawing

BRP - Brown & Root Piping Isometrics

CAR - TUGCO Corrective Action Report

CPRT - Comanche Peak Response Team

CPSES - Comanche Peak Steam Electric Station

DR - Deviation Report

ERC - Evaluation Research Corporation

GHH - Gibbs & Hill Small Bore Pipe Hanger Location Drawing

HVP - Hardware Validation Program. Recommended as part of this assessment to be performed by TUGCO to ensure hardware adequacy of safety-related piping systems.

LDL - Line Designation List

NCR - Nonconformance Report issued by TUGCO

QA/QC - Quality Assurance/Quality Control

SWEC - Stone & Webster Engineering Corporation

SRP - Stress Requalification Program performed by SWEC

SVP - Supplemental Verification Programs. Recommended as part of this assessment to be performed by TUGCO to verify attributes related to safety-related piping systems.

TUGCO - Texas Utilities Generating Company

79-14 - NRC IE Bulletin 79-14 for the Seismic Analysis for As-Built Safety-Related Piping Systems

CPPP-5 - Comanche Peak Project Procedure for SWEC field walkdowns

CPPP-8 - Comanche Peak Project Procedure for piping and pipe support system engineering walkdown by SWEC

CPPP-6 - Comanche Peak Project Procedure for the pipe stress/support requalification effort

Safety Significant - As used in this report (and the ERC program), an identified discrepancy which, if uncorrected, could result in loss of capability of the affected system, structure, or component to perform its intended safety function (no credit is taken for redundancy).

10CFR50 - Title 10, Part 50 of the Code of Federal Regulations

10CFR50.55e - Section in the Code of Federal Regulations which contains the requirements for the reporting of potential issues which could adversely affect the safe operation of the plant.

Normal Inspection Process - QA/QC Inspection program originally performed by the installer contracted by TUGCO to meet the requirements of the Erection Specification, Appendix B to 10CFR50 and/or ASME III.

Safety-Related Piping System -As used in this report, an all-inclusive term which includes all ASME III piping and pipe supports. Also includes continuations of the code piping after the code class break up to the end of the pipe stress analyzical model.

Computer-Analyzed - As used in this report, a term associated with small bore piping which reflects the type of detailed computer analysis used to analytically qualify the piping.

Noncomputer-Analyzed - As used in this report, a term associated with small bore piping which reflects the type of standard 'cookbook' or hand-calculated analysis used to qualify the piping.

Attribute - As used in this report, a term which refers to the qualitative characteristics of safety-related piping systems.

Large Bore Piping - Piping systems which are 2.5-inches nominal pipe diameter and greater.

Small Bore Piping - Piping systems which are less than 2.5-inches nominal pipe diameter.

Stress Requalification Program (SRP) - Requalification of safety-related piping and pipe supports being performed by SWEC.

Deviation - As used in this report, a verified failure to meet a licensing commitment, to meet a regulatory requirement, or to properly install bardware. Although this is a term defined by ERC, it also is used to represent SWEC observations for simplicity.

SUMMARY

During the Nuclear Regulatory Commission (NRC)/Texas Utilities Generating Company (TUGCO) public meeting held on October 2 and 3, 1985, in Granbury, Texas, the NRC Staff raised questions about the TUGCO program and the organizations involved in addressing the requirements of NRC IE Bulletin 79-14, Seismic Analysis for As-Built Safety-Related Piping Systems. TUGCO commissioned a task group to conduct an overall assessment of relevant activities associated with piping and pipe supports at Comanche Peak Steam Electric Station - Unit 1.

The purpose of this assessment was to determine whether the existing programs are effective to ensure the adequacy and completeness of the asbuilt documents used in the stress requalification program (SRP) being performed by Stone & Webster Engineering Corporation (SWEC).

The assessment process involved the identification of attributes that are required for input to pipe stress analysis and pipe support design. This included the attributes identified in NRC IE Bulletin 79-14 and other asbuilt documentation related to the SRP.

The existing programs of TUGCO, SWEC, and Evaluation Research Corporation (ERC) were reviewed to determine which key attributes were addressed. The procedures that evaluated the adequacy of these attributes and the organizational interfaces were also evaluated for completeness and effectiveness.

The assessment identified the following:

- There are existing procedures to ensure that all attributes identified in IE Bulletin 79-14 are verified. The assessment further identified that these procedures apply to other as-built documentation used in the SRP.
- There are programs in place to ensure that adverse as-built conditions are identified, evaluated for generic implications, and corrected; however, some improvements are recommended.
- Modifications of the programmatic interfaces are recommended to improve communication between the involved organizations.

Recommendations are presented by the Task Group that will enhance the overall program.

1.0 INTRODUCTION

During the Nuclear Regulatory Commission (NRC)/Texas Utilities Generating Company (TUGCO) public meeting held on October 2 and 3, 1985, in Granbury, Texas, the NRC Staff raised questions germane to the attributes in IE Bulletin 79-14, Seismic Analysis for As-Built Safety-Related Piping Systems, how they were being addressed and verified, and the relationship and interfaces between the organizations involved (TUGCO, Evaluation Research Corporation (ERC), and Stone & Webster Engineering Corporation (SWEC)). Subsequent to the above meeting, questions regarding the adequacy of the as-built documentation have been raised during NRC Staff audits of the SWEC effort.

TUGCO commissioned a Task Group of L. S. Wigley (SWEC - Group Leader), R. A. Bain (SWEC - Lead Engineer - Engineering Mechanics) and M. P. Polachek (SWEC - Principal Engineer - Engineering Mechanics) to conduct an overall assessment of activities associated with safety-related piping systems to address the above concerns.

2.0 PURPOSE

The purpose of this assessment was to determine whether the existing programs are effective to ensure the adequacy and completeness of the as-built documents used in the stress requalification program (SRP) being performed by SWEC.

3.0 SCOPE

The scope of this assessment includes:

- An identification of as-built attributes critical to the SRP, including those in IE Bulletin 79-14, and the organizations responsible for verification of the attributes.
- An evaluation of the programs currently in place at Comanche Peak Steam Electric Station (CPSES) - Unit 1 to verify the attributes.
- 3. An evaluation of the process followed by ERC, TUGCO, and SWEC for the evaluation of as-built discrepancies critical to the SRP, including the interface among the FRC, SWEC, and TUGCO programs and the applicable procedures used in the process.

Attachment 1 provides the action plan used by the Task Group for gathering and evaluating the information necessary to conduct this assessment.

4.0 ATTRIBUTES

Attributes associated with SWEC's SRP are listed in Table 1. All attributes identified in IE Bulletin 79-14 are included in this list.

Documents which are used to record the attributes also are identified in Table 1. The primary documents are American Society of Mechanical Engineers (ASME) control drawings for piping (BRPs) and hangers (BRHs), and

hanger locations (BRHLs for large bore piping and GHHs or BRHLs for small bore piping). Other drawings or documents used include the line designation list (LDL) for insulation, structural drawings for fire walls, and penetration schedule for penetration seals.

It is important to reinforce at the outset that the purpose of this assessment was not to inspect the attributes directly, but to determine: whether programs are in place to inspect the attributes; that the programs are effective; that the results are included in the stress requalification program (SRP); that root cause, trends, and generic implications are addressed; and that corrective action is taken, if appropriate.

Section 5.0 describes the programs of the involved organizations, while Section 6.0 discusses the adequacy and completeness of the programs and the attributes each verifies.

5.0 EXISTING PROGRAMS

5.1 TEXAS UTILITIES GENERATING COMPANY (TUGCO)

TUGCO developed a program for as built piping verification to meet the general intent of IE Bulletin 73-14 requirements. Specifically, the TUGCO procedure (CP-EI-4.5-1) required a physical walkdown of piping systems in addition to the normal inspection process (described below). This as-built program verified the following:

- 1. Piping dimensions, elevations, and directional changes
- 2. Support and valve orientation
- 3. Sleeve clearance
- 4. Equipment orientation
- 5. Support mark numbers
- 6. Support and valve location
- 7. Support type
- 8. General support configuration
- 9. Clearance between the pipe and support

The above TUGCO procedure applied to all safety-related large bore and computer-analyzed small bore piping and pipe supports.

Other attributes not included in the above TUGCO as-built procedure were addressed in accordance with the normal inspection process. The normal inspection process, as used in this report, consists of the activities required to meet the ASME III code, Appendix B to Title 10, Part 50 of the Code of Federal Regulations (10CFR50), and/or the contractor specification. Also included in this term are the quality control procedures and construction procedures developed to meet these requirements. For

example, embedments were designed and installed in accordance with Comanche Peak Specification No. 2323-SS-30, Structural Embedments. The specification provided for a normal inspection program. No special walkdown was required.

Valve weights were addressed in accordance with the Valve Weighing Program, Comanche Peak Procedure No. CP-EI-2.2-1. The procedure provided for physical weighing of a representative sample of generic types of valves and operators. The procedure further provided for an engineering evaluation if the valve was not available for weighing or if additional information was required.

Pipe attachments are typically shown on the BRH for lugs or trunnions. Verification of this attribute was also dependent on the normal inspection process.

Table 1 lists other attributes related to safety-related piping systems which were not addressed in the TUGCO As-Built Program. Typically, these attributes were verified in accordance with the normal inspection process. Comanche Peak Specification No. 2323-MS-100 identified the requirements for piping and support erection. This normal inspection process was also used for the noncomputer-analyzed small bore piping excluded from the TUGCO As-Built Program.

In addition to the above programs, TUGCO is responsible for the processing of Comanche Peak Response Team (CPRT) Deviation Reports/Out-of-Scope Observations in accordance with Comanche Peak Procedure No. CP-QP-16.3. This procedure provides TUGCO with a mechanism to document, on nonconformance reports (NCRs), relevant ERC findings (discussed below) or any other organizations' (e.g., SWEC) relevant findings.

Additionally, TUGCO evaluates NCRs for potential reportability under 10CFR50.55e in accordance with Comanche Peak Procedure Nos. CP-QAP-16.1, Control of Nonconforming Items, and NEO-CS-1, Evaluation of and Reporting of items/events under 10CFR21 and 10CFR50.55(e). NCRs dispositioned use-as-is are evaluated by SWEC to verify the acceptability of the change to the design document. Generic corrective action and root cause are addressed in accordance with Comanche Peak Procedure No. CP-QP-17.0, Corrective Action.

5.2 STONE & WEBSTER ENGINEERING CORPORATION (SWEC)

TUGCO has contracted SWEC to perform a stress requalification effort for the safety-related piping and pipe supports of CPSES. As part of this effort, SWEC has performed three walkdowns to review existing TUGCO documents being used in the SRP. Two walkdowns were performed in accordance with Comanche Peak Project Procedure CPPP-5 and one in accordance with CPPP-8. Any deviations identified during these walkdowns have been or are being forwarded to TUGCO.

The two CPPP-5 walkdowns were sample inspections performed to verify that the existing documentation was adequate to initiate the SRP with an acceptable risk such that the analysis would not have to be redone upon completion of the ERC Program. Valve location, hanger location, hanger

function, and valve and support orientation were the attributes verified. These attributes were selected since they have the greatest potential for impact on pipe stress analysis. The first walkdown examined a sample of large bore Class 2 and 3 piping systems. A sample of the small bore noncomputer-analyzed piping systems which were not included in the TUGCO As-Built Program was addressed in the second walkdown.

The CPPP-8 walkdown was performed by experienced pipe stress and support engineers on a sample of large bore stress problems to review physical relationships and critical configurations which could impact conclusions regarding overall piping system design and acceptance. The objectives of this walkdown were as follows:

- To determine whether there were technical configuration issues, other than existing technical findings from previous reviews, which should be evaluated relative to the functional behavior of the system, and
- For experienced SWEC personnel to become familiar with the physical aspects of the design and determine whether additional refinements of design inputs, guidelines, or procedures were necessary for the SRP.

The walkdowns were based on a sample size of stress problems consistent with the ERC program (see below).

In addition to these walkdowns, SWEC has committed, in the Pipe Stress/Support Requalification Procedure (CPPP-6), to a final walkdown for clearances. This walkdown will ensure that any clearance violations exist between piping systems and nearby structures will be satisfactorily resolved based on the movements from the SRP.

5.3 EVALUATION RESEARCH CORPORATION (ERC)

ERC has developed a program to determine the adequacy of the CPSES construction Quality Assurance/Quality Control (QA/QC) program and the adequacy of the installed hardware. ERC was assigned this responsibility by the Comanche Peak Response Team (CPRT). The CPRT has been charged with responding to and resolving concerns raised by external sources (i.e., NRC Staff's Technical Review Team, NRC Staff's Construction Assessment Team, Cygna Independent Assessment Program) regarding the adequacy of safety-related hardware. Additionally, the CPRT is charged with advising TUGCO Management as to whether there is reasonable assurance that CPSES has been designed and constructed such that it is capable of being operated safely.

To this end, ERC has formulated a program with three main components. The first two address the issues raised by the external sources. The third component addresses the quality of construction as it relates to all safety-related aspects of the plant. This effort involves a sample reinspection of hardware that is representative of activities and processes used in the construction of safety-related aspects of the plant. Also included is the investigation and determination, where possible, of

the root cause of each identified safety-significant deficiency or adverse trend of nonsafety-significant deviations. The implications from the root cause are analyzed to determine the extent that other construction activities could be deficient for similar reasons. Generic implications, an overview of corrective action, and a collective evaluation of the deviations are also within the scope of the ERC program.

Pertinent to the SRP are the quality instructions (QIs), listed below, developed by ERC to address the construction adequacy of safety-related piping systems:

QI-19 Reinspection of Small Bore Pipe Supports

QI-21 Reinspection of Piping System Bolted Joint/Materials

QI-25 Reinspection of Large Bore Piping Configuration

QI-26 Reinspection of Small Bore Piping Configuration

QI-27 Reinspection of Large Bore Pipe Supports - Rigid

QI-29 Reinspection of Large Bore Pipe Supports - Nonrigid

QI-43 Reinspection of Concrete Placement

QI-49 Reinspection of Large Bore Piping = Welds/Materials

QI-51 Reinspection of Pipe Whip Restraints

Checklists were developed by ERC in accordance with the procedure for Preparation of Checklists and Data Base Reports (Comanche Project Procedure CPP-7) to identify the attributes to be inspected. The list of attributes and corresponding QI is prepared by the responsible ERC QA/QC discipline and reviewed and approved by the Lead Discipline Engineer and the QA/QC Engineering Supervisor. Inspections are then performed by personnel certified to Level II or III in accordance with American National Standards Institute (ANSI) N45.2.6, Qualifications of Inspection, Examination and Testing Personnel for the Construction Phase of Nuclear Power Plants; United States Nuclear Regulatory Commission Regulatory Guide 1.58, Qualification of Nuclear Power Plant Inspection, Examination and Testing Personnel; and additional requirements set forth in the ERC procedure for Indoctrination, Training and Certification of Personnel (CPP-3).

The inspections are based on a sampling plan described in detail in Appendix D of the CPRT Program Plan. Items not in conformance are recorded on Deviation Reports (DRs). The DRs are evaluated by the ERC's Safety Significance Evaluation Group for safety-significance in accordance with the ERC procedure for Safety-Significant Evaluations of Deviation Reports (CPP-16). Any item determined to have a potential safety-significant impact results in expanding the inspection sample potentially up to a 100-percent effort for the affected attribute.

Other pertinent procedures applicable to the ERC program include the following:

CPP-1 - Preparation of Project Procedures and Quality Instructions

CPP-5 - Establishing Population

CPP-6 - Sample Selection

- CPP-11 Evaluations of Adverse Trend Analysis, Safety-Significant Deficiencies, and QA/QC Program Deficiencies
- CPP-13 Collective Evaluation of the Quality of Construction
- CPP-14 Collective Evaluation of Construction QA/QC Program
- CPP-21 CPSES Project Corrective Action

All DRs are also forwarded to TUGCO QA in accordance with CPP-10 (Preparation of DRs) for generation of an NCR, if applicable.

5.4 SUMMARY OF EXISTING PROGRAMS

As discussed in further detail in Section 6.0, the attributes applicable to the SRP are being addressed by TUGCO, ERC, or SWEC; however, each organization has different purposes when reviewing the attributes as shown by the following:

- TUGCO Normal Inspection process performed by Brown & Root Quality Control personnel to meet the requirements of 10CFR50, Appendix B, and the ASME III Code.
- TUGCO As-Built Program performed to supplement the normal inspection process and to meet certain requirements of IE Bulletin 79-14.
- TUGCO Specific Quality Control Backfit Type Inspections performed due to design changes or generic corrective action programs.
- ERC Program performed to determine the quality of construction.
- SWEC CPPP-5 Walkdowns performed to assess the adequacy of key field inputs to the SRP.
- SWEC CPPP-8 Walkdown performed to determine the adequacy of the SRP procedures.

In general, the TUGCO normal inspection process was supplemented in part by the TUGCO as-built program. More recently, ERC sample inspections were also performed to determine the quality of construction. The SWEC sample inspections are also recent efforts which were performed to determine the adequacy of the requirements of the SRP procedures.

The interface and flow of work between the three organizations, shown in Figure 1, can be divided into six categories:

- Initial information developed by TUGCO which is provided to SWEC and ERC.
- 2. Sample inspections by SWEC and ERC.

- Evaluations and recommendations by SWEC and ERC (identification of individual deviations and generic concerns).
- 4. Corrective action by TUGCO (disposition of individual deviations and resolution of generic concerns).
- Revision of documents by TUGCO and transmittal to SWEC for the SRP.
- 6. Completion of the SRP by SWEC.

The required documents are obtained from TUGCO by SWEC and ERC for their verification programs. These documents are also used by SWEC for the SRP. SWEC and ERC use sample techniques to evaluate the TUGCO documents. ERC identified deviations are evaluated by ERC for safety significance and adverse trends and, if necessary, are also forwarded to TUGCO for generic corrective action. SWEC deviations are evaluated by SWEC for impact on the SRP. SWEC generic concerns are addressed by revising the SRP procedures or by TUGCO generic corrective action. All ERC and SWEC individual deviations are forwarded to TUGCO to initiate an NCR.

All TUGCO NCRs related to safety-related piping systems and dispositioned "use-as-is" are distributed to SWEC and incorporated into the as-built documents to ensure that they are included in the SRP.

Figure 2 shows the interface between ERC and SWEC inspections and evaluations and TUGCO corrective action in more detail. Note that Figure 2 includes proposed programs recommended in Section 8.0.

6.0 DISCUSSION

A discussion of the attributes and the adequacy of various programs and procedures is presented in this section. In cases where the final conclusions of the ERC sample inspection programs and SWEC walkdown efforts have not been completed, the adequacy as discussed in this report is assessed based on draft reports and in-process data. In cases where ERC or SWEC concerns already have been identified, TUGCO corrective action is addressed as future work even though all or part may be in progress or complete.

6.1 ADEQUACY OF ATTRIBUTES

6.1.1 Adequacy of Attributes Included in the TUGCO As-Built Program

As shown in Table 2, the original TUGCO As-Built Program (described in Section 5.1) addressed several attributes. Table 2 also identifies the ERC and SWEC procedures that inspect the attributes and the procedures which have currently identified any generic concerns.

Support location and support function are attributes which were included in both the ERC and SWEC CPPP-5 programs. Pipe run geometry was indirectly included by virtue of checking support locations. No generic concerns that could result in TUGCO generic corrective action have been identified to date.

Support design was included in the ERC program and the SWEC CPPP-8 program for general configuration. Although deviations have been identified by both programs, it does not appear that this will result in a generic concern that requires TUGCO generic corrective action.

Although clearance between piping and supports (gaps) was included in the ERC and SWEC CPPP-8 programs, the specified tolerances have been revised as part of the SRP. The adequacy of this attribute will be addressed by TUGCO generic corrective action.

Valve identification and orientation were included in the ERC program and SWEC CPPP-5 program. No generic concern has been identified for the valve identification; however, the orientation has been identified as a generic concern which requires a TUGCO 100-percent reinspection. This is also the case for support orientation.

Clearances between piping and sleeves were included in the ERC and SWEC CPPP-8 programs; however, the ERC program only addressed this as a general clearance attribute. Sleeve clearance and type were not included as specific attributes. The CPPP-8 program did identify this to be a generic concern. As a result, all safety-related piping penetrations (including fire walls) will require TUGCO generic corrective action for clearance and type of seal.

In general, there are generic concerns regarding specific attributes included in the TUGCO As-Built Program. A root cause evaluation (discussed in Section 6.3, Corrective Action) and generic corrective action are necessary to resolve the concerns.

6.1.2 Adequacy of Other Attributes

As shown in Table 2, TUGCO also utilized the normal inspection process to address attributes related to the SRP. The ERC and SWEC procedures which inspected the attribute and the procedures which have identified any generic concerns also are tabulated. Some examples follow.

Embedments were included in the ERC program. Since they are not within the scope of the SRP, they were excluded from the SWEC programs. No generic concerns have been identified by ERC to date; however, while conducting a third-party design assessment, CYGNA Engineering Services determined that the normal inspection requirements were incomplete. Specifically, the minimum separation requirements for welded attachments to embedded plates and the minimum spacing criteria between loaded Richmond inserts and embedded plates were not specified. These requirements were not included in the ERC program. Generic corrective action by TUGCO is therefore necessary.

Pipe attachments were included in the ERC and SWEC CPPP-8 programs. No generic concerns have been identified.

Valve weights were reviewed as part of the SWEC CPPP-8 program. Since this attribute is not really related to the quality of construction, it was not included in the ERC program. The SWEC CPPP-8 program identified

a concern regarding the documentation of additional mass as a result of remote operators. TUGCO corrective action is necessary.

As listed in Table 2, other attributes related to safety-related piping systems were assessed. The majority of these attributes were addressed by TUGCO as part of the normal inspection process. Table 2 also shows the ERC and SWEC programs that address the attribute. Included also are the programs which have identified concerns to date (e.g., expansion joints, tie-back support location, Class 5 continuations, insulation, clamp and support orientation, and loose, missing, or damaged hardware).

6.1.3 Summary of Attributes

In general, the verification of each attribute falls into one of the following categories:

- The attribute was originally included in a TUGCO inspection program (normal or as-built) and is verified in both the ERC and SWEC programs.
- The attribute was originally included in a TUGCO inspection program and is verified in either the ERC program or the SWEC program.
- The attribute was not originally included in a TUGCO inspection program and is verified as part of TUGCO generic corrective action.

In the first two cases, the SWEC and/or the ERC programs identify any individual deviation or generic concerns to TUGCO for corrective action. In the third case, missed attributes (i.e., embedments) are identified as part of design adequacy reviews which are conducted by SWEC and other organizations. These attributes are identified to TUGCO for generic corrective action.

Also, the -lequary of each attribute falls into one of the following:

- 1. The SWEC and/or ERC program(s) identified no deviations.
- The SWEC and/or ERC program(s) identified deviations which require disposition on an NCR but which do not require generic corrective action.
- SWEC and/or ERC and/or other organizations identified deviations and concerns which require disposition on an NCR and which also require generic corrective action.

In summary, there are programs in place to ensure that all attributes related to the SRP, including those identified in IE Bulletin 79-14, are included in a verification program and evaluated for adequacy. The adequacy of the SWEC and ERC evaluation process and TUGCO corrective action process is discussed in the following sections.

6.2 ADEQUACY OF EVALUATION PROCESS

Each individual deviation is dispositioned as part of the NCR program. The NCR process ensures that the particular deviation is corrected either by rework or by technical justification to use-as-is. Although the process also includes an evaluation for potential reportability under 10CFR50.55(e), it is unlikely that any one deviation considered by itself would be reportable. More important is the cumulation of similar deviations which could result in a generic concern. An evaluation for potential reportability of a generic conern is addressed in Section 6.3 as part of corrective action. The adequacy of the process by which the deviations are considered together is discussed in this section.

of construction

The ERC program is designed to verify the adequacy as described in detail in the Comanche Peak Response Team Program. This program has been evaluated by the NRC (Safety Evaluation Report for CPSES, NUREG-0797, Supplement 13). The Staff concluded that the program provides an overall structure for addressing all existing and future issues and, if properly implemented, will provide important evidence of the construction quality of CPSES and will identify any needed corrective action. The Staff also identified items to be addressed during the implementation phase.

The quality of construction of piping and pipe supports is therefore addressed under the ERC program for those attributes in the program. As such, ERC is considered to be adequately verifying the as-built information being used by SWEC in the SRP. For those attributes not addressed in the ERC program, other programs are verifying their adequacy.

The SWEC CPPP-5 and 8 walkdowns address all field attributes that affect the adequacy of the SRP (embedments are not in the SRP scope). Although the SWEC deviations are not formally evaluated for trends, generic implications, and safety significance similar to the ERC deviations, SWEC does assess the deviations for generic impact on the SRP. Due to the nature of the SWEC programs, the assessment for impact on the SRP is essentially equivalent to a detailed trending, generic implication, and safety-significant evaluation. Specifically, the SWEC program does require that generic concerns which could impact the SRP are either corrected by TUGCO or corrected by refining or modifying the SRP procedures.

Since trending, generic implications, and safety significance for safety-related piping systems are being performed by ERC for construction quality and by SWEC for design adequacy, there is no need for TUGCO to repeat these efforts. It should be noted that this applies only to reinspections of work previously completed. For ongoing construction and current in-process inspections, TUGCO does have a program for trending, generic implications, and safety significance. This ensures that current trends are not improperly influenced by past trends.

In summary, each individual deviation is reviewed for potential reportability and dispositioned rework or use-as-is. The process by which individual deviations are evaluated is therefore considered adequate. The process by which deviations are evaluated for trends and generic implications is considered adequate based on acceptance of the ERC program by the NRC Staff and further supplemented by the SWEC program.

However, the effectiveness can be improved as described in Recommendations 8.3 and 8.4. Recommendation 8.3 suggests that SWEC also review the ERC DRs for impact on the SRP. Recommendation 8.4 suggests that ERC review the SWEC walkdown results to supplement ERC's collective evaluation.

6.3 ADEQUACY OF CORRECTIVE ACTION

Corrective action is addressed by TUGCO utilizing two main processes, NCRs and CARs. As stated above, the NCR process ensures that each individual deviation is processed to determine whether the deviation is valid. If the deviation is valid, an NCR is initiated and a determination is made as to whether the NTR should be reworked or used as is. Since SWEC evaluates all NCRs associated with safety-related piping systems, and the NCRs are further incorporated into the as-built documents, all valid individual deviations related to safety-related piping systems are considered in the SRP.

The corrective action report (CAR) is utilized by TUGCO to address the generic concerns identified by SWEC, ERC, or any other organization. This program ensures the concern is evaluated for extent, root cause, corrective action, and potential reportability under 10CFR50.55e. The CAR also is utilized to track the corrective action to closure.

Both ERC and SWEC identify generic concerns to TUGCO through independent programs. SWEC generic concerns are initially addressed through TUGCO Engineering, while ERC generic concerns are addressed through TUGCO Quality Control (QC). Although TUGCO QC and Engineering do interface, the process should be better defined to avoid a duplication of efforts.

Recommendations 8.1 and 8.2 suggest that TUGCO develop two types of programs to organize any generic corrective action which deals with verification of specific attributes. A hardware validation program (HVP - Section 8.1) would address items such as loose, missing, damaged, or misaligned hardware. A supplemental verification program (SVP - Section 8.2) would address other items such as penetration seal requirements, tie-back supports, and insulation thickness. The distinction between the two is that the HVP is geared towards tightening, replacing, or reworking the hardware so that there is no change to the as-built drawings, while the SVP is geared towards documenting changes to the current requirements that could affect the SRP. The two programs could directly refer to the NCR and CAR procedures to ensure that all TUGCO corrective action is appropriately addressed.

In summary, the process by which each individual deviation identified by SWEC or ERC is corrected is adequate. The process by which generic corrective action is addressed should be improved so that it will be better organized and efforts will not be duplicated.

7.0 CONCLUSIONS

The assessment identified the following:

- There are existing procedures to ensure that all attributes identified in IE Bulletin 79-14 are verified. The assessment further identified that there are existing procedures to ensure that other design inputs related to the SRP are verified.
- There are programs in place to ensure that adverse as-built conditions will be identified and corrected; however, some improvements should be implemented.
- Programmatic interfaces should be modified to improve communication between the involved organizations.

8.0 RECOMMENDATIONS

Figures 1 and 2 show the existing and recommended programs in flow chart form.

8.1 RECOMMENDATIONS REGARDING HARDWARE-RELATED CONCERNS

ERC and SWEC have and are in the process of identifying hardware-related concerns which normally will require rework to the specified requirements and have no impact on the SRP. Items such as missing cotter pins, loose jam nuts, damaged components, misaligned struts or snubbers, and nonparallel clamp ears are examples. These items should be grouped into a single verification program entitled hardware validation program (HVP) to improve the corrective action process. The following additional recommendations would then apply:

- TUGCO should define the scope and establish the HVP program, since all concerns are identified to TUGCO.
- Since the HVP will close ERC issues, ERC is required by program (CPP-21) to review the applicable HVP procedure and results. SWEC should also review the HVP procedure to ensure that SWEC concerns are adequately addressed.
- 3. The procedure should directly reference the procedures for corrective action and potential reportability addressed further in Recommendation 8.6. This will avoid duplication of efforts and organize the process.
- Operations personnel should be involved to facilitate the transition from a final as-built system to an operating system. In addition, programs should be verified to be effective to ensure maintainability of as-built configurations. Modification of Procedures STA-802-5, Final Acceptance of Station Systems and Equipment, and STA-804-2, Control of Station Areas, should be considered to implement or interface with the HVP.
- Scheduling of the HVP should consider the completion of modifications as a result of the SRP.
- 6. The HVP should be developed such that components can be corrected without having to generate individual NCRs. However, a system to identify corrected items should be provided. The followup report should include a quantitative analysis for historical record.

8.2 RECOMMENDATIONS REGARDING OTHER CONCERNS

ERC and SWEC have and are in the process of identifying other concerns which may or may not require rework to the specified requirements and therefore may affect the SRP. Items such as penetration type and clearance, fire wall clearance, insulation thickness and stand-off dimensions, tie-back supports, valve orientation, certain Class 5 continuation piping, embedments, and expansion joints are examples. Those items

evaluated by TUGCO to require a field verification should be grouped into a single program called the supplemental verification program (SVP) to improve the corrective action process. The following additional recommendations would then apply:

- TUGCO should define the scope and establish the SVP program, since all concerns are identified to TUGCO.
- Since the SVP will close ERC issues, ERC is required by program
 to review the applicable SVP procedure(s) and results. SWEC
 should also review the SVP procedure(s) to ensure that SWEC
 concerns are adequately addressed.
- 3. The procedure(s) should directly reference the procedures for corrective action and potential reportability addressed further in Recommendation 8.6. This will avoid duplication of efforts and organize the process.
- Completion of the SVP and subsequent action should be expedited to minimize potential impacts to the SRP.
- An accounting system to identify the corrected items should be provided for historical record.
- The Protection and Analysis Group should participate in the resolution of penetration/sleeve concerns, since they have primary responsibility for the seals.
- 7. Resolution of concerns regarding embedments should consider identification of spacing violations and overloaded conditions as an initial objective. Since pipe supports may have to be modified to qualify the embedment, it is advantageous to identify these cases as early as possible.

8.3 RECOMMENDATIONS REGARDING REVIEW OF ERC DRs FOR IMPACT ON THE SRP

SWEC should review the ERC DRs related to safety-related piping systems to ensure that they are evaluated for potential impact on the SRP. This evaluation should be done to ensure that any potentially generic items are identified and evaluated to determine whether corrective action is required.

8.4 RECOMMENDATIONS REGARDING ERC REVIEW OF SWEC WALKDOWN RESULTS

ERC should review SWEC walkdown procedures and results to ensure that relevant information is utilized. Additionally, SWEC walkdowns may identify cases where TUGCO/SWEC have already evaluated or corrected a specific concern that overlaps an ERC concern.

8.5 RECOMMENDATIONS REGARDING DISTRIBUTION OF SWEC/ERC RESULTS

SWEC should provide ERC the walkdown reports. Conversely, ERC should provide the piping and pipe support DRs to SWEC.

8.6 RECOMMENDATIONS REGARDING ROOT CAUSE AND 10CFR50.55(e) EVALUATIONS

The root cause of the ERC/SWEC concerns should be addressed prior to initiating the HVP and SVP to prevent recurrence of the concern. Potential 10CFR50.55(e) evaluations should be grouped such that all deviations due to the same root cause are addressed once. This will provide for more meaningful preventive action and more efficient corrective action. For example, the evaluation of an insulation concern for root cause should consider the following:

- 1. Adequacy of original inspections
- 2. Adequacy of original criteria, such as minimum and maximum thickness requirements
- 3. Adequacy of QC inspection plan
- Requirements to identify changes to the responsible stress analysis organization

After determining that one or more of these items represent the root cause, appropriate action can be taken to prevent recurrence of the concern. Corrective action should also consider that it may be expedient and less costly to proceed directly to a 100-percent verification.

8.7 RECOMMENDATIONS REGARDING PLANNING

A single TUGCO focal point (individual) should be responsible for monitoring all activities associated with completing the safety-related piping systems. The task should include the following:

- Comprehensive scheduling of the SVP, HVP, and ongoing modifications or rework
- 2. NCR generation and disposition
- 3. Design change generation and disposition
- 4. Drawing updates and issue of revisions

9.0 REFERENCES

NRC IE Bulletin 79-14, Seismic Analysis for As-built Safety-Related Piping Systems

TUGCO Internal Guidelines for As-built Verification - Unit 1, Reverification of Strut, Snubber, Spring and Valve Orientation; Subsequent As-built Review; NCR/DN Tracking and Closure

TNE-AD-5-2, Processing Non-Conformance Results

TNE-DC-7-3, Preparation of Design Drawing by TSMD

TNE-DC-24-1, Program for As-built Piping Verification

TNE-DC-25, Control of Activities for the PSE HFT Results Groups

CP-EI-2.2-1, Valve Weighing Program

CP-EI-4.0-39, Performance Instruction for PSI HFT Design Change Control Group

CP-EI-4.5-1, General Program for As-built Piping Verification

CP-QAP-16.1, Control of Non-Conforming Items

CP-QP-16.3, Processing CPRT Deviation Reports/Out of Scope Observation

CP-QP-17.0, Corrective Action

STA-802-5, Final Acceptance of Station Systems and Equipment

STA-804-2, Control of Station Areas

NED-CS-1, Evaluation of the Reporting of Items/Events under 10CFR27 and 10CFR50.55(e)

CPP-001 through 023, Comanche Peak Response Team QA/QC Review Team Project Procedure

CPPP-5, Comanche Peak Project Procedure for Field Walkdown - Unit 1

CPPP-6, Comanche Peak Project Procedure for Pipe Stress/Support Requalification Effort - Unit 1

CPPP-7, Comanche Peak Project Procedure for Design Criteria for Pipe Stress and Pipe Supports

CPPP-8, Comanche Peak Project Procedure for Piping and Support System Engineering Walkdown - Unit 1

CPPP-18, Comanche Peak Project Procedure for the Evaluation by SWEC of Deviation Reports Generated by the ERC

Specification No. 2323-SS-30, Structural Embedments

Specification No. 2323-MS-21, Valve Extension Stems

Specification No. 2323-MS-46A, Nuclear Safety Class Pipe Hangers and Supports

Specification No. 2323-MS-100, Piping Erection

Specification No. 2323-MS-200, Design Specification for all ASME III Code Class 2 and 3 Piping

- QI-019, Reinspection of Small Bore Pipe Supports
- QI-021, Reinspection of Piping System Bolted Joints/Material
- QI-025, Reinspection of Large Bore Piping Configuration
- QI-026, Reinspection of Small Bore Piping Configuration
- QI-027, Inspection Procedures for Large Bore Pipe Supports Rigid
- QI-029, Inspection Procedures for Large Bore Pipe Supports Non-Rigid
- QI-043, Reinspection of Concrete Placement
- QI-049, Reinspection of Large Bore Piping Welds/Material
- QI-051, Reinspection of Pipe Whip Restraints
- TUGCO Letter No. TXX-3597 (to NRC), IE Bulletin 79-14 dated December 3, 1982
- TUGCO Letter No. TXX-4729 (to NRC), Status of As-built Virification Program, dated April 6, 1986
- NUREG-0797, Supplement No. 13, Safety Evaluation Report Related to the Operation of Comanche Peak Steam and Electric Station, Juits 1 and 2 (Docket Nos. 50-445 and 50-446) dated May 1986

TABLE 1

ATTRIBUTES

- 1. Pipe run geometry is shown on Brown & Root Piping Drawings (BRP).
- Support design is shown on support hanger drawings (BRH).
- Support location is shown on large and small bore hanger location drawings (BRHLs and GHHs).
- 4. Support function is shown on BRHs.
- 5. Support clearances/gaps are shown on BRHs.
- 6. Embedments are shown on structural drawings.
- 7. Pipe attachments are shown on BRPs.
- 8. Valve and Valve Operator Location
 - a. Identification is shown on BR?s.
 - b. Orientation is shown on BRPs.
- 9. Valve and valve operator weights are controlled by the valve list.
- 10. Clearance between pipe and sleeves are shown on BRPs. Fire walls are shown on structural drawings, and penetrations are shown on the penetration schedule.
- 11. Component type and identification (valves, strainers, expansion joints, flanges, reducers, flex hoses) are shown on BRPs.
- 12. Bends/elbows (standard, short radius, 5D, etc) are shown on BRPs.
- 13. Branch connection types (ANSI tee, unreinforced tee, reinforced tee, sockolet, weldolet, boss, coupling, half coupling, swagelock) are shown on BRPs.
- 14. Branches/intersections (small bore, vents and drains, instrumentation taps) are shown on BRPs.
- 15. Equipment locations and identification are shown on BRPs.
- Material type/size/class (including substitutions and specification violations) are shown on BRPs and specification NCRs.
- 17. Tie-back supports are shown on small bore hanger drawings (BRHs) and small bore hanger location drawings (GHHs).
- 18. Identifications and type of supports are shown on BRHs.
- 19. Support welds are shown on BRHs.

- 20. Base plates are shown on BRHs.
- 21. Integral/nonintegral attachments to pipe are shown on BRHs, except for those abandoned which are shown on the BRPs.
- 22. Attachments to support structures are shown on BRHs.
- 23. Bill of materials is shown on BRHs.
- 24. Class 5 piping installation analyzed with Class 1, 2, and 3 piping is shown on BRHs, BRHLs, and GHHs.
- 25. Insulation thickness and type is shown on the LDL.
- 26. Whip restraints/moment restraints are shown on structural drawings and Brown & Root installation drawings.
- 27. Support/clamp orientation is shown on BRHs.

TABLE 2
ATTRIBUTE MATRIX

INSPECTION/VERIFICATION PROGRAMS

	Items	TUGCO	ERC	SWEC (Note 1)	Remarks
1.	Pipe run geometry	A/B Program	QI-25,26	CPPP-5	CPPP-5 indirectly verifies geome /
2.	Support design (configuration)	A/B Program	QI-19,27,29	CPPP-8	
3.	Support location	A/B Program	QI-19,27,29	CPPP-5	
4.	Support function	A/B Program	QI-19,27,29	CPrP-5	
5.	Support clearances/gaps	A/B Program	QI-19,27,29	CPPP-5, 8	Being Verified to Revised Criteria
6.	Embedments				
	a. Spacing of attachmentsb. Other embedment attributes	No Normal Insp	No QI-43	No No	CYGNA Concern (Note 2)
7.	Pipe attachments	Normal Insp	QI-25,26	CPPP-8	
8.	Valves				
	Identification	A/B Program	QI-25,26	CPPP-8	
	Orientation	A/B Program	QI-25,26	CPPP-5	CPPP-5 Concern (Note 2)
9.	Valve weights	Normal Insp	No	CPPP-8	CPPP-8 Concern (Note 2)
10.	Clearance				
	Sleeve type	A/B Program	No	CPPP-8	CPPP-8 Concern (Note 2)

	TUGCO	ERC	SWEC	Remarks
Items	A/B Program	No	CPPP-6, 8	CPPP-8 Concern (Note 2)
Sleeve clearance	A/B Program	No	CPPP-8	CPPP-8 Concern (Note 2)
Fire walls	A/B Program	QI-25,26	CPPP-5, 8	ERC and CPPP-8 Concern for Expansion Joints Only (Note 2)
11. Piping components			CPPP-5	
12. Piping bends	Normal Insp	Q1-25,26		
	Normal Insp	QI-25,26	CPPP-8	
. Laurtions	Normal Insp	Q1-25,26	CPPP-5	
location/id	A/B Program	Q1-25,26	CPPP-5, 8	
and anterial	Normal Insp	QI-25,26	CPPP-18	CPPP-8 Concern (Note 2)
	Normal Insp	No	CPPP-8	
. identification/type	A/B Program	QI-19,27,29	CPPP-5, 8	
14e	Normal Insp	QI-19,27,29	No	
	Normal Insp	QI-19,27,29	CPPP-8	
20. Base plates 21. Integral/nonintegral attachments	Normal Insp	QI-19,27,29	CPPP-8	
	Normal Insp	QI-19,27,29	CPPP-8	
22. Support attachments	Normal Insp	Q1-19,27,29		CPTP-8 Concern (Note 2)
23. Bill of materials	Normal Insp	No	CPPP-8	CPPP-8 Concern (Note 2)
24. Class 5 continuations	Normal Insp	, No	CPPP-8	Chhb-9 concern (man
25. Insulation				

	Items	TUGCO	ERC	SWEC (Note 1)	Remarks
26.	Moment restraints	Normal Insp	Q1-51	CPPP-8	
27.	Hardware	Normal Insp	A11	CPPP-8	ERC and CPPP-8 Concern (Note 3)
28.	Clamp/support orientation	Normal Insp	QI-26,27,29	CPPP-5, 8	ERC and CPPP-8 Concern (Note 2)
29.	Clearances	Normal Insp	All	CPPP-6	

INSPECTION DESCRIPTION

TUGCO	ERC	SWEC
Normal Insp - Covered by Brown & Root Inspection Program for ASME piping	QI-19 - small bore pipe supports	CPPP-5 - initial SWEC walkdown for key attributes only
and pipe supports	QI-21 - bolted joints	accidences only
		CPPP-8 - SWEC walkdown for general at-
	QI-25 - large bore piping	tributes
A/B Program - Covered by Brown & Root Inspection Program CP-EI-4.5-1	QI-26 - small bore piping	CPPP-6 - final walkdown for clear .e
for large bore and small bore computer- analyzed piping	QI-27 & 29 - large bore pipe support	
	QI-43 - concrete placement	
	QI-51 - whip restraints	

- Note 1 A SWEC procedure is recommended (8.3) to review deviations identified by ERC.
- Note 2 Resolution of the concern is a candidate for the SVP (8.2).
- Note 3 Resolution of the concern is a candidate for the HVP (8.1).

munna

FIGURE 1
ORGANIZATIONAL INTERRELATIONSHIPS





FIGURE 2

ORGANIZATIONAL INTERRELATIONSHIPS — DETAILED FLOWCHART



ATTACHMENT 1

ACTION PLAN

- List all attributes required to fulfill the requirements of NRC IE Bulletin 79-14 and Supplements.
- Identify attributes covered under TUGCO IE Bulletin 79-14 walkdown program which are to include, but not be limited to, the following:
 - a. Procedures used for project (copy of each, plus description).

b. Report(s) of original effort.

c. Final documents resulting from TUGCO program.

d. Procedures to ensure that the documentation is kept up to date.

1) Examples from current SWEC effort.

- Include discussion of how current modifications are controlled/verified.
- Verify that attributes required by Item 1 above are included in program. If not all-inclusive, discuss action taken to verify/complete.
- 4. Describe the ERC process associated with Issue-Specific Action Plan VII.c (Construction Reinspection/Documentation Review Plan). Description is to include, but not be limited to, the following:
 - a. List procedures associated with IE Bulletin 79-14 attributes and process directives associated with pipe stress, pipe supports, piping configuration, and concrete population, if applicable.
 - b. Identify the attributes in the ERC program that are applicable to the SWEC Stress Requalification Program (SRP).
 - c. Describe ERC DR program, root cause/generic implication, and trend analysis.
 - d. Determine whether ERC should provide a copy of all DRs associated with the SRP to SWEC.
 - e. Determine whether ERC, as part of the program, should analyze all DRs that are associated with SWEC.
 - f. Compare ERC and IE Bulletin 79-14 required attributes.
 - g. Determine whether ERC should change/develop a procedure (for-malize process) for d. above.

- Describe the SWEC (SRP) Discipline-Specific Action Plan (DSAP IX).
 Description is to include, but not be limited to, the following:
 - a. List procedures associated with IE Bulletin 79-14 attributes and process directives related to pipe stress, pipe supports, and piping configuration.
 - b. Identify all attributes (documents):
 - 1) That are associated with pipe stress.
 - 2) That are associated with pipe supports.
 - c. Identify what attributes SWEC is using for the SRP.
 - 1) Identify sources of the above documents.
 - 2) Evaluate adequacy of the above information.
 - d. Evaluate document control procedure for TUGCO.
 - Determine whether ERC is looking at this under a separate ERC Action Plan and review the preliminary results.
 - Evaluate whether the documents being sent to SWEC are current.
 - e. Describe walkdowns conducted by SWEC (SRP), to include:
 - 1) CPPP-5 (2)
 - 2) CPPP-8 (1)
 - 3) CPPP-6 (to be done)

and results and implications for as-built data from these walkdowns.

- f. Determine if a formalized program should be developed by SWEC to evaluate all DRs received from ERC and NCRs from TUGCO.
 - Include consideration of generic implication, a trend analysis program, and SWEC's need to develop a procedure.
- Compare attributes of ERC and SWEC programs to ensure that all attributes associated with the SRP are examined.

If not all covered, identify verification program to examine.

- 7. Describe the overall integration of the TUGCO, ERC, and SWEC programs associated with the piping and pipe support stress program. Description is to include, but not be limited to, the following:
 - a. All SWEC walkdowns.
 - What has TUGCO done as a result of the walkdown data?

15454-N(C)-007 File R4.8 Revision 2

DOCUMENTATION OF ASME JII NA-1140 REVIEW FOR PIPING AND SUPPORTS

Prepared for

TEXAS UTILITIES ELECTRIC COMPANY (TU ELECTRIC)
COMANCHE PEAK STEAM ELECTRIC STATION
UNITS 1 AND 2

by

W. H. Green/A. J. Cokonis P. J. McQuaid

September 30, 1987

Approved by

FOR R. R. Wracke

Project Engineer - Unit 1

C. A. Fonseca

Assistant Project Manager

S. C. Chow

Manager Engineering Mechanics Division

E. H. Cloth for

R. Ryan

Assistant Manager Materials Division

R. P. Klause Project Manager

Copyright 1987
Stone & Webster Engineering Corporation
Cherry Hill Office
Cherry Hill, New Jersey

2000

TABLE OF CONTENTS .

Subject	Page
DESCRIPTION OF CHANGE	iii
BACKGROUND	1
OBJECTIVE	1
REFERENCES	1
CONCLUSIONS	2
DISCUSSION	3
GENERAL	
	3
ALTERNATES TO THE CODE OF RECORD	3
 1977 EDITION - WINTER 1978 ADDENDA Appendix O - Rules for Design of Safety Valve Installations 	3
2. 1983 EDITION NC-3658.2 - Standard Flange Joints at Moderate Pressures and Temperatures NC-3658.3 - ANSI B16.5, Flanged Joints with High- Strength Bolting	5
ND-3658.2 - Standard Flange Joints at Moderate Pressures and Temperatures ND-3658.3 - ANSI B16.5, Flanged Joints with High- Strength Bolting	
3. 1983 EDITION - WINTER 1984 ADDENDA Figure NC-3673.2(b)-1 - Flexibility and Stress Intensificat on Factors (Do/tm<100)(Branch Connections, Buttwelds, and Fillet Welds)	6
Figure NC-3673.2(b)-2 - Branch Dimensions Figure ND-3673.2(b)-1 - Flexibility and Stress Intensification Factors (Do/tm<100)(Branch Connections, Buttwelds, and	
Figure ND-3673.2(b)-2 - Branch Dimensions	

		Pag
4	1977 EDITION - WINTER 1978 ADDENDA XVII-2211 - Stress in Tension Figure XVII-2111(c)-1 - Illustrations of Maximum Design Stress in Through Thickness Direction of Flates and Elements of Rolled Shapes (Figure Deleted)	
	NF-3226 - Through Plate Thickness Tensile Limit Figure NF-3226.5-1 - Illustrations of Maximum Design Stress in Through Thickness Direction of Places and Elements of Rolled Shapes (Figure Deleted)	
	NF-3321.1 - Design Conditions	
5.	NF-3391.1 - Allowable Stress Limits (Class 2 and MC Plate/Shell)	9
	NF-3392.1 - Allowable Stress Limits (Class 2 and MC Linear)	
6.	1980 EDITION NF-1133 - Intervening Elements in Relation to Juris- dictional Boundaries	10
	NF-1131.6 - Portion F	
7.	1980 EDITION XVII-2462 - Minimum Edge Distance	11
8.	1983 EDITION - SUMMER 1983 ADDENDA NF-3225 - Design of Bolting NF-3324.6 - Design Requirements for Bolted Joints	12
9.	1983 EDITION - SUMMER 1985 ADDENDA NF-4721 - Bolt Holes	13
10.	1974 EDITION - WINTER 1975 ADDENDA NC-6221 - Minimum Required Hydrostatic Test Pressure	14
11.	1974 EDITION - WINTER 1975 ADDENDA XVII-2410 - General Requirements (for the Design of Connections and Joints)	14
12.	1980 EDITION - WINTER 1982 ADDENDA	15

Discussion

Item 9. Editorial corrections in first paragraph.

Discussion

Item 10. Complete revision of discussion to reflect the effect of pre-1974 requirements in accordance with Code interpretation III-1-83-96.

Discussion

Item 11. Second paragraph was revised to indicate that the design margin may be reduced to that inherent in the code design methods and allowables.

BACKGROUND

Safety-related piping and pipe supports on the Comanche Peak Steam Electric Station (CPSES) Units 1 and 2 are designed and constructed to the requirements of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code Section III, Division I, Rules for Construction of Nuclear Power Plant Components (Code) (Reference 1). Paragraph NA-1140(f) of the Code provides rules for the use of specific provisions within an edition or addendum, provided all related requirements are met. For CPSES piping, the Code effective date (Code of record) is the 1974 Edition, including the Summer 1974 Addenda. For pipe supports, the Code of record is the 1974 Edition, including the Winter 1974 Addenda.

Many code requirements for piping and pipe supports, at the time of and as specified within the Code of record in 1974, were either not explicitly addressed or were still under development. For example, since the first issuance of Subsection NF for component supports in the 1974 Code Edition, the requirement of intervening elements in relation to jurisdictional boundaries was not specified until the later 1980 Code Edition (see Item 6 in Discussion). In order to provide more definitive design requirements and additional Code guidance developed subsequent to the issuance of the Code of record, the design criteria for requalification of CPSES piping and pipe supports, CPPP-7 (Reference 2) invoked specific provisions of later Code editions/addenda, as permitted by NA-1140(f) of the Code of record. Review of all related requirements for these alternatives to the Code of record was performed to justify their implementation.

OBJECTIVE

This report documents the results of the review performed in order to assure that the use of specific Code provisions in CPPP-7 (Reference 2) is in conformance with Paragraph NA-1140(f) of the Code, which states:

"Code Editions, Addenda, and Cases which have not become mandatory on the contract date for a component may be used by mutual consent of the Owner or his agent and Manufacturer or Installer on or after the dates permitted by (a) through (d) above. It is permitted to use specific provisions within an Edition or Addenda provided that all related requirements are met."

The report will document compliance with the above paragraph for the alternates to the code of record, which are listed in Sections 2.1 and 2.2 of CPPP-7 and Project Memorandum PM-163 (Reference 3). Related requirements (if any) will be defined and identified, and the method of compliance to them will be explained.

REFERENCES

- American Society of Mechanical Engineers Boiler and Pressure Vessel Code, Section III, 1974 Edition
- Project Procedure CPPP-7, Design Criteria for Pipe Stress and Pipe Supports, Revision 3, February 23, 1987

- Project Memorandum PM-163, CPPP-7 Piping and Pipe Support Code Applicability Changes, May 27, 1987
- Report No. SEM-001-001, ASME Code Stress Intensification Factors for Comanche Peak Steam Electric Station - Units 1 and 2, by S. E. Moore, May 21, 1987
- Project Memorandum PM-155, Stress Intensification Factors Evaluation of Branch Connections, June 8, 1987
- Project Procedure CPPP-6, Fipe Stress/Support Requalification Procedure - Unit 1, Revision 4, April 8, 1987
- Project Procedure CPPP-9, Pipe Stress/Support As-Built Procedure - Unit 2, Revision 4, April 8, 1987
- Piping Erection Specification No. 2323-MS-100, Revision 9, July 9, 1987

CONCLUSIONS

The related requirements for the invoked special paragraphs from the later Code editions/addends have been identified, reviewed, and addressed in Items 1 through 12 of the Discussion section. CPPP-7 incorporated these special paragraphs to provide additional and more rigorous Code guidance. These alternates represent the mandatory design requirements (with the exception of nonmandatory Appendix O in Item 1) of later Code editions, but were not explicitly addressed by the Code of record.

All applicable requirements related to these elternates have been implemented and incorporated in the CPSES piping and pipe support requalification project procedures. As a result, application of all the alternates invoked in Sections 2.1 and 2.2 of CPPP-7 and PM-163 are in compliance with of Paragraph NA-1140(f) of the Code of record.

DISCUSSION

GENERAL

For the purpose of this report, the related requirements specified in Paragraph NA-1140(f) are considered to be those contained in the Subsections NC/ND for Piping, NF for supports, NA (or NCA) for general requirements, and the appendixes of the alternatives of later Code Editions/Addenda Section III. They will be reviewed and addressed with respect to the corresponding requirements in the Code of record in the following order:

- Article 1000 Introduction
- Article 2000 Materials
- Article 3000 Design
- Article 4000 Fabrication and Installation
- Article 5000 Inspection
- Article 6000 Testing (NC only)
- Article 7000 Overpressurization Protection (NC only)
- Article 8000 Nameplates
- Subsection NA (or NCA)
- Appendixes

Each of the above areas of the code will be discussed for the alternates with respect to the Code of record identified below. If there are any related requirements in Section II, Material Specifications, or Appendix I, Materials, they will be discussed under Article 2000.

ALTERNATES TO THE CODE OF RECORD

 1977 Edition - Winter 1978 Addenda Appendix O-- Rules for Design of Safety Valve Installations

Appendix O first appeared in the Winter 1978 Addenda, and it provides guidance for the design and analysis of the piping components containing safety valves, which was not available in the Code of record. It provides the safety valve load computation, the stress acceptance criteria, and general design considerations for both open and closed safety valve discharge systems. Related requirements in NC/ND-3652 and NC/ND-3643.3(c)(6) of the alternate are consistent with the corresponding paragraphs in the Code of record.

Related Requirements

Article NC/ND-1000 - Introduction

There are no related requirements affected by this change.

Article NC/ND-2000 - Materials

There are no related requirements affected by this change.

Article NC/ND-3000 - Derign

Appendix O is used to develop the SRV fluid transient forces. This appendix refers to Equation (9) of paragraphs NC/ND-3652 for the evaluation of the reaction force moment (Mb) and subparagraphs NC/ND-3643.3(c)(6) for the reinforcement of multiple openings. The Code of record is used to evaluate the above criteria, and the corresponding paragraphs were not less restrictive than the Winter 1978 Addenda criteria; therefore, the related requirements are met.

Article NC/ND-4000 - Fabrication and Installation

There are no related requirements affected by this change.

Article NC/ND-5000 - Examination

There are no related requirements affected by this change.

Article NC/ND-6000 - Testing

There are no related requirements affected by this change.

Article NC/ND-7000 - Overpressure Protection

There are no related requirements affected by this change.

Article NC/ND-8000 - Nameplates, Stamping, and Reports

There are no related requirements affected by this change.

Subsection NA - General Requirements

There are no related requirements affected by this change.

Appendixes

2. 1983 Edition

Paragraph NC-3658.2 - Standard Flange Joints at Moderate Pressures and Temperatures

Paragraph NC-3658.3 - ANSI B16.5 Flanged Joints with High-Strength Bolting

Paragraph ND-3658.2 - Standard Flange Joints at Moderate Pressures and Temperatures

Paragraph ND-3658.3 - ANSI B16.5 Flanged Jc. ats with High-Strength Bolting

The above paragraphs in the 1983 Edition were invoked for this topic because guidance was not provided by the Code of record. These paragraphs are intended for the simplified analysis of standard flanges (e.g., ANSI B16.5).

Related Requirements:

Article NC/ND-1000 - Introduction

There are no related requirements affected by this change.

Article NC/ND-2000 - Materials

Paragraphs NC/ND-3658.3 require the use of 1983 S (bolt allowable stress, psi) values, since S must be > 20,000 psi. All selected bolt materials have been checked and in fact satisfy the criteria in the 1983 Code thus allowing use of this procedure.

Article NC/ND-3000 - Design

Paragraphs NC/ND-3658.3 refer to Tables NC/ND-3673.2(b)-1 for the evaluation of the stress intensification factors of pipe to flange welds. The weld stress intensification factor used in the design is discussed in Item 3. Therefore, the related requirements have been met.

Article NC/ND-4000 - Fabrication and Installation

This section has no related requirements to NC/ND-3658.3. Bolting requirements discussed in NC/ND-4720 are identical in both years 1983 and 1974.

Article NC/ND-5000 - Examination

There are no related requirements affected by this change.

Article NC/ND-6000 - Testing

Article NC/ND-7000 - Overpressure Protection

There are no related requirements affected by this change.

Article NC/ND-8000 - Nameplates, Stamping, and Reports

There are no related requirements affected by this change.

Subsection NA

There are no related requirements affected by this change.

Appendixes

Subparagraphs NC/ND-3658.2 and NC/ND-3658.3, which apply to simplified analysis of standard flanges, do not require the implementation of Appendix XI. Appendix XI is required for detailed (ponsimplified) analysis of all types of flanges (standard and nonstandard). The code of reference can be used for an Appendix XI evaluation.

 1983 Edition - Winter 1984 Addenda Subparagraphs NC/ND-3673.2(b) - Flexibility and Stress Intensification Factors

Figure NC-3673.2(b)-1 - Flexibility and Stress Intensification Factors (Do/tm<100)(For Branch Connections, Buttwelds, and Fillet Welds)

Figure NC-3673.2(b)-2 - Branch Dimensions

Figure ND-3673.2(b)-1 - Flexibility and Stress Intensification Factors (Do/tm<100)(For Branch Connections, Buttwelds, and Fillet Welds)

Figure ND-3673.2(b)-2 - Branch Dimensions

The 1983 Edition/1984 Winter Addenda (1983-W84) stress intensification factors (SIFs) formulation for run pipe/branch connections 's invoked because SIF for the run pipe end moment loads was not speci in the 1974 Code of record.

An independent review (Reference 4) performed by S. E. Moore, cluded that the 1983-W84 SIF formulation for branch connections, butt word, and fillet welds is acceptable for CPSES piping requalification the one exception. That exception is that the use of General Note 2. Figures NC/ND-3673.2(b)-2 will be less restrictive than the Code of record. Consequently, Project Memorandum PM-155 (Reference 5) was issued, which specified the use of adjustment factors to provide sufficient margin in the calculated stresses and obviate this concern.

Related Requirements:

Article NC/ND-1000 - Introduction

Article NC/ND-2000 - Materials

There are no related requirements affected by this change.

Article NC/ND-3000 - Design

The branch connection stress intensification formulation of the 1974 code was not specified; hence it was necessary to use the later editions. S. E. Moore reviewed the related requirements for the 1983-W84 SIF formulations for branch connections and additionally for girth butt welds and circumferential fillet welds. The review results, documented in Reference 4, concluded that the use of 1983-W84 formulation is acceptable, with the exception of General Note (2), Figures NC/ND-3673.2(b)-2 for the branch connection. Consequently, PM-155 (Reference 5) was issued to address the related requirements for the branch connection. The other items, girth butt welds and circumferential fillet welds, are addressed in CPPP-7.

Article NC/ND-4000 - Fabrication and Installation

There are no related requirements affected by this change.

Article NC/ND-5000 - Examination

There are no related requirements affected by this change.

Article NC/ND-6000 - Testing

There are no related requirements affected by this change.

Article NC/ND-7000 - Overpressure Protection

There are no related requirements affected by this change.

Article NC/ND-8000 - Nameplates, Stamping, and Reports

There are no related requirements affected by this change.

Subsection NA

There are no related requirements affected by this change.

Appendixes

There are no related requirements affected by this change.

4. 1977 Edition - Winter 1978 Addenda
Paragraph XVII-2211 - Stress in Tension
Figure XVII-2211(c)-1 - Illustrations of Maximum Design Stress in
Through-Thickness Direction of Plates and
Elements of Rolled Shapes (Figure Deleted)
Paragraph NF-3226 - Through-Plate Thickness Tensile Limit

Figure NF-3226.5-1 - Illustrations of Maximum Design Stress in Through-Thickness Direction of Plates and Elements of Rolled Shapes (Figure Deleted)

Paragraph NF-3321.1 - Design Loadings

Invoking these paragraphs deletes the original code requirement to use reduced allowables with through-thickness tensile stress in plates or rolled sections. The original code concern was that high applied through-thickness stress in plates and rolled sections might increase the possibility of lameliar tearing (subsurface splitting of the material parallel to its rolled surfaces). The original Code-amposed limits on the through-thickness allowable tensile stress had the effect of requiring the designer to increase the weld size to achieve the lower allowable stress. Later, the Code committee recognized that excessive weld size increases the joint's susceptibility to lamellar tearing due to increased weld residual stresses.

The 1977 Edition, Winter 1978 Addenda (1977-W78) code edition for these paragraphs deleted the requirement to reduce the allowable stress in the through-thickness direction. This, in effect, reduces the weld size. It recognizes that smaller welds induce less residual stress, which can cause lamellar tearing, and that this has a more beneficial effect than a larger weld with lower calculated applied stresses.

The above alternates to the Code of record address Class 1 plate and shell and Class 1 linear supports. Through thickness stresses for Class 2 and MC and for Class 3 are addressed in subparagraph NF-3391.1 for plate and shell designs, and subparagraph NF-3392.1 for linear designs (see next Item 5).

Related Requirements

Article NF-1000 - Introduction

This article addresses scope, owner's responsibility, boundaries, and types of supports and attachments and is not affected by the deletion of a rule for a calculation of a specific type of stress. Therefore, there are no related requirements affected-by this change.

Article NF-2000 - Materials

No materials have been added or deleted, nor have there been any changes to the requirements for test coupons, fracture toughness, welding, or examination, which are directly related to through-thickness properties. Therefore, there are no related requirements affected by this change.

Article NF-3000 - Design

No other stress criteria has been added or deleted in the Winter 1978 addenda or later to compensate for this change. Therefore, there are no related requirements in this article affected by this change.

Article NF-4000 - Fabrication and Installation

There are no related requirements affected by this change.

Article NF-5000 - Examination

The Winter 1978 Addenda of this article is more restrictive for welds with a groove or throat dimension of 1 in. or greater, requiring surface examination (magnetic particle or liquid penetrant) instead of visual examination. However, the Code committee position for the removal of reduced allowables for through-thickness stress is related to lamellar tearing. Surface examination methods are effective only for detecting flaws which come to the surface. The addition of surface examination requirements to the Code is not related to the deletion of the reduced allowables. Considering this, there are no related requirements.

Article NT-8000 - Nameplates, Stamping, and Reports

There are no related requirements affected by this change.

Subsection NA

There are no related requirements affected by this change.

Appendixes

The related requirements in Appendix XVII are addressed automatically by reference in Subsection NF. There are no other requirements in the appendices related to this change.

 1977 Edition - Winter 1979 Addenda Subparagraph NF-3391.1 - Allowable Stress Limits Subparagraph NF-3392.1 - Allowable Stress Limits

See prior discussion on through-thickness stresses. These paragraphs apply to Class 2 and MC plate and shell (NF-3391.1) and linear (NF-3392.1) support designs.

6. 1980 Edition
Paragraph NF-1133 - Intervening Elements in Relation to Jurisdictional Boundaries
Subparagraph NF-1131.6 - Portion F

Intervening elements were introduced into Section III of the ASME Code through Code Case N-199 and the Summer 1978 Addenda to allow items in the load path to be used when these items met other standards or were not appropriate for Section III. Items such as non-pressure retaining portions of ASME III control valves to which ASME III NF supports are attached are considered intervening elements. The appropriate paragraphs of the 1980 Edition were invoked in order to apply this criteria to the project, which was not available in the Code of record.

Related Requirements

Article NF-1000 - Introduction

There are related requirements. They are contained in paragraph NF-1111, Owner's Responsibility for Component Supports, which requires that the Owner 1) ensure that the intervening elements are adequately designed and 2) provide specific information in the design specification, and in paragraph NF-1112, Owner's Review, which requires that a design verification report be provided.

The method for satisfying these related requirements is contained in CPPP-6 and CPPP-9 (References 6 and 7).

Article NF-2000 - Materials

No materials have been added or deleted nor have there been any changes to the subsections on test coupons, fracture toughness, welding, or examination, which are directly related to intervening elements. Therefore, there are no related requirements affected by this change.

Article NF-3000 - Design

No other stress criteria has been added or deleted to compensate for this change. Therefore, there are no related requirements affected by this change.

Article NF-4000 - Fabrication and Installation

There are no related requirements affected by this change.

Article NF-5000 - Examination

There are no related requirements affected by this change.

Article NF-8000 - Nameplates, Stamping, and Reports

Subsection NA

There are no related requirements affected by this change.

Appendixes

There are no related requirements affected by this change.

1980 Edition Paragraph XVII-2462 - Minimum Edge Distance

The paragraph in 1980 Code Edition provides the minimum edge distance criteria with requirements imposed on the ultimate strength, material thickness, and bearing stress of the plate holes. The 1974 Code of record empirically prescribed the tabular values, based on the traditional practice of limiting the ratio of edge distance to the bolt diameter between 1.25 to 1.8. The 1980 Code provision was invoked to incorporate the alternates for minimum edge distance, which provides a more rigorous, complete, and precise rule to prevent the tear-out failure or excessive deformation of the plate.

Related Requirements

Article NF-1000 - Introduction

There are no related requirements affected by this change.

Article NF-2000 - Materials

No materials have been added or deleted nor have there been any changes to the subsections on test coupons, fracture toughness, welding, or examination, which are directly related to minimum edge distance criteria. Therefore, there are no requirements directly related to this change.

Article NF-3000 - Design

No other stress criteria has been added or deleted to compensate for this change. Therefore, there are no requirements directly related to this change.

Article NF-4000 - Fabrication and Installation

There are no related requirements affected by this change.

Article NF-5000 - Examination

There are no related requirements affected by this change.

Article NF-8000 - Nameplates, Stamping, and Reports

Subsection NA

There are no related requirements affected by this change.

Appendixes

This change is in Appendix XVII and there are no related requirements in this or any other appendix affected by this change.

1983 Edition - Summer 1983 Addenda
 Subparagraph NF-3225 - Design of Bolting
 Subparagraph NF-3324.6 - Design Requirements for Bolted Joints

The Summer 1983 Addenda is invoked for the design of bolting to enable the updated allowable stresses in the 1983 Edition to be used in support designs. In particul. Appendix F was upgraded by the addition of explicit tension are requirements for bolting design for the faulted condition. Also, for bolts loaded in combined tension and shear, the three straight-line interaction curves of the Winter 1974 Addenda have been replaced by a more precise elliptical interaction curve of the second degree. The newer code provides a clearer treatment of the subject.

Related Requirements

Article NF-1000 - Introduction

There are no related requirements affected by this change.

Article NF-2000 - Materials

No materials have been added or deleted nor have there been any changes to the subsections on test coupons, fracture toughness, welding, or examination, which are related to the design of bolting. Therefore, there are no related requirements affected by this change.

Article NF-3000 - Design

No other stress criteria has been added or deleted to compensate for this change. Therefore, there are no related requirements affected by this change.

Article NF-4000 - Fabrication and Installation

There are no related requirements affected by this change.

Article NF-5000 - Examination

Article NF-8000 - Nameplates, Stamping, and Reports

There are no related requirements affected by this change.

Subsection NA

There are no related requirements affected by this change.

Appendixes

The related requirements in Appendix F are addressed automatically by specific direction in Table NF-3225.2-1 of the Code of record. There are no other related requirements affected by this change.

 1983 Edition - Summer 1985 Addenda Paragraph NF-4721 - Bolt Holes

The Code of record in the Winter 1974 Addenda did not address holes for concrete anchor bolts. In the Winter 1974 Addenda, this paragraph addressed only oversized holes and a method of fabricating holes. The Summer 1985 criteria provides more detail on hole size requirements, provides new criteria for long-slotted and short-slotted holes, addresses holes for concrete anchors and holes for no-shear applications, and provides direction for use of washers. This newer criteria provides clearer direction and additional coverage in the support designs.

Related Requirements

Article NF-1000 - Introduction

There are no related requirements affected by this change.

Article NF-2000 - Materials

No materials have been added or deleted nor have there been any charges to the subsections on test coupons, fracture toughness, welding or examination, which are directly related to bolt hole clearances. Therefore, there are no related requirements affected by this change.

Article NF-3000 - Design

No other stress criteria has been added or deleted to compensate for this change. Therefore, there are no related requirements affected by this change.

Article NF-4000 - Fabrication and Installation

Article NF-5000 - Examination

There are no related requirements affected by this change.

Article NF-8000 - Nameplates, Stamping, and Reports

There are no related requirements affected by this change.

Subsection NA

There are no related requirements affected by this change.

Appendixes

There are no related requirements affected by this change.

10. 1974 Edition - Winter 1975 Addenda Paragraph NC-6221 - Minimum Required System Hydrostatic Test Pressure

The Winter 1975 Addendum revised the minimum completed system hydrostatic test pressure from 1.5 times to 1.25 times the design pressure. This, in effect, restored the pre-1974 code requirement of 1.25 times the design pressure as documented in Code Juterpretation III-1-83-96.

This Code interpretation identifies the Code of Record requirement as an error, the correction of which should have been identified as Errata in the Summer 1975 Addenda. Therefore, there are no related requirements affected by this change.

 1974 Edition - Winter 1975 Addenda Paragraph XVII-2410 - General Requirements (for the Design of Connections and Joints)

This paragraph addresses: types of connections permitted (XVII-2411), minimum design strength of connections (XVII-2412), provision for eccentric connections (XVII-2413), and placement of bolts and welds (XVII-2414). Only Subparagraph XVII-2412 was affected by the adoption of the Winter 1975 Addenda; it was deleted in its entirety. Subparagraph XVII-2412 stated, "Connections carrying calculated stresses, except for lacing, shall be designed to support not less than 6 kips."

The welds are designed on an as-loaded basis. There is sufficient inherent margin in the design using allowables of welds from the Code of record.

Related Requirements

Article NF-1000 - Introduction

Article NF-2000 - Materials

There are no related requirements affected by this change.

Article NF-3000 - Design

There are no related requirements affected by this change.

Article NF-4000 - Fabrication and Installation

There are no related requirements affected by this change.

Article NF-5000 - Examination

There are no related requirements affected by this change.

Article NF-8000 - Nameplate Stamping and Reports

There are no related requirements affected by this change.

Subsection NA

There are no related requirements affected by this change.

Appendixes

There are no related requirements affected by this change.

1980 Edition - Winter 1982 Addenda Paragraph NF-3324.5

Paragraph NF-3324.5 of the 1980 Edition, Winter 1982 Addenda, gives the design requirements for welds on Class 1, 2, 3, and MC linear type supports. Prior to this version, this information was given in Paragraphs NF-3292, NF-3293, NF-3392, NF-3393, and NF-3400; the general reorganization of Article NF-3000 in the 1980 Edition, Winter 1982 Addenda regrouped the design requirements by support type (i.e., plate and shell supports and linear supports) as opposed to Class 1, 2, 3, or MC in the Code of record.

This alternative to the Code of record was invoked because it contains a much greater degree of detail in its discussion of allowable stress limits which must be satisfied for design loadings and of rules and stress limits which must be satisfied for Level A through D service test loadings. In addition, this alternative to the Code of record recognizes several different permissible weld types absent from the Code of record.

Related Requirements

Article NC-1000 - Introduction

Article NC-2000 - Materials

There are no related requirements affected by this change.

Article NF-3000 - Design

There are no related requirements affected by this change.

Article NF-4000 - Fabrication and Installation

There are no related requirements affected by this change.

Article NF-5000 - Examination

There are no related requirements affected by this change.

Article NF-8000 - Nameplate Stamping and Reports

There are no related requirements affected by this change.

Subsection NA

There are no related requirements affected by this change.

Appendixes

STONE & WEBSTER ENGINEERING CORPORATION

CALCULATION TITLE PAGE

NOTED APR 0 9 1986 LOCKING

CLIENT & PROJECT	EMD	- GENER	c/_	PAGE	1 OF	1	14.11
Stress Intense Fabricated from	E (indicative of the Objective Excation Pactors for I "Welded-In" Piping to 331.1 Pipe Stress Anal	Lateral Brand to be used in	hes	6 :	- NUC	ETY REL	
J. 0. OR W.O. NO.	DIVISION & GROUP	CURRENT	OPTIONAL			TIONAL	NO.
599:470.1.01	MP (B)	75	76				
PREPARER (3) / DATE (NATURE & DATE KOTEL		ME Y	W CA	RSEDES LC. NO. EV. NO.	CONFIRM REQUI	
L.Raghavan L.Raghavan L.Raghavan	GARENA Jun 3.17-82	G ARENA D Gura	Rev	. O N/	'A		x
L.Rayna		9. Jun 5.5.82	REV	1 1	/A	×	×
		DISTRIBUTIO)N •				COPY
GROUP	NAME & LOCATION	SENT	GROUP	NAME	& LOCA	TION !	SENT
RECORDS MGT. FILES (OR FIRE FILE IF NONE) EMO FILES	M HYNES 2448 DA Van Dyne 245/8 RF Hankman	0 7 7 7 7					

	culation No			(G) - 75-X6
Thi	is calculation has been r	eviewed in accor	dance with Ex	TP 8.26 and was
	Comparison with a simil	ar previous Calc	ulation No	·
(b.)	Review of calculation.			
c.	Alternate Calculation N	ю		
		Signature of Revi	ever	3-/7-82 Date
		Signature of Inde Reviewer (where of from Reviewer)	pendent ifferent	Date
	REV1	Suy fres	REVIEWER	5/5/82 DATE

STONE & WEBSTER ENGINEERING CORPORATION CALCULATION SHEET

9010 68	CALCULATION IDENTIFICATION NUMBER				
JO. OR W.O. NO. 599. 470. 1-01	DIVISION & GROUP	CALCULATION NO.	OPTIONAL TASK CODE	PAGE 3	

REVISION STATUS

REVISION O

ORIGINAL ISSUE

REVISION 1

PAGES REVISED: 13

PAGES ADDED : N/A

PAGES VOIDED : N/A

REASON FOR CHANGE : DELETED CODE SUBPARAGRAPH REFERENCE

IN CONCLUSION NOTE > 1.

5010 65	CALCULAT	ON IDENTIFICATION N	UMBER	
J.O. OR W.O. NO. 590.470-1-01	NPCB)	CALCULATION NO. 75	OPTIONAL TASK CODE	PAGE 4
	TABL	E OF CON	TENTS :	
			PAGE	
	TITLE P	AGE	1	
		STATEMENT	2	
	REVISION	HISTORY SHEE	т 3	
	TABLE O	F CONTENTS	4	
	NOMENCL	ATURE	s	
1-0	DEJECT	IVE	6	
2.0	Assume	TIONS	7	
2.0			8	
3.0	. REFE	ZENCES		
4.0	AMALY.	515	9-11	
. 5.0	SAMMA	RY OF RESULT	5 12	
6.0	CONC	-0510115	13	
	1 1 1 1		ES 14-27	
7.0	TABLE	S AND FIGUR	7	
		14	and an extended the same first to the same for all the same states and the same states are same states as the same states are same st	
		-		

	CALCULAT	ION IDENTIFICATION N	UMBER			
The state of the s		CALCULATION NO.	OPTIONAL TASK CODE	E PAGE 5		
	THE LAND					
Nomenciature		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1				
D and R = mean pix d and r = mean br. T = thick t = thick s/S = const const fill tee A, = $\rho^2(1 - \frac{\tau}{4})$ = cross due A, and ρ_0 = exter	ectional area of reinfor e to fillet in horizontal p nal fillet radius of	on C _L and C _{SL} (d/t)/ external C _S ees and cotch of C _{IS} cement C _{OS} lateral ICos	pipe and plane tively = experimental press tion = experimental limit pipe = stable experimenta couple = stable experiment limit couple = unstable experiment	pressure of con ipe ouple of plan branch respec- ure in connec- couple of plan in-plane limital al out-of-plan		
wh	ere crotch makes an actuse angle, respectively age yield strength of con	ute and Cp4	plastic couple theoretical limit couple of pi pipe at constant internal press			
	annice .	or(1)	types of tensile tests i			
to p	oretical elastic axial st internal pressure of ipe with closed ends had densions of branch or pectively	a plane aving di-	to internal press pipe with closed mensions of the respectively referring to eas or ea	essure of a planted ends having done branch or pip		
	rring to eig or eip	628	= experimental elast			
er ir	ic stress ratio in thin p reposed to axial force a ig tic stress ratio in this ue to Fg and C/g	nd beed.	due to internal pr = axial force acting o differences in ma constituting the li = theoretical elastic	n branch due to gnitude of force mit couple extremum axis		
D _N = Box	ninal diameter of pipe	of welcom	strain due to an having dimension pipe, respectively = referring to eca or ec	of branch an		
		F.	experimental axial ternal couple me to neutral axis exerage of magnitu	strain due to ex asured at 90 de		
		·	stituting limit con	iple		

STRESS INTENSIFICATION FACTORS (SIF)

FOR UNREINFORCED LATERAL BRANCH CONNECTIONS

1.0 OBJECTIVE.

Paragraph NC 3650 of the ASME Section III, (12)*, code provides a method of analysis of class 2 and 3 piping products. The analysis utilizes Stress Intensification Factors (SIF) along with some simple equations to establish acceptable limits on stresses.

Figure NC 3673.2(b)-1, (12)*, provides SIF's for commonly used standard piping products. For non-standard piping products NC 3673.2(b), (12)*, states that SIF may be taken as $C_2K_2/2$ where C_2 and K_2 are class 1 stress indices given in Table NB 3682.2-1, (12)*. Lateral branch connections are not among the components for which SIF or C_2 and K_2 stress indices are available. Thus, code evaluation of lateral branch connection by simplified analysis is not possible.

The purpose of this calculation is to establish a method to derive an appropriate SIF for use in the evaluation of lateral "stub-in" branches using NC-3650 rules, (12)*, based upon the results of a published literature survey.

^{*} Numbers in () indicate reference numbers listed in Section 3.

0.7, 0.8, 0.9, 0.95, 1.0 indicates increments will be used applying to 70%, 80%, 90%, 95%, and 100% of the load history (as defined on the loading cards).

- 4. TIMEP is the period of this analysis step. Default value is one which means that normalized time is used.

 Note: this time period for static analysis is not accumulated over different steps. The time period must be non-zero.
- 5. NUMBER this parameter is used to initiate the automatic load incrementation option and to suggest the increment size. For example, NUMBER = 5 will make the first increment equal to 0.2 of the total time. However, the program will now adjust the time increment based on the number of cycles needed in each increment with the limitation being that the time increments will not be larger than 0.2 of the total time.

Note: NUMBER and DIRECT are mutually exclusive parameters.

6. CUTMAX - the maximum number to times the suggested uniform increment size may be subdivided.

J.O. OR W.O. NO. 599. 470-1-01							
	Z.O ASSU	MPTIONS		CONFIRMATI REQUIRED (
				YES	NO		
connection		at unreinforced last o be indicative of avior.			x		
tubular join	ent stress indices nts (no hole at the nch connections.	(c, and k,) are see intersection) as	ame for . well		x		
3, All other as	ssumptions are not	ed in the body of	the text.		x		
		4					
				*			

3.0 : References:

- Markl A.R.C., "Fatigue Tests of Piping Components"- Transactions ASME, April 1952, pp. 287-303.
- Schroeder, J., Srinvasaich, K.R., and Graham, P., "Analysis
 of test data on branch connections exposed to internal pressure
 and/or external couples", Bulletin No. 200, Welding Research
 Council, New York, 1974.
- Kuang, J.G., Potvin, A.B., and Leick, R.D., "Stress concentrations in Tubular Joints", Paper No. OTC 2205, Off-Shore Technology conference, Houston 1975.
- 4. Hsiao C. and Kahn. A.S., "Stress intensification effects in unreinforced oblique branch intersections due to external moments" PVP Volume 50 ASME, New York 1981.
- Wichman, K.R., Hopper A.G., and Mershon, J.L., "Local Stresses in spherical and cylindrical shells due to External Loadings" Bulletin No. 107, Welding Research Council, New York.
- Visser W. " On the structural design of tubular joints" OTC 2117 Proc. Sixth Annual Off-Shore Technology Conference, Houston (May 6-8, 1974) Volume II pp. 881-894
- 7. Reber, J.B. Jr. "Ultimate Strength Design of Tubular Joints" OTC 1664 Proc. Fourth Annual Off-Shore Technology Conference Houston (May 1-3, 1972) Volume I pp. 447-458
- Beale L.A. and Toprac, A.A. "Analysis of in-plane T,Y, and K Welded Tubular Connections" Welding Research Council Bulletin 125 Oct. 1967 pp. 1-30.
- 9. Gurner, T.R., "Fatigue of Welded Structures" Second Edition 1979 Cambridge University Press.
- Khan, A.S. and Hsiao C., "Strain Field in the intersection region of two obliquely inclined straight cylindrical shells, An Experimental Study". Submitted for publication in "Experimental Mechanics".
- Mukhopadhyay A., Itoh, Y., Bouwkamp, J. G., "Fatigue Behavior of Tubular Joints in Offshore Structures", OTC 2207, Seventh Annual Offshore Technology Conference, Houston (May 5-8, 1975).
- 12. ASME Boiler and Pressure Vessel Code, Section III, 1980 Edition.
- 13. ANST B31-1, American National Standard Code for Pressure Piping, Power Piping, 1977 Edition.

4.0 ANALYSIS

Stress intensification factors (i) for various piping components are, in large part, based upon Markl's (1)* approach and test data generated by his work.

The Markl cyclic moment fatigue tests did not cover lateral branch connections and code does not provide either 'i' factors or C_2 , K_2 stress indicies for lateral branch connections. Several authors have investigated this problem and references (2)*, (3)*, and (4)* are some of the significant published reports.

WRC Bulletin 200 (2)* reports and analyzes test data on branch connections including unreinforced laterals exposed to internal pressure and/or external couples. Tests were conducted on plain pipes, tees (normal branch connections) and 45° laterals, to determine "limit loads" of the components when subject to internal pressure, in-plane and out-of-plane bending moments. No fatigue tests were conducted.

Figures 1 and 2, (2)*, show results of in-plane couple tests on a 45° lateral and a 90° normal branch connection, both of identical dimensions except for the angle of branch connection. Table 1, (2)*, summarizes the data and test results as well. From these figures and table, it is clear that the limit load for the lateral is higher compared to that of 90° tee indicating that the laterals are plastically stronger than tees. The same conclusions are arrived at for out-of-plane couples as observed by test results shown in figures 3, 4, and 5 and Table 2, (2)*. However, as observed in the Pe/P₁p column in Table 1, (2)*, the following is concluded:

- Laterals are plastically stronger than 90° branch connections when subjected to external bending moments.
- Laterals are plastically weaker compared to tees when exposed to internal pressures.

Conclusion 2 is drawn as a point of interest since in class 2, 3, and B31.1 stress analysis, the pressure loading terms are not intensified. The branch construction need only meet the local pressure reinforcement requirements stated in the applicable codes.

While reference (2)* conducted tests on 45° lateral branch connections only reference (3)* reports results of tests conducted on tubular joints laterals with angle of branch connections ranging from 0° to 90°. Reference (3)* presents the finite element model analytical results as well as results of experimental investigations and provides stress concentration factor (SCF) for radial thrusts loads, in-plane, out-of-plane bending moments applied to both normal and lateral branch connections. The SCF value reported does not represent maximum or peak stress in the joint, but rather the equivalent of the maximum primary plus secondary membrane plus bending stresses as represented by the C2 stress indices of NB 3650.

^{*} Numbers in () indicate reference numbers listed in Section 3.

B2-12241-9

^{**} FIGS. \$TABLES POLLON CONCLUSION SECTION

J.G. Kuang, et al, (3)* performed a parametric study to best fit the experimental results to those arrived at by finite element analysis. The following parameters that govern the stress distribution in branch connections were chosen: the run thickness to diameter ratio T/D, the branch the run pipe thickness ration t/T, the branch to run diameter ratio d/D, and most significantly to our current investigation, the angle of branch connection. The T/D and t/T ratios govern the stress distribution by influencing the radial flexibility of the run pipe (Figure 6), (3)*, and by bending stress in the branch at the intersection. The d/D ratio and the angle of branch connection influence the stress distribution by the load transfer mechanism.

When a tee is subjected to axial branch loading, the load is transferred to the run primarily via local bending and punching shear. As a result if the branch is inclined at other than 90° only the component of the load normal to the run wall is of primary concern, as the horizontal component is transferred by compression or tension in the run.

Reference (3)* developes empirical equations to derive SCF's based on the parameters discussed a ove. The applicability and accuracy of the empirical equations developed were verified by comparing the test results to results obtained by the empirical equations. Figure 7(3)* shows good agreement between the experimental and analytical results. The empirical expression for radial loads, in-plane, and out-of-plane bending loads contain a multiplying term $\sin^2\theta$ where θ is the angle, of branch connection, [see Table 3] and 'a' is a constant greater than zero. This indicates that the maximum stress for the branch connection and SCF increases as the angle θ increases, $0^{\circ} \leq \theta \leq 90^{\circ}$.

Several other researchers' investigations, (6)*, (7)*, and (8)* have resulted in empirical equations for SCF's that include a sin θ term reinforcing the conclusion arrived at in reference (3)*. Table 4, (9)*, also indicates the agreement between the results arrived at by various authors.

Reference (3)* imposes a set of limitations on geometric parameters to minimize dispersion between experimental and analytical results. Most important of them are:

- 0.2 ≤ t/T ≤ 0.8
- 0.3 ≤ d/D ≤ 0.8
- · 0° 5 0 5 90°

As mentioned earilier, the SCF derived in reference (3)* is akin to C_2 stress indices of the code. From reference (3)* it is clear that the SCF and therefore, C_2 for laterals are lower thean 90° branch connections. By considering the geometry, branch and lateral connections must have similar K_2 indices and thus the product of C_2K_2 for laterals will always be lower than that for branches. Therefore stress intensification factor 'i' which is equal to $C_2K_2/2$ (NC 3673.1(b)) for laterals will always be lower than that for 90° branches.

^{*} Numbers in () indicate reference numbers listed in Section 3.

While it is true that Reference (3)* deals with tubular joints, (no hole at the run-branch intersection) the same conclusions are arrived at by C. Hsiao and A.S. Kahn (4)* for piping intersetions. C. Hsiao, et al, present the result of finite element investigation of 5 x 3 brench connections for three branch angles, namely 30°, 60°, and 90°, subjected to in-plane and out-of-plane loads.

The output of the finite element analysis in the form of membrane stresses and bending moments in the local coordinates are properly combined to obtain total stresses at the run/branch pipe intersection. These stresses are divided by "beam type stresses" (= M/Zr) for the known applied in-plane and out-of-plane moment to obtain a "stress ratio". Here M is the applied moment and Zr the elastic section - modules of the run pipe. The stress ratio thus obtained are compared to the experimental data, (10)*, for in-plane and out-of-plane loadings available for 30° and 60° branch connection angles. Figures 8, 9, 10, and 11, (4)*, exhibit good agreement between the experimental and analytical results. Reviewing figures 12 through 20, (4)*, indicate that the stress ratio increases with the increase in the angle of branch connection thus confirming results of reference (3)*.

Reference (11)* provides a basis to evaluate the fatigue capacities of a lateral in comparison to a 90° branch of equal size under equivalent loading conditions. Figure 21 results indicate a trend to initial failure (crack initiation) occurring at 90° branches sooner than at equivalent laterals and complete failure (through-wall crack) predominantly occurring in 90° branch connections. The tests were run using stress ranges above those allowed by the piping codes for a 7,000 cycle life. The laterals withstood greater than 7,000 cycles in all cases. These trends indicate that a lateral is less sensitive to cyclic damage than its equivalent 90° branch.

^{*} Numbers in () indicate reference numbers listed in Section 3.

5.0 SUMMARY OF RESULTS

- Under a single load to failure, the lateral branch connection is stronger plastically than the normal branch connection.
- Under cyclic loading the lateral branch connection has greater fatigue strength than a normal branch connection.
- Laterals are plastically weaker compared to tees when exposed to internal pressure.
- 4. While reference (3)* tests are on tubular joints the results are applicable to branch connections considering the similar conclusions arrived at in reference (1)* and (4)*.
- 5. Reference (3)* imposes geometric parameter limitations for the empirical expressions for SCF to be valid. However, it is reasonable to assume that the dispersion between experimental and analytical results for tees and laterals will be in the same direction so that the laterals SCF's will always be lower than that of tees even outside the geometric limitations.

^{*} Numbers in () indicate reference numbers listed in Section 3.

6.0 CONCLUSIONS

- In a piping analysis a lateral branch connection can be safely analyzed similar to a normal branch connection for class 2 and 3 and non-ASME pipes.
- 2. In general the results of this investigation indicates that unreinforced fabricated lateral connections are stronger than corresponding 90° connections. It is expected that this same conclusion could be drawn for reinfored lateral connections as well. However, until more data becomes available to confirm this it is recommended that a factor be applied for additional conservatism in the calculation of stress intensification factors (SIF) for leterial connections.

The SIF for either an unreinforced or reinforced connections may be determined by calculating the SIF for an equivalent 90° connection and increasing it by 25 percent.

- The above must be subjected to the following restrictions:
 - The branch connections must meet all the pressure reinforcement requirements of NC 3643 of ASME Section III or ANSI B31.1 Paragraph 104.3.1.
 - The branch connection angle (the angle between the run and branch pipe axes) is between 45° and 90° both inclusive

- ASME Section III code version is limited to the summer 1981 addenda and earlier. Winter 1981 addenda requires that pressure terms be modified by "B" indices.
- The use of lateral branch connections would be restricted to ASME Class 2 and 3 and B31.1 systems; insufficient data exists to draw conclusions for Class 1 applications.


^{*} Numbers in () indicate reference numbers listed in Section 3.


J.O. OR W.O. NO. DIVISION & NP							ATION NO.		OPTIONAL TASK CODE		
				TABLE	1:			REF :	2 7	١, معاملد	
						Umit Pressu	on Facto				
N TT		d D 1 0.63 0.83 1 1 0.63 1 1 0.63 1 1 1 0.77	D T 33 35 26 25 31 34.5 26.8 29 26.8 14.6 17	0.9	32 4T 28 4T 8T 8T 8T	(Asri) 33.3 31.4 40.4 36.5 28.2 35.0 30.3 31.6 30.3 35.7 38.9 33.9	PLP (Asi) 2.02 1.80 3.11 2.92 1.82 2.03 2.25 2.18 2.26 4.89 4.57 3.94	Ps (kmi) 1.45 1.40 1.88 1.8 ± 0 2.1 0.78 0.80 1.15 0.87 ± (3.4 2.1 2.5	1.16 0.39 0.35 0.51	1 3 3 3 3 1 1 1 1 4 4 4 4 4 4 4 4 4 4 4	20 21 22 23 24 25 26, 27 28 29 30, 32 31, 33 34
The	prod P	1 ,	a of all la	terrals is 45	BLE			REF 2	Tab	than a fillet.	
Connector Pipe		D * S 21 41 24 1 25 1 25 1 27 1	0.14 2 0.37 3 0.28 9	28.7 (Az.) 28.7 (Az.) 28.7 (Az.) 28.7 (Az.) 27.7 (Az.)	PLP CL (heri) (D	of Plain Pipe or Cal P p-kip) (kai) 13.0 11.8 0.78 14.6 7.3 0 12.5 0 12.5 0 14.2 0 15.4 1.0 15.5 0 15.5 0	C 2 0 (in-	# C / S C S ()	C12 P 0.86 0.83 0.96 0.91 0.84 0.96 0.96 0.96 0.96 0.96 0.96	2 dial 2 55 2 2	7 ig. N for test des 37 38 40 41 (2, 43, 45 46 47
The	hranch-	pipe angie	e of all l		des. Con of	P. is 27.8 in.	kip.				
-		-041	a on Out-o			ts and Plastic	ally Uns	rtable Out-e	-Mane Cour	1000	F
Course F PA No. T. T. T. T.	0 ! 0 ! 0 !	25 34.5 33 22 25 42	1 0 0.55 0 1	Af 2T 22 3.5T 6T 07 2T 34 6T 044 5T	(ksi) (ksi) (ksi) 33.6 29.5 33.2 31.4 24.1 31.0 1.	7 8 20.2 16.1 54.0 23.1	P C. (in-	6 0.72 4 0.90	(iA-Aip) C >7.8 9.7 0	Cos dial 1 2 2 1.48 1 1.59 1 1.49 3 2	Fig. N for test do 50 51 52 54 55, 5
					-		-		-	-	NAME OF TAXABLE PARTY.

TABLE 3 (REE 3 Table 3)

A 5010 65	TABLE 3 (REF 3 Table 3)	
J.O. OR W.O. N	O. DIVISION & GROUP CALCULATION NO. OPTIONAL TASK CODE PAG	15
590.470.1	01 NP(B) 75 X6	
STRESS CON	NCENTRATION FACTORS FROM SPES472, OTC 2205 AUG	, 1977
1	T, Ychan = 1.177 (To)-0808 = 1.2(00) (ty) 1.333 (02)-0.057 sin 1.6946	Τ-
	T, Y orand= 2.784(To)-0.55 e-1.35(do)3(t/)(D/)-0.12 sin'.94 6	7-
2013	Kalord = 0.949 (76) -0.666 (46) -0.059 (54) 1104 (36) 0.067 sin 1.5216	T-
	Kananch = 0.825 (1/6) -0.15) (1/6) -0.441 (1/7) 0.560 (1/6) 0.058 e 1.440 sind	т.
	T.Kchard = 1.26 (T/D) -0.54 (d/D) 0.12 (t/T) 1.068 sin +	Τ-
	T. Keranch = 5.65(T/D) -0.1(d/D) -0.36 (t/T) 0.68 (9,+92) 0.126 sin 0.50	Τ-
514	T, KBranch = 12.88 (76) -01 (0/6) -0.36 (4/7) 0.68 (91+92) 0.126 sin 2.880	Т-
	Tol T, K = 4.491 (To) -0123 (do) -0.396 (t/) 0.672 (31+92) 0.159 sin 2.2674	7-1
1	T,Ycom= 0.463 (T/p) -0.6 (d/p) -0.04 (t/) 0.86 510 0.57 0-	T-1
N. FLANE BENDING	T.Y Brand = 1.109 (7/6) -0.23 (d/6) -0.38 (t/7)0.38 sin 0.21+	T-1
	Kcharl = 1.40 (T/0)-0.38 (d/0)0.06 (t/) 0.94 sin 0.94	T-r
M.PLANE BENTING	KBranch = 2.871 (d/D)-0.35 (t/T) 0.35 six 0.5 0	T- K
	T, Y clare = 0.507 (T/2) -1.014 (d/2) 0.787 (t/T) 0.889 sin 1.557 & 0.3 < d/0 < 0.55	T-1
-	T.YCLON = 0.229 (T/D)-1.014(d/D)-0.619 (t/T) assign 1.557 f	T-10
TRANSVERSE	. 0.55 & d/D & 0.75 T. YBranch = 0.843(T/D)-0.852(d/D)0.801 (t/T)0.543 sin 2.035 A	7-1
SENDING	0.3 < d/D < 0.55 T,Y Brand = 0.441 (T/D) -0.852 (d/D) -0.281 (+/T) 0.543 sin 2033 & 0.55 & d/D & 0.75	T-18
D = Char	d Outside Dia. d = Branch Outside Dia	
T = Chora	Nominal Thickness t = Branch Nominal Thickness	

					AND DESCRIPTION OF THE PARTY OF	N NUMBER		E PAGE 16
J.O. OR W.O. NO				ATION NO. OPTI		NAL TASK COD	E PAGE TE	
			2 4 1	1 1 1				
			1		1 1 1			
					1 1			
MATERIAL DE					-			
		-		-				
				-	,		-	
							-	
	Table 7.2				*			
		SCF in c	hord	Andrew Waller	SCF in t	race	- Allerton	
	Formula	$\beta = 0.3$	8 = 0.55	B = 08	$\beta = 0.3$	B = 0.55	\$ = 0.8	
				Asial load	on the b	race	3.44	
	Gibstein	5.25	5.58	4.08	5.79	6.20	5.24	
	Kuang	5.92	4.58	3.06	8.36	6.27	3.97	
	Wordsworth ▲ Smedley	5.87	6.66	4.98	4.70	5.20	4.14	
	a salesie,		1	In-plan	ne bending	1	200	والمتناف الماري
	Gibstein	2.03	2.03	1.83	2.03	2.02	1.83	
	Kuang	1.59	1.55	1.53	2.59	2.06	1.78	and the second
	& Smedley	2.14	2.23	2.04	2.35	2.40	2.29	
				Ош-обр	lane bend	ing		-
	Gibstein	2.91		. 4.32	2.78	4.64	4.93	
	Kuang Wordsworth	2.44	3.94	3:10	3.15	5.12		
	& Smedley	2.87	5.09	5.87	2.81	4.21	4.70	
		4 *				-		
		-	TABLE	. 4				
			MOL					
		-			commence and the con-	activities and other		
			REF :	9	PA	SE 18	8	
			3.40-377.7986 19					
Contraction and the								
5. March 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- christ							
		.00				*		
					1			
THE THE PERSON NAMED IN			-	-	-		a many of a second programme of	
						-		






CALCULATION SHEET

CALCULATION IDENTIFICATION NUMBER

J.O. OR W.O. NO. DIVISION & GROUP . CALCULATION NO. OPTIONAL TASK CODE PAGE 19

590-701-01 NPLB) 75- X6



REF: 3

REF: 3

(11 ونع)

FIGURE G





Fig. 11 - Comparison of experimental and empirates SCT6 for various joints.

CALCULATION SHEET



CALCULATION SHEET

