U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. Docket No.	50-443/78-13 50-444/78-13 50-444 CPPR-135		Δ	
License No.		Priority	Category A	
Licensee:	Public Service	Company of New Hampshire		
	1000 Elm Street			
	Manchester, New	Hampshire		
Facility Na	ame: Seabrook S	tation, Units 1 and 2		
Inspection	at: Seabrook,	New Hampshire		
Inspection Inspectors:	errors areas massered MM to Microsia cana vincular and made	Reactor Inspector	9/25 date sig	-/78 ined
	refreshives show the commission of the constraint of the constrain		date sig	ned
Approved by		Chief, Projects Section, P	date signatural date signatura date signatural date signatural date signatural date signatura	126,1979

Inspection Summary:

Inspection on September 5-8, 1978 (Report No. 50-443/78-13)

Areas Inspected: Routine, unannounced inspection by a regional based inspector of piping contractor's quality assurance program, and installation of containment reinforcing steel. The inspector performed a construction site tour and reviewed licensee action on previous inspection findings. The inspection involved 20 inspector-hours onsite by one NRC regional based inspector.

Results: No items of noncompliance were identified.

Inspection on September 5-8, 1978 (Report No. 50-444/78-13)

Areas Inspected: Routine, unannounced inspection by a regional based inspector of piping contractor's quality assurance program. The inspector performed a construction site tour and reviewed licensee action on previous inspection findings. The inspection involved 11 inspector-hours onsite by one NRC regional based inspector. Results: No items of noncompliance were identified.

Region I Form 12 (Rev. April 77) 88111000974

DETAILS

1. Persons Contacted

Yankee Atomic Electric Company

Mr. D. L. Covill, Quality Assurance Field Engineer, Civil

Mr. W. J. Gagnon, Quality Assurance Field Engineer, Mechanical

*Mr. J. H. Herrin, Site Manager

*Mr. W. P. Johnson, Vice President

Mr. G. McDonald, Quality Assurance Engineer (Westborough)

Mr. R. P. Pizzuti, Construction Manager

*Mr. T. M. Sherry, Director of Construction

*Mr. J. W. Singleton, Field Quality Assurance Manager

Mr. A. J. Stewart, Site Geologist

Perini Power Constructors

Mr. R. A. Brasells, Carpenter Superintendent

Mr. P. Antonich, Assistant Superintendent Quality Assurance

United Engineers and Constructors

Mr. M. A. Edgar, Resident Construction Engineer

Mr. G. B. Frey, Project Superintendent Operations

Mr. B. F. McCoy, Security Supervisor

Mr. R. N. Moyer, Field Superintendent Quality Assurance/Quality Control

Mr. D. R. Rhyne, Lead Startup and Test Engineer

*Mr. T. P. Vasallo, Jr., Quality Assurance Engineer

Mr. J. P. Zabielski, Concrete Superintendent

Royal Globe Insurance Companies

*Mr. J. R. Boyd, Inspection Specialist

*Mr. C. O'Sullivan, Authorized Nuclear Inspector

Pullman/Higgins (Piping)

*Mr. R. G. Davis, Field Quality Assurance Manager

Mr. D. R. Jones, Quality Assurance Controller

*Mr. J. P. Rowley, Resident Construction Manager

Pittsburgh Des Moines

Mr. J. Hill, Site Construction Superintendent

Mr. W. Stiger, Site Quality Assurance Superintendent

The inspector also interviewed other licensee and contractor employees including craft personnel, supervisors, and QC inspectors during this inspection.

* denotes those present at the exit interview.

2. Plant Tour

The inspector conducted a walk-through inspection of the construction site and observed completed work, and work in progress. The areas observed for Unit 1 were containment building base mat, reactor pit liner, auxiliary building reinforcing steel, and concrete curing and placements. In Unit 2, dewatering, containment building reinforcing steel installation and cooling tower structural slab. The inspector examined construction operations for compliance with regulatory requirements and licensee commitments. Specific activities observed by the inspector in both units included preparation for concrete placements, form stripping, excavating, backfilling, soil compaction, grinding, welding, and pressure testing.

No items of noncompliance were identified.

3. Licensee Action on Previous Inspection Findings

(Closed) Unresolved Item (443/77-03-01 and 444/77-03-01): Licensee review of NRC Circulars 77-01, 77-05, and 77-06. These Circulars had not originally been sent by YAEC to UE&C for action, but this has since been done. The inspector has reviewed the licensee's actions relating to these Circulars (Inspection Reports 50-443/78-08) and 50-444/78-08), and found them to be acceptable. The inspector had no further questions on this matter.

(Closed) Unresolved Item (Peference: Inspection Reports 50-443/76-02, Paragraph 6; and 50-444/76-02, Paragraph 6). PSAR amendment for control of specifications. The PSAR revision to correct this condition was issued on January 21, 1977. The inspector had no further questions on this matter.

4. Quality Assurance Program - Pullman Power Products Company

The installation of all piping at Seabrook Units 1 and 2 will be performed by Pullman/Higgins, a joint venture of the Pullman Power Products Company and J. C. Higgins Company. Installation of safety-related piping is scheduled to start in October, 1978. The inspector

5. Testing of Coarse and Fine Aggregate

The inspector reviewed the testing of coarse and fine aggregate for conformance to ASTM C-33, and to UE&C Specification 5-1, February 24, 1975. Aggregate samples were being tested for gradation, moisture, fines, organic matter, flat and elongated, friable, lightweight, soft fragments, specific gravity, absorption, soundness, potential reactivity and LA abrasion.

Pittsburgh Testing Laboratory Reports; for examples, Lab. No. 992 August 31, 1978 and Lab No. 987, August 31, 1978 were examined and the sampling schedule and test results confirmed that required sampling frequencies were being maintained, and that the aggregate met the specification requirements.

6. Exit Interview

The inspector met with the licensee and contractor representatives (denoted in Paragraph 1) at the conclusion of the inspection on September 8, 1978. The inspector summarized the scope and findings of the inspection.