

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Catawba Nuclear Station, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 1 1 3	PAGE (3) 1 OF 0 4
--	--	----------------------

TITLE (4) Technical Specification Violation Because Both Trains Of The Containment Spray System Being Inoperable Due To A Management Deficiency

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)		
0 2	2 9	8 8	8 8	0 1 3	0 0	0 3	3 1	8 8	N/A			0 5 0 0 0		
												0 5 0 0 0		

OPERATING MODE (9) 1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 1 0 0	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
	<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.36(e)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)						
	<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.36(e)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)						
	<input checked="" type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)								

LICENSEE CONTACT FOR THIS LER (12)		TELEPHONE NUMBER	
NAME	AREA CODE		
Julio G. Torre, Associate Engineer - Licensing	71014	317 13 1-18 10 21 9	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES (if yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On the evening of February 29, 1988, Containment Spray (NS) System Pump 1B was taken out of service for preventive maintenance. A Shift Supervisor declared Train B of the NS System inoperable. On March 1, 1988, another Shift Supervisor entered Train A of the Containment Pressure Control System (CPCS) into the TSAIL for calibrations but did not declare NS Train A inoperable. This placed both trains of the NS System in an inoperable condition violating Technical Specifications. The NS System would have initiated on a High-High Containment Pressure signal and secured at the low pressure setpoint. The inoperability was due to not meeting one sector of the surveillance requirements. The Technical Specification violation ended at 2228 hours, on March 1, 1988. The Unit was in Mode 1, Power Operation, at the time of this incident.

This incident has been attributed to a management deficiency due to the Shift Supervisor not recognizing that allowing the calibration of the CPCS would render NS Train A inoperable. At the time of this incident, the correct interpretation for NS operability when the CPCS was taken out of service was not identified in the Control Room Technical Specifications. This contributed to the Shift Supervisor allowing the Train A CPCS work to commence. This discrepancy in Technical Specifications with respect to the operability requirements for the CPCS had previously been identified and a Technical Specification change had been initiated. This incident has been reviewed with the involved personnel, and the Control Room Technical Specification copy has been highlighted to direct the Shift Supervisors to the appropriate interpretation. The health and safety of the public were unaffected by this event.

JK72
/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Catawba Nuclear Station, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 1 3	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8	- 0 1 3	- 0 0	0 2	OF	0 4

TEXT (If more space is required, use additional NRC Form 365A's) (17)

BACKGROUND:

The Containment Spray (EIIS:BE) (NS) System is an engineered safety feature which keeps the Containment Building pressure within design limits by removing thermal energy after an accident.

The system consists of two parallel flow paths, each with its associated pump (EIIS:P), heat exchanger (EIIS:HX), valves (EIIS:V), spray header and piping.

The Solid State Protection (EIIS:JC) System automatically initiates operation of the NS System upon high-high Containment pressure. To prevent depressurization, the operation of the NS System is automatically terminated when Containment pressure returns to normal by the Containment Pressure Control System (CPCS).

The CPCS is designed to prevent excessive or inadvertent operation of the NS System. It ensures that both trains of the NS System are inhibited when the Containment pressure is less than or equal to 0.25 psig. To function in this manner, the CPCS is designed to ensure that a single fault will not allow an erroneous operation of an NS train when Containment pressure is less than or equal to 0.25 psig. It also ensures that a single fault in the CPCS will not incapacitate both trains of NS when Containment pressure is greater than 0.25 psig and that the Control Room Operator is aware when portions of the NS System are nonresponsive to control demands.

DESCRIPTION OF INCIDENT:

On the evening of February 29, 1988, the Train B NS Pump was taken out of service for preventive maintenance. The Shift Supervisor entered the NS System inoperability into the Technical Specification Action Item Log (TSAIL). On March 1, 1988, at 0824 hours, the Shift Supervisor was requested to sign on Work Request 3646 SWR to calibrate Train A of the CPCS. He reviewed the Technical Specification requirements, Table 3.3-3, for operability of the CPCS and complied with the action statement requirements. He then entered Train A of the CPCS as being inoperable and that one channel was out of service for calibration in the TSAIL. The channel of the CPCS that was taken out of service resulted in the Train A of NS being inoperable. This caused both trains of NS to be inoperable but this was not recognized at the time. With both trains of the NS System inoperable Technical Specification 3.0.3 applied and required that one channel of the NS System be returned to operable status within one hour or within certain time limits be in a Mode which the specification did not apply. At 2130 hours, on March 1, 1988, during a review of the TSAIL, it was discovered that both trains of the NS System were inoperable and Technical Specification 3.0.3 was entered. At 2228 hours, Train B of the NS System was restored to operability and Technical Specification 3.0.3 was exited.

Through discussions with the Technicians involved with the calibration of the CPCS, it was determined that the Train A CPCS was returned to operable status at approximately 1445 hours, on March 1, 1988. However, it was not removed from the TSAIL because the work request signature process could not be completed until the next day. The actual Technical Specification violation lasted from 0824 hours to approximately 1445 hours, on March 1, 1988.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Catawba Nuclear Station, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 1 3	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		13	00		03	OF 04

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CONCLUSION:

This incident has been attributed to a management deficiency. The Shift Supervisor did not recognize that allowing calibration of CPCS Train A would render NS Train A inoperable. The Shift Supervisor relied on the Control Room copy of Technical Specifications to indicate the operability requirements for equipment taken out of service. He also used this copy to reference the Technical Specification Interpretation to review before making decisions to release equipment for maintenance. The Containment Spray, and the Containment Air Return And Hydrogen Skimmer System Technical Specifications were highlighted and the correct Technical Specification Interpretation noted. When the Technical Specification requirements for operability of the CPCS were reviewed, it did not reference the Containment Spray Technical Specification Interpretation and the Shift Supervisor assumed that the only operability requirements were those specified by the action statement requirements for the CPCS.

Technical Specification Interpretations are entered into the Technical Specification Interpretation Manual by the Technical Specification number noted on the interpretation. An interpretation for Technical Specification 3/4.6 had previously been issued but referenced Section 3/4.3, Table 4.3-2. If the interpretation had referenced Section 3/4.3, Table 3.3-3, the Control Room copy of Technical Specifications would have been highlighted and the Shift Supervisor would have been aware of the interpretation.

The inconsistency in the CPCS Technical Specification action statement had previously been recognized and a Technical Specification change had been submitted.

There has been at least one previous Technical Specification violation due to inconsistencies in interpreting Technical Specifications (see LER 413/87-44). Therefore, this incident satisfies the Nuclear Safety Assurance guidelines for a recurring event.

CORRECTIVE ACTION:

SUBSEQUENT

- (1) This event was reviewed with the involved personnel.
- (2) The Control Room copy of Technical Specifications was highlighted to direct the Shift Supervisors to the appropriate Technical Specification interpretation.
- (3) Technical Specification Interpretation 3/4.6, Containment Systems, was revised to include Instrumentation Section 3/4.3, Table 3.3-3.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) ata Nuclear Station, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 1 3 8 8 -	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
			0 1 3 -	0 0 0	4	OF

TEXT We space is required, use additional NRC Form 366A (1) (11)

SAFETY ANALYSIS:

Had an inadvertent Engineered Safeguards Containment Spray Actuation (Sp) signal occurred during this event with the Containment pressure below the permissive set point, the NS System would have been prevented from actuating due to the interlocked Train A pump. The opening of the NS valves would have caused no adverse affects and would have been repositioned by the Control Room Operator.

Had an actual High-High Containment Pressure occurred, the NS System would have functioned normally on initiation. Upon securing at the low pressure set point, the Train A pump would have tripped as expected and Containment Spray would have terminated. However, the NS valves would have remained open. The open NS valves would have no adverse effects.

This event is reportable pursuant to 10 CFR 50.73, Section (i)(2)(i)(B).

The health and safety of the public were unaffected by this incident.

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

March 31, 1988


Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: Catawba Nuclear Station, Unit 1
Docket No. 50-411
LER 413/88-13

Gentlemen:

Pursuant to 10 CFR 50.73 Section (a) (1) and (d), attached is Licensee Event Report 413/88-13 concerning a Technical Specification violation due to a management deficiency. This event was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

JGT/10014/sbn

Attachment

xc: Dr. J. Nelson Grace
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, New York 10020

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. P. K. Van Doorn
NRC Resident Inspector
Catawba Nuclear Station

IE22
11