+4)	LI	CENSEE EVENT RE	PORT (LER)	U 8. MUX AJ 63	CLEAR REQULATORY COMMISSION PROVED OMB NO 3150-0104 (PIRES 5/31/96
ACILITY NAME (1)				DOCKET NUMBER	2) PAGE 15
Trojan Nuclear P	lant			0 15 0 0 1	0 3 4 4 1 OF 01
EHC Switch Failu	re Caused Load Re	eiection - React	or Tripped Man	ually	
EVENT DATE (8)	LER NUMBER (6)	AEPORT DATE (7)	OTHER	PACILITIES INVOL	V 60 (8)
MONTH DAY YEAR YEAR	A SEQUENTIAL AEVEKO	MONTH DAY YEAR	- ACILITY NA		DOCKET NUMBER(S)
			N/A		0 5 0 0 0 1
1 2 0 6 8 7 8 7	7 0 3 7 0 0	0 1 0 5 8 8			0 15 10 10 101 1 1
OPERATING THIS	REPORT IS SUBMITTED PURBUANT	TO THE REQUIREMENTS OF 1	O CFR §: /Check and ar more	of the followings (11)	
POWER	20.402(b)	20.408(e) 80.38(e)(1)	X 80.73(a)(2)(iv)		73.71(6)
INDI 100	20.408(a)(1)(X)	80.38(e)(2)	80.73(a)(2)(v8)	in the second	OTHER (Specify in a set
	20.408(s)(1)(W)	00.7 3(a) (2) (i)	60.73ia)(2)(viii)(A)	JESA
H	20.408(a)(1)(h)	80.73(a)(2)(8)	80.73(a) (2)(vill)(•	
••••••••••••••••••••••••••••••••••••••		LICENSEE CONTACT FOR THIS	LER (12)		
AME					ELEPHONE NUMBER
Bill Kershul, Pl	lant Review Board	Engineer		5,0,3	5, 5, 6, -, 3, 7, 1, 3
	COMPLETE ONE LINE FO	A LACH COMPONENT FAILURE	DESCRIBED IN THIS REPOR	1 (13)	
CAUSE SYSTEM COMPONENT	MANUFAC REPORTABLE TURER TO NPROS	CAUSE	SYSTEM COMPONENT	MANUFAC. TURER	TO NPROS
X JIJ HISII	M111218 No				
X WII IISIVI	C [6] 3] 5 Yes			1.1.1	
	BUPPLEMENTAL REPOR	T EXPECTED IN	the stand when the stand	EXPECTED	MONTH DAY YEAR
YES IT YAL COMONN EXPECTE	O SUBMISSION DATE	XI NO		DATE (15)	
On December rejection t reported to pump had no generator b closed foll as designed The cause o push button turbine-dri in the auto closed was closure ind The plant w button was auto-start were checke MO-2808 was	r 6, 1987, the real transient. About to the control room of automatically so plowdown isolation lowing the main to lowing the main to lowing the main to lowing the main to lowing the main to low to the thread lication for the very vas placed in Mode replaced. The lo circuitry was tig of for tightness, a repaired and tes	Actor was manual ten minutes aft in that the turbis started. The pur- n valve MO-2808 arbine trip. The cion transient was hydraulic contro auto-start was do The failure of led valve seat by valve. al (hot standby pose connection thened. Other and no discrepa ited satisfactor	lly tripped for the reactor ine-driven aux imp was manual failed to ind he upstream iso vas a failure of ol (EHC) system due to a loose of valve MO-280 oacking out and v). The EHC lo in the turbing accessible ter incies were for ily.	llowing a r tripped, iliary fee ly started icate comp plation va of the loa n. The fa electrica 08 to indi d preventi oad decrea e-driven A rminal con ind. Blow	load it was dwater (AFW) . Steam letely lve closed d decrease ilure of the l connection cate fully ng complete se push FW pump nections down valve

UICENSEE	E EVENT REPORT (LER) TEXT CONTINUATION								U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMBINO 3150-0104 EXPIRES 8-31-85														
FACILITY NAME (1)	0	oc	KET	NU	MBE	R (2	1				Г		LE	-	UMB	ER 16			1		PAG	(3)	
												EAR	1	SEC	UEN	T AL ER		AEV S	ON ER		T	T	
Trojan Nuclear Plant	0	0	5	0	10	1	0	31	4	4	8	[7	_	0	В	17	_	01	0	01	20	F	0 3

Description of Event

On December 6, 1987, the plant was in Mode 1 (power operations) with the reactor coolant system at 2250 psig and 585°F. At 1010 hours with no evolutions in progress, a load rejection transient began as evidenced by a turbine runback and control rods stepping-in. The load decrease continued and at about 15 megawatts, the reactor and turbine were manually tripped. Event Specific Emergency Instruction (ES)-0.1, "Reactor Trip Response" was entered. At 1012 hours, auxiliary feedwater (AFW) flow was observed to be adequate at about 240 gallons per minute (gpm) to each of the four steam generators. (ES-0.1 specifies that total AFW flow be > 495 gpm, but does not require that individual AFW pumps be confirmed to be running.) Shortly thereafter, it was noted by personnel in the pump room that the turbine-driven AFW pump was not running. At 1020 hours, control room operators were informed of this condition and it was determined that the AFW turbine trip and throttle valve (MO-3071) was closed. AFW flow rate at this time was determined to be about 150 gpm to each steam generator. An auxiliary operator was dispatched to the turbine-driven AFW pump room and it was confirmed that valve MO-3071 was closed. The pump was started manually from the control room and it was confirmed to be functioning properly. During the post-trip review, it was determined that the turbine-driven AFW pump had not automatically started during the transient. It was also determined that steam generator blowdown isolation valve MO-2808 failed to indicate fully closed following the main turbine trip. Upstream blowdown isolation valve MO-6719 did close as designed.

Cause of Occurrence

The cause of the load rejection transient was a failure of the load decrease push button in the electro hydraulic control (EHC) system. The push button was determined to have a failed microswitch which was believed to have failed randomly due to normal aging.

The failure of the turbine-driven AFW pump to auto-start was due to a loose electrical connection in the auto-start circuitry in control room panel C-05. The affected terminal previously had two wires connected. Investigation determined that a 1985 Detailed Construction Package (DCP) to improve pump reliability had removed a wire from that terminal. The remaining lead was touching the terminal but was not tightened. Although not firmly tightened, the lead still made contact with the terminal resulting in successful automatic starts on several occasions during testing since 1985. Since the last automatic start, the lead lost contact with the terminal which caused the failure. The initial indicated AFW flow of about 240 gpm to each steam generator and subsequent decrease to about 150 gpm was verified as normal overshoot of the diesel-driven AFW pump when it automatically starts.

UCENSEE EVEN	T REPORT (LER) TEXT CONTIN	EPORT (LER) TEXT CONTINUATION									
FACILITY NAME (1)	DOCKET NUMBER (2)		LER NUM	BER 16		PAGE (3)					
A State of the second		YEAR	SEQUE	NT AL	NUMBER						
Trojan Nuclear Plant	0 5 0 0 3 4 4	817	-013	317	- 010	013	OF	0 3			

TEXT IM more space is required, use additional NRC Form 366A 3/ (17)

The failure of valve MO-2808 to indicate fully closed was due to the threaded valve seat backing out. This prevented the valve stem from traveling the normal distance to closure, resulting in the close limit switch not actuating. The valve was 'ctually closed and would have performed its design function.

Corrective Action

The immediate corrective action was to place the plant in Mode 3 (hot standby). The EHC load decrease push button was replaced.

The loose connection in the turbine-driven AFW pump auto-start circuitry was tightened. Other accessible terminal connections (about 75% of the total) in C-05 and local control panel C-160 were checked for tightness. No other discrepancies were found. Panel C-160 is scheduled to be replaced as part of a system upgrade in the 1988 refueling outage. The frequency and method of testing the AFW pump auto-start circuitry is being reviewed for improvements. Procedures associated with verification of AFW auto-start are being reviewed for improvements to ensure that the operating status of each AFW pump is confirmed. These reviews will be completed by March 4, 1988.

Blowdown valve MO-2808 was repaired and tested satisfactorily. A check of maintenance records for MO-2808 indicated that the valve was assembled and installed per the vendor technical manual. This valve had failed to indicate full closure in September 1987 and on November 29, 1987. On both occasions the valve was confirmed closed with no evidence of leakage, and the limit switch was adjusted. The limit switch adjustment following the November 1987 event was considered excessive and, therefore, an internal Event Report 87-185 was issued and is presently being evaluated. This valve and all similar 3/4 inch blowdown valves will be replaced as part of a system modification in the 1988 refueling outage.

The review of this event is continuing. Any significant changes identified when this review is completed will be included in a revision to this Licensee Event Report.

Significance of Occurrence

This event had no effect on public health and safety. Adequate AFW was provided to the steam generators. The loose electrical lead did not affect manual operation of the turbine-driven pump and still allowed all automatic features to function with the exception of opening of steam supply valve MO-3170.



January 5, 1988 CAO-006-88

Portland General Electric Company Trojan Nuclear Plant 71760 Columbia River Hwy Rainier, Oregon 97048 (503) 556-3713

> US Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Gentlemen:

Licensee Event Report No. 87-37 is attached. This report discusses an event in which the reactor was manually tripped following a load rejection transient caused by a switch failure in the electro-hydraulic control system.

Sincerely,

C. A. Olmstead General Manager Trojan Nuclear Plant

C:

Mr. John B. Martin Regional Administrator US Nuclear Regulatory Commission

Mr. Dave Yaden, Director State of Oregon Department of Energy

Mr. R. C. Barr USNRC Resident Inspector Trojan Nuclear Plant

IE 22