



Log # TXX-88159
File # 10110
909.2
Ref # 10CFR50.55(e)

William G. Council
Executive Vice President

February 4, 1988

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
SERVICE WATER SYSTEM WATER HAMMER
SDAR: CP-87-130 (FINAL REPORT)

Gentlemen:

On January 6, 1988, we notified you via our report logged TXX-88034 of a reportable deficiency involving Service Water System water hammer and column separation at the inlet and outlet of the emergency diesel generator jacket water coolers which can occur subsequent to a service water pump trip. In that report we discussed the deficiency description, cause, scope restrictions, safety implications and the corrective action required to resolve the condition. The purpose of this report is to address the schedule for implementation of the corrective action, pursuant to the provisions of 10CFR50.55(e).

The corrective actions specified in our previous report, TXX-88034, are scheduled for completion in Unit 1 by May 13, 1988. Unit 2 corrective actions will be completed prior to the start of the primary system cold hydrostatic test.

This is our final report on this issue.

Very truly yours,

W. G. Council

BB02090587 BB0204
PDR ADOCK 05000445
S PDR

By: John W. Beck
John W. Beck
Vice President,
Nuclear Engineering

MCP/grr

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

IE27
1/0