Carolina Power & Light Company Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461-0429 February 1, 1988 FILE: B09-13510A SERIAL: BSEP/88-0069 Dr. J. Nelson Grace, Administrator U.S. Nuclear Regulatory Commission Suite 2900 101 Marietta Street NW Atlanta, GA 30323 BRUNSWICK STEAM ELECTRIC PLANT UNIT 2 DOCKET NO. 50-324 LICENSE NO. DPR-62 SUPPLEMENTAL RESPONSE TO I&E BULLETIN 80-13 Dear Dr. Grace: This confirms the telephone conversation at 1500 hours on January 25, 1988, between Mr. R. M. Poulk Jr. of my staff and Mr. S. J. Vias of your staff concerning inspections of core spray piping per I&E Bulletin 80-13. While performing visual inspections of the in-vessel core spray piping, a crack indication was identified in the heat affected zone on the A loop east header to T-box weld at azimuth 90 degrees. The crack is circumferential and extends approximately from the 90 degree position to the 180 degree position. Due to physical limitations, the camera cannot view beyond the 180 degree position; therefore, it cannot be determined at this time if the indication proceeds beyond the 180 degree position. During vessel level reduction for scheduled vessel maintenance/inspection during this outage, further examination on this indication will be conducted. Corrective actions and the final results of the core spray inspections will be provided in the final report required by the bulletin within 30 days of completing the inspections. Very truly yours, C. R. Dietz, General Manager Brunswick Steam Flectric Plant MJP/mcg Enclosure cc: NRC Document Control Desk BSEP NRC Resident Office Mr. E. D. Sylvester 8802170308 880201 PDR ADOCK 05000324