



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

COMMONWEALTH EDISON COMPANY

DOCKET NO. 50-295

ZION NUCLEAR POWER STATION, UNIT 1

AMENDMENT TO FACILITY OPERATING LICENSE

Amendment No. 108
License No. DPR-39


1. The Nuclear Regulatory Commission (the Commission) has found that:
 - A. The application for amendment by Commonwealth Edison Company (the licensee) dated September 22, 1987, modified by letter dated October 27, 1987, complies with the standards and requirements of the Atomic Energy Act of 1954, as amended (the Act) and the Commission's rules and regulations set forth in 10 CFR Chapter I;
 - B. The facility will operate in conformity with the application, the provisions of the Act, and the rules and regulations of the Commission;
 - C. There is reasonable assurance (i) that the activities authorized by this amendment can be conducted without endangering the health and safety of the public, and (ii) that such activities will be conducted in compliance with the Commission's regulations;
 - D. The issuance of this amendment will not be inimical to the common defense and security or to the health and safety of the public, and
 - E. The issuance of this amendment is in accordance with 10 CFR Part 51 of the Commission's regulations and all applicable requirements have been satisfied.
2. Accordingly, the license is amended by changes to the Technical Specifications as indicated in the attachment to this license amendment, and paragraph 2.C.(2) of Facility Operating License No. DPR-39 is hereby amended to read as follows:

(2) Technical Specifications

The Technical Specifications contained in Appendices A and B, as revised through Amendment No.108, are hereby incorporated in the license. The licensee shall operate the facility in accordance with the Technical Specifications.

3. This license amendment is effective as of the date of its issuance.

FOR THE NUCLEAR REGULATORY COMMISSION

A handwritten signature in cursive script, reading "Daniel R. Muller".

Daniel R. Muller, Director
Project Directorate III-2
Division of Reactor Projects - III,
IV, V and Special Projects

Attachment:
Changes to the Technical
Specifications

Date of Issuance: February 5, 1988

ATTACHMENT TO LICENSE AMENDMENTS

AMENDMENT NO. 108 FACILITY OPERATING LICENSE NO. DPR-39

DOCKET NO. 50-295

Revise Appendix A as follows:

Remove Page

295AA1

Insert Page

295AA1

LIMITING CONDITIONS FOR OPERATION

3.22. Shock Suppressors (Snubbers) (Continued)

2. Hydraulic Snubbers

- A. All safety related hydraulic snubbers listed in station procedures shall be OPERABLE.

APPLICABILITY: MODES 1,2,3,4 and 7

(MODES 5 and 6 for snubbers located on systems required OPERABLE in those MODES.)

ACTION:

With one or more snubbers inoperable, within 72 hours replace or restore the inoperable snubber(s) to OPERABLE status and perform an engineering evaluation per Specification 4.22.2.A.3 on the supported component or declare the supported system inoperable and follow the appropriate ACTION statement for that system.

SURVEILLANCE REQUIREMENT

4.22. Shock Suppressors (Snubbers)

2. Hydraulic Snubbers

- A. Each hydraulic snubber shall be demonstrated OPERABLE by performance of the following augmented inservice inspection program.

1. Visual Inspections - Hydraulic Snubbers

All hydraulic snubbers shall be visually inspected in accordance with the following schedule:

No. Inoperable Snubbers per Inspection Period	Subsequent Visual Inspection Period [*] , [#]
0	18 months \pm 25%
1,2	12 months \pm 25% ^{##}
3,4	6 months \pm 25%
5-8	124 days \pm 25%
9-14	62 days \pm 25%
15,16	31 days \pm 25%

The snubbers may be categorized into two groups: Those accessible and those inaccessible during reactor operation. Each group may be inspected independently in accordance with the above schedule.

- * The inspection interval shall not be lengthened more than one step at a time.
- # The provisions of Specification 4.0.2 are not applicable.
- ## For Fall 1986, Unit 1 outage, the subsequent visual inspection period may be delayed until achieving Cold Shutdown during the Spring 1988 Refueling Outage, for inaccessible snubbers only.