

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1): Joseph M. Farley - Unit 1 DOCKET NUMBER (2): 0 5 0 0 0 3 4 0 1 PAGE 3 OF 0 3

TITLE (4): 10CFR73.71 Report: Unauthorized Individual Entered The Main Control Room

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME		DOCKET NUMBER (3)
d	1	14	88	001	00	0	2	12	88	J. M. Farley - Unit 2	0 5 0 0 0 3 6 4
											0 5 0 0 0 1 1 1

OPERATING MODE (9): 1 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)

20.402(b)	20.406(e)	60.73(a)(2)(iv)	X	73.71(b)
20.406(a)(1)(ii)	60.36(a)(1)	60.73(a)(2)(v)		73.71(c)
20.406(a)(1)(iii)	60.36(a)(2)	60.73(a)(2)(vi)		OTHER (Specify in Abstract below and in Text, NRC Form 365A)
20.406(a)(1)(iv)	60.73(a)(2)(i)	60.73(a)(2)(vii)(A)		
20.406(a)(1)(v)	60.73(a)(2)(ii)	60.73(a)(2)(vii)(B)		
20.406(a)(1)(vi)	60.73(a)(2)(iii)	60.73(a)(2)(viii)		
20.406(a)(1)(vii)	60.73(a)(2)(iv)	60.73(a)(2)(ix)		

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
J. D. Woodard, General Manager - Nuclear Plant	2 0 5 8 9 9 1 - 5 1 5 6

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (if yes, complete EXPECTED SUBMISSION DATE): NO: X

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 words, i.e., approximately fifteen single-space typewritten lines) (16)

At 0643 on 1-14-88, a contractor employee entered the main control room without authorized access. Since the control room is a vital area, this report is being submitted in accordance with 10CFR73.71.

The contractor employee was going to the Waste and Decontamination (W&D) group's break room where his group's shift turnovers are conducted. It was his second day on the job and he did not know how to get to the break room. He asked a permanent Farley Nuclear Plant worker for directions. The Farley Nuclear Plant worker, unaware that the contractor was not authorized to enter the control room, told the contractor to follow him since he was going that way. Since the contractor was unfamiliar with this part of the Auxiliary Building layout, he was unaware that he was about to enter the control room. When he inserted his key-card, his access to the control room was denied which caused an alarm in the Security Central Alarm Station. The man did not recognize that he was denied access and continued to follow the Farley Nuclear Plant worker into the control room.

Security personnel responded to the alarm. They located the individual at approximately 0700 in the W&D break room and escorted him out of the auxiliary building.

No safety systems were affected or threatened. The contractor has been counseled concerning this event. The applicable training programs will be revised to emphasize card reader indication of access denial and the specific requirements regarding access to the control room.

2022

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Joseph M. Farley - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 8 8 8 - 0 0 1 - 0 1 0 0 2 OF 0 3	LER NUMBER (3)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (if more space is required, use additional NRC Form 366A's) (17):

Date and Time of Event

0643 on 01-14-88.

Location of Event

FNP main control room (shared between Units 1 and 2).

Operating Phase

At the time of this event, both Units were operating at 100 percent power.

Safety Systems Affected or Threatened

No safety systems were affected or threatened.

Type of Security Force Onsite

FNP has a proprietary security force.

Number and Type of Personnel Involved

One contractor employee and one permanent employee.

Method of Discovery of Event

The attempted access by an unauthorized individual generated an alarm in the Security Central Alarm Station. Security personnel responded to the alarm.

Procedural Errors Involved

Established procedures were not followed.

Immediate Actions Taken In Response To The Event

The contractor employee was located and escorted out of the auxiliary building.

Corrective Actions Taken or Planned

The contractor employee has been counseled concerning this event. The installation of more prominent local alarms at vital area doors is being investigated. The applicable training programs will be revised to emphasize card reader indication of access denial and the specific requirements regarding access to the control room.

Local, State, or Federal Law Enforcement Agencies Contacted

None.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Joseph M. Farley - Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 4 8 8 8	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8	0 0 1	0 0	0 3	OF	0 3

TEXT (if more space is required, use additional NRC Form 365A's) (17)

Description of Media Interest or Press Release

None.

Indication of Previous Similar Events


LER 87-020-00 Unit 1 (dated 11-03-87) and LER 87-022-00 Unit 1 (dated 12-02-87) reported similar events at FNP.

Knowledgeable Contact

Larry W. Enfinger, Administrative Manager, (205) 899-5156 Extension 2221.

Alabama Power Company
600 North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291-0400
Telephone 205 250-1835

R. P. McDonald
Senior Vice President



February 12, 1988

Docket No. 50-348

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555


Dear Sir:

Joseph M. Farley Nuclear Plant - Unit 1
Licensee Event Report No. LER 88-001-00

Joseph M. Farley Nuclear Plant, Unit 1, Licensee Event Report No. LER 88-001-00 is being submitted in accordance with 10CFR50.73.

If you have any questions, please advise.

Respectfully submitted,



R. P. McDonald

RPM/JAR:dst-D-LER

Enclosure

cc: IE, Region II

IE22
11