Georges W

UNCLASSIFIED
September 14, 1960

COPY NO.____

ATOMIC ENERCY COMMISSION

INCIDENT AT KERR-MOJEE OIL INDUSTRIES, INC. SHIPROCK, N, M.

Note by the Secretary

The General Manager has requested that the attached memorandum from the Director of Compliance be circulated for the information of the Commission.

W. B. McCool Secretary

DISTRIBUTION	COPY NO.	DISTRIBUTION	COPY NO.
Secretary Commissioners Gamaral-Manager Deputy Gen. Mgr. Asst. Gen. Mgr. Asst. Gen. Mgr. Mfg. Asst. Gen. Mgr. R&S Asst. Gen. Mgr. Adm. Asst. to the GM General Counsel Biology & Medicine	2 - 6 8 9 - 10 11 12 13 14 15 - 18 19	Compliance Congr. Relations Health & Safety Public Information Inspection Licensing & Regulation Raw Materials Grand Junction Oprns. D. C. Office Secretariat	20 21 22 23 - 24 25 - 27 28 - 29 30 31 - 33 34 - 38

SEP 20 1960

A190

ID

9602130140 960125 PDR FDIA CUNNING95-468 PDR

9-14-60 AEC 981/21

DATE. August 31, 1960

UNITED STATES GOVERNMENT

Memorandum

THEU

A. R. Luedecke, General Manager

: W. F. Pinan, Annistant General Hanager

for Degulation and Safety L. D. Low, Director your

TROM

Division of Complime

Stapper

KERR-NG GGE OIG INSUSTRIES, TUC., SHIPROCK, NEW MEXICO

Licinot to. R-157

CYMBOL: CO:VEE

We have been informed that a dam retaining the liquid effluence from subject company's uranium mill broke on August 22, 1986, and released from 150,000 to 200,000 gallons of the liquid to the San Juan River. As a result of this release, it would appear that quantities of redium-226 and thorium-230 oure probably released in excess of AEC standards. On the basis of an initial estimate, the incident has been classified as a Type B as defined in 10 CFR 20 and AEC 0707.

The licensed did not advise AEC of this incident and it was not until August 30, 1960, that we were informed by the Utah State Health Department of its occurrence. A representative of the ID Inspection Division arrived at the mill on August 31, 1960, and is conducting a complete investigation. We also understand that the USINS and the Utah and New Mexico State health Departments may conduct investigations. Our investigation will be coordinated with these agencies. We shall inform you of any significant developments in this matter.

The Division of Licensing and Regulation, the Office of the General Councel and the Office of Public Information have been informed of this incident. We have discussed this matter with the Office of Congressional Lielson who we understand have informed the Joint Committee staff by telephone.

8605220494 18

G=0 92/5 SEP 2 1 1980

H. L. Price, Director Division of Licensing and Regulation

Bigned by L D. Low

L. D. Low, Director Division of Compliance

KERR-MCCKE OIL INDUSTRIES, INC., LICENSE NO. N-157

SYMBOL: CO:WEK

There is attached a copy of the report dated August 25, 1960, together with the ID transmittal memoranduse also dated August 25, 1960, with respect to the follow-up inspection of subject licensee.

It was observed during the inspection that the licensee has failed to conduct proper surveys to determine the exposure of individuals within the restricted area and with respect to the concentration of radioactive material in liquid and airborne effluents released to the unrestricted areas. In addition, the licensee failed to post areas to indicate the presence of airborne radioactive material.

We suggest that the licensee be informed of these matters of noncompliance and be directed to describe in detail the corrective action taken or planned to be taken with respect thereto, including specific dates for completion, etc. (Please note paragraphs 2, 3, and 4 of the ID transmittal memorandum dated August 25, 1960.) We also suggest that mention be made of the fact that the investigation is still in progress with respect to the recent possible release of radium and thorium to the San Juan River.

We have suggested an order in this case for two reasons. First, the licensee was initially inspected in January, 1958, and on May 14, 1958, the licensee was requested to inform AEC of the actions they had taken or had planned to take to correct the items of noncompliance. The licensee's reply dated December 22 2 1958, and the corrective action as noted in the follow-up report have not resulted in full compliance. Secondly, orders have been issued to several other mills when follow-up inspection findings resulted in similar circumstances.

Attachment: Copy ID report dtd 8/25/60 Copy memo fm D. Walker to L. D. Lov ata 8/25/60

CC: T. Conner, GC, w/attach D. I. Walker, ID, w/o attach.

SEP 23 196

ID COMPLIA

991

RECEIVER

GC CO CO

W.KRIRGSMAN:sd T. Conner L. D. Low

9/20/60

L. D. Low, Director, Division of Compliance, ARC Headquarters

Done. 1. walker, Director, Division of Licensee LIS B. Stanged by FOLLOW-UP INSPECTION REPORT - KERR-Meddes CIL INDUSTRIES, INC., ON CHIPROCK, NEW MEXICO - SOURCE MATTRIAL LICENSE NO. R-157

LI: GHE

Transmitted herewith are four (") copies of subject report.

The following items of honomagliance were observed or otherwise noted:

14 JAR 20.201 Surveys

- (b) Surve and air contamination but in restricted and investricted areas, and survey to determine concentrations of Radium-226 released to unrestricted areas are incomplete in that:
 - (1) Surveys to determine amounts of airborne radioactive materials released to unrestricted areas have not been made.
 - (2) Breathing one samples have not been collected and time studies to relate exposures of employees to airborne concentrations of radioactive materials in restricted areas have not been made.
 - (3) Some restricted areas found to have high concentrations of airborne uranium during AEC sampling progrems have not been surveyed by the licensee.
 - (4) The licensee had not, since the inclusion of a vanadium recovery circuit in the mill and the subsequent resumption of production on February 6, 1,60, conducted a complete survey for airborie uranium contermation in the mill.

(Continued)

- (5) The licensee, at the time of the inspection, had not sufficiently sampled the tailings pond seepsge and the Ean Juan River to determine the status of compliance with 10 CPR 20.103(b)
- 10 CFR 20.203 Caution signs, labels, and signals
 (d)(1)(ii) Areas having amounts of airborne licensed material
 in excess of 25 per cent of specified limits are
 not posted.

The above items of noncompliance were discussed with the following officers and employees of Kerr-McGee Gil Industries, Inc.: Dean A. McGes, Fresident, Oklahoma City, Oklahoma; V. L. Mattson, General Manager, Minerals Division, Oklahoma City, Oklahoma; Wayne C. Haten, Director, Metallurgical Research Laboratories, Colden, Colorado; C. L. wise, Manager, Mavajo Uranium Division, Shiprock, Mew Mexico; F. L. Hanagarne, Metallurgist, Mavajo Uranium Division, Shiprock, New Mexico. Mr. wise and Mr. Hanagarne were contacted during the inspection of the mill while Mr. McGee, Mr. Mattson, and Mr. Seren were contacted in Oklahomm City, Oklahoma. Mr. Make in stated that he had contacted Mr. wise and had instructed him to have complete surveys made of the mill once a month; these surveys are to include breathing come samples. samples to determine amounts of airborne licensed asterial released to unrestricted areas, and samples from areas previously not surveyed. Concerning the areas found to be excessively high as a results of the AEC sampling program, Mr. Mattson said that he would contact Mr. Vise and tell him to institute engineering studies so that adequate dust collection apparatus could be installed in these areas.

Four seepage areas from the Shiprock mill tailings pends to the San Juan River have been found by the licensee. Only two sets of completed samples analyses of these seepage areas are trailable: one set of samples taken by the licensee and one set of samples taken by the inspectors. Both AEC and licensee sample data show concentrations of Radium-226 in the water from one seepage area to be greater than the MPC for Radium-226 in an unrestricted area. I do not feel that two samples constitute adequate evidence for notification of noncompliance under 10 CFR 20.105(b). However, the Shiprock mill has a definite problem with this seepage and should be greatly concerned. Licensee personnel are in disagreement on the possible effects of this seepage on a nearby U. S. Government belium plant and associated housing area.

(Continued)

Mr. Hanagarna said that the helium plant obtained drinking water from the Shiprock municipal water system; on the other band, Mr. Mattaon stated that the helium plant pumped water directly from the San Juan River, downstream from the mill, for use in the plant and the adjoining bousing area. Mr. Mattaon said that a program was in the planning state whereby they would determine the drainage of the tailings neepage and its possible effects on local water users.

It is my opinion that an extensive campling program should be instituted by the licensee, to:

- 1. Determine the volume of tailings liquor released to warestricted areas by seepage.
- 2. Determine the concentrations of Radius-226 and Thorium-236 in the tailings liquor seepage.
- Determine the present and potential effects of the tailings liquor seepage on all people living and working in the unrestricted areas surrounding the mill.

It is the opinion of the inspectors that Mr. Wise and Mr. Hansgarme concider the Ast regulatory program a necessary evil over which all production problems take precedence. (It appears that their compliance program is sandwiched into various persons' schedules, to be taken care of only when their horsal jobs are completed; this is evidenced by the fact that the plant murse does the air sampling.) Some statements made by the licensee were not consistent with previous inspection findings; e.g., Mr. Wise and Mr. Hansgarme stated that they had not seen the results of the September, 1939, ABC sampling program, but Mr. Peery, in the report of his December, 1939, visit to the mill, mentions comparing AEC sampling data to licensee sempling data with Mr. Hansgarme. It is our opinion, since contacting Mr. McGee and Mr. Mattson, that they were not aware of the conditions existing at the Eniprock mill and now that they are aware of their status of compliance, they will see that a realistic program is initiated.

In view of the enclosed report and the above finding, this office recommends that the Division of Licensing and Regulation contact the licensee through Mr. Dean A. McGee, President, Kerr-McGee Oil Industries, Inc., Chlahoma City, Oklahoma, to:

1. Inform him of the above items of noncompliance.

(Continued)

· AUG 2 5 1968

L. D. LOW

- Request him to submit plans for a complete air survey progress. This information should include:
 - a. The names, qualifications, and duties of the persons assigned to the survey program.
 - b. The types and specifications of the instruments to be used in the survey program.
 - c. The areas of the still which will be sampled, including the frequency of sampling and the types of samples to be taken, e.g., breathing zone or general air samples.
 - d. The method of determining amounts of airborne natural uranium released to unrestricted areas, including frequency of stack sampling, locations of unrestricted areas to be sampled, and frequency of sampling of unrestricted areas.
 - e. The analytical method to be used to determine the concentrations of uranium in the above-mentioned samples.
- Request him to sake t plans for the rtilization of the results of the air survey program, where necessary, to achieve compliance with 10 CFR 20.101, 20.102 and 20.203.
- 4. Request him to institute a comprehensive program to evaluate the extent and effect of the mill effluent seepage.
- Thank him for the courtesies and cooperation shown the inspectors by company personnel during the inspection of the mill and the visit to his office.

It is further recommended that copies of the above correspondence be sent to: Mr. V. L. Mattson, General Manager, Minerals Division, Kerr-Widee Oil Industries, Inc., Oklahoma City, Oklahoma; and Mr. C. L. Wise, Manager, Mavajo Uranium Division, Kerr-McGee Oil Industries, Inc., Eniprock, New Maxico.

The status of the above items of noncompliance will be checked during a follow-up inspection conducted after the completion of correspondence between DLR and the licensee.

Enclosure: Inspection Report (Kerr-McGee) 4 cys

OFFICE DOTE DOTE DOTE DO THE BOOK OF SURNAME DATE DOTE DO THE BOOK OF SURNAME DATE DOTE DO THE BOOK OF SURNAME PRINTING OFFICE 18-62761-3