NSIC Accession Number: 154451

Date: February 12, 1980

Title: Inadvertent Opening of PORV at Haddam Neck

The failure sequence was:

- 1. With the reactor at full power, spurious signal to the PORV and its isolation block valve was initiated in Pressurizer Pressure Control Channel 1.
- 2. Both valves opened and the RCS depressurized to 1992 psig.
- 3. The PORV and its associated block valve were remote-manually closed within approximately 10 seconds of the start of the transient. RCS pressure was restored to greater than 2000 psig within 2 minutes, terminating the transient.


Corrective action:


1


Investigation and testing did not reveal the source of the problem. The channel and valve controls were placed in the normal operating mode.

Design purpose of failed system or component:

PORVs are designed to prevent challenges to the main safety valves and to assist in control of RCS pressure.







NSIC 154451 - Sequence of Interest for Inadvertent Opening of PORV at Haddam Neck

Yes

7

CATEGORIZATION OF ACCIDENT SEQUENCE PRECURSORS

NSIC ACCESSION NUMBER: 154451 LER NO.: 80-04/3L DATE OF LER: February 12, 1980 DATE OF EVENT: February 4, 1980 SYSTEM INVOLVED: Pressurizer relief system COMPONENT INVOLVED: PORV and block valve CAUSE: Spurious actuation signal SEQUENCE OF INTEREST: Small break LOCA ACTUAL OCCURRENCE: Inadvertent opening of a PORV and block valve REACTOR NAME: Haddam Neck DOCKET NUMBER: 50-213 REACTOR TYPE: PWR DESIGN ELECTRICAL RATING: 580 MWe REACTOR AGE: 12.5 years VENDOR: Westinghouse ARCHITECT-ENGINEERS: Stone and Webster OPERATORS: Connecticut Yankee Atomic Power Co. LOCATION: 13 miles east of Meriden, Connecticut DURATION: N/A PLANT OPERATING CONDITION: Full power TYPE OF FAILURE: Inadequate performance; inadvertent operation DISCOVERY METHOD: Operational event COMMENT: Actuation logic for the PORV and block valve has been modified from a one channel pressure signal to a 2 out of 3 channels to

prevent spurious actuations.