#### Accident Sequence Precursor Program Event Analysis

LER No:

321/88-018

Event Description: Reactor scram with loss of nonessential loads and

RCIC degraded operation

Date of Event:


December 17, 1988

Plant:

Hatch Unit 1

# Summary

Following a reactor scram, a loss of power to the nonessential loads was experienced. During the recovery from the scram, the RCIC system turbine tripped on the second and several later initiations of the system on overspeed but was successfully recovered. The conditional core damage probability associated with the event is  $1.5 \times 10^{-5}$ . The relative significance of this event compared with other potential transients at Hatch 1 is shown below.



#### Event Description

The reactor was at ~85% power when the main turbine tripped on a loss of electrohydraulic control system (EHC) pressure, resulting in a reactor scram. It is believed that the loss of EHC system pressure was caused by an operator racking out EHC breakers for the wrong unit. Upon transfer of the nonessential loads to the startup auxiliary transformer (SAT) (as expected) the protective relaying for SAT 1D actuated (caused by a malfunctioning relay), resulting in a loss of power to the nonessential The emergency diesel generators started because of a temporary undervoltage condition on the essential bus but did not load because the voltage transient was over and normal voltage was being supplied.

Because of level transients caused by the reactor trip and subsequent loss of feedwater caused by the loss of power to the nonessential loads, RCIC was manually initiated to control reactor pressure vessel water level. HPCI cycled off as designed; however, the RCIC turbine steam supply valve failed to close fully (a result of incorrectly tightened yoke bushing set screws), and upon reinitiation the RCIC turbine tripped on overspeed on several occasions. The RCIC was restored and continued to assist in controlling reactor pressure.

Nonessential loads were not recovered until 22 h after the trip. For the first 8 h, the battery-powered emergency lighting system functioned. After this time period, lighting was unavailable except in the control room.


# ASP Modeling Assumptions and Approach

The event has been modeled as a LOFW with failure of RCIC. The likelihood of not recovering RCIC was assumed to be 0.12.

## Analysis Results

The conditional probability of severe core damage estimated for this event is  $1.5 \times 10^{-5}$ .

The dominant sequence postulated for this event (highlighted on the following event tree) involves a failure of one of the SRVs to close (p = 0.036) with subsequent HPCI (p = 0.02) and ADS failure (p = 0.013, including operator error to initiate depressurization). The highest probability sequence impacted by RCIC is a factor of 16 in probability below the dominant sequence, an indication of the lack of importance of RCIC failure in this event.



### CONDITIONAL CORE DAMAGE PROBABILITY CALCULATIONS

Event Identifier: 321/88-018

Event Description: Trip with loss of non-essential loads and RCIC degraded

Event Date: 12/17/88
Plant: Hatch 1

INITIATING EVENT

NON-RECOVERABLE INITIATING EVENT PROBABILITIES

TRANS 1.0E+00

SEQUENCE CONDITIONAL PROBABILITY SUMS

End State/Initiator Probability

CD

TRANS 1.5E-05

Total 1.5E-05

ATWS

TRANS 3.0E-05

Total 3.0E-05

#### SEQUENCE CONDITIONAL PROBABILITIES (PROBABILITY ORDER)

		Sequence .	End State	Prob	N Rec**
28	trans -rx.shutdown FW/PCS.TRANS hpci		CD	9.3E-06	5.0E-01
12	trans -rx.shutdown FW/PCS.TRANS -hpci	PCS/TRANS srv.chall/transscram -srv.close rhr(sdc) rhr(spcool)/rhr(sdc)	CD	5.2E-06	1.1E-01
20	trans -rx.shutdown FW/PCS.TRANS hpci	PCS/TRANS srv.chall/transscram -srv.close RCIC crd srv.ads	CD	5.9E-07	6.0E-02
99	trans rx.shutdown		ATWS	3.0E-05	1.0E+00

#### \*\* non-recovery credit for edited case

# SEQUENCE CONDITIONAL PROBABILITIES (SEQUENCE ORDER)

		Sequence		End State	Prob	N Rec**
12			<pre>srv.chall/transscram -srv.close rhr(spcool)/rhr(sdc)</pre>	CD	5.2E-06	1.1E-01
20	trans -rx.shutdown FW/PCS.TRANS hpci		<pre>srv.chall/transscram -srv.close srv.ads</pre>	CD	5.9E-07	6.0E-02
28	trans -rx.shutdown FW/PCS.TRANS hpci		<pre>srv.chall/transscram srv.close</pre>	CD	9.3E-06	5.0E-01
99	trans rx.shutdown			ATWS	3.0E-05	1.0E+00

<sup>\*\*</sup> non-recovery credit for edited case

SEQUENCE MODEL: a:\sealmod\bwrcseal.cmp
BRANCH MODEL: a:\sealmod\hatch.sl1
PROBABILITY FILE: a:\sealmod\bwr\_csl1.pro

No Recovery Limit

BRANCH FREQUENCIES/PROBABILITIES

Branch	System	Non-Recov	Opr Fail
trans	6.1E+04	1.0E+00	
loop	1.6E-05	3.6E-01	
loca	3.3E-06	5.0E-01	

Event Identifier: 321/88-018

rx.shutdown	3.0E-05	1.0E+00	
rx.shutdown/ep	3.5E-04	1.0E+00	
PCS/TRANS	1.7E-01 > 1.0E+00	1.0E+00	
Branch Model: 1.0F.1			
Train 1 Cond Prob:	1.7E-01 > Unavailable		
srv.chall/transscram	1.0E+00	1.0E+00	
srv.chall/loopscram	1.0E+00	1.0E+00	
srv.close	3.6E-02	1.0E+00	
emerg.power	5.4E-04	8.0E-01	
ep.rec	1.6E-01	1.0E+00	
FW/PCS.TRANS	4.6E-01 > 1.0E+00	3.4E-01 > 1.0E+00	
Branch Model: 1.0F.1			
Train 1 Cond Prob:	4.6E-01 > Unavailable		
fw/pcs.loca	1.0E+00	3.4E-01	
hpci	2.9E-02	7.0E-01	
RCIC	6.0E-02 > 1.0E+00	7.0E-01 > 1.2E-01	
Branch Model: 1.0F.1			
Train 1 Cond Prob:	6.0E-02 > Failed		
crd	1.0E-02	1.0E+00	1.0E-02
srv.ads	3.7E-03	7.1E-01	1.0E-02
lpcs	3.0E-03	3.4E-01	
lpci(rhr)/lpcs	1.0E-03	7.1E-01	
rhr(sdc)	2.1E-02	3.4E-01	1.0E-03
rhr(sdc)/-lpci	2.0E-02	3.4E-01	1.0E-03
rhr(sdc)/lpci	1.0E+00	1.0E+00	1.0E-03
rhr(spcool)/rhr(sdc)	2.0E-03	3.4E-01	
rhr(spcool)/-lpci.rhr(sdc)	2.0E-03	3.4E-01	
rhr(spcool)/lpci.rhr(sdc)	9'.3E-02	1.0E+00	
rhrsw	2.0E-02	3.4E-01	2.0E-03

<sup>\*</sup> branch model file \*\* forced

Minarick 11-14-1989 06:09:15