


Accident Sequence Precursor Program Event Analysis

LER No: 366/88-017
 Event Description: Reactor trip and failure of RCIC pump
 Date of Event: May 27, 1988
 Plant: Hatch Unit 2

Summary

A deficient condensate and feedwater pump vent and fill procedure resulted in air binding in the condensate booster pumps, which caused a trip of main feedwater and subsequent reactor trip. As the reactor level dropped in response to the reduced feedwater flow, HPCI and RCIC started as designed; however, RCIC failed to inject because of a failed limit switch. The conditional probability of core damage has been estimated at 2.0×10^{-5} . The relative significance of this event compared with other potential events at Hatch 2 is shown below.



Event Description

While at 98%, operators were preparing a condensate pump for service later in the day. In the process of filling and venting the pump, an air bubble was released into the condensate system, which tripped the condensate booster pumps and the reactor feedwater pumps. Reactor level dropped, causing a reactor scram and automatic initiation of the HPCI and RCIC pumps. Although RCIC started as designed, the pump failed to ramp up due to a failed limit switch on valve 2E51-F045. As a consequence of the failed limit switch, the RCIC woodward controller would not respond to speed demands.


The root cause of the event has been identified as a deficient condensate and feedwater vent and fill procedure while the unit is at power. Additionally, the limit switch on valve 2E51-F045 was replaced.

ASP Modeling Assumptions and Approach

This event has been modeled as a loss of feedwater and reactor trip with RCIC failed.

Analysis Results

The conditional probability estimated for the event is 2.0×10^{-5} , a moderate significance event. The dominant sequence to core damage ($p = 9.3 \times 10^{-6}$) involves failure of an SRV to close following the trip ($p = 0.036$), failure of HPCI ($p = 0.02$), and failure to depressurize using ADS ($p = 0.013$). The failure of RCIC impacts the third most dominant sequence (4.9×10^{-6}). In this sequence, all SRVs successfully close, but all high-pressure injection plus depressurization capability is lost. The dominant core damage sequence is shown on the following event tree.



Dominant Core Damage Sequence for LER 366/88-017

CONDITIONAL CORE DAMAGE PROBABILITY CALCULATIONS

Event Identifier: 366/88-017
 Event Description: LOFW and RCIC fails to inject water
 Event Date: 05/27/88
 Plant: Hatch 2

INITIATING EVENT

NON-RECOVERABLE INITIATING EVENT PROBABILITIES

TRANS 1.0E+00

SEQUENCE CONDITIONAL PROBABILITY SUMS

End State/Initiator	Probability
CD	
TRANS	2.0E-05
Total	2.0E-05
ATWS	
TRANS	3.0E-05
Total	3.0E-05

SEQUENCE CONDITIONAL PROBABILITIES (PROBABILITY ORDER)

	Sequence	End State	Prob	N Rec**
28	trans -rx.shutdown PCS/TRANS srv.chall/trans.-scram srv.close FW/PCS.TRANS hpci srv.ads	CD	9.3E-06	5.0E-01
12	trans -rx.shutdown PCS/TRANS srv.chall/trans.-scram -srv.close FW/PCS.TRANS -hpci rhr(sdc) rhr(spcool)/rhr(sdc)	CD	5.2E-06	1.1E-01
20	trans -rx.shutdown PCS/TRANS srv.chall/trans.-scram -srv.close FW/PCS.TRANS hpci RCIC crd srv.ads	CD	4.9E-06	5.0E-01
99	trans rx.shutdown	ATWS	3.0E-05	1.0E+00

** non-recovery credit for edited case

SEQUENCE CONDITIONAL PROBABILITIES (SEQUENCE ORDER)

	Sequence	End State	Prob	N Rec**
12	trans -rx.shutdown PCS/TRANS srv.chall/trans.-scram -srv.close FW/PCS.TRANS -hpci rhr(sdc) rhr(spcool)/rhr(sdc)	CD	5.2E-06	1.1E-01
20	trans -rx.shutdown PCS/TRANS srv.chall/trans.-scram -srv.close FW/PCS.TRANS hpci RCIC crd srv.ads	CD	4.9E-06	5.0E-01
28	trans -rx.shutdown PCS/TRANS srv.chall/trans.-scram srv.close FW/PCS.TRANS hpci srv.ads	CD	9.3E-06	5.0E-01
99	trans rx.shutdown	ATWS	3.0E-05	1.0E+00

** non-recovery credit for edited case

SEQUENCE MODEL: c:\asp\sealmod\bwrcseal.cmp
 BRANCH MODEL: c:\asp\sealmod\hatch.s11
 PROBABILITY FILE: c:\asp\sealmod\bwr_cs11.pro

No Recovery Limit

BRANCH FREQUENCIES/PROBABILITIES

Branch	System	Non-Recov	Opr Fail
trans	6.1E-04	1.0E+00	
loop	1.6E-05	3.6E-01	
loca	3.3E-06	5.0E-01	

Event Identifier: 366/88-017

rx.shutdown	3.0E-05	1.0E+00	
rx.shutdown/ep	3.5E-04	1.0E+00	
PCS/TRANS	1.7E-01 > 1.0E+00	1.0E+00	
Branch Model: 1.OF.1			
Train 1 Cond Prob:			
srv.chall/trans.-scram	1.7E-01 > Failed		
srv.chall/loop.-scram	1.0E+00	1.0E+00	
srv.close	2.6E-02	1.0E+00	
emerg.power	5.4E-04	8.0E-01	
ep.rec	1.6E-01	1.0E+00	
FW/PCS.TRANS	4.6E-01 > 1.0E+00	3.4E-01 > 1.0E+00	
Branch Model: 1.OF.1			
Train 1 Cond Prob:			
fw/pcs.loca	4.6E-01 > Failed		
hpci	1.0E+00	3.4E-01	
RCIC	2.9E-02	7.0E-01	
	6.0E-02 > 1.0E+00	7.0E-01 > 1.0E+00	
Branch Model: 1.OF.1			
Train 1 Cond Prob:			
crd	6.0E-02 > Failed		
srv.ads	1.0E-02	1.0E+00	1.0E-02
lpcs	3.7E-03	7.1E-01	1.0E-02
lpci(rhr)/lpcs	3.0E-03	3.4E-01	
rhr(sdc)	1.0E-03	7.1E-01	
rhr(sdc)/-lpci	2.1E-02	3.4E-01	1.0E-03
rhr(sdc)/lpci	2.0E-02	3.4E-01	1.0E-03
rhr(spcool)/rhr(sdc)	1.0E+00	1.0E+00	1.0E-03
rhr(spcool)/-lpci.rhr(sdc)	2.0E-03	3.4E-01	
rhr(spcool)/lpci.rhr(sdc)	2.0E-03	3.4E-01	
rhrsw	9.3E-02	1.0E+00	
	2.0E-02	3.4E-01	2.0E-03

* branch model file
** forced

Minarick
11-13-1989
17:24:28