



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

FEB 08 1988

Docket Nos. 50-348
and 50-364

LICENSEE: Alabama Power Company (APCo)
FACILITY: Joseph M. Farley Nuclear Plant, Units 1 and 2
SUBJECT: SUMMARY OF MEETING HELD ON JANUARY 15, 1988, BETWEEN NRC AND
APCo REPRESENTATIVES TO DISCUSS GENERIC IMPLICATIONS OF A
CRACKED 6-INCH SAFETY INJECTION PIPE AT FARLEY UNIT 2 (TAC
66773)

Introduction

The NRC Project Manager (E. Reeves) reviewed the purpose of the meeting as noticed. The meeting was requested by NRC to have APCo discuss the event, the actions taken following the event, the results of the metallurgical examinations, the causal factors (thermal fatigue), the actions taken to preclude further problems, and a review of the small break loss of coolant accident reanalysis. The list of attendees and a meeting agenda are enclosed. Enclosure pages 1-98 are the handouts used during the meeting.

Discussion

APCo (R. P. McDonald, Senior Vice President Nuclear) provided the opening remarks and noted that J. Garlington of APCo would coordinate the presentations which included Westinghouse representatives (G. Rao, D. Rourty and R. Magee) and APCo (R. Fucich and S. Burns). The handouts were used extensively during the discussions of each specific area identified in the enclosed agenda. A brief synopsis is given in these minutes.

The event occurred at Unit 2 on December 8, 1987, as described in Licensee Event Report No. 87-010 dated January 6, 1988. A coolant pressure boundary leakage of slightly less than 1.0 gpm was discovered in a section of safety injection (SI) piping on the reactor coolant system loop B cold leg. The unit was operating at 33 percent power prior to shutdown on December 9. The refueling outage for Cycle 6 operation had been completed on December 2, 1987.

APCo (R. Fucich) presented a discussion, II. Overview (enclosure pages 1-7), including the crack summary, event chronology, testing methodology and instrumentation installed on loop B and C SI line sections. He stated that the interim engineering evaluation attributes the crack to thermal fatigue and supports continued operation of both units while the evaluation is being finalized.

APCo (S. Burns) presented a discussion, III. Inspections (enclosure pages 8-16), including test personnel, procedures, and non-destructive examination (NDE) techniques. The results using enhanced ultrasonic techniques confirmed the presence of cracks on both sides of weld #16 with approximately 6-inches of combined length. The through-wall crack was about one inch in length at the 6 o'clock position (bottom of a horizontal line). Table 1 on enclosure page 16 shows the NDE test results of the 6-inch loop B SI line welds including weld #16 which cracked.

8802250389 880208
PDR ADOCK 05000348
P PDR

Westinghouse (G. RAO) presented a discussion, IV.1 Metallurgical Evaluations (enclosure pages 17-47), with the objective of establishing the mechanism and causes of the cracking. A summary of the results of surface examination confirmed the presence of circumferential cracks, one on each side of the weld, approximately three inches long which then ran into the weld metal near the 6 o'clock location (refer to pages 22 and 23 of enclosure). Fractographic examination results suggest that cracking was initiated on the ID surface and progressed radially outward to the OD. The conclusion is that the cracking occurred by a high cycle fatigue mechanism. No abnormalities were reported in the mechanical or chemical properties of the pipe or the weld.

Westinghouse (D. Rourty) presented a discussion, IV.2 Evaluations of Unit 2 Loop Experience (enclosure pages 48-53), describing the operational test program installed on loop B and on loop C as a control location. Both thermal measuring instruments and vibration instruments were utilized in the analysis. The thermal measurements revealed that large temperature stratifications (exceeding 200°F) and temperature fluctuations existed from the top to the bottom of the SI pipe in the bottom of the pipe where the failures (cracks) occurred. The evaluation shows that cooler water in small quantities (less than 1 gpm estimated) was flowing through the upstream checkvalve in the B loop SI piping. The colder water came from a leaking bypass valve around the boron injection tank. When the flow was diverted to reduce the pressure upstream of the check valve, the temperature cycling and stratification ceased.

Westinghouse (D. Rourty) continued with a discussion, IV.3 Analytical Evaluations and IV.4 Conclusions (enclosure pages 54-58), which concluded that the pipe cracked by fatigue due to thermal loads resulting from thermal cycling combined with temperature stratification.

The discussion continued with agenda item V, Forward Looking Evaluations and Actions, with the participation of Westinghouse and APCo representatives. This included discussions of fluid systems, impact of in-leakage on the nozzle thermal sleeve, and other lines subject to similar experiences. Other lines were the auxiliary spray line, normal charging and alternate charging lines, and both the cold leg and hot leg SI lines. Westinghouse (R. Magee and D. Rourty) gave these discussions. The conclusion was that a potential mechanism exists on the hot leg SI line as well as the cold leg SI line, but the probability is minimized given a secure pressure boundary from cooler water in-leakage as occurred in the B loop cold leg SI line where the crack was found. The auxiliary spray line and the normal and alternate changing lines would not be of significant concern according to the evaluation presented (enclosure pages 59-71).

Thermal sleeves located inside the SI lines at the entry to the reactor coolant loop were considered in the evaluation. Farley Unit 1 and 2 B loop cold leg SI line thermal sleeves were previously dislodged and recovered in the reactor vessels (Unit 1 during the 1983 refueling outage and Unit 2 during the recent outage). Westinghouse has recommended elimination of thermal sleeves from such plant designs later than the Farley time frame. Previous Westinghouse studies have concluded that the thermal sleeve failures resulted from flow induced vibration. The discussion, V.2 Thermal Sleeve Considerations (enclosure pages 72 and 73), concludes that the thermal sleeve integrity and nozzle integrity would not be affected by the thermal mechanism which caused the pipe cracks.

Westinghouse (D. Rourty) concluded the discussion with agenda item V.3, Continued Acceptability of Units 1 and 2 (enclosure pages 74-93). The review was very comprehensive including the list of items shown on page 74 of the enclosure. The thermal cycling mechanism which resulted in the crack projection was clearly shown by use of temperature profiles versus time plotting. A conclusion was drawn that the preliminary leak-before-break evaluations indicate that no double ended break would occur prior to leak detection.

Summary

The licensee (R. McDonald) summarized future actions being considered at this time as follows:

- (1) Additional monitoring review
- (2) Completion of the final Westinghouse analyses
- (3) Contact with Owner's Group in active lead role
- (4) A revised entry to the INPO Notepad to supplement their earlier one
- (5) Westinghouse considering letter to customers

APCo (J. Garlington) presented agenda item VI, A Small Break Loss of Coolant Accident (SBLOCA) Evaluation (enclosure pages 94-98). He noted that a letter dated January 14, 1988, has been sent to NRC with the detailed description per 10 CFR 50.46, Appendix K. Evaluation results (see page 97 of enclosure) show a +46°F spillage correction and a +9°F reporting correction. Thus, Units 1 and 2 proposed fuel peak clad temperatures are 1875°F and 1758°F, respectively. Considerable margin exists to the 10 CFR 50.46 limit of 2200°F.

In closing, APCo (R. McDonald) expressed appreciation for the opportunity to review the current status of the actions taken since the event occurred. NRC (G. Lainas) expressed the staff's appreciation to APCo for a very complete and detailed licensee presentation. At this point the meeting adjourned.

151

Edward A. Reeves, Senior Project Manager
Project Directorate II-1
Division of Reactor Projects - I/II

Enclosures:
As Stated

cc w/Enclosure:
See next page

ER
PM: PDII-1
EReeves
2/5/88

EA
DC: PDII-1
EAdensam
2/8/88

MEETING SUMMARY DISTRIBUTION

Docket No. 50-400 ^{348, 364}

NRC PDR

Local PDR

PD II-1 r/f

E. Adensam

Attorney, OGC

P. Anderson

E. Jordan

J. Partlow

ACRS (10)

Project Manager E. Reeves

NRC PARTICIPANTS

E. Reeves

E. Lobe1

R. Woodruff

G. Lainas

E. Merschoff

A. Herdt

C. Y. Cheng

K. Wichman

W. Troskoski

H. Dance

I. Bukulmez

J. Thoma

M. Hum

S. Seller

S. Lee

R. Jones

W. Hodges

J. Richardson

P. Kuo

Mark Hartzman

Kamal Manoly

E. Brown

W. Hazelton

L. Marsh

R. Wright

K. Eccleston

CC: Applicant & Service List

Mr. R. P. McDonald
Alabama Power Company

Joseph M. Farley Nuclear Plant

cc:

Mr. W. O. Whitt
Executive Vice President
Alabama Power Company
Post Office Box 2641
Birmingham, Alabama 35291-0400

D. Biard MacGuineas, Esquire
Volpe, Boskey and Lyons
918 16th Street, N.W.
Washington, DC 20006

Mr. Louis B. Long, General Manager
Southern Company Services, Inc.
Post Office Box 2625
Birmingham, Alabama 35202

Charles R. Lowman
Alabama Electric Corporation
Post Office Box 550
Andalusia, Alabama 36420

Chairman
Houston County Commission
Dothan, Alabama 36301

Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 2900
Atlanta, Georgia 30303

Ernest L. Blake, Jr., Esquire
Shaw, Pittman, Potts and Trowbridge
2300 N Street, N.W.
Washington, DC 20037

Claude Earl Fox, M.D.
State Health Officer
State Department of Public Health
State Office Building
Montgomery, Alabama 36130

Robert A. Buettner, Esquire
Balch, Bingham, Baker, Hawthorne,
Williams and Ward
Post Office Box 306
Birmingham, Alabama 35201

Mr. J. D. Woodard
General Manager - Nuclear Plant
Post Office Box 470
Ashford, Alabama 36312

Resident Inspector
U.S. Nuclear Regulatory Commission
Post Office Box 24 - Route 2
Columbia, Alabama 36319

List of Attendees

E. A. Reeves, NRR
R. Lobel, NRR
Roger Woodruff, NRR
G. Lainas, NRR
E. W. Merschoff, RII
A. R. Herdt, RII
C. Y. Cheng, NRR
K. R. Wichman, NRR
W. Troskoski, OEDO
H. C. Dance, RII
I. Bukulmez, NRR
J. Thoma, NRR
M. Hum, NRR
C. D. Sellers, NRR
S. Lee, NRR
R. C. Jones, NRR
Wayne Hodges, NRR
D. V. Jagannath, Bechtel
K. C. Gandhi, Bechtel
W. J. Engel, Bechtel
A. A. Jerome, Westinghouse
Ken Voytell, Westinghouse
Robert Magee, Westinghouse
David Rourty, Westinghouse
Gutti Rao, Westinghouse
Clem Eicheldinger, Westinghouse
Lid Burns, Alabama Power Co.
Robert Fucich, Alabama Power Co.
Robert Davis, Southern Co. Service
D. C. Adamonis, Westinghouse
Bill Shipman, Alabama Power Co.
John Garlington, Alabama Power Co.
Pat McDonald, Alabama Power Co.
Jim Richardson, NRR
P. T. Kuo, NRR
Mark Hartzman, NRR
Kamal Manoly, NRR
Walt Tauche, Westinghouse
Robert Osterrletder, Westinghouse
Carl Hirst, Westinghouse
Earl J. Brown, AEOD
Warren S. Hazelton, NRR
L. B. Marsh, NRR
Robert J. Wright, NRR
K. Eccleston, NRR

MEETING AGENDA

JANUARY 15, 1988

Farley Nuclear Plant Unit 2 Cold Leg
Safety Injection Line Crack

9:00 a.m.	I. Preface - Opening Remarks	R. P. McDonald
9:10 a.m.	II. Overview	R. S. Fucich
9:35 a.m.	III. Inspections - Nondestructive examinations at FNP	S. T. Burns
	IV. Evaluations With Respect to Unit 2 B Loop Experience	Westinghouse
9:45 a.m.	1. Metallurgical evaluations -- <i>GUTTI RAO - W</i>	
10:30 a.m.	2. Test instrumentation -- <i>DAVID ROURTY - W</i>	
10:45 a.m.	3. Analytical evaluations -- <i>DAVID ROURTY - W</i>	
11:20 a.m.	4. Conclusion	
	V. Forward Looking Evaluations and Actions (Units 1 & 2)	
11:30 a.m.	1. Discussion of other locations in Units 1 and 2 subject to same concern	Westinghouse <i>ROBERT MAGEE</i>
11:40 a.m.	2. Thermal sleeve evaluations	Westinghouse <i>D. ROURTY</i>
11:50 a.m.	3. Continued acceptability of Unit 2 B loop CL SI line and components	Westinghouse <i>D. ROURTY</i>
12:00 p.m.	4. Summary of future actions	R. P. McDonald
12:10 p.m.	VI. Small Break LOCA Analysis	J. E. Garlington
12:20 p.m.	VII. Questions and Answers	All
	VIII. Conclusion	R. P. McDonald

II. OVERVIEW - R. FUCICH

CRACK SUMMARY

EVALUATIONS AND TESTING CONDUCTED TO DATE INDICATE THAT THE CRACKING RESULTED FROM FATIGUE CAUSED BY THERMAL CYCLING

OVERVIEW PURPOSE

TO QUICKLY REVIEW THE EVENT AND ACTIONS TAKEN TO DETERMINE ITS CAUSE

TO SET THE STAGE FOR OTHER PRESENTATIONS WHICH WILL PROVIDE DETAILS OF INSPECTIONS AND EVALUATIONS WHICH HAVE BEEN PERFORMED TO DATE

CRACK EVENT CHRONOLOGY

12/08/87 (2255) UNIT 2 AT 33% POWER RETURNING FROM REFUELING OUTAGE

- CONTAINMENT COOLER DRAIN POT LEVELS NOTED AS ABNORMALLY HIGH

- A CONTAINMENT ENTRY WAS MADE WHICH IDENTIFIED A LEAK IN THE VICINITY OF THE B LOOP RESISTANCE TEMPERATURE DETECTOR (RTD) MANIFOLD

A UNIT SHUTDOWN WAS MADE TO REPAIR THE LEAK

CLOSE EXAMINATION AFTER SHUTDOWN REVEALED PRESSURE BOUNDARY LEAKAGE IN A WELDED JOINT (WELD 16) ON THE B LOOP COLD LEG SI/RHR SIX INCH LINE BETWEEN A CHECK VALVE AND THE RCS LOOP

WHILE IN HOT STANDBY LEAKAGE WAS SLIGHTLY LESS THAN ONE GALLON PER MINUTE

12/09/87 (1916) UNIT 2 ENTERED COLD SHUTDOWN

CONVENTIONAL ULTRASONIC EXAMINATION (UT) LOCATED THE CRACK
BUT DID NOT INDICATE A REPORTABLE INDICATION

ENHANCED UT WAS USED TO LOCATE AND VERIFY THE EXTENT OF THE
CRACK; X-RAY (RT) CONFIRMED CRACK

AS UNIT 1 WAS IN A SHUTDOWN (EQ MODIFICATIONS), THE FOLLOWING
INVESTIGATIONS WERE CARRIED OUT ON BOTH FNP UNITS TO
DETERMINE THE EXTENT OF THE PROBLEM AND POSSIBLE CAUSES:

- WELDS ON EACH SIX INCH COLD LEG SI/RHR LINES
WERE INSPECTED USING ENHANCED UT
- FABRICATION AND CONSTRUCTION X-RAYS FOR THESE WELDS
WERE REVIEWED FOR ANY POSSIBLE MISSED INDICATIONS
- ALL SIX LINES WERE WALKED DOWN FOR EVIDENCE OF
VIBRATION OR BINDING AND GENERAL PIPING GEOMETRY
- THE FATIGUE ANALYSES WERE REVIEWED

- NO OTHER CRACKS WERE FOUND NOR WERE ANY
CONDITIONS FOUND WHICH COULD EXPLAIN THE CRACK

THE FOLLOWING ADDITIONAL ITEMS WERE REVIEWED FOR THE UNIT 2
B LINE:

- STRESS REPORT
- HOT FUNCTIONAL TEST DATA
- OPERATION HISTORY (SAFETY INJECTIONS, CHEMISTRY
EXCURSIONS, WATER HAMMER, ETC.)
- NO EVIDENCE WAS FOUND TO EXPLAIN THE CRACKED JOINT

THE PIPE SECTION WAS REMOVED AND SENT TO WESTINGHOUSE FOR
EXAMINATION

- PRELIMINARY RESULTS INDICATED A FATIGUE MECHANISM
- NO SIGNIFICANT MOVEMENT WAS NOTED WHEN THE PIPE WAS CUT

WHILE THE PIPE SECTION WAS REMOVED, A VISUAL EXAMINATION WAS
CONDUCTED ON THE NOZZLE INSIDE DIAMETER FOR DEGRADATION
CAUSED BY THE LOSS OF THE THERMAL SLEEVE

REPLACEMENT PIPING WAS WELDED IN PLACE, EXAMINED AND TESTED
AS REQUIRED BY THE ASME CODE

RESISTANCE TEMPERATURE DETECTORS AND ACCELEROMETERS WERE
ATTACHED TO THE REPAIRED LOOP B PIPING AND TO LOOP C AS
A CONTROL

THE REPAIRED LINE WAS MONITORED DURING ITS HEATUP TO VERIFY THERMAL MOVEMENT WAS AS PREDICTED AND THAT IT WAS NOT BINDING

TEMPERATURE DATA REVEALED A THERMAL CYCLE OCCURRING IN THE B LOOP, DOWNSTREAM OF V051B

FLOW FROM THE BORON INJECTION TANK BYPASS LINE WAS DIVERTED TO THE BORON INJECTION SURGE TANK


THERMAL CYCLING ON THE B LOOP, DOWNSTREAM OF V051B, STOPPED; HOWEVER, A THERMAL CYCLE APPEARED UPSTREAM

VIBRATION DATA COLLECTION WAS TERMINATED WHEN VIBRATION WAS ELIMINATED AS A POTENTIAL CAUSE


THE UPSTREAM THERMAL CYCLING STOPPED IN THE EARLY MORNING HOURS OF 01/08/88 BEFORE A CAUSE COULD BE DETERMINED

AN INTERIM ENGINEERING EVALUATION WAS OBTAINED WHICH ATTRIBUTES THE CRACK TO THERMAL FATIGUE AND WHICH SUPPORTS CONTINUED OPERATION OF BOTH UNITS WHILE THE EVALUATION IS BEING FINALIZED

TEMPERATURE MONITORING IS CONTINUING



9



NOT TO SCALE

III. INSPECTIONS - *S. BURNS*

1. Personnel and Procedures
 - ° Personnel Certifications
 - ° Procedures
2. NDE Methods, Techniques and Results
 - ° Liquid Penetrant Examination
 - ° Ultrasonic Examination
 - Preservice and Inservice History
 - Conventional Technique
 - Enhanced Technique
 - Summary of Results
 - ° Radiographic Examination
 - ° Visual Examination
 - ° Construction Radiograph Review

1. PERSONNEL AND PROCEDURES

- ° Personnel certified to Level II or III for major NDE methods in accordance with Section XI and ASNT-TC-1A (1980)
- ° UT personnel certified to EPRI Program for IGSCC detection, sizing and overlay inspection in BWR plants
- ° UT procedures used:
 - Most conservative application of Section XI, Appendix III (S83) requirements
 - Replicated conventional procedures utilized for ISI to Section XI and Section V (S75)
- ° Other procedures used:
 - Standard practice per Section V and XI requirements


2. NDE METHODS, TECHNIQUES AND RESULTS

- ° Liquid Penetrant Examination
 - Attempted for information purposes only
 - Solvent based technique inappropriate for this application
 - No meaningful results obtained
- ° Ultrasonic Examination
 - Preservice and Inservice Inspection history of cracked weld
 - ° Preservice Inspection (8-20-79)
 - 0° and 45° shear wave examinations
 - visual examination
 - no indications recorded
 - ° Inservice Inspection (4-17-86)
 - 45° shear wave examination
 - no indications recorded
 - Conventional ultrasonic examination
 - ° 45° shear wave transducer - 3/8", 2.25 MHz
 - ° upstream, downstream and two directional circumferential scans
 - ° no recordable indications in excess of reference levels
 - ° scanning factors (Figure 1)
 - pipe configuration limits elbow side exam due to intrados
 - weld crown configuration
 - signal masking due to counter bore and root geometries
 - beam redirection decreases angle below ideal 45°

- Enhanced ultrasonic examination
 - ° 45° shear wave transducer - 3/8", 2.25 MHz
 - ° same scanning directions
 - ° 60° shear wave transducer - 3/8", 1.5 MHz
 - ° upstream and downstream scans
 - ° circumferential scan at higher angles will not permit examination of ID region
 - ° detected crack-like indications (Figure 2)
 - ° enhancements:
 - beam redirection effects on 60° shear wave improve their detection ability as true angle approaches 45°
 - additional 8 db gain improves scanning sensitivity of 45° transducer
 - recording level at 50% DAC of ^{REFERENCE}~~scanning~~ sensitivity
- Summary of results
 - ° Unit 2 (Table 1 and Figure 3)
 - one recordable indication on Loop B, weld No. 16
 - no other recordable indications on Loops A or C
 - ° Unit 1
 - Loops A, B and C had no recordable indications except for 3 welds which exhibited OD geometry (verified by signal dampening)
- ° Radiographic Examination
 - Ir 192 source at 54 curies
 - Double loaded cassettes using Type M film or equivalent
 - Confirmed presence of crack with line filled
 - ° crack located on elbow side
 - ° approximately 2 1/2" long

- Confirmed presence of cracks with line empty
 - ° cracks located on both sides of weld
 - ° approximately 6" long (total combined length)
- ° Visual Examination (Information Only)
 - Utilized high resolution video camera
 - VT-1 visual examination
 - Confirmed satisfactory condition of thermal sleeve nozzle ID, especially areas where the sleeve was tack welded to the nozzle
- ° Construction Radiograph Review
 - Purpose: To evaluate construction film and disposition of indications as shown on original reader sheets against the Section III Code requirements
 - In most cases, reader sheet accurately reflected film interpretation
 - There was insufficient information to fully disposition 5 indications (4 on Unit 2 and 1 on Unit 1) found in the review
 - Corrective actions:
 - ° Unit 2, Loop B - None required as both welds were removed as a part of the repair (Table 1 and Figure 3)
 - ° Unit 2, Loop A - Both welds were radiographed and results were satisfactory
 - ° Unit 1, Loop C - One weld will be radiographed at the next refueling outage

②




FARLEY NUCLEAR PLANT
UNIT 2
APR-1 4210 WELD NO. 16

6" ELBOW
SCH. 160

⑬

①

6" ELBOW
SCH. 160
WALL THK. 0.719"



FARLEY NUCLEAR PLANT-UNIT 2
APR-1 4210
WELD NO. 16

①4

APR 1-4210


LOOP #2 6"-4"+2" SIS (C.L.)

6" CCA-22
4" CCA-22
2" CCA-26

5CH-160
5CH-160
5CH-160

C/B APR-1
C/B ALA-7
C/B ALA-9

Q2E21CCA26 E7862
SKE11CV2022



LOOP #2 (C.L.)
CONT'D ON
ISO 1-4200

A	2SI-R145
B	2SI-R148
C	2SI-R146
D	2SI-R147
E	2SI-R149
WS-1	2SI-R150
F	2SI-R151
G	2SI-BR9

- 16-BW 6"
- 2-BW 4"
- 6-SW 2"
- 1-BC 2"
- 1-WS
- 7-SC

D35

TABLE 1

FARLEY NUCLEAR PLANT - UNIT 2
 NDE RESULTS FROM INSPECTION
 OF 6" LOOP B SI LINE & RECORDS REVIEW

<u>SKETCH NO.</u>	<u>WELD NO.</u>	<u>UT RESULTS</u>	<u>RT REVIEW</u>	<u>RT RESULTS</u>
APR 1- 210	18	NRI	RI (3)	- (5)
	17	NRI	NC	NRI (6)
	16	RI (1)	RI (4)	RI (5) (7)
	15	NRI	NC	-
	14	NRI	-	-
	13	NRI	-	-
	12	NRI (2)	-	-

KEY:

NRI = NO RECORDABLE INDICATIONS
 RI = RECORDABLE INDICATIONS
 NC = NO CHANGE FROM DISPOSITION ON ORIGINAL RT READER SHEET

NOTES:

1. Crack-like indications determined to be approximately 6" long and 100% through-wall for a distance of 1" and centered at the 6 o'clock position.
2. Partial examination due to support clamp.
3. Slag indication 3/16" long evaluated to be acceptable.
4. Porosity with linear indications located outside the area of interest.
5. These welds were removed and replaced as a part of the repair.
6. Weld No. 17 was radiographed to confirm the absence of defects as a result of a non-recordable indication found by UT.
7. Informational radiographs verified the presence of cracks on both sides of the weld.

IV. 1. METALLURGICAL EVALUATIONS - G. RAO

OBJECTIVES:

- O ESTABLISH THE MECHANISM AND CAUSE(S) OF THE OCCURRENCE OF CRACKING

- O DEVELOP INFORMATION THAT WOULD BE HELPFUL IN TAKING CORRECTIVE ACTIONS

METALLURGICAL EVALUATIONS

MAJOR TASKS:

- 0 SURFACE EXAMINATIONS
- 0 NDE EXAMINATIONS
- 0 METALLOGRAPHIC EXAMINATIONS
- 0 FRACTOGRAPHIC EXAMINATIONS
- 0 CHEMISTRY EVALUATIONS
- 0 MICROHARDNESS MEASUREMENTS





Fig. — Schematic illustration of the SI line configuration showing the location of leakage.




Vertical
Pipe-End

Horizontal
Pipe End

Leak Location



Light macrophotographs, schematically illustrating
the sectioning procedure employed for the leaked weld.




9 O'Clock

6 O'Clock

3 O'Clock

(20)




6 O'Clock

(21)


ID surface examination results of the elbow-to-horizontal pipe weld joint showing the location of cracks seen on the elbow side and the pipe side. (3.25x)

SUMMARY OF SURFACE EXAMINATION RESULTS

- 0 SURFACE EXAMINATION RESULTS OF THE ID SURFACE OF THE WELD JOINT AT THE LEAK LOCATION CONFIRMED THE PRESENCE OF CIRCUMFERENTIAL CRACKS ONE ON EACH SIDE OF THE WELD. THE CRACK ON THE PIPE SIDE WAS LOCATED AT THE WELD INTERFACE, MEASURED APPROXIMATELY THREE INCHES LONG, AND RAN INTO THE WELD METAL NEAR THE SIX O'CLOCK LOCATION OF THE PIPE. THE CRACK ON THE ELBOW SIDE WAS LOCATED IN THE COUNTERBORE REGION OF THE BASE METAL, RAN ALONG THE SURFACE MACHINING GROOVES, AND MEASURED APPROXIMATELY THREE INCHES IN LENGTH.



General morphology of cracks seen on transverse sections taken at various locations along the weld.



(Light Etch)




(Macro-Etch)




(Darkfield)

Light optical micrographs shown in different lighting conditions,
illustrating the location and morphology of crack at the weld-to-pipe
interface(F-2 3.25X)



Light optical metallography results of the Section "C" illustrating the HAZ microstructures.




Section B

Section E

Section E

Section F

General morphology of cracks seen on transverse sections taken at various locations along the weld.



(8x)




(100x)

Illustration of the initiation of cracks at the ID surface machining grooves in the counterbore region of the elbow.


SUMMARY OF METALLOGRAPHIC EXAMINATION RESULTS

0 METALLOGRAPHIC EXAMINATIONS CONDUCTED ON TRANSVERSE SECTIONS TAKEN AT SEVERAL CIRCUMFERENTIAL LOCATIONS IN THE REGION OF CRACKING, CONFIRMED THAT THE ID SURFACE CRACKING WAS EXTENDED DEEP INTO THE PIPE THICKNESS ALL THE WAY UP TO THE OD SURFACE OF THE PIPE. THE RESULTS SHOWED THAT THE MAJOR CRACK IN THE ELBOW SIDE INITIATED AT THE KNEE OF THE COUNTERBORE REGION, PROGRESSED THROUGH THE BASE METAL AND TERMINATED IN THE WELD METAL. THE CRACK ON THE PIPE SIDE WAS INITIATED AT THE WELD METAL TO BASE METAL INTERFACE AND PROGRESSED THROUGH THE WELD METAL TOWARDS THE OUTSIDE DIAMETER SURFACE. THE CRACKING WAS PRIMARILY STRAIGHT AND TRANSGRANULAR IN CHARACTER. NO APPRECIABLE BRANCHING OR CRACK DEPOSITS WERE OBSERVED. METALLOGRAPHIC EXAMINATIONS CONDUCTED ON SEVERAL SECTIONS THROUGH THE MAJOR CRACKS FAILED TO CONFIRM THE PRESENCE OF ANY MAJOR DEFECTS IN THE WELD METAL. THE METALLOGRAPHIC EXAMINATIONS ALSO CONFIRMED THE PRESENCE OF SEVERAL FINE CRACKS INITIATED FROM THE MACHINED GROOVES OF THE COUNTERBORE REGION OF THE ELBOW.

THE OVERALL RESULTS OF THE METALLOGRAPHIC EXAMINATIONS CONFIRMED THAT THE WELD CRACKING WAS INITIATED ON THE ID SURFACE AND PROGRESSED RADIALY OUTWARDS TOWARD THE OD SURFACE. THE CRACKING WAS DEEPEST (THROUGHWALL) NEAR 6 O'CLOCK LOCATION OF THE PIPE. THE CRACKING WAS PRIMARILY CONTROLLED BY TENSILE LOADS AXIAL TO THE PIPE WITH NO APPRECIABLE CONTRIBUTION FROM ENVIRONMENTAL FACTORS.





Sample B






Sample D




Light optical fractographs illustrating the fracture morphology of the cracks seen in pieces B and D. (3.25x)




30
Scanning electron fractographs illustrating the fracture morphology of crack in piece "B".




Scanning electron fractographs of the endoxided weld crack on the pipe side illustrating the morphology of the field fractured and laboratory fractured regions.



Scanning electron fractographs of the endoxed weld crack on the pipe side illustrating the evidence of fatigue striations.




Sample B



Sample D

Light optical fractographs illustrating the positioning of various replica grids employed for the examination of the evidence for fatigue striations in Samples B and D. (3.25x)




(13,000X)




(22,000X)

Replica transmission electron micrographs illustrating the typical appearance of the fatigue striations seen at grid location G in sample B.



(6000X)




(10,000X)

Replica transmission electron micrographs illustrating the typical appearance of the fatigue striations seen at grid location I in sample D.



(3600X)



(17,000X)

Replica transmission electron micrographs illustrating the typical appearance of the fatigue striations seen at grid location F in sample B.


SUMMARY OF FRACTOGRAPHIC EXAMINATION RESULTS

- 0 FRACTOGRAPHIC EXAMINATION OF THE FRESHLY OPENED CRACKS BOTH IN THE BASE METAL AND WELD METAL REGIONS SHOWED THAT THE CRACKING WAS INITIATED ON THE INSIDE DIAMETER SURFACE AND PROGRESSED RADIALY OUTWARDS TO THE OUTSIDE DIAMETER SURFACE. CRACKING APPEARS TO HAVE BEEN INITIATED AT SEVERAL LOCATIONS OVER A BROADER REGION OF THE ID SURFACE RATHER THAN FROM A SINGLE ISOLATED INITIATION SITE. THE FRACTURE MORPHOLOGY FOLLOWED TRANSGRANULAR FACETS. HIGHER MAGNIFICATION SCANNING ELECTRON FRACTOGRAPHY CONFIRMED THE PRESENCE OF FATIGUE STRIATIONS PROGESSING FROM THE INSIDE DIAMETER SURFACE TO ALL THE WAY TO THE CRACK TIP NEAR OUTSIDE DIAMETER SURFACE. THE EVIDENCE OF FATIGUE STRIATIONS WAS ALSO CONFIRMED IN THE FRESHLY OPENED CRACK IN THE WELD METAL. HIGH RESOLUTION TRANSMISSION ELECTRON MICROSCOPY CONDUCTED ON REPLICAS TAKEN FROM VARIOUS LOCATION THE ENDOXED FRACTURE FACES CONFIRMED THAT THE FATIGUE STRIATION SPACING RANGED FROM APPROXIMATELY 4×10^{-6} TO 8×10^{-6} INCHES.

THE OVERALL RESULTS SUGGEST THAT CRACKING WAS INITIATED ON THE ID SURFACE AND PROGRESSED RADIALY OUTWARD TO THE OD. CRACKING OCCURRED BY HIGH CYCLE FATIGUE MECHANISM.

FARLEY SI PIPE
 PR= 1005 100SEC 0 INT
 U=8192 H=10KEV 1:30 AO=10KEV 10


CRACK TIP
 AREA 1A



(a)

FARLEY SI PIPE
 PR= 1005 100SEC 0 INT
 U=16K H=10KEV 1:30 AO=10KEV 10

CRACK TIP
 AREA 3A




(a)

FARLEY SI PIPE
 PR= S 109SEC 0 INT
 U=8192 H=10KEV 1:10 AO=10KEV 10

PHOTO 10,
 AREA SCAN

PIECE "E"
 WELD CRACK




(b)

FARLEY SI PIPE
 PR= S 100SEC 0 INT
 U=8192 H=10KEV 1:10 AO=10KEV 10

PHOTO 4,
 AREA SCAN

PIECE "E"
 WELD CRACK



(b)

Typical energy dispersive X-ray analysis results obtained from the crack deposits seen on the a) elbow and b) pipe cracks, in the "as opened" conditions.

CHEMISTRY ANALYSIS RESULTS OF THE
ID SURFACE DEPOSITS

(ELEMENT/COMPOUND GMS/AREA SWABBED)	F	CL	P ₀₄	N ₀₃	S ₀₄
CLEAN AREA	0.32	21.3	1.02	9.6	19.4
ID SURFACE	0.37	21.0	1.02	9.3	16.1

NO EVIDENCE OF ANY CORROSIVE ELEMENTS WAS SEEN ON THE ID
SURFACE

SUMMARY OF CHEMISTRY ANALYSIS RESULTS

ELEMENT (WT O/D)	CR	MN	Cu	Co	Ni	Mo	P	S	SI	C	FE
ELBOW MATERIAL	19.30	1.74	0.109	0.081	10.58	0.143	0.021	0.021	0.429	0.046	BAL
HORIZ. PIPE	18.48	1.72	0.121	0.056	10.68	0.155	0.018	0.014	0.474	0.068	BAL
WELD METAL	19.86	1.33	0.158	0.10	10.10	0.154	0.016	0.013	0.376	0.022	BAL
TYPE 304 S. STEEL REQUIREMENTS	18-20	2.0 MX	--	--	8 - 10.5	--	0.045	0.03	1.0 MX	0.08 MX	BAL
TYPE 308 S. STEEL STICK ELECTRODE REQUIREMENTS	19.5- 22 19.21	1.0- 2.5	0.75 MX	--	9-11 10-12	0.75 MX	0.03 MX	0.03 MX	0.3- 0.65	0.08 MX	BAL

THE CHEMISTRY OF THE ELBOW AND PIPE MATERIALS MET THE TYPE 304 STAINLESS STEEL REQUIREMENTS.
THE CHEMISTRY OF THE WELD METAL MET THE TYPE 308 STAINLESS STEEL STICK ELECTRODE REQUIREMENTS.

40

SUMMARY OF CHEMISTRY EVALUATION RESULTS

- 0 CHEMISTRY EVALUATION OF CRACK DEPOSITS BY ENERGY DISPERSIVE X-RAY ANALYSIS FAILED TO CONFIRM EVIDENCE OF ANY AGGRESSIVE ELEMENTS CONTRIBUTING TO THE CRACKING PROCESS. WET CHEMISTRY ANALYSIS RESULTS OF THE PIPE, ELBOW AND WELD MATERIALS SHOWED THAT THE ELBOW AND PIPE MATERIALS MEET THE TYPE 304 STAINLESS STEEL REQUIREMENTS WHILE THE WELD METAL MEETS THE TYPE 308 STAINLESS STEEL REQUIREMENTS.

THE OVERALL RESULTS OF THE CHEMISTRY EVALUATIONS SHOWED THAT NO CORROSIVE ELEMENTS CONTRIBUTED TO THE CRACKING PROCESS AND THAT THE ELBOW, PIPE AND WELD MATERIALS MEET THE SPECIFICATION REQUIREMENTS.

SUMMARY OF MICROHARDNESS MEASUREMENT RESULTS

	AVERAGE KNOOP HARDNESS	APPROX. TENSILE STRENGTH (KSI)
ELBOW MATERIAL	160	70
PIPE MATERIAL	158	70
WELD METAL	207	91

NO ABNORMALITIES IN THE STRENGTH LEVELS OF THE ELBOW, PIPE
AND WELD MATERIALS

HAZ MICROHARDNESS MEASUREMENT RESULTS

SERIAL NUMBER	DISTANCE FROM CRACK	KHN 500 GMS	APPROX. TENSILE STRENGTH
1	.005	238.2	107
2	.010	230.8	102
3	.015	210.7	92
4	.020	210.7	92
5	.025	211.7	93
6	.035	222.7	100
7	.055	236.9	107
8	.075	199.6	88
9	.095	192.1	85
10	.115	196.8	87
11	.135	172.8	77
12	.155	203.5	90

EBLOW HAZ HAS A SLIGHTLY HIGHER HARDENER COMPARED TO THE UNAFFECTED BASE METAL

SUMMARY OF MICROHARDNESS MEASUREMENT RESULTS

O MICROHARDNESS MEASUREMENTS MADE ON THE POLISHED SECTION OF THE WELD JOINT SHOWED THAT THE MICROSTRUCTURES OF THE ELBOW, WELD AND PIPE MATERIALS, RESPECTIVELY CORRESPONDED TO KNOOP HARDNESS LEVELS OF 160, 207 AND 158. THESE HARDNESS VALUES CORRESPONDED TO AN APPROXIMATE TENSILE STRENGTH LEVELS OF 90 KSI IN THE WELD METAL AND 70 KSI IN THE PIPE AND ELBOW MATERIALS.

NO ABNORMALITIES IN MECHANICAL PROPERTIES WERE SEEN.

OTHER MECHANISMS

- O NO EVIDENCE OF BRANCHING, CRACK DEPOSITS OR CONTAMINANTS. STRESS CORROSION IS NOT A MECHANISM.

- O NO EVIDENCE OF OVERLOAD DIMPLES. OVERLOAD IS NOT A MECHANISM.

- O NO WELD DEFECTS. HOT CRACKING OR OTHER WELD DEFECTS ARE NOT CONTRIBUTING FACTORS.

CONCLUSIONS

- 0 THE OBSERVED CRACKING IN THE FARLEY 2 SI LINE WELD WAS INITIATED AT THE ID SURFACE AND PROGRESSED RADIALLY OUTWARD TOWARDS THE OD SURFACE OF THE PIPE.

- 0 THE CRACKING OCCURRED BY HIGH CYCLE FATIGUE MECHANISM.

- 0 MACHINING MARKS IN THE COUNTER BORE REGION (IN THE ELBOW) AND THE WELD INTERFACE (IN THE PIPE) SERVED AS PREFERRED SITES FOR CRACK INITIATION.

- 0 THE FATIGUE STRIATION SPACINGS ON THE FRACTURE FACE VARIED APPROXIMATELY BETWEEN 2×10^{-6} IN. TO 8×10^{-6} IN.

NONDESTRUCTIVE EXAMINATION RESULTS

- 0 FLUORESCENT DIE PENETRANT TEST RESULTS OF THE ID SURFACE OF THE ELBOW TO VERTICAL PIPE WELD JOINT DID NOT REVEAL EVIDENCE OF ANY ID INITIATED CRACKING.

- 0 RT EXAMINATIONS RESULTS OF THIS WELD JOINT SHOWED PRESENCE OF ACCEPTABLE LEVEL OF INCLUSION SITES IN THE WELD.

- 0 PT EXAMINATION RESULTS OF THE ID SURFACE OF THE ELBOW, BOTH ON THE INTRADOS AND EXTRADOS REGIONS DID NOT SHOW EVIDENCE OF ANY ID INITIATED CRACKING.

CONCLUSION: THE ELBOW AND THE WELD JOINT #17 MAY NOT BE SEEING THE LOADING CONDITIONS SEEN BY WELD #16

IV.2 EVALUATIONS OF UNIT 2 B LOOP EXPERIENCE - *D. ROURTY*

2. OPERATIONAL TEST PROGRAM.

A. SELECTION OF INSTRUMENTATION

- o ASSUMED CRACK RESULTED FROM FATIGUE
MECHANICAL - VIBRATION
THERMAL - STRATIFICATION & CYCLING
- o VIBRATION MEASUREMENTS: ACCELEROMETERS
TYPE: PIEZOELECTRIC, ENDEVCO 7701-100
RANGE: 1 - 5000 HZ, 0 - 1000 g
- o THERMAL MEASUREMENTS RTD'S
TYPE: PLATINUM SURFACE RTD; HY-CAL: RTS-63
RANGE: - 100⁰ TO 900⁰F
- o STRAIN GAUGES NOT USED DUE TO INHERENT DIFFICULTIES
WITH CYCLIC THERMAL LOADINGS

IV.2

B. SELECTION OF TEST LOCATIONS

o VIBRATION

LOOP B - CRACK LOCATION

LOOP C - CONTROL

MAXIMUM ANTICIPATED VIBRATION

o THERMAL

LOOP B - CRACK LOCATION

LOOP C - CONTROL

OUTSIDE WALL TEMPERATURE

o LOOP C AS CONTROL

LOOP A HAD ADDITIONAL RIGID RESTRAINT

NEAR VALVE V051

LOOP C HAS LONGER HORIZONTAL RUN AND COULD

EXHIBIT MORE EFFECTS OF STRATIFICATION

LOOP A OR LOOP C ACCEPTABLE AS CONTROL, FINAL

CHOICE BASED ON CONTAINMENT ACCESS CONSIDERATIONS

IV.2

C. SUMMARY OF TEST RESULTS

1. VIBRATION

FFT ANALYSIS TO OBTAIN PEAK SPECTRUM
REVIEWED FREQ. RANGE 4-100 HZ
MAXIMUM G LEVELS APPROX: .1
MAXIMUM DISPLACEMENT LEVELS: .00077 INCHES

2. THERMAL RESULTS PRIOR TO BIT FLOW DIVERSION

LOOP B: LARGE STRATIFICATION
215⁰F DOWNSTREAM
128⁰F UPSTREAM

LOOP B: TEMPERATURES FLUCTUATE SIGNIFICANTLY,
PARTICULARLY AT BOTTOM OF PIPE, PERIOD
OF CYCLING BETWEEN 2 AND 20 MINUTES

LOOP C: VERY LITTLE STRATIFICATION OR
FLUCTUATIONS

CONCLUSIONS

LOOP C CONFIGURATION AS EXPECTED
LOOP B PROBABLY HAD SMALL FLOW OF COOLER
WATER FLOWING INTO DOWNSTREAM PIPING

IV.2

D. EVALUATION OF CAUSE OF DOWNSTREAM THERMAL CYCLING

- o COOLER WATER IN SMALL QUANTITIES
FLOWED INTO RCS PIPING AT VARIOUS RATES
- o FLOW REQUIRED A WATER SOURCE WITH GREATER THAN
RCS PRESSURE (CHARGING SYSTEM)
- o TWO POSSIBLE CAUSES IDENTIFIED:
 - o VALVE 8885 LEAKAGE - 3" GATE
 - o VALVE 8911 LEAKAGE - 1" GLOBE - BYPASS LINE

IV.2

E. BIT FLOW DIVERSION

- o LEAKAGE FLOW DIVERTED TO BIT SURGE TANK
- o RTD READINGS INDICATE DOWNSTREAM STRATIFICATION AND CYCLING STOPPED
- o NO CHANGE IN LOOP C READINGS
- o TEMPORARY THERMAL CYCLING OBSERVED UPSTREAM ON LOOP B
- o CURRENTLY STEADY-STATE RESPONSE ON ALL READINGS, POSSIBLY FLOW IN LOOP B UPSTREAM
- o CONCLUSION:

FLOW DIVERSION HAS STOPPED COLD WATER
FLOW TO RCS

MOST LIKELY CAUSE OF LEAKAGE WAS VALVE 8911

IV.2

F. THERMAL - AFTER B. I. FLOW DIVERSION - CURRENT STATUS

- o LOOP B DOWNSTREAM STRATIFICATION AND TEMPERATURE FLUCTUATION
- o LOOP C - NO EFFECT
- o INITIALLY OBSERVED LOW FREQUENCY THERMAL OSCILLATIONS, UPSTREAM LOOP B
- o CURRENTLY LOOP B AND C STEADY STATE

IV.3 ANALYTICAL EVALUATIONS - D. ROVRTY

A. VIBRATION

- o CORRELATED SPECTRAL CURVES TO MODAL ANALYSIS
- o MAXIMUM STRESS ABOUT 500 PSI AT WELD
- o CONCLUSION: VIBRATION HAD NEGLIGIBLE EFFECT ON OBSERVED PIPE CRACK

B. COLD SPRING

- o SMALL AMOUNT OF COLD SPRING (ABOUT .6 INCH) EVALUATED
- o LESS THAN 500 PSI AT WELD
- o CONCLUSION: NOT RELATED TO PIPE CRACK

C. VALVE EFFECTS

- o VALVE LEAKAGE THROUGH SMALL GLOBE VALVE PRIMARY CAUSE OF CYCLING
- o THE EXPECTED OPENING AND CLOSING OF THE CHECK VALVE (V051B) WITH A SMALL ΔP PROBABLY CAUSED THE FLUCTUATION IN THE THERMAL LOAD
- o BACK LEAKAGE AT CHECK VALVE CAN CAUSE STRATIFICATION BUT NOT THERMAL CYCLING
- o NO KNOWN RELATIONSHIP BETWEEN CHECK VALVE PERFORMANCE AND MECHANISM OBSERVED

IV.3.D THERMAL CYCLING EVALUATIONS

1. THERMAL STRESS ANALYSIS

a) DEVELOPMENT OF THERMAL LOADING

o FINITE ELEMENT CORRELATION OF OUTSIDE WALL TEMPERATURE AND INSIDE TEMPERATURE INDICATES FULL TEMPERATURE CYCLING AND THREE MINUTE PERIOD REASONABLE ASSUMPTION

o CONCLUSION:

-- REASONABLE TO ASSUME 550° TO 100° CYCLING

-- REASONABLE TO ASSUME 3 MINUTE PERIOD

b) THERMAL CYCLING STRESSES

o UNIFORM TEMPERATURE CYCLES APPLIED TO 2-D AXISYMMETRIC FINITE ELEMENT MODEL

o MAXIMUM 550° TO 100° STEP CHANGES, 3 MINUTE PERIOD

o MAXIMUM MINIMUM STRESS PROFILE DETERMINED

D. THERMAL CYCLING EVALUATION

2. FRACTURE MECHANICS/FATIGUE CRACK GROWTH

a) ANALYSIS BASED ON METALOGRAPHY

- o STRIATION SPACING USED TO ESTIMATE
DA/DN VS T
- o DA/DN = CRACK GROWTH PER CYCLE
T = WALL THICKNESS
- o USE DA VS T CURVE TO ESTIMATE ΔK
 ΔK = RANGE OF STRESS INTENSITY
- o USE K TO DETERMINE ΔS
 ΔS = RANGE OF APPLIED STRESS
- o OBTAIN CYCLES TO LEAKAGE

b) ANALYSIS BASED ON THERMAL STRESS ANALYSIS

- o THERMAL STRESS USED IN FATIGUE CRACK
GROWTH CALCULATION
- o DA/DN FOR AUSTENITIC STAINLESS STEEL
$$DA/DN = (2.42 \times 10^{-20})(E)(\Delta K)^{3.3}$$

E = ENVIRONMENTAL FACTOR (2.0)
- o OBTAIN CYCLES TO LEAKAGE

CONCLUSION: STRESS PROFILE CALCULATED FROM STRIATION
SPACING IS CHARACTERISTIC OF THERMAL LOADINGS

IV.3.

3. ASME FATIGUE EVALUATION

- o PURPOSE: CALCULATE USAGE FACTORS PER ASME CODE SECTION III, FOR SIS COLD LEG PIPING

- o EVALUATION INCLUDED ALL CLASS 1 PIPING COMPONENTS ON 6" SIS COLD LEG LINES PLUS RCL NOZZLE

- o LOADINGS INCLUDED:
 - DESIGN TRANSIENTS (SI, RHR, OBE, ETC.)
 - THERMAL CYCLING (BEFORE AND AFTER B.I. FLOW DIVERSION)

- o CONCLUSION:
ALL COMPONENTS SATISFY ASME REQUIREMENTS FOR PLANT LIFE

IV.4 CONCLUSION

- o PIPE CRACK WAS NOT CAUSED BY POOR FABRICATION/INSTALLATION/MATERIALS
- o PIPE CRACK WAS NOT CAUSED BY ENVIRONMENTAL CONSIDERATIONS
- o PIPE CRACK WAS NOT CAUSED BY DESIGN LOADINGS
- o PIPE CRACK WAS NOT CAUSED BY VIBRATION
- o PIPE CRACK WAS NOT RELATED TO CHECK VALVE MAINTENANCE HISTORY
- o CRACKING CAUSED BY FATIGUE DUE TO THERMAL LOADS
- o THERMAL LOADS RESULTED FROM THERMAL CYCLING COMBINED WITH STRATIFICATION
- o THERMAL CYCLING AND STRATIFICATION CAUSED BY COOLER WATER FLOW FROM HIGH PRESSURE UPSTREAM SOURCE TO RCS
- o COOLER WATER FLOW PROBABLY RESULTED FROM LEAKAGE THROUGH 1" BIT BYPASS VALVE
- o SIS COLD LEG PIPING SATISFIES ASME REQUIREMENTS

V. / FLUID SYSTEMS EVALUATION OF A AND C
COLD LEG INJECTION LINES

- NDE PROVIDED NO EVIDENCE OF THERMAL CYCLING ON A AND C LOOPS
- GIVEN THE AMOUNT OF IN-LEAKAGE, THE EVALUATION OF THE LOOP B TEMPERATURE TRACES CONCLUDES THAT THE A AND C LOOPS WERE NOT EFFECTED
- INSTRUMENTATION ON C LOOP DETECTED NO THERMAL CYCLING

CONCLUSION:

LOOP B PROVIDED A PREFERRED LEAK PATH AND WAS THEREFORE THE ONLY EFFECTED LINE.


FLUID SYSTEMS EVALUATION OF IMPACT OF
IN-LEAKAGE ON THERMAL SLEEVE

- IN-LEAKAGE WAS RELATIVELY SMALL, AND UNABLE TO SWEEP THE ENTIRE CROSS SECTION OF THE 6" HORIZONTAL SI LINE
- RELATIVELY COLD FLUID WOULD HAVE TO TRAVEL 22" ALONG THE HORIZONTAL SECTION AND 17" ALONG THE VERTICAL SECTION BEFORE REACHING THE THERMAL SLEEVE
- THE VERTICAL SECTION IS CHARACTERIZED BY SIGNIFICANT MIXING OF FLUID GIVEN:
 - CIRCULATION DUE TO NATURAL CONVECTION
 - PROXIMITY TO THE DISCHARGE OF THE RCP

CONCLUSION:

GIVEN THE AMOUNT OF IN-LEAKAGE, DISPERSION EFFECTS IN THE HORIZONTAL AND VERTICAL PIPE SECTIONS PRECLUDES THE THERMAL SLEEVE FROM EXPERIENCING THE THERMAL TRANSIENT

Loop B C. L. Injection Line



OTHER LINES SUBJECT
TO
SIMILAR EXPERIENCES

CRITERIA:

ANY ISOLATED LINE WHERE RELATIVELY COLD FLUID COULD BE INJECTED INTO THE RCS DUE TO AN IN-LEAKAGE FROM A HIGH PRESSURE SOURCE.


HIGH PRESSURE SOURCE:


THE CHARGING/SI SYSTEM IS THE ONLY ON LINE HIGH PRESSURE SOURCE CAPABLE OF INJECTING FLOW INTO THE RCS DURING NORMAL OPERATING PRESSURES.

OTHER LINES WHERE POTENTIAL MECHANISM EXISTS

- AUXILIARY SPRAY LINE
- CHARGING OR ALTERNATE CHARGING LINES
- HHSI C. L. INJECTION LINES
- HHSI H. L. INJECTION LINES

Charging, Alternate Charging and Auxiliary Spray Lines





79

AUXILIARY SPRAY LINE:

- LEAKAGE WOULD HAVE TO OCCUR ACROSS 8145
- DELTA P ACROSS VALVE IS LOW (APPROXIMATELY 7 PSID)
- IN-LEAKAGE TEMPERATURE IS APPROXIMATELY 500°F

CHARGING AND/OR ALTERNATE CHARGING LINES:

- LEAKAGE WOULD HAVE TO OCCUR ACROSS 8147, 8146,
OR 8392
- DELTA P ACROSS VALVES IS (APPROXIMATELY 7 PSID)
- IN-LEAKAGE TEMPERATURE IS APPROXIMATELY 500°F

HHSI C, L, AND H, L, INJECTION LINES:

- LEAKAGE WOULD HAVE TO OCCUR ACROSS VALVES 8885,
8886, 8884 OR 8911
- DELTA P ACROSS VALVES IS APPROXIMATELY 320 PSID
- IN-LEAKAGE TEMPERATURE IS APPROXIMATELY 100°F

QUALITATIVE EVALUATION OF VALVE LEAKAGE

THREE PRIMARY FACTORS EFFECTING PROBABILITY OF VALVE
TO MAINTAIN A SECURE PRESSURE BOUNDARY

- VALVE TYPE
- VALVE OPERATOR
- DELTA P

VALVE TYPE

- GATE VALVE IS HIGHLY RELIABLE
- GLOBE VALVE IS SLIGHTLY LESS RELIABLE THAN
GATE

VALVE OPERATOR

- MOV PROVIDES THE TIGHTEST AND MOST REPEATABLE
SEAT
- AIR OPERATOR IS SLIGHTLY LESS EFFECTIVE
- MANUAL VALVES ARE LEAST LIKELY TO MAINTAIN
A SECURE PRESSURE BOUNDARY

DELTA P

- LOWER DELTA P REDUCES LIKELIHOOD OF VALVE
LEAKAGE

VALVE CHARACTERISTICS

VALVE	SIZE	TYPE	OPERATOR	MAX ▲P	RELATIVE PROBABILITY OF LEAKAGE
8145	2"	GLOBE	AIR	7 PSID	LOW
8147	3"	GLOBE	AIR	7 PSID	LOW
8146					
8392	3/4"	GLOBE	MANUAL	7 PSID	LOW-MED
8885	3"	GATE	MOV	320 PSID	LOW
8884					
8886					
8911	1"	GLOBE	MANUAL	320 PSID	MED

EVALUATION OF INDIVIDUAL LINES


AUXILIARY SPRAY LINE

- LOW PROBABILITY OF IN-LEAKAGE
 - LOW DELTA P
 - RELIABLE PRESSURE BOUNDARY
- IN-LEAKAGE INITIATES AT A RELATIVELY HIGH TEMPERATURE
- PRESENCE OF COLD TRAP DOWNSTREAM OF LAST CHECK VALVE REDUCES TEMPERATURE GRADIENT ACROSS THE VALVE

CONCLUSION:

THE AUXILIARY SPRAY LINE DOWNSTREAM OF LAST C.V IS NOT SUBJECT TO THERMAL CYCLING

Auxiliary Spray Injection
Line to Normal Spray Line



CHARGING LINES (NORMAL AND AUXILIARY)

- LOW PROBABILITY OF IN-LEAKAGE
 - LOW DELTA P
 - RELIABLE PRESSURE BOUNDARY
- IN LEAKAGE INITIATES AT A RELATIVELY HIGH TEMPERATURE
- CHARGING LINES ARE INSULATED, THEREFORE COOLDOWN OF IN-LEAKAGE PRIOR TO INJECTION INTO RCS IS MINIMIZED

CONCLUSION:

EVALUATION SUGGESTS THAT THERMAL CYCLING IS HIGHLY UNLIKELY

HHSI H. L. AND C. L. INJECTION LINES

- LOW PROBABILITY OF IN-LEAKAGE
 - H. L. INJECTION LINE PRESSURE BOUNDARY IS PROVIDED BY MOV GATE VALVES
 - WITH 8801A/B OPEN, THE C. L. INJECTION LINE PRESSURE BOUNDARY IS PROVIDED BY MOV GATE VALVE

CONCLUSION:

ALTHOUGH THE POTENTIAL MECHANISM EXISTS ON THE H. L. INJECTION LINES THE PROBABILITY OF THERMAL CYCLING IS MINIMIZED GIVEN A SECURE PRESSURE BOUNDARY.

WITH LEAKAGE THROUGH THE BIT BYPASS LINE DIVERTED, THE C. L. INJECTION LINE HAS AN EQUALLY SECURE PRESSURE BOUNDARY. PROBABILITY OF THERMAL CYCLING IS MINIMIZED.

V.2 THERMAL SLEEVE CONSIDERATIONS



- o SUMMARY OF CURRENT PLANT STATUS
- o THERMAL SLEEVES INCORPORATED IN ORIGINAL DESIGN TO PROTECT PRESSURE BOUNDARY FROM THERMAL SHOCK
- o ANALYTICAL METHODS AVAILABLE AT TIME OF ORIGINAL DESIGNS NOT ABLE TO EVALUATE STRUCTURAL INTEGRITY OF COMPONENT
- o FINITE ELEMENT TECHNIQUES AND IMPROVEMENTS IN ASME CODE ANALYSIS PERMITTED QUALIFICATION OF NOZZLE WITH AND WITHOUT SLEEVE
- o FARLEY SIS NOZZLES QUALIFIED WITH AND WITHOUT SLEEVES
- o RECOMMENDATION MADE TO ELIMINATE SLEEVE FROM DESIGN
- o ANALYSIS OF RECORD CONSIDERED DESIGN TRANSIENTS
- o THERMAL MIXING CONSIDERED BUT INSUFFICIENT ΔT IN NOZZLE REGION TO CAUSE FATIGUE
- o SIS LOOP B THERMAL CYCLING DID NOT HAVE IMPACT ON NOZZLE INTEGRITY
- o PRELIMINARY THERMAL HYDRAULIC EVALUATION DEMONSTRATE FLOW MIXING IN VERTICAL RISER BEFORE NOZZLE REGION
- o THIS IS SUPPORTED BY LACK OF INDICATION IN DOWNSTREAM WELDS

V .2


- o UT ON NOZZLE SAFE-END WELD FOUND NO RECORDABLE INDICATIONS
- o UT/RT/AND PT ON DOWNSTREAM (INSIDE AND OUTSIDE SURFACES) ELBOW WELD FOUND NO INDICATION OF CRACK
- o PREVIOUS STUDY'S CONCLUDED THERMAL SLEEVE FAILURE RESULTED FROM FLOW INDUCED VIBRATION
- o VIBRATION LOADS ON CRACKED WELD RESULTING FROM THE SLEEVE PROTRUDING INTO THE RCS FLOW HAVE BEEN EVALUATED AND ARE NOT CONSIDERED PROBABLE SOURCES OF FATIGUE
- o CONCLUSIONS
 - o NOZZLE INTEGRITY NOT AFFECTED BY SIS LOOP B THERMAL MECHANISM, WITH OR WITHOUT SLEEVES
 - o THERMAL SLEEVE INTEGRITY PROBABLY NOT RELATED TO SIS LOOP B THERMAL MECHANISM

V .3 CONTINUED ACCEPTABILITY OF UNITS 1 AND 2

- o SYSTEMS DESIGN EVALUATION INDICATES SIS COLD LEG MOST LIKELY CANDIDATE
- o NDE ON PIPING COVERED ALL MOST SUSCEPTIBLE REGIONS WITH NO RECORDABLE INDICATIONS
- o UNIT 2 CYCLING MECHANISM ELIMINATED
- o UNIT 1 SCHEDULED FOR OUTAGE IN MARCH:
NDE FOUND NO RECORDABLE INDICATIONS
INSUFFICIENT TIME FOR THERMAL CYCLING TO PROPAGATE CRACK THROUGH-WALL
- o PRELIMINARY LEAK-BEFORE-BREAK EVALUATIONS INDICATE NO DOUBLE END BREAK PRIOR TO LEAK DETECTION




IDENTIFICATION OF INSTRUMENTATION



FARLEY SIS CL TEMPERATURE PROFILE


PRIOR TO BI FLOW DIVERSION

B LOOP DOWNSTREAM




66

FARLEY SIS CL TEMPERATURE PROFILE
PRIOR TO BI FLOW DIVERSION
LOOP B





FARLEY SIS CL TEMPERATURE PROFILE
PRIOR TO BI FLOW DIVERSION
LOOP C



66

FARLEY SIS CL TEMPERATURE PROFILE


PRIOR TO BI FLOW DIVERSION



80


FARLEY SIS CL TEMPERATURE PROFILE

DEC. 28 LP B UPSTREAM PRIOR TO BI FLOW DIVERSION



FARLEY SIS CL TEMPERATURE PROFILE



DEC. 28 LP C PRIOR TO BI FLOW DIVERSION



82

FARLEY SIS CL TEMPERATURE PROFILE


DURING BI FLOW DIVERSION



(83)


FARLEY SIS CL TEMPERATURE PROFILE

INTERIM CYCLING AFTER FLOW DIVERSION




FARLEY SIS CL TEMPERATURE PROFILE

INTERIM CYCLING AFTER FLOW DIVERSION




OS

FARLEY SIS CL TEMPERATURE PROFILE
AFTER BI FLOW DIVERSION LONG TERM
LOOP B



98

FARLEY SIS CL TEMPERATURE PROFILE
AFTER BI FLOW DIVERSION LONG TERM
LOOP C




47 0000


NOE 11:15 (11:15) 11:15

28

PLANE OF SYMMETRY




FINITE ELEMENT MODEL USED IN HEAT TRANSFER ANALYSIS






FINITE ELEMENT MODEL USED IN THERMAL STRESS ANALYSIS


THROUGH WALL STRESS DISTRIBUTION



PARABOLIC DISTRIBUTION OF FATIGUE STRIATION



THROUGH-WALL STRESS DISTRIBUTION DERIVED FROM
PARABOLIC DISTRIBUTION OF STRIATION



VI


EVALUATION OF THE EFFECT OF
REDUCED SAFETY INJECTION FLOW
CORRESPONDING TO SPILLING TO
CONTAINMENT BACKPRESSURE ON THE
JOSEPH M. FARLEY SMALL BREAK LOCA
ANALYSIS

(94)

BACKGROUND

- ° Crack in SI line led to questions concerning Farley SBLOCA analysis of record (WFLASH)
- ° Review noted that the Farley WFLASH analysis inappropriately spilled the 6-inch break to RCS backpressure, not containment pressure
- ° Evaluation conducted to determine effect of the inappropriate spillage assumption
- ° This evaluation revealed an additional finding of an incorrectly reported PCT in the Farley FSAR

JOSEPH M. FARLEY ECCS HIGH HEAD INJECTION CURVES
(Minimum Safeguards, 1 Pump Operating, 1 Line Spilling)



EVALUATION RESULTS

- ° Increase of PCT by 45.7°F due effects of earlier core uncover and delayed recovery time (3.84 seconds)
- ° Increase of PCT by 9°F due to more precise reading of computer analysis output instead of summary sheets

SUMMARY PCT TABLE

	<u>UNIT 2</u>	<u>UNIT 1</u>
FSAR	1703°F	1820°F
reporting correction	+9°F	+9°F
spillage correction	+46°F	+46°F
FSAR (proposed)	1758°F	1875°F

- ° Conclusion: considerable margin still exists to 2200°F 10CFR50.46 limit and to the LBLOCA analysis result of 2013°F

APCo ACTIONS

- ° Letter to NRC detailing evaluation and results dated January 14, 1988
- ° Safety Evaluation for FSAR change approved by PORC January 14, 1988
- ° Change to be incorporated into FSAR at next appropriate revision