

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M I D C C 2 | 2 | 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 | 3 | 4 1 1 1 1 1 | 4 | \_\_\_\_\_ | 5  
 7 8 9 | LICENSEE CODE | 14 15 | LICENSE NUMBER | 25 26 | LICENSE TYPE | 30 57 | CAT 58

CON'T

0 1 | REPORT SOURCE | L | 6 | 0 5 0 0 0 3 | 1 | 6 | 7 | 0 8 0 9 7 8 | 8 | 0 9 0 8 7 8 | 9  
 7 8 | 60 61 | DOCKET NUMBER | 68 69 | EVENT DATE | 74 75 | REPORT DATE | 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | DURING NORMAL OPERATION ON AUGUST 9 AND 14 , WITH REACTOR POWER AT 97% IT WAS \_\_\_\_\_  
 0 3 | DISCOVERED THAT THE APDMS COMPUTER FAILED TO PRINTOUT ALL THE F<sub>j</sub> (Z) SCANS AS \_\_\_\_\_  
 0 4 | REQUIRED BY T.S.4.2.6.1. ON THE AUGUST 9 EVENT POWER WAS REDUCED TO 90% WHILE ON THE \_\_\_\_\_  
 0 5 | AUGUST 14 EVENT THE APDMS COMPUTER WAS RETURNED TO OPERATION IMMEDIATELY. \_\_\_\_\_  
 0 6 | PREVIOUS OCCURRENCES OF A SIMILAR NATURE INCLUDE: 050-315/78-03,06, 76-34 316/78-48, \_\_\_\_\_  
 0 7 | \_\_\_\_\_  
 0 8 | \_\_\_\_\_  
 7 8 9

0 9 | SYSTEM CODE | I E | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | G | 13 | COMPONENT CODE | I N S T R U | 14 | COMP. SUBCODE | X | 15 | VALVE SUBCODE | Z | 16  
 7 8 | 9 10 | 11 12 | 13 18 | 19 20  
 17 | LER/RO REPORT NUMBER | 7 8 | 21 22 | EVENT YEAR | 7 8 | 23 | SEQUENTIAL REPORT NO. | 0 6 0 | 24 26 | OCCURRENCE CODE | 0 3 | 28 29 | REPORT TYPE | L | 30 31 | REVISION NO. | 0 | 32  
 33 | ACTION TAKEN | A | 18 | 34 | FUTURE ACTION | F | 19 | 35 | EFFECT ON PLANT | B | 20 | 36 | SHUTDOWN METHOD | Z | 21 | 37 | HOURS | 0 0 0 3 | 40 | 22 | ATTACHMENT SUBMITTED | Y | 23 | 41 | 23 | NPRD-4 FORM SUB. | Y | 24 | 42 | 24 | PRIME COMP. SUPPLIER | N | 25 | 43 | 25 | COMPONENT MANUFACTURER | W 1 2 0 | 47  
 33 34 | 35 36 | 37 40 | 41 42 | 43 44 | 45 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | INVESTIGATION REVEALED THE CAUSE TO BE THE APDMS COMPUTER. THE DETECTORS WERE \_\_\_\_\_  
 1 1 | PERFORMING THE SCANS PROPERLY. HOWEVER, THE DATA WAS NOT ACCEPTED BY THE COMPUTER. \_\_\_\_\_  
 1 2 | THIS RESULTED IN THE COMPUTER MISSING SOME F<sub>j</sub> (Z) CALCULATIONS. A FAULTY CARD WAS \_\_\_\_\_  
 1 3 | IDENTIFIED AND REPLACED. NO FURTHER MALFUNCTIONS HAVE BEEN EXPERIENCED. A DESIGN \_\_\_\_\_  
 1 4 | CHANGE HAS BEEN INITIATED TO INSTALL A MODIFICATION (RFC-12-1617) SEE SUPPLEMENT \_\_\_\_\_  
 7 8 9

1 5 | FACILITY STATUS | E | 28 | 8 9 | % POWER | 0 9 7 | 29 | 10 12 | OTHER STATUS | NA | 30 | 13 44 | METHOD OF DISCOVERY | B | 31 | 45 46 | DISCOVERY DESCRIPTION | ROUTINE OPERATOR CHECK | 32 | 80

1 6 | ACTIVITY CONTENT | Z | 33 | 7 8 9 | RELEASED OF RELEASE | Z | 34 | 10 11 | AMOUNT OF ACTIVITY | NA | 35 | 44 45 | LOCATION OF RELEASE | NA | 36 | 80

1 7 | PERSONNEL EXPOSURES | 0 0 0 | 37 | 7 8 9 | NUMBER | Z | 38 | 10 11 | TYPE | DESCRIPTION | NA | 39 | 12 13 | 80

1 8 | PERSONNEL INJURIES | 0 0 0 | 40 | 7 8 9 | NUMBER | DESCRIPTION | NA | 41 | 10 11 | 80

1 9 | LOSS OF OR DAMAGE TO FACILITY | Z | 42 | 7 8 9 | TYPE | DESCRIPTION | NA | 43 | 10 11 | 80

2 0 | PUBLICITY ISSUED | N | 44 | 7 8 9 | DESCRIPTION | NA | 45 | 10 11 | 80

NRC USE ONLY

7809190243

NAME OF PREPARER J. L. Rischling

PHONE 616-465-5901

SUPPLEMENT TO LER #78-060/03L-0

CAUSE DESCRIPTION

WHICH WILL PROVIDE AN AUDIBLE ALARM ON THIS TYPE FAILURE.