	and the local diversion of the local diversio							LEI	R 88-05				
RC Form 300 -831		CLEAR RECULAT											
ACILITY NAME (1)							DOCKET NUMBER	(2)					
VERMON	T YANKEE	NUCLEAR	POWER STA	NTION			0   5   0   0	10/2/7/1	1 0#01				
POTENTIAL LO	OSS OF SGE	T TRAIN	DUE TO EX	TENSI	ON O	F LOOP SE	AL						
EVENT DATE (B)			REPORT DAT	1 (7)		OTHER	ACILITIES INVO	LVED (B)					
INTH DAY YEAR YEAR	NULIBER	NUMBER	MONTH DAY	YEAR		FACILITY NAM		DOCKET NUMBER					
						N/A		C 15 0 10	101 1 1				
4178888	005	01	0 5 2 7	8 8		N/A		0 15 10 10	10111				
	HORT IS BUSINETTI	D PURBUANT TI	O THE REQUIREME	NTS OF 10	CFR \$ 10	Check one or many ( 80.734a)(2)(iv)	of the following) (1	1) 72.7**)	and a second				
POWYE # 28.402(%) 29.466(a)   LEVEL 28.472(a)(1)(0) 90.29(a)(1) X   (10) 1 (0) 29.45%(a)(1)(8) 90.29(a)(2)   29.408(a)(1)(1)(1) 90.73(a)(2)(1) X   29.408(a)(1)(1)(1) 90.73(a)(2)(1) X   29.408(a)(1)(1)(1) 90.73(a)(2)(1) X   29.408(a)(1)(1)(1) 90.73(a)(2)(1) X								eñy in Abeboer Taxt, NRC Form					
Mê			CENSEE CONTACT	POR THIS	LER (12)	A		L					
	AREA CODE	TELEPHONE NUM	BEA										
JAMES P. PEI	and some other distances in the second s						81012	215171-	5171-1717111				
			LACH COMPONENT	PAILURE	DESCRIBE	D IN THE REPOR	7 (1.3)						
AUSE SYSTEM COMPONENT	TURER	TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	TO NERDS	•				
	111				1		111						
N/A	1 1 1					N/A							
TES (// you, somethin EXMECTED		NTAL REPORT					EXPECTO SUBMISSIO DATE IN	DN NC	DAY YEAN				
During 100% existing Tygon t height of the dr (EIIS=BH). Foll column height co of the SBAT trai charcoal beds. original height.	power op ubing had ain loop owup by t uld preve	eration been re seals fo he opera nt the S	on G4-17- placed wi pr both St tor revea BGT moist	andby led t ure s	Gas Gas hat e epara	that had Treatment excessive tor from	increase (SBGT) drain lo draining	d the ver trains op seal w . The fi	ater lling				
It was deter the safety design have been affecter cleanup is a des:	ed during	Post 1 0	CA loop to	111 11	le rsi	AR. Howe	ver, the	"B" trai	lled n would t				
The root cau that led to the e									tified				
The use of T Mechanical Bypas: tubing being used Plant personnel w	in an on	eration	1 configu	une p	erroi	rmed to a	ssure tha	nated per it any oth introlled.	a her				
In an attemp extension of 10 d Inspector.	t to iden	tify the	Dropan -	ant a				tion, an sident	1/1				
PDR S	7260038 ADOCK	880527 050002 PI	271										

.1

1

1431	LIGENSEE EVENT REPORT (LER) TEXT CONTINUATION												R 83-05 Rev									
Vermant Junkse Mucleur Mamer Station		DOCK 17 WUMBER 3																••	-		_	
			, 11	5	0	0	0	12	17	11	8	8	-	0	101	5 -	011	01	2		0	13

# DESCRIPTION OF EVENT

On 04-17-88, during 100% power operations, an operator identified that the existing Tygon tubing had been replaced with tubing that had increased the vertical height of the drain loop seals for both Standby Gas Treatment (SBGT) trains (EIIS=BH).

The original Tygon tubing increased the vertical height of the manufacturers loop seal just enough to allow the operators visible indication of water level in the hard pixed loop seal. The original tubing has been in place since early plant operation. The tubing ended approximately 20" off the floor. It was installed because the original manufacturer's design did not provide the operators with loop seal level indication. The Tygon tubing was installed before the Mechanical Bypass Program existed. During the 1987 outage the tubing was replaced because it had become dirty and it was difficult to see loop seal level. The tubing was replaced without a Maintenance Request by two operators. The operators understood the significance of the loop seal and function of the drain. The tramember leaving the end of each tubing at approximately the same height as the original tubing. On 4/17/88, the end of the drain tubing was found to be 30" off the floor for the "A" train and 36" for the "B" train.

After identifying the problem, Operations had the drain tubing corrected.

The evaluation of this event identified that the increased water column height would not have prevented either train from fulfilling its safety design basis function. However, the "B" train would have been affected during Post-LOCA long term containment cleanup. Containment cleanup is not a safety design basis function for SBGT.

1

In an attempt to identify the proper root cause and corrective action an extension of 10 days was requested of and granted by the NRC Senior Resident Inspector.

### CAUSE OF EVENT

The exact root cause of this event could not be determined. However, it is felt that the following contributed to this event:

Human Factors - As identified during a review of this event, Tygon tubing is most commonly used as a temporary drain, to contain leakage, to drain equipment during maintenance and to assist in housekeeping. It is not normally considered to be plant equipment or have the capability of impacting plant equipment. When it was replaced, this human factor bias caused it to be treated as a "housekeeping item" instead of "plant equipment".

# ANALYSIS OF EVENT

The VY FSAR states that the SBGT system shall:

1. Maintain a negative pressure in the Reactor Building so that any air leakage will be into the Reactor Building, and

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION															-	144 ALGULATOR - COMMISSION IOVED DWE NO 2150-0104 ALS 8-21 85										
ILITY MADE (1)	00	NCR I	17 1	-	<b>B4</b> A	121	-			-			-	-		-		-				,				
Vermant Jankes Muclear Mampr Station														••						1	-	-				
	1.1	18	Ē	0	0	10	12	17	1	8	8		01	01	5	_	01	1	0 1	3	OF	0	3			

LER 88-05 Rev. 1

ANALYSIS OF EVENT (Cont.)

2. Provide sufficient air filtration such that in the event of a design basis accident, release of gaseous contaminants will result in doses which are within the limits specified in 10 CFR 100.

The additional tubing height of the drain seal would not prevent the SBGT system from fulfulling its design basis as stated above. During a design basis accident, the secondary containment environment is analyzed as having higher than normal humidity which the SBGT system is designed for. The SBGT system uses a heating element to lower the relative humidity which minimizes the amount of water absorbed by the charcoal filters. Additionally, the SBGT units contain a demister which is designed to separate water spray/water particles and reduce water impingement of the charcoal beds. The demister drains to an internal drip pan which drains through a loop seal. Since the only time the demister could encounter suspended water particles is during a Post-LOCA primary containment environment (which is not a safety design basis), both units would have operated successfully if called upon to provide their intended function. Only the "B" train could have filled with water if deliberately lined up to the primary containment considering long term Post-LOCA environment. The demister drip pan could overfill from the combined effect of the additional water height and the vacuum pressure inside the "B" SBGT. The additional water then decreases the charcoal trays' effectiveness to remove iodine. Additionally, all other operating and surveillance modes were investigated to ensure that no water build up could occur.

### CORRECTIVE ACTION

- In order to evaluate and document the SBGT drains, Operations shall initiate a Mechanical Bypass Request and tag the Tygon tubing configuration as plant equipment.
- A review will be performed to identify if there are any other instances of Tygon tubing being used for operating purposes. If any other instances are identified, they will be reviewed and documented per the Mechanical Bypass Request Procedure and tagged.
- Plant personnel will be given specific training on this event as well as the result of item 2 (above).

#### ADDITIONAL INFORMATION

No similar occurrences have been reported to the Commission in the lact five years.



# VERMONT YANKEE NUCLEAR POWER CORPORATION

P. O. BOX 157 GOVERNOR HUNT ROAD VERNON, VERMONT 05354

> July 18, 1988 VYV 88-141

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

REFERENCE: Operating License DPR-28 Docket No. 30-271 Reportable Occurrence No. LER 88-05 Rev.1

Dear Sirs:

As defined by 10CFR50.73, we are reporting the attached Reportable Occurrence as LER 88-05 Rev.1 .

Very truly yours,

VERMONT YANKEE NUCLEAR POWER CORPORATION

Mancy

Plant Manager

cc: Regional Administrator USNRC Office of Inspection and Enforcement Region I 475 Allendale Road King of Prussia, PA 19406