(RC Form 388 9-8-7)			LICI	ENSEE EN	VENT RE	PORT	LER)	U.S. NUCI	LEAR REGULATO	AY COMMISSIO 3150-0104		
ACILITY NAME (1)							00	CKET NUMBER (2)	PAGE		
Davis-Besse	Unit 1	1					0	15 0 0	0 3 4 16	1 OF O		
Nuclear Saf	ety Rel	lated Equi	pment Po	otential	ly Impa	cted b	y Non-Sei	smic Equi	pment			
	-	LER NUMBER I	. 1	REPORT	DATE (7)		ACILITIES INVOLVED (8)					
EVENT DATE (8) SEQUENTIAL REVISION M					Y YEAR		DOCKET NUMBERIS)					
									0 15 0 10	1011		
			- 1						0 1510 10	101 1		
0 3 1 2 8	8 8 8		D PURSUANT T	OTHE REQUIR	EMENTS OF 1	CFR \$: (C	theck one or more of	the followings (11)		1 1 1		
OPERATING MODE (8)	5 20	402(b)		20.406(c)		Ĺ	50.73(a)(2)(iv)		73.71(b)			
POWER	20	406(a)(1)(i)		50.36(e)(1)			60.73(a)(2)(v)		73.71(4)			
(10) 0101	0 20	405(a)(1)(ii)		50.38(c)(2)		-	50.73(a)(2)(vii)	-	below and i	n Text, NRC Fo		
	20	406(a7(1)(iii)	-	50.73(a)(2)(i)	11.11	-	50.73(a)(2)(viii)(8)					
	20	406 (a) (1) (v)	X	50.73(a)(2)(H	0		50.73(a)(2)(x)					
				ICENSEE CONT	ACT FOR THIS	LER (12)						
NAME							1.1.1.1.1	AREA CODE I	TELEPHONE NUN	198H		
M. J. Roder	Assis	stant Nucl	ear Eng	ineer. 7	Cechnica	1 Plan	ning	41110	21/101-151010			
		COMPLETE	ONE LINE FOR	EACH COMPO	NENT FAILUR	DESCRIBE	ID IN THIS REPORT	141121	£ 19121-	12 10 10		
		MANUFAC	REPORTABLE		- Come	Everen	COMPONENT	MANUFAC	REPORTABLE			
CAUSE SYSTEM C	MPONENT	TURER	TO NPROS		CAUSI	5.5.5.6	COMPONENT!	TURER	TO NPHOS			
						1.1		1.1.1				
						+						
	1.1.1	111				1	111					
		BUPPLEMI	ENTAL REPORT	EXPECTED IN	4			EXPECTE	ID MONT	H DAY Y		
			-				DATE 1	0N				
YES (If you, compl	IN EXPECTED	SUBMISSION DATI		X I	16)							
On March 12 be located Subsequent walkdown of within its During the C5751 to fa NSR equipmerestrained electrical corrective also be tra	, 1988 within invest these fallin prepar ull and ent nea during panels action ained.	at 0930 h the falli igation re panels id g arc dist ation of s impact NS r panel CS the fifth is to be s. Outsid	nours, N ng arc vealed lentifie ance. subseque R equip 751 will refuel conduct le organ	uclear S distance three mo d one of Original nt modif ment was l be rel ing outs ed to io izations	Safety R of non- ther pan linstal fication s overlo located age. A dentify s involv	elated -seism seismi el (C) lation s the oked. and pa sample any s red in	d (NSR) eq nic electr ic panels 5751) with n of C4601 potential anel C4601 e of non-s imilar con the hazar	will be will be and c575 for pane	was disco al C4601. to C4601. Ipment lo bl was co als C4601 seismica ree stand and any a sis revie	A cated rrect. and lly ing iddition. w will		
This findin design bas	ng is b	eing repor	rted und	er 10CF	R50.73(a)(2)(ii)(B) as	a condit:	ion outsi	de the		
		*							JEZ	S.		
8804 PDR S	180450 ADOCK	880408 0500034 END	6									

LICENSEE	EVENT REPORT (LER) TEXT CON	TINUATION	US NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85					
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NU	MBER (6)	PAGE (3)				
Davis-Besse Unit 1		YEAR SEQU	ALL REVISION					

6 5 0 0 0 3 4 E 8 8 - 0 0 8 - 0 0 0 2 0F 0 3

TEXT (If more space is required, use additional NRC Form 3664's) (17)

Description of Occurrence:

On March 12, 1988, at 0930 hours the reactor was in Mode 5 at 0 percent Reactor Thermal Power. During a walkdown for Facility Change Request (FCR) 84-0083, Design Engineering Personnel identified a non-seismically mounted electrical panel (C4601, computer analog multiplexer) that, during a seismic event, could fall and impact nearby Nuclear Safety Related (NSR) equipment.

Subsequent investigation revealed three more non-seismically mounted electrical panels (C5751, C5752, and C5753) that were similar to C4601. A walkdown of the three panels was conducted. Two of the panels (C5752 and C5753) were determined to not affect any NSR equipment. The third panel (C5751, computer digital input/output multiplexer) was identified as having the potential to fall during a seismic event and impact NSR equipment.

Installed equipment and facility modifications currently being implemented were reviewed to determine the NSR equipment potentially affected. This review identified the following equipment:

Installed equipment

Cable No. Function

1PD106A Power for High Pressure Injection Pump 1-1 DC Lube Oil Pump Power for High Pressure Injection Pump 1-2 AC Lube Oil Pump 2PBF1231A Power for Containment Post Accident Normal Range Radiation Monitor 2PBF1609A 2CSF1723D Station Vent Effluent High Range Radiation Monitor 2PY211AA Power to Hot Leg Level Monitor 1CFV100EF Main Steam Isolation Valve Line 2 Reset 1CFV100DG Main Steam Isolation Valve Line 2 Reset 2CFV101EF Main Steam Isolation Valve Line 1 Reset 2CFV101DG Main Steam Isolation Valve Line 1 Reset

Non-Installed equipment

Cable No. Function

2PBF1208F	Power for Makeup Pump Discharge Cross Connection Line Isolation Valve
2PBF1616F	Power for Bypass Valve in the MU 32 Miniflow Line
2PBF1617D	Power for Reator Coolant Makeup Pump Suction Valve
2PBF1108E	Power for Containment Isolation Valve V6422
2CY208AA	Neutron Flux Audible Indication Circuitry for the Control Room and Containment
2CY208AB	Neutron Flux Audible Indication Circuitry for the Control Room and Containment
2LNF5875C	Neutron Flux Audible Indication Circuitry for the Control Room and Containment
2LNF5875D	Neutron Flux Audible Indication Circuitry for the Control Room and Containment
2LNF5875E	Neutron Flux Audible Indication Circuitry for the Control Room and Containment
2LNF5875F	Neutron Flux Audible Indication Circuitry for the Control Room and Containment
2LNF5875G	Neutron Flux Audible Indication Circuitry for the Control Room and Containment

NRC Form 366A (9-83)	LICENSEE EVENT REPOR	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION							
			£ x 1	PIRES 8/31 85					
FACILITY NAME (1)		DOCKET NUMBER (2)	LER NUMBER (6)	PAGE (3)					

Davis-Besse Unit 1

	0	15	10	10	0	13	46	8 8	-	0 0	8	- 0	0	0 3	OF	0	3
(T Ut more space is required, use additional NRC Form 3864 (s) (17)																	
USAR Section 3.2.1.1 and Regulatory could fail and adversely impact NSR seismic event does not cause such a	Guid equi fail	le .pm .ur	1.: en e.	29, t t	Fe c t	be	uary desig	1976, ned a	re	cons	te e	equip	so	t wh tha	ich t a		

This event is being reported under 10CFR50.73(a)(2)(ii)(B) as a condition outside the design basis of the plant.

Designation of Apparent Cause of Occurrence:

Original non-seismic installation of panels C4601 and C5751 was correct. Subsequent facility modifications installed NSR equipment in the vicinity of these panels. The potential for panels C4601 and C5751 to impact the NSR equipment was overlooked during hazards analysis review required by modification procedures.

Analysis of Occurrence:

Panels C4601 and C5751 could fall during a seismic event potentially impacting nearby Nuclear Safety Related equipment and rendering it inoperable. Had this occurred, the capability to reset both Main Steam Isolation Valves (MSIV) could have been lost. The MSIVs, however, would either move to or remain in their fail-safe closed position. For other circuits not associated with the MSIV resets, safe shutdown of the reactor would have been assurred due to redundant equipment located in other areas remaining unaffected.

Corrective Action:

Panel C5751 is located in Room 502, control cabinet room. Nuclear Safety Related equipment within the falling arc distance of the panel will be relocated to cabinets C5762N and C5792N during the fifth refueling outage under MOD 87-1107.

Panel C4601 is located in Room 427, electrical penetration room. Panel C4601 will be seismically restrained during the fifth refueling outage under Facility Change Request 84-0083 supplement 03.

A sample of non-seismic free standing electrical panels will be performed by June 30, 1988 to determine if similar conditions exist and if any additional corrective actions are required. Hazards analysis review training has been conducted for Toledo Edison Personnel and a list of Qualified Design Reviewers is being maintained. Outside organizations involved in the hazards analysis review will be trained and added to the Qualified Design Reviewers list by May 31, 1988. Controls are in place so that only those identified on the Qualified Design Reviewers list will perform these reviews.

Failure Data:

LER 86-015 previously identified non-seismic domestic water piping installed over Nuclear Safety Related equipment.

REPORT NO: NP-33-88-08

PCAQ NO(s): 88-0177

SEQUENTIAL NUMBER

VEAN

April 8, 1988



Docket No. 50-346 License No. NPF-3

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Gentlemen:

LER No. 88-008 Davis-Besse Nuclear Power Station Unit No. 1 Date of Occurrence March 12, 1988

Enclosed is Licensee Event Report 88-008, which is being submitted in accordance with 10CFR50.73 to provide 30 day written notification of the subject occurrence.

Yours truly,

Reus Louis F. Storz Plant Manager Davis-Besse Nuclear Power Station

LFS/ed

cc: Mr. A. Bert Davis Regional Administrator USNRC Region III

> Mr. Paul Byron DB-1 NRC Resident Inspector

IE22

TOLEDO, OHIO 43652