


Plans for Restoration

The sensor assembly, including the retaining device, was replaced and the system returned to OPERABLE status on April 5, 1988. Repair of this device was delayed because adverse weather conditions (i.e. high winds) prevented timely troubleshooting of the problem. The manufacturer indicated that they have had no problems with the retaining device. Also, this sensor assembly has been in service at Clinton for over seven years without failure of the the retaining device. In that this is the first such failure CPS has experienced with this component, no further corrective action is warranted.

If you have any questions regarding this event, please contact me.

Sincerely yours,



F. A. Spangenberg, III
Manager - Licensing and Safety

KBR/krm

cc: NRC Clinton Licensing Project Manager
NRC Resident Office
Illinois Department of Nuclear Safety