

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Limerick Generating Station - Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 3 5 2										PAGE(S) 1 OF 5													
TITLE (4) Reactor Water Cleanup Isolation Due to High Differential Flow Caused by a Pressure Transient While Removing a Filter Demineralizer From Service																																	
EVENT DATE (6)						LER NUMBER (6)						REPORT DATE (7)						OTHER FACILITIES INVOLVED (8)															
MONTH		DAY		YEAR		YEAR		SEQUENTIAL NUMBER		REVISION NUMBER		MONTH		DAY		YEAR		FACILITY NAMES															
0 3		2 6		8 8		8 8		0 1 1		0 0		0 4		2 5		8 8		DOCKET NUMBER (3) 0 5 0 0 0															
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																															
1		20.402(a)										20.402(a)										20.736(a)(1)(iv)										72.71(b)	
POWER LEVEL (10)		20.402(a)(1)(i)										20.304(a)(1)										20.736(a)(1)(iv)										72.71(a)	
19 5		20.402(a)(1)(ii)										20.304(a)(2)										20.736(a)(2)(iv)										OTHER (Specify in Abstract below and in Text, NRC Form 208A)	
		20.402(a)(1)(iii)										20.736(a)(2)(i)										20.736(a)(2)(iv)(A)											
		20.402(a)(1)(iv)										20.736(a)(2)(ii)										20.736(a)(2)(iv)(B)											
		20.402(a)(1)(v)										20.736(a)(2)(iii)										20.736(a)(2)(iv)(C)											
		20.402(a)(1)(vi)										20.736(a)(2)(iv)										20.736(a)(2)(iv)											
LICENSEE CONTACT FOR THIS LER (12)																																	
NAME Charles A. Mengers, Senior Engineer, Licensing Section																		TELEPHONE NUMBER															
																		AREA CODE															
																		2 1 5 8 4 1 - 5 1 8 4															
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																	
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC																							
SUPPLEMENTAL REPORT EXPECTED (14)																		EXPECTED SUBMISSION DATE (15)		MONTH		DAY		YEAR									
YES (If you complete EXPECTED SUBMISSION DATE)																		X NO															

ABSTRACT (Limit to 1600 spaces, i.e., approximately fifteen single-spaced typewritten lines) (16)

Abstract: 88-011

On March 26, 1988 at 0615 hours, a Reactor Water Cleanup (RWC) isolation occurred on a Nuclear Steam Supply Shutoff System (NSSSS), an Engineering Safety Feature, Group III Channel A and D "high differential flow" isolation signal. Operations personnel, removing the 'A' RWC filter demineralizer from service in order to restart the 'C' RWC pump, opened the filter demineralizer bypass valve HV-44-1F044 in conjunction with closing the 'A' filter demineralizer flow control valve FV-C-45-1-66A. The filter demineralizer bypass valve HV-44-1F044 could not be adjusted to permit the minimum required system flow. This caused the 'A' RWC pump to trip on low suction flow, resulting in a pressure transient, which caused a high differential flow initiating an NSSSS Group III, A and D Channel "high differential flow" isolation signal. The RWC inboard and outboard isolation valves HV-044-1F001 and HV-044-1F004 closed isolating RWC. The isolation was reset at 0640 hours and RWC was returned to normal operation at 0905 hours. There were no adverse consequences associated with this event and there was no release of radioactive material. The filter demineralizer bypass valve HV-44-1F044 has been scheduled to be replaced, during an outage of sufficient length, with a valve more appropriate for this application after the new valve has been procured.

222  
118805030042 880425  
PDR ADOCK 05000352  
DCD  
S

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-J104

EXPIRES 8/21/86

FACILITY NAME (1)  Dimerick Generating Station Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 3 5 2	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8	0 1 1	0 0	0 2	OF	0 5

TEXT: If more space is required, use additional NRC Form 285A's (17)

Unit Conditions Prior to the Event:

Operating Mode 1 (Power Operation)

Reactor Power 95%

Description of the Event:

On March 26, 1988 at 0615 hours, a Reactor Water Cleanup (RWCU) isolation occurred on a Nuclear Steam Supply Shutoff System (NSSSS) Group III Channel A and D "high differential flow" isolation signal. The isolation occurred when the 'A' RWCU filter demineralizer was being removed from service to restart the 'C' RWCU pump. The filter demineralizer bypass valve HV-44-1F044 was being opened in conjunction with closing the 'A' filter demineralizer flow control valve FV-C-45-1-66A in accordance with procedures. The required bypass flow was not achieved as the filter demineralizer flow control valve was closed and the filter demineralizer bypass valve was opened (see attached sketch). The system flow fell below the minimum required 60 gpm flow rate causing the 'A' RWCU pump to trip on low suction flow. This resulted in a pressure transient causing a high differential flow condition, for greater than the 45 second time delay, initiating the Nuclear Steam Supply Shutoff System (NSSSS) Group III isolation signal. The RWCU inboard and outboard isolation valves HV-044-1F001 and HV-044-1F004 closed, as designed, isolating RWCU.

The high differential flow isolation was not immediately reset because indicated RWCU inlet flow, sensed by flow element FE-44-1N035, continued to fluctuate between 60 to 80 gpm due to flow turbulence which was caused by the flow path that existed from the bottom head drain to RWCU and back to the recirculation suction line via the HV-044-1F015 valve (see attached sketch). Operations personnel closed the inlet valve, HV-044-1F105, leading from the reactor recirculation pump suction. Indicated RWCU inlet flow and bottom head drain flow dropped to zero and the NSSSS Group III isolation was reset at 0640 hours.

The duration of the isolation was 0 hours and 25 minutes.

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMS NO 3180-0104  
EXPIRES 8/7/81

FACILITY NAME (1):  Limerick Generating Station  Unit 1	DOCKET NUMBER (2):  0 5 0 0 0 3 5 2 8 8	LER NUMBER (5):			PAGE (3):	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 8	0 1 1	0 0	0 3	OF 0 5

TEXT IS MORE SPACE IS REQUIRED, USE REVERSE SIDE NRC Form 200A 2/1/73

Consequences of the Event:

The RWCU system isolated as designed on the high differential flow NSSSS Group III, A and D channel isolation signal. There was no release of radioactive material to the environment. RWCU was out of service for 3 hours and 30 minutes and reactor water purity remained within specified limits following the event. If the RWCU system remained out of service for greater than 4 hours reactor water chemistry grab samples would have been taken, in accordance with Technical Specifications, to determine reactor water purity. In the event that one of the NSSSS Group III isolation signals failed to isolate RWCU, the redundant channel isolation signal is designed to isolate the system.

Cause of the Event:

RWCU isolated on a pressure transient. The pressure transient was caused by the inability of the demineralizer bypass valve HV-44-1F044 to be adjusted to properly control system flow. This valve is believed to be oversized for its application. As a result, Operations personnel experienced difficulty controlling RWCU flow while removing the 'A' filter demineralizer from service (see attached sketch). Operations personnel could not maintain the minimum required 60 gpm system flow because system flow is controlled by adjusting the filter demineralizer bypass valve (HV-44-1F044) in a very narrow range, less than 10% valve full open. This globe valve has a standard plug, or quick opening, type disc and the adjusting requirements are beyond the capability of the plug type disc. As a result, the 'A' RWCU pump tripped on low suction flow (pump protection). A pressure transient ensued causing a high differential flow condition of greater than 54.9 gpm. This condition lasted for greater than 45 seconds thereby initiating an NSSSS Group III, A and D Channel "high differential flow" isolation signal.

Corrective Actions:

The isolation was reset at 0640 hours and RWCU was returned to operation at 0905 hours.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1):  Limerick Generating Station Unit 1	DOCKET NUMBER (2):  0 5 0 0 0 3 5 2 8 8	LER NUMBER (3):			PAGE (3)  0 4 OF 0 5
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
		8 8	0 1 1	0 0	

TEXT IF MORE SPACE IS REQUIRED, USE ADDITIONAL NRC Form 2064 2/ (17)

## Actions Taken to Prevent Recurrence:

The inability to properly adjust the valve HV-44-1F044 had been previously identified. A modification has been issued to replace the valve with a valve more appropriate for this application and it will be completed during a future outage of sufficient length after a new valve has been procured.

## EIIS Codes:

NSSSS - JM  
RWCU - CE  
Isolation Valve - ISV  
Filter Demineralizer - FDM  
Pump - P

## Previous Similar Occurrences:

Limerick LERs 84-031, 85-002, 85-003, 85-051, 85-082, and 86-033 reported RWCU isolations on high differential flow conditions.

Tracking Code: (B) Design Deficiency.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8-31-95

FACILITY NAME (1)

DOCKET NUMBER (2)


LER NUMBER (3)

PAGE (3)

Limerick Generating Station Unit 1

0500035288-011-0005 OF 05

TEXT (If more space is required, use additional NRC Form 366A 2/117)





PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

April 25, 1988

Docket No. 50-352

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555


SUBJECT: Licensee Event Report  
Limerick Generating Station - Unit 1

This LER concerns a Nuclear Steam Supply Shutoff System (NSSSS) Group III isolation of the Reactor Water Cleanup System due to a high differential flow caused by a pressure transient while removing a RWCU filter demineralizer from service.

Reference:	Docket No. 50-352
Report Number:	88-011
Revision Number:	00
Event Date:	March 26, 1988
Report Date:	April 25, 1988
Facility:	Limerick Generating Station P.O. Box A, Sanatoga, PA 19464

This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(iv).

Very truly yours,



R. H. Logue  
Assistant to the Manager  
Nuclear Support Division

cc: W. T. Russell, Administrator, Region I, USNRC  
T. J. Kenny, USNRC Senior Resident Inspector

IER2  
1/1