

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
River Bend Station

DOCKET NUMBER (2)
050000458

PAGE 3
1 OF 03

TITLE (4)
Hydrogen Sample Not Taken Contrary to Technical Specification Action

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
12	28	85	85	064	00	02	07	86			050000
											050000

OPERATING MODE (9) 1

POWER LEVEL (10) 008

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.408(a)	<input type="checkbox"/> 90.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.408(a)(1)(i)	<input type="checkbox"/> 90.38(a)(1)	<input type="checkbox"/> 90.73(a)(2)(v)	<input type="checkbox"/> 73.71(a)
<input type="checkbox"/> 20.408(a)(1)(ii)	<input type="checkbox"/> 90.38(a)(2)	<input type="checkbox"/> 90.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.408(a)(1)(iii)	<input checked="" type="checkbox"/> 90.73(a)(2)(i)	<input type="checkbox"/> 90.73(a)(2)(vii)(A)	
<input type="checkbox"/> 20.408(a)(1)(iv)	<input type="checkbox"/> 90.73(a)(2)(ii)	<input type="checkbox"/> 90.73(a)(2)(vii)(B)	
<input type="checkbox"/> 20.408(a)(1)(v)	<input type="checkbox"/> 90.73(a)(2)(iii)	<input type="checkbox"/> 90.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME: C. L. Nash - Chemistry Supervisor

TELEPHONE NUMBER: 504 635-6094

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)

NO

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 12/27/85 with the reactor at 8 percent power, the main condenser off-gas explosive gas monitoring system (hydrogen analyzers) were declared inoperable. Limiting Condition for Operation 85-0468 was initiated for once per four hour grab sampling of the off-gas system for hydrogen concentration. Due to the sample point being inaccessible due to potentially high airborne radioactivity in the Turbine Building on 12/28/85, the grab sample due at 0950 hours was not obtained until 1210 hours. In the future, appropriate respiratory protection equipment will be donned to obtain required samples when there is a potential for airborne radioactivity. Additionally, all personnel involved were informed of the importance for meeting all Technical Specification requirements. There were no safety consequences or implications to the public as a result of this event.

IE 22
11

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) River Bend Station	DOCKET NUMBER (2) 0 5 0 0 0 4 5 8 8 5	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 5	- 0 6 4	- 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 365A 2) (17)

Reported Condition:

On 12/27/85 with the unit at 8 percent power in operational condition 1 (power operation), the main condenser off-gas explosive gas monitoring system (hydrogen analyzers) were declared inoperable. Per Technical Specifications 3.3.7.11, Table 3.3.7.11-1, Action 123, grab sampling of the off-gas system for hydrogen analysis was initiated on a once per four hour frequency. This activity was tracked through Limiting Condition for Operation (LCO) 85-0468.

On 12/28/85, a hydrogen gas grab sample was due at 0950 hours and past due at 1050 hours. During this time and until 1200 hours, the Turbine Building was placed under a precautionary evacuation due to potentially high airborne radioactivity resulting from a minor steam leak on the 67 foot elevation. Since the sample point for the off-gas system is located in the Turbine Building, the grab sample for hydrogen analysis was not obtained until 1210 hours.

Investigation:

Failure to perform the 1 per 4 hour hydrogen sampling frequency constituted a condition prohibited by Technical Specifications. Table 3.3.7.11-1, Action 123, of the Technical Specifications requires the condition be reported in the next Semi-Annual Radioactive Effluent Release Report. This reporting requirement was misinterpreted to mean that a Licensee Event Report was not required. This was not realized until 01/06/86.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) River Bend Station	DOCKET NUMBER (2) 0 5 0 0 0 4 5 8 8 5	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 5	— 0 6 4	— 0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 388A's) (17)

Corrective Action:

In the future when airborne radioactivity is present, the Nuclear Chemistry Technician will don the appropriate respiratory protection equipment, as specified by Radiation Protection personnel, to obtain the required samples. Additionally, the importance of meeting all Technical Specification requirements was re-emphasized to all persons involved.

Safety Assessment:

Since the plant has never detected concentrations of hydrogen in the off-gas system, and since the previous and subsequent grab samples did not indicate a hydrogen gas concentration build-up, this occurrence posed no threat to the public safety and welfare.



GULF STATES UTILITIES COMPANY

RIVER BEND STATION POST OFFICE BOX 220 ST. FRANCISVILLE, LOUISIANA 70775
AREA CODE 504 635-8094 346-8651

February 7, 1986
RBG- 23152
File Nos. G9.5, G9.25.1.3

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Dear Sir:

River Bend Station - Unit 1
Docket No. 50-458

Please find enclosed Licensee Event Report No. 85-064 for River Bend Station - Unit 1. This report is submitted pursuant to 10CFR50.73.

Sincerely,

Eddie R. Hunt
for J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

JEB
JEB/TFP/DRG/BEH/ebm

cc: U. S. Nuclear Regulatory Commission
611 Ryan Plaza, Suite 1000
Arlington, TX 76011

INPO Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

IE22
1/1