NRC For: (9-63)	. 366						LIC	ENSEE E	EVENT	RE	PORT	(LER)	U.S. N	UCLEAR REGULA	TORY COMMIS 0 3150-0104	SION	
FACILITY	-	E (1)											DOCKET NUMBER	(2)	PAGE	(3)	
H. B. Robinson, Unit 2									0 15 10 10 10 12 16 1 1 105 012								
TITLE IS	3													4	1 1-1		
Rea	acto	r	Trip) -	Nuc	lear Ins	trumenta	tion Sy	stem H	ligl	n Neut	ron Flux					
EV	ENT DA	TE	(5)			LER NUMBER	(6)	REPORT	TOATE (7)	I		OTHER	FACILITIES INVO	LVED (B)			
MONTH	DAY		YEAR	¥1	YEAR SEQUENTIAL NUMBER			WER MONTH DAY				FACILITY NA	MES	DOCKET NUMBERIS			
	1			T									1	0 5 0 0	1		
0 1	2	2	8 6	8	6	0 0 4	- 0 0	0 2 1	9 8	6			der er	0 15 10 10 10 1 1 1			
OP	RATIN	10	1	TN	IS REP	OAT IS SUBMITT	ED PURSUANT	TO THE REQUI	REMENTS	OF 10	CFR § 10	theck one or more	of the followings (1	1)			
MODE (8) POWER LEVEL (10) 3 3				20.402(b) 20.406(a)(1)(i) 20.406(a)(1)(iii) 20.406(a)(1)(iii)			20.406(e) 50.36(e)(1) 50.36(e)(2) 50.73(e)(2)(i)			X 80.73(a)(2)(iv) 50.73(a)(2)(v) 50.73(a)(2)(vii) 50.73(a)(2)(viii)(A)			73.71(b) 73.71(c) OTHER (Specify in Abstract below and in Text, NRC Form 366A)				
			F	20.406(a)(1)(v) 20.406(a)(1)(v)			50,73(a)(2)(iii) 50,73(a)(2)(iii)			50.73(a)(2)(x)			Section Association				
_								ICENSEE CON	TACT FOR	THIS	LER (12)						
Roy	, с.	A	bbot	t									AREA CODE	3 8 3	-, 4,5,1	2,4	
		-		-		COMPLETE	ONE LINE FOR	EACH COMPO	NENT FAIL	LURE	DESCRIBE	D IN THIS REPO	RT (13)		4 4 4		
CAUSE	SYST	EM	COMP	ONE	ONENT MANUFAC		REPORTABLE TO NPROS		0	AUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPROS			
	1		1	1	,						1						
	1		1	1	1	111					1	LIL	111				
						SUPPLEM	ENTAL REPORT	EXPECTED (1	4)				EXPECT	ED MONT	DAY Y	EAR	
YES IIF YAS COMPILE EXPECTED SUBMISSION DATE! X NO								SUBMISSI DATE I	0N 51		1						
Abs At	tra 112	<u>ct</u>	hour	s (on J	anuary 2	2, 1986,	with t	he uni	it	operat	ing at 3	3% power,	the Plan	t		

At the time of the trip, an evolution was in the process to reduce the NIS trip setpoints on the four Power Range Channels (N-41 through N-44). The bistable for N-42 had been placed in the "Tripped" position and the setpoint reduced. When returning N-42 to "Normal", the individual inadvertently opened the N-43 cabinet and switched the bistable for N-43 to the "Tripped" position. This satisfied the two-out-of-four channel logic needed to initiate the reactor trip.

The Plant was placed in a safe hot shutdown condition in accordance with the Emergency Operating Procedures. All systems functioned properly.

Labeling was installed inside each NIS cabinet to identify the associated NIS Channel. Additionally, the individual involved was counseled for his actions.

IE 22

8602250370 860219 PDR ADOCK 05000261 S

Neutron Flux Trip signal.

IS-83)	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION									
FACILITY NAME (1)	DOCKET NUMBER (2)	T	LE	ER NUMBER (6)	(6)			PAGE (3)		
	잘 많이 잘 많는 것 같이 봐야? 한 것	YEAR		SEQUENTIAL	REV	SION		11		
H. B. Robinson, Unit 2	0 15 10 10 10 1 2 16 1 1	816	_	0,0,4	_ 0	, 0	0,	2	0,2	

Event Description

On January 22, 1986, the Plant was operating at 33% power. At 1127 hours, the Plant received a reactor trip from a Nuclear Instrumentation System (NIS) Power Range High Neutron Flux Trip signal.

At the time of the trip, an Instrument and Control (I&C) Technician was reducing the NIS trip setpoints on the four Power Range Channels (N-41 through N-44). This reduction in setpoint was required by power distribution control procedures during recovery from a Plant trip that occurred the day before. The resetting of the setpoint for Channel N-41 had been completed, and the channel was returned to service. The setpoint for Channel N-42 had been reduced; however, the channel was still removed from service. This means that the bistable for NIS Channel N-42 was in the "Tripped" position as required by the procedure. When the technician returned to the back of the cabinet to reset the bistable for N-42 to "Normal", he inadvertently entered the cabinet for Channel N-43 and switched the N-43 bistable to the "Tripped" position. This placed another Power Range Channel in the tripped position satisfying the two-out-of-four channel logic needed to initiate the reactor trip. The Plant was placed in a safe hot shutdown condition in accordance with the Emergency Operating Procedures.

The event was the result of personnel error. The N-43 cabinet was labeled, and the bistable trip switch in the cabinet is labeled as to "NORMAL" and "TRIPPED" positions. However, some improvements regarding the location of and specific information on the labeling were identified.

To ensure each NIS Cabinet is clearly marked, labeling has been added inside each cabinet beside the bistable switch which identifies the associated NIS Channel. Additional labeling for the cabinet doors identifying the NIS Channel will be installed near the lock on each door.

The technician involved in this event was counseled and formally reprimanded by his management. No further corrective actions are considered necessary.



Carolina Power & Light Company

ROBINSON NUCLEAR PROJECT DEPARTMENT POST OFFICE BOX 790 HARTSVILLE, SOUTH CAROLINA 29550

FEB 1 9 1986

Robinson File No: 13510C

Serial: RNPD/86-584

United States Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

> H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-261 LICENSE NO. DPR-23 LICENSEE EVENT REPORT 86-004

Dear Sir:

In accordance with 10CFR50.73, Licensee Event Report System, the enclosed Licensee Event Report is submitted. This report fulfills the requirements for a written report within (30) days of a reportable event and is in accordance with the format set forth in NUREG-1022, September, 1983.

Very truly yours,

lelllergan

R. E. Morgan General Manager H. B. Robinson S. E. Plant

SAG: jch

.

Enclosure

cc: J. N. Grace INPO H. E. P. Krug