

**GPU Nuclear** 

100 Interpace Parkway
Parsippany, New Jersey 07054
201 263-6500
TELEX 136-482
Writer's Direct Dial Number:

October 23, 1985 RFW - 0665

Mr. Stewart D. Ebneter, Director Division of Reactor Safety U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

Dear Mr. Ebneter:

Subject: Oyster Creek Nuclear Generating Station

Docket No. 50-219

IE Bulletin (IEB) No. 79-14 Reinspection Program

The purpose of this letter is to document our recent agreement with Mr. J. P. Durr of your office concerning the inspection schedule for Recirculation System piping/supports (Understanding (2)(a) of Inspection Report 50-219/85-22). Additional information is also provided for Understandings No. 1 and 3 of Inspection Report 50-219/85-22 which was transmitted to us by your letter dated July 23, 1985.

As it was explained in our recent phone conversation with Mr. Durr, Oyster Creek Recirculation System will be decontaminated to conduct Induction Heating Stress Improvement (IHSI) of the piping welds during Cycle II refueling outage scheuled to commence in April, 1986. The reduction in radiation exposure by deferring the Recirculation System piping/supports inspection until after the IHSI, is expected to be significant (approximately 18.5 man-rems). This will also enable us to inspect the pipe supports in their "re-assembled" configuration following the IHSI during which some supports may be disassembled. On August 29, 1985 Mr. Durr, in his phone conversation with GPUN staff (M. Laggart), stated that the deferment of the inspection for the remaining Recirculation System lines/supports is acceptable provided that no significant discrepancies were found on the loop already inspected. During a plant shutdown in June 1985 one complete loop of the Recirculating System was inspected and no significant discrepancies were found on 21 supports inspected.

The scope of our planned reinspection effort does not include the removal of thermal insulation which obstructs the inspection of support details or prohibits the determination of the location of pipe supports within inspection tolerances. The justification for this exception to the requirements of IEB No. 79-14, Supplement 2, Page 2 of 2 is based on a sample population of 218 uninsulated and insulated but inspectable supports outside the drywell. Approximately 3 to 5% of these supports were found to have discrepancies which could affect the function of the support. For the supports inspected inside the drywell, for which complete inspection without removal of insulation was possible (5 total), no significant discrepancies were discovered. Based on this sampling we feel removal of insulation at this time is not warranted. However, as a confirmatory measure, several piping systems inside the drywell