



**Commonwealth Edison**  
One First National Plaza, Chicago, Illinois  
Address Reply to: Post Office Box 767  
Chicago, Illinois 60690 - 0767

September 2, 1988

Mr. T. E. Murley  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, DC. 20555

Attn: Document Control Desk

Subject: Braidwood Units 1 and 2  
Limatorque Operator Lubrication  
NRC Document No. 50-456

Reference: (a) NUREG-1002, Safety Evaluation Report, Supplement #6,  
dated May, 1988  
(b) August 26, 1988 S.C. Hunsader letter to T.E. Murley

Dear Mr. Murley:

Section 3.9.1 of Reference (a) provided the NRC staff's review of Commonwealth Edison's (Edison) submittals that addressed mixed grease within Limatorque valve operators. On page 3-1, the NRC acknowledged that Edison had identified 68 operators in both Units 1 and 2, that had grease mixtures greater than 5% SUN EP 50 mixed with Exxon Nebula EPO/EP1. (At this time, these operators have had the grease removed and replaced with Exxon Nebula EP1.) On page 3-3, the NRC staff provided the following comment:

"There is limited data on the affects of radiation exposure on mixed greases. Niagara Mohawk environmental testing of a mixture of calcium and lithium lead based greases resulted in no unacceptable degradation due to radiation. Although the test data is not directly applicable to the Braidwood grease mixture (similar grease bases, but unidentified trade names and composition), it does provide an indication of the radiation resistance of a mixture of similar chemical constituents."

In response to this comment and to verify that the as-found grease mixtures at Braidwood Station would have performed their intended function, mixtures of SUN EP50 and Exxon Nebula EPO/EP1 greater than 5% were radiation tested. The results of that testing were provided to the NRC staff in reference (b). The samples of Exxon Nebula EPO/EP1 mixed with Sun EP50 had maintained a

8809140024 880902  
PDR ADOCK 05000456  
G PNU

Aool  
1/0


consistency whereby the lubricating capability had not been reduced. Under a radiation exposure condition, it was verified that the grease will perform its intended lubricating function.

As indicated in reference (b), valve LRC 8001 A is a main loop isolation valve that is power locked out during all operational modes. Power is restored only during shutdown to expedite NSSS maintenance. This valve serves no safety function beyond maintaining the Reactor Coolant System boundary, thus operability and E.Q. qualification are not issues. The grease in this valve has not yet been changed out. Appropriate documents are being revised to indicate this change in EQ status.

In light of discussions held during the Enforcement Conference held at RIII on August 17, 1988, this information has been provided to the NRC staff to be reviewed for the purpose of assessing safety significance. The results of such a review will be relevant to any final enforcement actions taken.

Please address any questions concerning this matter to this office.

Very truly yours,



S. C. Hunsader  
Nuclear Licensing Administrator

/klj  
cc: S. Sands-NRR  
W. Forney-RIII  
Braidwood Resident Inspector

5076K