

FOR	NAME	DATE
	ADDRESS	<input type="checkbox"/> CHGTS <input type="checkbox"/> M S <input type="checkbox"/> RNO <input type="checkbox"/> NO
----- Paid here for return -----		
FROM	NAME	EXTENSION
	ADDRESS	<input type="checkbox"/> CHGTS <input type="checkbox"/> M S <input type="checkbox"/> RNO <input type="checkbox"/> NO

ON 4-19-84
 I DAVID Albury went
 to the seal table
 to run the cleaning
 cable into one of the
 thimbles I DAVID Albury
 was turning the crank
 when it broke.

David Alby 4-19-84

TM 450 (03-80) INTEROFFICE MAILING SLIP

B603040531 851231
 PDR FOIA
 STEPHEN85-706 PDR

11

pressure to the crank handle to get the cable to continue to move. Crank 78 was completed and 79 started with a slight movement of the crank and guide, water started spraying from the side of the guide. David removed his hand from the crank and guide and started leaving the area. The crank and guide fell from the seat table. The platform, water started spraying to the ceiling. The cable started laying back on the grating at the head of the stairs where I was. Approx. 50 ft. of was out when I turned to exit. After dressing I went to the control room and explained what happened.

Jerry Clift

85-706

App. C docs

FOR	NAME	DATE
	ADDRESS	<input type="checkbox"/> Drafts <input type="checkbox"/> M S <input type="checkbox"/> Reply <input type="checkbox"/> No
Fold here for reply		
FROM	NAME	EXTENSION
	ADDRESS	<input type="checkbox"/> Drafts <input type="checkbox"/> M S <input type="checkbox"/> Reply <input type="checkbox"/> No

ON APRIL, 19, 1984 MYSELF, BILL SIMPSON, DAVID ALBURY WENT TO THE SEAL TABLE TO RUN THE ~~CABLE~~ CABLE INTO ONE OF THE THIMBLES. WE WERE ACCOMPANIED BY CHUCK BAKER SF FOREMAN, JERRY CLIFT SF GENERAL FOREMAN, HAROLD GAMMAGE MECH. ENG., & TWO H.P. TECHS. MR. ALBURY WAS ^{CRANKING} ~~FEEDING~~ THE CABLE INTO THE THIMBLE TUBE, MR SIMPSON WAS FEEDING THE CABLE INTO THE CRANK, I WAS BEHIND MR SIMPSON WAITING TO RELIEVE EITHER HIM OR MR ALBURY WHEN THEY TIRED. MR. BAKER AND MR GAMMAGE WERE COUNTING THE TURNS ON THE CRANK AND LETTING MR ALBURY KNOW. THE H.P. TECHS WERE MONITORING THE CABLE AND THE

F O R M	NAME	DATE
	ADDRESS	<input type="checkbox"/> CHATTA <input type="checkbox"/> M S <input type="checkbox"/> RENO <input type="checkbox"/> NEV
Fold here for return		
F O R M	NAME	EXTENSION
	ADDRESS	<input type="checkbox"/> CHATTA <input type="checkbox"/> M S <input type="checkbox"/> RENO <input type="checkbox"/> NEV

AREA. MR ALBURY HAD STOPPED
 (I THINK) TWICE, TO ADJUST THE
 TUBE, TO THE CRANK. ■

WHILE MR ALBURY WAS CRANKING
 THE HIGH PRESSURE SEAL BROKE
 LOOSE, AND WE QUICKLY EXITED
 THE AREA

Dewey W. Paschal

FOR	NAME	DATE	4-19-84	
	ADDRESS	<input type="checkbox"/> Office	<input type="checkbox"/> M.S.	<input type="checkbox"/> No.
----- Fold here for return -----				
FROM	NAME	EXTENSION		
	ADDRESS	<input type="checkbox"/> Office	<input type="checkbox"/> M.S.	<input type="checkbox"/> No.

It was decided that we would ~~use~~ drive the cable + bush in the tube it was already in. David Albery was turning the crank, + Bill Simpson was maintaining the angle of the tube feeding to the seal table + keeping the cable in line going into the ~~tube~~ tube. Harald Stompage + myself were on either side of Bill watching the operation + counting the turns on the crank. Jerry Cleft was above us observing the operation.

FOR	NAME	DATE
	ADDRESS	<input type="checkbox"/> CHATTA <input type="checkbox"/> M. S. <input type="checkbox"/> KNOX <input type="checkbox"/> NOR.
----- Fold here for return -----		
FROM	NAME	EXTENSION
	ADDRESS	<input type="checkbox"/> CHATTA <input type="checkbox"/> M. S. <input type="checkbox"/> KNOX <input type="checkbox"/> NOR.

H. I. Teaka were ~~on~~ the
 far side of the seat table.
 David cranked the cable in
 50 turns & stopped to
 verify the count & inspect
 the cable, & adjusted the
 angle of the feeder tube, and
~~can~~ said the the cable
 seemed to be dragging a
 little. David turned it in
 to 69 turns & stopped to
 inspect the cable, again, at
 that time the cable showed
 several ~~to~~ rough areas ~~at~~
~~the~~ ~~at~~ the feeder tube
 & David said that ~~he~~ he
 didn't know about that
 area. He then started

FOR	NAME	DATE
	ADDRESS	<input type="checkbox"/> Office <input type="checkbox"/> M. S. <input type="checkbox"/> Home <input type="checkbox"/> No
Fold here for return		
FROM	NAME	EXTENSION
	ADDRESS	<input type="checkbox"/> Office <input type="checkbox"/> M. S. <input type="checkbox"/> Home <input type="checkbox"/> No

turning the ^{crank} cable again and
 on the 27 turn the crank
 started getting harder to
 turn, & we were nearly
~~on the~~ through the 28
 turn when the tubing broke.
 David was having to apply
 some pressure on the crank
 handle to ~~turn~~ turn it.
~~Then~~ it. That's when it
 broke, & we all got out
 as fast as possible.

Charles S. Baker

I was one of the last two workers to enter the work area. One of two H.P. personnel was setting up for air sample, the other was setting up its monitor for high level radiation, when removing cable from thimble tubes. Engineer Harold Gammage and fitter David Alburg was in the process of skinning the cable drive mechanism. I positioned myself to feed the cable from its can container to the drive mechanism. We proceeded to feed the cable ~~to~~ in, on approx, the 50th turn in David stopped, he and chuck agreed on the number of turns in. Then before he started to run the cable on in David suggested that I raise the arch of the cable feed to minimize resistance. On approx, 10 to 15 more turns in we noticed

that the cable had a few small kinks,
nothing to stop or bind the cable drive.
Within the next few turns the cable
feed had more resistance, but nothing that
required excessive pressure. ~~On~~

On Approach from 6 o'clock to 9 o'clock
position on the drive mechanism was
when the break occurred. Evacuation
and Control room notification was the
next step.

William Simpson

4-19-84

10-84
2:00 AM

} TIME OF WRITING THIS REPORT

AT 2:20 EASTERN TIME I ENTERED ZONE TO LOCATE THIMBLE POSITIONS TO BE CLEANED. FITTERS AND HP FOLLOWED BEHIND WITHIN 10 MINUTES. THE BASE MOUNT, TOP EXTENSION AND HAND CRANK WERE MOUNTED ON THIMBLE D-12. THE DUMMY CABLE WAS INSIDE THE THIMBLE APPROXIMATELY 10 TO 12 FEET. [THIS CABLE HAD BEEN RUN INTO THE CORE (ABOUT MIDWAY OF CORE LENGTH) AND WITHDRAWN DURING DAYSHIFT. AS THE END OF THE CABLE APPROACHED THE SEAL TABLE RADIATION READINGS REACHED 40 R CONTACT SO THE CABLE WAS REINSERTED TO REDUCE READINGS.] IT HAS BEEN DECIDED BECAUSE OF THE DOSE RATES THAT THE HOT END OF THE CABLE WOULD BE CUT OFF, TIED OFF, AND LEFT IN ~~THE~~ BELOW THE SEAL TABLE UNTIL A DISPOSAL METHOD COULD BE REACHED. BEFORE CUTTING THE CABLE I DECIDED TO REINSERT THE CABLE TO CLEAN THE THIMBLE AS MUCH AS POSSIBLE. AT THIS POINT I ROUGHLY CALCULATED THAT WE NEED TO RUN IN AROUND 120 TURNS

WITH 2 HP JACKS, 3 FITTERS, ONE FITTER FOREMAN, AND MYSELF AROUND THE SEAL TABLE AND JERRY CLIFF ON THE PLATFORM ABOVE WE INSERTED THE DUMMY CABLE TO 50 TURNS OF THE CRANK VERIFYING THIS POSITION BEFORE PROCEEDING. WE THEN WENT TO 68 TURNS AT WHICH POINT THE CABLE BECAME TOUGHER TO INSERT. WE HAD PREVIOUSLY NOTICED THAT THE CABLE HAD SOME ROUGH SPOTS PRIOR TO 68 TURNS. [NO EXCESSIVE FORCE WAS USED AT THIS POINT] THE BREAK OCCURRED AT THIS POINT @ 21:57. INITIALLY WATER WAS RELIEVING BETWEEN THE TOP EXTENSION BASE AND THE LOWER BASE. WE IMMEDIATELY LEFT THE SEAL TABLE TO THE AIR LOCK. (THE INNER AND OUTER DOORS OF THE AIR LOCK WERE CLOSED). THE INNER DOOR WAS OPENED AND ALL PERSONNEL LEFT. [I WAS WEARING A DIGITAL ALARM DOSE RATE METER. JUST PRIOR TO THE BREAK THERE WAS 2 MR READING ON IT. FROM THE TIME OF THE BREAK TO WE ENTERED THE AIR LOCK (APPROXIMATELY 15 SECONDS ELAPSED) THE RATE ALARM HAD GONE OFF AND I HAD A READING OF 25 MR]. WE LEFT THE AIR LOCK AND

Called AT THE GUARD TO NOTIFY THE CONTROL ROOM
OF THE INCIDENT. HE MADE SEVERAL CALLS WITHOUT
REACHING ANYONE SO I LEFT THE ZONE AND
REACHED EPPERSON IN THE CONTROL ROOM AND
EXPLAINED THE SITUATION AS BEST AS I KNEW IT.
~~ALL PERSON~~ [I FOUND OUT FROM HIM LATER THAT
THE TIME OF MY CALL WAS 2200 EASTERN TIME.
ALL PERSONNEL LEFT THE AREA AND I HAD
THE GUARD ON DUTY TO LOCK THE AIRLOCK
DOORS.

AS BEST AS I CAN DETERMINE THE HIGH
PRESSURE SEAL BETWEEN THE IMBLE AND THE
HIGH PRESSURE LINE FROM THE SEAL TABLE TOP
FAILED CAUSING THE RELEASE.

Harold H. Gammage
Harold H. Gammage

To: Jim Robinson

Date: 4-20-84-0150 A.

Subject: Breaking of High Pressure seal on the seal Table

Time: 2120 signed in on RWP for seal Table work. I went in with Harold Gammage ahead of the fitters and marked the detector paths we were going to brush. The fitters came in approx. 10 minutes later consisting of 2 HP Personell, Fitter Foreman Chuck Baker, Steamfitters David Albury, Bill Simpson and Dewey Paschal. Harold and David shimed under the guide block to insure it was tight on the seal table. We were going to run the cable in the detector path one or two more times to insure it was clean before cutting the end of the cable off and moving to another detector path. We established that David would turn the crank, Chuck Baker would count revolutions of the crank handle, Bill Simpson would hold the overhead guide tube and keep the cable straight, Dewey Paschal would watch the cable in the bucket for bad places. David made one revolution with the crank Harold wanted to verify the length of cable per crank. Harold measured the 2nd crank then again the 3rd crank. Each crank was approx 10". At this time Harold told David and Chuck how many revolutions David was to turn the crank. David started, he stopped at 50 turns to verify the count. David started again and stopped at 69 cranks looked at the cable and said he did not know whether or not it would go. On the 75th crank the cable

27

84 051720028

L05 840517 800

MAY 17 1984

R. A. Sessoms
1760 CST2-C

Subject: SEQUOYAH NUCLEAR PLANT - UNIT 1 - INCORE THIMBLE EJECTION -
INVESTIGATION AND REVIEW OF EVENTS FOR INDUSTRIAL SAFETY
IMPLICATIONS

Reference: Your memorandum to me dated May 2, 1984 (L01 840502 803)

As you requested in the referenced memorandum, an investigation committee
has conducted an industrial safety evaluation of the subject incident.
A report of their findings is attached.

L. C. Ellis
Chairman, Investigation Committee

LCE:BLF

Attachment

cc (Attachment):

NUC PR ARMS, 1520 CST2-C

- H. N. Culver, 249A HBB-K
- James P. Darling, 1750 CST2-C
- Arthur E. Ives, 1350 CUBB-C
- C. C. Mason, NUC PR, Sequoyah
- Jim Robinson, NUC PR, Sequoyah
- G. F. Stone, 215 MPB-M

U
0
0
7
1
4
1
0
1

C/2

INCORE THIMBLE EJECTION - SEQUOYAH NUCLEAR PLANT, UNIT 1

An investigation committee composed of Lonnie C. Ellis, Jim Robinson, and Arthur E. Ives completed an industrial safety evaluation of the subject incident. The evaluation involved an inspection of the seal table area; review of procedures, sketches, and drawings; discussions with Westinghouse; and interviews with the majority of employees involved. Those interviewed were J. Clift, General Foreman; H. Gammage, Engineer; D. Albury, Steamfitter; and S. Harrison and M. Edwards, Health Physics Technicians.

We initially evaluated the incident based on its potential to have resulted in a fatality, hospitalization of five or more of the involved employees, and property damage of greater than \$100,000. Although we would not want to downplay the seriousness of this incident and the stress of the moment, there was in this case adequate prior warning of bubbling and low-volume flow of relatively cool water to allow egress from the most remote point prior to total seal failure and subsequent thimble tube ejection. There were three paths of egress, two of which were remote from each other, and the individuals involved were knowledgeable of them. The air lock was the most desirable and the one used.

The air lock had been out of service for periods of time during the day. Welding under workplan 9606R2 was being done inside the air lock. This necessitated opening the outside door, thereby making the inner door inoperative. Had the incident occurred during this work, egress through the air lock would have been delayed or primary egress would have been through the submarine hatch.

The incident in total will exceed \$100,000 in property damage, cleanup, and restoration. The majority of costs result from the radiological aspects of the incident. The Designated Agency Safety and Health Official and the Office manager were notified of the incident.

We do not believe this investigation was significantly hindered due to the restoration of the area prior to our involvement. Only a visual observation of the ejected tube was not available to us and that was viewed on blown-up photos.

Sequence of Events

Initial cleaning of thimble tubes was begun on March 28, 1984, and was reported complete on April 5, 1984. The unit was in Mode 5. The thimble drive units were reinstalled and the incore probes were inserted to verify adequate cleaning. Several of the cleaned tubes failed to pass the thimble and others previously identified as clear were now identified as plugged.

U O U 7 7 1 4 1 0 2

Sequence of Events (continued)

Subsequently, a maintenance request (attachment 1) was written on April 18, 1984, to dry brush the blocked thimble on the incore monitor tubes. It was assigned to Field Services and was proceeding when the second shift reported on April 19, 1984. Applicable sections of SMI-0-94-1 (attachment 2) were identified under work instructions for reference.

D-12, the tube that failed, was not included in the maintenance request as a tube to be cleaned but was being used to measure the length of the cleaning cable.

A crew of six was assigned to brush the tubes. They were H. Gammage, Engineer; D. Pascal, B. Simpson, and D. Albury, Steamfitters; and S. Harrison and M. Edwards, Health Physics Technicians. The General Foreman, J. Clift, and the Steamfitter Foreman, C. Baker, were also on the seal table platform observing the work and assisting as necessary. Seven of the eight employees were arrayed on the seal table platform operating the brushing mechanism, while the eighth, Mr. Clift, was on the platform above.

The reactor was in Mode 1 (approximately 30 percent power) which places the pressure at 2250 psi and the temperature at 547°F.

The specially designed brushing mechanism is composed of several feet of heliflex cable fed through a stabilizing tube and forced through the thimble tube by a hand crank. Attachment 3 shows a cut-away detail of the thimble tube connection. The hand crank is attached to the thimble tube at point 1, with the brush entering the connection at that point.

The brush had entered at approximately one-half of the tube's 120-foot length and was meeting some slight increased resistance. Various levels of sound were heard by the involved employees and water began flowing from the connection. The tube was not observed being ejected, nor was steam observed at this time. The employees immediately left the platform, opened and entered the air lock, and exited the area. Looking back through the air lock portholes they could see steam begin to build in the room. Exit time from platform to safety in the air lock was no greater than 20 seconds. Under the circumstances, the exit appeared very orderly and there were no injuries.

The failure occurred at the reactor pressure boundary seal, point #2 (attachment 3). This seal is obtained by a 5/16-inch swagelok nut and ferrules crimped onto a smaller stainless steel heavy wall tube expanded to 5/16 inch. This union is protected from external tampering by a plastic boot (point 3).

U O U / 7 I 4 1 0 3

000771 4104

Conclusions

The reason for the failure is not evident. Existing possibilities are (1) the tube was not expanded sufficiently or to a sufficient depth (specifications require a minimum of 1.5 inches), (2) the swagelok was not tightened sufficiently (hand tight and 1.25 additional turns) to set the ferrule, (3) the nut had inadvertently been loosened since the union was made, allowing the ferrule to relax, or (4) the partial crack in the ferrule allowed the tube to be released. The flexing activity of the brushing would have aggravated any of the above conditions leading to the failure. Following this failure all fittings were checked and some were tightened. SMI-0-94-1 states that this procedure is not to be used at power. Since the unit was in Mode 1, this procedure was violated.

Recommendations

1. All cleaning and brushing of these tubes should be done with the reactor at Mode 5.
2. If for some reason the brushing iteration is required past Mode 5, a thorough prejob safety analysis should be performed and the procedure approved by PORC. As a minimum, a mechanism should be installed to preclude tube ejection and leakage and a clear path of egress should be established.
3. A rigidly mounted attachment should be fabricated on which the brushing mechanism and crank would mount which will eliminate any stress or flex on the thimble tube connection. An alternative method of cleaning which would mount independently of the thimble tube would be preferred.
4. All work on any system where there is no secondary pressure boundary should be evaluated on a case-by-case basis and adequate means to mitigate an inadvertent pressure failure should be applied.
5. Ensure the constant availability of the primary egress route, i.e., the air lock. Consideration should be given to leaving the inner door open (with the shift engineer's permission) or providing a person to man the door.
6. Ensure that all emergency notification systems are in constant operation. The air lock telephone was out of service during this event.
7. Reinstall the plastic boots or install other means around all reactor pressure boundary seal unions to prevent tampering.
8. Commend the eight employees for their coolness under pressure and their ability to reason through egress options under the stressful situation.

LCE:BLF
5/14/84

ATTACHMENT 1

U O O J 7 1 4 1 0 5

FUNCTION SYSTEM		SYSTEM COMPONENT		ACTIVITY
1 MST		94		
ASSIGNED TO				TRAVELING INCORE MONITOR
MECH	ELEC	INST	TEST	EQUIPMENT LOCATION
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	E1 693 Seal Table
DESCRIBE WORK REQUESTED:				Dry brush blocked thimbles listed below: See Attached
				** Use <u>No</u> Water or Neclube **
ORIGINATOR		SECTION		SUPV INITIAL
D.P. Roberts		Eng. (N)		WR
PRIORITY:				EQUIPMENT CATEGORY:
EMERGENCY	IMMEDIATE ATTENTION	ROUTINE	CSSC	OTHER
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
WORK INSTRUCTION: Dry Brush only Followings applicable				
SECTIONS OF SMI-O-94-11				
QA OR POST MAINT. TEST REQUIREMENTS PER SMI-O-94-11				
INVOLVES REPLACEMENT OF EQUIPMENT QUALIFIED PERSONNEL? <input type="checkbox"/> NO <input type="checkbox"/> YES ATTACH TVA FORM 64360				
QA REVIEW		DATE		
<input checked="" type="checkbox"/>		4-18-84		

U
0
0
7
7
1
4
1
0
6

Detector	Path	Core	Location
A-1			H-15
A-2			K-2
A-4			P-4
A-8			E-9
A-10			L-5
B-9			H-13
C-1			G-9
C-2			R-8
C-3			C-5
C-4			B-13
C-5			H-11
C-6			J-14
C-7			J-1
C-8			L-8
C-9			F-3
C-10			E-5
D-6			D-14
D-8			D-3
E-8			F-8
E-9			C-8
F-3			B-3
F-5			N-4
- -			A -

ATTACHMENT 3

EXISTING SWAGELOK UNION
FLARE FITTING


THIMBLE TUBE

PLASTIC BOOT

EXISTING SWAGELOK UNION

SWAGELOK NUT
& FERRULES

EXISTING THIMBLE GUIDE TUBE



SWAGELOK FERRULES

REACTOR PRESSURE
BOUNDARY SEAL

2

REACTOR PRESSURE
BOUNDARY SEAL

EXISTING
SEAL TABLE

EXISTING THIMBLE TUBE CONNECTION

U O O 7 7 1 4 1 2 7



October 15, 1985

nuclear · awareness · network

1347½ massachusetts · lawrence, kansas 66044 · (913) 749-1640

Director
Office of Administration
US Nuclear Regulatory Commission
Washington, D.C. 20555

FREEDOM OF INFORMATION
ACT REQUEST

FOIA-85-706

Rec'd. 10-21-85

FREEDOM OF INFORMATION ACT REQUEST

To Whom It May concern:

Pursuant to the Freedom of Information Act, U.S.C. 522, as amended, the Nuclear Awareness Network requests the following documents regarding the Wolf Creek Nuclear Generating Plant. Please consider "documents" to include reports, studies, test results, correspondence, memoranda, meeting notes, meeting minutes, working papers, graphs, charts, diagrams, notes and summaries of conversations and interviews, computer records, and any other forms of written communication, including internal NRC staff memoranda. The documents are specifically requested from, but not limited to, the following offices of the NRC: Office of Analysis and Evaluation of Operational Data (AEOD); Office of Nuclear Reactor Research (NRR); Office of Nuclear Regulatory Research (Research); Office of Inspection and Enforcement (I&E); Office of Investigations (OI); Generic Issues Branch of the Division of Safety Technology, and the Operating Reactors Branches of the Division of Licensing.

In your response, please identify which documents correspond to which requests below.

Pursuant to this request, please provide all documents prepared or utilized by, in the possession of, or routed through the NRC related to the Wolf Creek Nuclear Generating Plant:


- 1.) Any and all information relating to the "Sequoyah Incident" which would have occurred prior to August 20, 1985-- probably during 1984. This incident occurred during a maintenance procedure which involved Chuck Mason and 3 other workers who may have been put in jeopardy. It was purported to have been investigated by the Nuclear Safety Review Staff (NSRS) which is a part of TVA, and reports were made to a Mr. Willis at TVA. Included in this request are any and all documents submitted by TVA, NSRS, and/or Mr. Willis on this subject.
- 2.) Any and all information surrounding an incident on or about August 4, 1985 involving a release, or potential release, of radiation at Wolf Creek into the cooling lake and/or atmosphere.

If any of the material covered by this request has been destroyed and/or removed, please provide all surrounding documentation, including but not limited to a description of the action(s) taken, relevant date(s), and justification(s) for the actions.

For any documents or portions that you deny due to a specific FOIA exemption, please provide an index itemizing and describing the documents or portions of documents withheld. The index should provide a detailed justification of your grounds for claiming each exemption, explaining why each exemption is relevant to the document or portion of the document withheld. This index is required under Vaughn v. Rosen (I), 484 F.2d 820 (D.C. Cir. 1973), cert. denied, 415 U.S. 977 (1974).

We look forward to your response to this request within ten days.

Sincerely,

A handwritten signature in cursive script that reads "Stevi Stephens". The signature is written in dark ink and is positioned to the right of the typed name.

Stevi Stephens