

NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
HOLYOKE WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

General Offices • Selden Street, Berlin, Connecticut

P.O. BOX 270
HARTFORD, CONNECTICUT 06141-0270
(203) 665-5000

May 16, 1988
MP-11817

Re: 10CFR50.73(a)(2)(i)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Reference: Facility Operating License No. NPF-49
Docket No. 50-423
License: Event Report 88-015-00

Gentlemen:

This letter forwards Licensee Event Report 88-015-00 required to be submitted within thirty days pursuant to 10CFR50.73(a)(2)(i), any operation or condition prohibited by the Plant's Technical Specifications.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

Stephen E. Scace
Station Superintendent
Millstone Nuclear Power Station

SES/NDH:mo

Attachment: LER 88-015-00

cc: W. T. Russell, Region I
W. J. Raymond, Senior Resident Inspector

8805230247 880516
PDR ADOCK 05000423
S PDR

IE22
11

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Millstone Nuclear Power Station Unit 3	DOCKET NUMBER (2) 0 5 0 0 0 4 2 3	PAGE (3) 1 OF 3
-------------------------------------------------------------	--------------------------------------	--------------------

TITLE (4)
Reactor Coolant System Unidentified Leakage Action Statement Improperly Terminated

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																																																																
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)																																																														
04	15	88	88	015	00	05	16	88			05000																																																														
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:15%;">OPERATING MODE (9)</td> <td style="width:15%;">3</td> <td colspan="10">THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)</td> </tr> <tr> <td rowspan="6">POWER LEVEL (10)</td> <td rowspan="6">000</td> <td>20.402(b)</td> <td></td> <td>20.405(c)</td> <td></td> <td>50.73(a)(2)(iv)</td> <td></td> <td>73.71(b)</td> <td></td> </tr> <tr> <td>20.405(a)(1)(i)</td> <td></td> <td>50.38(e)(1)</td> <td></td> <td>50.73(a)(2)(v)</td> <td></td> <td>73.71(e)</td> <td></td> </tr> <tr> <td>20.405(a)(1)(ii)</td> <td></td> <td>50.38(e)(2)</td> <td></td> <td>50.73(a)(2)(vi)</td> <td></td> <td>OTHER (Specify in Abstract below and in Text, NRC Form 366A)</td> <td></td> </tr> <tr> <td>20.405(a)(1)(iii)</td> <td></td> <td>X 50.73(a)(2)(i)</td> <td></td> <td>50.73(a)(2)(viii)(A)</td> <td></td> <td></td> <td></td> </tr> <tr> <td>20.405(a)(1)(iv)</td> <td></td> <td>50.73(a)(2)(ii)</td> <td></td> <td>50.73(a)(2)(viii)(B)</td> <td></td> <td></td> <td></td> </tr> <tr> <td>20.405(a)(1)(v)</td> <td></td> <td>50.73(a)(2)(iii)</td> <td></td> <td>50.73(a)(2)(ix)</td> <td></td> <td></td> <td></td> </tr> </table>												OPERATING MODE (9)	3	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)										POWER LEVEL (10)	000	20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)		20.405(a)(1)(i)		50.38(e)(1)		50.73(a)(2)(v)		73.71(e)		20.405(a)(1)(ii)		50.38(e)(2)		50.73(a)(2)(vi)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)		20.405(a)(1)(iii)		X 50.73(a)(2)(i)		50.73(a)(2)(viii)(A)				20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)				20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(ix)			
OPERATING MODE (9)	3	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																																																																							
POWER LEVEL (10)	000	20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)																																																																	
		20.405(a)(1)(i)		50.38(e)(1)		50.73(a)(2)(v)		73.71(e)																																																																	
		20.405(a)(1)(ii)		50.38(e)(2)		50.73(a)(2)(vi)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)																																																																	
		20.405(a)(1)(iii)		X 50.73(a)(2)(i)		50.73(a)(2)(viii)(A)																																																																			
		20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)																																																																			
		20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(ix)																																																																			

LICENSEE CONTACT FOR THIS LER (12)

NAME Nelson D. Hulme, Senior Engineer X5398	TELEPHONE NUMBER AREA CODE: 203 447-1791
------------------------------------------------	------------------------------------------------

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15) MONTH: DAY: YEAR:
--------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On April 15, 1988 at 1500 hours in Mode 3 (Hot Standby) 557 degrees and 2250 psia, it was determined that the action taken to terminate a previously documented Unidentified Leakage Event had been improperly performed.

At 1715 hours on April 14, the action statement for an unidentified Reactor Coolant System (RCS) leakrate of greater than 1 gallon per minute (gpm) was entered based on the increased leakrate observed by Volume Control Tank make up. At 2107 hours on April 14, after a leak source was identified and isolated, the action statement was exited based on qualitative assessment of plant parameters being steady. Following the resolution of computer problems and the completion of RCS sampling, a leakage surveillance program was initiated at 0900 hours on April 15. At 1332 hours, the leakrate was determined to be 1.15 gpm. Root cause of this event was personnel error. The decision was made to terminate the Unidentified Leakage Action Statement without a detailed quantitative analysis to determine the unidentified leakrate.

All Operations Department personnel have been sent a memorandum stipulating that approved surveillances or other quantitative methods, must be used to determine whenever RCS unidentified leakage has been corrected. The applicable operating procedure has been changed to provide better guidance on measuring unidentified RCS leakage.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Millstone Nuclear Power Station Unit 3	DOCKET NUMBER (2)						LER NUMBER (6)			PAGE (3)									
							YEAR	SEQUENTIAL NUMBER	REVISION NUMBER										
	0	5	0	0	0	4	2	3	8	8	0	1	5	0	0	0	2	OF	0

TEXT (If more space is required, use additional NRC Form 306A's) (17)

I. Description of Event

On April 15, 1988 at 1500 hours with the plant in Mode 3 (Hot Standby) at 0% power, 557 degrees Fahrenheit and 2250 psia, it was determined that the action taken to terminate a previously documented Unidentified Leakage Event had been improperly performed.

At 1715 hours on April 14, 1988, the Action Statement for an Unidentified Reactor Coolant System (RCS) leakrate of greater than 1 gallon per minute (gpm) was entered based on the increased leakrate observed by Volume Control Tank make up. At 2006 hours on the same day, stem leakoff was discovered at a pressurizer relief block valve. After the leak was isolated, Volume Control Tank (VCT) and Pressurizer levels were monitored for further changes. At 2107 hours, based only on qualitative assessment of steady VCT and Pressurizer levels, the Action Statement for RCS Unidentified Leakage was exited. A leakrate surveillance program was initiated at 2330 hours, but due to computer problems unreliable results were obtained. Sampling of the RCS by the Chemistry Department also introduced errors in the calculations. At approximately 0900 hours on April 15, 1988, a leakrate surveillance program was reinitiated. At 1332 hours it was evident that an unidentified leakrate of greater than 1 gpm still existed. Therefore, an Unidentified Leakage Event was again declared.

II. Cause of Event

The root cause of this event was personnel error. The decision was made to terminate the Unidentified Leakage Action Statement without performing the leakrate surveillance program, or without performing some detailed quantitative analysis to precisely determine the unidentified RCS leakrate.

III. Analysis of Event

This Licensee Event Report (LER) is being submitted in compliance with 10CFR50.73(a)(2)(i) due to operating in a condition prohibited by the plant's Technical Specifications.

There were no safety consequences as a result of this event. The plant was in Hot Standby at 1715 hours on April 14 when the leakage was first discovered and the plant was eventually placed in Cold Shutdown, as required by the Technical Specifications, after an unidentified leakrate of 1.15 gpm was determined at 1332 hours on April 15.

IV. Corrective Action

All Operations Department personnel have been sent an internal department memorandum describing this event. The memo stresses that approved surveillances or other quantitative methods must be used whenever RCS unidentified leakage has been corrected. The applicable Operating procedure has been changed to provide better guidance on measuring unidentified RCS leakage.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) Millstone Nuclear Power Station Unit 3	DOCKET NUMBER (2) 0 5 0 0 0 4 2 3	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8 -	0 1 5 -	0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

V. Additional Information

There have been no previous events where an Action Statement was improperly terminated.

EIIS Codes

System

Reactor Coolant System - AB