

**PSC**

Precision  
Surveillance  
Corporation

Main Title Ten Year Visual Tendon Surveillance of the Arkansas Nuclear One - Unit 2 Primary Reactor Containment Building

Sub-Title Surveillance Report

BY

Joseph Willich, Acting Manager, Engineering

Reviewed by: Ronald Hough, P.E. General Manager

ENGINEERING DEPARTMENT

ABSTRACT

This report presents the findings of the ten year visual tendon surveillance of Arkansas Nuclear One - Unit 2. This surveillance mainly consisted of sheathing filler analysis and tendon anchorage inspection. Based on the results of this surveillance, no abnormal degradation of the containment post tensioning is evident.

REVISION CONTROL LOG

Rev.	Revision Date	By	Approved By	Pages Affected
△	5/13/88	JW	RSH	1 thru iv, 1 thru 9, A-1 thru A-2, B-1 thru B-37,
⊙	7/1/88	JW	RDH	C-1, D-1 thru D-111, E-1 thru E-2, F1 thru F10,
△				
△				
△				
△				
△				
△				
△				
△				
△				
△				

8809200065 PDR R  
880909 05000368 PNU ADOCK

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

Summary

This report covers the Ten-Year visual tendon surveillance of the Arkansas Nuclear One - Unit 2 primary reactor containment building. The tendon surveillance program consists of periodic visual inspection for physical condition of a randomly pre-selected group of surveillance tendons. Visual tendon surveillance consists of removing grease caps, sheathing filler analysis, anchorage inspection, and resealing.

The Ten-Year tendon surveillance was performed approximately 123 months after completion of the structural integrity test and involved 9 tendons (3 verticals, 3 hoops, and 3 domes).

Only one item should be noted, that tendon 31H36 had two ounces of water found in the field end.

Inspection of the anchorages, sheathing filler, buttonheads, and wire continuity were all found acceptable. Therefore, based on the results of this ten-year surveillance, no abnormal degradation of the containment post-tensioning is indicated.

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

TABLE OF CONTENTS

Summary.....	1
Table of Contents.....	ii
List of Tables.....	iii
Section 1	
Introduction.....	iv
Section 2	
I. Surveillance Procedures .....	1
II. Sheathing Filler Analysis .....	1
III. Tendon End Anchorage Inspection .....	2
IV. Other Observations .....	3
V. Comparison with Past Surveillances .....	3
Section 3	
Conclusion .....	8
List of References .....	9
Section 4	
Appendix A. Ten Year Surveillance Tendon Locations.....	A-1
Section 5	
Appendix B. Arkansas Nuclear One (Unit 2) Tendon Surveillance Test Procedure.....	B-1
Section 6	
Appendix C. Sheathing Filler Analysis Reports .....	C-1
Section 7	
Appendix D. Tendon Surveillance Data Sheets.....	D-1
Section 8	
Appendix E. Material Certification .....	E-1
Section 9	
Appendix F. Equipment Calibrations or Gauge Calibration ....	F-1

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

LIST OF TABLES

I.	Summary of Laboratory Analysis of Sheathing Filler ....	4
II.	Summary of Tendon End Anchorage Inspections .....	5
	Notes on Table II.....	6
III.	Summary of Water Inspection.....	7

## Ten Year Visual Tendon Surveillance of the Arkansas Nuclear One - Unit 2 Primary Reactor Containment Building

### Introduction

This report covers the ten-year visual tendon surveillance of the Arkansas Nuclear One - Unit 2 primary reactor containment building. The containment building tendon surveillance program is a systematic means of assessing the continuing quality and structural performance of the post tensioning system. The ten-year tendon surveillance is the fourth in a series with additional tests scheduled at five year intervals hereafter.

The Arkansas Nuclear One - Unit 2 containment meets the guidelines established in Regulatory Position C2 of Regulatory Guide 1.35, Revision 2 for identical containment structures on one site, without environmental or other apparent differences, constructed in a continuous manner by the same contractor. Therefore, only a visual surveillance was performed. The contractor for Arkansas Nuclear One - Units 1 and 2 was Bechtel Power Corporation, San Francisco, California.

This tendon surveillance program consists of periodic visual inspection for physical condition of a randomly pre-selected group of surveillance tendons. This inspection provides confidence in the condition and functional capability of the system and an opportunity for timely corrective measures if adverse conditions are detected. Visual tendon surveillance consists of removing grease caps, sheathing filler analysis, anchorage inspection, and resealing.

The ten-year tendon surveillance of the Arkansas Nuclear One-Unit 2 reactor building post tensioning system was performed in February 1988 (approximately 123 months after completion of the structural integrity test performed in October, 1977). The surveillance was conducted in accordance with "Reactor Building Tendon Surveillance Procedure", Operating Procedure No. 2402.48 Revision 2. A copy of that Test Procedure is included in this report under Appendix B. The group of three vertical, three hoop, and three dome tendons were selected for inspection in compliance with NRC Regulatory Guide 1.35 (Rev. 2 January 1976). The location and identification of these surveillance tendons are shown in Appendix A.

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

I. Surveillance Procedures

Detailed procedures for the conduct of surveillance operations are included in Appendix B. The following summarizes the typical activities performed on a surveillance tendon.

Following removal of the tendon anchorage cap, samples of filler are taken from each cap for laboratory analysis. Sheathing filler is then removed from the hardware, and the various anchorage components are inspected for physical condition. The inspection includes: a count of missing, split, deformed, and unseated buttonheads; examination of the stressing anchorages, shims, and bearing plate for cracks and other visual deformations and examination of all metal components for coverage by filler as well as corrosion. The results of these examinations and inspections are recorded on appropriate data sheets. Also recorded for unexpected conditions is the general appearance of the filler material, the amount of water (if any) drained from or found in the cap, and the estimated amount of filler removed or drained from the anchorage and tendon sheathing as well as the amount of filler replaced.

II. Sheathing Filler Analysis

A sample of sheathing filler was removed from each end of each surveillance tendon. Chemical tests were performed on one sample from each tendon. The sample analyzed was selected arbitrarily from the tendon shop or field end. Chemical tests on the second samples from a tendon were required only if the results of the tests on the first sample failed to meet the acceptance criteria of Attachment 4 of Operating Procedure 2402.48 Rev. 2.

Maximum acceptance limits of 10% by weight water and 10 parts per million for water-soluble chlorides, nitrates, and sulfides were established in Attachment 4 of Operating Procedure 2402.48 Rev. 2. Those limits for water-soluble ions are the same as given by ASME Section III, Division 2-Part E: Concrete Reactor Vessels and containments for new sheathing filler while no limit for water content was given by the ASME Code. All samples tested met the acceptance criteria for water and water-soluble ions. The results of the analysis of the sheathing filler are given in Appendix C and the sheathing filler removal and installation procedures are given in Appendix D. A summary of the report results are tabulated in Table I.

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

III. Tendon End Anchorage Inspection

The anchorage components were inspected after end cap removal to determine whether sheathing filler coverage was adequate. In every case but one the tendon wire buttonheads were completely coated by the sheathing filler while 73% of the other metal components were completely coated. In no case was coating less than 50%.

After the sheathing filler was cleaned off, the anchorage components were inspected for corrosion, cracks, and buttonhead size and condition. Corrosion of anchorage components was found to be either corrosion level No. 1 - "bright metal, no visible oxidation" or corrosion level No. 2 - "reddish brown, no pitting". No cracks in anchorheads, shims, or bearing plates were observed. A total of 10 buttonheads were found to have splits which were judged to be acceptable as the heads were seated and wires were carrying load.

Inspection of buttonhead size is not intended to be a basis for acceptance or rejection of each tendon but rather a recording of the as-inspected condition. Eight tendons had offsize buttonheads of 10 to 20 while one other tendon exhibited eight offsize buttonheads. No offsize buttonheads showed any signs of cracking (neither slips nor splits). In some cases, the go-no go gage would not pass over pairs or groups of buttonheads, but further inspection showed the heads were not offsize but spaced too closely for the gage wall to pass between.

A possible condition that would explain this problem was conjectured in the last surveillances for Unit 2. From the regular pattern of these offsize buttonheads, it seems that the hole spacings on the anchorheads may be slightly irregular. This condition would not have been observed during construction, as buttonheads are checked for size before tensioning, and the heads would not be fully seated. Since the offsize buttonheads were subjected to 80% of the ultimate strength during construction without buttonhead failures, and no visible signs of in-service failure such as cracking were observed, the offsize buttonheads have no harmful effect on the post tensioning system integrity.

A tabulated summary of the tendon end anchorage inspection results is given in Table II while the complete set of data sheets are in Appendix D.

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

III. Tendon End Anchorage Inspection, Continued

A review of the grease replacement and losses from Table II, shows that replacement was equal to or more than the amount removed. However, this amount was no greater than four gallons, which is a very small percent of the total and common occurrence for tendon system surveillances.

IV. Other Observations

The neutralization test is generally run by grease manufacturers on new batches of product. It is a method of determining the overbase additives in the grease. Degradation of the sheathing filler will yield a change in acidity of the material and would be detected as an increase in ion content (chlorides, nitrates, and sulfides). Up until this third surveillance, the neutralization number was tested for as per ASTM D644. ASME Section III Division 2 Code requiring the neutralization number to be tested for as per ASTM D974 - Modified. This revision was used in the Third and this surveillance.

Tendon V56 showed a low neutralization of 2.62. This indicates that V56 was probably filled with 2090P grease rather than 2090P-4. Both greases were used on the site and the neutralization numbers are in a range to be expected for 2090P and 2090P-4 grease.

Tendon 31H36 field end had two ounces of water found in the grease can. The grease was discolored as it was for tendon 12H18 shop end. Laboratory testing of grease for water found the water content below 1% for both tendons. Therefore, the occurrence of discoloring was localized and the condition of water being present was not a sign of degradation of the system. It is most likely the water was present from a leaking seal. Since the seals were replaced and the water content was at acceptable levels, the condition is accepted as is.

V. Comparison With Past Surveillances

All tendons inspected during this surveillance had never been inspected in previous surveillances. The data from this surveillance's operations; grease testing, control of grease quantity, and visual inspection are consistent with results obtained in past surveillances.



Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

TABLE I - SUMMARY OF LABORATORY ANALYSIS OF SHEATHING FILLER

Tendon	End	Water Solubles - ppm			Water Content (ASTM D95) (% W/W)	Neutralization
		Chlorides (ASTM D512)	Nitrates (ASTM D992)	Sulfides (APHA)		Number mg KOH/g Per ASTM D974  (Modified) Base Number
V9	F	0.515	<0.05	0.013	0.19	38.71
V56	S	0.456	0.05	0.014	0.20	2.62
V95	F	0.603	<0.05	0.012	0.54	43.79
12H18	S	0.162	<0.05	0.037	0.14	42.76
31H36	F	0.132	<0.05	0.003	0.92	41.55
32H50	F	0.074	<0.05	0.012	0.10	40.65
3D104	F	0.074	<0.05	0.003	0.22	40.77
2D219	S	0.132	<0.05	<0.001	0.25	43.95
1D327	S	0.191	<0.05	<0.001	0.32	45.45
Allowable Maximum		10 ppm	10 ppm	10 ppm	10% W/W	>0.00

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building  
Summary of Tendon End Anchorage Inspections

Table II

Tendon	End	TENDON SHEATHING FILLER			ANCHORAGE COVERAGE (%)				
		Amount Removed (Gal.)	Amount Replaced (Gal.)	Color Change	Cap	Button- heads	Anchor heads	Shims	Bearin- Plate
V9	S	.5	.5	None	100	100	100	100	100
	W	.5	.5	None	100	100	100	N/A	100
V54 4	S	.25	3.25	None	100	100	100	100	100
V56	S	.5	4.5	None	100	100	100	100	100
	W	.5	.5	None	100	100	100	N/A	100
V95	S	.5	.25	None	100	100	100	100	100
	W	.5	.5	None	100	100	100	N/A	100
12H18	S	2.5	4.75	Yes	80	100	90	80	80
	W	1.75	3.75	None	80	100	80	80	80
31H36	S	2.5	4.25	None	80	100	95	80	100
	W	2.25	5.25	Yes	50	50	50	50	50
32H50	S	2.25	2.25	None	80	100	80	80	80
	W	3.0	3.75	None	80	100	100	100	100
3D104	S	3.25	4.0	None	100	100	100	100	100
	W	3.75	4.25	None	100	100	100	100	100
2D219	S	3.0	4.5	None	100	100	100	100	100
	W	3.0	4.0	None	100	100	100	100	100
1D327	S	3.25	5.0	None	100	100	100	100	100
	W	2.75	5.25	None	100	100	100	100	100

ANCHORAGE CORROSION LEVELS

BUTTONHEADS

Tendon	End	ANCHORAGE CORROSION LEVELS				BUTTONHEADS		
		Button- heads	Anchor- heads	Shims	Bearing Plate	Missing	Split	Offsize
V9	S	1	1	1	1			10
	W	1	1	N/A	1			
V54 4	S	1	1 (80%)	1	1			8
	W		2 (20%)					
V56	S	1	1	1	1		10	
	W	1	1	N/A	1			
V95	S	1	1	1	1			12
	W	1	1	N/A	1			
12H18	S	1	1	1	1			20
	W	1	1 (98%)	1	1			
			2 (2%)					
31H36	S	1	1	1	1			14
	W	1	1	1	1			
32H50	S	1	1	1	1			19
	W	1	1	1	1			
3D104	S	1	1	1	1			6
	W	1	1	1	1			13
2D219	S	1	1	1	1			4
	W	1	1	1	1			10
1D327	S	1	1 (80%)	1	1			2
	W		2 (20%)					
		1	1	1	1			14

See Page 6 for Notes on Table II

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

Notes on Table II: Summary of Tendon End Anchorage Inspections

1. Corrosion levels are defined as follows:
  - 1 = Bright Metal, No Visible Oxidation
  - 2 = Reddish Brown, No Pitting
  - 3 = 0" < Pitting < .003"
  - 4 = .003" < Pitting < .006"
  - 5 = .006" < Pitting < .010"
  
2. Tendon end defined as:
  - S = Shop End (top for Verticals)
  - F = Field End (bottom for Verticals)
  
3. N/A = not applicable (there are no shims on the field end of the vertical tendons)
  
4. Obstruction of field end V54 was found, therefore, V56 was substituted as the surveillance tendon per review and instruction of A.P. & L. Engineering.

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

Summary of Water Inspections

TABLE III

TENDON NUMBER	SHOP	FIELD
V9	None	None
V53	None	N/A
V54	None	N/A
V55	None	N/A
V56	None	None
V57	None	N/A
V95	None	None
12H18	None	None
31H36	None	Two Oz.
32H50	None	None
3D104	None	None
2D219	None	None
1D327	None	None

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

Conclusions

The anchorage inspection showed that the anchorage components had no observed cracking and negligible corrosion. The sheathing filler from every surveillance tendon was found to be acceptable. The tendon wire buttonheads were found to be acceptable, with only negligible variances existing. All surveillance tendons were visually inspected for discontinuous wires and none were found.

Based on the results of the ten-year tendon surveillance of Arkansas Nuclear One - unit 2, no abnormal degradation of the containment post-tensioning is indicated.

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

LIST OF REFERENCES

1. United States NRC Regulatory Guide 1.35, Inservice Inspection of UngROUTED Tendons in Pre-Stressed Concrete Containment Structures, Revision 2, January 1976.
2. Arkansas Nuclear One, Unit 2, One-Year Visual Tendon Surveillance Report, prepared by Bechtel National, Inc. Research and Engineering Group.
3. Arkansas Nuclear One, Unit 2, Three-Year Visual Tendon Surveillance Report, prepared by Bechtel Power Corporation, Special Services & Testing.
4. Arkansas Nuclear One, Unit 2, Five-Year Visual Tendon Surveillance Report, prepared by Inryco, Incorporated, Surveillance Department.

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

APPENDIX A - Ten Year Surveillance  
Tendon Locations

# PSC

Precision Surveillance Corporation

ARKANSAS POWER & LIGHT AND UNIT #2



10th YEAR SURVEILLANCE

CALCULATION NO:

SAFETY RELATED

NON-SAFETY RELATED

PAGE A1 OF 2



PREPARED BY *Bill Carter*

DATE 7-1-88

REVIEWED BY

DATE



# PSC

Precision Surveillance Corporation

ARKANSAS POWER & LIGHT ANO UNIT #2


10th YEAR SURVEILLANCE

CALCULATION NO:

SAFETY RELATED

NON-SAFETY RELATED

PAGE A2 OF 2



HORIZONTAL TENDONS DEVELOPED ELEVATION

PREPARED BY *Bill Carter*

DATE 7-1-88

REVIEWED BY

DATE

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

APPENDIX B - Arkansas Nuclear One  
(Unit 2)  
Tendon Surveillance  
Test Procedure



# ARKANSAS POWER & LIGHT COMPANY

## Arkansas Nuclear One

JO# 74910

TITLE: RECORD OF CHANGES AND REVISIONS

FORM NO. 1000.06A

MECHANICAL MAINTENANCE

REV. # 24

TENDON SURVEILLANCE PROCEDURE  
2407.048 REV. 2

*William W. Gandy # 105*

SAFETY RELATED YES  NO

PAGE	REV	PAGE	REV	PAGE	REV	PAGE	REV	PAGE	REV
1	2	20	2						
2	2	21	2						
3	2	22	2						
4	2	23	2						
5	2	24	2						
6	2	25	2						
7	2	26	2						
8	2	27	2						
9	2	28	2						
10	2	29	2						
11	2	30	2						
12	2	31	2						
13	2	32	2						
14	2	33	2						
15	2	34	2						
16	2	35	2						
17	2	36	2						
18	2								
19	2								

APPROVED BY

*Stephen M. Demery*

APPROVAL DATE

2/17/88

REQUIRED EFFECTIVE DATE:



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	1 of 36		
REVISION	2	DATE	07/12/88
CHANGE		DATE	

## TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE NO.</u>
1.0 PURPOSE.....	2
2.0 SCOPE.....	2
3.0 DESCRIPTION.....	2
4.0 REFERENCES.....	-
5.0 TEST EQUIPMENT, SPECIAL TOOLS, AND SUPPLIES.....	3
6.0 LIMITS AND PRECAUTIONS.....	4
7.0 PREREQUISITES AND INITIAL CONDITIONS.....	4
8.0 INSTRUCTIONS.....	5
9.0 RESTORATION AND CHECKOUT.....	12
10.0 ATTACHMENTS AND FORMS.....	13
10.1 Attachment 1 - Go-No Gauge.....	14
10.2 Attachment 2 - Drawing Index.....	15
10.3 Attachment 3 - Instructions for Replacing Filler Material...	16
10.4 Attachment 4 - Procedure for Laboratory Testing of Sheathing Filler Material.....	19
10.5 Attachment 5 - Data Sheet.....	23
10.6 Attachment 6 - Grease Sample Tool.....	28
10.7 Attachment 7 - Inspection for Water in the Tendon Void, in the Grease Can and Around the Tendon Anchorage.....	29



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 2 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## 1.0 PURPOSE

The purpose of this procedure is to provide the instructions and documentation requirements to assess the continuing quality and structural performance of the Unit 2 Containment post-tensioning system.

## 2.0 SCOPE

2.1 This procedure covers the following:

- 2.1.1 Visual inspection and laboratory testing of the sheathing filler samples from each of the surveillance tendons.
- 2.1.2 Inspection of the anchor assembly of each of the surveillance tendons for deficiencies such as corrosion, cracks, missing wires, or off-size buttonheads.
- 2.1.3 Evaluation of the test and inspection results to assess the general condition of the post-tensioning system and evaluation of time dependent factors such as corrosion.

2.2 This procedure does contain monitoring requirements for assessing conformance with Limiting Conditions for Operation (LCO) of the the Unit 2 Technical Specifications.

2.3 This procedure may be used as a partial procedure in conjunction with an approved corrective action Job Order.

2.3.1 When using this procedure in a partial performance, the sections and the steps to be performed shall be listed below as designated by the Cognizant Supervisor.

N/A

Michael M. Conner  
Cognizant Supervisor

2/15/88  
4/20/88 from 4/20/88  
Date

## 3.0 DESCRIPTION

The tendon surveillance consists of a periodic inspection for the physical condition of a randomly selected group of surveillance tendons. This provides confidence in the condition and functional capability of the system and an opportunity for timely corrective measures should adverse conditions be found. Tendon surveillance testing consists of sheathing filler inspection, anchorage inspection, inspection of anchorage components and vertical repacking and sealing. Twenty-one (21) tendons are to be randomly designated as surveillance tendons during each of the the first three surveillances. The surveillance tendons consist of ten hoop



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

B4 of 37  
NO:  
2402.048

## ARKANSAS NUCLEAR ONE

PAGE	3 of 36		
REVISION	2	DATE	02/12/88
CHANGE		DATE	

tendons, five vertical tendons located at approximately equally spaced intervals, and six dome tendons - two in each of the three groups of the dome tendons as operating conditions allow. The number of surveillance tendons in each of the succeeding surveillance years is nine (9) which consists of three hoop tendons, one from each 240° sector; three vertical tendons; and three dome tendons, one from each group. The recommended surveillance tendons may be varied provided that the selection is based on a random and representative basis and the total number of tendons in each of the different groups to be tested remains unchanged. One tendon in each group (Dome, Vertical, Hoop) shall remain unchanged after the initial selections to develop a history of tendon performance and to correlate the observed data. The tendon numbering system and the tendon locations are defined on the design drawings for the post tensioning system. An index to these drawings are provided in Attachment 2. Drawing C-2608 Sheet 4 through 6 shows the surveillance years, the corresponding surveillance numbers and the recommended surveillance tendons for the life of Unit 2.

### 4.0 REFERENCES

#### 4.1 References used in the preparation of this procedure:

- 4.1.1 CE Memo 83-205 dated 9-22-1983
- 4.1.2 Unit 2 Technical Specifications 3.6.1.1, 3.6.1.5 and 4.6.1.5.
- 4.1.3 Drawing C-2608 Sheets 4, 5 and 6.

#### 4.2 References which are required to be used in conjunction with this procedure.

- 4.2.1 Drawing C-2608 Sheets 4, 5 and 6.

#### 4.3 Regulatory correspondence containing NRC commitments which have been incorporated in this procedure.

- 4.3.1 None

### 5.0 TEST EQUIPMENT, SPECIAL TOOLS, AND SUPPLIES

- 5.1 Grease Sampling Tool
- 5.2 "Go No-Go" Gauge
- 5.3 Thermometer
- 5.4 Viscosity Oil Company Visconorust 2090 P-4.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 4 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## 6.0 LIMITS AND PRECAUTIONS

### 6.1 Limits

- 6.1.1 The Steps in this procedure must be followed in sequence.
- 6.1.2 The Tendon Surveillance may be performed during operation of Unit 2.
- 6.1.3 The Tendon Surveillance shall be performed 1 year, 3 years and 5 years from the date of the structural integrity test (October 17, 1977) and at five year intervals thereafter.
- 6.1.4 The time between removal and replacement of the sheathing filler from the tendon shall NOT exceed 3 weeks; during this period the tendons and anchors shall be protected with Viscosity Oil Company Visconorust 2090 P-4.
- 6.1.5 IF during the performance of this procedure any equipment or component is found to be non-functioning or out of tolerance,  
THEN,  
stop and initiate a RAC.

### 6.2 Precautions

- 6.2.1 Performing the Tendon Surveillance could require working at high elevations - Safety lines and safety belts shall be used.
- 6.2.2 Do not attempt to blow the Filler Material out of the tendons, high pressure air could rupture the tendon sheath.

## 7.0 PREREQUISITES AND INITIAL CONDITIONS

7.1 Verify that areas below the work location that are accessible by other personnel have been posted and barricaded to prevent injury to personnel from dropped objects.

EB 12/20/88

7.2 Record the Tendon Numbers that are to be tested in accordance with Drawing C-2608 Sheets 4, 5 and 6.

Vertical: V9  
V54 \*  
V95

Hoop: 12H18  
31H36  
32H50

Dome: 1D327  
2D219  
3D104

\*V54 FIELD END INACCESSIBLE.  
V56 INSPECTED BOTH ENDS IN LIEU OF EB 2/24/88

EB 12/20/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

36 of 37  
NO:  
2402.048

## ARKANSAS NUCLEAR ONE

PAGE 5 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

7.3 Verify that the Supporting Engineer has been notified that the job is ready to start.

*CS 12/20/88*

### NOTE

Completion of the steps in this procedure should be initial/dated on Attachment 5.

## 8.0 INSTRUCTIONS

### NOTE

The sheathing filler could be found in a liquid, gel or a solid form. Complete removal of the sheathing filler is not required provided that all of the filler that is removed during this surveillance is replaced.

### 8.1 Sheathing Filler Inspection

8.1.1 Record the Tendon Number on Attachment 5.

A. Inspect for water in the tendon void, in the grease can and around the tendon anchorage using the instructions in Attachment 7.

8.1.2 Remove the Tendon Filler Cap from the Tendon.

8.1.3 Record the amount (volume) of sheathing filler material removed on Attachment 5.

8.1.4 Record the Ambient Temperature (T1) on Attachment 5.

### NOTE

Step 8.1.5 applies to vertical tendons only.

8.1.5 Check the level of the filler in the following manner:

### NOTE

Ambient temperature is defined as the containment exterior concrete temperature.

A. Record the Ambient Temperature (T1) on Attachment 5.

B. Add the temperature readings of 2TE-5606-5 and 2TE-5606-6 together and divide by two (2) and record the result as T2 on Attachment 5.

C. Add the temperature (T1) and temperature (T2) together, divide by two (2) and record the result as T3 on Attachment 5.





PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE


NO:  
2402.048

**ARKANSAS NUCLEAR ONE**

PAGE 6 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE


D. Determine what the correct level of the filler material is supposed to be from the chart below.

T3 (°F)	140	130	120	110	100	90	80	60	40
D (inch)	1.5	8.5	12.0	14.5	16.5	18.5	20.0	24.0	28.0



$$T_3 = \frac{(T_1 + T_2)}{2}$$

- T<sub>1</sub> • AMBIENT TEMPERATURE
- T<sub>2</sub> • AVERAGE TEMPERATURE INSIDE CONTAINMENT
- T<sub>3</sub> • AVERAGE TEMPERATURE



D • DISTANCE FROM TOP OF UPPER CAP TO THE SHEATHING FILLER LEVEL.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	7 of 36	
REVISION	2	DATE 02/12/88
CHANGE		DATE

E. Measure the distance (D) from the top of the Tendon Trumpet to the level of the Filler material and record the measurement on Attachment 5.

8.1.6 Compare the color of the filler with new unused filler and record the color comparison on Attachment 5.

A. IF the filler is tan colored,  
THEN obtain a one quart sample of the tan colored grease and place in storage for 24 hours,  
IF NOT,  
THEN mark this step N/A.

B. IF the filler is still tan colored after 24 hours in storage,  
THEN submit the colored sample for testing to the Cognizant Supervisor.

NOTE

It is acceptable to obtain the sample from the top (shop) end of the vertical tendons using the special long handled tool that is shown in Attachment 6. The correct way to use the long handle tool is to first thoroughly clean the tool with Viscosity Number 16 solvent and then push the tool into the grease (filler); pull the tool out and scrape the grease (filler) into the sample container. This operation may be repeated until a full sample is obtained.

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

NOTE

IF a sample was taken for a color comparison THEN taking another one-quart sample for chemical testing is NOT required. It is acceptable to use samples taken for color comparison for the chemical testing.

8.1.7 Obtain a one quart sample of filler from each end on the tendons to be inspected.



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE:	NO:
	TENDON SURVEILLANCE PROCEDURE	2402.048
ARKANSAS NUCLEAR ONE		PAGE 8 of 36
		REVISION 2 DATE 02/12/88
		CHANGE DATE

8.1.8 Label each sample in a manner that shows which tendon and which end of the tendon the sample was taken from.

NOTE

Two samples are taken from each of the tendons that are inspected. One of the samples is submitted for analysis and the other is stored.

- 8.1.9 Submit one of the two one quart samples for chemical testing.
- A. IF the first sample fails the chemical analysis, THEN submit the second sample that was taken from the same tendon for testing, IF NOT, THEN dispose of the second sample.
  - B. IF the second sample fails the chemical analysis THEN initiate a PEAR so that an evaluation can be performed to determine if replacement of the filler material is required.

8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the Stressing Plate and the Buttonheads with Viscosity Number 16 Solvent.

NOTE

Step 8.2.2 is a visual inspection. The Buttonheads are actually the end part of the wire cable that have been formed into the shape of a Button-head. A suspect wire is a missing buttonhead or a loose or raised button head.

- 8.2.2 Inspect the Buttonheads for the following and record the results of this inspection on Attachment 5.
- Broken or missing Buttonheads
  - Shape of the Buttonhead
  - Cracks
  - Corrosion
  - Overall General Appearance.
  - Buttonheads that are not seated tightly in the Stressing Plate



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	9 of 36		
REVISION	2	DATE	02/12/88
CHANGE		DATE	

- A. IF any Buttonheads are found to be missing, THEN strain the grease through a fine mesh screen until the Buttonhead is found.
- B. IF three or more buttonheads are found loose or broken, THEN inspect all the wires (Buttonheads) in one tendon on each side of the tendon that has broken wires.

NOTE

IF both of the tendons adjacent to the deficient tendon show evidence to indicate less than three broken wires per tendon THEN the deficiency should be considered to be unique and acceptable.

- C. IF either OR both of the tendons on either side of the tendon that has broken wires have three or more broken wires, THEN initiate a Plant Engineering Action Request (PEAR) so that an evaluation can be made.

NOTE

Attachment 1 shows a drawing of the Go/No Gage. It is acceptable to fabricate this gage as long as the gage is within the tolerances shown on the drawing.

- 8.2.3 Inspect each Buttonhead using the Go/No-Go Gage and record results on Attachment 5.
- 8.2.4 Inspect the anchor head, shims and the stress plate for corrosion, cracks or evidence of deterioration. Record the results of this inspection on Attachment 5.
- 8.2.5 Apply a coating of Viscosity Oil Company's 2090 P-4 to the tendon end anchorage following the inspection.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 10 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## 8.3 Vertical Tendon Repacking

NOTE

The average Tendon temperature (T3) is the average value of the ambient temperature (T1) and the average temperature inside Unit 2 Containment building (T2) at the time when the sheathing filler is checked, removed or added.

NOTE

Repacking the top and the bottom caps for the vertical tendons may be done using unheated Sheathing filler material providing the amount of material drained off does not exceed 5 gallons for the top cap and 25 gallons for the bottom cap IF the average tendon temperature (T3) does NOT exceed 70°F.

8.3.1 Determine the average temperature (T3) in the following manner:

NOTE

Ambient temperature is defined as the Containment exterior concrete temperature.

- A. Record the Ambient Temperature (T1) on Attachment 5.
- B. Add the temperature readings of 2TE-5606-5 and 2TE-5606-6 together and divide by two (2) and record the result as T2 on Attachment 5.
- C. Add the temperature (T1) and temperature (T2) together, divide by two (2) and record the result as T3 on Attachment 5.

NOTE

The correct sheathing filler material to use to refill the tendons is Viscosity Oil Company's Visconorust 2090-P.

CAUTION

• Using heated filler material with a temperature less than 120° or higher than 240° could damage the sheath.

### 8.3.2 Repacking Sheathing Filler Material

- A. IF the Sheathing Filler material that was removed is less than 5 gallons for the top cap and less than 25 gallons for the bottom cap and the average temperature (T3) is less than 70°F, THEN Repack the Top and the Bottom caps with unheated sheathing Filler material, IF NOT, THEN mark this step N/A.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:

TENDON SURVEILLANCE PROCEDURE

NO:

2402.048

# ARKANSAS NUCLEAR ONE

PAGE	11 of 36
REVISION	2 DATE 02/12/88
CHANGE	DATE

- B. IF the average temperature (T3) exceeds 70°F and/or the amount of the Filler Material drained from the Bottom Cap exceeds 25 gallons, THEN repack the tendon using heated Filler Material  
IF NOT,  
THEN mark this step N/A.
- C. IF the Sheathing Filler material was repacked with heated filler material THEN record the temperature of the filler material at the pump,  
IF NOT,  
THEN mark this step N/A.
- D. Install the Filler Cap.

## 8.4 Dome and Hoop Repacking

### NOTE

The correct sheathing filler material to use to refill the tendons is Viscosity Oil Company's Visconorust 2090-P.

### CAUTION

- Using heated filler material with a temperature less than 120° or higher than 240° could damage the sheath.

- 8.4.1 Pump heated filler material through the hose until all old filler material has been purged from the hose.
- 8.4.2 Attach the hose to the shop or field end of the hoop or dome tendon.
- 8.4.3 Verify that all valves, vents and drains for the tendon are open.

### NOTE

If less than 5 gallons of filler material has been removed from each filler end, Then it is acceptable to replace the filler material by pumping or pouring into each end provided that each end is vented to bleed out air.

- 8.4.4 Pump heated filler material (120°F to 240°F) into the tendon until at least five gallons of filler material without air bubbles or foreign material is visible in the filler material.
- 8.4.5 Record the filler material temperature at the pump on Attachment 5.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	12 of 36	
REVISION	2	DATE 02/12/88
CHANGE		DATE

- 8.4.6 Record the filler material installation pressure on Attachment 5.
- 8.4.7 Record the Ambient Temperature (T1) on Attachment 5.
- 8.4.8 Record the date that the filler cap was installed on Attachment 5.

## 8.5 Tendon Resealing

.....

CAUTION

.....

Only new unused gaskets, washers, gasket sealant and o-rings may be used.

.....

- 8.5.1 Install the tendon filler cap.
  - A. Torque the vertical tendon bottom caps to 160 ft-lbs in 40 ft-lbs increments in a criss cross pattern.
  - B. Torque the top vertical tendons caps and all other filler caps to 50 ft-lbs (two passes at 50 ft-lbs) in criss cross pattern.

NOTE

Step 8.5.2 is to be performed at least 24 hours after the completion of step 8.5.1.

- 8.5.2 Check the torque value by torquing the filler caps to 160 ft-lbs for vertical tendon bottom caps and 50 ft-lbs for all other tendon filler caps.

## 9.0 RESTORATION AND CHECKOUT

- 9.1 Verify that all tools and equipment have been returned to their proper storage location.
- 9.2 Submit copies of Attachment 5 (for each tendon) to ANO Plant engineering so that a comparison with the original stressing record and/or the previous surveillances to determine the following:
  - 9.2.1 Additional wires have been broken since the last inspection.
  - 9.2.2 A change in corrosion status of the sheathing filler material has occurred.
- 9.3 Verify that the Unit 2 Operations Shift Supervisor has been notified that the job is complete.

02/14/20/88

02/14/20/88

02/14/20/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	13 of 36	
REVISION	2	DATE 02/12/88
CHANGE		DATE

## 10.0 ATTACHMENTS AND FORMS

- 10.1 Attachment 1 - Go-No Gauge
- 10.2 Attachment 2 - Drawing Index
- 10.3 Attachment 3 - Instructions for Replacing Filler Material
- 10.4 Attachment 4 - Procedure for Laboratory Testing of Sheathing Filler Material
- 10.5 Attachment 5 - Data Sheet
- 10.6 Attachment 6 - Grease Sample Tool
- 10.7 Attachment 7 - Inspection for Water in the Tendon Void, in the Grease Can and around the Tendon Anchorage



B15 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE


PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	14 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

## ATTACHMENT 1 GO/NO-GO GAUGE



### NOTES:

1. Holes shall be sized after heat treating.
2. Hole diameter shall be certified prior to all tendon surveillance by using calibrated equipment.
3. Each gage shall have an identifying number.
4. Hole diameter shall be certified at the completion of tendon surveillance using calibrated equipment.

016 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	15 of 36	
REVISION	2	DATE 02/12/88
CHANGE		DATE

## ATTACHMENT 2

## DRAWING INDEX

The following drawings describe the elements of the post-tensioning system relevant to the tendon surveillance. These drawings are available from the Arkansas Power & Light Company.

<u>Preson Drawing Number</u>	<u>Drawing Description</u>
2A04, 2A05, 2A06	Anchor Details
2A07	Tendon washer and shims details
2A08	Deadend plate-bottom vertical
2PH02, 2PH03, 2PH04 2PH06, 2PH07, 2PH08	Horizontal tendon numbering system and tendon locations
2DPO4, 2DPO5, 2DPO6 2DPO7, 2DPO8	Dome tendon numbering system and tendon locations
2PV11 2PV29	Vertical tendon number system and tendon locations

<u>Bechtel Drawing</u>	<u>Drawing Description</u>
A2200	Reactor Building Developed Elevation and details



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	16 of 36
REVISION	2 DATE 02/12/88
CHANGE	DATE

## ATTACHMENT 3

### Instructions For Replacing Filler Material

1.0 Record the Tendon Number \_\_\_\_\_ /

.....

CAUTION

• The temperature of the heated sheathing material should be between 190°F and 300°F.

.....

.....

CAUTION

• It is advisable to pump the sheathing filler material into the bottom of vertical tendons to prevent trapping air in the sheath.

.....

2.0 Pump heated (temperature between 190°F and 300°F) sheathing filler material into the tendon until at least five gallons of filler material without any air bubbles or visible foreign material comes out of the outlet farthest from the pump. \_\_\_\_\_ /

NOTE

The vertical tendon bottom filler caps are to be torqued to 160 ft-lbs in 40 ft-lbs increments using a criss cross pattern. The other filler caps are to be torqued to 50 ft-lbs using a criss cross pattern. Only new gaskets, washers, gasket sealant and o-rings shall be used.

3.0 Torque the filler caps to the desired torque value.  
Torque wrench used \_\_\_\_\_ /

NOTE

The following steps are for vertical tendons only and are to be performed 24 hours after step 3.0 has been completed.

4.0 Remove the top filler cap. \_\_\_\_\_ /

5.0 Check the level of the filler material in the following manner:

5.1 Determine the Average Temperature (T3) in the following manner:

NOTE

Ambient temperature is defined as the Containment exterior concrete temperature.

5.1.1 Record the Ambient Temperature \_\_\_\_\_ °F (T1) \_\_\_\_\_ /



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

**ARKANSAS NUCLEAR ONE**

PAGE 17 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE


ATTACHMENT 3

Instructions For Replacing Filler Material

- 5.1.2 Record the Temperature Readings of  
2TE-5605-5 \_\_\_\_\_ °F, and  
2TE-5606-6 \_\_\_\_\_ °F /
- 5.1.3 Add the two temperature readings  
taken in step 5.1.2 and divide by  
2 and record the result:  
\_\_\_\_\_ °F (T2) /
- 5.1.4 Add T1 (from step 5.1.1) and  
T2 (from step 5.1.3) and divide  
by 2 and record the result  
\_\_\_\_\_ °F (T3) /


5.2 Determine the desired Sheathing filler level  
from the following chart:

T3 (°F)	140	130	120	110	100	90	80	60	40
D (inch)	1.5	8.5	12.0	14.5	16.5	18.5	20.0	24.0	28.0



$$T_3 = \frac{T_1 + T_2}{2}$$

- T<sub>1</sub> = AMBIENT TEMPERATURE
- T<sub>2</sub> = AVERAGE TEMPERATURE INSIDE CONTAINMENT
- T<sub>3</sub> = AVERAGE TEMPERATURE





PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	18 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

## ATTACHMENT 3

### Instructions For Replacing Filler Material

Page 3 of 3

5.3 Measure the actual level of the sheathing filler in the tendon and record \_\_\_\_\_"

\_\_\_\_\_ /

5.4 IF the level is not within 1.5" of the desired level  
THEN adjust as required (add or remove filler material) until the level is correct,  
IF the level is within 1.5" of the correct level,  
THEN mark this step N/A.

\_\_\_\_\_ /

NOTE

The vertical tendon bottom filler caps are to be torqued to 160 ft-lbs in 40 ft-lbs increments using a criss cross pattern. Only new gaskets, washers, gasket sealant and o-rings may be used.

5.5 Install the filler cap.

\_\_\_\_\_ /

5.6 Torque the filler caps to the desired torque value.  
Torque wrench used \_\_\_\_\_

\_\_\_\_\_ /



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	19 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

## ATTACHMENT 4

### PROCEDURE FOR LABORATORY TESTING OF THE SHEATHING FILLER MATERIAL

#### NOTE

The instructions in this Attachment are to be performed by the testing laboratory. The following is a list of tests and the acceptance criteria for each of the tests.

TEST	LIMITS
Water Soluble Chloride	Less than 10.0 ppm
Water Soluble Nitrates	Less than 10.0 ppm
Water Soluble Sulfides	Less than 10.0 ppm
Water content	Less than 10% Dry Weight
Neutralization Number (Reserve Alkalinity)	The base number shall be at least 50% of the as installed value, unless the as installed value is 5 or less, in which case the base number shall be no less than zero. If the tendon duct is filled with a mixture of materials having various as installed base numbers, the lowest number shall govern acceptance .

#### 1.0 PURPOSE

This Attachment provides the instructions and documentation requirements to be used by the test laboratory for testing The Sheathing Filler material used in Arkansas Nuclear One Unit 2 Containment Building Tendons.

#### 2.0 SCOPE

2.1 The one-quart samples are to be tested for the following:

- 2.1.1 The amount of water soluble chlorides, nitrates, and sulfides which are leached from a given contact area between water and the sheathing filler under standard conditions.
- 2.1.2 The water content of the Sheathing Filler Material.
- 2.1.3 The reserve alkalinity of the sheathing filler material.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	20 of 36
REVISION	2      DATE 02/12/08
CHANGE	DATE

## ATTACHMENT 4

### PROCEDURE FOR LABORATORY TESTING OF THE SHEATHING FILLER MATERIAL

2.1.4 This document does not relieve the testing laboratory of responsibility for conducting the necessary laboratory tests in a manner consistent with industry standards.

#### 3.0 REFERENCES

- 3.1 Chlorides (Cl) by ASTM D-512.
- 3.2 Nitrate (NO3) by ASTM-992 Brucine Method or Cadmium Reduction Method.
- 3.3 Sulfides (S) by APHA (American Public Health Association) Standard Method - Methylene Blue

#### 4.0 INSTRUCTIONS

NOTE

Water Soluble Chlorides should be less than 10.0 ppm. Water Soluble Nitrates should be less than 10.0 ppm. Water Soluble Sulfides shall be less than 10.0 ppm.

#### 4.1 Water Soluble Impurities

- 4.1.1 A Water extraction of each sample of filler material shall be made and tested as follows:
- A. Use a Spatula coat the inside (bottom and sides) of a 1-liter glass beaker with a 1/4" layer of sheathing filler.
  - B. Fill the beaker with room temperature distilled water.

CAUTION

While performing the next step do NOT heat on a hot plate; INSTEAD use an oven or an immersion heater so that the water will remain clear for the tests.

- C. Heat the water to a controlled temperature of 100°F and maintain for four hours.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:

TENDON SURVEILLANCE PROCEDURE

NU:

2402.048

# ARKANSAS NUCLEAR ONE

PAGE	21 of 36
REVISION	2 DATE 02/12/88
CHANGE	DATE

## ATTACHMENT 4

### PROCEDURE FOR LABORATORY TESTING OF THE SHEATHING FILLER MATERIAL

- D. Run a blank on the distilled water.
  - 1. IF titrated, THEN use a microburet, 1 ml or 5 ml with 0.01 - 0.05 ml graduation intervals.
  
- E. Decant the water and analyze for soluble ions. Test only for salts in leached water. The water analysis shall be as follows:
  - 1. Chlorides (Cl) by ASTM D-512.
  - 2. Nitrate (NO3) by ASTM D-992 Brucine Method or Cadmium Reduction Method.
  - 3. Sulfides (S) by APHA (American Public Health Association) Standard Method - Methylene Blue.

NOTE

The water content shall be less than 10% dry weight.

#### 4.2 Water Content

- 4.2.1 Determine the water content in accordance with ASTM-D95.

NOTE

Neutralization Number (Reserve Alkalinity). The base number should be at least 50% of the as installed value, unless the as installed value is 5 or less, in which case the base number should be no less than zero. IF the tendon duct is filled with a mixture of materials having various as installed base numbers THEN the lowest number will govern acceptance. This number is determined for information purposes only.

#### 4.3 Neutralization Number

NOTE

The Neutralization number is to be determined in accordance with ASTM D-974 (modified).

- 4.3.1 Heat a 10 gram sample, 10 ml isopropyl alcohol, and 5 ml toluene until the sample is solubilized.
- 4.3.2 Add 90 ml distilled water, 20 ml 1N sulfuric acid and place in a steam bath for 1/2 hour. Stir well.



B23 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	22 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

## ATTACHMENT 4

Page 4 of 4

### PROCEDURE FOR LABORATORY TESTING OF THE SHEATHING FILLER MATERIAL

- 4.3.3 Add 1% phenolphthalein indicator and titrate with 1N sodium hydroxide.
- 4.3.4 Calculate the base number (mg KOH perg):  

$$\frac{[(20) (\text{acid normality}) - (\text{ml base})(\text{base normality})]}{56/\text{g of sample}}$$

### 5.0 Report

- 5.1 Submit two copies of the report of the sheathing filler material to Arkansas Power and Light.
- 5.2 The Report shall contain the following:
  - 5.2.1 Sample Identification Number.
  - 5.2.2 Concentration of water soluble chlorides, nitrates, and sulfides with an accuracy of 0.1 ppm.
  - 5.2.3 Concentration of water (H2O) with an accuracy of 0.1 percent of the dry weight of the filler material.
  - 5.2.4 Neutralization number with an accuracy of 0.01 mg reagent per gram of filler material.

8.24 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

8.1.1 Tendon Number \_\_\_\_\_ /

8.1.2 Remove the Tendon Filler Cap.  
Field End \_\_\_\_\_ /  
Shop End \_\_\_\_\_ /

8.1.3 Volume of Sheathing Filler Removed: \_\_\_\_\_ gal. /

8.1.4 Ambient Air Temperature (T1): \_\_\_\_\_ °F /

8.1.5 Filler Material Level (Vertical Tendons)

A. Ambient Temperature (T1) \_\_\_\_\_ °F. /

B. Inside Containment Temperature (T2)  
\_\_\_\_\_ °F. /

C. Average Temperature (T3) \_\_\_\_\_ °F. /

D. Desired Filler Material Level  
\_\_\_\_\_ " /

E. Actual Filler Material Level \_\_\_\_\_ " /

### 8.1.6 Color Comparison

A. Tan Colored? Yes \_\_\_\_\_ No \_\_\_\_\_ /

B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A \_\_\_\_\_ /

Sample Submitted because of Tan Colored  
Filler Material. Yes \_\_\_\_\_ No \_\_\_\_\_ /

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.  
Shop End \_\_\_\_\_ /  
Field End \_\_\_\_\_ /

\_\_\_\_\_  
Independent Verifier Date

B25 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	24 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) \_\_\_\_\_

A. Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_ /

B. Second Sample Submitted:

Yes \_\_\_\_\_ No \_\_\_\_\_

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A \_\_\_\_\_

Filler Material Require Replacement?

Yes \_\_\_\_\_ No \_\_\_\_\_ /

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads

Amount Removed (Gal.) \_\_\_\_\_ /



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 25 of 36  
REVISION 2 DATE 02/16/88  
CHANGE DATE


## ATTACHMENT 5 DATA SHEET

ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. \_\_\_\_\_  
LOCATION \_\_\_\_\_

### 8.2.2 Buttonhead Inspection

PERFORMED BY	_____
APPROVED BY	_____
DATE	_____
FILLER COVERAGE	_____
CAP	_____
BUTTONHEADS	_____
ANCHOR END	_____
SHIMS	_____
BEARING PLATE	_____
CORROSION LEVEL	_____
BUTTONHEADS	_____
ANCHOR END	_____
SHIMS	_____
BEARING PLATE	_____



LEGEND FOR CORROSION LEVEL  
 #1 BRIGHT METAL, NO VISIBLE OXIDATION  
 #2 REDDISH BROWN - NO PITTING  
 #3 0 < PITTING < .003"  
 #4 .003" < PITTING < .006"  
 #5 .006" < PITTING < .010"

NOTE  
 THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - ◐ WIRE REMOVED PREVIOUSLY
  - ◑ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE


PAGE	26	of	36
REVISION	2	DATE	02/12/88
CHANGE		DATE	

## ATTACHMENT 5 DATA SHEET

ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. \_\_\_\_\_  
LOCATION \_\_\_\_\_

BY _____	
DATE _____	
APPROVED BY _____	
DATE _____	
FILLER COVERAGE	
CAP _____	
BUTTONHEADS _____	
ANCHOR HEAD _____	
SHIMS _____	
BEARING PLATE _____	
CORROSION LEVEL	
BUTTONHEADS _____	
ANCHOR HEAD _____	
SHIMS _____	
BEARING PLATE _____	



LEGEND FOR CORROSION LEVEL  
 #1 BRIGHT METAL, NO VISIBLE OXIDATION  
 #2 REDDISH BROWN - NO PITTING  
 #3 0 < PITTING < .003"  
 #4 .003" < PITTING < .006"  
 #5 .006" < PITTING < .010"

NOTE  
 THE LOCATION OF THE ANCHOR HEAD PK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - WIRE REMOVED PREVIOUSLY
  - DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

- 8.3 Vertical Tendon Repacking
  - 8.3.1 Average Temperature (T3)
    - A. Ambient Temperature (T1) \_\_\_\_\_ °F. /
    - B. Containment Temperature (T2) \_\_\_\_\_ °F. /
    - C. Average Temperature (T3) \_\_\_\_\_ °F. /
  - 8.3.2 Tendon repacked with heated Filler material?
    - Yes \_\_\_\_\_ No \_\_\_\_\_ /
    - Amount of filler material repacked into tendon (Gal) \_\_\_\_\_ /
    - Filler Temperature at the Pump \_\_\_\_\_ °F. /
    - Filler Cap Installed. /
- 8.4 Dome and Hoop Repacking
  - 8.4.1 Purge pumping hose of old filler material. /
  - 8.4.2 Attach pumping unit hose to tendon. /
  - 8.4.3 verify that all valves, vents and drains are open. /
  - 8.4.4 Amount of Filler material repacked into tendon. \_\_\_\_\_ (gal) /
  - 8.4.5 Filler Temperature at the pump \_\_\_\_\_ °F /
  - 8.4.6 Filler Installation Pressure \_\_\_\_\_ psi /
  - 8.4.7 Ambient Temperature (T1) \_\_\_\_\_ °F /
  - 8.4.8 Date Filler Cap Installed \_\_\_\_\_ /
- 8.5 Tendon Resealing
  - 8.5.1 Install the filler caps.
    - Final torque value of the tendon filler caps: \_\_\_\_\_ Ft-lbs
    - \_\_\_\_\_ Ft-lbs
    - Torque Wrench used \_\_\_\_\_ /
  - 8.5.2 Tendon filler cap retorqued after 24 hours.
    - Final Torque Value: \_\_\_\_\_ ft-lbs
    - \_\_\_\_\_ ft-lbs
    - Torque Wrench used \_\_\_\_\_ /

B29 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE


NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	28	OF	36
REVISION	2	DATE	02/12/88
CHANGE		DATE	

## ATTACHMENT 6

### GREASE SAMPLE TOOL



#### NOTES:

1. MATERIAL AND FABRICATION TO BE NON-Q.
2. ROD ENDS TO HAVE A SMOOTH FINISH.

B30 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	29 of 36		
REVISION	2	DATE	02/12/88
CHANGE		DATE	

ATTACHMENT 7

Page 1 of 8

INSPECTION FOR WATER IN THE TENDON VOID,  
IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
January 1, 1988  
Page 1 of 7  
REVISION 0

ARKANSAS POWER & LIGHT CO.  
ARKANSAS NUCLEAR ONE  
UNITS 1 & 2

PRECISION SURVEILLANCE CORPORATION  
IN-SERVICE INSPECTION  
QUALITY CONTROL PROCEDURE

INSPECTION FOR WATER IN THE TENDON VOID, IN THE  
GREASE CAN AND AROUND THE TENDON ANCHORAGE

Prepared by H. F. [Signature] Title ASR, R.A. Date 1-15-88  
 Approved by [Signature] Title MR, R.A. Date 1-15-88  
 Approved by [Signature] Title Mgt, Eng Date 1-15-88





PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 30 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

Page 2 of 8

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHCRAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
January 15, 1988  
Page 2 of 7

#### 1. PURPOSE

This procedure will establish the requirements for performing an inspection of the Post-Tensioning Tendon System for evidence of water during the scheduled In-Service Inspection of the Tendon System of Arkansas Power & Light Company's Arkansas Nuclear One - Units 1 and 2.

#### 2. SCOPE

This procedure will be limited to performing and documenting the inspection for water from the tendon void or around the tendon anchorage assembly, including the grease can. This inspection shall be performed just prior to removal of the grease can and during the physical inspection of the tendon anchorage assembly.

#### 3. RESPONSIBILITY

As stated in PSC Procedure QA 4.0.

#### 4. QUALIFICATION

As stated in PSC Procedure QA 4.1.

#### 5. EQUIPMENT

No special equipment is required. It is expected that this inspection take place as part of the procedure for the removal of grease can.

##### 5. 1. QUALITY CONTROL EQUIPMENT

5. 1. 1. Suitable quantities of clean, unused non-metallic containers for obtaining water samples.
5. 1. 2. Clean unused rags or wipers.
5. 1. 3. Indelible permanent marking devices and/or labels for the sample containers.
5. 1. 4. Flashlights and batteries.
5. 1. 5. Pens, Markers, Data Sheets.

sq6-1.ano

B32 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	31 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

## ATTACHMENT 7

Page 3 of 8

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
January 15, 1988  
Page 3 of 7

#### 6. PRECAUTIONS

Review the Safety Comments provided in the Surveillance Program Quality Control Manual for the following items that shall apply both for tendon force control and personnel safety.

6. 1. Section 3.1: Tendon Wire Breaking Strength
6. 2. Section 3.2.1: Personnel Safety
6. 3. Section 3.5: Construction Safety: Personnel Safety
6. 4. A tendon grease can weighs in excess of 100 pounds and may contain about 100 pounds of grease. Be prepared to support this weight when the grease can is unbolted and removed.
6. 5. The sheathing filler, grease, may be in liquid, gel or solid form. Tendons in the area of steam or feed penetrations in operating plants, may contain hot grease and some caution should be exercised. It is not necessary to drain all the grease from a tendon void and is to be avoided, if possible.
6. 6. CAUTION - NEVER STRIKE THE BUTTONHEADS, THE WIRES, OR THE ANCHORHEADS OF A STRESSED TENDON WITH A HAMMER OR ANY OTHER OBJECT.
6. 7. Have sufficient quantities or sizes of containers on hand to catch the grease, as it may fall from the tendon void anchorages or grease can.
6. 8. IF AT ANY TIME A CRACKED OR BROKEN ANCHORHEAD IS DETECTED AS A RESULT OF THESE INSPECTIONS, ALL WORK SHALL STOP. ALL PERSONNEL SHALL BE MOVED AWAY FROM THAT AREA. THE PSC CONSTRUCTION SUPERVISOR SHALL BE NOTIFIED. THE WORK AND/OR INSPECTIONS SHALL CONTINUE AFTER A SAFETY EVALUATION HAS BEEN MADE AND ONLY AT THE DIRECTION AND CONTROL OF THE PSC CONSTRUCTION SUPERVISOR AND THE RESPONSIBLE ENGINEER REPRESENTING ARKANSAS POWER & LIGHT COMPANY DURING THE ARKANSAS NUCLEAR ONE IN-SERVICE-INSPECTION.



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE:	NO:
	TENDON SURVEILLANCE PROCEDURE	2402.048
ARKANSAS NUCLEAR ONE	PAGE	32 of 36
	REVISION	2 DATE 02/12/88
	CHANGE	DATE

ATTACHMENT 7

INSPECTION FOR WATER IN THE TENDON VOID,  
IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
January 18, 1988  
Page 4 of 7

7. QUALITY CONTROL

There are no hold points for this operation. Quality Control Inspectors shall perform the inspections that are described in this procedure and document those results on Data Sheet 6.1.

- 7. 1. The Quality Control Inspector shall be responsible for properly identifying any water samples that may have been collected. The inspector shall also be responsible for controlling those samples until they are turned over to the Owner or his agent or sent out for testing.

8. PREREQUISITES

- 8. 1. CCD- Document the tendon identification, tendon end, buttress number, unit number and other information on Data Sheet 6.1.
- 8. 2. Provide support for the Grease Can. Be prepared to catch any grease that may fall during loosening and removal.
- 8. 3. Care shall be exercised to avoid splashing or spilling grease on concrete and other surfaces. Spilled grease shall be removed and cleaned using Viscosity Oil, Viscor #16 industrial solvent or equivalent. It may be advantageous to tape plastic sheeting around the bearing plate and concrete to lessen the effect of spilled grease.
- 8. 4. This inspection will be performed as a prelude to the removal of the grease can. It is expected that all the tools and preparation for the removal of the grease can will be in place or have been performed. As the main purpose of this procedure is to detect the presence of water in the tendon void, the Inspector shall be afforded access to the tendon during loosening of the grease can bolts to see if water is in evidence.

834 of 37



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
3402.048

# ARKANSAS NUCLEAR ONE

PAGE	33 of 36
REVISION	2 DATE 02/12/88
CHANGE	DATE

## ATTACHMENT 7

Page 5 of 8

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
January 15, 1988  
Page 5 of 7

#### 9. GREASE CAN REMOVAL

If upon removal of the grease can, it is determined that the anchorhead is broken, all work shall stop on that tendon and all personnel shall leave the area of the tendon. The PSC Construction Supervisor and the Responsible Engineer of the Owner or his agent shall determine the seriousness of this event and evaluate the feasibility and safeness of continuing operations in that tendon.

9. 1. Position platform, as required, at the end of the tendon to be inspected. (As part of Grease Can Removal Procedure)
9. 2. Place a container and/or a protective cover under the tendon grease can to protect adjacent areas from dripping grease.
9. 3. Have a clean dry plastic container available for catching water samples.
9. 4. As the main purpose of this procedure is to determine the presence of water in the grease can or around the anchorhead, the Inspector shall be alert to obtain samples of that water as the can is loosened and removed and to estimate the quantity detected.
9. 4. 1. QCD- Document the quantity of water detected and if a sample was collected.
9. 5. Remove the bolts holding the grease can to the bearing plate. The grease can must be fully supported as the bolts are being removed. Care should be taken when removing the end cap since the bulk filler may drop off or drip as a liquid of medium viscosity. Allow the Inspector the opportunity to obtain water samples, if any water is present.
9. 6. CAUTION - BE PREPARED TO SUPPORT THE GREASE CAN. IT MAY WEIGH UP TO 100 POUNDS.
9. 7. Carefully remove the grease can to avoid spilling the contents. The Inspector shall inspect the interior of the can for the presence of water and if possible collect a sample of that water.

B35 of 31



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:

TENDON SURVEILLANCE PROCEDURE

NO:

2402.048

# ARKANSAS NUCLEAR ONE

PAGE 34 of 36

REVISION 2 DATE 02/12/88

CHANGE DATE

## ATTACHMENT 7

Page 6 of 8

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SR 6.1  
INSPECT FOR WATER  
January 15, 1988  
Page 6 of 7

- 9. 7. 1. QCD- Document the quantity of water detected and if a sample was collected.
- 9. 8. Inspect the tendon anchorage assembly, shims, bearing plate, anchorhead and buttonheads for the presence of water.
- 9. 8. 1. QCD- Document the quantity of water detected and if a sample was collected.
- 9. 9. Work shall continue for the In-Service Inspection as regularly scheduled or as required by the Procedures in the Surveillance Program Quality Control Manual.
- 9. 10. The next point that water could be encountered would be during or just after Detensioning the Tendon. Therefore, the Inspector shall be especially vigilant during his portion of the In-Service Inspection to detect the presence of water. Inspect for the presence of water during or after Detensioning the Tendon.
- 9. 10. 1. QCD- Document the quantity of water detected and if a sample was collected.

#### 10. DISTINGUISHING CHARACTERISTICS

The quantity of water observed in or on the tendon during the In-Service Inspection is important from the standpoint of the Corrective Action which could be required by the Owner or his agent. The quantity could vary from condensation, wetness without running off, to that condition where water pours out from the tendon void. The following terms will be used to describe the condition of moisture that will be reported to the Owner or his agent.

#### 10. 1. OBSERVABLE MOISTURE

"Observable Moisture" is defined as that quantity of water which has been immediately observed by the Inspector to be concentrated, collected or draining out from the grease can or tendon anchorage assembly. While this is intended to describe that moisture condition associated with condensation, it could be present in quantities of less than 8 ounces.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	35 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 4.1  
INSPECT FOR WATER  
January 15, 1988  
Page 7 of 7

10. 2. SIGNIFICANT MOISTURE

"Significant Moisture" is defined to be a quantity of water 1/2 pint (8 ounces) or more which has collected, concentrated or observed to be draining out of the tendon anchorage assembly or grease can. This quantity is considered to be from a condition other than water formed through condensation.

11. NOTIFICATION

The Owner or his agent shall be formally notified when water, regardless of quantity, has been detected during the In-Service Inspection. This Notification shall define the condition detected referencing Section 10 of this Procedure and the specific quantity detected.

- 11. 1. The Owner or his agent shall be responsible for any corrective action and/or Notification of the NRC should that be required.
- 11. 2. The work and inspection shall continue until completed or formal notification by the Owner or his agent halt the work at some agreed on point.

12. SAMPLE RETENTION/TESTING

The samples may be temporarily retained by the PSC Quality Control Inspector until such time that the method of testing can be determined or the samples are turned over to the Owner or his agent.

- 12. 1. QCD- Verify that the water samples are adequately identified.
- 12. 2. QCD- Document the location of storage for the samples.

13. DOCUMENTATION

The items in this procedure requiring documentation shall be documented on Data Sheet 6.1.

- 13. 1. The Data Sheet references the applicable section number of the procedure for each QCD Point.

14. ATTACHMENTS

- 14. 1. Data Sheet 6.1.

sq6-1.ano



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

Page 8 of 8

INSPECTION FOR WATER IN THE TENDON  
IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: \_\_\_\_\_ DATE: \_\_\_\_\_  
TENDON NO.: \_\_\_\_\_ TENDON END/BUTTRESS NO.: \_\_\_\_\_ SURVEILLANCE \_\_\_\_\_  
OTHER TENDON END LOCATION INFO \_\_\_\_\_

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED Yes No DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No

(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff \_\_\_\_\_ Level \_\_\_\_\_ Date \_\_\_\_\_

QC Review \_\_\_\_\_ Level \_\_\_\_\_ Date \_\_\_\_\_

Title \_\_\_\_\_

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

APPENDIX C - Sheathing Filler  
Analysis Reports



# SUBURBAN LABORATORIES, Inc.

C 1 of 1

4140 LITT DRIVE

HILLSIDE, ILLINOIS 60162 1183

EARL I ROSENBERG  
President

April 13, 1988

H.R. THOMAS, JR.  
Director

Precision Surveillance Corporation  
3468 Tatling Street  
East Chicago, Indiana 46312

Attention: Mr. Harry F. Hendrickson,  
Manager, Quality Assurance

Re: P.O. #536

**APPROVED** PSC

QUALITY SECTION

BY H.F. Hendrickson

DATE 4-18-88

Samples Received: <u>3/16/88</u>	(ppm) <u>Chloride*</u>	(%) <u>Water Content</u>	Neutralization Number (mg/KOH/g)	(ppm) <u>Nitrate*</u>	(ppm) <u>Sulfide*</u>
<u>ANO-UNIT # 2 #4/1/88</u> <u>Grease Samples</u>					
S/L #8-2570 - V 95 - Gallery - Field End	0.603	0.54	27.79	< 0.05	0.012
S/L #8-2571 - V 9 - Gallery - Field End	0.515	0.19	28.71	< 0.05	0.013
S/L #8-2572 - V 56 - Top - Shop End	0.456	0.20	2.62	0.05	0.014
S/L #8-2573 - 12H 18 - Buttress 1 - Shop End	0.162	0.14	42.76	< 0.05	0.037
S/L #8-2574 - 31H 36 - Buttress <del>1</del> Field End <i>N.S. 4/1/88</i>	0.132	0.92	41.55	< 0.05	0.003
S/L #8-2575 - 32H 50 - Buttress <del>2</del> Field End <i>N.S. 4/1/88</i>	0.074	0.10	40.65	< 0.05	0.012
S/L #8-2576 - 1D 327 - Field End	0.191	0.32	45.45	< 0.05	< 0.001
S/L #8-2577 - 2D 219 - Shop End	0.132	0.25	43.95	< 0.05	< 0.001
S/L #8-2578 - 3D 104 - Shop End	0.074	0.22	40.77	< 0.05	0.003

ANALYSIS CERTIFIED BY: \_\_\_\_\_

\_\_\_\_\_, Director (HRT/ak)

\*Water Soluble

Moisture / Method: ASTM D-95

Chlorides / Method: ASTM D-512

Sulfides / Method: APHA-427C

Nitrates / Method: ASTM-992

Neutralization # / Method: ASTM-974 (N=0.110)

Members of American Society of Mass Spectrometry

American Chemical Society • American Society for Microbiology

Water Pollution Control Federation • Institute of Food Technology

Certifications: U.S.D.A. #1783 • Ill. Dept. of Public Health #17135 • Amer. Spice Trade Assn. • F.D.A. Reg. #1419676 • Ill. EPA #100225

Wis. DNR #999318210

FAX Available

*N.S. 4/1/88*

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

APPENDIX D - Tendon Surveillance  
Data Sheets



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO DATE: 2/20/88  
TENDON NO.: V9 TENDON END/BUTTRESS NO.: Shop end SURVEILLANCE 4<sup>th</sup>  
OTHER TENDON END LOCATION INFO: N/A (Top)

(9.4) DURING LOOSENING OF GREASE CAN

(9.4.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.7) IN GREASE CAN

(9.7.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.8) AROUND TENDON ANCHORAGE

(9.8.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.10) DURING DETENSIONING

(9.10.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(11.) OWNER/AGENT NOTIFIED Yes  No  DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No  N/A

(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. Lead Level II Date 2/20/88

QC Review Shroeder Level III Date 3/22/88  
Title MGR, Q.C.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V9 ML 12/20/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End  
Shop End Top side N/A  
ML 12/20/88
- 8.1.3 Volume of Sheathing Filler Removed: 1/4 gal. ML 12/20/88
- 8.1.4 Ambient Air Temperature (T1): 54 °F ML 12/20/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) 50 °F. ML 12/20/88
  - B. Inside Containment Temperature (T2)  
2TE5605-5 78.7°F 78.7 °F. ML 12/20/88
  - 2TE5606-6 78.7°F
  - C. Average Temperature (T3) 64.4 °F. ML 12/20/88
  - D. Desired Filler Material Level  
Approx. 23 ". ML 12/20/88
  - E. Actual Filler Material Level 21.4 ". ML 12/20/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No  ML 12/20/88
  - B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A  ML 12/20/88
  - Sample Submitted because of Tan Colored  
Filler Material. Yes \_\_\_\_\_ No  ML 12/20/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
Shop End Top side  
Field End ML 12/20/88  
N/A

CM 12/23/88  
Independent Verifier Date



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V9 Shop End

## ATTACHMENT 5 DATA SHEET

Sample Submitted for Testing :  
(Shop or Field end) EB 3/10/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

EB 4/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?

Yes \_\_\_\_\_ No X

EB 4/19/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 1/20/88

A thin coat of 2090 P-4 applied  
to buttonheads, anchorhead and shims  
(1/4 gal)

ML 2/20/88

torque to 50 ft-#  
with TW-321.

ML 2/20/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 5  
DATA SHEET

Page 4 of 5

10<sup>th</sup> Y-5r ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH


TENDON NO. V9  
LOCATION Shop End (Cap)

BY *M. L. G.*  
DATE 2/20/88  
APPROVED BY *[Signature]*  
DATE 3/22/88

PC 230-27

FILLER COVERAGE	
CAP	100%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%
CORROSION LEVEL	
BUTTONHEADS	I
ANCHOR HEAD	I
SHIMS	I
BEARING PLATE	I

Shim Stack - 13.25" (3/8", 1/2", 4-3")  
Coop/110-60 - GNG-003



LEGEND FOR CORROSION LEVEL  
#1 BRIGHT METAL, NO VISIBLE OXIDATION  
#2 REDDISH BROWN - NO PITTING  
#3 0 < PITTING < .003"  
#4 .003" < PITTING < .006"  
#5 .006" < PITTING < .015"

NOTE  
THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD'S (small) were large
  - BUTTONHEAD WITH SPLIT
  - ◐ WIRE REMOVED PREVIOUSLY
  - ◑ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V9 Shop end

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 42 °F.

ML 12/29/88

B. Containment Temperature (T2)  
2TE5605-S 76.3  
2TE5606-U 75.7 °F. } Avg. 76°F

ML 12/29/88  
ML 12/29/88

C. Average Temperature (T3) 59 °F.

8.3.2 Tendon repacked with heated Filler material?  
Yes  No

ML 12/29/88

Amount of filler material repacked into tendon (Gal) 1/4 + 1/4 Control = 1/2 Total

ML 12/29/88

Filler Temperature at the Pump 169 °F.

ML 12/29/88

Filler Cap Installed.

Final Filler Material level 23"  
Desired Filler Material level is 24" } ML 12/29/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 12/29/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/29/88

8.4.3 verify that all valves, vents and drains are open.

N/A ML 12/29/88

8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 12/29/88

8.4.5 Filler Temperature at the pump N/A °F

ML 12/29/88

8.4.6 Filler Installation Pressure N/A psi

ML 12/29/88

8.4.7 Ambient Temperature (T1) N/A °F

ML 12/29/88

8.4.8 Date Filler Cap Installed N/A

ML 12/29/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } TW-321  
50 Ft-lbs

ML 12/29/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: N/A ft-lbs

Torque Wrench used N/A

ML 13/1/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

**ARKANSAS NUCLEAR ONE**

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V9 Shop End

ATTACHMENT 5  
DATA SHEET

Sheathing Filler Material level  
check after 24 hours of  
refilling. Page 2 of 5  
Page 5 of 5

8.3 Vertical Tendon Repacking

8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 42 °F.

ML 13/1/88

B. Containment Temperature (T2)

2TE 5605-5 76.2 °F.  
2TE 5606-6 75.7 °F. } Avg. 76 °F

ML 13/1/88  
ML 13/1/88

C. Average Temperature (T3) 59 °F.

8.3.2 Tendon repacked with heated Filler material?  
Yes N/A No N/A

ML 13/1/88

Amount of filler material repacked into  
tendon (Gal) N/A

ML 13/1/88

Filler Temperature at the Pump N/A °F.

ML 13/1/88

Filler Cap Installed.

ML 13/1/88

8.4 Dome and Hoop Repacking } Desired Filler Material Level 24"  
Final Filler Material Level 23 1/2" } ML 3/1/88

8.4.1 Purge pumping hose of old filler  
material.

N/A ML 13/1/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 13/1/88

8.4.3 verify that all valves, vents and drains are  
open.

N/A ML 13/1/88

8.4.4 Amount of Filler material repacked into  
tendon. N/A (gal)

ML 13/1/88

8.4.5 Filler Temperature at the pump N/A °F

ML 13/1/88

8.4.6 Filler Installation Pressure N/A psi

ML 13/1/88

8.4.7 Ambient Temperature (T1) N/A °F

ML 13/1/88

8.4.8 Date Filler Cap Installed N/A

ML 13/1/88

8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler

caps: 50 Ft-lbs }  
50 Ft-lbs }

Torque Wrench used TW-321

ML 13/1/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

50 ft-lbs

Torque Wrench used TW-321

ML 13/1/88





PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO.  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit 2 DATE: 2/26/88  
TENDON NO.: V9 TENDON END/BUTTRESS NO.: Field SURVEILLANCE 4th  
OTHER TENDON END LOCATION INFO: Gallery

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(11.) OWNER/AGENT NOTIFIED Yes  No N/A DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No  N/A  
(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. Lech Level II Date 2/26/88  
QC Review Shroob Level III Date 3/22/88  
Title MGR, Q.C.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

8.1.1 Tendon Number V9

ML 12/26/88

8.1.2 Remove the Tendon Filler Cap.  
Field End  
Shop End

ML 12/26/88  
N/A ML 12/26/88

8.1.3 Volume of Sheathing Filler Removed: 1/4 gal.

ML 12/26/88

8.1.4 Ambient Air Temperature (T1): 69 °F

ML 12/26/88

8.1.5 Filler Material Level (Vertical Tendons)

A. Ambient Temperature (T1) N/A °F.

ML 12/26/88

B. Inside Containment Temperature (T2)  
N/A °F.

ML 12/26/88

C. Average Temperature (T3) N/A °F.

ML 12/26/88

D. Desired Filler Material Level  
N/A "

ML 12/26/88

E. Actual Filler Material Level N/A "

ML 12/26/88

8.1.6 Color Comparison

A. Tan Colored? Yes \_\_\_\_\_ No

ML 12/26/88

B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A

ML 12/26/88

Sample Submitted because of Tan Colored  
Filler Material. Yes \_\_\_\_\_ No

ML 12/26/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.  
Shop End  
Field End

N/A ML 12/26/88  
ML 12/26/88

\_\_\_\_\_  
Independent Verifier

ML 12/26/88  
Date



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	24	of	36
REVISION	2	DATE	02/12/88
CHANGE		DATE	

V9 Field End

ATTACHMENT 5  
DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) 02/3/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

02/4/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X  
2nd Sample Testing Results:  
Sat \_\_\_\_\_ Unsat \_\_\_\_\_  
N/A X

Filler Material Require Replacement?  
Yes \_\_\_\_\_ No X

02/4/88

## 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 2/26/88

1/2 Gal. Cold packed around  
anchorage components.

ML 2/26/88

Grease Can Installed using  
Old gasket, temporarily, and  
torqued to 160 ft-lbs in  
40 ft-lb increments.

ML 2/26/88

Gasket replaced and new  
"O" rings installed. SEE  
Page 5 of 5 Section 8.5. ML 2/26/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 25 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

10<sup>th</sup> Year ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH


TENDON NO. V9  
LOCATION Field End

PERFORMED BY DM Lab 2/24/88  
APPROVED BY [Signature]  
DATE 3/23/88

FILLER COVERAGE	2.2 Buttonhead Inspection
CAP	100%
BUTTONHEADS	100%
ANCHOR END	100%
SHIMS	N/A
BEARING PLATE	100%
CORROSION LEVEL	
BUTTONHEADS	1
ANCHOR END	1 (M.I. Scale)
SHIMS	N/A
BEARING PLATE	1

Co/No-60 # GAG-003

extra wire protruding  $\approx 1/2$ " from  
center grease hole.



- LEGEND**
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - ⊖ WIRE REMOVED PREVIOUSLY
  - ⊘ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE
- NOTE**  
THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.
- LEGEND FOR CORROSION LEVEL**
- #1 BRIGHT METAL, NO VISIBLE OXIDATION
  - #2 REDDISH BROWN - NO PITTING
  - #3 0 < PITTING < .003"
  - #4 .003" < PITTING < .006"
  - #5 .006" < PITTING < .010"

11 of 11



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	27 of 36	
REVISION	2	DATE 02/12/88
CHANGE	DATE	

V9 Field End

## ATTACHMENT 5 DATA SHEET

Page 5 of 5

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 69 °F.

ML 12/26/88

B. Containment Temperature (T2)

2TE 5605-5 73.2  
2TE 5606-6 74.8 °F. 75.0 Average

ML 12/26/88  
ML 12/26/88

C. Average Temperature (T3) 72 °F.

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No ✓

ML 12/26/88

Amount of filler material repacked into tendon (Gal) 1/2 (Coated Anchor)

ML 12/26/88

Filler Temperature at the Pump N/A °F.

ML 12/26/88

Filler Cap Installed. 2/26/88

ML 12/26/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 12/26/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/26/88

8.4.3 verify that all valves, vents and drains are open.

N/A ML 12/26/88

8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 12/26/88

8.4.5 Filler Temperature at the pump N/A °F

ML 12/26/88

8.4.6 Filler Installation Pressure N/A psi

ML 12/26/88

8.4.7 Ambient Temperature (T1) N/A °F

ML 12/26/88

8.4.8 Date Filler Cap Installed N/A

ML 12/26/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 160 Ft-lbs } In 40 ft-lb  
N/A Ft-lbs } Increments

ML 12/26/88

Torque Wrench used TW-321

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 160 ft-lbs  
N/A ft-lbs

ML 12/29/88

Torque Wrench used TW-321

112 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

Page 8 of 8

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit 2 DATE: 2/29/88  
TENDON NO.: V53 TENDON END/BUTTRESS NO.: Shop SURVEILLANCE 4<sup>th</sup>  
OTHER TENDON END LOCATION INFO: (Top)

(9.4) DURING LOOSENING OF GREASE CAN

(9.4.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.7) IN GREASE CAN

(9.7.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.8) AROUND TENDON ANCHORAGE

(9.8.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.10) DURING DETENSIONING

(9.10.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(11.) OWNER/AGENT NOTIFIED Yes  No  DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes  No

(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. Ledwith Level II Date 2/29/88  
QC Review [Signature] Level III Date 3/22/88  
Title MGR, Q.C.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

## FILLER LEVEL CHECK

Page 1 of 5

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V53 MML 12/29/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End N/A MML 12/29/88  
Shop End MML 12/29/88
- 8.1.3 Volume of Sheathing Filler Removed: None gal. MML 12/29/88
- 8.1.4 Ambient Air Temperature (T1): 50 °F MML 12/29/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) 42 °F. MML 12/29/88
  - B. Inside Containment Temperature (T2)  
2TE 5605-5 76.3 } Avg. 76 °F. MML 12/29/88  
2TE 5606-6 75.7 }
  - C. Average Temperature (T3) 59 °F. MML 12/29/88
  - D. Desired Filler Material Level  
24 " MML 12/29/88
  - E. Actual Filler Material Level 2 1/2 " MML 12/29/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No  MML 12/29/88
  - B. Tan Colored after 24 hours? Yes \_\_\_\_\_ No \_\_\_\_\_ N/A  MML 12/29/88

Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No  MML 12/29/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
Shop End N/A  
Field End N/A
- N/A MML MML 12/29/88  
1 MML 12/29/88
- Independent Verifier Date

1314 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	24 of 36		
REVISION	2	DATE	02/12/88
CHANGE		DATE	

V53 Shop end

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) N/A

A. Testing Results:  
Sat N/A Unsat N/A

ML 2/29/88

B. Second Sample Submitted:  
Yes N/A No N/A  
2nd Sample Testing Results:  
Sat N/A Unsat N/A  
N/A N/A

Filler Material Require Replacement?  
Yes N/A No N/A

ML 2/29/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) NONE

ML 2/29/88



1/5 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V53 Shop End

ATTACHMENT 5  
DATA SHEET

Page 5 of 5

- 8.3 Vertical Tendon Repacking
  - 8.3.1 Average Temperature (T3)
    - A. Ambient Temperature (T1) N/A °F. ML 12/29/88
    - B. Containment Temperature (T2) N/A °F. ML 12/29/88
    - C. Average Temperature (T3) N/A °F. ML 12/29/88
  - 8.3.2 Tendon repacked with heated Filler material?
    - Yes N/A No N/A ML 12/29/88
    - Amount of filler material repacked into tendon (Gal) N/A ML 12/29/88
    - Filler Temperature at the Pump N/A °F. ML 12/29/88
    - Filler Cap Installed. ML 12/29/88
- 8.4 Dome and Hoop Repacking
  - 8.4.1 Purge pumping hose of old filler material. N/A ML 12/29/88
  - 8.4.2 Attach pumping unit hose to tendon. N/A ML 12/29/88
  - 8.4.3 verify that all valves, vents and drains are open. N/A ML 12/29/88
  - 8.4.4 Amount of Filler material repacked into tendon. N/A (gal) ML 12/29/88
  - 8.4.5 Filler Temperature at the pump N/A °F. ML 12/29/88
  - 8.4.6 Filler Installation Pressure N/A psi ML 12/29/88
  - 8.4.7 Ambient Temperature (T1) N/A °F. ML 12/29/88
  - 8.4.8 Date Filler Cap Installed N/A ML 12/29/88
- 8.5 Tendon Resealing
  - 8.5.1 Install the filler caps.
    - Final torque value of the tendon filler caps: 50 Ft-lbs } Two Passes
    - 50 Ft-lbs
    - Torque Wrench used TW-321 ML 12/29/88
  - 8.5.2 Tendon filler cap retorqued after 24 hours.
    - Final Torque Value: 50 ft-lbs
    - 50 ft-lbs
    - Torque Wrench used TW-321 ML 13/1/88

D/6 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: AND  
TENDON NO.: V54 TENDON END/BUTTRISS NO.: Shop end DATE: 2/20/88  
OTHER TENDON END LOCATION INFO: Top SURVEILLANCE 4th

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(11.) OWNER/AGENT NOTIFIED Yes No  DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No   
(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. L. G. Level II Date 2/20/88

QC Review [Signature] Level III Date 3/22/88  
Title MGR, Q.C.

117 of 111



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE WORK PLAN TITLE: TENDON SURVEILLANCE PROCEDURE	NO: 2402.043
<b>ARKANSAS NUCLEAR ONE</b>		PAGE 23 of 36
		REVISION 2 DATE 02/12/88
		CHANGE DATE

ATTACHMENT 5  
DATA SHEET

Page 1 of 5

8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V54 ML 12/20/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End  
Shop End Top side N/A  
ML 12/20/88
- 8.1.3 Volume of Sheathing Filler Removed: 1/4 gal. ML 12/20/88
- 8.1.4 Ambient Air Temperature (T1): 54 °F ML 12/20/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) 50 °F. ML 12/20/88
  - B. Inside Containment Temperature (T2)  
2 TE 5605-5 77.7 (77.7) °F. ML 12/20/88
  - 2 TE 5606-6 77.7
  - C. Average Temperature (T3) 64.4 °F. ML 12/20/88
  - D. Desired Filler Material Level  
Approx. 23 ". ML 12/20/88
  - E. Actual Filler Material Level 44 3/4 ". ML 12/20/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No  ML 12/20/88
  - B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A  ML 12/20/88

Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No  ML 12/20/88

INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
Shop End Top ML 12/20/88  
N/A

ML 12/23/88  
Independent Verifier Date

DIP of 11



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	24	of	36
REVISION	2	DATE	02/12/88
CHANGE		DATE	

V54  
Shop End

## ATTACHMENT 5 DATA SHEET

Sample Submitted for Testing :  
(Shop or Field end) NONE CB 3/10/88

A. Testing Results:  
Sat N/A Unsat N/A

CB 3/10/88

B. Second Sample Submitted:  
Yes N/A No N/A  
2nd Sample Testing Results:  
Sat N/A Unsat N/A  
N/A N/A

Filler Material Require Replacement?  
Yes N/A No N/A

CB 3/10/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) Unmeasurable  
this coating

MIL 2/20/88

Coat Anchorage Assembly with 2090 P-H  
(1/4 Gal)

MIL 2/20/88

Torgued Caps to 50 ft-lbs with TW 321

MIL 2/20/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

19 of 1

## ATTACHMENT 5 DATA SHEET

Page 4 of 5

10<sup>th</sup> Year  
ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. V54  
LOCATION Skyl End (Exp)

BY W.L. Lord  
DATE 2/20/88  
APPROVED BY [Signature]  
DATE 3/1/88

FILLER COVERAGE  
CAP 100%  
BUTTONHEADS 100%  
ANCHOR HEAD 100%  
SHIMS 100%  
BEARING PLATE 100%


*Coating was very thin.*

### CORROSION LEVEL

BUTTONHEADS 1  
ANCHOR HEAD 1 & 2 (see Note)  
SHIMS 1  
BEARING PLATE 1

*Shim Stack 12.8" (3.3" 2, 3")  
Co/No-Co # ENG-003*

*Approx. 5.23" Area of light rust  
Level #2*



LEGEND FOR CORROSION LEVEL  
#1 BRIGHT METAL, NO VISIBLE OXIDATION  
#2 REDDISH BROWN - NO PITTING  
#3 0 < PITTING < .003"  
#4 .003" < PITTING < .006"  
#5 .006" < PITTING < .010"

NOTE  
THE LOCATION OF THE ANCHOR HEAD PK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

LEGEND  
○ OFF-SIZE BUTTONHEAD (seal to be large)  
● BUTTONHEAD WITH SPLIT  
● WIRE REMOVED PREVIOUSLY  
● DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE  
✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V54 Shop End

## ATTACHMENT 5 DATA SHEET

Page 5 of 5  
Page 1 of 2

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 42 °F.

ML 12/29/87

B. Containment Temperature (T2)

2TE 5605-5 76.3 °F.  
2TE 5606-6 75.7 °F. > Avg. 76 °F

ML 12/29/87  
ML 12/29/87

C. Average Temperature (T3) 59 °F.

8.3.2 Tendon repacked with heated Filler material?  
Yes  No

ML 12/29/87

Amount of filler material repacked into tendon (Gal) 3 + 1/4 Cont'd = 3 1/4 Total

ML 12/29/87

Filler Temperature at the Pump 169 °F.

ML 12/29/87

Filler Cap Installed.

Final Filler Material level 23" ML 12/29/87  
Dried Filler Material Level is 24"

ML 12/29/87

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 12/29/87

8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/29/87

8.4.3 verify that all valves, vents and drains are open.

N/A ML 12/29/87

8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 12/29/87

8.4.5 Filler Temperature at the pump N/A °F

ML 12/29/87

8.4.6 Filler Installation Pressure N/A psi

ML 12/29/87

8.4.7 Ambient Temperature (T1) N/A °F

ML 12/29/87

8.4.8 Date Filler Cap Installed N/A

ML 12/29/87

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } Two Passes  
50 Ft-lbs }

ML 12/29/87

Torque Wrench used TW-321

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: N/A ft-lbs

Torque Wrench used N/A ft-lbs

ML 13/1/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

D21 of 1

NO:  
2402.043

**ARKANSAS NUCLEAR ONE**

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V54 Shop End

ATTACHMENT 5  
DATA SHEET

Sheathing Filler Material level  
check after 24 hours of  
Refilling.

Page 5 of 5  
Page 2 of 2

8.3 Vertical Tendon Repacking

8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 42 °F.

B. Containment Temperature (T2)

2TE5605-5 76.2 °F.  
2TE5606-6 75.7 °F. } Avg. 76 °F

C. Average Temperature (T3) 59 °F.

ML 13/1/88

ML 13/1/88  
ML 13/1/88

8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

ML 13/1/88

Amount of filler material repacked into  
tendon (Gal) N/A

ML 13/1/88

Filler Temperature at the Pump N/A °F.

ML 13/1/88

Filler Cap Installed.

ML 13/1/88

8.4 Dome and Hoop Repacking

Desired Filler Material Level 24"  
Final Filler Material Level 23 3/4" } ML 3/1/88

8.4.1 Purge pumping hose of old filler  
material.

N/A ML 13/1/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 13/1/88

8.4.3 verify that all valves, vents and drains are  
open.

N/A ML 13/1/88

8.4.4 Amount of Filler material repacked into  
tendon. N/A (gal)

ML 15/1/88

8.4.5 Filler Temperature at the pump N/A °F

ML 13/1/88

8.4.6 Filler Installation Pressure N/A psi

ML 13/1/88

8.4.7 Ambient Temperature (T1) N/A °F

ML 13/1/88

8.4.8 Date Filler Cap Installed N/A

ML 13/1/88

8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler  
caps: 50 Ft-lbs } Two Passes  
50 Ft-lbs }

ML 13/1/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs  
50 ft-lbs

Torque Wrench used TW-321

ML 13/3/88

022 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 7

Page 8 of 8

## INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: AND Unit 2 DATE: 2/29/88  
TENDON NO.: V55 TENDON END/BUTTRESS NO.: Skop SURVEILLANCE 4th  
OTHER TENDON END LOCATION INFO: (Top)

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity N/A Sample Taken Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity N/A Sample Taken Yes No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity N/A Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No Quantity N/A Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED Yes  No N/A DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes  No N/A  
(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. Lord Level II Date 2/29/88

QC Review [Signature] Level III Date 3/23/88  
Title NGR, O.C.





PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 5  
DATA SHEET

FILLER LEVEL  
CHECK

Page 1 of 5

## 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V55 ML 12/29/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End N/A ML 12/29/88  
Shop End ML 12/29/88
- 8.1.3 Volume of Sheathing Filler Removed: None gal. ML 12/29/88
- 8.1.4 Ambient Air Temperature (T1): 50 °F ML 12/29/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) 42 °F. ML 12/29/88
  - B. Inside Containment Temperature (T2) ML 12/29/88  

2TE 5605-5	76.3	} Avg 76	°F.
2TE 5606-6	75.7		
  - C. Average Temperature (T3) 59 °F. ML 12/29/88
  - D. Desired Filler Material Level 24 " ML 12/29/88
  - E. Actual Filler Material Level 23 1/2 " ML 12/29/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes  No  ML 12/29/88
  - B. Tan Colored after 24 hours?   
Yes  No  N/A  ML 12/29/88

Sample Submitted because of Tan Colored Filler Material. Yes  No  ML 12/29/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
Shop End N/A ML 12/29/88  
Field End N/A ML 12/29/88
- N/A ML 12/29/88  
Independent Verifier Date

024 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	24 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

V55 Shop End

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) N/A

A. Testing Results:  
Sat N/A Unsat N/A

ML 12/29/87

B. Second Sample Submitted:  
 Yes N/A No N/A  
 2nd Sample Testing Results:  
 Sat N/A Unsat N/A  
 N/A N/A  
 Filler Material Require Replacement?  
 Yes N/A No N/A

ML 12/29/87

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) None

ML 12/29/87

025 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V55 Shop end

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

ML 12/29/88

B. Containment Temperature (T2)

N/A °F.

ML 12/29/88

C. Average Temperature (T3) N/A °F.

ML 12/29/88

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

ML 12/29/88

Amount of filler material repacked into tendon (Gal) N/A

ML 12/29/88

Filler Temperature at the Pump N/A °F.

ML 12/29/88

Filler Cap Installed.

ML 12/29/88

### 8.4 Dome and Hoop Repacking

#### 8.4.1 Purge pumping hose of old filler material.

N/A ML 12/29/88

#### 8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/29/88

#### 8.4.3 verify that all valves, vents and drains are open.

N/A ML 12/29/88

#### 8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 12/29/88

#### 8.4.5 Filler Temperature at the pump N/A °F

ML 12/29/88

#### 8.4.6 Filler Installation Pressure N/A psi

ML 12/29/88

#### 8.4.7 Ambient Temperature (T1) N/A °F

ML 12/29/88

#### 8.4.8 Date Filler Cap Installed N/A

ML 12/29/88

### 8.5 Tendon Resealing

#### 8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } Two Passes  
50 Ft-lbs

Torque Wrench used TW-321

ML 12/29/88

#### 8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

Torque Wrench used TW-321

ML 13/1/88

D26 at 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 7

Page 8 of 8

## INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit 2 DATE: 2/27/88  
TENDON NO.: V56 TENDON END/SUTURES NO.: Shop SURVEILLANCE 4<sup>th</sup>  
OTHER TENDON END LOCATION INFO: On Top

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No  Quantity N/A Sample Taken Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No  Quantity N/A Sample Taken Yes No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No  Quantity N/A Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No  Quantity N/A Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED Yes  No  DATE \_\_\_\_\_  
CONDITION: OBSERVABLE  SIGNIFICANT

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes  No   
(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. L. Q. Level II Date 2/27/88

QC Review [Signature] Level III Date 3/22/88  
Title NGB, Q.C.

D270 F 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V56 AMZ 12/27/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End  
Shop End N/A AMZ 12/27/88
- 8.1.3 Volume of Sheathing Filler Removed: 1/4 gal. AMZ 12/27/88
- 8.1.4 Ambient Air Temperature (T1): 59 °F AMZ 12/27/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) 50 °F. AMZ 12/27/88
  - B. Inside Containment Temperature (T2)
    - 2TE 5605-5 74.8
    - 2TE 5606-5 74.5
 Average 74.7 °F. AMZ 12/27/88
  - C. Average Temperature (T3) 62.3 °F. AMZ 12/27/88
  - D. Desired Filler Material Level  
24 ". AMZ 12/27/88
  - E. Actual Filler Material Level 43 3/4 ". AMZ 12/27/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No ✓ AMZ 12/27/88
  - F. Tan Colored after 24 hours?
    - Yes \_\_\_\_\_ No \_\_\_\_\_ N/A ✓ AMZ 12/27/88

Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No ✓ AMZ 12/27/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon end which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.  
Shop End  
Field End

AMZ 12/27/88  
N/A AMZ 12/27/88

AMZ 12/27/88  
Independent Verifier Date

02805111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V56 shop End

ATTACHMENT 5  
DATA SHEET

Page 2 of 5

Sample Submitted for Testing :

Shop or Field end) 02 3/10/88

A. Testing Results:

Sat  Unsat \_\_\_\_\_

02/14/19/88

B. Second Sample Submitted:

Yes \_\_\_\_\_ No

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A

Filler Material Require Replacement?

Yes \_\_\_\_\_ No

02/14/19/88

## 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 12/27/88

1/2 Gal. Cold Packed around anchorage  
components

ML 2/27/88

Torqued can bolts to 50 ft-lbs  
(Two passes) with torque wrench TW-321 ML  
2/27/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 5  
DATA SHEET

10<sup>th</sup> Year ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. V56  
LOCATION Shop

PC231 130

BY M. Lead  
DATE 2/27/88  
APPROVED BY [Signature]  
DATE 3/22/88

FILLER COVERAGE

CAP	100%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%


CORROSION LEVEL

BUTTONHEADS	I
ANCHOR HEAD	I
SHIMS	I
BEARING PLATE	I

Shim Stack 13 1/4" (3-3/4", 1/2", 3/8", 3")

Co/No-60 # GNG-003

2 - Approx. .016"  
Others are less than .010"



LEGEND FOR CORROSION LEVEL

- #1 BRIGHT METAL, NO VISIBLE OXIDATION
- #2 REDDISH BROWN - NO PITTING
- #3 0 < PITTING < .003"
- #4 .003" < PITTING < .006"
- #5 .006" < PITTING < .010"

NOTE

THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT (10 Total)
  - ⊙ WIRE REMOVED PREVIOUSLY
  - ⊖ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V56 Shop End

ATTACHMENT 5  
DATA SHEET

Page 5 of 5  
Page 1 of 2

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 42 °F.

ML 12/29/88

B. Containment Temperature (T2)

2TE5605-5 76.3 °F.  
2TE5606-6 75.7 °F. } Avg. 76 °F

ML 12/29/88

C. Average Temperature (T3) 59 °F.

ML 12/29/88

8.3.2 Tendon repacked with heated Filler material?  
Yes  No

ML 12/29/88

Amount of filler material repacked into tendon (Gal) 4 + 1/2 Contd = 4 1/2 Total

ML 12/29/88

Filler Temperature at the Pump 169 °F.

ML 12/29/88

Filler Cap Installed.

Final Filler Material Level 23 1/4" } ML 12/29/88

ML 12/29/88

### 8.4 Dome and Hoop Repacking *Damaged filler material Level is 24"*

8.4.1 Purge pumping hose of old filler material.

N/A ML 12/27/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/27/88

8.4.3 verify that all valves, vents and drains are open.

N/A ML 12/27/88

8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 12/27/88

8.4.5 Filler Temperature at the pump N/A °F

ML 12/27/88

8.4.6 Filler Installation Pressure N/A psi

ML 12/27/88

8.4.7 Ambient Temperature (T1) N/A °F

ML 12/27/88

8.4.8 Date Filler Cap Installed N/A

ML 12/27/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } Two Passes  
50 Ft-lbs }

ML 12/29/88

Torque Wrench used TW-321

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: N/A ft-lbs  
N/A ft-lbs

Torque Wrench used A

ML 13/1/88



D31 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V56 Shop End

ATTACHMENT 5  
DATA SHEET

Sheathing Filler Material level  
check after 24 hours of  
Refilling.

Page 5 of 5  
Page 2 of 2

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 42 °F.

ML 13/1/88

B. Containment Temperature (T2)

2TE 5605-5 76.2 °F.  
2TE 5606-6 75.7 °F. } Avg 76 °F

ML 13/1/88

C. Average Temperature (T3) 59 °F.

ML 13/1/88

#### 8.3.2 Tendon repacked with heated filler material?

Yes N/A No N/A

ML 13/1/88

Amount of filler material repacked into  
tendon (Gal) N/A

ML 13/1/88

Filler Temperature at the Pump N/A °F.

ML 13/1/88

Filler Cap Installed

ML 13/1/88

### 8.4 Dome and Hoop Repacking

Desired Filler Material Level 24"  
Final Filler Material Level 23 1/2" } ML 3/1/88

#### 8.4.1 Purge pumping hose of old filler material.

N/A ML 13/1/88

#### 8.4.2 Attach pumping unit hose to tendon.

N/A ML 13/1/88

#### 8.4.3 verify that all valves, vents and drains are open.

N/A ML 13/1/88

#### 8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 13/1/88

#### 8.4.5 Filler Temperature at the pump N/A °F

ML 13/1/88

#### 8.4.6 Filler Installation Pressure N/A psi

ML 13/1/88

#### 8.4.7 Ambient Temperature (T1) N/A °F

ML 13/1/88

#### 8.4.8 Date Filler Cap Installed N/A

ML 13/1/88

### 8.5 Tendon Resealing

#### 8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } Two Passes  
50 Ft-lbs

Torque Wrench used TW-321

ML 13/1/88

#### 8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs  
50 ft-lbs

Torque Wrench used TW-321

ML 13/3/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: AND Unit 2 DATE: 2/27/88  
TENDON NO.: V56 TENDON END/BUTTRESS NO.: Field SURVEILLANCE 4  
OTHER TENDON END LOCATION INFO: Chiller

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(11.) OWNER/AGENT NOTIFIED Yes  No  DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT: \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No   
(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. Led Level II Date 2/27/88  
QC Review [Signature] Level III Date 3/22/88  
Title NCR, Q.C.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V56 ML 12/27/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End  
Shop End ML 12/27/88  
N/A ML 12/27/88
- 8.1.3 Volume of Sheathing Filler Removed: 1/4 gal. ML 12/27/88
- 8.1.4 Ambient Air Temperature (T1): 72 °F ML 12/27/88
- 8.1.5 Filler Material Level (Vertical Tendons)
- A. Ambient Temperature (T1) N/A °F. ML 12/27/88
  - B. Inside Containment Temperature (T2) N/A °F. ML 12/27/88
  - C. Average Temperature (T3) N/A °F. ML 12/27/88
  - D. Desired Filler Material Level N/A ". ML 12/27/88
  - E. Actual Filler Material Level N/A ". ML 12/27/88
- 8.1.6 Color Compariscr.
- A. Tan Colored? Yes  No  ML 12/27/88
  - B. Tan Colored after 24 hours? Yes  No  N/A  ML 12/27/88
- Sample Submitted because of Tan Colored Filler Material. Yes  No  ML 12/27/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
Shop End  
Field End

N/A ML 12/27/88  
ML 12/27/88

ML  
Independent Verifier

12/29/88  
Date

134 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	29	of	36
REVISION		DATE	02/12/88
CHANGE		DATE	

V56 Field End

ATTACHMENT 5  
DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
Shop or Field end 02/10/88

A. Testing Results:  
Sat  Unsat \_\_\_\_\_

02/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No   
2nd Sample Testing Results:  
Sat \_\_\_\_\_ Unsat \_\_\_\_\_  
N/A

Filler Material Require Replacement?  
Yes \_\_\_\_\_ No

02/19/88

## 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 2/27/88

1/2 Gal. Cold packed around  
anchorage components.

ML 2/27/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:

TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 25 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 5  
DATA SHEET

10th of ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH


TENDON NO. V5L  
LOCATION Field End

PERFORMED BY M.L.D. 2/27/88  
APPROVED BY [Signature]  
DATE 3/22/88

FILLER COVERAGE	2.2
CAP	100%
BUTTONHEADS	100%
ANCHOR END	100%
SHIMS	N/A
BEARING PLATE	100%
CORROSION LEVEL	
BUTTONHEADS	1
ANCHOR END	1
SHIMS	N/A
BEARING PLATE	2

Buttonhead Inspection

Co/No-Go # GNG-003



LEGEND FOR CORROSION LEVEL  
 #1 BRIGHT METAL, NO VISIBLE OXIDATION  
 #2 REDDISH BROWN - NO PITTING  
 #3 0 < PITTING < .003"  
 #4 .003" < PITTING < .006"  
 #5 .006" < PITTING < .010"

NOTE  
 THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - ⊖ WIRE REMOVED PREVIOUSLY
  - ⊘ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ⊙ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V56 Field End

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 71 °F.

ML 12/27/88

B. Containment Temperature (T2)

2 TE 5605-5 74.8 °F. } Average 74.7

ML 12/27/88

2 TE 5606-4 74.5 °F. }  
C. Average Temperature (T3) 72.8 °F.

ML 12/27/88

#### 8.3.2 Tendon repacked with heated filler material?

Yes N/A No

ML 12/27/88

Amount of filler material repacked into tendon (Gal) 1/2 (coated anchorage)

ML 12/27/88

Filler Temperature at the Pump N/A °F.

ML 12/27/88

Filler Cap Installed.

ML 12/27/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 12/27/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/27/88

8.4.3 verify that all valves, vents and drains are open.

N/A ML 12/27/88

8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 12/27/88

8.4.5 Filler Temperature at the pump N/A °F

ML 12/27/88

8.4.6 Filler Installation Pressure N/A psi

ML 12/27/88

8.4.7 Ambient Temperature (T1) N/A °F

ML 12/27/88

8.4.8 Date Filler Cap Installed N/A

ML 12/27/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 160 Ft-lbs } 40 ft-lb increments  
N/A Ft-lbs }

ML 12/27/88

Torque Wrench used TW-321

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 160 ft-lbs  
N/A ft-lbs

ML 12/29/88

Torque Wrench used TW-321



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 7.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANC DATE: 2/29/88  
TENDON NO.: V5 TENDON END/BUTTRESS NO.: SHOP/TEP SURVEILLANCE 10<sup>th</sup> YR  
OTHER TENDON EN. LOCATION INFO \_\_\_\_\_

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING N/A  
(9.10.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED N/A Yes No DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No N/A

(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. Lohd Level II Date 2/29/88

QC Review [Signature] Level III Date 3/22/88  
Title MGR, Q.C.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

## CHECK FILLER LEVEL

Page 1 of 5

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V57 ML 12/29/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End N/A ML 12/29/88  
Shop End ML 12/29/88
- 8.1.3 Volume of Sheathing Filler Removed: NONE gal. ML 12/29/88
- 8.1.4 Ambient Air Temperature (T1): 50 °F ML 12/29/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) 42 °F. ML 12/29/88
  - B. Inside Containment Temperature (T2) ML 12/29/88  
 $2TE - 5605 - 5 = 76.3$   
 $2TE - 5606 - 6 = 75.7$   
 } AVG. 76 °F.
  - C. Average Temperature (T3) 59 °F. ML 12/29/88
  - D. Desired Filler Material Level ML 12/29/88  
24 "
  - E. Actual Filler Material Level 21 ". ML 12/29/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No X ML 12/29/88
  - B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A X ML 12/29/88

Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No X ML 12/29/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.  
Shop End  
Field End

N/A ML 12/29/88  
N/A ML 12/29/88

\_\_\_\_\_  
Independent Verifier Date



D39 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V57  
SHOP

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing ;  
(Shop or Field end) N/A

A. Testing Results:  
Sat N/A Unsat N/A

ML 12/29/88

B. Second Sample Submitted:  
Yes N/A No N/A  
2nd Sample Testing Results:  
Sat N/A Unsat N/A  
N/A N/A

Filler Material Require Replacement?  
Yes N/A No N/A

ML 2/29/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads.  
Amount Removed (Gal.) N/A (None)

ML 2/29/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V57  
SHOF

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

ML 2/29/88

B. Containment Temperature (T2)

ML 2/29/88

N/A °F.  
C. Average Temperature (T3) N/A °F.

ML 2/29/88

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

ML 2/29/88

Amount of filler material repacked into tendon (Gal) N/A

ML 2/29/88

Filler Temperature at the Pump N/A °F.

ML 2/29/88

Filler Cap Installed.

ML 2/29/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 2/29/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 2/29/88

8.4.3 verify that all valves, vents and drains are open.

N/A ML 2/29/88

8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 2/29/88

8.4.5 Filler Temperature at the pump N/A °F

ML 2/29/88

8.4.6 Filler Installation Pressure N/A psi

ML 2/29/88

8.4.7 Ambient Temperature (T1) N/A °F

ML 2/29/88

8.4.8 Date Filler Cap Installed N/A

ML 2/29/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs 2 TW-PASSES  
50 Ft-lbs

ML 2/29/88

Torque Wrench used TW-321

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs  
50 ft-lbs

ML 3/1/88

Torque Wrench used TW-321



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO DATE: 2/20/88  
TENDON NO.: V95 TENDON END/BUTTRESS NO.: Skp End SURVEILLANCE 4<sup>th</sup>  
OTHER TENDON END LOCATION INFO: Top Side

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments N/A

(11.) OWNER/AGENT NOTIFIED Yes No  DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFI. LMT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No   
(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. L. D. Level II Date 2/20/88

QC Review [Signature] Level III Date 3/23/88  
Title NBR, Q.C.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

**ARKANSAS NUCLEAR ONE**

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

042 of 111

ATTACHMENT 5  
DATA SHEET

Page 1 of 5

8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V95 ML 12/20/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End  
Shop End Top Side N/A  
ML 12/20/88
- 8.1.3 Volume of Sheathing Filler Removed: 1/4 gal. ML 12/20/88
- 8.1.4 Ambient Air Temperature (T1): 54 °F ML 12/20/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) 50 °F. ML 12/20/88
  - B. Inside Containment Temperature (T2)  
2E5605-5 77.7 (77.7) °F. ML 12/20/88
  - C. Average Temperature (T3) 64.4 °F. ML 12/20/88
  - D. Desired Filler Material Level  
Approx. 23 ". ML 12/20/88
  - E. Actual Filler Material Level 20.10 ". ML 12/20/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes  No  ML 12/20/88
  - B. Tan Colored after 24 hours?  
Yes  No  N/A  ML 12/20/88

Sample Submitted because of Tan Colored Filler Material. Yes  No  ML 12/20/88

INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
Shop End Top Side ML 12/20/88  
Field End N/A

\_\_\_\_\_  
Independent Verifier

ML 12/23/88  
Date

D43 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V95  
Shop End

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) 02/10/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

02/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X

2nd Sample Testing Results:  
Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?  
Yes \_\_\_\_\_ No X

02/19/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 2/20/88

Coated Anchorage Assembly with 2090 P. 4 (1/4 Gal.)

ML 2/20/88

Torqued Caps 50 ft. # with TW-321

ML 2/20/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE

TENDON SURVEILLANCE PROCEDURE

NO:

2402.C48

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36

REVISION 2

DATE 02/12/88

CHANGE

DATE

## ATTACHMENT 5 DATA SHEET

Page 4 of 5

10<sup>th</sup> Year  
ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. V95  
LOCATION Shop End (Trap)


*Marked with in first 2/12/88*

BY M. Lode  
DATE 2/20/88  
APPROVED BY [Signature]  
DATE 3/22/88

FILLER COVERAGE

CAP	100%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%
<u>CORROSION LEVEL</u>	
BUTTONHEADS	1
ANCHOR HEAD	1
SHIMS	1
BEARING PLATE	1

Shim Stack 12.10" (2-3", 2-1", 1/2", 1/4", 3")  
Co/No-60 # GNG-003



LEGEND

- OFF-SIZE BUTTONHEAD (see 1 to 6, 10a, 1c)
- BUTTONHEAD WITH SPLIT
- ◐ WIRE REMOVED PREVIOUSLY
- ◑ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
- ✕ MISSING WIRE

NOTE

- #1 BRIGHT METAL, NO VISIBLE OXIDATION
- #2 REDDISH BROWN - NO PITTING
- #3 0 < PITTING < .003"
- #4 .003" < PITTING < .006"
- #5 .006" < PITTING < .010"

LEGEND FOR CORROSION LEVEL

- #1 BRIGHT METAL, NO VISIBLE OXIDATION
- #2 REDDISH BROWN - NO PITTING
- #3 0 < PITTING < .003"
- #4 .003" < PITTING < .006"
- #5 .006" < PITTING < .010"

D45.f.11



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE: TENDON SURVEILLANCE PROCEDURE	NO: 2402.048
<b>ARKANSAS NUCLEAR ONE</b>		PAGE 27 of 36
		REVISION 2 DATE 02/12/88
		CHANGE DATE

V95 Shop End

ATTACHMENT 5  
DATA SHEET

- 8.3 Vertical Tendon Repacking
- 8.3.1 Average Temperature (T3)
- A. Ambient Temperature (T1) 42 °F. M.L. 12/29/88
- B. Containment Temperature (T2) M.L. 12/29/88
- 2TE 5605-5 76.3 °F. > Avg. 76
- 2TE 5606-6 75.7 °F.
- C. Average Temperature (T3) 59 °F. M.L. 12/29/88
- 8.3.2 Tendon repacked with heated filler material?  
Yes \_\_\_\_\_ No  M.L. 12/29/88
- Amount of filler material repacked into tendon (Gal) None + 1/4 Contol = 1/4 Total M.L. 12/29/88
- Filler Temperature at the Pump N/A °F. M.L. 12/29/88
- Filler Cap Installed. M.L. 12/29/88
- Final Filler Material level 24" } M.L. 2/20/88  
Desired Filler Material Level is 24" }
- 8.4 Dome and Hoop Repacking
- 8.4.1 Purge pumping hose of old filler material. N/A M.L. 12/29/88
- 8.4.2 Attach pumping unit hose to tendon. N/A M.L. 12/29/88
- 8.4.3 verify that all valves, vents and drains are open. N/A M.L. 12/29/88
- 8.4.4 Amount of Filler material repacked into tendon. N/A (gal) M.L. 12/29/88
- 8.4.5 Filler Temperature at the pump N/A °F M.L. 12/29/88
- 8.4.6 Filler Installation Pressure N/A psi M.L. 12/29/88
- 8.4.7 Ambient Temperature (T1) N/A °F M.L. 12/29/88
- 8.4.8 Date Filler Cap Installed N/A M.L. 12/29/88
- 8.5 Tendon Resealing
- 8.5.1 Install the filler caps.
- Final torque value of the tendon filler caps. 50 Ft-lbs } Two Passes  
50 Ft-lbs } M.L. 12/29/88
- Torque Wrench used TW-321
- 8.5.2 Tendon filler cap retorqued after 24 hours.
- Final Torque Value: 50 ft-lbs
- 50 ft-lbs
- Torque Wrench used TW-321 M.L. 1/31/88

D46 of 111



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE: TENDON SURVEILLANCE PROCEDURE	NO: 2402.048
ARKANSAS NUCLEAR ONE		PAGE 36 OF 36
		REVISION 2 DATE 02/12/88
		CHANGE DATE

ATTACHMENT 7

INSPECTION FOR WATER IN THE TENDON VOID,  
IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 13, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit 2 DATE: 2/26/88  
 TENDON NO.: V95 TENDON END/BUTTRESS NO.: Field SURVEILLANCE 2x  
 OTHER TENDON END LOCATION INFO: Gallery

(9.4) DURING LOOSENING OF GREASE CAN  
 (9.4.1) Water Detected Yes  No  Quantity N/A Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
 (9.7.1) Water Detected Yes  No  Quantity N/A Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
 (9.8.1) Water Detected Yes  No  Quantity N/A Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.10) DURING DETENSIONING  
 (9.10.1) Water Detected Yes  No  Quantity N/A Sample Taken Yes No  
 Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED Yes No  DATE \_\_\_\_\_  
 CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No   
 (12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. L. G. Level II Date 2/26/88  
 QC Review [Signature] Level III Date 3/22/88  
 Title MGR, Q.C.



D47 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO.  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number V95 MIL 12/26/88
- 8.1.2 Remove the Tendon Filler Cap.  
 Field End MIL 12/26/88  
 Shop End N/A MIL 12/26/88
- 8.1.3 Volume of Sheathing Filler Removed: 1/4 gal. MIL 12/26/88
- 8.1.4 Ambient Air Temperature (T1): 68 °F 2/24/88 MIL 12/26/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) N/A °F. MIL 12/26/88
  - B. Inside Containment Temperature (T2) N/A °F. MIL 12/26/88
  - C. Average Temperature (T3) N/A °F. MIL 12/26/88
  - D. Desired Filler Material Level N/A ". MIL 12/26/88
  - E. Actual Filler Material Level N/A ". MIL 12/26/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No  MIL 12/26/88
  - B. Tan Colored after 24 hours? Yes \_\_\_\_\_ No \_\_\_\_\_ N/A  MIL 12/26/88

Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No  MIL 12/26/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
 Shop End  
 Field End N/A MIL 12/26/88

CM 2/26/88  
Independent Verifier Date

D44 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V95 Field End

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing:  
(Shop or Field end) 02/3/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

02/4/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?

Yes \_\_\_\_\_ No X

02/4/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

AML 2/26/88

1/2<sup>(total)</sup> Cold Packed (control)  
Around Anchorage Components

AML 2/26/88

149 of 11



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	25 of 36		
REVISION	2	DATE	02/12/88
CHANGE		DATE	

## ATTACHMENT 5 DATA SHEET

Page 3 of 5

104 ARKANSAS UNIT 2  
Year TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. V95  
LOCATION Field


PERFORMED BY M.L.D. 2/25/88  
APPROVED BY [Signature]  
DATE 3/27/88

### WIRE COVERAGE

CAV	100%
BUTTONHEADS	100%
ANCHOR END	100%
SHIMS	N/A
BEARING PLATE	100%
CORROSION LEVEL	
BUTTONHEADS	1
ANCHOR END	1
SHIMS	N/A
BEARING PLATE	1

### Buttonhead Inspection

Co/No-60 # CNG-003



- LEGEND**
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - ⊖ WIRE REMOVED PREVIOUSLY
  - ⊘ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ⊙ MISSING WIRE
- NOTE**  
THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.
- LEGEND FOR CORROSION LEVEL**
- #1 BRIGHT METAL, NO VISIBLE OXIDATION
  - #2 REDDISH BROWN - NO PITTING
  - #3 0 < PITTING < .003"
  - #4 .003" < PITTING < .006"
  - #5 .006" < PITTING < .010"



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

V95 Field End

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) 68 °F.

ML 12/26/88

B. Containment Temperature (T2)

2TE 5605-5 75.2  
2TE 5606-6 74.8 °F. Average 75.0 °F

ML 12/26/88  
ML 12/26/88

C. Average Temperature (T3) 71.5 °F.

8.3.2 Tendon repacked with heated Filler material?  
Yes N/A No

ML 12/26/88

Amount of filler material repacked into tendon (Gal) 1/2 (Coated Anchorage)

ML 12/26/88

Filler Temperature at the Pump N/A °F.

ML 12/26/88

Filler Cap Installed. 2/26/88

ML 12/26/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 2/26/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/26/88

8.4.3 verify that all valves, vents and drains are open.

N/A ML 12/26/88

8.4.4 Amount of Filler material repacked into tendon. N/A (gal)

ML 12/26/88

8.4.5 Filler Temperature at the pump N/A °F

ML 12/26/88

8.4.6 Filler Installation Pressure N/A psi

ML 12/26/88

8.4.7 Ambient Temperature (T1) N/A °F

ML 12/26/88

8.4.8 Date Filler Cap Installed N/A

ML 12/26/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 160 Ft-lbs  $\int$  in 40 ft-lb increments  
N/A Ft-lbs  
Torque Wrench used TW-321

ML 12/26/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 160 ft-lbs  
N/A ft-lbs

Torque Wrench used TW-321

ML 12/29/88

051.4 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 13, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO DATE: 2/26/88  
TENDON NO.: 12413 TENDON END/SUPPORT NO.: SHOP/ATT #1 SURVEILLANCE 10<sup>th</sup> YR  
OTHER TENDON END LOCATION INFO \_\_\_\_\_

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING N/A  
(9.10.1) Water Detected N/A Yes No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED N/A Yes No DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED N/A Yes No

(12.2) SAMPLES STORED AT N/A

QC Signoff Chrom Level III Date 2/26/88

QC Review M. Lard Level II Date 4/20/88  
Title Q.C. Inspector

D52 of 111



PLANT MANUAL SECT:ON:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

8.1.1 Tendon Number 12H18 CB 2/24/88

8.1.2 Remove the Tendon Filler Cap.  
Field End N/A CB 2/26/88  
shop End CB 2/26/88

8.1.3 Volume of Sheathing Filler Removed: 2 gal. CB 2/26/88

8.1.4 Ambient Air Temperature (T1): 74 °F CB 2/26/88

#### 8.1.5 Filler Material Level (Vertical Tendons)

A. Ambient Temperature (T1) N/A °F. CB 2/26/88

B. Inside Containment Temperature (T2)  
N/A °F. CB 2/26/88

C. Average Temperature (T3) N/A °F. CB 2/26/88

D. Desired Filler Material Level  
N/A ". CB 2/26/88

E. Actual Filler Material Level N/A ". CB 2/26/88

#### 8.1.6 Color Comparison JUST AROUND 1/2 OF BUTTONHEADS

A. Tan Colored? Yes X No CB 2/26/88

B. Tan Color (er 24 hours?)  
Yes X N/A CB 13/1/88

Sample Submitted because of Tan Colored Filler Material. Yes X No CB 13/10/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.

Shop End  
Field End

M. L. ...  
Independent Verifier

2/26/88  
Date

CB 2/26/88  
N/A CB 2/26/88

D53 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

12418  
SHOP  
END

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing :

Shop or Field end) 02 3/10/88

A. Testing Results:

Sat X Unsat \_\_\_\_\_

02 4/19/88

B. Second Sample Submitted:

Yes \_\_\_\_\_ No X

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?

Yes \_\_\_\_\_ No X

02 4/19/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads

Amount Removed (Gal.) 1/2

02 2/26/88

1/4 GAL COATED GREASE ON  
ANCHORAGE COMPONENTS 02 2/26/88

D54 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 5  
DATA SHEET

ARKANSAS UNIT 2  
10<sup>th</sup> /R TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. 12H18  
LOCATION SHOP

BY Grucha  
DATE 2/26/88  
APPROVED BY R. Lead  
DATE 4/20/88

FILLER COVERAGE

CAP	80
BUTTONHEADS	100
ANCHOR HEAD	90
SHIMS	80
BEARING PLATE	80

CORROSION LEVEL

BUTTONHEADS	1
ANCHOR HEAD	1
SHIMS	1
BEARING PLATE	1


SHIM STACK 5.7" ( $1/2, 1/2, 1/2, 1/2, 1/2, 1/2, 1/2$ )

GAG # 64 GAUGE  
OFFSIZE BUTTONHEADS LARGE

- LEGEND FOR CORROSION LEVEL
- #1 BRIGHT METAL, NO VISIBLE OXIDATION
  - #2 REDDISH BROWN - NO PITTING
  - #3 0 < PITTING < .003"
  - #4 .003" < PITTING < .006"
  - #5 .006" < PITTING < .010"

- NOTE
- THE LOCATION OF THE ANCHOR HEAD PK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD
  - ◉ BUTTONHEAD WITH SPLIT
  - ◐ WIRE REMOVED PREVIOUSLY
  - ◑ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ⊗ MISSING WIRE







PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

12H18  
SHOP  
END

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F. OB 12/26/88

B. Containment Temperature (T2)

C. N/A °F. Average Temperature (T3) N/A °F. OB 12/26/88  
OB 12/26/88

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A OB 12/26/88

Amount of filler material repacked into tendon (Gal) N/A OB 12/26/88

Filler Temperature at the Pump N/A °F. OB 12/26/88

Filler Cap Installed. N/A OB 12/26/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material. N/A OB 13/1/88

8.4.2 Attach pumping unit hose to tendon. N/A OB 13/1/88

8.4.3 verify that all valves, vents and drains are N/A open. (AIR VENTED) OB 13/1/88

8.4.4 Amount of Filler material repacked into tendon. 4 1/2 (gal) \* 1/4 COATED = 4 3/4 TOTAL OB 13/1/88

8.4.5 Filler Temperature at the pump 190 °F OB 13/1/88

8.4.6 Filler Installation Pressure N/A psi OB 13/1/88

8.4.7 Ambient Temperature (T1) 54 °F OB 13/1/88

8.4.8 Date Filler Cap Installed 2/26/88 OB 12/26/88

### 8.5 Tendon Resealing

#### 8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs TWO PASSES  
N/A Ft-lbs

8.5.2 Torque Wrench used TW-382 OB 12/26/88  
Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs  
N/A ft-lbs

Torque Wrench used TW-382 OB 13/1/88



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE:	NO:
	TENDON SURVEILLANCE PROCEDURE	2402.048
ARKANSAS NUCLEAR ONE		PAGE 36 of 36
		REVISION 2 DATE 02/12/88
		CHANGE DATE

ATTACHMENT 7

INSPECTION FOR WATER IN THE TENDON VOID,  
IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
 INSPECT FOR WATER  
 DATA SHEET 6.1  
 JANUARY 15, 1988  
 Page 1 of 1  
 Revision 0

PROJECT: ANO DATE: 2/23/88  
 TENDON NO.: 12H18 TENDON END/BUTRESS NO.: FWD/2 SURVEILLANCE 10<sup>th</sup> YR  
 OTHER TENDON END LOCATION INFO \_\_\_\_\_

(9.4) DURING LOOSENING OF GREASE M  
 (9.4.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
 (9.7.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
 (9.8.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.10) DURING DETENSIONING N/A  
 (9.10.1) Water Detected N/A Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED N/A Yes  No  DATE \_\_\_\_\_  
 CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED N/A Yes  No

(12.2) SAMPLES STORED AT N/A

QC Signoff [Signature] Level III Date 2/23/88  
 QC Review M. L. [Signature] Level II Date 4/20/88  
 Title: S.C. Inspector



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

8.1.1 Tendon Number 12H18 EB 12/23/88

8.1.2 Remove the Tendon Filler Cap.  
Field End EB 12/23/88  
Shop End N/A EB 12/23/88

8.1.3 Volume of Sheathing Filler Removed: 1 1/2 gal. EB 12/23/88

8.1.4 Ambient Air Temperature (T1): 48 °F EB 12/23/88

#### 8.1.5 Filler Material Level (Vertical Tendons)

A. Ambient Temperature (T1) N/A °F. EB 12/23/88

B. Inside Containment Temperature (T2)  
N/A °F. EB 12/23/88

C. Average Temperature (T3) N/A °F. EB 12/23/88

D. Desired Filler Material Level  
N/A ". EB 12/23/88

E. Actual Fill Material Level N/A ". EB 12/23/88

#### 8.1.6 Color Comparison

A. Tan Colored? Yes \_\_\_\_\_ No X EB 12/23/88

B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A X EB 12/23/88

Sample Submitted because of Tan Colored  
Filler Material. Yes \_\_\_\_\_ No X EB 12/23/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.  
Shop End N/A EB 12/23/88  
Field End EB 12/23/88

M. L. [Signature] 12/23/88  
Independent Verifier Date



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/68  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET


ARKANSAS UNIT 2  
10<sup>th</sup> YR TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

BY *Struck*  
DATE 2/23/88  
APPROVED BY *Pat Kaye*  
DATE 4/20/88

FILLER COVERAGE	
CAP	80%
BUTTONHEADS	100%
ANCHOR HEAD	80%
SHIMS	80%
BEARING PLATE	80%
CORROSION LEVEL	
BUTTONHEADS	#1
ANCHOR HEAD	#1 + 2 SEE AREA
SHIMS	1
BEARING PLATE	1

SHIM STACK 5.6" (1/2, 1/2, 1/2, 1/2, 1/2, 3)

BUTTONHEADS  
OFFSIZE ARE  
LARGE - GNG-003 GAUGE



- LEGEND**
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - WIRE REMOVED PREVIOUSLY
  - DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE
- NOTE**
- THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.
- LEGEND FOR CORROSION LEVEL**
- #1 BRIGHT METAL, NO VISIBLE OXIDATION
  - #2 REDDISH BROWN - NO PITTING
  - #3 0 < PITTING < .003"
  - #4 .003" < PITTING < .006"
  - #5 .006" < PITTING < .010"

TENDON NO. 12 H18

LOCATION FIELD

PC239-513

060 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE	27 of 36		
REVISION	2	DATE	02/12/88
CHANGE		DATE	

12H18  
FIELD

ATTACHMENT 5  
DATA SHEET

Page 5 of 5

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

- A. Ambient Temperature (T1) N/A °F. EB 12/23/88
- B. Containment Temperature (T2) N/A °F. EB 12/23/88
- C. Average Temperature (T3) N/A °F. EB 12/23/88

#### 8.3.2 Tendon repacked with heated Filler material?

- Yes N/A No N/A EB 12/23/88
- Amount of filler material repacked into tendon (Gal) N/A EB 12/23/88
- Filler Temperature at the Pump N/A °F. EB 12/23/88
- Filler Cap Installed. N/A EB 12/23/88

### 8.4 Dome and Hoop Repacking

- 8.4.1 Purge pumping hose of old filler material. N/A EB 12/25/88
- 8.4.2 Attach pumping unit hose to tendon. N/A EB 12/25/88
- 8.4.3 verify that all valves, vents and drains are N/A open. (AIR VENTED) EB 12/25/88
- 8.4.4 Amount of Filler material repacked into tendon. 3 1/2 (gal) + 1/4 COATED = 3 3/4 TOTAL EB 12/25/88
- 8.4.5 Filler Temperature at the pump 168 °F EB 12/25/88
- 8.4.6 Filler Installation Pressure N/A psi EB 12/25/88
- 8.4.7 Ambient Temperature (T1) 68 °F EB 12/25/88
- 8.4.8 Date Filler Cap Installed 2/23/88 EB 12/23/88

### 8.5 Tendon Resealing

- 8.5.1 Install the filler caps.
  - Final torque value of the tendon filler caps: 50 Ft-lbs
  - N/A Ft-lbs
  - Torque Wrench used TW-382 EB 12/23/88
- 8.5.2 Tendon filler cap retorqued after 24 hours.
  - Final Torque Value: 50 ft-lbs
  - N/A ft-lbs
  - Torque Wrench used TW-382 EB 12/25/88



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE: TENDON SURVEILLANCE PROCEDURE	NO: 2402.048
<b>ARKANSAS NUCLEAR ONE</b>		PAGE 36 of 36
		REVISION 2      DATE 02/12/88
		CHANGE            DATE

ATTACHMENT 7

INSPECTION FOR WATER IN THE TENDON VOID,  
IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
 INSPECT FOR WATER  
 DATA SHEET 4.1  
 JANUARY 15, 1988  
 Page 1 of 1  
 Revision 0

PROJECT: ANO  
 TENDON NO.: 31436 TENDON END/BUTRESS NO.: SHOP/3 DATE: 2/25/88  
 OTHER TENDON END LOCATION INFO \_\_\_\_\_

(9.4) DURING LOOSENING OF GREASE CAN  
 (9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
 (9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
 (9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments \_\_\_\_\_

(9.10) DURING DETENSIONING N/A  
 (9.10.1) Water Detected N/A Yes No Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED N/A Yes No DATE \_\_\_\_\_  
 CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED N/A Yes No

(12.2) SAMPLES STORED AT N/A

QC Signoff [Signature] Level III Date 2/25/88  
 QC Review M. Lee Level II Date 4/20/88  
 Title R.C. Inspector

062 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

8.1.1 Tendon Number 31436 EB 2/25/88

8.1.2 Remove the Tendon Filler Cap.  
Field End N/A EB 2/25/88  
EB 2/25/88  
Shop End

8.1.3 Volume of Sheathing Filler Removed: 2 gal. EB 2/25/88

8.1.4 Ambient Air Temperature (T1): 56 °F EB 2/25/88

#### 8.1.5 Filler Material Level (Vertical Tendons)

A. Ambient Temperature (T1) N/A °F. EB 2/25/88

B. Inside Containment Temperature (T2)  
N/A °F. EB 2/25/88

C. Average Temperature (T3) N/A °F. EB 2/25/88

D. Desired Filler Material Level  
N/A ". EB 2/25/88

E. Actual Filler Material Level N/A ". EB 2/25/88

#### 8.1.6 Color Comparison

A. Tan Colored? Yes \_\_\_\_\_ No X EB 2/25/88

B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A X EB 2/25/88

Sample Submitted because of Tan Colored  
Filler Material. Yes \_\_\_\_\_ No X EB 2/25/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.

Shop End  
Field End

Mr. Lesh 2/25/88  
Independent Verifier Date

EB 2/25/88  
N/A EB 2/25/88

063 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

31436  
SHOP

ATTACHMENT 5  
DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) 03/10/85

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

03/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X

2nd Sample Testing Results:  
Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?

Yes \_\_\_\_\_ No X

03/19/88

## 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing plate and the Buttonheads  
Amount Removed (Gal.) 1/2

03/25/88

1/4 GAL GREASE COATED  
AROUND ANCHORAGE COMPONENTS  
03/25/88





PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 5  
DATA SHEET

Page 4 of 5

ARKANSAS UNIT 2  
10<sup>th</sup> YR TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

BY *[Signature]*  
DATE 2/25/88  
APPROVED BY *[Signature]*  
DATE 4/20/88

FILLER COVERAGE

CAP 80  
BUTTONHEADS 100  
ANCHOR HEAD 95  
SHIMS 80  
BEARING PLATE 100

CORROSION LEVEL

BUTTONHEADS 1  
ANCHOR HEAD 1  
SHIMS 1  
BEARING PLATE 1

SHIM STACK 5.6 (1/2, 1, 1, 3)  
GWB GAUGE 064


LEGEND FOR CORROSION LEVEL  
#1 BRIGHT METAL, NO VISIBLE OXIDATION  
#2 REDDISH BROWN - NO PITTING  
#3 0 < PITTING < .003"  
#4 .003" < PITTING < .006"  
#5 .006" < PITTING < .010"

NOTE  
THE LOCATION OF THE  
ANCHOR HEAD MK NUMBER  
SHALL BE INDICATED ON  
THE SKETCH TO DEFINE  
BUTTONHEAD ORIENTATION.

LEGEND  
○ OFF-SIZE BUTTONHEAD  
● BUTTONHEAD WITH SPLIT  
● WIRE REMOVED PREVIOUSLY  
● DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE  
✕ MISSING WIRE

TENDON NO. 31136  
LOCATION SHOP

PC234-221



065 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

31436  
SHOP

## ATTACHMENT 5 DATA SHEET

Page 5 of 5

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

EB 12/25/88

B. Containment Temperature (T2)

N/A °F.

EB 12/25/88

C. Average Temperature (T3) N/A °F.

EB 12/25/88

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

EB 12/25/88

Amount of filler material repacked into tendon (Gal) N/A

EB 12/25/88

Filler Temperature at the Pump N/A °F.

EB 12/25/88

Filler Cap Installed.

N/A EB 12/25/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A EB 12/25/88

8.4.2 Attach pumping unit hose to tendon.

N/A EB 12/25/88

8.4.3 verify that all valves, vents and drains are N/A open. (AIR VENTED)

EB 12/25/88

8.4.4 Amount of Filler material repacked into tendon. 4 (gal) + 1/4 COATED = 4 1/4 TOTAL

EB 12/25/88

8.4.5 Filler Temperature at the pump 182 °F

EB 12/25/88

8.4.6 Filler Installation Pressure N/A psi

EB 12/25/88

8.4.7 Ambient Temperature (T1) 56 °F

EB 12/25/88

8.4.8 Date Filler Cap Installed 2/25/88

EB 12/25/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs TWO PASSES

N/A Ft-lbs

Torque Wrench used TW-382

EB 12/25/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

N/A ft-lbs

Torque Wrench used TW-382

EB 12/26/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO DATE: 2/27/88  
TENDON NO.: 3/H36 TENDON END/BUTTRESS NO. FIELD/BUTT SURVEILLANCE 10<sup>th</sup> YR  
OTHER TENDON END LOCATION INFO #1

(9.4) DURING LOOSENING OF GREASE CAN

(9.4.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken N/A Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN

(9.7.1) Water Detected  Yes  No Quantity APPROX. 2 OZ Sample Taken  Yes  No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE

(9.8.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING N/A

(9.10.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED Yes  No  - NOT ON 2/7/88 YES ON 2/29/88 DATE \_\_\_\_\_  
CONDITION: OBSERVABLE  SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED  Yes  No

(12.2) SAMPLES STORED AT PSC TRAILER

QC Signoff [Signature] Level III Date 2/27/88

QC Review M. Lord Level II Date 4/20/88

Title Q.C. Inspector



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	23 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

## ATTACHMENT 5 DATA SHEET

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number 31H36 CB 12/27/88
- 8.1.2 Remove the Tendon Filler Cap.
  - Field End CB 12/27/88
  - Shop End N/A CB 12/27/88
- 8.1.3 Volume of Sheathing Filler Removed: 2 gal. CB 12/27/88
- 8.1.4 Ambient Air Temperature (T1): 62 °F CB 12/27/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) N/A °F. CB 12/27/88
  - B. Inside Containment Temperature (T2) N/A °F. CB 12/27/88
  - C. Average Temperature (T3) N/A °F. CB 12/27/88
  - D. Desired Filler Material Level N/A ". CB 12/27/88
  - E. Actual Filler Material Level N/A ". CB 12/27/88
- 8.1.6 Color Comparison JUST AROUND  
BUTTONHEADS
  - A. Tan Colored? Yes  No  CB 12/27/88
  - B. Tan Colored after 24 hours? Yes  No  N/A  CB 13/1/88

Sample Submitted because of Tan Colored Filler Material. Yes  No  CB 13/10/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.
  - Shop End
  - Field End N/A CB 12/27/88

M. Lutz 12/27/88  
Independent Verifier Date

264 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	24 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

31436  
FIELD

ATTACHMENT 5  
DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) EB 3/19/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

EB 4/19/88

B. Second Sample Submitted:  
 Yes \_\_\_\_\_ No X  
 2nd Sample Testing Results:  
 Sat \_\_\_\_\_ Unsat \_\_\_\_\_  
 N/A X  
 Filler Material Require Replacement?  
 Yes \_\_\_\_\_ No X

EB 4/19/88

## 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
 stressing Plate and the Buttonheads  
 Amount Removed (Gal.) 1/4

EB 2/27/88

1/4 GAL. GREASE COATED AROUND  
ANCHORAGE COMPONENTS EB 2/27/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

ARKANSAS UNIT 2  
10<sup>th</sup> YR TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. 31H36  
LOCATION FIELD


PC242-667

BY *Brooks*  
DATE 2/27/88  
APPROVED BY *M. Lead*  
DATE 4/20/88

FILLER COVERAGE	
CAP	80 50 60 2/27/88
BUTTONHEADS	50
ANCHOR HEAD	50
SHIMS	50
BEARING PLATE	50
CORROSION LEVEL	
BUTTONHEADS	1
ANCHOR HEAD	1
SHIMS	1
BEARING PLATE	1

6NG GAUGE 064  
SHIM STACK (.2, 1, 1, 3)  
5.3

OTHER OFF-SIZE BUTTONHEADS  
ARE LARGE



LEGEND FOR CORROSION LEVEL

- #1 BRIGHT METAL, NO VISIBLE OXIDATION
- #2 REDDISH BROWN - NO PITTING
- #3 0 < PITTING < .003"
- #4 .003" < PITTING < .006"
- #5 .006" < PITTING < .010"

NOTE

THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - ⊙ WIRE REMOVED PREVIOUSLY
  - ⊘ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - X MISSING WIRE

070 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

31436  
FIELD END

## ATTACHMENT 5 DATA SHEET

Page 5 of 5

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

EB 12/29/88

B. Containment Temperature (T2)

N/A °F.

EB 12/29/88  
EB 12/29/88

C. Average Temperature (T3) N/A °F.

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

EB 12/29/88

Amount of filler material repacked into tendon (Gal) N/A

EB 12/29/88

Filler Temperature at the Pump N/A °F.

EB 12/29/88

Filler Cap Installed.

N/A EB 12/29/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A EB 12/29/88

8.4.2 Attach pumping unit hose to tendon.

N/A EB 12/29/88

8.4.3 verify that all valves, vents and drains are N/A open. (AIR VENTED)

EB 12/29/88

8.4.4 Amount of Filler material repacked into tendon. 5 (gal) + 1/4 COATED = 5 1/4 TOTAL

EB 12/29/88

8.4.5 Filler Temperature at the pump 162 °F

EB 12/29/88

8.4.6 Filler Installation Pressure N/A psi

EB 12/29/88

8.4.7 Ambient Temperature (T1) 76 °F

EB 12/29/88

8.4.8 Date Filler Cap Installed 2/27/88

EB 12/27/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs TWO PASSES

N/A Ft-lbs

Torque Wrench used TW-382

EB 12/27/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

N/A ft-lbs

Torque Wrench used TW-382

EB 12/29/88

**PSC**

Precision Surveillance Corporation

SAFETY RELATED

NON-SAFETY RELATED

PAGE OF

TO: MIKE COOMBS-ANO


DATE: 2-29-88

SUBJECT: UNIT 2 TENDON SURVEILLANCE  
PROCEDURE 2402.048 REV. 2  
ATTACHMENT 7 - INSPECT FOR  
WATER - SECTION 11

PER PSC PROCEDURE SQ6.1 SECTION 11  
OF ATTACHMENT 7 OF ANO PROCEDURE  
2402.048 REV. 2 "THE OWNER OR HIS  
AGENT SHALL BE FORMALLY NOTIFIED  
WHEN WATER, REGARDLESS OF QUANTITY,  
HAS BEEN DETECTED DURING THE IN-  
SERVICE INSPECTION."

THIS IS TO NOTIFY YOU THAT WATER  
WAS FOUND IN THE GREASE CAN OF  
TENDON 31H36 - FIELD END - BUTTRESS  
1 - APPROX. 2 OZ. WAS FOUND AND  
COLLECTED.

PER SECTION 10.1 OF THE ABOVE  
MENTIONED PROCEDURE THIS WATER  
IS DEFINED AS "OBSERVABLE MOISTURE"  
ANY QUESTIONS OR COMMENTS PLEASE  
NOTIFY.



C. BROOKS  
MGR, Q.C./PSC





PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

Page 6 of 6

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO DATE: 2/27/88  
TENDON NO.: 32H50 TENDON END/BUTRESS NO.: SHOP/BUTT SURVEILLANCE 10<sup>th</sup> YR  
OTHER TENDON END LOCATION INFO: 3

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING N/A  
(9.10.1) Water Detected N/A Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED N/A Yes No DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED N/A Yes No

(12.2) SAMPLES STORED AT N/A

QC Signoff [Signature] Level: III Date 2/27/88

QC Review M. Leo Level: II Date 4/20/88

Title: QC Inspector

073 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number 32H50 EB 12/27/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End N/A EB 12/27/88  
Shop End EB 12/27/88
- 8.1.3 Volume of Sheathing Filler Removed. 2 gal. EB 12/27/88
- 8.1.4 Ambient Air Temperature (T1): 80 °F EB 12/27/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) N/A °F. EB 12/27/88
  - B. Inside Containment Temperature (T2)  
N/A °F. EB 12/27/88
  - C. Average Temperature (T3) N/A °F. EB 12/27/88
  - D. Desired Filler Material Level  
N/A ". EB 12/27/88
  - E. Actual Filler Material Level N/A ". EB 12/27/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No X EB 12/27/88
  - B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A X EB 12/27/88
  - Sample Submitted because of Tan Colored  
Filler Material. Yes \_\_\_\_\_ No X EB 12/27/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.

Shop End  
Field End

*M. Leed*

Independent Verifier

12/27/88

Date

EB 12/27/88  
N/A EB 12/27/88

D74 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	24 of 36
REVISION	2
DATE	02/12/88
CHANGE	DATE

32450  
SHOP END

ATTACHMENT 5  
DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or ~~Field~~/end) EC 3/10/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

EC 4/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X  
2nd Sample Testing Results:  
Sat \_\_\_\_\_ Unsat \_\_\_\_\_  
N/A X

Filler Material Require Replacement?  
Yes \_\_\_\_\_ No X

EC 4/19/88

## 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

EC 3/27/88

1/4 GAL. GREASE COATED  
ON ANCHORAGE COMPONENTS EC 2/27/88

075 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 5  
DATA SHEET

Page 4 of 5

10<sup>th</sup> ARKANSAS UNIT 2  
YR TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH


BY Abrecht  
DATE 2/27/88  
APPROVED BY M. Lead  
DATE 4/20/88

FILLER COVERAGE

CAP	80
BUTTONHEADS	100
ANCHOR HEAD	80
SHIMS	80
BEARING PLATE	80
CORROSION LEVEL	
BUTTONHEADS	1
ANCHOR HEAD	1
SHIMS	1
BEARING PLATE	1

P2233-209

SHIM STACK 6.2" (3,3)  
GUB GAUGE #064



TENDON NO. 32450  
LOCATION SHOP

- LEGEND**
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - WIRE REMOVED PREVIOUSLY
  - DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE
- NOTE**  
THE LOCATION OF THE ANCHOR HEAD PK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.
- LEGEND FOR CORROSION LEVEL**
- #1 BRIGHT METAL, NO VISIBLE OXIDATION
  - #2 REDDISH BROWN - NO PITTING
  - #3 0 < PITTING < .003"
  - #4 .003" < PITTING < .006"
  - #5 .006" < PITTING < .010"

076 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

32450  
SHOP

## ATTACHMENT 5 DATA SHEET

Page 5 of 5

- 8.3 Vertical Tendon Repacking
- 8.3.1 Average Temperature (T3)
- A. Ambient Temperature (T1) N/A °F. EB 12/27/88
- B. Containment Temperature (T2) N/A °F. EB 12/27/88
- C. Average Temperature (T3) N/A °F. EB 12/27/88
- 8.3.2 Tendon repacked with heated Filler material?
- Yes N/A No N/A EB 12/27/88
- Amount of filler material repacked into tendon (Gal) N/A EB 12/27/88
- Filler Temperature at the Pump N/A °F. EB 12/27/88
- Filler Cap Installed. N/A EB 12/27/88
- 8.4 Dome and Hoop Repacking
- 8.4.1 Purge pumping hose of old filler material. N/A EB 12/29/88
- 8.4.2 Attach pumping unit hose to tendon. N/A EB 12/29/88
- 8.4.3 verify that all valves, vents and drains are N/A open. (AIR VENTED) EB 12/29/88
- 8.4.4 Amount of Filler material repacked into tendon. 2 (gal) + 1/4 COATED = 2 1/4 EB 12/29/88
- 8.4.5 Filler Temperature at the pump 166 °F EB 12/29/88
- 8.4.6 Filler Installation Pressure N/A psi EB 12/29/88
- 8.4.7 Ambient Temperature (T1) 72 °F EB 12/29/88
- 8.4.8 Date Filler Cap Installed 2/27/88 EB 12/27/88
- 8.5 Tendon Resealing
- 8.5.1 Install the filler caps.
- Final torque value of the tendon filler caps: 50 Ft-lbs TWO PASSES EB 12/27/88
- N/A Ft-lbs
- Torque Wrench used TW-382
- 8.5.2 Tendon filler cap retorqued after 24 hours.
- Final Torque Value: 50 ft-lbs
- N/A ft-lbs
- Torque Wrench used TW-382 EB 12/29/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO  
TENDON NO.: 32H50 TENDON END/BUTTRESS NO.: FIELD/BUTT 2 DATE: 2/24/88 SURVEILLANCE 10<sup>+</sup> hr  
OTHER TENDON END LOCATION INFO \_\_\_\_\_

(9.4) DURING LOOSENING OF GREASE CAN

(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN

(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE

(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING N/A

(9.10.1) Water Detected N/A Yes No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED N/A Yes No DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED N/A Yes No

(12.2) SAMPLES STORED AT N/A

QC Signoff [Signature] Level III Date 2/24/88  
QC Review [Signature] Level II Date 4/20/88  
Title: P.I. Inspector



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number 32450 CS 12/24/88
- 8.1.2 Remove the Tendon Filler Cap.
  - Field End CS 12/24/88
  - Shop End CS 12/24/88
- 8.1.3 Volume of Sheathing Filler Removed: 2 1/2 gal. CS 12/24/88
- 8.1.4 Ambient Air Temperature (T1): 58 °F CS 12/24/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) N/A °F. CS 12/24/88
  - B. Inside Containment Temperature (T2) N/A °F. CS 12/24/88
  - C. Average Temperature (T3) N/A °F. CS 12/24/88
  - D. Desired Filler Material Level N/A ". CS 12/24/88
  - E. Actual Filler Material Level N/A ". CS 12/24/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No X CS 12/24/88
  - B. Tan Colored after 24 hours? Yes \_\_\_\_\_ No \_\_\_\_\_ N/A X CS 12/24/88

Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No X CS 12/24/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.  
Shop End  
Field End N/A CS 12/24/88  
CS 12/24/88

M. Ledt 12/24/88  
Independent Verifier Date



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:

TENDON SURVEILLANCE PROCEDURE

NO:

2402.04

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36

REVISION 2

DATE 02/12/88

CHANGE

DATE

32450  
FIELD  
END

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) 02/3/10/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

02/4/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?

Yes \_\_\_\_\_ No X

02/4/19/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/2

02/12/24/88

1/4 GAL. USED TO COAT  
ANCHORAGE COMPONENTS 02/24/88



880 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 4 of 5


ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. 32H50  
LOCATION FIELD

BY *[Signature]*  
DATE 2/24/88  
APPROVED BY *[Signature]*  
DATE 4/20/88

FILLER COVERAGE	
CAP	80%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%
CORROSION LEVEL	
BUTTONHEADS	1
ANCHOR HEAD	1
SHIMS	1
BEARING PLATE	1

SHIM STACK 6.1" (3,3)  
OFF SIZE BUTTONHEADS MARKED  
LARGE



LEGEND FOR CORROSION LEVEL  
 #1 BRIGHT METAL, NO VISIBLE OXIDATION  
 #2 REDDISH BROWN - NO PITTING  
 #3 0 < PITTING < .003"  
 #4 .003" < PITTING < .006"  
 #5 .006" < PITTING < .010"

NOTE  
 THE LOCATION OF THE  
 ANCHOR HEAD MK NUMBER  
 SHALL BE INDICATED ON  
 THE SKETCH TO DEFINE  
 BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - ◐ WIRE REMOVED PREVIOUSLY
  - ◑ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

32H50  
FIELD

ATTACHMENT 5  
DATA SHEET

Page 5 of 5

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

CS 2/24/88

B. Containment Temperature (T2)

N/A °F.

CS 2/24/88

Average Temperature (T3) N/A °F.

CS 2/24/88

3. Tendon repacked with heated Filler material?

\* N/A No N/A

CS 2/24/88

Amount of filler material repacked into tendon (Gal) N/A

CS 2/24/88

Filler Temperature at the Pump N/A °F.

CS 2/24/88

Filler Cap Installed.

N/A CS 2/24/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A CS 2/24/88

8.4.2 Attach pumping unit hose to tendon.

N/A CS 2/24/88

8.4.3 verify that all valves, vents and drains are open. (AIR VENTED)

N/A CS 2/24/88

8.4.4 Amount of Filler material repacked into tendon. 3 1/2 (gal) + 1/4 COATED = 3 3/4 TOTAL

CS 2/24/88

8.4.5 Filler Temperature at the pump 130 °F

CS 2/24/88

8.4.6 Filler Installation Pressure N/A psi

CS 2/24/88

8.4.7 Ambient Temperature (T1) 58 °F

CS 2/24/88

8.4.8 Date Filler Cap Installed 2/24/88

CS 2/24/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs TWO PASSES

N/A Ft-lbs

Torque Wrench used TW-382

CS 2/24/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

N/A ft-lbs

Torque Wrench used TW-382

CS 2/25/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit 2 DATE: 2/24/88  
TENDON NO.: 3D104 TENDON END/BUTTRESS NO.: SHOP SURVEILLANCE 4th  
OTHER TENDON END LOCATION INFO: West of Buttress 1

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(11.) OWNER/AGENT NOTIFIED Yes No  DATE \_\_\_\_\_  
CONDITION: OBSERVABLE  SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No   
(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. Leach Level II Date 2/24/88  
QC Review [Signature] Level III Date 3/22/88  
Title MGR, Q.C.

D83.4 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number 3D104 DMZ 12/24/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End  
Shop End N/A DMZ 12/24/88
- 8.1.3 Volume of Sheathing Filler Removed: 3 gal. DMZ 12/24/88
- 8.1.4 Ambient Air Temperature (T1): 58 °F DMZ 12/24/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) N/A °F. DMZ 12/24/88
  - B. Inside Containment Temperature (T2) N/A °F. DMZ 12/24/88
  - C. Average Temperature (T3) N/A °F. DMZ 12/24/88
  - D. Desired Filler Material Level N/A ". DMZ 12/24/88
  - E. Actual Filler Material Level N/A ". DMZ 12/24/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No  DMZ 12/24/88
  - B. Tan Colored after 24 hours? Yes \_\_\_\_\_ No \_\_\_\_\_ N/A  DMZ 12/24/88

Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No  DMZ 12/24/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
Shop End  
Field End

DMZ 12/24/88  
N/A DMZ 12/24/88

DMZ 12/24/88  
Independent Verifier Date

084 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.C48

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

3D104  
SHOP END

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
Shop or Field end) EB 3/10/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

EB 4/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X

2nd Sample Testing Results:  
Sat \_\_\_\_\_ Unsat \_\_\_\_\_

F/A X

Filler Material Require Replacement?  
Yes \_\_\_\_\_ No X

EB 4/19/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 12/24/87

1/2 Gal. Cold packed  
Around Anchorage Components

ML 12/24/87

D85 of 11



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 4 of 5

10<sup>th</sup> ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

PC233-18 (142 fire stamped)

BY *M. Leal*  
DATE 2/24/88  
APPROVED BY *[Signature]*  
DATE 3/22/88

### FILLER COVERAGE

CAP	100%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%

### CORROSION LEVEL

BUTTONHEADS	1
ANCHOR HEAD	1 (mill scale)
SHIMS	1
BEARING PLATE	1

Shim Stack 4 5/8" (1" 3/8", 3/16", 3")


Co/Wo-Co #GNG-003

Bearing Plate PC224 AR251

LEGEND FOR CORROSION LEVEL

- #1 BRIGHT METAL, NO VISIBLE OXIDATION
- #2 REDDISH BROWN - NO PITTING
- #3 0 < PITTING < .003"
- #4 .003" < PITTING < .006"
- #5 .006" < PITTING < .010"

TENDON NO. 3D104  
LOCATION SHOP



NOTE

- 1. THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD found to be 1/16" - 1/8"
  - BUTTONHEAD WITH SPLIT
  - ◐ WIRE REMOVED PREVIOUSLY
  - ◑ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE

086 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

3D104  
SHOP End

## ATTACHMENT 5 DATA SHEET

Page 5 of 5

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

- A. Ambient Temperature (T1) N/A °F.
- B. Containment Temperature (T2) N/A °F.
- C. Average Temperature (T3) N/A °F.

ML 12/24/88  
ML 12/24/88  
ML 12/24/88

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

ML 12/24/88

Amount of filler material repacked into tendon (Gal) N/A

ML 12/24/88

Filler Temperature at the Pump N/A °F.

ML 12/24/88

Filler Cap Installed.

N/A ML 12/24/88

### 8.4 Dome and Hoop Repacking

#### 8.4.1 Purge pumping hose of old filler material.

N/A ML 2/25/88

#### 8.4.2 Attach pumping unit hose to tendon.

N/A ML 2/25/88

#### 8.4.3 verify that all valves, vents and drains are open. (Air Vented)

N/A ML 2/25/88

#### 8.4.4 Amount of Filler material repacked into tendon. 3 1/2 (gal) + 1/2 Gal. Control = 4 Total

ML 2/25/88

#### 8.4.5 Filler Temperature at the pump 180 °F

ML 2/25/88

#### 8.4.6 Filler Installation Pressure N/A psi

ML 2/25/88

#### 8.4.7 Ambient Temperature (T1) 54 °F

ML 2/25/88

#### 8.4.8 Date Filler Cap Installed 2/24/88

ML 2/24/88

### 8.5 Tendon Resealing

#### 8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } Two Passes  
50 Ft-lbs }

Torque Wrench used TW-321

ML 2/24/88

#### 8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

Torque Wrench used TW-321

ML 2/25/88

087 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 7

Page 8 of 8

## INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 13, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit 2 DATE: 2/23/88  
TENDON NO.: 3D104 TENDON END/BUTTRISS NO.: Field End SURVEILLANCE 4th  
OTHER TENDON END LOCATION INFO: North of Buttress 3  
SOUTH EG 2/24/88

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No  Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments: N/A

(11.) OWNER/AGENT NOTIFIED Yes  No  DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes  No  N/A

(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Signoff M. Led Level II Date 2/23/88

QC Review [Signature] Level III Date 3/22/88  
Title MGR, Q.C.





D 89 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE	24 of 36	
REVISION	2	DATE 02/12/88
CHANGE		DATE

3D104  
FIELD End

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing:  
Shop or Field end) 02/10/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

02/14/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X  
2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_  
N/A X

Filler Material Require Replacement?  
Yes \_\_\_\_\_ No X

02/14/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 12/23/87

1/4 Gal. Cold Packed  
Around Anchorage components ML 2/23/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

ARKANSAS UNIT 2  
10<sup>th</sup> YR TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. 3D104


LOCATION Field End

PC243-690

BY M. L. [Signature]  
DATE 2/23/88  
APPROVED BY [Signature]  
DATE 3/22/88

FILLER COVERAGE	
CAP	100%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%
CORROSION LEVEL	
BUTTONHEADS	1
ANCHOR HEAD	1 (Same as Scale)
SHIMS	1
BEARING PLATE	1

Shim Stack 4 7/8" (1", 1/4", 1/2", 3")  
Co/No-60 # GNG-003



LEGEND FOR CORROSION LEVEL

#1 BRIGHT METAL, NO VISIBLE OXIDATION  
 #2 REDDISH BROWN - NO PITTING  
 #3 0 < PITTING < .003"  
 #4 .003" < PITTING < .006"  
 #5 .006" < PITTING < .010"

NOTE

THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD FOUND TO BE LARGE
  - BUTTONHEAD WITH FLIT
  - ⊙ WIRE REMOVED PREVIOUSLY
  - ⊘ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

SD104  
FIELD

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

ML 12/23/88

B. Containment Temperature (T2)

N/A °F.

ML 12/23/88

C. Average Temperature (T3) N/A °F.

ML 12/23/88

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

ML 12/23/88

Amount of filler material repacked into tendon (Gal) N/A

ML 12/23/88

Filler Temperature at the Pump N/A °F.

ML 12/23/88

Filler Cap Installed.

N/A ML 12/23/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 12/25/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/25/88

8.4.3 verify that all valves vents and drains are N/A open. (Air Vented)

ML 12/25/88

8.4.4 Amount of Filler material repacked into tendon. 4 (gal) + 1/4 Coated = 4 1/4 Total

ML 12/25/88

8.4.5 Filler Temperature at the pump 198 °F

ML 12/25/88

8.4.6 Filler Installation Pressure N/A psi

ML 12/25/88

8.4.7 Ambient Temperature (T1) 54 °F

ML 12/25/88

8.4.8 Date Filler Cap Installed 2/23/88

ML 12/23/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } Two passes  
50 Ft-lbs }

ML 12/23/88

Torque Wrench used TW-321

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

Torque Wrench used TW-321

ML 12/25/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	36 of 36		
REVISION	2	DATE	02/12/88
CHANGE		DATE	

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit II DATE: 2/24/88  
 TENDON NO.: 2D219 TENDON END/BUTTRESS NO.: SHOP SURVEILLANCE 4<sup>th</sup>  
 OTHER TENDON END LOCATION INFO: North of Buttress 3

(9.4) DURING LOOSENING OF GREASE CAN  
 (9.4.1) Water Detected Yes  No Quantity        Sample Taken Yes No  
 Comments N/A

(9.7) IN GREASE CAN  
 (9.7.1) Water Detected Yes  No Quantity        Sample Taken Yes No  
 Comments N/A

(9.8) AROUND TENDON ANCHORAGE  
 (9.8.1) Water Detected Yes  No Quantity        Sample Taken Yes No  
 Comments N/A

(9.10) DURING DETENSIONING  
 (9.10.1) Water Detected Yes  No Quantity        Sample Taken Yes No  
 Comments N/A

(11.) OWNER/AGENT NOTIFIED Yes No  DATE         
 CONDITION: OBSERVABLE        SIGNIFICANT       

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No   
 (12.2) SAMPLES STORED AT       

QC Signoff M. L. L... Level I Date 2/24/88  
 QC Review M. L. L... Level III Date 3/22/88  
 Title MGR, Q.C.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.043

# ARKANSAS NUCLEAR ONE

PAGE	23	of	36
REVISION	2	DATE	02/12/88
CHANGE		DATE	

## ATTACHMENT 5 DATA SHEET

### 8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number 2D219 ML 12/24/88
- 8.1.2 Remove the Tendon Filler Cap.  
Field End N/A ML 12/24/88  
Shop End ML 12/24/88
- 8.1.3 Volume of Sheathing Filler Removed: 2<sup>3</sup>/<sub>4</sub> gal. ML 12/24/88
- 8.1.4 Ambient Air Temperature (T1): 58 °F ML 12/24/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) N/A °F. ML 12/24/88
  - B. Inside Containment Temperature (T2) N/A °F. ML 12/24/88
  - C. Average Temperature (T3) N/A °F. ML 12/24/88
  - D. Desired Filler Material Level N/A ". ML 12/24/88
  - E. Actual Filler Material Level N/A ". ML 12/24/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No  ML 12/24/88
  - B. Tan Colored after 24 hours? Yes \_\_\_\_\_ No \_\_\_\_\_ N/A  ML 12/24/88
  - Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No  ML 12/24/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

- 8.1.5 One quart sample taken.  
Shop End ML 12/24/88  
Field End N/A ML 12/24/88
- ML 12/24/88  
Independent Verifier Date

D9L of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:

TENDON SURVEILLANCE PROCEDURE

NO:

2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36

REVISION 2 DATE 02/12/88

CHANGE DATE

2D219  
SHOP  
END

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing :

Shop or Field end) 02 3/10/88

A. Testing Results:

Sat X Unsat \_\_\_\_\_

02 4/19/88

B. Second Sample Submitted:

Yes \_\_\_\_\_ No X

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?

Yes \_\_\_\_\_ No X

02 4/19/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 2/24/88

Cold Packed 1/2 Gal. of 2090-P4  
Around Anchorage Components

ML 2/24/88

095 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 5  
DATA SHEET

Page 4 of 5

10<sup>th</sup> Yr. ARKANSAS UNIT 2  
TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. 2D219  
LOCATION SHOP

BY M.L. Led  
DATE 2/24/88  
APPROVED BY [Signature]  
DATE 3/22/88


FILLET COVERAGE

CAP 100%  
BUTTONHEADS 100%  
ANCHOR HEAD 100%  
SHIMS 100%  
BEARING PLATE 100%

CORROSION LEVEL

BUTTONHEADS 1  
ANCHOR HEAD 1 (Pit Scale)  
SHIMS 1  
BEARING PLATE 1

Shim Stack 4 7/8" (1 1/4", 1 1/2", 3")  
Co/No-60 # GAG-003



- LEGEND**
- OFF-SIZE BUTTONHEAD found to be large
  - BUTTONHEAD WITH SPLIT
  - WIRE REMOVED PREVIOUSLY
  - DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE
- NOTE**  
THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.
- LEGEND FOR CORROSION LEVEL**
- #1 BRIGHT METAL, NO VISIBLE OXIDATION
  - #2 REDDISH BROWN - NO PITTING
  - #3 0 < PITTING < .003"
  - #4 .003" < PITTING < .006"
  - #5 .006" < PITTING < .010"





PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

2D219  
SHOT

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

ML 12/24/88

B. Containment Temperature (T2)

N/A °F.

ML 12/24/88  
ML 12/24/88

C. Average Temperature (T3) N/A °F.

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

ML 12/24/88

Amount of filler material repacked into tendon (Gal) N/A

ML 12/24/88

Filler Temperature at the Pump N/A °F.

ML 12/24/88

Filler Cap Installed.

N/A ML 12/24/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 12/25/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 12/25/88

8.4.3 verify that all valves, vents and drains are open. (Air Vented)

N/A ML 12/25/88

8.4.4 Amount of Filler material repacked into tendon. 4 (gal) + 1/2 Gal. (contd) = 4 1/2 Total

ML 12/25/88

8.4.5 Filler Temperature at the pump 120 °F

ML 12/25/88

8.4.6 Filler Installation Pressure N/A psi

ML 12/25/88

8.4.7 Ambient Temperature (T1) 54 °F

ML 12/25/88

8.4.8 Date Filler Cap Installed 2/24/88

ML 12/24/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } Two Passes  
50 Ft-lbs }

ML 12/24/88

Torque Wrench used TW-321

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

50 ft-lbs

Torque Wrench used TW-321

ML 12/25/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 7

### INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit 2 DATE: 2/25/88  
TENDON NO.: 20219 TENDON END/BUTTRISS NO.: Field SURVEILLANCE 4th  
OTHER TENDON END LOCATION INFO: South of Buttriss 2

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity        Sample Taken Yes No  
Comments N/A

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity        Sample Taken Yes No  
Comments N/A

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity        Sample Taken Yes No  
Comments N/A

(9.10) DURING DETENSIONING  
(9.10.1) Water Detected Yes  No Quantity        Sample Taken Yes No  
Comments N/A

(11.) OWNER/AGENT NOTIFIED Yes  No N/A DATE         
CONDITION: OBSERVABLE        SIGNIFICANT       

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No  N/A

(12.2) SAMPLES STORED AT       

QC Signoff M. Lord Level II Date 2/25/88

QC Review [Signature] Level III Date 3/22/88  
Title: MGR, Q.C.



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 23 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET

Page 1 of 5

### 8.1 Sheathing Filler Inspection

8.1.1 Tendon Number 2D219

ML 12/25/88

8.1.2 Remove the Tendon Filler Cap:  
Field End  
Shop End

ML 12/25/88  
N/A ML 12/25/88

8.1.3 Volume of Sheathing Filler Removed: 2<sup>3</sup>/<sub>4</sub> gal.

ML 12/25/88

8.1.4 Ambient Air Temperature (T1): 58 °F

ML 12/25/88

8.1.5 Filler Material Level (Vertical Tendons)

A. Ambient Temperature (T1) N/A °F.

ML 12/25/88

B. Inside Containment Temperature (T2)  
N/A °F.

ML 12/25/88

C. Average Temperature (T3) N/A °F.

ML 12/25/88

D. Desired Filler Material Level  
N/A "

ML 12/25/88

E. Actual Filler Material Level N/A "

ML 12/25/88

8.1.6 Color Comparison

A. Tan Colored? Yes \_\_\_\_\_ No

ML 12/25/88

B. Tan Colored after 24 hours?  
Yes \_\_\_\_\_ No \_\_\_\_\_ N/A

ML 12/25/88

Sample Submitted because of Tan Colored  
Filler Material. Yes \_\_\_\_\_ No

ML 12/25/88

### INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.  
Shop End  
Field End

N/A ML 12/25/88  
ML 12/25/88

\_\_\_\_\_  
Independent Verifier

12/25/88  
Date



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

2D219  
Field end

## ATTACHMENT 5 DATA SHEET

Page 2 of 5

Sample Submitted for Testing:

Shop or Field end) 02 3/10/88

A. Testing Results:

Sat X Unsat \_\_\_\_\_

02/4/19/88

B. Second Sample Submitted:

Yes \_\_\_\_\_ No X

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?

Yes \_\_\_\_\_ No X

02/4/19/88

### 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

ML 12/25/88

1/4 Gal. Cold Packed  
Around Anchorage Components

ML 2/25/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:

TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE	26 of 36
REVISION	2 DATE 02/12/88
CHANGE	DATE

## ATTACHMENT 5 DATA SHEET

10<sup>th</sup> Year  
 ARKANSAS UNIT 2  
 TENDON SURVEILLANCE  
 TENDON END ANCHOR SKETCH

TENDON NO. 2D219  
 LOCATION Field

BY M. Lead  
 DATE 2/25/88  
 APPROVED BY [Signature]  
 DATE 3/22/88


### FILLER COVERAGE

CAP	100%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%

### CORROSION LEVEL

BUTTONHEADS	1
ANCHOR HEAD	1 (M.II Scale)
SHIMS	1
BEARING PLATE	1

PC 239- Shim Stack 4 1/16" (1 1/2", 1/2", 3")  
 475 Co/No-60 # GANG-003



LEGEND

- OFF-SIZE BUTTONHEAD (and to be large)
- BUTTONHEAD WITH SPLIT
- ⊙ WIRE REMOVED PREVIOUSLY
- ⊖ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
- ✕ MISSING WIRE

NOTE

THE LOCATION OF THE ANCHOR HEAD MK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

LEGEND FOR CORROSION LEVEL

- #1 BRIGHT METAL, NO VISIBLE OXIDATION
- #2 REDDISH BROWN - NO PITTING
- #3 0 < PITTING < .003"
- #4 .003" < PITTING < .006"
- #5 .006" < PITTING < .010"



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

2D219  
Field End

## ATTACHMENT 5 DATA SHEET

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

- A. Ambient Temperature (T1) N/A °F.
- B. Containment Temperature (T2) N/A °F.
- C. Average Temperature (T3) N/A °F.

MMZ 12/25/88  
MMZ 12/25/88  
MMZ 12/25/88

#### 8.3.2 Tendon repacked with heated Filler material? Yes N/A No N/A

MMZ 12/25/88

Amount of filler material repacked into tendon (Gal) N/A

MMZ 12/25/88

Filler Temperature at the Pump N/A °F.

MMZ 12/25/88

Filler Cap Installed.

N/A MMZ 12/25/88

### 8.4 Dome and Hoop Repacking

#### 8.4.1 Purge pumping hose of old filler material.

N/A MMZ 12/25/88

#### 8.4.2 Attach pumping unit hose to tendon.

N/A MMZ 12/25/88

#### 8.4.3 verify that all valves, vents and drains are N/A open. (Air-Vented)

MMZ 12/25/88

#### 8.4.4 Amount of Filler material repacked into tendon. 3 3/4 (gal) + 1/4 Coated = 4 total

MMZ 12/25/88

#### 8.4.5 Filler Temperature at the pump 175 °F

MMZ 12/25/88

#### 8.4.6 Filler Installation Pressure N/A psi

MMZ 12/25/88

#### 8.4.7 Ambient Temperature (T1) 54 °F

MMZ 12/25/88

#### 8.4.8 Date Filler Cap Installed 2/25/88

MMZ 12/25/88

### 8.5 Tendon Resealing

#### 8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs } two passes  
50 Ft-lbs }

MMZ 12/25/88

Torque Wrench used TW-321

#### 8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

Torque Wrench used TW-382

MMZ 12/26/88



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE:	NO:
	TENDON SURVEILLANCE PROCEDURE	2402.048
ARKANSAS NUCLEAR ONE		PAGE 36 of 36
		REVISION 2 DATE 02/12/88
		CHANGE DATE

ATTACHMENT 7

INSPECTION FOR WATER IN THE TENDON VOID,  
IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT FOR WATER  
DATA SHEET 6.1  
JANUARY 15, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO Unit 2 DATE: 2/23/88  
 TENDON NO.: 1D327 TENDON END/BUTRESS NO.: Shop End SURVEILLANCE 4<sup>th</sup>  
 OTHER TENDON END LOCATION INFO: North of Buttress 3  
SOUTH EB 2/24/88

(9.4) DURING LOOSENING OF GREASE CAN  
 (9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments N/A

(9.7) IN GREASE CAN  
 (9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments N/A

(9.8) AROUND TENDON ANCHORAGE  
 (9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments N/A

(9.10) DURING DETENSIONING  
 (9.10.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
 Comments N/A

(11.) OWNER/AGENT NOTIFIED Yes No  DATE \_\_\_\_\_  
 CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED Yes No

(12.2) SAMPLES STORED AT \_\_\_\_\_

QC Sign-off M. Lud Level II Date 2/23/88

QC Review [Signature] Level III Date 3/22/88  
 Title MGR, Q.C.







PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE: TENDON SURVEILLANCE PROCEDURE	NO: 2402.048
<b>ARKANSAS NUCLEAR ONE</b>		PAGE 24 of 36
		REVISION 2      DATE 02/12/88
		CH/ NGE      DATE

1D327  
Shop End

ATTACHMENT 5  
DATA SHEET

Sample Submitted for Testing :  
(Shop or Field end)      CB 3/10/88

A. Testing Results:  
Sat X      Unsat \_\_\_\_\_

CB 4/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_      No X

2nd Sample Testing Results:  
Sat \_\_\_\_\_      Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?  
Yes \_\_\_\_\_      No X

CB 4/19/88

8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads  
Amount Removed (Gal.) 1/4

MTL 12/23/88

1/2 Gal. Cold Packed  
Around Anchorage components

MTL 2/23/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET


10<sup>th</sup> Year TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. 1D327  
LOCATION Shop End

BY M. Lead  
DATE 2/23/88  
APPROVED BY [Signature]  
DATE 3/22/88

Note: Level 2 corrosion  
Approx 5" x 4 1/2" (W/1/2 trust)

FILLER COVERAGE	
CAP	100%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%
CORROSION LEVEL	
BUTTONHEADS	#1
ANCHOR HEAD	1 & 2 (See Note)
SHIMS	1
BEARING PLATE	1
Shim Size 4 3/4" (#1, 3/4", 1/4", 3")	
Co/No Co # GMG-003	



LEGEND FOR CORROSION LEVEL

- #1 BRIGHT METAL, NO VISIBLE OXIDATION
- #2 REDDISH BROWN - NO PITTING
- #3 0 < PITTING < .003"
- #4 .003" < PITTING < .006"
- #5 .006" < PITTING < .010"

NOTE: THE LOCATION OF THE ANCHOR HEAD PK NUMBER SHALL BE INDICATED ON THE SKETCH TO DEFINE BUTTONHEAD ORIENTATION.

LEGEND

- OFF-SIZE BUTTONHEAD (found)
- BUTTONHEAD WITH SPLIT
- ◐ WIRE REMOVED PREVIOUSLY
- ◑ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
- ✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

1D327 shop end

## ATTACHMENT 5 DATA SHEET

Page 5 of 5

### 8.3 Vertical Tendon Repacking

#### 8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

ML 1/2/23/88

B. Containment Temperature (T2)

N/A °F.

ML 1/2/23/88  
ML 1/2/23/88

C. Average Temperature (T3) N/A °F.

#### 8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

ML 1/2/25/88

Amount of filler material repacked into tendon (Gal) N/A

ML 1/2/23/88

Filler Temperature at the Pump N/A °F.

ML 1/2/23/88

Filler Cap Installed.

N/A ML 1/2/23/88

### 8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A ML 1/2/25/88

8.4.2 Attach pumping unit hose to tendon.

N/A ML 1/2/25/88

8.4.3 verify that all valves, vents and drains are N/A open. (Air Vented)

ML 12/25/88

8.4.4 Amount of Filler material repacked into tendon. 4 1/2 (gal) + 1/2 Gal. Coated = 5 Total

ML 1/2/25/88

8.4.5 Filler Temperature at the pump 200 °F

ML 1/2/25/88

8.4.6 Filler Installation Pressure N/A psi

ML 1/2/25/88

8.4.7 Ambient Temperature (T1) 54 °F

ML 1/2/25/88

8.4.8 Date Filler Cap Installed 2/23/88

ML 12/23/88

### 8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps:

50 Ft-lbs } Two Passes  
50 Ft-lbs }

Torque Wrench used TW-321

ML 1/2/23/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

50 ft-lbs

Torque Wrench used TW-321

ML 1/2/24/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 36 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

ATTACHMENT 7

## INSPECTION FOR WATER IN THE TENDON VOID, IN THE GREASE CAN AND AROUND THE TENDON ANCHORAGES

PSC PROCEDURE SQ 6.1  
INSPECT T/R WATER  
DATA SHEET 6.1  
JANUARY 13, 1988  
Page 1 of 1  
Revision 0

PROJECT: ANO DATE: 2/23/88  
TENDON NO.: 10327 TENDON END/BUTTRSS NO.: FIELD/NEAR BUTT SURVEILLANCE 10<sup>+</sup> YR #2  
OTHER TENDON END LOCATION INFO \_\_\_\_\_

(9.4) DURING LOOSENING OF GREASE CAN  
(9.4.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.7) IN GREASE CAN  
(9.7.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.8) AROUND TENDON ANCHORAGE  
(9.8.1) Water Detected Yes  No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(9.10) DURING DETENSIONING N/A  
(9.10.1) Water Detected N/A Yes No Quantity \_\_\_\_\_ Sample Taken Yes No  
Comments \_\_\_\_\_

(11.) OWNER/AGENT NOTIFIED N/A Yes No DATE \_\_\_\_\_  
CONDITION: OBSERVABLE \_\_\_\_\_ SIGNIFICANT \_\_\_\_\_

(12.1) SAMPLES ADEQUATELY IDENTIFIED N/A Yes No

(12.2) SAMPLES STORED AT N/A

QC Signoff [Signature] Level III Date 2/23/88

QC Review [Signature] Level II Date 4/20/88

Title Q.C. Inspector



PLANT MANUAL SECTION: MECHANICAL MAINTENANCE	PROCEDURE/WORK PLAN TITLE:	NO:
	TENDON SURVEILLANCE PROCEDURE	2402.048
ARKANSAS NUCLEAR ONE		PAGE 23 of 36
		REVISION 2 DATE 02/12/88
		CHANGE DATE

ATTACHMENT 5  
DATA SHEET

8.1 Sheathing Filler Inspection

- 8.1.1 Tendon Number 10327 CB 12/23/88
- 8.1.2 Remove the Tendon Filler Cap.
  - Field End CB 12/23/88
  - Shop End N/A CB 12/23/88
- 8.1.3 Volume of Sheathing Filler Removed: 2 1/2 gal. CB 12/23/88
- 8.1.4 Ambient Air Temperature (T1): 44 °F CB 12/23/88
- 8.1.5 Filler Material Level (Vertical Tendons)
  - A. Ambient Temperature (T1) N/A °F. CB 12/23/88
  - B. Inside Containment Temperature (T2) N/A °F. CB 12/23/88
  - C. Average Temperature (T3) N/A °F. CB 12/23/88
  - D. Desired Filler Material Level N/A ". CB 12/23/88
  - E. Actual Filler Material Level N/A ". CB 12/23/88
- 8.1.6 Color Comparison
  - A. Tan Colored? Yes \_\_\_\_\_ No X CB 12/23/88
  - B. Tan Colored after 24 hours? Yes \_\_\_\_\_ No \_\_\_\_\_ N/A X CB 12/23/88
  - Sample Submitted because of Tan Colored Filler Material. Yes \_\_\_\_\_ No X CB 12/23/88

INDEPENDENT VERIFICATION

An Independent Verifier shall ensure that all the samples are correctly labeled indicating the correct tendon and which end of the tendon the sample was taken from.

8.1.5 One quart sample taken.  
Shop End  
Field End N/A CB 12/23/88  
CB 12/23/88

M. Lutz 12/23/88  
 Independent Verifier Date

D109 of 111



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:

TENDON SURVEILLANCE PROCEDURE

NO:

2402.048

# ARKANSAS NUCLEAR ONE

PAGE 24 of 36

REVISION 2 DATE 02/12/88

CHANGE DATE

10327  
FIELD END

ATTACHMENT 5  
DATA SHEET

Page 2 of 5

Sample Submitted for Testing :  
(Shop or Field end) CB 3/10/88

A. Testing Results:  
Sat X Unsat \_\_\_\_\_

CB 4/19/88

B. Second Sample Submitted:  
Yes \_\_\_\_\_ No X

2nd Sample Testing Results:

Sat \_\_\_\_\_ Unsat \_\_\_\_\_

N/A X

Filler Material Require Replacement?

Yes \_\_\_\_\_ No X

CB 4/19/88

## 8.2 Inspection of the Anchorage Components

8.2.1 Clean the filler material away from the  
stressing Plate and the Buttonheads

Amount Removed (Gal.) 1/4

CB 7/22/88

1/4 GAL COLD PACKED  
AROUND ANCHORAGE COMPONENTS CB 2/23/88



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

# ARKANSAS NUCLEAR ONE

PAGE 26 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

## ATTACHMENT 5 DATA SHEET


PAGE 4 OF 5

ARKANSAS UNIT 2  
10<sup>th</sup> YR. TENDON SURVEILLANCE  
TENDON END ANCHOR SKETCH

TENDON NO. 1D327  
LOCATION FIELD

BY *[Signature]*  
DATE 2/23/88  
APPROVED BY *[Signature]*  
DATE 4/26/88

PC 243-717



FILLER COVERAGE	
CAP	100%
BUTTONHEADS	100%
ANCHOR HEAD	100%
SHIMS	100%
BEARING PLATE	100%
CORROSION LEVEL	
BUTTONHEADS	#1
ANCHOR HEAD	#1
SHIMS	#1
BEARING PLATE	#1

SHIM STACK 4.7" (1" 3/8", 1/4", 3")  
OFF-SIZE BUTTONHEADS FOUND  
WERE LARGE  
GNG 003 GAUGE

LEGEND FOR CORROSION LEVEL  
#1 BRIGHT METAL, NO VISIBLE OXIDATION  
#2 REDDISH BROWN - NO PITTING  
#3 0 < PITTING < .003"  
#4 .003" < PITTING < .006"  
#5 .006" < PITTING < .010"

NOTE  
THE LOCATION OF THE  
ANCHOR HEAD MK NUMBER  
SHALL BE INDICATED ON  
THE SKETCH TO DEFINE  
BUTTONHEAD ORIENTATION.

- LEGEND
- OFF-SIZE BUTTONHEAD
  - BUTTONHEAD WITH SPLIT
  - ◐ WIRE REMOVED PREVIOUSLY
  - ◑ DISCONTINUOUS WIRE REMOVED THIS SURVEILLANCE
  - ✕ MISSING WIRE



PLANT MANUAL SECTION:  
MECHANICAL  
MAINTENANCE

PROCEDURE/WORK PLAN TITLE:  
TENDON SURVEILLANCE PROCEDURE

NO:  
2402.048

ARKANSAS NUCLEAR ONE

PAGE 27 of 36  
REVISION 2 DATE 02/12/88  
CHANGE DATE

10327  
FIELD END

ATTACHMENT 5  
DATA SHEET

Page 5 of 5

8.3 Vertical Tendon Repacking

8.3.1 Average Temperature (T3)

A. Ambient Temperature (T1) N/A °F.

CB 12/23/88

B. Containment Temperature (T2)

N/A °F.

C. Average Temperature (T3) N/A °F.

CB 12/23/88  
CB 12/23/88

8.3.2 Tendon repacked with heated Filler material?

Yes N/A No N/A

CB 12/23/88

Amount of filler material repacked into tendon (Gal) N/A

CB 12/23/88

Fill Temperature at the Pump N/A °F.

CB 12/23/88

Filler Cap Installed.

N/A CB 12/23/88

8.4 Dome and Hoop Repacking

8.4.1 Purge pumping hose of old filler material.

N/A CB 12/25/88

8.4.2 Attach pumping unit hose to tendon.

N/A CB 12/25/88

8.4.3 verify that all valves, vents and drains are N/A open.

(AIR VENTED) CB 12/25/88

8.4.4 Amount of Filler material repacked into tendon. 5 (gal) + 1/4 COATED = 5 1/4 TOTAL

CB 12/25/88

8.4.5 Filler Temperature at the pump 160 °F

ML 12/25/88

8.4.6 Filler Installation Pressure N/A psi

CB 12/25/88

8.4.7 Ambient Temperature (T1) 68 °F

CB 12/25/88

8.4.8 Date Filler Cap Installed 2-23-88

CB 12/23/88

8.5 Tendon Resealing

8.5.1 Install the filler caps.

Final torque value of the tendon filler caps: 50 Ft-lbs (TWO PASSES)

N/A Ft-lbs

Torque Wrench used TW-382

CB 12/23/88

8.5.2 Tendon filler cap retorqued after 24 hours.

Final Torque Value: 50 ft-lbs

N/A ft-lbs

Torque Wrench used TW-382

CB 12/25/88



Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

APPENDIX E - Material Certification



LUBRICANTS SINCE 1892

# PRODUCT INFORMATION

E1 of 2

CUSTOMERS PURCHASE  
 ORDER NO. 533  
 BATCH NO. 01258

*PSC approved  
 etw/wh 1/29/88*

## QUALITY CONTROL SPECIFICATION SHEET VISCOR INDUSTRIAL NO. 16A

<u>PHYSICAL PROPERTIES</u>	<u>TEST RESULTS</u>	<u>REQUIRED</u>
Pounds per Gallon @ 60°F	<u>6.45</u>	6.3 - 6.6
Specific Gravity @ 60°F	ASTM D-287 <u>0.774</u>	0.75 - 0.79
Flash Point	ASTM D-56 <u>105</u>	100 - 106
Residual Odor	<u>mild</u>	mild
Sulfur H <sub>2</sub> S/Doctor	ASTM D-130 <u>1A</u>	1B max
Aromatics Volume %	<u>6.5</u>	7.5 max

<u>CHEMICAL PROPERTIES</u>	<u>TEST RESULTS</u>	<u>REQUIRED</u>
Water Soluble Chlorides	ASTM D-512 <u>1.0</u>	2 ppm Max.
Water Soluble Nitrates	ASTM D-992 <u>1.4</u>	4 ppm Max.
Water Soluble Sulfides	APHA No. 427C (1958 Edition) <u>0.8</u>	2 ppm Max.

This certifies compliance with the specifications or requirements used by customer's Purchase Order.

BY John M. Adelle  
 CONTROL CHEMIST  
 DATE 1/26/88




**Viscosity Oil**  
 A Tenneco Company  
 Chicago, Illinois U.S.A.

# Viscosity Oil

A Tenneco Company

3200 South Western  
Chicago, Illinois 60606  
(312) 847-0224  
TWX: 910-221-0245

E20F2 

*PSC Approved  
EB 1/29/88*

PETROLIA, PA

Job Order No. 533

Lot No. 7-7518

QUALITY CONTROL SPECIFICATION SHEET  
VISCONORUST 2090P-4 CASING FILLER  
NUCLEAR GRADE

<u>PHYSICAL PROPERTIES</u>	<u>METHOD</u>	<u>RESULTS</u>	<u>REQUIRED</u>
Pound per gallon @ 60°F (15.5°C)		<u>7.5</u>	7.3-7.8
Specific Gravity @ 60°F (15.5°C)	ASTM D-287	<u>0.90</u>	0.88-0.94
Congealing Point, °F (°C)	ASTM D-938	<u>147</u>	135- <del>155</del> (57-63)
Flash Point °F (°C)	ASTM D-92	<u>425</u>	420 (215) min.
Viscosity SUS @ 210°F (98.9°C)	ASTM D-88	<u>156</u>	150-300
ASTM Consistency (cone penetration) @ 77°F (25°C)	ASTM D-937	<u>178</u>	170-200
Total Base No. (Modified)	ASTM D-974	<u>60.5</u>	35 min.
Water Content (% by Wt.)	ASTM D-95	<u>0.1</u>	0.4 Max.
<u>CHEMICAL PROPERTIES</u>			
Water Soluble Chlorides	ASTM D-512	<u>1.0</u>	2 ppm max.
Water Soluble Nitrates	ASTM D-992	<u>2.0</u>	4 ppm max.
Water Soluble Sulfides	APHA No. 427 (15th Ed.) Methylene Blue	<u>1.0</u>	2 ppm max.

This certifies compliance with the Specifications or requirements covered by Customer's Purchase Order.

BY John Schellin  
CONTROL CHEMIST

DATE 1-26-58



21286

Ten Year Visual Tendon Surveillance of the Arkansas  
Nuclear One - Unit 2 Primary Reactor Containment Building

APPENDIX F - Equipment Calibrations or Gauge Calibrations



# ARKANSAS POWER & LIGHT COMPANY

## Arkansas Nuclear One

TITLE: CALIBRATION DATA SHEET

FORM NO. 1303.154B

REV. # 1 FC #

Page 1 of 1

INSTRUMENT ID #: GNG-003 DESCRIPTOR: \_\_\_\_\_

SERIAL #: \_\_\_\_\_ Go, No-Go Gages

Accuracy ± As Specified Test Equipment Used: See TP.

Gage P/N No.	Function	Desired Reading	Micrometer Reading		Tolerance
			Before Cal.	After Cal.	
<u>GNG 003</u>	<u>'Go' Gage</u>	<u>.3906 in</u>	<u>0.3905 in</u>	<u>5 in</u>	<u>+0.000</u> <u>-0.0005</u>
	<u>'No-Go' Gage</u>	<u>.3594 in</u>	<u>0.3594 in</u>	<u>↓</u>	<u>+0.0005</u> <u>-0.000</u>

Remarks: \_\_\_\_\_

Calibration Performed By: Raymond Pugh Date: 6-29-58

Calibrated Due Date: 6-29-59

Reviewed By: Jack R. Kuhn Date: 6-29-58



ARKANSAS POWER & LIGHT COMPANY  
Arkansas Nuclear One

TITLE: MICROMETER TORQUE WRENCH

FORM NO. 1303.130B

CALIBRATION DATA SHEET

REV. 04 PC 0

Instrument ID#: TW- 382

Descriptor: \_\_\_\_\_

Serial #: 86860057206

Torque Wrench

Accuracy ± 4% Right, 6% Left

Test Equipment Used: TT-005

7.2.5 Calibration Check of Micrometer Type Torque Wrenches							
Percent of Range	Torque Wrench Setting	Before Cal		After Cal		Acceptance Tolerance	
		STD Torq	% Error	STD Torq	% Error		
20%	20 <i>41 lbs</i>	21.5	7.5	20.5	2.5	± 4%	
40%	40	41.5	3.75	40	0	± 4%	
60%	60	60.5	.83	59	1.66	± 4%	
80%	80	80	0	79	1.25	± 4%	
100%	100	100	0	98	2.0	± 4%	
7.2.7 Calibration Torque Wrench for Left Hand Torque							
20%	20 <i>41 lbs</i>	22	10.0	20	0	± 6%	
40%	40	42	5.0	40	0	± 6%	
60%	60	61	1.66	59	1.66	± 6%	
80%	80	80	0	78	2.5	± 6%	
100%	100	100	0	98.5	1.5	± 6%	

Remarks: 50-755662

Calibration Performed By: *Paul Alabab* Date: 4-28-88

Calibration Due Date: 7-27-88

Reviewed By: *John R. Ruck* Date: 5-1-88

Out-of-Calibration Report Required Date: 4-23-88

30037511531



# ARKANSAS POWER & LIGHT COMPANY Arkansas Nuclear One

WFLC CALIBRATION DATA SHEET

FORM NO. 1303.1548  
REV. 8-1 PC 1

Page 1 of 1

INSTRUMENT ID #: GNG 003

DESCRIPTOR: \_\_\_\_\_

SERIAL #: \_\_\_\_\_

Go, No-Go Gages

Accuracy: As Specified

Test Equipment Used: See TD

Gage P/N No.	Function	Desired Reading	Micrometer Reading		Tolerance
			Before Cal.	After Cal.	
<u>GENERAL</u>	'Go' Gage	<u>1.3906</u>	<u>1.3902</u>	<u>Stand</u>	<u>±.0005 in</u>
<u>GNG 003</u>	'No-Go' Gage	<u>1.3599</u>	<u>1.3599</u>	<u>↓</u>	<u>±.0005 in</u>

Remarks: JO # 746005

Calibration Performed By: Randy D. Boyd Date: 2-15-88

Calibrated Due Date: 2-15-89

Reviewed By: Jack R. ... Date: 2-15-88

10000133



# ARKANSAS POWER & LIGHT COMPANY

## Arkansas Nuclear One

TITLE: CALIBRATION DATA SHEET

FORM NO. 1303.154B

REV. # 1 PC #

Page 1 of 1

INSTRUMENT ID #: GNG - 064 DESCRIPTOR: \_\_\_\_\_  
 SERIAL #: \_\_\_\_\_ Go, No-Go Gages  
 Accuracy ± As Specified Test Equipment Used: \_\_\_\_\_

Gage P/N No.	Function	Desired Reading	Micrometer Reading		Tolerance
			Before Cal.	After Cal.	
<u>PG-3193-1</u>	<u>'Go' Gage</u>	<u>.3906 in</u>	<u>.3903 in</u>	<u>Same</u>	<u>+0.0000 in</u> <u>-0.0005 in</u>
<u>PG-3193-1</u>	<u>'No-Go' Gage</u>	<u>.3594 in</u>	<u>.3597 in</u>	<u>↓</u>	<u>+0.0005 in</u> <u>-0.0000 in</u>

Remarks: JO. # 751345

Calibration Performed By: Raymond Nyels Date: 2-23-88  
 Calibrated Due Date: 2-23-89  
 Reviewed By: Robert L. Fisher Date: 2-24-88





# ARKANSAS POWER & LIGHT COMPANY

## Arkansas Nuclear One

TITLE: CALIBRATION DATA SHEET

FORM NO. 1303.154B

REV. # 1 PC #

Page 1 of 1

INSTRUMENT ID #: GNG 064 DESCRIPTOR: PG-3193-1

SERIAL #: \_\_\_\_\_ Go, No-Go Gages

Accuracy ± As Specified Test Equipment Used: SMI 003,  
SBM-001

Gage P/N No.	Function	Desired Reading	Micrometer Reading		Tolerance
			Before Cal.	After Cal.	
<u>PG-3193-1</u>	<u>'Go' Gage</u>	<u>.3906 in</u>	<u>.3906 in</u>	<u>Same</u>	<u>+ .0005 in</u> <u>- .0005 in</u>
<u>PG-3193-1</u>	<u>'No-Go' Gage</u>	<u>.3594 in</u>	<u>.3594 in</u>	<u>↓</u>	<u>+ .0005 in</u> <u>- .0005 in</u>

Remarks: \_\_\_\_\_

Calibration Performed By: Raymond Hopt Date: 6-2-88

Calibrated Due Date: 6-2-89

Reviewed By: Jack L. L... Date: 6-8-88



# ARKANSAS POWER & LIGHT COMPANY Arkansas Nuclear One

MTLE: MICROMETER TORQUE WRENCH

FORM NO. 1303.130B

CALIBRATION DATA SHEET

REV. 04 PC 0

Instrument ID#: TW-320

Descriptor: 0-200<sup>F</sup>VI

Serial #: 12850055574

Torque Wrench

Accuracy ± 4% Right, 6% Left

Test Equipment Used: TT-005

7.2.5 Calibration Check of Micrometer Type Torque Wrenches						
Percent of Range	Torque Wrench Setting	Before Cal		After Cal		Acceptance Tolerance
		STD Torq	% Error	STD Torq	% Error	
20%	40	40	0	SAME	SAME	± 4%
40%	80	80	0	}	}	± 4%
60%	120	121	.8			± 4%
80%	160	160	0			± 4%
100%	200	201	.5			± 4%
7.2.7 Calibration Torque Wrench for Left Hand Torque						
20%	40	39	2.5	SAME	SAME	± 6%
40%	80	75.5	1.8	}	}	± 6%
60%	120	119	.8			± 6%
80%	160	159	.6			± 6%
100%	200	199	.5			± 6%

Remarks: SEE 70-741740 APTCK CHECK

Calibration Performed By: [Signature] Date: 10-23-87

Calibration Due Date: 1-12-88

Reviewed By: [Signature] Date: 10-23-87

Out-of-Calibration Report Required Date: N/A

00034980216



ARRKANSAS DEPARTMENT OF TRANSPORTATION  
 ARKANSAS HIGHWAY DEPARTMENT

MICROMETER TORQUE WRENCH

FORM NO. 10-10-100

CALIBRATION DATA SHEET

REV. 4-1-88

Instrument ID# TV 370

Description 0.125 lb

Serial # 12950088874

Torque Wrench

Accuracy  $\pm$  4% Right, 6% Left

Test Equipment 1100

7.2.5 Calibration Check of Micrometer Type Torque Wrenches

Percent of Range	Torque Wrench Setting	Before Cal.		After Cal.		Accuracy
		STD Torque	% Error	STD Torque	% Error	
20%	<u>40 FF Lbs</u>	<u>47</u>	<u>7.5%</u>	<u>49</u>	<u>0.5%</u>	<u>±5%</u>
40%	<u>80 FF Lbs</u>	<u>89</u>	<u>10.7%</u>	<u>81</u>	<u>-1.25%</u>	<u>±5%</u>
60%	<u>120 FF Lbs</u>	<u>127</u>	<u>5.83%</u>	<u>123</u>	<u>-2.5%</u>	<u>±5%</u>
80%	<u>160 FF Lbs</u>	<u>167</u>	<u>4.375%</u>	<u>159</u>	<u>-0.625%</u>	<u>±5%</u>
100%	<u>200 FF Lbs</u>	<u>206</u>	<u>3%</u>	<u>202</u>	<u>-1.5%</u>	<u>±5%</u>

7.2.7 Calibration Torque Wrench for Left Hand Torque

20%	<u>40 FF Lbs</u>	<u>45</u>	<u>12.5%</u>	<u>38.5</u>	<u>-7.5%</u>	<u>±5%</u>
40%	<u>80 FF Lbs</u>	<u>85</u>	<u>6.25%</u>	<u>79</u>	<u>-1.25%</u>	<u>±5%</u>
60%	<u>120 FF Lbs</u>	<u>124</u>	<u>3.33%</u>	<u>118</u>	<u>-0.83%</u>	<u>±5%</u>
80%	<u>160 FF Lbs</u>	<u>161</u>	<u>2.5%</u>	<u>157</u>	<u>-1.875%</u>	<u>±5%</u>
100%	<u>200 FF Lbs</u>	<u>202</u>	<u>1.5%</u>	<u>200</u>	<u>0%</u>	<u>±5%</u>

Remarks:

Calibration Performed By: Roman O. W. J. Jr. Date: 3-2-88

Calibration Due Date: 6-1-90

Reviewed By: [Signature] Date: 3-2-88

Out-of-Calibration Report Required Date: 3-2-88

9993662537



**ARKANSAS POWER & LIGHT COMPANY**  
**Arkansas Nuclear One**

TITLE: MICROMETER TORQUE WRENCH

FORM NO. 1303.130B

CALIBRATION DATA SHEET

REV. # 4 PC #

Instrument ID#: TW-321

Descriptor: Snap-on

Serial #: \_\_\_\_\_

Torque Wrench

Accuracy ± 4% Right, 6% Left

Test Equipment Used: TT-005

7.2.5 Calibration Check of Micrometer Type Torque Wrenches						
Percent of Range	Torque Wrench Setting	Before Cal		After Cal		Acceptance Tolerance
		STD Torq	% Error	STD Torq	% Error	
20%	40 <u>AL 162</u>	41	2.5	SAME	SAME	± 4%
40%	80	82	2.5	↓	↓	± 4%
60%	120	123	2.5	↓	↓	± 4%
80%	160	163	2.7	↓	↓	± 4%
100%	200	202	1	↓	↓	± 4%
7.2.7 Calibration Torque Wrench for Left Hand Torque						
20%	40 <u>AL 162</u>	40	0	SAME	SAME	± 6%
40%	80	80	0	↓	↓	± 6%
60%	120	122	1.6	↓	↓	± 6%
80%	160	162	1.25	↓	↓	± 6%
100%	200	204	2	↓	↓	± 6%

Remarks: J.C. # 747351

Calibration Performed By: [Signature] Date: 12-30-87

Calibration Due Date: 3-29-88

Reviewed By: [Signature] Date: 12-30-87

Out-of-Calibration Report Required Date: N/A



# ARKANSAS POWER & LIGHT COMPANY Arkansas Nuclear One

TITLE: MICROMETER TORQUE WRENCH

FORM NO. 1303.130B

CALIBRATION DATA SHEET

REV. # 4 PC #

Instrument ID#: TW- 321

Descriptor: \_\_\_\_\_

Serial #: 12853054804

Torque Wrench

Accuracy ± 4% Right, 6% Left

Test Equipment Used: \_\_\_\_\_

30-200 Ft Lbs

7.2.5 Calibration Check of Micrometer Type Torque Wrenches							
Percent of Range	Torque Wrench Setting	Before Cal		After Cal		Acceptance Tolerance	
		STD Torq	% Error	STD Torq	% Error		
20%	<u>40 Ft Lbs</u>	<u>40</u>	<u>0</u>	<u>SAME</u>	<u>SAME</u>	<u>± 4%</u>	
40%	<u>80</u>	<u>81</u>	<u>1.25</u>			<u>± 4%</u>	
60%	<u>120</u>	<u>124</u>	<u>3.33</u>			<u>± 4%</u>	
80%	<u>160</u>	<u>164</u>	<u>2.5</u>			<u>± 4%</u>	
100%	<u>200</u>	<u>207</u>	<u>3.5</u>			<u>± 4%</u>	

7.2.7 Calibration Torque Wrench for Left Hand Torque							
Percent of Range	Torque Wrench Setting	Before Cal		After Cal		Acceptance Tolerance	
		STD Torq	% Error	STD Torq	% Error		
20%	<u>40</u>	<u>41</u>	<u>2.5</u>	<u>SAME</u>	<u>SAME</u>	<u>± 6%</u>	
40%	<u>80</u>	<u>80</u>	<u>0</u>			<u>± 6%</u>	
60%	<u>120</u>	<u>123</u>	<u>2.5</u>			<u>± 6%</u>	
80%	<u>160</u>	<u>163</u>	<u>1.87</u>			<u>± 6%</u>	
100%	<u>200</u>	<u>205</u>	<u>2.5</u>			<u>± 6%</u>	

Remarks: JO-753759

Calibration Performed By: Daf Uchib Date: 3-31-88

Calibration Due Date: 6-29-88

Reviewed By: Jan R. Puh Date: 3-31-88

Out-of-Calibration Report Required Date: N/A

00037071970



# ARKANSAS POWER & LIGHT COMPANY Arkansas Nuclear One

TITLE: MICROMETER TORQUE WRENCH

FORM NO. 1303.130B

CALIBRATION DATA SHEET

REV. # 4 PC #

Instrument ID#: TV-382  
Serial #: 06860057206  
Accuracy ± 4% Right, 6% Left

Descriptor: QJR 2100D  
Torque Wrench  
Test Equipment Used: TT-005

7.2.5 Calibration Check of Micrometer Type Torque Wrenches

Percent of Range	Torque Wrench Setting	Before Cal		After Cal		Acceptance Tolerance
		STD Torq	% Error	STD Torq	% Error	
20%	20 <u>41 lbs</u>	20	0	<u>SAME</u>	<u>SAME</u>	± 4%
40%	40	40	0	↓	↓	± 4%
60%	60	59	1.6	↓	↓	± 4%
80%	80	80	0	↓	↓	± 4%
100%	100	99	1	↓	↓	± 4%

7.2.7 Calibration Torque Wrench for Left Hand Torque

Percent of Range	Torque Wrench Setting	Before Cal		After Cal		Acceptance Tolerance
		STD Torq	% Error	STD Torq	% Error	
20%	20 <u>41 lbs.</u>	20	0	<u>SAME</u>	<u>SAME</u>	± 6%
40%	40	41	2.5	↓	↓	± 6%
60%	60	60	0	↓	↓	± 6%
80%	80	80	0	↓	↓	± 6%
100%	100	100	0	↓	↓	± 6%

Remarks: J.O. # 743836

Calibration Performed By: [Signature] Date: 1-29-88  
Calibration Due Date: 4-28-88  
Reviewed By: [Signature] Date: 2-19-88  
 Out-of-Calibration Report Required Date: N/A

*TJR # 5234*