(9.83)	LICENSEE EVENT REPORT (LER)											U.S. NUCLEAR REGULATORY COMMISSION, APPROVED OMB NO. 3150-0104 EXPIRES 8/31/88												
FACILITY	NAME IT	1									-		-			Tooc	KET P	VUMBE	R (2)				PAGE	(3)
Millstone Nuclear Power Station Unit 3										0	0 15 10 10 10 14 12 3				2 3	110	1 OF 0 P							
TITLE (4)							CALL NO.		A.W. J. W.	American de	-					-			-	141	P	1.1.	10	-
V	iola	tic	n	of	Pla	nt T	echr	nic	al Si	necif	icat	tion !	3.8	4.1										
Violation of Plant Technica EVENT DATE (8) LER NUMBER (6)												R FAC	R FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR		YEA	Q .				REVISION		DAY	YEAR		FACILITY NAMES			DOCKET NUM			NUMBE	BER(S)			
													1							151	0 1 0	101	10111	
2	0 2	8	6	8	6 -	6 6	17	-	00	0 3	01	4 8 6	, [		in all		7		0	151	0 10	. 0 .		,
OPE	RATING			-	STATE OF THE PARTY NAMED IN	T IS SU	BMITTE	D PUR	SUANT	TO THE P	REQUIRE	MENTS O	F 10 (	CFR 5 10	Check one or more	* 0/ 1/	ie fani	(wing)		1-1				
MC	MODE (9) 4				20.402(6)					7				50.73(a)(2)(iv)					73.71(b)					
LEVE			2	-	20.406(a)(1)(ii) 20.406(a)(1)(iii)									50.73(a)(2)(v)	0			_	73.71(c) OTHER (Specify in Abstract below and in Text NRC Form					
(10)	0	101	3	-							50.38(c)(2) 50.73(s)(2)(vii)							-						
					20,406(a)(1)(iii)					50.73(a)(2)(i) 50.73(a)(2)(viii								3864						
1				20.406(a)(1)(iv)						50.73(a)(2)(ii)				50 73(a)(2)(viii)(8) 50 73(a)(2)(a)										
-	-			_		*******				_		CT FOR T	MIS I	59 (12)	90.73(8)(2)(A)	-	-	-					-	
NAME		-	-								69111	GT TON	110	EN 118		-		-	TE	LEPHON	E / UN	MER		-
																	AREA CODE							-
Robert N. Keller, Associate Engineer								0	ß	4	4 7	*1	1 0	7 8	11									
						CON	APLETE	ONE L	INE FOR	EACH C	OMPONE	ENT FAILL	JAE D	DESCRIBE	D IN THIS REPO	TRO	13)			-	-	-		-
CAUSE	SYSTEM	cr	COMPONENT			MANUFAC F		REPORTABLE TO NPRDS		HERM		CAL	CAUSE SYSTE		COMPONENT		MANUFAC			REPORTABLE TO NPROS		ATE		
А	EΑ							N							1.1.1									
			1 1	1		1 1											1							
		-	-		-	SU	PPLEME	NTAL	REPORT	EXPECT	ED (14)					+			-		MONTH	T CAY	-	YEAR
								7	8	EXPEC	5510h			1	+									
YES	of year o	ampil	re Ex	(PECT	TED SUE	MISSIO	N DATE			3	X NO							DATE	(15)			1		1

On 2/2/86 at 1420 hours, with the plant operating normally in Mode 2, it was discovered that the limiting condition for operation and action statement for Technical Specification 3.8.4.1 had not been met. Technical Specification 3.8.4.1 requires verification, once per seven days, that each inoperable containment electrical penetration protective circuit breaker is racked out or removed, or its backup circuit breaker is tripped. The plant entered Mode 4 on 1/13/86 at 0417 hours, at which time there were nine containment penetration breakers inoperable (with their backup circuit breakers tagged in the trip position). The required verification had not been performed since that date, but was completed immediately upon discovery of the violation.

Investigation into the incident revealed apparent cause to be a failure to adequately track this weekly surveillance requirement. To preclude recurrence, the action statement for Limiting Condition of Operation 3.8.4.1 has been added to the Operations Department Surveillance Tracking System. In addition, all I miting conditions for operation that cannot be met are identified on the daily schedule with individual department responsibilities assigned.

This report is being submitted in accordance with 10CFR50.73 (a) (2) (i) (B).

8603100542 860304 PDR ADOCK 05000423 PDR 1000

NRC Form 366A (9-8-)	LICENSEE EVENT REPO		EGULATORY COMMISSION OMB NO 3150-0104 31/88					
FACILITY NAME (1)		DOCKET NUMBER (2)	L	ER NUMBER (6)		PAGE (3)		
Millsto	ne Nuclear Power Station		YEAR	SEQUENTIAL	REVISION NUMBER			
Unit 3	ie nacrear romer seatron	0  5  0  0  0   1 2   2	d 6 -	dda	- 010	N o OF	ola	

On 2/2/86 at 1420 hours, with the plant operating normally in Mode 2 at 3% power level, it was discovered that the limiting condition for operation and action statement for Technical Specification 3.8.4.1 had not been met. Technical Specification 3.8.4.1, which is applicable in Modes 1 through 4, requires that each containment electrical penetration protective circuit breaker be operable. If one or more are declared inoperable, the Technical Specification Action Statement requires that the following be done once per seven days: Verify that the inoperable breaker(s) are removed or racked out of service, or its backup circuit breaker is tripped. On 1/11/86, while the plant was in Mode 5, a total of nine containment penetration breakers were declared inoperable due to a lack of satisfactory test data. The backup circuit breakers for each were tagged in the trip position on that date. Two days later, on 1/13/86 at 0417 hours, the plant entered Mode 4, at which time Technical Specification 3.8.4.1 became applicable. The required verification was not performed from 1/13/86 to 2/2/86, but was completed immediately upon discovery of the violation.

Apparent cause of the incident was a failure to adequately track the seven day surveillance requirements of Technical Specification 3.8.4.1. The Maintenance Department notified Operations on 1/11/86 that the breakers were inoperable. At that time it became Operations' responsibility for meeting the action statement when the limiting condition for operation became applicable. The Operations Department failed to adequately address the administrative tracking of the weekly requirement.

The action statement for Technical Specification 3.8.4.1 has since been added to the Operations Surveillance Tracking System. In addition to this, all limiting conditions for operation that cannot be met are now carried on the daily schedule for promulgation to all departments.

There were no immediate safety concerns to the public or plant as a result of this incident. In order for an accident to occur related to this violation, three failures would have to occur simultaneously: 1) A failure of the Plant Administrative Tagging System whereby tags would be erroneously removed and a circuit energized without declaring the penetration circuit breaker fully operable; 2) A fault would have to occur downstream of the containment electrical penetration which would draw enough overcurrent to challenge the integrity of the penetration, and; 3) The secondary backup circuit breaker would have to fail to trip on overcurrent. None of these failures actually took place.

This report is being submitted in accordance with 10CFR50.73 (a) (2) (i) (B).



General Offices . Selden Street, Berlin, Connecticut

P.O. BOX 270 HARTFOPD, CONNECTICUT 06141-0270 (203) 666-6911

March 4, 1986 MP-8778

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

Reference:

Facility Operating License No. NPF-49

Docket No. 50-423

Licensee Event Report 50-423/86-007-00

Gentlemen:

This letter forwards Licensee Event Report 86-007-00 required to be submitted within thirty days pursuant to 10CFR50.73 (a) (2) (i) (B), any operation or condition prohibited by the Plant's Technical Specifications.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

Way o An

Wayne D. Romberg Station Superintendent Millstone Nuclear Power Station

WDR/RNK:se

Attachment: LER 86-007-00

cc: Dr. T. E. Murley, Region I

IE22