

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1): Millstone Nuclear Power Station Unit 3 DOCKET NUMBER (2): 05000423 PAGE (3): 1 OF 02

TITLE (4): Feedwater Isolation Due to Main Steam/Feedwater Transient

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		MONTH	DAY	YEAR	FACILITY NAMES		
02	06	86	01	2	00	03	07	86			
									DOCKET NUMBER(S):		
									050000		
									050000		

OPERATING MODE (9): 1

POWER LEVEL (10): 0115

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11):

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(c)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.38(a)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.38(a)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(vii)(A)	
<input type="checkbox"/> 20.405(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(vii)(B)	
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12):

NAME: Paul G. Atkinson III, Associate Engineer TELEPHONE NUMBER: 2101341471-1171911

AREA CODE: 210

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13):

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
A	J	P	W	N					

SUPPLEMENTAL REPORT EXPECTED (14):

YES (if yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15):

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16):

At 1025 hours on 2/6/86, while operating at 15% power, the plant received a Feedwater Isolation signal from the high-high water level off of Steam Generator "C". High water level in Steam Generator "C" was the end result of a Steam/Feedwater transient initiated by the Turbine Bypass (Steam Dump) valves modulating closed. All Engineered Safety Features Systems actuated properly. The restoration from Feedwater Isolation was performed in accordance with plant procedures.

Subsequent investigation revealed that the Main Steam Supply Header pressure signal was momentarily shorted out in the process of installing a temporary strip chart recorder. This caused the Main Steam Supply Header pressure to momentarily fail to zero (0) psig which caused the Turbine Bypass (Steam Dump) valves to modulate closed. The resulting Main Steam/Feedwater transient caused a high-high water level in Steam Generator "C" which initiated a feedwater isolation.

This report is being submitted in accordance with 10CFR50.73 (a) (2) (iv).

IE 22  
1/1

8603110332 860307  
PDR ADOCK 05000423  
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Millstone Nuclear Power Station Unit 3	DOCKET NUMBER (2)  050004238	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		86	0112	00	02	02

TEXT (if more space is required, use additional NRC Form 366A 2/ (17))

At 1025 hours on 2/6/86, while operating at 15% power, the plant received a Feedwater Isolation signal from the high-high water level off of Steam Generator "C". High water level in Steam Generator "C" was the end result of a Steam/Feedwater transient initiated by the Turbine Bypass (Steam Dump) valves modulating closed. All Engineered Safety Features Systems actuated properly. The restoration from Feedwater Isolation was performed in accordance with plant procedures.

An investigation revealed that the Main Steam Supply Header pressure signal was momentarily shorted out during the installation of a temporary strip chart recorder. The recorder was being installed to support Turbine Bypass (Steam Dump) valve testing as a part of the Power Ascension Test Program.

The Main Steam Supply Header pressure signal is provided as an analog signal for Turbine Bypass Valve control, Main Turbine Driven Feedpump speed control, and Main Control Board indication. Shorting out this signal caused Main Steam Supply header pressure to signal zero (0) psig. This resulted in the Turbine Bypass Valves modulating closed. The short was discovered immediately and removed. Upon removal of the short, the Turbine Bypass Valves modulated full open.

The Feedwater Bypass Flow Control Valves and Turbine Bypass Valves were changed to manual control to maintain Reactor Coolant System temperature and Steam Generator level. However, subsequent swelling in Steam Generator "C" initiated a high-high level Feedwater Isolation. All systems responded as required during the Feedwater Isolation and restoration was performed in accordance with plant procedures.

Further investigation revealed that the test probes on the leads assembled by the I&C department to connect the strip chart recorder to the Westinghouse 7300 Driver Card for the Main Steam Supply header pressure signal were of too great a length. Upon installation, the end of the pins shorted out on the Driver Card.

The I&C department modified the test probes on the leads used for connection of the strip chart recorder in this application and directed that all leads assembled to be used in similar applications be modified. In addition, a Technical Bulletin was issued within the I&C department and a department meeting was held to inform I&C technicians of this problem.

There were no safety implications to the public as all equipment performed its intended function.

This report is being submitted as required by 10CFR50.73 (a) (2) (iv).

# NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY  
WESTERN MASSACHUSETTS ELECTRIC COMPANY  
HOLYOKE WATER POWER COMPANY  
NORTHEAST UTILITIES SERVICE COMPANY  
NORTHEAST NUCLEAR ENERGY COMPANY

General Offices • Selden Street, Berlin, Connecticut

P.O. BOX 270  
HARTFORD, CONNECTICUT 06141-0270  
(203) 666-6911

March 7, 1986  
MP-8793

U. S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D. C. 20555

Reference: Facility Operating License No. NPF-49  
Docket No. 50-423  
Licensee Event Report 50-423/86-012-00

Gentlemen:

This letter forwards Licensee Event Report 86-012-00 required to be submitted within thirty days pursuant to 10CFR50.73 (a) (2) (iv), any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF).

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

*Wayne D. Romberg*

Wayne D. Romberg  
Station Superintendent  
Millstone Nuclear Power Station

WDR/PGA:se

Attachment: LER 86-012-00

cc: Dr. T. E. Murley, Region I

IER  
1/1