NRC Form 366 (9.63)						(LER)	U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88					
FACILITY NAME (1)				-		-	-		DOCKET NUMBER	(2)	PAC	SE (3)
Wolf Creek Generating Station							0  5   0   0	10141812	1 OF	013		
In Sur	cal S	Speci:	fication Procedu	Violat	ion Caused	by C	hanne	1 Check F			Andrewson of the company	market and the state of
EVENT DATE (8)			LER NUMBER (6	printering and transport and	REPORT DATE	(7)	OTHER FACILITIES INV			Market Control of the		
MONTH DAY YE	EAR Y	YEAR SEQUENTIAL REVISION MONTH DAY YEAR FACILITY NAMES		LMES	DOCKET NUMBER(S)							
							1			0  5  0  0	101	
018218	8 8	8 8	0114	- 00	0 9 1 9	8   8			THE S	0   5   0   0	101	
OPERATING MODE (9)	TH	IS REPOR	T IS SUBMITTED	PURSUANT 1	TO THE REQUIREMEN	8 OF 10	OFR S. /	thack one or more	of the following) (11	1)		
MODE (9)	11	20 4021		-	20.406(e)		-	60.73(a)(2)(iv)		73.71(6)		
POWER	-	20.406		-	50.38(e)(1)			50.73(a)(2)(v)		73.71(e)		
(10) 1 11 010		20.406(a)(1)(iii) 20.406(a)(1)(iii)			50.78(a)(2)(i)		_	50.73(a)(2)(vii)		OTHER (Specify in Abstract below and in Text, NRC Form		
							50.73(a1(2))(viii)(A)		3664)			
		20.405(a)(1)(iv)		-	50.73(a)(2)(ii)		-	50.73(a)(2)(viii)(B) 50.73(a)(2)(x)		10 35 7		
	20.406(a)(**\x\)   50.73(a)(2)(iii)   50   LICENSEE CONTACT FOR THIS LER (12)			DO:73(8)(2)(K)	734(4)(4)							
NAME	-	-	-		TOURSE CONTINUE	TOR THIS	64M (14)	-		TELEPHONE NUM	BER	
									AREA CODE	6		
Merlin	G. Wi	lliar	ns - Man	ager Pl	ant Suppor	t ·	X		31.1.16	3 6 4 -	1818	1311
			COMPLETE C	NE LINE FOR	EACH COMPONENT	PAILURE	DESCRIBE	D IN THIS REPO		L-24-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4	13.10	L-X-L-
CAUSE SYSTEM C	OMPONE	NT .	MENUFAC- TURER	REPORTABLE TO NPROS		CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	REPORTABLE TO NPROS		
	11				Programme and the second			111	111			
	11		111									
SUPPLEMENTAL REPORT EXPECTED (14)							EXPECTED MONTH DAY		DAY	YEAR		
YES III yes, complete EXPECTED SUBMISSION DATE! X NO						SUBMISSION DATE (15)						
ABSTRACT (Limit to 14	00 комова	18. 80010	almately fifteen a	ingle-space fyipe	movemen lines (16)							

On August 21, 1988, at approximately 1806 CDT, Operations personnel discovered that the surveillance procedure for the Engineered Safety Features Actuation System Auxiliary Feedwater Pump Low Suction Pressure Instrumentation Channel Check did not meet the surveillance requirements of Technical Specification (T/S) 4.3.2.1. Subsequent review determined that the surveillance procedure had not met the T/S surveillance requirements since May 2, 1985.

The root cause of this event was determined to be two separate errors. The first by contractor procedure writers in changing the channel check instrumentation identified in the surveillance procedure when a revision was made. The second by the individuals involved in the procedure review process who did not identify this error. A detailed recreation of the circumstances surrounding the revision to the surveillance procedure could not be made because some of the personnel involved are no longer employed at Wolf Creek Generating Station. Therefore, the cause of the channel check instrumentation being changed in the surveillance procedure could not be determined. A temporary procedure change was issued to correct the surveillance procedure on August 22, 1988. A review of this surveillance procedure meets the T/S surveillance requirements.

8809260068 880821 PDR ADDCK 05000482 IE22

LICENSEE EVENT R	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION					
FAC LITY NAME (1)	DOCKET NUMBER (2)	LER NUMBE	R (6)	PAGE (3)		
		YEAR SEQUENT	REVISION NUMBER			
Wolf Creek Generating Station	0 15 10 10 10 1 41 812	8:8 - 0:1	4 - 010	0 12 OF 0 13		

EXT Iff more space is required, use additional NRC Form 366A's) (17

#### INTRODUCTION

On August 21, 1988, at approximately 1806 CDT, Operations personnel performing a routine review as a result of ongoing maintenance activities, discovered that STS CR-001, the surveillance procedure for the performance of Engineered Safety Features Actuation System (ESFAS) [JE] Auxiliary Feedwater Pump [BA-P] Low Suction Pressure Instrumentation [BA-PI] Channel Check did not meet the surveillance requirements of Technical Specification (T/S) 4.3.2.1. Subsequent review determined that surveillance procedure STS CR-001, "Shift Log for Modes 1, 2 and 3", had not met the T/S surveillance requirements for Modes 1, 2, and 3 since May 2, 1985. This event is being reported pursuant 10CFR50.73(a)(2)(i)(B) as a violation of the plant's T/S.

# DESCRIPTION OF EVENTS

The T/S surveillance requirement 4.3.2.1 requires that each ESFAS instrumentation channel shall be demonstrated operable by the performance of the ESFAS Instrumentation Surveillance Requirements specified in Table 4.3-2 of the T/S. Table 4.3-2 of the T/S requires that the ESFAS Auxiliary Feedwater Pump Low Suction Pressure Instrumentation is demonstrated operable by periodic performance of surveillances that require:

- A channel check at least once per 12 hours,
- b. An Analog Channel Operational Test (ACOT) at least once per 31 days, and
- c. A channel calibration at least once per 18 months.

The requirements of the channel check of the ESFAS Auxiliary Feedwater Pump Low Suction Pressure Instrumentation was originally in STS CR-001, Revision 0. On May 2, 1985, when a revision was made to the surveillance procedure, the instrumentation identified in the procedure was changed from the ESFAS instrumentation to other installed Auxiliary Feedwater Pump Suction pressure indicators [BA-PI]. Therefore, the incorrect instrumentation was surveilled from May 2, 1985, until August 21, 1988, when the error was discovered.

### ROOT CAUSE

The root cause of this event was determined to be two separate errors. The first by contractor procedure writers in changing the instrumentation identified in the surveillance procedure when the revision was made and the second, by the individuals involved in the procedure review process who did not identify this error. A detailed recreation of the circumstances surrounding the revision to the surveillance procedure could not be made because some of the personnel are no longer employed at Wolf Creek Generating Station. Therefore, the cause of the channel check instrumentation being changed in the surveillance procedure could not be determined. The "reason for change" procedure change form states, "Add NRC comments, update to current format, correct refs (references) and numbers to current T/S", which does not give enough detail to determine why the specified instrumentation was changed.

LICENSEE EVENT RE	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION					
FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUM	SER (6)	PAGE (3)		
		YEAR SEQUE	NTIAL PEVISION			
Wolf Creek Generating Station	0  5   0   0   0   4   8   2	318 - 011	14-010	013 05 0 13		

TEXT III more space is required, usr additional NRC Form 366A's) (17)

# CORRECTIVE ACTIONS

Upon discovery of this event, Operations personnel began surveilling the correct instrumentation and initiated a procedure change to correct STS CR-001. A temporary procedure change was issued to correct the surveillance procedure on August 22, 1988. This change will incorporated as a permanent change to the surveillance procedure. A review of this surveillance procedure has been conducted to ensure that this surveillance procedure meets the T/S surveillance requirements. In addition, an in-depth review of the entire T/S surveillance requirements to ensure that they are procedurally addressed is being conducted.

# ADDITIONAL INFORMATION

Although the ESFAS for the Auxiliary Feedwater Pump Low Suction Pressure Instrumentation channel check was not being adequately performed as required by T/S 4.3.2.1, the instrumentation was operable throughout this event. This was verified by the satisfactory completion of a daily checklist that includes the ESFAS Auxiliary Feedwater Pump Low Suction Pressure Instrumentation, and the monthly ACOT and 19-month channel calibration also required by T/S 4.3.2.1. Therefore, at no time during this event did conditions develop that posed a risk to the health or safety of the public. There was no damage of plant equipment or release of radioactivity during this event.

Licensee Event Report (LER) 88-004-00 discusses a previous T/S violation caused by this particular procedure revision. The corrective actions discussed in that report are specific to that event and therefore had no effect on this event. LER 87-029-00 discusses an occurrence of a T/S requirement being deleted from surveillance procedure. The changes and enhancements made to the procedure review and change process as a result of the events discussed in LER 87-029-00 should prevent future occurrences of this event.



Bart D. Withers President and Chief Executive Officer

September 19, 1988

WM 88-0231

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Mail Station P1-137 Washington, D. C. 20555

Subject: Docket No. 50-482: Licensee Event Report 88-014-00

Gentlemen:

The attached Licensee Event Report (LER) is submitted pursuant to 10 CFR 50.73 (a) (2) (i) concerning a Technical Specification violation.

Very truly yours,

Bart D. Withers

President and

Chief Executive Officer

BDW/jad

Attachment

oc: B. L. Bartlett (NRC), w/a

D. D. Chamberlain (NRC), w/a

R. D. Martin (NRC), w/a

P. W. O'Connor (NRC), w/a (2)