TENNESSEE VALLEY AUTHORITY CHATTANOOGA, TENNESSEE 37401 5N 157B Lookout Place MAY 19 1988

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555

Gentlemen:

In the Matter of Tennessee Valley Authority Docket No. 50-328

SEQUOYAH NUCLEAR PLANT (SQN) UNIT 2 - STEAM GENERATOR (S/G) TUBE PLUGGING

On April 5, 1988, SQN identified a primary-to-secondary leak on unit 2. Enclosed is the status of the tubes plugged in each unit 2 S/G. Also noted are the tubes that were previously plugged. The unit 2 row 1 tubes have been plugged as a preventative measure but may be returned to service after heat treatment and eddy current testing of the S/G tubes in a future outage.

If you have any questions concerning this matter, please call M. R. Harding at (615) 870-6422.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

R. Gridley, Director Nuclear Licensing and Regulatory Affairs

Enclosure cc: See page 2

8805310160 880519 PDR ADOCK 05000328 S PDR

Do30

cc (Enclosures):

4.3

Mr. K. P. Barr, Acting Assistant Director for Inspection Programs TVA Projects Division U.S. Nuclear Regulatory Commission Region II 101 Marietta Street, NW, Suite 2900 Atlanta, Georgia 30323

Mr. G. G. Zech, Assistant Director for Projects TVA Projects Division U.S. Nuclear Regulatory Commission One White Flint, North 11555 Rockville Pike Rockville, Maryland 20852

Sequoyah Resident Inspector Sequoyah Nuclear Plant 2600 Igou Ferry Road Soddy Daisy, Tennessee 37379

SON Unit 2 S/G Plugged Tubes

The following provides a summary of the status of unit 2 S/G tubes that were plugged as corrective and preventative actions taken to ensure S/G integrity.

SI	G	No.	1	(a)	

	Row	Column	Indication % / Test Method	Location	Reason for Plugging
	1	1-94	N/A / N/A	N/A	Prevent. measure
S/G	No. 2	(6)			
	Row	Column	Indication % / Test Method	Location	Reason for Plugging
	1	1-94	N/A / N/A	N/A	Prevent. measure
S/G	No. 3	(c)			
	Row	Column	Indication % / Test Method	Location	Reason for Plugging
	1	3 39	60/ECT* 97/ECT 100/Hellum leak test	U-Bend U-Bend	Req. by TS Req. by TS
	1	48 49 1-94	100/Helium leak test 100/Helium leak test N/A / N/A	U-Bend U-Bend N/A	Leaker Leaker Prevent. measure
S/G	No. 4				
	Row	Column	Indication % / Test Method	Location	Reason for Plugging

Row	Column	Indication % / Test Method	Location	Reason for Plugging
1	1-94	N/A / N/A	N/A	Prevent. measure

- (a) The following tubes were previously plugged in S/G No. 1:
 - RIC7, RIC12, RIC26, RIC29, RIC36, RIC59, RIC61, RIC62, RIC63, RIC66, RIC67, RIC68, RIC69, RIC88, RIC89, and RIC91.
- (b) The following tubes were previously plugged in S/G No. 2: R1C87, R1C88, R1C90, R1C49, and R1C50.
- (c) The following tubes were previously plugged in S/G No. 3: RIC1, RIC13, and RIC29.
- (*) ECT Eddy Current Testing.