

APPROVED BY OMB NO. 3150-0104 EXPIRES 06/30/2001  
Estimated burden per response to comply with this mandatory information collection request: 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

### LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

FACILITY NAME (1) Hope Creek Generating Station	DOCKET NUMBER (2) 05000354	PAGE (3) 1 OF 4
--	-------------------------------	--------------------

TITLE (4)  
Inadequate Performance of Primary Containment Integrity Verification

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
09	16	98	98	006	00	10	13	98		05000
									FACILITY NAME	DOCKET NUMBER
										05000

  

OPERATING	1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more) (11)								
		20.2201(b)		20.2203(a)(2)(v)	<input checked="" type="checkbox"/>	50.73(a)(2)(i)		50.73(a)(2)(viii)		
POWER	100	20.2203(a)(1)		20.2203(a)(3)(i)		50.73(a)(2)(ii)		50.73(a)(2)(x)		
		20.2203(a)(2)(i)		20.2203(a)(3)(ii)		50.73(a)(2)(iii)		73.71		
		20.2203(a)(2)(ii)		20.2203(a)(4)		50.73(a)(2)(iv)		OTHER		
		20.2203(a)(2)(iii)		50.36(c)(1)		50.73(a)(2)(v)		Specify in Abstract below or in NRC Form 366A		
		20.2203(a)(2)(iv)		50.36(c)(2)		50.73(a)(2)(vii)				

**LICENSEE CONTACT FOR THIS LER (12)**

NAME Paul Duke, Licensing Engineer	TELEPHONE NUMBER (Include Area Code) 609-339-1466
---------------------------------------	--

**COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)**

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

<b>SUPPLEMENTAL REPORT EXPECTED (14)</b>	<b>EXPECTED</b>	MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE).	<input checked="" type="checkbox"/> NO			

**ABSTRACT** (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On September 16, 1998 at approximately 1650 hours, PSE&G discovered that containment isolation valve position verification was not being performed properly for valve 1BHV-031, a test valve located within the containment isolation boundary for the Standby Liquid Control discharge line. The procedure for PRIMARY CONTAINMENT INTEGRITY verification satisfies Technical Specification Surveillance Requirement 4.6.1.1.b by monthly position status verification in the valve status database (TRIS+) and by monthly field verification. For valve 1BHV-031, the monthly field verification was not being performed. The cause for this event was personnel error which resulted in an inadequate revision to the surveillance procedure for PRIMARY CONTAINMENT INTEGRITY verification. Corrective actions included verification that the valve was closed. This event is being reported pursuant to 10CFR50.73(a)(2)(i)(B) as an operation or condition prohibited by Technical Specifications.

9810200089 981013  
PDR ALOCK 05000354  
S PDR

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3) 2 OF 4
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	
Hope Creek Generating Station	05000354	98	-- 006 --	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**PLANT AND SYSTEM IDENTIFICATION**

General Electric - Boiling Water Reactor (BWR/4)  
Standby Liquid Control System - EIIS Identifier {BR/--}\*

\* Energy Industry Identification System (EIIS) codes and component function identifier codes appear as {SS/CC}

**IDENTIFICATION OF OCCURRENCE**

Event Date: December 9, 1996  
Discovery Date: September 16, 1998

**CONDITIONS PRIOR TO OCCURRENCE**

The plant was in OPERATIONAL CONDITION 1 (POWER OPERATIONS), at approximately 100% of rated thermal power. There were no structures, systems, or components that were inoperable at the beginning of the event that contributed to the event.

**DESCRIPTION OF OCCURRENCE**

On September 16, 1998 at approximately 1650 hours, PSE&G discovered that containment isolation valve position verification was not being performed properly for valve 1BHV-031, a test valve located within the containment isolation boundary for the Standby Liquid Control discharge line. Technical Specification Surveillance Requirement (SR) 4.6.1.1.b requires verification at least once per 31 days that all primary containment penetrations not capable of being closed by OPERABLE containment automatic isolation valves and required to be closed during accident conditions are closed by valves, blind flanges, or deactivated automatic valves secured in position.

The procedure for PRIMARY CONTAINMENT INTEGRITY verification satisfies SR 4.6.1.1.b by monthly verification of valve position status for manual primary containment isolation valves in the valve status database (TRIS+) and also by monthly field verification. For valves located in high radiation areas outside containment, field verification may be waived based on a review of operations, maintenance and testing activities in those areas.

During a review of the surveillance procedure, it was noted that the field verification was being waived for valve 1BHV-031. The valve was listed in

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Hope Creek Generating Station	05000354				3	OF 4
		98	-- 006 --	00		

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**DESCRIPTION OF OCCURRENCE (continued)**

the procedure among the valves located in high radiation areas. However, valve 1BHV-031 is actually in a non-high radiation area.

Field verification was also being waived for three other valves not in high radiation areas. However, these valves are located in a locked room posted as a neutron exposure area, and waiver of the field verification was appropriate.

Failure to perform the required verification for valve 1BHV-031 until September 16, 1998 is reportable pursuant to 10CFR50.73(a)(2)(i)(B) as an operation or condition prohibited by Technical Specifications.

**APPARENT CAUSE OF OCCURRENCE**

The apparent cause for this event was personnel error which resulted in an inadequate revision to the surveillance procedure for PRIMARY CONTAINMENT INTEGRITY verification. In a revision to the procedure implemented in October 1996, valve 1BHV-031, which is in a non-high radiation area, was incorrectly relocated to the list of valves in high radiation areas. Field verification of valve position may be waived for valves in high radiation areas. The basis for the procedure change was not documented, and personnel involved in preparing the revision are no longer on site.

**SAFETY SIGNIFICANCE AND IMPLICATIONS**

PRIMARY CONTAINMENT INTEGRITY ensures that the release of radioactive materials from the containment atmosphere will be restricted to those leakage paths and associated leak rates assumed in the accident analyses. This restriction, in conjunction with the leakage rate limitation, will limit the site boundary radiation doses to within the limits of 10 CFR Part 100 during accident conditions.

There were no actual safety consequences associated with this condition. Valve 1BHV-031 was verified to be locked closed on September 16, 1998. In addition, the valve was verified to be locked closed during plant shutdowns in November 1996 and November 1997. The valve's position status was verified monthly in the TRIS+ database and the valve locking device was

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Hope Creek Generating Station	05000354	98	006	00	4	4

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**SAFETY SIGNIFICANCE AND IMPLICATIONS (continued)**

controlled by the Operations Department. Valve 1BHV-031 is used for containment penetration leak rate surveillance testing. After the test is completed, the valve is checked and independently verified to be in the correct locked closed position. Since the valve was confirmed to be in the correct position, and position status was checked monthly, a valve mispositioning error is highly unlikely. This event did not affect the health and safety of the public.

**PREVIOUS OCCURRENCES**

A review of previously reported events identified one instance within the last two years in which required PRIMARY CONTAINMENT INTEGRITY verification was not performed.

LER 354/95-033-04 reported an event in which certain primary containment penetration test and drain valves were not periodically verified to be closed in accordance with the requirements of TS SR 4.6.1.1.b. The valves had been omitted from the procedure that verifies primary containment integrity. The omitted valves were then added to the surveillance procedure. A review of all primary containment penetrations was performed as a corrective action for this event, and LER 354/95-033-11 reported that approximately 390 additional containment isolation valves were identified that also had not been previously verified in accordance with TS SR 4.6.1.1.b. A verification of these valves was performed promptly and the surveillance procedure was revised to include the required components. During this revision to the procedure, valve 1BHV-031 was incorrectly relocated to the list of valves in high radiation areas.

**CORRECTIVE ACTIONS**

1. In accordance with Technical Specification requirements, valve 1BHV-031 was verified to be closed and locked on September 16, 1998.
2. The surveillance procedure for PRIMARY CONTAINMENT INTEGRITY verification will be revised to ensure current area radiological conditions are assessed in determining when field verification of valve position is required. This activity will be completed by October 15, 1998.