

LICENSEE EVENT REPORT (LER)

Facility Name (1) QUAD-CITIES NUCLEAR POWER STATION, UNIT TWO										Docket Number (2) 0   5   0   0   0   2   6   5   1   of   0   4			Page (3) 1   of   0   4	
Title (4) REACTOR CORE ISOLATION COOLING INOPERABLE - STEAM SUPPLY VALVE AUXILIARY CONTACT BINDING														
Event Date (5)			LER Number (6)				Report Date (7)			Other Facilities Involved (8)				
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names		Docket Number(s)			
11	03	87	87	0116	011	09	22	88			0   5   0   0   0   1   1			
OPERATING MODE (9) 3			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)											
POWER LEVEL (10) 0   0   3			20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)			73.71(c)		
			20.405(a)(1)(i)		50.36(c)(1)		X 50.73(a)(2)(v)		Other (Specify in Abstract below and in Text)					
			20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)							
			20.405(a)(1)(iii)		50.73(a)(2)(i)		50.73(a)(2)(viii)(A)							
			20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)							
			20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(ix)							
LICENSEE CONTACT FOR THIS LER (12)														
Name J. D. Pacilio, Technical Staff Engineer, Ext. 2187										TELEPHONE NUMBER AREA CODE 3   0   9   6   5   4   -   2   2   4   1				
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)														
CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFAC-TURER	REPORTABLE TO NPRDS				
X	B   N	C   N   T   R	Q   0   8   0	Y										
SUPPLEMENTAL REPORT EXPECTED (14)										Expected Submission Date (15)				
[Yes (if yes, complete EXPECTED SUBMISSION DATE)] X   NO														
ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)														

At 0020 hours, on November 3, 1987, Quad Cities Unit Two was in the STARTUP/HOT STANDBY mode at approximately three percent reactor thermal power. While performing the Reactor Core Isolation Cooling (RCIC) System valve operability test, it was found that steam supply valve 2-1301-16 did not automatically close as it should when its companion steam supply valve (2-1301-17) was closed. It also would not close with the control switch on the 902-4 panel in the control room. RCIC was declared inoperable and Technical Specification required testing was completed at 0525 hours. NRC notification via the Emergency Notification System was completed at 0230 hours.

The cause of this event (2-1301-16 failure to close) was the result of auxiliary contact binding in the 480 volt contactor associated with this valve. The auxiliary contact was replaced like for like as well as the movable contact support T-bar. Following this replacement, RCIC was tested and declared operable at 1225 hours of the same day. A preventive maintenance program is to be developed that will address periodic lubrication of the auxiliary contact plunger guides. This report is provided per 10CFR50.73(a)(2)(v) (B and D).

EB09290051 880922  
PDR ADOCK 05000265  
3 PNU



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			Page (3)		
		Year	Sequential Number	Revision Number			
Quad Cities Unit TWO	0   5   0   0   0   2   6   5	8   7	-   0   1   6	-   0   1	0   3	OF	0   4
TEXT							

C. APPARENT CAUSE OF EVENT:

This report is supplied to satisfy 10CFR50.73(a)(2)(v) (B and D), which requires the reporting of any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to remove residual heat or mitigate the consequences of an accident.

The cause for this event (failure of 2-1301-16 to automatically close) was determined to be auxiliary contact binding. The bound auxiliary contact caused the movable contact support T-bar to overheat on the B phase. The 2-1301-16 valve power supply is located on 480 volt Motor Control Center (MCC) 28-1A-1.

D. SAFETY ANALYSIS OF EVENT:

RCIC is designed to provide cooling water to the reactor in the event the reactor becomes isolated from the main condenser simultaneously with a loss of the reactor feedwater system. The 2-1301-16 and 17 valves are interlocked to close when a Group V isolation signal is received. The initiating signals for a Group V isolation are: Low reactor pressure, high steam line differential pressure, and high area temperature. Because the 2-1301-17 valve was immediately closed, containment integrity was insured and the safety impact was minimal.

The safety of public and plant personnel was not affected due to this event. When the RCIC system is determined to be inoperable, it must be restored to an operable condition within seven days, provided HPCI is operable. Since HPCI was proven operable by 0525 hours of the same day, the safety significance of this event is minimal.

E. CORRECTIVE ACTIONS:

The corrective action for this event was to have the Electrical Maintenance Department replace the auxiliary contact like for like and install a new movable contact support T-bar. A thin coat of Aero-Shell #7 was applied to the auxiliary contact plunger guides. This was completed and RCIC was declared operable at 1225 hours (November 3, 1987) following satisfactory completion of QOS 1300-S3 (valve operability) and QOS 1300-S2 (pump operability).

The station has experienced auxiliary contact plunger guide binding in this type contactor in the past. The plunger guides in the EQ and safety related motor control centers are being lubricated with Aero-Shell #7 grease as covered in GEJ-5277 during scheduled refueling outages. This will continue until all plunger guides in the EQ and safety related motor control centers are lubricated during the next two refuel cycles on each unit (Nuclear Tracking System 26520086007R3.1). During this lubrication process, a preventive maintenance program will be developed defining the frequency of the lubrication schedule (NTS 26520086007R3.2).

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			Page (3)		
		Year	Sequential Number	Revision Number			
Quad Cities THQ TEXT	0   5   0   0   0   2   6   5	8   7	-   0   1   6	-   0   1	0   4	0   F	0   4

F. PREVIOUS EVENTS:

Reportable Events:

Subject

254-81-01/03L	1/2 B Standby Gas Treatment (SBGT) Discharge Damper would not close
254-82-14/03L	1/2 B SBGT Discharge Damper would not open
265-81-12/03L	Residual Heat Removal (RHR) 2-1001-7B would not open
265-80-39/03L	RHR 2-1001-34A would not open
265-80-13/03L	RHR 2-1001-36A would not close
265-80-21/03L	Core Spray 2-1402-3A would not open
265/86-007 Revision 3	Failure of 2B Core Spray Room Cooler

All of these events have been identified as being caused by auxiliary contact binding. The above identified events were caused by the same or similar type of auxiliary contact.

G. COMPONENT FAILURE DATA:

<u>Manufacturer</u>	<u>Nomenclature</u>	<u>Model Number</u>
General Electric	Auxiliary Contact	CR105X100P



**Commonwealth Edison**  
Quad Cities Nuclear Power Station  
22710 206 Avenue North  
Cordova, Illinois 61242  
Telephone 309/654-2241

RLB-88-324

September 22, 1988

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Reference: Quad-Cities Nuclear Power Station  
Docket Number 50-265, DPR-30, Unit Two

Enclosed is Licensee Event Report (LER) 87-016 Revision 01, for Quad-Cities Nuclear Power Station. This revision provides additional information regarding corrective action.

This report is submitted in accordance with the requirements of the Code of Federal Regulations, Title 10, Part 50.73(a)(2)(v) (B and D), which requires the reporting of any event that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to remove residual heat or mitigate the consequences of any accident.

Respectfully,

COMMONWEALTH EDISON COMPANY  
QUAD-CITIES NUCLEAR POWER STATION

R. L. Bax  
Station Manager

RLB/AAF/ad

Enclosure

cc: I. Johnson  
R. Higgins  
INPO Records Center  
NRC Region I/I

1108H/03817

IE22  
1/1