

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) **PLANT HATCH, UNIT 1** DOCKET NUMBER (2) **0 5 0 0 0 3 2 1 1** OF **0 5** PAGE (3)

TITLE (4) **LOOSE GEAR FASTENER IN FLOW CONTROLLER RESULTS IN INOPERABILITY OF HPCI**

EVENT DATE (5)			LER NUMBER (6)		REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES
08	26	88	88	012	00	09	20	88	
									DOCKET NUMBER(S) 0 5 0 0 0

OPERATING MODE (8) **1**

POWER LEVEL (10) **100**

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(e)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 50.36(c)(1)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(c)
<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 306A)
<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(vii)(A)	
<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(vii)(B)	
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME: **Steven B. Tipps, Manager Nuclear Safety and Compliance, Hatch**

TELEPHONE NUMBER: **9 1 2 3 6 7 - 7 8 5 1**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
X	BJ	F F C	G Q 8 0	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (if yes, provide EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15): MONTH  DAY  YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 08/26/88, at approximately 1515 CDT, Unit 1 was in the run mode at an approximate power level of 2436 CMWT (approximately 100 percent of rated thermal power). At that time, the High Pressure Coolant Injection (HPCI, EIS Code BJ) system was declared inoperable due to a malfunctioning system flow controller. The controller was subsequently repaired and returned to service. At approximately 2120 CDT, the HPCI system was declared operable following successful completion of procedure 34SV-E41-002-1S, HPCI Pump Operability.

The cause of the flow controller malfunction was a loose fastener on an intermediate gear in the gearing mechanism of the controller. When the fastener became loose, the intermediate gear became unmeshed with the adjacent gearing. This caused a break in the gear train preventing adjustment of the controller setting.

Corrective actions include placement of the gear into the gear train and tightening of the fastener. To prevent recurrence, procedures will be revised to require a periodic check of the gear train and fasteners.

8809290142 880920  
PDR ADOCK 05000321  
S PNU

IE22  
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  PLANT HATCH, UNIT 1	DOCKET NUMBER (2)  0   5   0   0   0   8   2   1	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8   8	-   0   1   2	-   0   0	0   2	OF	0   5

TEXT (if more space is required, use additional NRC Form 366A's) (17)

Plant and System Identification:

General Electric - Boiling Water Reactor  
Energy Industry Identification System codes are identified in the text as (EIIIS Code XX).

Summary of Event

On 08/26/88, at approximately 1515 CDT, Unit 1 was in the run mode at an approximate power level of 2436 CMWT (approximately 100 percent of rated thermal power). At that time, the High Pressure Coolant Injection (HPCI, EIIIS Code BJ) system was declared inoperable due to a malfunctioning system flow controller. The controller was subsequently repaired and returned to service. At approximately 2120 CDT, the HPCI system was declared operable following successful completion of procedure 34SV-E41-002-1S, HPCI Pump Operability.

Description of Event

On 08/26/88, at approximately 1515 CDT, routine surveillance testing of the HPCI pump in accordance with procedure 34SV-E41-002-1S had been satisfactorily completed. At that time, a licensed plant operator was restoring the system to the standby mode and was unable to adjust the setting of the flow controller to the system design flowrate as required by the procedure. Inability to restore the controller setting to the system design flowrate would have prevented the HPCI pump from achieving the design flowrate during an automatic initiation of the system. The HPCI pump was subsequently declared inoperable at 1515 CDT.

At the time of the event, the Residual Heat Removal/Low Pressure Coolant Injection (RHR/LPCI, EIIIS Code B0) system 'B' pump was tagged out of service for preventive maintenance. As required by Technical Specification Section 3.5.D.3, when the HPCI system and a loop of the RHR system LPCI mode are inoperable, "an orderly shutdown shall be initiated and the reactor vessel pressure shall be reduced to 150 psig or less within 24 hours." Consequently, at 1515 CDT, procedure 34G0-OPS-013-1S, Normal Plant Shutdown, was initiated.

LICENSÉE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  PLANT HATCH, UNIT 1	DOCKET NUMBER (2)  0 5 1 0 0 0 3 2 1	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8	0 1 2	0 0	0 3	OF	0 5

TEXT (if more space is required, use additional NRC Form 388A's) (17)

At approximately 1715 CDT, preventive maintenance on the LPCI 'B' pump was complete and the pump was declared operable following satisfactory completion of procedure 34SV-E11-001-1S, Residual Heat Removal Pump Operability. At approximately 1730 CDT, Unit 1 was in full compliance with the Limiting Condition of Operation of Technical Specification Section 3.5.D.2 and normal plant shutdown activities were terminated.

Following the discovery of the flow controller malfunction, maintenance personnel began investigating the problem. At approximately 1925 CDT, the controller had been repaired and returned to service and operability testing of the HPCI system per 34SV-E41-002-1S was in progress. On 08/26/88, at approximately 2120 CDT, following successful completion of procedure 34SV-E41-002-1S, the HPCI system was declared operable.

Cause of Event

The immediate cause of the event was a loose fastener in the gear train of the HPCI system flow controller. The loose fastener allowed an intermediate gear in the gear train to become unmeshed from adjacent gearing. The break in the gear train prevented adjustment of the controller setting. Thus, the controller could not be adjusted to the required system design flowrate and placed in the automatic mode.

The root cause of the fastener loosening could not be conclusively determined. No previous similar controller failures have occurred at Plant Hatch, and a review of the Nuclear Plant Reliability Data System (NPRDS) records also indicates no history of similar failures at other plants. The mechanism for holding the fastener in place was a star washer for which no preventative maintenance was required by the controller's vendor manual to preclude fastener loosening. A review of the maintenance history for the controller did not reveal any probable causes for the fastener loosening. This appears to be an isolated incident as a result of normal operation of the controller.

Reportability Analysis and Safety Assessment

This report is required per 10 CFR 50.73 (a)(2)(v) because a component failure occurred in the HPCI system which would have prevented the system from functioning as designed to mitigate the consequences of an accident. The failure would have prevented the HPCI system from reaching design flow upon automatic initiation of the system.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  PLANT HATCH, UNIT 1	DOCKET NUMBER (2)  0 5 0 0 0 3 2 1	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8	0 1 2	0 0	0 4	OF	0 5

TEXT (if more space is required, use additional NRC Form 365A 2) (17)

The HPCI system is provided to assure that the reactor is adequately cooled to limit fuel-clad temperature in the event of a small break in the nuclear system and a loss of coolant which does not result in rapid depressurization of the reactor vessel. The Automatic Depressurization System (ADS, EIIIS Code JE) is a backup for the HPCI system. Upon ADS initiation, the reactor is depressurized to a point where either the LPCI system or the Core Spray (CS, EIIIS CODE BM) system can operate to maintain adequate core cooling.

In the event addressed in this report, the HPCI system and one of the four LPCI pumps were inoperable. Three of the four LPCI pumps and their associated equipment, ADS, and both loops of CS were operable. Based upon the Unit 1 Final Safety Analysis Report (FSAR), either loop of the CS system or the LPCI system, consisting of two operable pumps in one RHR loop and at least one operable pump in the other RHR loop, can supply sufficient cooling to the reactor for any rupture of the nuclear safety boundary up to and including the Design Basis Accident (DBA). Based on this information, it is concluded that this event had no adverse impact on nuclear plant safety.

Since the reactor was operating at approximately 100 percent power at the time of the event, the event would not have been more severe had it occurred under other operating conditions.

Corrective Action

Procedures 57CP-CAL-044-1/2S, GE Type 547-01 Self Synchronizing M/A Transfer Station, will be permanently revised by 01/15/89 to require a check of the controller gearing and gearing fasteners during calibration of the controller. Also, procedures 52PM-E41-003-1/2S, HPCI System Maintenance, will be permanently revised by 01/15/89 to require a check of the controller gearing and gearing fastener on a twelve month frequency. In the interim, the controllers of this type will be visually inspected, by the Maintenance Department, during the upcoming Unit One refueling outage.

Additional Information

No systems other than the HPCI system were directly affected by the component failure.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  PLANT HATCH, UNIT 1	DOCKET NUMBER (2)  0 5 0 0 0 3 2 1	LER NUMBER (3)			PAGE (3)	
		YEAR 8 8	SEQUENTIAL NUMBER 0 1 2	REVISION NUMBER 0 0	0 5	OF 0 5

TEXT (if more space is required, use additional NRC Form 365A 1/ (17))

The component failure is considered to be an isolated incident in that no previous component failures were caused by a loose fastener in the component gear train. However, a HPCI flow controller malfunction was reported in LER 50-366/1987-017, dated 12/15/87, in which the HPCI flow controller failed to properly control HPCI system flowrate in the automatic mode. Corrective actions for the event included replacing an amplifier card and repairing a defective solder joint in a support module for the controller. These corrective actions would not have prevented the event addressed in this report since they did not involve the gearing of the flow controller.

Failed Component Identification:

MPL (Plant Index Identifier): 1E41-R612  
 Manufacturer: General Electric Company  
 Model Number: 547-01  
 Type: Self-synchronizing Basic Control Station  
 EIIS Code: FFC

Georgia Power Company  
333 Piedmont Avenue  
Atlanta, Georgia 30308  
Telephone 404 526-6526

Mailing Address:  
Post Office Box 4545  
Atlanta, Georgia 30302

W. G. Hairston, III  
Senior Vice President  
Nuclear Operations

*The southern electric system*

HL-78  
0191t  
X7GJ17-H310

September 20, 1988

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555

PLANT HATCH - UNIT 1  
NRC DOCKET 50-321  
OPERATING LICENSE DPR-57  
LICENSEE EVENT REPORT  
LOOSE GEAR FASTENER IN FLOW CONTROLLER  
RESULTS IN INOPERABILITY OF HPCI

Gentlemen:

In accordance with the requirements of 10 CFR 50.73(a)(2)(v), Georgia Power Company is submitting the enclosed Licensee Event Report (LER) concerning a condition that could have prevented an Engineered Safety Feature (ESF) from fully performing its safety function. This event occurred at Plant Hatch - Unit 1.

Sincerely,

  
W. G. Hairston, III

SB/ct

Enclosure: LER 50-321/1988-012

c: (see next page)

IE22  
1/1

U. S. Nuclear Regulatory Commission  
September 20, 1988  
Page Two

c: Georgia Power Company  
Mr. H. C. Nix, General Manager - Plant Hatch  
Mr. L. T. Gucwa, Manager, Licensing and Engineering - Hatch  
GO-NORMS

U. S. Nuclear Regulatory Commission, Washington, D. C.  
Mr. L. P. Crocker, Licensing Project Manager - Hatch

U. S. Nuclear Regulatory Commission, Region II  
Dr. J. N. Grace, Regional Administrator  
Mr. J. E. Menning, Senior Resident Inspector - Hatch