

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Pilgrim Nuclear Power Station	DOCKET NUMBER (2) 05000293	PAGE (3) 1 OF 4
--	-------------------------------	--------------------

TITLE (4)  
Inadvertent Manual Start of the 'B' Emergency Diesel Generator

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
04	25	88	88	013	000	05	25	88	N/A		05000
									N/A		05000

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

OPERATING MODE (9) N	20.402(b)	20.405(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(v)	73.71(b)
POWER LEVEL (7) C/O/O	20.405(a)(1)(i)	50.38(c)(1)	<input type="checkbox"/>	50.73(a)(2)(iv)	73.71(c)
	20.405(a)(1)(ii)	50.38(c)(2)	<input type="checkbox"/>	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.405(a)(1)(iii)	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)	
	20.405(a)(1)(iv)	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)	
	20.405(a)(1)(v)	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME Douglas W. Ellis - Compliance Division Engineer	TELEPHONE NUMBER 617-747-1216
---	----------------------------------

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input checked="" type="checkbox"/>	<input type="checkbox"/>				

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)

On April 25, 1988 at 1430 hours, an inadvertent manual start of the 'B' Emergency Diesel Generator (EDG) occurred. The generator started but did not supply power to its Bus (A-6) because the Bus was already energized. Following immediate investigation by the operating shift personnel, the generator was returned to normal standby service at approximately 1445 hours.

The cause for the manual start was utility technician personnel error. The technician mistakenly pushed the manual start switch instead of an annunciator reset switch during a work activity involving the local control panel of the generator.

Improvements to the local control panels of both EDGs ('A' and 'B') have been identified and are being tracked. The improvements include possible relocation of the annunciator reset switch(es) and modification of the manual start switch(es).

This event occurred during an extended outage while in cold shutdown. The reactor mode switch was in the SHUTDOWN position. The control rods were in the inserted position. The Reactor Vessel water temperature was 95 degrees Fahrenheit with negligible core decay heat. The Reactor Vessel pressure was zero psig. The reactor power level was zero megawatts-thermal. The 'A' EDG was operable and in standby service. Emergency Busses A-5 and A-6 were energized with 4160 VAC power from the offsite transmission system.

This event posed no threat to the health and safety of the public. *JEED*

8806020298 880525  
PDR ADOCK 05000293  
PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Pilgrim Nuclear Power Station	DOCKET NUMBER (2)  0 5   0   0   0   2   9   3	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8   8	- 0   1   3	- 0   0	0   2	OF 0   4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

EVENT DESCRIPTION

On April 25, 1988 at 1430 hours, an inadvertent manual start of the 'B' Emergency Diesel Generator (EDG) occurred. The generator did not supply power to its emergency 4160 VAC Bus (A-5) because the Bus was already energized, but was capable of this function at the time of the event.

Following immediate investigation by the operating shift personnel, the diesel generator was returned to normal standby service at approximately 1445 hours.

Failure and Malfunction Report 88-91 was written to document the event. The NRC Operations Center was notified on April 25, 1988 at 1627 hours.

This event occurred during an extended outage while in cold shutdown with the following plant conditions. The reactor mode selector switch was in the SHUTDOWN position. The control rods were in the inserted position. The Reactor Vessel water temperature was approximately 95 degrees Fahrenheit with negligible core decay heat. The Reactor Vessel pressure was zero psig. The reactor power level was zero megawatts-thermal. The 'A' EDG was operable and in normal standby service. Emergency Busses A-5 and A-6 were energized with 4160 VAC power from the offsite 345 KV transmission system.

CAUSE

The cause for the manual start of the diesel generator was utility technician personnel error. An Instrumentation and Control (I&C) technician mistakenly pushed the manual start switch instead of the annunciator reset switch on the local control panel (C-104B) of the diesel generator.

Factors contributing to the error were the location of the manual start switch and its proximity to the annunciator reset switch on the panel. The switches are located at the same level above the floor (i.e., at hip level) and are approximately six inches apart. The annunciator windows located on the panel are approximately five to six feet above the floor (i.e., at eye level).

The technician was calibrating the discharge pressure switch (PS-PLPS-B) for the electrically driven prelube oil pump of EDG 'B' (X-107B). The calibration was being performed in accordance with Procedure 8.E.38 (Revision 14) Attachment C, "Diesel Generator Instrumentation, Calibration and Functional Test". During the calibration the annunciator reset switch on the panel was to be pushed. While looking at the annunciator window the technician mistakenly pushed the manual start switch instead of the adjacent annunciator reset switch.

There were no component or system failures that caused this event or resulted from this event.

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Pilgrim Nuclear Power Station	DOCKET NUMBER (2)  0   5   0   0   0   2   9   3   8   8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		— 0   1   3	— 0   0	0   3	OF	0   4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

CORRECTIVE ACTION

Immediate corrective action consisted of investigating the cause of the manual start and returning the diesel generator to normal standby service.

A critique of the event was conducted on April 27, 1988 at approximately 1000 hours. The critique was attended by personnel including the responsible I&C technician. The critique was conducted to establish facts related to the event and to make recommendations regarding additional corrective actions.

An I&C workshop discussion of this event was conducted on May 13, 1988 with appropriate I&C technicians. Possible long term corrective actions have been identified via an Engineering Service Request (ESR 88-365). The ESR proposes the possible relocation of the annunciator reset switch on Panels C-103B and C-104B to the vicinity of the annunciator test and acknowledge switches. A possible modification of the existing manual start switch(es) to a single error resistant, double action type switch is also being considered.

The workshop discussion of the event, and the possible relocation of the annunciator reset switch(es) and possible modification of the manual start switch(es), is expected to reduce the likelihood of a similar event in the future.

SAFETY CONSEQUENCES

This event posed no threat to the health and safety of the public.

The generator functions to supply 4160 VAC power to Bus A-5 if the Bus becomes de-energized. The generator was capable of this function but did not supply power to the Bus because the Bus was energized at the time of the event. Therefore, the start was an unnecessary challenge to the starting function of the diesel generator.

A manual start of an EDG from its local control panel is signalled in the Control Room on Panel C-3. Control Room operator actions for response to the signal are addressed in "Alarm Response Procedure", ARP-C3L (Left).

This event was determined to be reportable pursuant to 10 CFR 50.73(a)(2)(iv) because an unplanned (manual) start of the 'B' EDG occurred. The generator supplies power to accident mitigating systems if Bus A-5 becomes de-energized (i.e., loss of offsite power).

SIMILARITY TO PREVIOUS EVENTS

A review of Pilgrim Station Licensee Event Reports (LERs) written since January 1984 did not identify an LER(s) submitted pursuant to 10 CFR 50.73 (a)(2)(iv) that involved the unplanned manual start of EDG 'A' or 'B'.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Pilgrim Nuclear Power Station	DOCKET NUMBER (2)  0   5   0   0   0   2   9   3   8   8	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8	0   1   3	0   0	0   4	OF 0   4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

ENERGY INDUSTRY IDENTIFICATION SYSTEM (EIIS) CODES

The EIIS codes for this event are as follows:

SYSTEMS

CODES

Emergency Onsite Power Supply System (EDG)  
Engineered Safety Features Actuation System (Panel C-104B)

EK  
JE

COMPONENTS

Annunciator (Panel C-104B)  
Panel (C-104B)  
Switch, Hand (Manual Start and Reset)

ANN  
PL  
HS



**BOSTON EDISON**

Pilgrim Nuclear Power Station  
Rocky Hill Road  
Plymouth, Massachusetts 02360

**Ralph G. Bird**  
Senior Vice President — Nuclear

May 25, 1988  
BECo Ltr. #88-083


U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Docket No. 50-293  
License No. DPR-35

Dear Sir:

The attached Licensee Event Report (LER) 88-013-00 "Inadvertent Manual Start of the 'B' Emergency Diesel Generator" is submitted in accordance with 10CFR Part 50.73.

Please do not hesitate to contact me if you have any questions regarding this report.

  
R.G. Bird

DWE/b1

Enclosure: LER 88-013-00

cc: Mr. William Russell  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Rd.  
King of Prussia, PA 19406

Sr. Resident Inspector - Pilgrim Station

Standard BECo LER Distribution

IE22  
||