LICENSEE EVENT REPORT (LER)												
Limes	rick Gene	erating	Stati	.o Uni	t 1	•			1013151	2 1 0 0 1		
Failu	e of RHRS	W System	Rad Mo	nitor Circ	uitr	y to	Meet Tech	unical S	necifics	tione		
EVENT DA	TE (8)	LER NUMBER	16)	REPORT DATE	1171		OTHER /	ACILITIES INVOL	VED 101	10115		
MONTH DAY YEAR YEAR SEDUCATIAL MUNSER MONTH DAY YEAR PACILITY NAMES DOCKET NUMBER(3)										A(3)		
					ł				0 161010	10111		
213	8686	012	00	0 3 1 4	86				0 151010			
MODE IN	THUS REP	OAT IS SUBMITTI	D PURSUANT	TO THE REQUIREMENT	NTS OF 1	EFR § !!		i she takowangi (11	1			
Pomia Livil 1		406 (a) (1) (2) 106 (a) (1) (2) 106 (a) (1) (2) 106 (a) (1) (2) 106 (a) (1) (2)	X	66.36 (a) (1) 66.36 (a) (2) 66.73 (a) (2) (4) 66.73 (a) (2) (4) 66.73 (a) (2) (4) 66.73 (a) (2) (4)			60.73(a)(2)(a) 60.73(a)(2)(a) 60.73(a)(2)(a) 60.73(a)(2)(a)(4) 60.73(a)(2)(a)(4) 60.73(a)(2)(a)(4) 60.73(a)(2)(a)		73.7161 73.7161 07168 (2)	meny in Abstract in Taol, NAC Form		
AME			1	CENSES CONTACT I	OA THE	LER (13)						
John	C. Nagle	, Senio	r Engi	neer, Li	cen	sing	Section	2, 1, 5	8.4.1-	. 5. 1. 8.4		
		COMPLETE		LACH COMPONENT	PAILURE			(13)	-1.19	1-1-1-1.		
AUSE STETE	-	TURER	TO MPADE	1200	CAUSE	-		HANUFAS TURER	TO MADE	123-33		
1	111	111		M. Carlos		1		1.1.1		R. Constant		
1.				1200 13 19 20						Miller .		
		BUPPLEME	NTAL REPORT	EXPLOTED (14)	1				1	- Far Inco		
TES // PM.		USMISSION BATI	U	X NO				BATE ILS				
On it Res con Not aut dov of	February was detend sidual He apliance te (1). comatical wnscale for their in	13, 19 ermined eat Remo with the The sub ly iso failure the constalla	986, w that oval S he Tec oject lating of a ircuit tion. were	hile in all four ervice W hnical S radiatio the RHR monitor. ry for t declared	Oper rad ater peci n mc SW s Th he r	atic iati (RH fica nito yste is c adia	onal Mod on moni IRSW) sy ation Ta ors were em in th capabili ation mo	e 1 at tors or stem we ble 4.3 not ca to even ty had onitors	99.8% h the ere not 3.7.11- apable t of a not be at the ppropr	power, in -1, of een e time iate		
Ac an moo	tion Stat alyzing d dification ere were	tement them fo on has no adv	was co r gros been c erse e	emplied w s radioa completed effects a	ith activ l ins as a	by c vity stal: resu	collecti every 8 ling the ult of t	ing gra hours prope this co	b samp . A r circ nditio	les and uitry. n.		
	860 PDF S	321009 ADDC	2 8403 k 0500	14 0352 PDR								

\* -

A-1

ZEZZ VI

-----

ARC Form 3464 19431 LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED ONE NO. 3150-0104 EXPIRES 6/21/05								
ACILITY NAME (1)	DOCKET NUMBER (2)	LEA NUMBER (8)	PAGE (3)					
Limerick Generating Station		YEAR SEQUENTIAL NUMBER						
Unit I	0 15 10 10 10 13 1 51	2816-0142-0	0 0 2 OF 0 14					
EXT (If more space is required, use additional NRC Form 3665) (17)	and the stand of t	······································						
Unit Conditions Prior	to the Event:							
Mode 1 (Power Ope Reactor Power (99	eration) 9.8%)							
Description of the Eve	ent:							
During a review of a r discovered that the in Removal Service Water although in compliance (FSAR) Section 11.5, " Monitoring and Samplin isolation of the RHRSW of a radiation monitor Table 4.3.7.11-1 (Note Although no automatic been signaled of a dow main control room and Meter (LCRM), which is	revision to a surv (RHRSW) system ef with the Final S Process and Efflu g Systems", did n V system in the ev as required by t a) pages 3/4 3-1 isolation occurre mscale failure vi a pilot light on b) located in the A	eillance test, i of the Residual fluent radiation afety Analysis R ent Radiological ot cause an auto ent of a downsca he Technical Spe 01 and 3/4 3-102 d, the operator a an annunciator the Logari Equipme	t was Heat monitors, eport matic le failure cification would have in the Count Rate nt Room.					
Consequences of the Ev	ent:							
There were no adverse	consequences resul	lting from this	condition					

The possible consequences of a failure to isolate the RHRSW system due to a downscale failure of the radiation monitors would have been minimal.

In the event of a downscale failure of one of the monitors, the operator would have been alerted via an annunciator in the control room. Upon receipt of this alert, the appropriate action would have been taken, which may have included a manual isolation of the system.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION						APPROVED C EXPIRES 8/3	REGULATORY COMMISSION D OMB NO. 3150-0104 8/31/85					
FACILITY NAME (1)		DOCKET NUMBER (2)	1	LER NUMBER (S)				PAGE (3)				
Limerick Generating	station		YEAR		SEQUENTIAL NUMPER	NUMBER		Π				
Unit l		0 15 10 10 10 13 1 51 2	8,6	_	01112	- 010	03	OF	0 14			

TEXT (II more space is required, use sedicional NRC Form 366s) (17)

## Cause of the Event:

This isolated event was the result of an administrative oversight during the development of the surveillance test for this equipment and during the review of the Technical Specifications conducted prior to receipt of the Operating License.

## Corrective Actions:

All four radiation monitors were immediately declared inoperable and the appropriate Action Statement entered; Technical Specification Table 3.3.7.11-1, page 3/4 3-100, Action 101 -"With the number of channels OPERABLE less than required by the Minimum Channels OPERABLE requirement, effluent releases via this pathway may continue for up to 30 days provided that, at least once per 8 hours, grab samples are collected and analyzed for gross radioactivity (beta or gamma) ...."

Modification No. 704, "Revise Output Circuitry of Selected LCRM Radiation Monitors", has been implemented in order to bring the system into compliance with the Technical Specification requirements.

A review was undertaken to determine if similar problems existed in other systems. This review revealed an additional problem with the RHRSW system. The "inop circuit failure" alarm feature had not been utilized as required on the RHRSW monitors. This feature provides a control room alarm and a RHRSW system effluent pathway isolation in the event of a circuit failure resulting from a low high voltage condition of a radiation monitor. The existing circuitry did provide isolation but did not provide a control room alarm in the event of an "inop circuit failure". This could have resulted in a system isolation which would not have been recognized as being caused by these radiation monitors.

Modification #704, mentioned previously, has also resolved this circuitry problem.

MRC Form Juda -3 431	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION										U.S. NUCLEAR REGULATORY COMMISSION APPROVED DWE NO 3150-0104 EAPIRES \$21/85								
FACILITY NAME IT		Station	DOCKET NUMBER (2)				LER NUM							PAGE 131					
Limerick	Generating										SIGUINT	-	ALVISH	-					
Uniti			0	15	10	0	101	3	5 12	8	16	_	0 11 1	2	- 01	00	14	OF	0 ] 4

In addition, this review determined that the "circuit failure" alarm feature had not been utilized on the Service Water Effluent Line radiation monitor (RISH-10-1K605). A temporary circuit alteration has been made to make this feature functional and a permanent modification is scheduled to be implemented by April 30, 1986.

## Action Taken to Prevent Recurrence:

Implementation of the modifications identified as a result of the investigation will prevent recurrence.

Previous Similar Occurrences:

None.

A- 4

## PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-4000

March 14, 1986

Docket No. 50-352

Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555

1

SUBJECT: Licensee Event Report Limerick Generating Station - Unit 1

This LER concerns a failure of the Residual Heat Removal Service Water System Effluent radiation monitors to meet a requirement of the Technical Specification.

Reference:	Docket No. 50-352						
Report Number:	86-012						
Revision Number:	00						
Event Date:	February 13, 1986						
Report Date:	March 14, 1986						
Facility:	Limerick Generating Station						
	P.O. Box A, Sanatoga, PA 19464						

This LER is being submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(i)(B).

Very truly yours,

millind

W. T. Ullrich Superintendent Nuclear Generation Division

cc: Dr. Thomas E. Murley, Administrator, Region I, USNRC E. M. Kelly, Senior Resident Site Inspector See Service List

