



**Northeast  
Nuclear Energy**

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station  
Northeast Nuclear Energy Company  
P.O. Box 128  
Waterford, CT 06385-0128  
(860) 447-1791  
Fax (860) 444-4277

The Northeast Utilities System

OCT 16 1998

Docket No. 50-336  
B17477

Re: 10 CFR 50.73(a)(2)(i)(B)

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Millstone Nuclear Power Station Unit No. 2  
Licensee Event Report 98-020-00  
Safety Injection Recirculation Header Piping Components Do Not Fully Satisfy  
Inservice Inspection Requirements in Accordance  
with ASME Code Section XI Criterion


This letter forwards Licensee Event Report (LER) 98-020-00, documenting a condition that was determined reportable at Millstone Nuclear Power Station, Unit No. 2, on September 29, 1998. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B).

The Northeast Nuclear Energy Company (NNECO) commitments made within this letter are included in Attachment 1.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

FOR: J. A. Price  
Director - Millstone Unit No. 2

BY:   
John T. Swintoniewski  
Assistant Unit Director  
Millstone Unit No.2

9810260077 981016  
PDR ADOCK 05000336  
S PDR

cc: see page 2

*IE22/1*

Attachments: 1. List of Regulatory Commitments  
2. LER 98-020-00

cc: H. J. Miller, Region I Administrator  
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2  
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2  
E. V. Imbro, Director, Millstone ICAVP Inspections  
S. Dembek, NRC Project Manager, Millstone Unit No. 1

Docket No. 50-336  
B17477

Attachment 1  
Millstone Nuclear Power Station, Unit No. 2  
Commitments

October 1998

Attachment 1

Regulatory Commitment Enclosure  
List of Regulatory Commitments

The following table identifies those actions committed to by NNECO in this document.

<b>REGULATORY COMMITMENT</b>	<b>COMMITTED DATE OR OUTAGE</b>
B17477.01: The Emergency Core Cooling System/Safety Injection (SI) leakage testing procedure will be revised to include the SI recirculation header piping.	Prior to entering Mode 4 from current outage
B17477.02: The revised Emergency Core Cooling System/Safety Injection leakage testing procedure will be performed.	Prior to entering Mode 4 from current outage

Docket No. 50-336  
B17477

Attachment 2

Millstone Nuclear Power Station, Unit No. 2

LER 98 020-00

October 1998