



UNION ELECTRIC COMPANY

Callaway Plant

DMB

March 31, 1986

Mr. James G. Keppler
Regional Administrator
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

ULNRC-1280

Dear Mr. Keppler:

DOCKET NUMBER 50-483
CALLAWAY PLANT UNIT 1
FACILITY OPERATING LICENSE NPF-30
SPECIAL REPORT 86-01
DIESEL GENERATOR FAILURE DURING AN INVALID TEST

The enclosed Special Report is submitted pursuant to
Technical Specification 4.8.1.1.3 and 6.9.2 concerning a diesel
generator failure during an invalid test.

A. L. Randolph
G. L. Randolph
Manager, Callaway Plant

By TPS
DEY/TPS/JWK/drs
Enclosure

cc: Distribution attached

8604080243 860331
PDR ADDCK 05000483
S PDR

APR 2 1986

11
TEOL

cc distribution for ULNRC-1280

Mr. Paul O'Connor
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Mail Stop P-316
7920 Norfolk Avenue
Bethesda, MD 20014

American Nuclear Insurers
c/o Dottie Sherman, Library
The Exchange Suite 245
270 Farmington Avenue
Farmington, CT 06032

Mr. J. H. Smith
Bechtel Power Corporation
SNUPPS Project
15740 Shady Grove Road
Gaithersburg, MD 20877-1454

NRC Resident Inspector

D. F. Schnell (400)
R. J. Schukai (470)
S. E. Miltenberger
J. F. McLaughlin
J. E. Davis (Z40LER)
(Z40LER) (w/c)
D. W. Capone/R. P. Wendling (470)
F. D. Field (470)
A. P. Neuhalfen
A. C. Passwater/D. E. Shafer/D. J. Walker (470)
G. A. Hughes
Z40.03 (QA Record)
J. M. Price
D. E. Young
M. E. Taylor
H. Wuertenbaecher, Jr. (100)
S. L. Auston (470) (NSRB)
J. D. Schnack
GLR Chrono
3456-0021.6
3456-0260
Z40ULNRC
G56.37
N. Date (Sandra Auston) (470)

Manager, Electric Department
Missouri Public Service Commission
P. O. Box 360
Jefferson City, MO 65102

Mr. O. Maynard
Kansas Gas and Electric Company
P. O. Box 208
Wichita, KS 62701

Mr. Nicholas A. Petrick
Executive Director, SNUPPS
5 Choke Cherry Road
Rockville, MD 20850

Records Center
Institute of Nuclear Power Operations
Suite 1500
1100 Circle 75 Parkway
Atlanta, GA 30339

SPECIAL REPORT 86-01
DIESEL GENERATOR FAILURE DURING AN INVALID TEST

Surveillance Procedure ISP-SA-2413A, Diesel Generator and Sequencer Testing (Train A), was in progress on 3/6/86 to satisfy various 18 month Technical Specification (T/S) surveillance requirements. The plant had entered Mode 5, Cold Shutdown, on 3/4/86. During performance of the "'A' Train Blackout Without SIS (Safety Injection Signal)" portion of ISP-SA-2413A, the 'A' emergency diesel generator (D/G) was intentionally secured without loading to at least 50% of continuous rating. The D/G was secured to investigate a failure of the load sequencer to properly sequence the required emergency loads onto the 4.16 kV safety-related bus (NB01) energized by 'A' D/G.

Since the successful D/G start was terminated intentionally without loading to at least 50% of continuous rating, it is not considered a valid test or failure in accordance with Regulatory Position C.2.e(4) of Regulatory Guide 1.108, Revision 1, August 1977. The D/G testing frequency established by T/S Table 4.8-1 is therefore not affected by this incident and this Special Report is being submitted as required for all D/G failures, valid or nonvalid, per T/S 4.8.1.1.3. It is noted that the D/G could have been manually loaded and a valid test completed had the operators not intentionally secured the D/G for troubleshooting of the load sequencer.

Starts of the D/G's have been tracked since the completion of Preoperational Testing on 5/11/84. The starting history of the D/G's as of the date of this report is summarized as follows:

D/G	<u>Number of Valid Tests</u>	<u>Number of Failures During Valid Tests</u>	<u>Number of Failures During Invalid Tests</u>
A	31	1*	5#
B	27	0	1§

* Reference Special Report 84-02.

Reference Special Reports 85-01, 85-02, 85-07, and 86-01.

§ Reference Special Report 85-05.

The following is a summary of the events applicable to this incident.

- The "'A' Train Blackout Without SIS" portion of ISP-SA-2413A began at approximately 2018 on 3/6/86.
- Loads shed off bus NB01 as required when the test signal (blackout without SIS) was initiated.
- 'A' D/G successfully started and attained the required voltage and frequency.

- 'A' D/G output breaker closed.
- Only 'A' Centrifugal Charging Pump and 'A' Component Cooling Water Pump sequenced onto bus NB01 and were powered by the 'A' D/G.
- Testing activities were halted and troubleshooting initiated.
- Troubleshooting of the 'A' D/G output breaker identified that the plunger bolt (which actuates certain stationary contacts when the breaker closes) was out of adjustment. Consequently, the stationary contacts did not initiate a signal to the load sequencer that the breaker was closed. The condition also prevented synchronizing of the D/G with offsite power by not allowing a synchronizing check relay to pick up.
- Temporary adjustments were made such that the synchronizing check relay picked up. The D/G was paralleled with offsite power and the loads were transferred off the D/G. The D/G output breaker was opened, and the D/G secured and declared inoperable at approximately 2350 on 3/6/86.
- The plunger bolt was found to be out of adjustment by approximately 3/32 of an inch. It was adjusted within tolerance per Electrical Preventive Maintenance Procedure MPE-ZZ-QS005, Cleaning, Inspection, and Lubrication of 13.8 kV and 4.16 kV Breakers, at 0210 on 3/7/86.
- The "'A' Train Blackout Without SIS" portion of ISP-SA-2413A was again commenced at approximately 2040 on 3/7/86 and completed satisfactorily.
- 'A' D/G was declared operable at 2222 on 3/7/86.

Verification of proper adjustment of the plunger bolt for 'A' D/G output breaker was last performed on 5/20/85 during an 18 month preventive maintenance inspection. The cause of the plunger bolt being out of adjustment is unknown. This type of problem has not been a frequently experienced occurrence associated with the D/G output breakers; however, due to the significance of the plunger bolt/stationary contacts function, a preventive maintenance inspection for proper adjustment of the plunger bolt will be evaluated for increased periodicity for 'A' and 'B' D/G output breakers.

This incident occurred while the plant was in Mode 5. In this mode, T/S 3.8.1.2 requires only one diesel generator to be operable. 'B' D/G was operable while 'A' D/G was out of service for testing and

inoperable due to the output breaker plunger bolt. Performance of ISP-SA-2413B, Diesel Generator and Sequencer Testing (Train B), began following completion of ISP-SA-2413A. On 3/10/86 the load sequencer for 'B' train functioned satisfactorily when the breaker closed during the "'B' Train Blackout Without SIS" portion of ISP-SA-2413B.

Surveillance tests are currently performed at least once per 31 days for each D/G. This is in conformance with the schedule of Regulatory Position C.2.d of Regulatory Guide 1.108, Revision 1, August 1977, and Technical Specification Table 4.8-1 which require the test interval to be not more than 31 days if the number of failures in the last 100 valid tests is one or zero.