

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) South Texas Unit 1 DOCKET NUMBER (2) 050004981 OF 02 PAGE (3)

TITLE (4) Leakage of Aluminum-Bronze Essential Cooling Water System

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)			
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)		
04	01	88	88	02	00	05	31	88	South Texas Unit 2	05000499		

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §. (Check one or more of the following) (11)

OPERATING MODE (9) 0	20.402(b)	20.406(c)	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10) 0.00	20.406(a)(1)(i)	50.38(a)(1)	50.73(a)(2)(v)	73.71(c)
	20.406(a)(1)(ii)	50.38(a)(2)	50.73(a)(2)(vi)	<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	20.475(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(viii)(A)	Voluntary
	20.406(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)	
	20.406(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(ix)	

LICENSEE CONTACT FOR THIS LER (12)

NAME: Charles Ayala - Supervising Licensing Engineer TELEPHONE NUMBER: 512 972-1862

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS
B									

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On April 1, 1988, while the plant was in Mode 3, operations personnel observed slight leakage occurring at a number of locations in the aluminum-bronze Essential Cooling Water (ECW) system. Further investigation revealed that some small bore (2 inch and under) fittings and valves in the ECW system have undergone crevice corrosion (dealloying) extensive enough to have resulted in through wall seepage. Leaking components found prior to the beginning of a May 2, 1988 outage and certain higher stressed small bore fittings and valves were replaced prior to resumption of operation. A long term solution is being developed which will result in more permanent corrective actions prior to startup from the first refueling outage.

8806100165 880531
PDR ADOCK 05000498
S PDR

NL.LER88028

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1) South Texas Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 4 9 8	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 8	- 0 2 8	-- 0 0	0 2	OF 0 2

TEXT (If more space is required, use additional NRC Form 368A's) (17)

A full description of this event and corrective actions was submitted to the NRC by letter ST-HL-AE-2652 (attached) dated May 12, 1988.

NL.LER88028

The Light company

Houston Lighting & Power

P.O. Box 1700 Houston, Texas 77001 (713) 228-9211

May 31, 1988
ST-HL-AE-2666
File No.: G26
10CFR50.73

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 1
Docket No. STN 50-498
Licensee Event Report 88-028 Regarding
Leakage of Aluminum-Bronze Essential Cooling Water System

Houston Lighting & Power Company (HL&P) is submitting the attached voluntary Licensee Event Report (LER 88-028) regarding aluminum-bronze essential cooling water system leakage. This event did not have any adverse impact on the health and safety of the public.

If you should have any questions on this matter, please contact Mr. C.A. Ayala at (512) 972-8628.

G.E. Vaughn by W.H. King
G. E. Vaughn
Vice President
Nuclear Plant Operations

GEV/BEM/nl

Attachment: Licensee Event Report 88-028
Regarding Leakage of Aluminum-
Bronze Essential Cooling Water
System

IER22
11

cc:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

Rufus S. Scott
Associated General Counsel
Houston Lighting & Power Company
P. O. Box 1700
Houston, TX 77001

George Dick
U. S. Nuclear Regulatory Commission
Washington, DC 20555

INPO
Records Center
1100 Circle 75 Parkway
Atlanta, Ga. 30339-3064

Dan R. Carpenter
Senior Resident Inspector/Operations
c/o U. S. Nuclear Regulatory Commission
P. O. Box 910
Bay City, TX 77414

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

Don L. Garrison
Resident Inspector/Construction
c/o U. S. Nuclear Regulatory Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

R. L. Range/R. P. Verret
Central Power & Light Company
P. O. Box 2121
Corpus Christi, TX 78403

R. John Miner (2 copies)
Chief Operating Officer
City of Austin Electric Utility
721 Barton Springs Road
Austin, TX 78704

R. J. Costello/M. T. Hardt
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

The Light company

Houston Lighting & Power

FILE COPY

P.O. Box 1700 Houston, Texas 77001 (713) 228-9211

May 12, 1988
ST-HL-AE-2652
File No.: G25

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Units 1 & 2
Docket Nos. STN 50-498 and STN 50-499
Leakage of Aluminum-Bronze Essential Cooling Water System

On April 1, 1988 Houston Lighting & Power Company (HL&P) operations personnel at the South Texas Project Electric Generating Station (STPEGS) Unit 1 observed slight leakage occurring at a number of locations in the aluminum-bronze Essential Cooling Water (ECW) system. This discovery has resulted in an intensive effort to determine the scope of the problem, its root cause and the necessary corrective actions.

Some small bore (2 inch and under) fittings and valves in the ECW system at STPEGS Unit 1 have undergone crevice corrosion (dealloying) extensive enough to have resulted in through wall seepage. Leaking components found prior to the beginning of the current outage and certain of the higher stressed small bore fittings and valves will have been replaced before resumption of operation.

Although destructive examinations have shown that small bore fittings and valves that had shown no sign of seepage have experienced varying degrees of crevice corrosion, data from extensive metallographic examinations have been combined with stress analyses, structural evaluations and estimates of the rate of dealloying to provide confidence that these components have substantial margins and will not fail as the result of postulated load combinations.

Failure analyses have shown that due to its ductile behavior and the low design stresses, aluminum-bronze will not undergo brittle failure. Furthermore, the components have substantial margins on a plastic limit load basis. Safety analyses demonstrate that the effects of leakage associated with the dealloying will not compromise the ability of the Essential Cooling Water system to accomplish its safety function. Further, the consequences of assumed failures have been found to be bounded by design basis calculations previously performed to evaluate postulated flooding and spray effects.

~~80152/0386~~
~~BT~~

L3/GT/NL

A Subsidiary of Houston Industries Incorporated

Although there is no evidence of any leakage from aluminum-bronze components larger than 2 inches, a destructive examination of an 8 inch cast aluminum bronze butterfly valve and an in-place examination of the crevice area behind a backing ring on an 8 inch cast weld neck flange have been conducted. The destructive examination on the butterfly valve confirmed that the depth of crevice corrosion is similar to that observed on the small bore components. The in-place examination in the crevice area behind the backing ring on the 8 inch weld neck flange showed only shallow dealloying.

Taken together, these examinations and analyses provide the basis for our confidence that STPEGS Unit 1 can be operated without undue risk to the health and safety of the public. Nevertheless, HL&P is working towards a more permanent solution for small bore fittings and valves. HL&P will have this solution in hand in time to be implemented prior to fuel loading in Unit 2. This schedule would support implementation of the more permanent corrective action prior to the return to service of Unit 1 after its first refueling outage.

If you should have any questions on this matter, please contact me at (512)972-7138.



S.L. Rosen
General Manager
Operations Support

MAM/jks

- Attachments:
1. HL&P Report on Evaluation of the ECW System at STPEGS
 2. Bechtel Report on Failure Analysis and Structural Integrity Evaluation of Leaking Aluminum-Bronze Cast Valve Bodies and Fittings in the ECW System

cc:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011

George Dick, Project Manager
U. S. Nuclear Regulatory Commission
1 White Flint North
11555 Rockville Pike
Rockville, MD 20859

Dan R. Carpenter
Senior Resident Inspector/Operations
c/o U. S. Nuclear Regulatory Commission
P. O. Box 910
Bay City, TX 77414

Don L. Garrison
Resident Inspector/Construction
c/o U. S. Nuclear Regulatory Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

R. L. Range/R. P. Verret
Central Power & Light Company
P. O. Box 2121
Corpus Christi, TX 78403

R. John Miner (2 copies)
Chief Operating Officer
City of Austin Electric Utility
721 Barton Springs Road
Austin, TX 78704

R. J. Costello/M.T. Hardt
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 1700
Houston, TX 77001

INPO
Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

Revised 03/18/88

L1/NRC/cc1

ATTACHMENT 1
ST-HL-AE-2652
MAY 12, 1988
HOUSTON LIGHTING & POWER COMPANY

EVALUATION OF THE ESSENTIAL
COOLING WATER SYSTEM AT THE
SOUTH TEXAS PROJECT ELECTRIC GENERATING STATION

~~8805240386~~
~~12 pp~~

Revision 0
May 12, 1988

TABLE OF CONTENTS

- I. Introduction
- II. Nature and Cause of Corrosion
- III. Immediate Actions
- IV. Evaluation of Area of Dealloying of Samples
- V. Statistical Analysis
- VI. Evaluation of Structural Integrity
- VII. Short Term Program
- VIII. Corrective Action for Small Bore Components
- IX. Large Bore System

Evaluation of the Emergency Cooling Water System
at the South Texas Project

I. INTRODUCTION

On April 1, 1988, several small bore socket connections in the ECW were observed to be leaking in a seepage fashion. Corrosion products and wetness were found on the surface. This discovery resulted in an intensive effort to determine the scope of the problem, its root cause and the necessary corrective actions.

A letter including an Action Plan was submitted to the NRC on April 21, 1988 (ST-HL-AE-2632). This plan included investigations into cause of corrosion, sampling of components by metallurgical sectioning, a review of the feasibility of non-destructive examination, stress and structural integrity analysis, on-going monitoring and the development of a replacement program for susceptible components in the small bore piping system.

The following is a summary of actions that have been taken to date and those planned.

II. NATURE AND CAUSE OF CORROSION

On April 11, 1988 three (3) components were removed from the system and examined for material condition and nature of the corrosion. The results of this diagnostic investigation are included in the Bechtel report (Attachment 2). The following conclusions were reached.

- o The nature of corrosion is "dealloying", a phenomenon in which the aluminum in one of the microstructural phases selectively corroded, leaving the balance of the matrix intact.
- o The material of the cast valves (ASME SB148 Grade CA954) and fittings (typically ASME SB148 Grade CA952) contained the Gamma-2 phase. This condition lends itself to selective corrosion of the Gamma-2 phase, causing dealloying, in severe corrosive environments.
- o The attack was significant at crevices, tapering off in parts away from the crevice.
- o The chemistry of the water in the socket crevices was significantly more acidic than the bulk water chemistry, thus causing the severe condition which, in combination with the metallurgical condition of the materials, resulted in the selective corrosion.
- o Piping and weld metal had suffered no corrosion, demonstrated that alloy CA614 was not subject to the observed phenomenon.

III. IMMEDIATE ACTIONS

A program of walkdowns was immediately instituted, which resulted in the detection of more indications of seepage. The seepages in many cases are difficult to identify because of the extremely low seepage rates. As a result it took several cycles of inspection to identify all leaking components. The baseline has now been established and the rate of occurrence of new leaks is low (See Figure 1). The maximum leak rate was estimated to be 10 ml/day.

Leaking components were removed from the system and sectioned to characterize the degree of corrosion and the structural integrity of the system. Additionally, fittings which had less than 70% margin in design wall thickness to meet Code stress allowables (under all loading conditions) were replaced to improve the structural integrity margins of the system. Fittings that were removed were replaced with spare aluminum bronze fittings or pipe. Replaced fittings (except the first four removed) were re-heat-treated by annealing and water quenching. Valves were replaced by available spare aluminum bronze valves. When the spare valves were depleted, carbon steel valves (N-stamped in accordance with ASME Code, Section III, Class 3) were installed.

These replacements restored the small bore system to a leak tight condition with improved structural integrity margins. The remaining partially dealloyed components in the system were analyzed as described below for structural integrity. The intent is to implement permanent corrective action prior to startup following the first refueling outage for Unit 1 and prior to fuel load on Unit 2.

IV. EVALUATION OF AREA OF DEALLOYING OF SAMPLES

Removed components were sent to Bechtel Materials & Quality Services for evaluation of area of dealloying. While most of the components removed had at least one socket end leaking, the sample included some components which had neither side leaking, as a result of the location of the cuts in the piping system. The sample was thus randomly selected.

The socket ends were examined for area of dealloying by cutting, polishing and etching. The worst case total area of dealloying was estimated by an iterative process of progressive slicing and etching. Figure 2 shows, in summary, the distribution of socket ends that were cut and evaluated in this fashion.

It has been observed that fittings were, in general, less dealloyed than valves, which is attributed to the lower aluminum content of the CA952 alloy used in small bore fittings. The total sample of susceptible cast materials, contained mostly leaking valves of the CA954 alloy and is thus biased in the conservative direction.

V. STATISTICAL ANALYSIS

The results of the measurement of dealloyed area in the sample of 24 leaking and 41 non-leaking socket ends were statistically analyzed to project the worst case dealloyed area in a previously leaking (replaced) socket end, and in a non-leaking socket end. It was determined with 95% probability and 95% confidence level that a socket end in the present non-leaking population has no more than 55% area dealloyed. The mean area dealloyed is 20% as shown in Figure 3.

VI. EVALUATION OF STRUCTURAL INTEGRITY

The worst case dealloyed cross section in the current population (with "leakers" and high stress points eliminated) was evaluated for structural integrity as follows.

Stress Evaluation

Stress analyses were performed on the components conservatively assuming them to be 100% dealloyed (although the 95% probable worst case is 55% dealloyed). The strength of dealloyed materials was established by tensile

tests as 30 ksi. Calculations were performed with this strength for the sustained and secondary loads in accordance with the ASME Code, Section III, and were found to be within Code allowables with significant margin.

Fracture Evaluation and Limit Load Analysis

Additionally, a linear elastic fracture mechanics screening analysis was performed. The fracture analysis treated the dealloying as a planar flaw which is highly conservative since there is actually no discontinuity. Brittle fracture was demonstrated not to be the controlling mechanism.

A limit load analysis for plastic collapse was then performed using two bounding cases: dealloying uniformly distributed in a circumferential plane, and dealloying concentrated in a worst case bending plane. In addition, the increase in the extent of dealloying three years into the future was also evaluated. The composite sections, allowing for the specification properties for aluminum bronze and 30 ksi for the dealloyed section, showed good margins to failure.

Rate of Corrosion

Attachment 2 establishes the rate of corrosion based on standard corrosion models, with the parameters based on observations at the South Texas Project. It is assumed conservatively, that the observed corrosion occurred over a 3 year period, though parts of the system may have been wetted earlier. It is also assumed, for the purposes of this projection, that in the worst case, 100% dealloying occurs over 3 years, although the mean area of dealloying for the leaking connections was 48%. This established a rate constant for the corrosion curve for observed phenomenon specific to the project. The projections of structural integrity discussed above are based on increased dealloying based on this projection.

Proof Tests

To establish the load capacity of partially dealloyed components, proof tests of partially dealloyed components were conducted. The proof tests subjected whole fittings with partial dealloying to hydrostatic pressure up to failure. The tests included components that had previously leaked. These components did not fail under proof test but eventually the leak rate exceeded the hydrostatic pump capacity. A test on a component without leakage resulted in the failure of a test cap before the fitting. Figure 4 shows the results in summary. It can be seen that the pressure load capacity of partially dealloyed components (even with prior through wall seepage) is from 49 to 74 times the design pressure. This demonstrated substantial safety margin. By comparison, the ASME code only requires a hydrostatic test at 1.25 times the design pressure.

Tensile Tests

Tensile tests measured the strength of the composite partially dealloyed cross section and of the dealloyed material itself. Figure 5 is a summary of these tests. Based on this, it can be seen that the dealloyed section has substantial strength, and contributes to the overall load carrying capacity.

VII. SHORT TERM PROGRAM

Prior to startup following the first refueling outage on Unit 1, HL&P will continue the present augmented surveillance program. Work is continuing to identify a more permanent solution.

VIII. CORRECTIVE ACTION FOR SMALL BORE COMPONENTS

A more permanent solution for susceptible small bore valves and fittings will be implemented prior to startup following the first refueling outage for Unit 1. The more permanent solution for susceptible small bore valves and fittings will be implemented for Unit 2 prior to fuel load. In preparation for this, alternate materials are being reviewed and tested. The options being examined include the following:

- o For small bore fittings - reheat treat available spares to a non-susceptible condition; or fabricate from non-susceptible CA 614 piping.
- o For valves - nickel aluminum bronze Grade CA958, 70/30 Cupro nickel Grade C71500, aluminum bronze castings equivalent to Grade CA614 (if available), certain stainless steels and carbon steel are being considered. Corrosion and metallurgical checks are in progress to select the material. Weld overlay of socket ends is also being investigated.

IX. LARGE BORE SYSTEM (ABOVE 2" DIAMETER)

No large bore components have leaked; however, some contain materials that have the potential for dealloying. In general, most large bore components have more wall thickness. The following is a review of the potentially susceptible components.

Fittings

Most fittings are wrought products of the CA614 type. This alloy is demonstrated to have no dealloying. Most fittings are also free from crevices. The exceptions are an estimated 42 weld neck flanges and reducing tees installed with backing rings. One backing ring was removed and the area under it examined. A superficial depth of dealloying of 0.015" was found. It appears that backing rings do not promote the same kind of tight crevice corrosion environment as do small bore sockets. The CA952 alloy is used in fittings is less susceptible to dealloying than the CA954 alloy used in valves.

Valves

A high percentage of valves are of the wafer butterfly type which have substantial wall thickness. A sample valve was examined for dealloying. Dealloying up to a depth of 0.15" was found, however these components have a substantial margin to the design minimum wall thickness. The crevice geometry is primarily at the gasket.

Pumps

The ECW pump discharge elbow and some internals are aluminum bronze castings. The ECW screen wash booster pump body is an aluminum bronze casting. Some dealloying indication was observed on the flange face of the booster pump.

Heat Exchangers

The tube sheets and channels of CCW Heat Exchangers and of the essential chiller condenser are plate materials of type CA614, a non-susceptible alloy.

Structural Integrity of Large Bore Components

Stresses at large bore welds with cast components and backing rings were reviewed for design margins and found to be acceptable per ASME Code requirements assuming 100% dealloyed sections.

Using methods similar to those used to evaluate small bore fittings, structural integrity of large bore components was established. Adequate margins were demonstrated.

It is therefore concluded that large bore components have no structural integrity issue.

ECW LEAKS SUMMARY CHRONOLOGY

NUMBER OF LEAKING COMPONENTS

<u>DATE</u>	<u>TOTAL CUMULATIVE</u>	<u>REPLACED</u>	<u>REMAINING</u>
4/08/88	50	.	
4/11/88		2	
4/15/88	64		64
4/16/88		9 (TRAIN C OUTAGE)	55
4/19/88	77		66
4/20/88	85		74
4/22/88		26 (TRAIN A OUTAGE)	48
4/26/88	89*		52
5/02/88	90		53
5/09/88	90	26 (TRAIN B OUTAGE)	27

* 5 NEW LEAKS IDENTIFIED BUT A PREVIOUS LEAK DETERMINED TO BE A CASTING INDICATION

FIGURE 1

STP UNIT 1 ALUMINUM/BRONZE ECWS
DISTRIBUTION OF SAMPLED FITTINGS




FIGURE 2

**STP UNIT 1 ALUMINUM/BRONZE ECWS
PIPING CUMULATIVE PERCENT DEALLOYED**




FIGURE 3

PROOF TESTS

ITEM	LEAKER/ NONLEAKER	SIZE	MAXIMUM CROSS SECTION AREA <u>DEALLOYED</u>	FAILURE* PRESSURE <u>PSI</u>	PRESSURE RATIO FAILURE TO DESIGN
COUPLING	L	2"	38%	8950	74.6
TEE	L	2"	52%	5900	49.2
ELBOW	NL	2"	0%	6500**	54.2

*FAILURE WAS BY LEAKING FASTER THAN THE 200CC/MIN. PUMP
COULD KEEP UP WITH.

CALCULATED THEORETICAL BURST PRESSURE IS 6800.

(ASSUMING NO DEALLOYING & NOMINAL TENSILE PROPERTIES)

** FAILED AT WELD TO CARBON STEEL END PLATE

FIGURE 4




FIGURE 5

ATTACHMENT 2
ST HL-AE-2652
MAY 12, 1988


BECHTEL REPORT
ON
FAILURE ANALYSIS AND STRUCTURAL
INTEGRITY EVALUATION OF LEAKING
ALUMINUM - BRONZE CAST VALVE BODIES
AND FITTINGS IN THE ECW SYSTEM

~~8805240389~~
~~4077~~


FAILURE ANALYSIS AND STRUCTURAL INTEGRITY EVALUATION
OF LEAKING ALUMINUM-BRONZE
CAST VALVE BODIES AND FITTINGS IN THE ECW SYSTEM

Report for
Houston Lighting and Power Company
South Texas Project

Prepared for J. L. Hurley

By 

R. A. White
Materials and Corrosion Group Manager

Approved 

R. A. Manley
Manager

Materials and Quality Services
Research and Development
BECHTEL NATIONAL, INC.
SAN FRANCISCO

Job No. 19280-001-042
Log No. 0318157

107im

Tech. Report No. 8804-06 FA
BLN No. 8804-07

May 11, 1988
Revision 0

ABSTRACT

This report presents the metallurgical failure analysis and the structural integrity evaluation of the leaking aluminum-bronze castings in the Essential Cooling Water system (ECW) at the South Texas Project (STP) Unit No. 1.

The failure analysis of two valves (one leaker, one non-leaker) and one fitting consisted of metallurgical cross sections, heat treatment studies, chemical and X-ray diffraction studies, microstructure analysis and the verification that the field replication procedure is satisfactory on aluminum-bronze. The failure analysis revealed that the leaks are caused by dealloying corrosion. The plain aluminum-bronze alloys in use (952 and 954) are susceptible to this form of corrosion.

The structural integrity evaluation consisted of cross sectioning and mapping the dealloying in 32 additional castings, performing miniature tensile tests on castings with known dealloying, performing proof tests on three fittings, two containing through wall leakage, and a statistical analysis of the extent of the dealloying plus fracture and limit load analysis.

The metallurgical and structural integrity analysis has demonstrated that the material has significant margin against failure for the design loading conditions. Proof tests of actual components with dealloying demonstrated load capacity on the order of 50 times the design pressure.

Key Words

dealloying
aluminum-bronze

FAILURE ANALYSIS AND STRUCTURAL INTEGRITY EVALUATION
OF LEAKING ALUMINUM-BRONZE
CAST VALVE BODIES AND FITTINGS IN THE ECW SYSTEM

CONTENTS

	<u>Page</u>
ABSTRACT	i
CONTENTS	ii
LIST OF ILLUSTRATIONS	iii
1.0 FAILURE ANALYSIS OF FIRST THREE SAMPLES	1.1
1.1 Introduction	1.1
1.2 Conclusions of the First Diagnostic Phase	1.1
1.3 Materials	1.2
1.4 Evaluation Methods	1.2
1.5 Discussion of Results	1.3
2.0 STRUCTURAL INTEGRITY	2.1
2.1 Introduction	2.1
2.2 Statistical Analysis	2.1
2.3 Stress Evaluation	2.3
2.4 Fracture Mechan.cs Integrity Analysis.....	2.5
2.5 Proof Tests	2.8
2.6 Dealloying Rate Studies.....	2.9

LIST OF ILLUSTRATIONS

TABLES

		<u>Page</u>
Table 1.1	Analysis of Cross Sections	1.5
Table 1.2	Chemical Analyses	1.7
Table 2.1	Statistical Sampling of ECW System Fittings	2.11
Table 2.2	Design and Operating Data	2.13
Table 2.3	Summary of Fitting Dimensions and Highest Stress Levels	2.14
Table 2.4	Stress Values.....	2.15

FIGURES

Figure 1.1	As-received parts	1.8
Figure 1.2	Typical microstructures	1.9
Figure 1.3	Location of cross sections, valve EW269.....	1.11
Figure 1.4	Location of cross sections, valve EW315	1.12
Figure 1.5	Location of cross sections, elbow	1.13
Figure 1.6	Comparison of photomicrographs of a specimen and a replica of the specimen	1.14
Figure 2.1	Bending Stress Capacity for Dealloying 2-inch Fitting..... Based on LEFM	2.16
Figure 2.2	Conditions for Net-Section Plastic Collapse for 360°..... Part-Through Dealloying	2.17
Figure 2.3	Conditions for Net-Section Plastic Collapse for..... Through-Wall Dealloying	2.18
Figure 2.4	Aluminum Bronze Fitting Stress Ratio to Allowable.....	2.19
Figure 2.5	Distribution of Sampled Fittings.....	2.20
Figure 2.6	Dealloying of Aluminum Bronze	2.21

1.0 FAILURE ANALYSIS OF FIRST THREE SAMPLES

1.1 Introduction

On April 1, 1988, weeping type leaks were found in valves and fittings in the 2 inch and smaller piping in the Essential Cooling Water System (ECW). This was in unit number 1 of the South Texas Project (STP). To date, 90 of the approximately 800 valves and fittings have signs of weeping. The weeping is limited to the valves and fittings, which are all aluminum-bronze castings. The aluminum-bronze piping and welds show no sign of weeping. This is consistent with the literature that shows that alloys with less than 8 percent aluminum (wrought pipe and weld metal) are resistant to dealloying and alloys with greater than 8 percent aluminum (valve and fitting castings) are subject to dealloying under certain conditions.

Bechtel's Materials and Quality Services was initially requested to perform a failure analysis of a weeping valve and a fitting. The intent of this initial analysis was to identify the mechanism that is causing the weeps and the underlying metallurgical, design and environmental factors that led to the failures.

1.2 Conclusions of the First Diagnostic Phase

- A. The leaks are caused by dealloying corrosion going through the wall of the cast valve or cast fitting.
- B. Only castings have any sign of dealloying.
- C. There is no sign of dealloying corrosion in either the weld metal or the wrought Al-bronze pipe.
- D. The greatest amount of through-wall corrosion occurs in the region of the crevice and gap between the pipe and valve or pipe and fitting (socket end).
- E. The metallurgical microstructure of the valves and fittings is a mix of three phases: alpha, beta and gamma₂. It is the aluminum in the gamma₂ phase that is preferentially corroded. The microstructures examined to date have a complete network of gamma₂ so that there is a path through the casting for dealloying to cause leaks.
- F. Forced air cooling as specified by the supplier's procedure does not prevent the formation of the gamma₂ phase, which is susceptible to dealloying.
- G. The chemistry of one valve body was check analyzed and was in conformance with the specification, ASME SB-148 CA 954.

- H. The corrosion products are as expected. They contain aluminum, iron, calcium, and copper. There is some evidence of Gallionella in the corrosion products. To date, we have found no evidence that this known iron bacteria has any effect on Al-bronze.
- I. The identification of the phases (alpha, beta and gamma₂) is based on:
 - 1. Sample photomicrographs provided by the material supplier (see Figure 1.2a).
 - 2. Heat treating three samples from a valve, and cooling them in water, air and in the furnace, and comparing their microstructures.
- J. Metallurgical plastic replicas were taken from a laboratory specimen and directly from an elbow. A comparison of the photomicrographs taken at 480X of the lab specimen and the two replicas shows them to be essentially the same.
- K. Field replicas can be used to nondestructively determine the microstructure of Al-bronze castings.
- L. The pH of the residual water inside valve EW-0269 (serial No. 61-382) was 6.0.
- M. The fittings and valves are experiencing dealloying corrosion because:
 - 1. The microstructure contains the gamma₂ phase which is susceptible to dealloying.
 - 2. The pH in the crevices due to the electrochemistry of the crevice is acidic, which promotes dealloying.
- N. The biocides and other water treatment chemicals do not appear to have promoted the dealloying. (See Appendix A for typical cooling water chemistry logs.)

1.3 Materials

- A. The valve bodies are specified to be cast aluminum-bronze to specification SB-148 CA 954 (10 - 11.5 percent aluminum).
- B. The fittings are specified to be cast aluminum-bronze to specification SB 148 CA 952 (8.5 - 9.5 percent aluminum).
- C. The pipe material conforms to SB 169 C61400 (6-8 percent aluminum).

1.4 Evaluation Methods

- A. The as-received pieces were photographed and are shown in Figure 1.1.

- B. In order to properly interpret the microstructure of Al-bronze, two actions were taken. The supplier of the raw castings was asked to send us photomicrographs of the typical microstructures of Al-bronze. Figure 1.2a is the information from them. Second, three small samples from Valve EW-0269 (serial No. 61-382) were heated above 1100°F for one hour. One sample was cooled in water, one in air and one was left in the furnace and slow cooled by turning off the power. Figure 1.2b shows the microstructure of the three specimens.
- C. Cross sections were taken through the valve that leaked, the fitting (elbow) that leaked and the valve that did not leak. Table 1.1 compiles all the information obtained from this work and references the applicable figures that show the microstructures and macrostructures.
- D. The chemistry of Valve EW 269 was determined. The results are listed in Table 1.2.
- E. The residue in the socket weld crevice in the elbow was analyzed by EDAX for elements and by X-ray diffraction for compounds. The residue was also analyzed for bacteria that are known to be active in microbiologically influenced corrosion. The results are in Table 1.2.
- F. When Valve EW 269 was unpacked, it was found to have been sealed up by plastic bags and tape. There was still a slight amount of moisture trapped in the valve. The pH was measured with litmus paper and was pH 6.0.
- G. It is common practice to use a technique called replication at a field location, when a metallurgist wants to know the microstructure of a piece of equipment but can't cut out a sample of material. This method is well understood for carbon and stainless steels. In case it was needed in the field, a test was made to be sure that the techniques also work for Al-bronze. The standard field replication techniques for grinding, polishing and etching work quite well. Replicas were taken from a laboratory specimen and from an elbow polished and etched as if it was being done in the field. The photomicrographs of the two replicas and of the actual piece of material are almost identical (see Figure 1.6).
- H. The chemistry as well as the pH of a saturated solution of welding flux were taken to determine if the flux might have been the source of the low pH.

1.5 Discussion of Results

- A. The study to determine the visual appearance of the three phases (alpha, beta and gamma₂) was completed in a satisfactory manner. A comparison of the sample photograph from the supplier and the photomicrographs prepared by Bechtel show how to identify the three phases. The cross sections show several things:

1. The valves and elbows contain gamma₂ phase, which indicate that the forced air cooling per the supplier's procedure did not prevent its formation.
 2. The microstructure of a fitting that was tempered and forced air cooled by Bechtel was identical to the as-received material. This confirms that forced air cooling does not prevent the formation of gamma₂.
 3. Dealloying is the corrosion mechanism that is causing the leaks.
- B. The chemistry of the base metal is as expected, as was the analysis of the corrosion products. The influence of MIC on this problem is unknown. Gallionella was found in moist residue in the crevice of the elbow.
- C. The pH of the sample of residual water found in Valve EW 269 was slightly low. The site records show a pH of 8 to 9 for the system. However, it was reported that a pH of 4 was measured in the water weeping from a leaking valve. This low pH is most likely a result of the electrochemical effect of the crevice.
- D. EDAX analysis of the welding flux reveals significant amounts of fluorine and sodium and lesser amounts of aluminum and silicon. Wet chemical analysis revealed 1.01 percent boron. The pH of a saturated solution both of as-received and of high temperature baked flux dissolved in distilled water (pH 6) was pH 7.2, i.e., the flux is basic.

TABLE 1.1

ANALYSIS OF CROSS SECTIONS OF
INITIAL SAMPLES

SERIAL NO. PROJECT ID NO.	VALVE OR FITTING, HEAT NO.	TYPE OF CROSS SECTION	WORST CASE LOCAL PENETRATION OF DEALLOYING	METALLURGICAL STRUCTURE	LOCATION OF CROSS SECTION	PHOTOMICROGRAPH	MOUNT NO.
61-382 EW 269	Valve H5174-44	Circumference 100 to 200 degrees	27% 0.12 in.	Alpha and γ_2 50%/50%	Fig. 1.3 Leaking ends	Continuous network of γ_2 dealloying and minor pits	7040
61-382 EW 269	Valve H5174-44	Longitudinal @ 180 degrees	100% plus 0.025 in. on the OD and ID	Alpha and γ_2 50/50%	Fig. 1.3 leaking end	Dealloying is "U" shaped. Continu- ous network of γ_2 in valve. Pipe and weld no γ_2	7041
61-382 EW 269	Valve H5174-44	Longitudinal @ 180 degrees thru bronze valve and carbon steel pipe (drain connection)	None	Alpha and γ_2 and small grey dots in both phases 50/50	Fig. 1.3 No Leak	No dealloying continuous network of γ_2	7042
466-185 EW 315	Valve H5174-36	Longitudinal @ 180 degrees Bronze valve to bronze pipe	50% Some were to 25%	Alpha γ_2 and beta. Small grey dots in both phases 50%/50%	Fig. 1.4 No Leak	Dealloying continuous γ_2 network	7043

TABLE 1.1 (cont'd)

SERIAL NO. PROJECT ID NO.	VALVE OR FITTING, HEAT NO.	TYPE OF CROSS SECTION	WORST CASE LOCAL PENETRATION OF DEALLOYING	METALLURGICAL STRUCTURE	LOCATION OF CROSS SECTION	PHOTOMICROGRAPH	MOUNT NO.
	Elbow	Longitudinal @ 180 degrees Bronze elbow to bronze pipe	100% @ socket weld gap.	Alpha and & gamma ₂	Fig. 1.5	Gamma ₂ network semi-continuous. Dealloying @ gap	7044
	H9528-31			70%/30%	Leaking end		
	Elbow	Circumference 100 to 200 degrees	60%	Alpha and gamma ₂		Dealloying on ID on the entire specimen.	7045
	H9528-31			70% alpha/ 30% gamma ₂	Leaking end		
	Elbow	Longitudinal 90 degrees away from leak and back from gap	40%	Alpha and gamma ₂		Dealloying on the ID around the gap and down toward weld	7046
	H9528-31			70% alpha/ 30% gamma ₂	Leaking end		
	Elbow	Circumference extrados	40% Small spot ----- Remainder is one or two grains deep ID	Alpha and gamma ₂		Dealloying on ID	7047
	H9528-31			70% alpha/ 30% gamma ₂	No leak		

TABLE 1.2

CHEMICAL ANALYSES

1. Base metal of Valve EW-269 by emission spec.

Element	<u>Cu</u>	<u>Al</u>	<u>Fe</u>	<u>Mn</u>	<u>Ni</u>
% Weight	84.9	10.6	4.25	0.11	0.06

2. Corrosion product analysis by EDAX

Element	<u>Al</u>	<u>Fe</u>	<u>S</u>	<u>Ca</u>	<u>Cl</u>	<u>Si</u>	<u>Cu</u>
% Screen Height	100	100	20	20	15	10	8

3. Corrosion product compound analysis by x-ray diffraction


$1/2 (\text{Fe}_2\text{O}_3 - \text{H}_2\text{O})$

CaCO_3

These are the only compounds with strong patterns. Since the EDX results show a strong line for aluminum, the only aluminum compound that has a very weak crystal pattern is $\text{Al}(\text{OH})_3$. It should be noted that this compound is most commonly the result of the corrosion of aluminum.

4. Bacterial analysis of the corrosion product revealed evidence of Gallionella, which is one of the bacteria known to be involved in the corrosion of steel and stainless steel.


Valve EW 269
Serial No. 61-352



Value handle @ 0°
Leak @ 180°


LEAK

Valve EW 315
Serial No. 466-185




Value handle @ 270°
No Leak in Valve
Leak in Fitting @ 180°

Elbow Heat No. H9528-36




LEAK


FIGURE 1.1 As Received




1. Wrought Structure
Alpha Phase




2. Slowly Cooled
Alpha Plus Beta Phases



3. Slowly Cooled
Alpha Phase Plus Eutectoid



4. Rapid Quench
Martensitic Beta




5. Rapid Quench Plus Anneal
Martensitic Beta Plus
Acicular Alpha




6. Slow Cool
Beta Plus Gamma Phases

FIGURE 1.2a Typical Microstructures




Heat at 1150°F one hour
Water Quench

Source: Bechtel Valve 269



Heat at 1220°F one hour
Air Cool - Fan


Source: Bechtel Elbow
Heat No. H95-28-36



Heat at 1250°F one hour
Furnace Cool


Source: Bechtel Valve EW 269

FIGURE 1.2b Typical Microstructures




Mount 7040
2X
NH₄OH - H₂O₂ etch

Mount 7040
480X
NH₄OH - H₂O₂




Mount 7041
5X
NH₄OH - H₂O₂

FIGURE 1.3 Valve EW 269




Mount 7043
5X
NH₄OH - H₂O₂

FIGURE 1.4 Valve EW 315



Mount No. 7044
2X
NH₄OH - H₂O₂

Mount 7047
500X
NH₄OH - H₂O₂



Mount No. 7045
2X
NH₄OH - H₂O₂




FIGURE 1.5 - Elbow Heat No. H9528-36

480X Replica


7040



Replica

480X

7040



Laboratory Mount

FIGURE 1.6 Comparison of replica micrograph with laboratory micrographs, Valve EW 269

2.0 STRUCTURAL INTEGRITY

2.1 Introduction

During the period prior to completion of replacement, STP asked Bechtel to do an analysis of the system in the current and future corroded condition on the basis of statistical probability of the condition of the system based on analysis of samples of leaking and non-leaking joints. In addition, Bechtel was asked to analyze the system from an ASME Code standpoint and from a fracture mechanics standpoint. Finally, proof tests were conducted to determine the inherent margins.

2.2 Statistical Analysis

In order to obtain data for statistical analysis, 65 component ends were sectioned circumferentially and longitudinally. Longitudinal cross sections were used to confirm the observation that the worst dealloying areas were the socket weld crevices. Additional circumferential cross sections were used to determine the maximum amount of dealloying. This was accomplished by making circumferential cross sections of the crevice area and polishing until the greatest amount of dealloying was found. Typical circumferential and longitudinal cross sections are shown in Figures 2.1 and 2.2. A summary of the data obtained is contained in Table 2.1.

The data in Table 2.1 were used to perform a statistical analysis. The procedure used and results obtained are described in the following sections.

2.2.1 Classification of Samples

The circumferential cross section for each end of the sampled fitting was classified from observations as a leaker or a non-leaker. Thus, the extent of dealloying for the leaker ends sampled represents the condition of any valve or fitting socket that was currently found leaking on the ECW system. The extent of dealloying for the non-leaking ends sampled represents the extent of dealloying of the current ends after the leakers were removed.

The results of the samples, presented on Table 2.1, are also shown on Figure 2.3.

2.2.2 Confidence Level

It is necessary to insure that the sampled fittings adequately represent the whole population of fittings. Therefore, the degree of confidence has been estimated.

From the sample, a probability p of finding a certain fraction dealloyed in a socket end is determined. This probability is then used to estimate the probability P of finding a certain fraction dealloyed in the population. The standard error of proportion is determined using the following relation:

$$sp = \sqrt{\frac{p(1-p)}{n}} \sqrt{\frac{N-n}{N-1}} \quad (\text{equation 2-1})$$

where:

N is the population size,
 n is the sample size, and
 p is the probability of finding a certain fraction dealloyed.

The error of estimation E for a 95% confidence level is found by using:

$$E = 1.96 \cdot sp \quad (\text{equation 2-2})$$

Therefore, the probability P of finding a certain fraction dealloyed in the population of fittings is given by:

$$P = p \pm E \quad (\text{equation 2-3})$$

From Equation 2-1 it is seen that as either the sample size approaches the population size or the probability approaches zero, or one, the error band will approach zero. To assure a 95% confidence level for a 95% probability we will solve equation 2-1 such that $p + E = 0.05$. The proportion of non-leaking socket ends exceeding 59.08% dealloying is estimated to fall between 0% and 5% ($1.044\% + 3.956\%$) while the proportion of leaking socket ends exceeding 92.25% dealloying is estimated to fall between 0% and 5% ($1.243\% + 3.757\%$).

2.2.3 Sample Distribution

The data presented on Table 2.1 were used to generate Figure 2.4. In this figure, the percent of exceeding a certain fraction of the cross section being dealloyed is plotted for all samples taken. The leakers and non-leakers are plotted separately along with the combination of all samples. As shown on this figure, the leaking ends have a higher percent of the cross section dealloyed than the non-leakers. Thus, it can be deduced that replacement of the leaking socket ends will remove the number of fittings with high dealloying and the remaining population will be characterized by the non-leaking data.

2.2.4 Leakage as a Function of Dealloyed Cross Section

As shown above, the leaking socket ends have correspondingly more of the cross section dealloyed than the non-leaking socket ends. Therefore, an attempt to determine the fraction of leaking socket ends as a function of dealloyed cross-sectional area is made. For this purpose, the probability distribution function of socket ends as a function of dealloyed cross section area needs to be determined.

Some assumptions must be made concerning the possible shape of this probability distribution function. Originally, the socket ends had little or no dealloying, thus the distribution function was narrow near zero. As time went on and corrosion set in, more and more socket ends were being dealloyed. This process can take the shape of an exponential or Weibull distribution function. As more and more fittings are dealloyed, the median shifts towards higher values and the shape changes towards a normal or log-normal distribution. From the data obtained from the sample, it can be seen that the non-leaking socket ends can be characterized by a Weibull distribution, while the leaking socket ends approximate a normal distribution.

The above distribution functions were then used to determine the percentage of leaking socket ends that can be observed as a function of cross section dealloying as shown on Figure 2.5.

2.3 Stress Evaluation

To establish the margins existing in the original design a review of the stress analysis of the small bore ECW system was performed.

In addition to this review further calculations were performed to determine the margins that exist when the stresses are compared with the minimum properties of the dealloyed material as determined by testing.

2.3.1 Objectives

The specific objectives of this task were as follows:

- 1) to review the original design calculations and establish the original design margins.
- 2) to demonstrate existing margins for dealloyed fittings using ASME Section III methods and the minimum properties of dealloyed materials as established by tests.

2.3.2 Analysis Assumptions

The original design bases for the small bore Al-bronze piping are established through ASME Section III Subsections NC 3600. In this particular analysis method stress multipliers or stress intensification factors (SIF) are used to account for geometric discontinuities. All stresses in the original

design analysis are referenced to the section properties of the piping material. For purposes of the stress review, the results of the original analysis for equations 9 and 11 of ASME Section III were reviewed and compared to allowable design stresses.

For equation 9B, the primary stress equation due to pressure weight and Operating Basis Earthquake (OBE), the allowable stress is 21.6 ksi and for equation 11, the effect of pressure, weight, other sustained load and thermal expansion, the allowable stress is 45.0 ksi.

To evaluate the margins that exist between design loads and actual material properties tensile tests were performed on material that was up to 100 percent dealloyed. The average ultimate tensile strength for the 100 percent dealloyed material was 30 ksi.

In the evaluation of actual stresses that exist in these fittings a value for SIF has been applied to the crevice location. The values for SIF have been established from the Reference 2 and Reference 3. In all cases the larger value (conservative case) from either reference was used.

Finally for the stress evaluation, ASME III Appendix III was used to establish a value for S_M , a value of the quarter of the ultimate tensile strength of 100 percent dealloyed material (7.5 ksi) was used.

The ASME Code equations with stress multipliers to account for geometry discontinuity due to dealloyed material are outlined below:

$$\text{EQ9: } C_p \frac{P_p D}{4t_f} + 0.75(C_m) \frac{M_b}{Z_f} \quad 9B < 1.2S_H$$

$$\text{EQ11: } C_p \frac{P_p D}{4t_f} + 0.75(C_m) \frac{M_a}{Z_f} \quad 9D < 2.4S_H$$

P_d : Design Pressure = 120 PSI

P_p : Peak Pressure = 40 PSI

t_f : Minimum Fitting Wall Thickness Per ANSI B16.11

Z_f : Minimum Section Modulus of Fitting = $R^2 T_F$

D : Outside Diameter of Fitting

C_p : Stress Multiplier for Pressure Stress (= 2.74) Per Reference 2

C_m : Stress Multiplier for Pressure Moment Stress (= 3.42) Using Greater Value From Reference 2 or Reference 3

S_H : $1/4$ (30.0 ksi) = 7.5 ksi per ASME Section III Appendix III

M_A : Resultant Moment Due to Weight

M_b : Resultant Moment Due to Earthquake and Occasional Loads

M_C : Range of Resultant Moments Due to Thermal Expansion

2.3.3 Analysis and Results

The original ASME Section III analysis was reviewed and stress values compared to allowable values for the original material. These results are shown in Figure 2.5. The stress ratios presented in the Figure 2.5 illustrate the fraction of the total allowable stress that exists in each fitting under the design conditions of sustained plus secondary loads.

It can be seen from these data that there are significant margins existing in the original design. The highest stress in the ECW small bore piping is about 77 percent of the code allowable stress. It can be seen from Figure 2.5 that in all cases these stress ratios show adequate stress margins.

An alternative design criteria was established with which to compare the calculation results of equations 9 and 11. In this case the allowable stress was based on the average ultimate tensile strength of 100 percent dealloyed material. This value is 30 ksi. Consistent with ASME Section III Appendix III, a value for S_H was established as one quarter of this value or 7.5 ksi. The stress allowables for equation 9, using ASME III Sections NC 3600 are 1.2 S_H or 9 ksi and for equation 11 the value is 18.75 ksi. Re-analyzing the system with this design basis gives the results shown in Table 2.4 and Figure 2.4. In this table and figure the calculated stress values have been compared to the average ultimate tensile strength as defined by tests. Again it may be seen from Table 2.4 and Figure 2.4 that in all cases significant margins exist between the sustained plus secondary loads and the available material tensile properties.

2.3.4 Conclusions

Based on the margins that exist in the original design condition, the reevaluation of stresses using fitting section properties and tensile properties from dealloyed material tests, all fittings are acceptable from the stress point of view. This is the case even when the worst case Stress Intensification Factors (SIF) values for fittings are used from the published literature. This result stems from the initial design margins illustrated in Figure 2.5, the effect of the increased section properties of the fitting (as compared to the pipe properties that were used in the original design analysis) and the low operating pressures at the ECW system.

2.4 Fracture Mechanics Integrity Analysis

2.4.1 Introduction

The ASME Code design rules for piping provide margins against failure for loading conditions encountered during normal service as well as postulated conditions such as seismic loads and abnormal events. In assessing the structural integrity of partially dealloyed aluminum bronze piping components, a conservative evaluation has been performed to assure that adequate margins still remain. This was accomplished by evaluating the condition where the dealloyed region is assumed to have lost its load carrying capacity and will behave like a crack-like flaw. Under these conditions, flaw evaluation procedures similar to Section XI of the ASME Code have been applied.

Unlike some carbon steels and low alloy steels, aluminum bronze is inherently ductile and tough. This stems from its crystal structure which is like that of Type 304 stainless steel. Thus, the fracture resistance of aluminum bronze is expected to be high and the affected fittings will be relatively insensitive to material flaws such as cracks.

2.4.2 Linear Elastic Fracture Mechanics

Although aluminum bronze is not expected to behave in a non-ductile manner, linear elastic fracture mechanics techniques (LEFM) were used to establish the load carrying capacity of partially dealloyed fittings when the dealloyed region is treated as a crack-like flaw. When LEFM principles are applied, the flaw tolerance of the component can be quantified in terms of applied stress, flaw size and shape, and the fracture toughness of the material. By defining any two of these parameters, the third parameter can be quantified by fracture mechanics relationships. Selection of conservative values for fracture toughness, and a conservative representation of the size and extent of dealloying as a flaw, will give a conservative determination of the structural capacity for a partially dealloyed fitting. In terms of LEFM, crack instability (or propagation) is predicted if the following condition is satisfied:

$$K_I \geq K_{Ic}$$

where K_I = applied stress intensity factor (a function of stress and flaw and part geometry)

and K_{Ic} = critical stress intensity factor (or fracture toughness)

K_{Ic} is a material property which can be determined through testing, like a yield strength in a tensile test. In this case, K_{Ic} data or any other toughness data (such as Charpy V-notch impact properties) for aluminum bronze are not readily available. However, based on test data of aluminum bronze welds in 10- and 30-inch diameter cooling lines given in Reference 4, it is estimated that K_{Ic} for aluminum bronze is in the 150 - 200 ksi $\sqrt{\text{in}}$ range. The cast product form has somewhat lower toughness. It is conservatively estimated that the lower bound toughness is 65 ksi $\sqrt{\text{in}}$, based on discussions with several sources.

K_I can be expressed, in simplified terms, as follows:

$$K_I = \sigma F \sqrt{\pi a}$$

where σ = nominal stress

a = crack size

F = functional relationship that accounts for flaw shape, body geometry and type of loading.

The relationship between critical bending stress and dealloyed area was determined for the case of two limiting conditions: a complete 360 degrees circumferential dealloyed region originating from the inside surface, and a through-wall dealloyed region extending part way around the circumference. In directly applying LEFM to these conditions, the dealloyed regions were conservatively modeled as flaws, debonded and without any load carrying capacity. The methods contained in Reference 5 and 6 were used to establish the stress intensity factors for these flaw geometries. The capacity of the remaining uncracked section for the two limiting cases is shown in Figure 2.1 as a function of the extent of dealloying (cracked cross-section) and two lower bound estimates of fracture toughness. Even for the lowest value of K_{Ic} assumed (i.e. 65 ksi $\sqrt{\text{in}}$), significant load-carrying capacity remains for through-wall flaws exceeding 50% of the circumference or 4.6 inches in surface flaw length.

For the summary stresses given in Table 2.3, the computed through-wall flaw lengths that can be tolerated in the system are as follows:

Nominal Pipe Size (inch)	Socket		Tolerable Size	
	Diam.	Circumference	Percent	Degrees
1	1.75	5.50	>65	>234
2	2.75	8.64	59	212

It is reasonable to assume, given the conservative nature of the LEFM evaluation assumptions, that non-ductile failure of partially dealloyed material is not an issue of concern. It is therefore concluded that adequate toughness exists to prevent fracture of ECW system fittings and plastic collapse is the governing failure mode.

2.4.3 Limit Load Analysis

Because sufficient fracture resistance exists in partially dealloyed fittings to allow for utilization of the inherent tensile strength margins in the ECW system design, the structural integrity for a net-section plastic collapse failure mode was evaluated. The two previous limiting cases of part-through and through-wall partially dealloying were again analyzed by assuming no load carrying capacity of fully-dealloyed regions. The bending stress for net-section plastic collapse was established from Reference 7. Reference 7 provides the technical basis for the flaw evaluation procedures of Paragraph IWB-3640 and Appendix C for austenitic piping given in Section XI of the ASME Code.

For a material flow stress defined as the average of the specified minimum yield strength and ultimate tensile strength for the lowest strength alloy, the tolerable levels of part-through dealloying uniformly distributed around the circumference are shown in Figure 2.2. Ample bending capacity is

observed up to dealloy depths in excess of 80 percent even when the residual strength of 100 percent dealloyed material has been neglected. When the strength of dealloyed material is used, the bending load capacity of the fitting is computed to be approximately five times the worst case design loads. This is shown by the horizontal line in Figure 2.2.

The through-wall dealloyed model, as shown in Figure 2.3, gives a lower prediction of bending stresses to cause plastic collapse than the 360 degree part-through model; however, significant margins are still calculated for through-wall dealloying extending 180 degree around the circumference. Again, because the strength of the fully dealloyed material is significant, the available bending load capacity will be greater than these conservative calculations and will not fall below the case of the fully dealloyed condition (See again Figure 2.3).

2.4.4 Summary

Based on LEFM analysis under the conservative assumption that dealloyed regions are debonded and will behave as cracks, very large amounts of dealloying can be tolerated in small bore fittings without a concern for non-ductile failure. Similarly, on a plastic collapse basis there is adequate strength even in the fully dealloyed condition to support the intended design loads with sufficient safety margins. It is reasonable to conclude that, based on the above analyses, the components will have significant integrity and margin against failure, for the design loading conditions.

2.5 Proof Tests

A leaking coupling, a leaking tee and a non-leaking elbow were selected for tests to failure. Steel plates were welded onto the open ends and then they were subjected to increasing water pressure. The two leakers failed by leaking faster than the pump (200 cubic cm/minute) could keep up with it rather than by breaking. The non-leaker failed by the end plate blowing off. The pressure to cause failure was as follows:

<u>Item</u>	<u>Condition</u>	<u>Percent of Cross Section Dealloyed at Area of Maximum Attack Area (percent)</u>	<u>Failure Pressure (psi)</u>
Coupling	Leaker	38	8950
Tee	Leaker	52	5900
Elbow	Non-Leaker	0	6500

The failure of the tee was at the weld we made to seal the casting. The welder noticed the casting material was difficult to weld (presumably because it was dealloyed at that point) and indicated he felt it would fail at that

closure. Therefore, we feel the coupling failure where the closure welds were made on wrought pipe is most representative of the pressure carrying capacity of the leaking dealloyed Al-bronze. For a pressure of 8950 psi in the 3.03 diameter coupling, the stress in the 0.255 inch wall to cause failure is 49.54 ksi. This is three times the design stress of 15.7 ksi. A conservative reference burst pressure was calculated by the following equation from Reference 8:

$$P_B = \sigma_u \sqrt{F_{cy1} \ln W}$$

The calculated burst pressure was 6800 psi. Therefore, the "proof" strength of the coupling exceeded the reference burst strength of a sound casting.

2.6 Dealloying Rate Studies

The dealloying rates reported by Upton in reference 9 are as follows:

<u>Heat Treatment</u>	<u>Twelve month tests Maximum Corrosion Rate (mpy)</u>
Water quenched	0.02 - general 0.03 in crevices
As-received bar stock	0.03 general 0.15 in crevices
Furnace cooled	2.0 mpy

Ferrara and Caton report in reference 10 a maximum dealloying rate of 30 mpy after one year and 22.5 mpy after two years. Both Upton's and Ferrara's results are lower than the 44 mpy average and 83 mpy maximum estimated at STP. The maximum rates are based on the assumption that dealloying occurred in 3 years to 100 percent of the wall and the average rate assumes 50 percent. The STP socket data are plotted in Figure 2.6 based on the commonly used expression for corrosion rate:

$$V = K_1 t^{-K_2}$$

where V = corrosion rate in mpy

$K_2 = 1/2$

K_1 experimentally determined = 1.36×10^4 for
STP sockets

t = time in hours

The data from Ferrara and Caton and from Upton were used to validate the form of the equation.

REFERENCES

- 1) ASME Boiler and Pressure Vessel Code Section III 1974 with Winter, 1975 Addenda
- 2) "Stress indices for girth welded joints, including radial weld shrinkage, mismatch and tapered-wall transitions". NUREG/CR-371 (ORNL/SUB-2913) by E. C. Rodabaugh and S. E. Moore.
- 3) "Stress indices for ANSI Standard B16.11 socket-welding fittings". ORNL-TM-4929 by E. C. Rodabaugh and S. E. Moore.
- 4) "Structural Integrity Analysis for Essential Cooling Water Lines", July 1983 by G. R. Egan and S. R. Paterson.
- 5) "Elastic-Plastic Fracture Analysis of Through-wall and Surface Flaws in Cylinder" EPRI Report NO-5596 January 1988 by V. Kumar and M. D. German.
- 6) "Evaluation of Flaws in Carbon Steel Piping", EPRI RP 1757-65, Draft Final Report, March 1988.
- 7) "Evaluation of Flaws in Austenitic Steel Piping", EPRI Report NP-4690-SR (April 1986)
- 8) C. P. Royer and S. T. Rolfe, Effect of Strain-Hardening Exponent and Strain Concentrations on the Bursting Behavior of Pressure Vessels, ASME Paper 74-MAT-1 (1974).
- 9) B. Upton, Corrosion (June 1963) 204t.
- 10) R.J. Ferrara and T.F. Caton, Materials Performance (February 1982)

Table 2.1

Statistical Sampling of ECW System Fittings

<u>Valves</u>	Percent of Cross-Section Area Lost to Dealloying	
	<u>Leakers</u>	<u>Non-Leakers</u>
EW102	A	43
	B	47
EW103	A	24
	B	0
EW104	A	54
	B	10
EW105	A	30
	B	10
EW335	A	14
	B	37
EW337	A	59
	B	21
EW338	A	10
	B	22
EW369	A	24
	B	3
EW116	A	9
	B	6
EW126	A	52
	B	82
EW415	A	8
	B	29
EW323	A	54
	B	13
EW235	A	46
	B	12
EW031	A	35
	B	37
EW332	A	5
	B	17
EW214	A	88
	B	20
EW115	A	59
	B	38
EW017	A	67
	B	18
EW114	A	0
	B	0
EW351	A	1
	B	11
EW215	A	68
	B	3
A8	A	0
	B	0
DA5	A	80
	B	19

Table 2.1 (continued)

Statistical Sampling of ECW System Socket Ends

<u>Valves (continued)</u>		Percent of Cross-Section Area Lost to Dealloying	
		<u>Leakers</u>	<u>Non-Leakers</u>
102	A		19
	B		36
MA13	A	57	
	B	44	
A2	A	62	
	B		64
L0582	A		29
	B		28
<hr/>			
<u>Tees</u>			
T337	A		0
	B		0
	C		0
T338	A		47
	B		37
	C		32
Burst	A		52
Test	B		38
	C		48
<hr/>			
<u>Couplings</u>			
C-6	A	38	
MA.2	A	50	
<hr/>			
Total Sampled		24	41
Mean Percent Dealloyed		48.79	19.39
Standard Deviation		21.02	17.39

Table 2.2

Design and Operational Data for the Aluminum
Bronze Cooling Water Piping

(1) Materials:	Pipe and Couplings	CA61400 (SB 169 or 150)
	Valve bodies	CA95200 (BA 148 or 271)
(2) Pipe size:	2-inch NPS and smaller, Schedule 40	
(3) Temperatures:	150°F maximum design; 160°F operating	
(4) Pressure:	120 psi maximum design; 41 psi operating	
(5) Fluid:	Brackish Water	
(6) Design Code:	ASME Section III, Class 3	

TABLE 2 3

SUMMARY OF FITTING DIMENSIONS AND HIGHEST STRESS LEVELS

NOMINAL FITTING SIZE (IN)	DESIGN PRESSURE (PSIG)	OPERATING PRESSURE (PSIG)	DIMENSIONS		FITTING STRESSES* (ksi)		
			Do (IN)	t (IN)	Pm	Pb	Pe
1/2	120	40	1.223	0.184	0.20	0.72	--
1	120	40	1.778	0.224	0.24	4.27	1.16
1-1/2	120	40	2.415	0.250	0.29	1.96	2.11
2	120	40	2.952	0.273	0.32	4.26	1.81

*NOTE: Fitting stresses listed are the highest (worst case) stresses calculated without distinction among service level (i.e., normal, upset, emergency or faulted). The stresses are summarized in categories of primary membrane (Pm), primary bending (Pb), and thermal expansion (Pe) with SIFs removed (i.e. unconcentrated) to be consistent with evaluation definitions of IWB-3640 and proposed IWB-3650.

TABLE 2.4

STRESS EVALUATION

FITTING SIZES	TOTAL NUMBER OF FITTINGS	TOTAL NUMBER OF FITTINGS	STRESS RATIO: MAX STRESS 30 KSI	
		MEET ALLOWABLES **		
1/2"	13 *	13 *	EQ.9	.074
			EQ.11	.039
1"	56	56	EQ.9	.289
			EQ.11	.192
1-1/2"	60	60	EQ.9	.181
			EQ.11	.283
2"	154	154	EQ.9	.326
			EQ.11	.276
TOTAL	283	283		

NOTES:

- * ONE OF THESE FITTINGS IS 1/4"
- ** $S_H - 1/4$ (30 KSI)
- EQUATION 9 ALLOWABLE IS $1.2 S_H$
- EQUATION 11 ALLOWABLE IS $(S_A + S_H)$
 $S_A = (1.25 S_C + 0.25 S_H)$
- TOTAL NUMBER OF FITTINGS ABOVE REPRESENTS STRESS DATA POINTS EXCLUDING THOSE FITTINGS AND VALVES REPLACED AND/OR DELETED

Figure 2.1 Bending Stress Capacity for Dealloyed 2 - inch Fittings Based on LEFM




Figure 2.2 Conditions for Net-Section Plastic Collapse for 360 Degree Part-Through Dealloying




Figure 2.3 Conditions for Net-Section Plastic Collapse for Through-Wall Dealloying




FIGURE 2.4

SOUTH TEXAS PROJECT - UNIT 1 ALUMINUM BRONZE FITTING STRESS RATIO TO ALLOWABLE





FIGURE 2.5

STP UNIT 1 ALUMINUM/BRONZE ECWS
 DISTRIBUTION OF SAMPLED FITTINGS



DEALLOYING OF LEAKING
ALUMINUM BRONZE SOCKETS

Figure 2.6

