

7590-01

UNITED STATES NUCLEAR REGULATORY COMMISSION

BOSTON EDISON COMPANY

PILGRIM NUCLEAR POWER STATION

DOCKET NO. 50-293

NOTICE OF ISSUANCE OF INTERIM DIRECTOR'S DECISION

Notice is hereby given that the Director, Office of Nuclear Reactor Regulation, has issued a "Second Interim Director's Decision" concerning a request filed pursuant to 10 CFR 2.206 by Massachusetts Governor Michael S. Dukakis and Attorney General James M. Shannon which requested that the Director of the Office of Nuclear Reactor Regulation (NRR) institute a proceeding to modify, suspend, or revoke the operating license held by Boston Edison Company (BECO, the licensee) for its Pilgrim Nuclear Power Station (Pilgrim).

On May 27, 1988, the Director of the Office of Nuclear Reactor Regulation issued an "Interim Director's Decision under 10 CFR 2.206" concluding that a portion of the request concerning the need for a probabilistic risk assessment was denied. The portion of the petition covering management and emergency preparedness would be addressed in a subsequent response.

The second response culminated in a "Second Interim Decision under 10 CFR 2.206" concerning numerous deficiencies in licensee management and for reasons explained in the Decision, that portion of the petition has been denied. A decision regarding emergency preparedness will be addressed in a final

BB10120046 891006
PDR ADDOCK 0500C293
G PNU

decision. A copy of the "Second Interim Decision under 10 CFR 2.206," DD-88-17 is available for public inspection in the Commission's Public Document Room, located in the Gelman Building, Lower-Level, 2120 L. Street, N.W., Washington, D.C. and at the Local Public Document Room at the Plymouth Public Library, 11 North Street, Plymouth, Massachusetts 02360.

A copy of the Decision will be filed with the Secretary for the Commission's review in accordance with 10 CFR 2.206(c). As provided in this regulation, the Decision will constitute the final action of the Commission, 25 days after issuance, unless the Commission, on its own motion institutes review of the Decision within that time period.

Dated at Rockville, Maryland, this 6th day of October 1988.

FOR THE NUCLEAR REGULATORY COMMISSION

R. H. Wessman

Richard H. Wessman, Director
Project Directorate 1-3
Division of Reactor Projects 1/II

OFC	: PDI-3	: PDI-3	: OGC	: PDI-3	:	:	:
NAME	: MRashbrook	: PMDonald:ck	: L. Chandler	: RWessman	:	:	:
DATE	: 9/15/88	: 12/8/88	: 9/30/88	: 9/27/88	:	:	:


OFFICIAL RECORD COPY

decision. A copy of the "Second Interim Decision under 10 CFR 2.206," DD-88-17 is available for public inspection in the Commission's Public Document Room, located in the Gelman Building, Lower-Level, 2120 L. Street, N.W., Washington, D.C. and at the Local Public Document Room at the Plymouth Public Library, 11 North Street, Plymouth, Massachusetts 02360.

A copy of the Decision will be filed with the Secretary for the Commission's review in accordance with 10 CFR 2.206(c). As provided in this regulation, the Decision will constitute the final action of the Commission, 25 days after issuance, unless the Commission, on its own motion institutes review of the Decision within that time period.

Dated at Rockville, Maryland, this 6th day of October 1988.

FOR THE NUCLEAR REGULATORY COMMISSION



Richard H. Wessman, Director
Project Directorate I-3
Division of Reactor Projects I/II



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406

D. McDaniel
NRR
1401

JUL 27 1988

Docket No. 50-293

Boston Edison Company
ATTN: Mr. Ralph G. Bird
Senior Vice President - Nuclear
Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, Massachusetts 02360

Gentlemen:

Subject: Systematic Assessment of Licensee Performance (SALP)
Board Report No. 50-293/87-99

Enclosed for your review, prior to our scheduled meeting of August 25, 1988, is the SALP Board Report for Pilgrim Nuclear Power Station covering the period February 1, 1987 through May 15, 1988.

In accordance with NRC policy, I have reviewed the SALP Board Report and concur with the assigned ratings. Highlights of the report are set forth below:

1. Category 1 performance rating was assigned to Engineering and Technical Support which continued strong performance through the assessment period.
2. Category 2 ratings were given in the functional areas of Surveillance, Fire Protection, Security and Safeguards and Assurance of Quality acknowledging Boston Edison Company's extensive efforts to upgrade performance from the previously assigned Category 3 ratings.
3. Category 3 Improving rating was assigned to the Radiological Controls functional area.

The assignment of the Category 3 improving rating indicates that improvement in the organization, programs and performance were noted in the Radiological Controls functional area. However, in our view, the results of these initiatives were coming to fruition at the close of the assessment period, and had not yet demonstrated the ability to sustain improved performance.

Additionally, on July 8, 1988, Region I advised you that Pilgrim remains categorized by NRC Senior Management as a plant that requires continued close monitoring and demonstration of programs which establish and implement performance improvements. This was done in conjunction with a letter from the NRC's Executive Director for Operations to your Chief Executive Officer. We recognize the progress demonstrated to date as a result of your extensive efforts, however, continued vigilance on your part is necessary to achieve and sustain overall results. NRC will also continue its increased attention to your facility. In this regard, we will conduct an assessment team inspection to further measure the effectiveness and readiness of your management controls, programs and personnel to support safe restart of the facility. Further, I plan to shorten the current SALP assessment period to permit an additional opportunity to measure the results of your programs.

~~2808164305~~ 3PP

At the SALP management meeting, please be prepared to discuss your evaluation of our assessment and the status of your performance improvement programs. Additionally, we solicit written comments within 30 days after the meeting to enable us to thoroughly evaluate your response and to provide you with our conclusions relative to them. Specifically, you are requested to respond addressing actions planned to continue to improve performance in the Radiological Controls area.

Your cooperation with us is appreciated. Should you have any questions concerning the SALP report, we would be pleased to discuss them with you.

Sincerely,



William T. Russell
Regional Administrator

Enclosure:
As stated

cc w/encl:

K. Highfill, Station Director
R. Anderson, Plant Manager
J. Keyes, Licensing Division Manager
E. Robinson, Nuclear Information Manager
R. Swanson, Nuclear Engineering Department Manager
The Honorable Edward J. Markey
The Honorable Edward P. Kirby
The Honorable Peter V. Forman
B. McIntyre, Chairman, Department of Public Utilities
Chairman, Plymouth Board of Selectmen
Chairman, Duxbury Board of Selectmen
Plymouth Civil Defense Director
P. Agnes, Assistant Secretary of Public Safety, Commonwealth of
Massachusetts
S. Pollard, Massachusetts Secretary of Energy Resources
R. Shimshak, MASSPIRG
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Massachusetts (2)
Chairman Zech
Commissioner Roberts
Commissioner Carr
Commissioner Rogers
K. Abraham, RI (18 copies)

JUL 27 1988

bcc w/encl:

Region I Docket Room (with concurrences)

M. Perkins, RI (w/o encl)

W. Russell, RI

J. Allan, RI

D. Holody, RI

W. Kane, RI

S. Collins, RI

J. Wiggins, RI

R. Blough, RI

L. Doerflein, RI

M. Kohl, RI

W. Johnston, RI

J. Durr, RI

R. Gallo, RI

W. Oliveira, RI

S. Ebnetter, RI

G. Sjoblom, RI

R. Bellamy, RI

R. Bores, RI

J. Taylor, DEDO

B. Boger, NRR

R. Wessman, NRR

D. McDonald, NRR

F. Akstulewicz, NRR

Board Members

ENCLOSURE
SALP BOARD REPORT

U. S. NUCLEAR REGULATORY COMMISSION
REGION I

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE
INSPECTION REPORT 50-293/87-99
BOSTON EDISON COMPANY
PILGRIM NUCLEAR POWER STATION
ASSESSMENT PERIOD: FEBRUARY 1, 1987 - MAY 15, 1988
BOARD MEETING DATE: JULY 5 and 6, 1988

TABLE OF CONTENTS

	<u>Page</u>
1.0 INTRODUCTION	1
1.1 Purpose and Overview	1
1.2 SALP Board Members	1
1.3 Background	2
2.0 CRITERIA	7
3.0 SUMMARY OF RESULTS	10
3.1 Overall Facility Evaluation	10
3.2 Facility Performance	12
4.0 PERFORMANCE ANALYSIS	13
4.1 Plant Operations	13
4.2 Radiological Controls	18
4.3 Maintenance and Modifications	24
4.4 Surveillance	29
4.5 Fire Protection	33
4.6 Emergency Preparedness	36
4.7 Security and Safeguards	38
4.8 Engineering and Technical Support	43
4.9 Licensing Activities	47
4.10 Training and Qualification Effectiveness	50
4.11 Assurance of Quality	53
5.0 SUPPORTING DATA AND SUMMARIES	57
5.1 Investigation and Allegations Review	57
5.2 Escalated Enforcement Actions	57
5.3 Management Conferences	58
5.4 Licensing Actions	59
5.5 Licensee Event Reports	63

TABLES

- Table 1 - Tabular Listing of Licensee Event Reports by Functional Areas
- Table 2 - Inspection Hours Summary
- Table 3 - Enforcement Summary
- Table 4 - Pilgrim SALP History Tabulation
- Table 5 - Management Meeting and Plant Tour Summary

1.0 INTRODUCTION

1.1 Purpose and Overview

The Systematic Assessment of Licensee Performance (SALP) is an integrated NRC staff effort to collect observations and data on a periodic basis and to evaluate licensee performance. The SALP process is supplemental to the normal regulatory processes used to ensure compliance to NRC rules and regulations. It is intended to be sufficiently diagnostic to provide a rational basis for allocating NRC resources and to provide meaningful guidance to licensee management in order to improve the quality and safety of plant operations.

An NRC SALP Board, composed of the Staff members listed in Section 1.2 below, met on July 5 and 6, 1988 to review the collection of performance observations and data in order to assess the Boston Edison Company's (BECO) performance at the Pilgrim Nuclear Power Station. This assessment was conducted in accordance with the guidance in NRC Manual Chapter 0516, "Systematic Assessment of Licensee Performance". A summary of the guidance and evaluation criteria is provided in Section 2.0 of this report.

This report is the SALP Board's assessment of the licensee's safety performance at the Pilgrim Nuclear Power Station for the period February 1, 1987 - May 15, 1988. The summary findings and totals reflect a 15 month assessment period.

1.2 SALP Board Members

Chairman

S. J. Collins, Deputy Director, Division of Reactor Projects (DRP)

Members

W. F. Kane, Director, DRP

J. T. Wiggins, Chief, Reactor Projects Branch 3, DRP

A. R. Blough, Chief, Reactor Projects Section 3B, DRP

J. P. Durr, Chief, Engineering Branch, Division of Reactor Safety (DRS)

G. L. Sjoblom, Acting Director, Division of Radiation Safety and Safeguards (DRSS)

R. R. Bellamy, Chief, Facilities Radiological Safety and Safeguards Branch, DRSS

D. H. Wessman, Director, Project Directorate I-3, Office of Nuclear Reactor Regulation (NRR)

D. G. McDonald, Licensing Project Manager, NRR

C. C. Warren, Senior Resident Inspector, Pilgrim Nuclear Power Station (PNPS), DRP

Other Attendees

J. J. Lyash, Resident Inspector, Pilgrim NPS, DRP
T. K. Kim, Resident Inspector, Pilgrim NPS, DRP
T. F. Dragoun, Senior Radiation Specialist, DRSS
G. C. Smith, Safeguards Specialist, DRSS
R. M. Gallo, Chief, Operations Branch, DRS
A. G. Krasopoulos, Reactor Engineer, DRS
T. Koshy, Reactor Engineer, DRS

1.3 BackgroundA. Licensee Activities

The plant has been shut down since April 12, 1986 for maintenance and to make program improvements and remained shut down throughout this assessment period. The reactor was defueled on February 13, 1987, to facilitate extensive maintenance and modification of plant equipment. The licensee completed fuel reload on October 14, 1987. The reactor vessel hydrostatic test and the containment integrated leak rate test were also completed successfully.

Since the end of the last SALP period there have continued to be extensive management changes at Boston Edison that affect Pilgrim. The licensee has aggressively recruited experienced personnel from outside sources. A new Senior Vice President assumed responsibility for the nuclear organization at the beginning of the period. The licensee's organizational structure was also significantly altered several times. Recent changes have more clearly defined the permanent onsite organizational structure. Essentially all key management positions had been filled with permanent employees by the close of the period.

The licensee developed several integrated action and testing plans to evaluate the readiness of plant management, staff and hardware to support restart. These include the Restart Plan, Material Condition Improvement Action Plan, Radiological Action Plan and Power Ascension Test Program. In addition, the licensee performed a self assessment near the end of the SALP period to identify plant issues and evaluate the effectiveness of implemented improvement actions.

During the assessment period the licensee completed extensive plant hardware and procedure modifications. The licensee's Safety Enhancement Program included addition of a third emergency diesel generator, containment spray header nozzle changes, installation of a backup nitrogen supply system, and additional protection features for anticipated transient without scram. Steps were also taken toward installation of a direct torus vent system and installation of a diesel driven fire pump tied to the residual heat removal system. License exemptions and modifications to the fire protection program and equipment to bring the plant into full compliance with 10 CFR 50 Appendix R, and to improve reactor level instrumentation were completed. The facility Emergency Operating Procedures were also upgraded to incorporate Revision 4 of the Boiling Water Reactor Owners Group Emergency Procedures Guidelines.

On March 31, 1987, the station experienced a loss of offsite power during a storm when a static line broke and fell onto the conductors at a location several miles from the site. Offsite power was restored within 45 minutes. A second loss of offsite power event occurred on November 12, 1987 due to excessive ice and snow accumulation on the transmission system during a severe winter storm. This event was complicated by a lockout of the plant startup transformer, the removal of one of the emergency diesel generators from service due to maintenance concerns and the limited availability of instrument air. A source of offsite power was reestablished about 21 hours after the initial loss. An NRC Augmented Inspection Team was dispatched to the site in response to this event.

On November 9, 1987, the licensee as a conservative measure halted ongoing maintenance and modification work at the station after determining that several incidents which occurred during the weekend of November 7 and 8, 1987, raised concerns regarding the control of ongoing work activities. The licensee's Senior Vice President-Nuclear directed that ongoing maintenance and modification work onsite be suspended, and contractor craft personnel were instructed to leave the site and were directed not to report for work until November 12, 1987. The licensee subsequently formed eight teams of engineering and management personnel to perform detailed evaluations of each incident prior to resuming station work activities.

On February 11, 1988, the control room received a report of a fire in a contaminated area of the machine shop. The licensee conservatively declared an Unusual Event. The fire was confined to a small area and was identified as burning insulation from a heat-treating machine which was being used in the machine shop. The fire was extinguished by the plant fire brigade with no plant damage noted, and the Unusual Event was secured.

Operator licensing examinations were conducted on two occasions during the period. A total of two senior reactor operators and 14 reactor operator candidates were examined with all candidates successfully completing the examinations.

In December 1986, the Secretary of Public Safety for the Commonwealth of Massachusetts (Charles V. Barry) submitted a report to Governor Dukakis assessing the status of offsite emergency preparedness for the Pilgrim station. The report identified several problems with the existing response program. FEMA performed a self-initiated review of the Pilgrim emergency response plan and on August 5, 1987, provided its report to the Commonwealth. FEMA identified six deficient areas and withdrew its interim finding that Massachusetts offsite emergency planning and preparedness were adequate to protect the public health and safety in the event of an accident at Pilgrim. The NRC requested the licensee to provide its plans and schedule for working with state and local organizations to resolve the deficiencies. The licensee submitted an action plan to address the deficiencies on September 17, 1987. A progress report issued October 15, 1987 by Charles V. Barry notes that, while substantial progress had been made in some areas, adequate plans for response to an accident at Pilgrim did not exist and substantial work remained to be done. At the close of the assessment period, the licensee was actively working with the Commonwealth and local agencies to address the deficiencies and upgrade the emergency plans.

B. Inspection Activities

Confirmatory Action Letter (CAL) 86-10 was issued in April, 1986 in response to a series of operational events. The CAL initially required that the licensee address these events, and was subsequently extended in August, 1986 to include resolution of programmatic and management concerns. In addition the CAL stated that the NRC Regional Administrator's approval would be required prior to restart. The CAL remained in effect throughout this assessment period.

Considerable inspection resources were expended at Pilgrim during this assessment period. The resident staff has been maintained at three inspectors. During the fifteen month assessment period, over 9698 hours of direct NRC inspection were performed (7758 hours on an annual basis). This represents a 43 percent increase above the previous assessment period, and is significantly in excess of that normally allocated to a single unit site. A detailed breakdown of the total inspection hours into SALP functional areas is included in Table 2.

Senior NRC management involvement was substantial during the period. Early in the assessment period, a Pilgrim Restart Assessment Panel was formed which consists of senior management from the NRC Office of Nuclear Reactor Regulation (NRR) and Region I. The panel generally meets biweekly to coordinate the planning and execution of NRC activities, and to assess the results of these activities to provide an independent judgement of the plants readiness for operation. A series of management meetings to discuss the licensee's progress and proposed programs were also held. Frequent site tours by NRC Commissioners, the Director of Nuclear Reactor Regulation and the Regional Administrator were conducted. NRC senior management participated in numerous public meetings and interacted extensively with local, state and federal officials. The NRC conducted public meetings in Plymouth to receive public comments on the plan. The staff's assessment of the comments and concerns received on the Restart Plan was presented to the public during a followup public meeting. A chronological listing of management meetings and tours is included as Table 5.

On July 15, 1986, Massachusetts State Senator William B. Golden and others filed a 10 CFR 2.206 petition regarding Pilgrim. After review by the NRC, the contentions raised in the petition regarding containment deficiencies and inadequacies in the radiological emergency response plan were denied. A decision regarding the management deficiencies was deferred to a subsequent response. This information was transmitted to the petitioners by letter dated August 21, 1987. Three of the petitioners filed an appeal in federal court on October 1, 1987.

On October 15, 1987, Massachusetts Attorney General James M. Shannon filed a 10 CFR 2.206 petition, on behalf of his office and Governor Michael S. Dukakis, requesting an order to show cause why Pilgrim should not remain shutdown until a full adjudicatory hearing resolves the issues raised in the petition. The petition cites evidence of continuing managerial, Mark I containment, and emergency planning deficiencies and requests that the licensee also be required to perform a probabilistic risk assessment (PRA). In a response dated May 27, 1988, the NRC denied the petitioners request that a PRA regarding the Mark I containment be required and deferred decisions regarding emergency planning and management issues.

During the assessment period nine NRC team inspections were conducted:

1. Appendix R Fire Protection Program Review
2. Plant Modification Program Review
3. Plant Effluent and Environmental Monitoring Program Review
4. Augmented Inspection Team (AIT) Review of the loss of off-site power event on November 12, 1987
5. Annual Emergency Plan Exercise Observation
6. Onsite Electrical Distribution Adequacy Review
7. Emergency Operating Procedures Review
8. Maintenance Program Review
9. In-plant Radiological Controls Review

An NRC Order issued in 1984 requiring the licensee to implement a Radiation Improvement Program was closed during the period based on the results of a special inspection and other program inspections which indicated that all terms of the Order had been satisfactorily completed. Two operator licensing examinations were also conducted. An enforcement conference was held on September 9, 1987 to discuss security related matters. Enforcement action on these issues is still pending.

Tabulations of inspection activities and associated enforcement actions are contained in Tables 2 and 3.

2.0 CRITERIA

Licensee performance is assessed in selected functional areas, depending upon whether the facility is in a construction, preoperational, or operating phase. Functional areas normally represent areas significant to nuclear safety and the environment. Some functional areas may not be assessed because of little or no licensee activities, or lack of meaningful observations. Special areas may be added to highlight significant observations.

This report also discusses "Training and Qualification Effectiveness", "Assurance of Quality" and "Engineering and Technical Support" as separate functional areas. Although these topics, in themselves, are assessed in the other functional areas through their use as criteria, the three areas provide a synopsis. For example, assurance of quality effectiveness has been assessed on a day-to-day basis by resident inspectors and is an integral aspect of specialist inspections. Major factors that influence quality, such as involvement of first line supervision, safety committees, quality assurance, and worker attitudes, are discussed in each area.

One or more of the following evaluation criteria were used to assess each functional area.

1. Management involvement and control in assuring quality
2. Approach to the resolution of technical issues from a safety standpoint
3. Responsiveness to NRC initiatives
4. Enforcement history
5. Operational events (including response to, analyses of, and corrective actions for)
6. Staffing (including management)
7. Training and Qualification Effectiveness

Based upon the SALP Board assessment, each functional area evaluated is classified into one of three performance categories. The definitions of these performance categories are:

Category 1. Licensee management attention and involvement are readily evident and place emphasis on superior performance of nuclear safety or safeguards activities, with the resulting performance substantially exceeding regulatory requirements. Licensee resources are ample and effectively used so that a high level of plant and personnel performance is being achieved. Reduced NRC attention may be appropriate.

Category 2. Licensee management attention to and involvement in the performance of nuclear safety or safeguards activities are good. The licensee has attained a level of performance above that needed to meet regulatory requirements. Licensee resources are adequate and reasonably allocated so that good plant and personnel performance is being achieved. NRC attention may be maintained at normal levels.

Category 3. Licensee management attention to and involvement in the performance of nuclear safety or safeguards activities are not sufficient. The licensee's performance does not significantly exceed that needed to meet minimal regulatory requirements. Licensee resources appear to be strained or not effectively used. NRC attention should be increased above normal levels.

The SALP Board also assesses a functional area to compare the licensee's performance during the last quarter of the assessment period to that during the entire period in order to determine the recent trend for each functional area. The SALP trend categories are as follows:

Improving: Licensee performance was determined to be improving near the close of the assessment period.

Declining: Licensee performance was determined to be declining near the close of the assessment period and the licensee had not taken meaningful steps to address this pattern.

A trend is assigned only when, in the opinion of the SALP Board, the trend is significant enough to be considered indicative of a likely change in the performance category in the near future. For example, a classification of "Category 2, Improving" indicates the clear potential for "Category 1" performance in the next SALP period.

It should be noted that Category 3 performance, the lowest Category, represents acceptable, although minimally adequate, safety performance. If at any time, the NRC concluded that a licensee was not achieving an adequate level of safety performance, it would then be incumbent upon NRC to promptly take appropriate action in the interest of public health and safety. Such matters would be dealt with independently from, and on a more urgent schedule than, the SALP process.

It should also be noted that the industry continues to be subject to rising performance expectations. For example, NRC expects licensees to actively use industry-wide and plant-specific operating experience to effect performance improvement. Thus, a licensee's safety performance would be expected to show improvement over the years in order to maintain consistent SALP ratings.

3.0 SUMMARY

3.1 Overall Facility Evaluation

The 1985 SALP determined that programmatic and performance weaknesses existed in several functional areas and that improvements were inhibited by the lack of resolution of factors which in turn depended heavily on management attitudes and aggressiveness of followup.

The 1986 SALP acknowledged that, although some improvements were made, the lack of a clear organizational structure, recurring management changes, and chronic staffing vacancies delayed the establishment of a stable licensee management team at the plant and inhibited progress during the period. These problems manifested themselves as Category 3 performance ratings in the Radiological Controls, Surveillance, Fire Protection, Security and Assurance of Quality functional areas.

Throughout this 1987-1988 SALP period the facility was maintained by BECO in an outage condition to make major plant facility modifications and complete a major equipment refurbishment program.

At the beginning of the assessment period the licensee made the most significant of numerous personnel changes when a new Senior Vice President-Nuclear was hired and his presence established on site. Additional personnel and organizational changes continued throughout the assessment period with the most substantial reorganization being completed in February, 1988. Although the organization in its present form did not formally emerge until late in the assessment period, many of the functional reporting chains have been in place for some time and appear to be functioning well. Allocated staffing levels in the new organization are significantly higher than in the past and the licensee has been generally successful in recruiting efforts. As a result of these transitions some individuals are relatively new to their positions and in some cases do not have extensive operating Boiling Water Reactor expertise.

The licensee has been aggressive in addressing most areas of known program weakness. However, implementation of certain program and organizational improvements was delayed due to the high priority placed on proceeding with outage work. Surveillance program responsibilities have been consolidated in the Systems Engineering Group and program weaknesses have been addressed. Hardware issues in both the fire protection and security areas have been corrected and performance in these areas has improved. Health Physics program problems identified in the previous SALP report continued to exist during the first half of this assessment period, however recent significant management attention and resource commitment to this area led to improved performance over the last part of the assessment period. Maintenance program improvements were implemented only

recently and their effectiveness remains under review. Licensee development of the Material Condition Improvement Action Plan, Restart Plan and performance of an extensive self assessment in response to the NRC August 1986 Confirmatory Action letter are evidence of the licensee's ability to self-identify and understand facility performance and material condition. The action plans to implement these necessary improvements and management's ability to effect lasting performance change remained under review at the close of the assessment period.

In summary, licensee efforts have been extensive including corporate and site reorganizations and a new management team which has undertaken numerous projects and programs to improve plant material condition and enhance programmatic performance. Management initiatives have been generally successful in correcting staffing, organization and material deficiencies. Programmatic performance improvements have been evident in areas of previously identified significant weakness and the licensee's self assessment process has identified areas where further management attention is warranted. In light of the past inability to implement lasting programs which result in long term improvements, a continued licensee management commitment is needed to confirm that past weakness have been identified and sustain the overall improving trend in performance.

3.2 Facility Performance

<u>Functional Area</u>	<u>Category Last Period*</u>	<u>Category This Period**</u>	<u>Recent Trend</u>
1. Plant Operations	2	2	
2. Radiological Controls	3	3	Improving
3. Maintenance and Modifications	2	2	
4. Surveillance	3	2	
5. Fire Protection	3	2	
6. Emergency Preparedness	2	2	Improving
7. Security and Safeguards	3	2	
8. Engineering and Technical Support	1	1	
9. Licensing Activities	2	2	
10. Training and Qualification Effectiveness	2	2	
11. Assurance of Quality	3	2	
Outage Management and Modifications Activities	1	***	

* November 1, 1985 to January 31, 1987

** February 1, 1987 to May 15, 1988

*** Not evaluated as a separate functional area; findings relative to outage activities are integrated into "Engineering and Technical Support", "Maintenance and Modifications", and other functional areas as appropriate

4.0 PERFORMANCE ANALYSIS

4.1 Plant Operations (2178 hours/22 percent)

(1) Analysis

This functional area is intended to assess the licensee's performance of plant operations. Throughout this assessment period the plant was in an extended maintenance and refueling outage. NRC observations of licensee performance during major plant activities included reactor core defuel and reload, the reactor vessel hydrostatic test, and the primary containment integrated leak rate test.

During the previous SALP period plant operations was assessed as a Category 2. Weaknesses identified included a shortage of licensed reactor operators and lack of professional support for the Operations Department. Although the licensee had taken actions to recruit new operators and improve the licensed operator training program, the shortage of licensed reactor operators (ROs) remained a significant problem. The effectiveness in professional staff support for the Operations Department was also not demonstrated due to delays in transferring personnel into the department, and their continuing collateral duties outside the department.

During the current assessment period, the licensee's planning and evaluation of their readiness for refueling, the reactor vessel hydrostatic test, and the primary containment integrated leak rate test were well managed. Strong Operations Department involvement was evident. Plant management and the Operations Review Committee (ORC) exhibited a conservative, safety conscious approach to these milestones. ORC review of refueling readiness was conducted in a thorough and deliberate manner including line item verification of the reload checklist. One exception was the licensee's use of Appendix G to the Final Safety Analysis Report to justify conditional operability of equipment needed for refueling. In this case plant management proposed to begin fuel movement with a Standby Gas Treatment System design deficiency uncorrected, by preparing an analysis supporting operability of the system under restricted conditions. Licensee management however, reconsidered this practice when concerns were raised by the NRC. Licensee senior management support for ORC decisions was visible throughout these major activities. Senior management's presence and direct involvement in activities also demonstrated their commitment to safety and expectations of high standards to the plant staff.

The licensee has taken aggressive actions to resolve the shortage of licensed operators. Improvements in recruiting and operator training programs have resulted in a significant increase in the size of the operations staff. The number of licensed reactor operators (ROs) increased by 14 during the period to the present total of 23. This contributed to a reduction in routine operator overtime, which had been a chronic past. The addition of new licenses to the operations staff is positive. However, additional operating experience will be required before these newly licensed personnel are fully qualified. The high RO attrition rate was a major factor in the RO shortage during the last assessment period. Increased management attention, reduced overtime, and higher morale have contributed to maintaining a stable operations organization during this period. The licensee currently maintains a staff of 20 equipment operators and eight of the 20 are scheduled to enter a reactor operator license training class later this year. Continued management support in maintaining a sound and aggressive recruiting and training program is required to prevent the recurrence of the operator shortage.

Despite the improvements in the staffing level, weaknesses continued to exist in attention to detail and in communications. Several procedural and personnel errors occurred during the refueling, the reactor vessel hydrostatic test, and the containment integrated leak rate test. Immediate actions taken by the operations staff in response to incidents were not always conservative. For example, operators continued refueling without stopping to assess a pendant light which was inadvertently dropped onto the reactor core. Problems in the operations area that contributed to the licensee's work stoppage on November 9, 1987 included inadequate system turnover, valve lineup problems, and poor radwaste system operation practices. Some weakness in coordination and communications between the operations staff and other groups was noted during the loss of offsite power (LOOP) event on November 11, 1987. The lack of clear management directions both in and out of the control room, a somewhat fragmented recovery effort, and poor communications may have delayed the full recovery from the LOOP and resulted in inadvertent manual shutdown of one of the emergency diesel generators. As a further example, operator communication during a dry run of the remote shutdown test was also informal and not completely effective.

During previous assessments, informality and poor attitude had been identified as a weakness among the control room staff. The discovery by the licensee of non-job related reading material and a card playing machine in the control room in October, 1987 was a further example of the lack of professionalism and implied inattentiveness to duty. As a result of management attention to this issue, positive trends in the control room atmosphere and conduct were noted during the last quarter of the assessment period. The significant increase in the size of the operations staff, strict control of operator overtime, and intensive communication training also aided licensee management's successful effort to improve operator professionalism. As an example, effective use of the simulator for training and implementation of control room hardware improvements have enhanced the control room atmosphere.

Significant effort has been made by the licensee to provide adequate support staff in the Operations Department. The department was reorganized and the Operations Support Group was created to strengthen effectiveness in identifying and resolving technical issues affecting Operations. The Operations Support Group consists of three staff engineers and six shift technical advisor (STA) positions. The licensee has filled the group manager and senior staff engineer positions and is actively recruiting to fill the other staff engineer positions. Three additional STAs were hired and trained during this period which increased the total number of qualified STAs to six. This represents an increase of six in the allocated operations support staff with four of the positions filled. The reorganization allowed the Chief Operating Engineer added opportunity to directly oversee operator performance. Operations staff involvement in developing and implementing the Emergency Operating Procedures was strong. The licensee's ongoing effort to develop a jumper and lifted lead log and a limiting condition of operation log are additional indications of improving staff support in the Operations Department.

The licensee's approach to problem investigation and root cause analysis improved significantly during the latter portion of the period. Event critiques led by the Operations Section Manager and root cause analyses performed by the onsite Systems Engineering Group were thorough and aggressive. The critique process also instilled a leadership role for the Operations Department and promoted better communication among interdepartmental groups.

The operator training program continued to improve during this assessment period. NRC operator license examinations on May 25, 1987 and December 7, 1987 had a 100 percent pass rate. Utilization of the plant specific simulator in requalification training and the new Emergency Operating Procedure training significantly enhanced the effectiveness of the training program. The licensee's effort to develop and implement the new Emergency Operating Procedures demonstrated high levels of senior management attention.

Reportable events were generally handled acceptably by the control room staff. The levels of detail, technical accuracy, and the overall quality of licensee event reports have improved during the period.

Monitoring and maintenance of plant chemistry is the responsibility of the Operations Department. The licensee's chemistry department is responsible for plant chemistry, radiochemistry, and the facility radiological effluents control program. The chemistry organization was clearly defined, adequately staffed, and appeared to interface well with other plant groups including the radwaste organization. Chemistry representatives are included in shiftly turnovers with the control room staff. Important plant chemistry parameters are discussed with station management daily at a morning planning meeting. Surveillance requirements were clearly established and performed on schedule. The licensee is meeting Technical Specification requirements for radiological effluent sampling and analysis. Effluent control instrumentation was maintained and calibrations performed in accordance with regulatory requirements. All release records were complete and well maintained. QA audits of this area were comprehensive and technically thorough.

The results comparison of NRC radioactivity standards submitted to the licensee for analyses indicated excellent performance by the licensee with all results in agreement. During the analysis of the NRC radioactivity standards, the licensee's chemistry staff demonstrated a clear understanding of the technical issues. In addition, the licensee was responsive to NRC suggested practices for program improvements. The licensee's chemical measurement capability was also evaluated twice during the assessment period. The results of the NRC chemical standards indicated good performance with only four of 54 measurements in disagreement. The licensee was responsive to NRC suggestions for program improvements in this area and also in the area of post accident sample analyses. Licensee management appears committed to providing adequate capital resources to the

Chemistry Department. The licensee possesses state of the art chemical and radiochemical laboratory instrumentation, and also maintains a state of the art chemistry computer data base for maintaining and trending laboratory data. The licensee's chemistry training program was also reviewed this assessment period. Both the training and retraining programs appear to be adequate as indicated by the results of the NRC standards analyses.

In summary, the licensee's aggressive recruiting and training program has resulted in a significant increase in the size and effectiveness of the Operations Department staff, the staffing improvement, strict control of operator overtime, appropriate management attention, and intensive communications training all have contributed to a recent trend in positive attitude and professional atmosphere in the control room. However, some weakness in attention to detail and procedural compliance were noted and require continued attention. The licensee's approach to problem investigation and root cause analyses has improved, and is generally prompt and positive. Overall performance in this functional area has improved, particularly during the last quarter of the assessment period.

(2) Conclusion

Rating: 2

Trend: None Assigned

4.2 Radiological Controls (1064 hours/12 percent)

(1) Analysis

The radiological controls functional area is an assessment of licensee performance in implementing the occupational radiation safety, chemistry, radiological environmental monitoring and transportation programs. In November 1984, the NRC issued a confirmatory order requiring broad scope improvements in the licensee's Radiological Controls Program. During the previous assessment period this area was rated Category 3. The NRC review found that some improvement had been made in the radiation safety program. However, significant weaknesses were identified which inhibited further performance improvement. These weaknesses included poor communications, antagonistic working relationships, lack of personnel accountability, poor ALARA performance, ineffective corrective actions, and vacancies in key radiological safety supervisory and management positions. As a result of these weaknesses the NRC confirmatory order was not closed out. Weaknesses were also identified in implementation of Radiological Effluent Technical Specification surveillance requirements and the licensee's environmental TLD program. During the previous assessment period, the licensee's transportation program exhibited a decline in performance with three violations being identified.

During the current assessment period there were nine inspections in this area of the occupational radiation safety program. The inspections focused on oversight of outage work, establishment of effective management controls for this area and efforts to close out the NRC Confirmatory Order and associated Radiological Improvement Plan (RIP). In addition, three inspections were performed in the chemistry, transportation, and radwaste systems areas.

Radiation Protection

The weaknesses noted during the previous assessment period persisted through the first half of this assessment period. However, in November, 1987 an inspection found that performance had improved to the point that the November 1984 NRC Confirmatory Order was closed out but, at the same time, acknowledged that additional improvements and continued management attention to these areas were needed. Actions that are planned by the licensee to continue to improve performance such as improved radiological awareness and increased staffing are documented in the licensee's Radiological Action Plan (RAP).

Toward the end of this period, the Radiation Protection program organization and staffing levels, a weakness during most of the assessment, improved. The organization, staffing levels, re-

sponsibilities, accountabilities, and interfaces are now well defined. Station management attention to the areas of communications, accountability, morale and the corrective action process over the last half of the period has improved working relationships and communications between other departments and radiation protection.

The recently revised Radiation Protection organization is approximately 90% filled by permanent personnel. Although the organization and staffing are adequate to support the program, the position of Chief Radiological Engineer (Radiation Protection Manager) was recently restaffed with a contractor, several managers have limited commercial nuclear power experience, and many personnel are new to their positions. Performance of this new organization will continue to be assessed in the future.

A well defined training and qualification program has been established. The program contributes to an adequate understanding of program requirements with few personnel errors. Training resources are adequate. The radiation protection training program is INPO certified. New training initiatives are in progress to sensitize management, workers and radiation protection personnel to assure they are aware of the need to minimize all occupational radiation exposure. Examples include training of management on ALARA for plant design changes and providing radiation awareness training to maintenance and operations personnel.

Licensee audits and assessments of program implementation and adequacy have improved. The audits and assessments, augmented by supervisory and management tours, have been generally adequate in following program implementation and identifying weaknesses, particularly toward the end of the period. Technical specialists are used to augment the QA audit teams. Additional QC surveillance of problem areas (e.g., High Radiation Area key control) has been implemented. However the scope of licensee audits have been principally compliance oriented. There is little external review of program adequacy and performance relative to the industry.

In the area of Internal Exposure Controls, no significant individual exposure of personnel during the period was identified. Also, during the major plant decontamination operation, exposure of workers to airborne radioactive material was well controlled. Approximately 90% of the station is now accessible in street clothes. Licensee quantification of radionuclides contained in the NRC whole body counting phantom was good. The use of sensitive whole body counting equipment combined with a capability to analyze the data reflects an adequate bioassay capability. Although performance in the area of Internal

Exposure Controls has improved, NRC review identified instances where about 1000 individuals had terminated from the site during the period without receiving confirmatory whole body counts. These termination body counts are not required by the NRC but are a normal good practice at most reactor sites and are recommended by Pilgrim site procedures. When brought to the licensee's attention they were unaware of the magnitude of these exceptions to the recommended practice, reflecting some weaknesses in oversight of this area.

During the assessment period three violations occurred which involved improper control of High Radiation Areas. Although no unplanned exposures resulted, when examined individually, these violations clearly reflect one or more of the previous assessment period concerns. In response, the licensee made certain short term corrective actions and established a task force to review the concerns and develop long term corrective actions. The licensee corrective actions for the most recent High Radiation Area access control concerns were appropriate, however, these corrective actions were prescribed by memorandum. The NRC has previously expressed concern regarding implementation of regulatory requirements by memoranda rather than by the use of formal, approved plant procedures. At the end of the assessment period, procedures were not yet revised to include these corrective actions. An additional weakness involved licensee attempts to resolve a concern with exposure reports in that, early in the period, NRC identified that the licensee had not sent a number of termination reports to individuals. The licensee instituted a corrective action program, but this matter is still under NRC review.

During the latter part of the assessment period, control, oversight and coordination of in-plant activities by the radiation protection department had significantly improved. The number of licensee technicians and first line supervisors was increased. Coincident with this staffing increase, licensee management selectively reduced contractor work force, keeping the most competent performers. The augmentation of first line supervisors combined with the elimination of a large number of contract technicians resulted in improved management control and accountability within the department.

In the area of radiation exposure, Pilgrim Station collective worker doses, calculated as 5 year rolling averages, have historically been among the highest in the nation. Some improvement was noted in the previous assessment period after a well documented ALARA program was instituted accompanied by a high visibility exposure goals program. Licensee activities during this period resulted in a collective worker dose (1580 person-rem) which was the highest of all domestic power reactors in

1987. Analysis by station management attributes the exposures to an expanded work scope during the prolonged outage with about 20% due to unplanned rework, poor contamination controls, and poor planning. Also, the large number of workers (about 2000) on site during the outage coupled with the high radiation source terms and poor work habits in the plant contributed to the high annual dose. During the initial part of this assessment period, NRC concerns included lack of understanding of day-to-day work activities due to poor maintenance planning and inaccurate description of work provided to radiation protection personnel which is incorporated into RWPs. Also, RWPs continued to be requested for work that was not performed. Improvements in this area were noted during the latter half of this assessment period.

Management efforts instituted to control exposure included hiring a large contractor staff to implement ALARA on the job, assigning six HP/ALARA coordinators to work groups, and implementation of dose saving techniques recommended by the ALARA Committee. The effectiveness of the six coordinators was particularly evident in the areas of maintenance and operations. For example, the use of glove bags to contain contamination during maintenance has been expanded. Contamination "spill drills" are routinely conducted to prepare operations personnel for dealing with future incidents so that the spread of contamination can be minimized.

NRC review of the selected ALARA goals indicated that they appeared to not be challenging and there was no formal mechanism to incorporate ALARA principles during the design of plant modifications. For example, during the outage the licensee was noted to have rebuilt a number of large valves (e.g., RHR System) without considering the need to reduce stellite, a major source of cobalt. During the latter part of the assessment period, the licensee was attempting to formalize a program to conduct ALARA reviews of plant design modifications during the conceptual design phase. A goal of 600 person-rem was initially planned for 1988 even though most of the outage work ended in February and a lower goal appeared achievable based upon anticipated radiological work. In addition, there was no long range planning evident to reduce the high general area dose rates at the station.

Radiological Environmental Monitoring Program

Midway through this assessment period an inspection of the licensee's radiological environmental monitoring program (REMP) was conducted. The REMP is administered by the corporate Radiological Engineering Group. The licensee's REMP conforms to Technical Specification requirements. The licensee has made plans for improvement of the annual REMP reports, and improve-

ments to the meteorological monitoring program even though the licensee's Technical Specifications contain no requirements in this area. In response to a program weaknesses identified by the NRC during the last assessment period, the licensee has eliminated the environmental thermoluminescent dosimeters TLD system which was in use during the previous assessment period and is now using TLDs supplied by the Yankee Atomic Environmental Laboratory. Planned personnel expansion in this area is indicative of the licensee's commitment to continued improvement of the REMP.

Transportation

One inspection of the licensee's transportation program was conducted midway through this assessment period. Two Severity Level IV violations were identified. Both violations related to shipments made during the previous assessment period. These violations suggested inattention to technical detail and quality control in the preparation of radioactive shipment records. However, during this assessment period the licensee increased quality control involvement in processing, preparation, packaging and shipping of solid radioactive waste. This indicated the licensee's clear understanding of issues relating to causes of the problems and, in addition, the implementation of corrective action. The licensee is meeting all commitments to the NRC with regard to training in this area. The licensee has implemented procedures which clearly define the roles of the departments involved in solid radwaste and transportation. Procedures for processing, preparation, packaging, and shipping solid radwaste were adequate.

Summary

In summary, there was an overall improvement in licensee Radiation Protection Program adequacy and performance, particularly during the last quarter of the assessment period. However management attention is still required to exceed minimum regulatory requirements in the in-plant radiation protection program. Communications and working relationships have improved. Facilities and equipment have been upgraded. Limited success in 1) upgrading the ALARA Program performance, 2) staff qualifications and stability, and 3) aggressive long term corrective actions for High Radiation Area access control were noted.

In contrast, licensee performance in the areas of REMP and transportation reflects substantial improvement. These areas, if rated separately, would receive the highest performance rating category. Previous weaknesses regarding radiological effluent technical specification surveillance and the environmental TLD program have been corrected and plans made for additional program improvements. The station has substantially upgraded quality control activities in the transportation area.

(2) Conclusion

Rating: 3.

Trend: Improving.

(3) Recommendations

Licensee: 1. Continue strong senior management involvement in the in-plant radiation protection program.

2. Strengthen the ALARA program and complete training on program implementation.

NRC: 1. Conduct a management meeting with the licensee to review radiological program status and ALARA program progress.

4.3 Maintenance and Modifications (2347 Hours/24 percent)

(1) Analysis

This functional area is intended to assess the licensee's performance in planning and implementing the station maintenance program, and in implementing and testing plant modifications. The adequacy of modification design is evaluated under the Engineering and Technical Support functional area. This SALP period includes the results of the April 25 - May 5, 1988 NRC Maintenance Team Inspection. It does not include evaluation of the licensee's Restart Readiness Self Assessment, nor does it evaluate the licensee's response to the Maintenance Team Inspection findings.

During the previous SALP period, plant maintenance performance was assessed as a Category 2. Maintenance staffing was weak due to first line supervisory vacancies and lack of direct professional support, hampering programmatic improvements. The scheduling of "A" priority maintenance was good, however lower priority maintenance scheduling was weak as demonstrated by the large maintenance backlog. This was particularly evident in the areas of fire protection and security, resulting in equipment unavailability. The maintenance planning group was effective in validating maintenance requests (MR), but was only marginally effective in planning daily maintenance activities. Maintenance program procedures were considered weak and contained only minimal information. No administrative guidance for the newly formed planning and procurement groups was in place, hampering their integration into the process.

During the current SALP period maintenance and modification activities were routinely monitored. Also seven special inspections were conducted to evaluate the licensee's maintenance and modification control programs. An Augmented Inspection Team and a special electrical system team inspection also evaluated aspects of maintenance program effectiveness. Near the close of the SALP period a special maintenance team inspection evaluated the licensee's effectiveness in implementing the program.

Licensee efforts to improve facility material condition during this assessment period have been highly evident. Overhauls of major plant equipment such as the Residual Heat Removal pumps, High Pressure Coolant Injection pump, and feedwater pumps were successfully completed. Commitment by senior licensee management to perform these and numerous other equipment overhauls is a positive indication that material improvement has been a licensee priority.

The maintenance section also provided strong support during the November, 1987, extended loss of offsite power recovery effort. The Maintenance Section Manager held meetings to ensure directed and coordinated efforts of the work force and developed plans for an organized approach. Inspector observation of maintenance task performance in the field indicates that workers are adequately trained in that they are generally knowledgeable of assigned activities and their impact on the plant.

Senior licensee management has acted to increase allocated maintenance staffing, however staffing levels remained a weakness during much of the period. The significant burden of outage activity combined with this weakness continued to delay the progress of program enhancements. Early in the period, first line supervisory vacancies resulted in a reduction in oversight of field activities. Qualified licensee personnel did not apply for the positions. The licensee aggressively recruited individuals from outside the organization and filled the vacancies. Three maintenance staff engineer positions were created and filled in an effort to provide maintenance department technical support.

These individuals concentrated largely on completion of outage tasks and therefore were not available to develop longer range maintenance program improvements. Late in the period the Maintenance Section Manager and both the Electrical and Mechanical Division Manager positions became vacant. The licensee filled these three vacancies immediately after the close of the SALP period. Turnover and difficulty in recruitment of in-house personnel continues to be a significant problem at the maintenance supervisor level. The licensee compensated for two of these vacancies by using contractors. These continuing supervisory staffing vacancies combined with maintenance management turnover resulted in a lack of stability and consistent direction in the maintenance organization.

Communications between the maintenance department and other organizational entities has improved significantly. Early in the SALP period poor communication between the maintenance, radiation protection and operations departments resulted in a large number of radiation work permits requested but not utilized, and processing of equipment isolations for maintenance activities which were subsequently delayed. Maintenance priorities were not always consistent with operational needs. To address these issues, licensee management assigned two experienced radiation protection technicians to maintenance to assist in job planning and to improve maintenance personnel appreciation of radiological considerations. Two senior reactor operators were assigned to provide direct input to the planning process, and to act as liaison between operations and maintenance.

These actions resulted in substantial communications improvement, and more efficient processing of maintenance and modifications tasks during the latter part of the assessment period.

During the period the licensee continued to devote resources to the improvement of the planning and scheduling function. Staffing of the maintenance planning group was augmented by the addition of significant contractor support. At the close of the SALP period all maintenance planning staff positions had been filled, with five positions filled by contractor personnel. This group actively collected existing MRs and verified spare parts availability but was not effective in developing integrated maintenance schedules or ensuring consistent high technical quality in maintenance packages. Licensee management also created the temporary Planning and Restart Group to assist in establishing outage scope and schedules. The functions of this group were later incorporated into the permanent line organization under the Planning and Outage Manager. The Planning and Outage Group appeared to be increasingly involved in developing and tracking longer term work schedules by the close of the SALP period. Continued attention to developing and implementing effective maintenance schedules, and to improving the detail and quality of maintenance work packages is needed.

In the previous SALP period, a large backlog of low priority maintenance had resulted in inoperable fire protection and security equipment, and reductions in operational flexibility due to equipment unavailability. During this assessment period, the licensee has effectively focused attention on defining and processing this large backlog of work. Recent completion of the major outage activities allowed further reductions. Late in the period the licensee directed increased effort at improving general equipment condition. Management frequently toured the station, evaluating the effectiveness of these efforts. However, because of a lack of sensitivity caused in part by concentration on backlog reduction, less significant maintenance deficiencies and poor maintenance practices were not always promptly addressed. An example of this is the poor condition of station batteries identified during a NRC team inspection.

Several routine inspections and a maintenance team inspection near the end of the SALP period found that maintenance program procedures and work instructions continued to be a significant weakness. Work control and implementation practices were not clearly delineated in approved procedures or other directives as evidenced by the excessive delay in issuing the Maintenance Manual. Maintenance requests contained little detail of the as-found condition, repairs effected and post-maintenance testing performed. This hindered subsequent root cause evaluations and reviews. Instructions provided to maintenance technicians

often were not sufficiently detailed to ensure proper performance of the task, and to document activities such as placement of jumpers or lifted leads. For example, a series of engineered safety feature (ESF) actuations were caused by lack of adequate instructions and planning of electrical relay replacements. There was also no effective process for management review of completed maintenance packages. A number of improvements had been implemented such as maintenance package checklists, worker prejob briefings and use of a temporary procedure to document lifted leads, but appropriate maintenance process procedures were not revised to reflect the changes. For much of the SALP period, actions taken in response to NRC concerns were directed at correcting problem symptoms and were not sufficiently comprehensive in nature. The licensee deferred the formal addressing of program weaknesses in this area and the application of interim improvements has been inconsistent and not wholly effective. Shortly after the assessment period, licensee attention to this areas intensified and major program improvements were initiated.

The licensee's post-maintenance test program was not clearly defined. No clear guidance for establishment of post-maintenance testing requirements existed. In one case MRs for extensive repair and retermination of electrical cables were designated as not requiring retest, even though the repairs disturbed numerous circuits upon which logic testing had previously been completed. Late in the period the licensee took action to strengthen the post-maintenance testing process and to create a matrix of testing requirements.

The licensee implemented several aggressive maintenance initiatives directed at improvement of component performance. Preventive maintenance on all safety-related motor operated valves (MOV) and AC circuit breakers was completed. However MOV procedures were found to be weak in some areas. Circuit breaker maintenance was not extended to include any safety-related DC circuit breakers until prompted by the NRC, even though none had been performed during the life of the plant. While management commitment is evident, follow through on initiatives was occasionally incomplete. The increasing involvement of the Systems Engineer Group has had a positive impact on maintenance performance, particularly the quality and promptness of maintenance problem root cause analysis. The licensee also significantly increased staffing, training and management direction of the Station Services Group resulting in improvements in the station decontamination and housekeeping programs.

The licensee has implemented a Material Condition Improvement Action Plan (MCIAP) which identifies many of the weaknesses described above. An independent monitoring group was estab-

lished by the licensee to monitor its effectiveness. This plan is intended to result in significant maintenance program improvements over the long term. The hardware aspects of the MCIAP were effectively addressed, however, program and procedural enhancements were deferred. The licensee also implemented a maintenance performance indicators program. This program has assisted licensee maintenance management in better focusing on adverse trends and department performance.

As a result of good working relationships between the Site Engineer Group and the Modification Management Group, licensee control of modification implementation and turnover was strong. A large number of complex modifications were completed during the period without significant problems. The program for controlling post-modification testing was generally effective. However, technical review of post-modification test procedures was occasionally inadequate. Examples of this included the failure of testing to identify the incorrect installation of reactor water level instruments, and the approval of several tests which either caused or would have caused unanticipated ESF actuations.

In summary, the licensee continues to give high priority to improvement of plant material condition, although program weaknesses in several areas were evident. The licensee implemented informal process enhancements which resulted in more rapid improvement during the last months of the SALP period. A long range plan, the MCIAP, has been established to promote program improvements in the areas of identified weakness. Licensee senior management attention to full and timely implementation of this plan is necessary to assure that permanent improvements are achieved. Staffing problems and management turnover however, need to be resolved so that these problems do not continue to hamper licensee efforts.

(2) Conclusion

Rating: 2

Trend: None Assigned

(3) Recommendations

Licensee:

- Complete implementation of program improvements and continue staffing efforts.
- Provide for staff continuity and development.

NRC: None.

4.4 Surveillance (1386 hours/14 percent)

(1) Analysis

The surveillance functional area is intended to assess the effectiveness of licensee management in assuring the development and implementation of a comprehensive surveillance testing program.

During the previous SALP period, surveillance was assessed as a Category 3. Testing was generally conducted in a careful, safety conscious manner, however no centralized management of the surveillance test program existed. Responsibility for program management was not clearly established. The system for control of surveillance scheduling was weak, principally because the key individual involved with this activity was not a technical staff member. The technical adequacy of surveillance procedures and the control of measuring and test equipment (M&TE) were also found to be inadequate. The licensee's surveillance test program had not received adequate management attention.

During this SALP period surveillance testing was routinely observed and procedure technical adequacy was evaluated. One management meeting and several inspections were conducted to assess licensee efforts to correct the previously identified problems. An Augmented Inspection Team dispatched in response to a loss of offsite power also evaluated aspects of surveillance program effectiveness.

During the previous assessment period, the absence of strong centralized control and responsibility for surveillance program oversight contributed to continuing weaknesses. Early in this SALP period the licensee assigned responsibility for program maintenance and upgrade to the Technical Section Manager. The Systems Engineering Group within the Technical Section has become increasingly involved with development of program improvements. A Surveillance Coordinator position was established and staffed by a senior systems engineer to help provide needed focus. In addition, a coordinator was assigned in each department responsible for surveillance test performance. Allocation of these resources has resulted in acceleration of program improvements and is an indication of management commitment.

The licensee has taken action to improve the technical adequacy of surveillance test procedures. Technically inadequate test procedures were a recurring problem identified during previous SALP periods, requiring repeated NRC initiatives to obtain licensee corrective action. During the current assessment period however, the licensee implemented an extensive effort to evaluate and upgrade surveillance procedures. A team composed of licensee Nuclear Engineering Department, Technical Section and Maintenance Section representatives was formed to address the problem. Initially the effort was intended to assure compliance with technical specifications. Licensee management expanded the upgrades however, to include testing of additional system design features beyond technical specification requirements. This is an indication of the licensee's desire to establish a more comprehensive program that goes beyond regulatory requirements. Implementation of the improved testing allowed the licensee to identify and correct several system performance problems. Another example of the licensee's intent to thoroughly test major systems was the use of a temporary boiler to perform extensive testing of the High Pressure Coolant Injection and Reactor Core Isolation Cooling systems with non-nuclear steam. While substantial progress has been made, and existing procedures have been upgraded sufficiently to assure compliance with the Technical Specifications, some procedural weaknesses continue to be noted. For example, the inoperability of an emergency diesel generator during a loss of offsite power could have been prevented if surveillance procedures had recorded and evaluated more than the required minimum instrument readings. Additionally, inadequate test procedures have caused unnecessary engineered safety features actuations.

The licensee began development of a new computer-based Master Surveillance Tracking Program (MSTP) in an attempt to resolve previously identified scheduling problems. Considerable licensee effort was expended on development of the new program. However, late in the SALP period the licensee concluded that it was not viable due to problems with vendor-supplied computer software. The licensee's Systems Engineering Group has initiated an interim manual tracking system, and is revising the previously used MSTP to compensate for the identified weaknesses. Substantial time was expended in the unsuccessful attempt to implement the new MSTP, and therefore final resolution of the scheduling problems has not been reached. However, it is evident that licensee management is committed to improving the system, responsibility for implementation has been established and progress is being made.

The licensee's program for control of Measuring and Test Equipment (M&TE) has improved significantly. The licensee dedicated four full-time individuals to the upgrade of the M&TE control program. Instruments were collected, assigned unique identification numbers and data was input to a computer-based tracking system. Control and implementation of the local leak rate test program have also improved since the last assessment period. The significant improvement in these areas is a clear result of management involvement.

Licensee personnel generally conducted testing in a careful, safety conscious manner. Major testing evolutions such as the reactor vessel hydrostatic test and the containment integrated leak rate test were well coordinated and executed. Occasional personnel performance lapses in the quality of testing were noted, however. For example, instrument and controls technicians failed to enable equipment sump level switches after calibration, causing sump overflow in the high pressure coolant injection pump room. During a similar drain system overflow incident operators did not perform required shiftly plant tours. As a result contaminated water was allowed to accumulate. These instances may indicate some weakness in personnel training.

The inservice inspection (ISI) program was effectively implemented. The licensee's ISI staff demonstrated a good understanding of technical issues. Management support of the ISI program is evident. For example, prompt action was taken to evaluate piping erosion and drywell liner corrosion in response to industry events.

In summary, the licensee has established appropriate responsibilities for management of the surveillance program. Sufficient senior management and technical resources have been allocated to affect the needed program improvements. Program responsibilities have been defined and assigned to the System Engineering Group. Test procedure technical adequacy and control of M&TE were substantially improved in response to recurring NRC concerns. While strengthening of surveillance scheduling has been slowed due to computer program problems, progress is currently being made. Continued licensee management attention is necessary to assure implementation of ongoing improvements, aggressive evaluation and correction of remaining weaknesses and reinforcement of newly established work standards.

(2) ConclusionRating: 2Trend: None Assigned(3) Recommendations

Licensee: Continue positive initiatives to upgrade surveillance procedures and impliment improved surveillance tracking programs.

4.5 Fire Protection (493 hours/5 percent)

(1) Analysis

This functional area is intended to assess the effectiveness of the licensee's station fire protection program, and the adequacy of modifications and procedures established to ensure compliance with 10 CFR 50 Appendix R. During the last period this area was rated as a Category 3. The fire protection program suffered from a chronic lack of management attention. The licensee was not aggressive in maintaining the operability of station fire protection equipment, resulting in heavy reliance on compensatory measures. Fire barrier surveillance procedures were unclear and incomplete. Personnel performing fire watches and serving on the fire brigade were poorly trained. Licensee senior management had taken steps at the end of the period to strengthen the program.

During this assessment period routine inspections monitored the progress of licensee improvement efforts, additionally two inspections were conducted to assess the status of the station fire protection program. In addition, a team inspection was performed to evaluate licensee compliance with 10 CFR 50, Appendix R. A management meeting was also held to discuss fire protection and Appendix R concerns.

The licensee demonstrated a high level of management involvement in ensuring fire protection and Appendix R program improvements. A fire protection group was established near the end of the last SALP period. During this period, staffing for the group was increased from one fire protection engineer to six permanent fire protection specialists. Frequent meetings with the fire protection group leader, and periodic status reports assisted senior licensee management in monitoring the group's progress. In the area of Appendix R the licensee established a temporary project management organization. A senior project engineer was dedicated to provide focused oversight and support. The Appendix R project organization and the fire protection group worked closely together to coordinate activities.

The licensee has been successful in reducing the backlog of fire protection equipment maintenance, which had contributed to a heavy reliance on compensatory measures. Fire protection group and maintenance managers worked effectively together to reduce the outstanding maintenance backlog, and to maintain it at a manageable level. Total outstanding fire protection maintenance was reduced from over 300 items to less than 50 items, and is currently tracked by licensee management as a performance indicator.

The control and quality of fire brigade training have improved. The fire protection group, with the assistance of the training department, developed and implemented a more comprehensive training program. A state certified instructor was hired to conduct the brigade training. The number of fire brigade drills conducted has substantially increased, and it appears that their effectiveness has improved. Through these actions the licensee has succeeded in developing a large core of trained personnel to serve as fire brigade members. Effective interaction and coordination between the fire brigade, the operations staff and local fire fighting companies was evident during several minor fire incidents occurring during the period, including a fire in the machine shop which prompted declaration of an Unusual Event.

The licensee initiated, and the NRC has approved several fire protection licensing actions during the assessment period. In response to past instances of problems with fire barrier adequacy, the licensee's Appendix R project organization implemented a well conceived program to identify, inspect and repair plant fire barriers. These inspections resulted in the identification of a significant number of deficient barrier seals. Licensee management exhibited a conservative philosophy, establishing compensatory fire watches for all plant barriers pending completion of inspections.

The licensee's approach to maintaining safe shutdown capability was found to assure redundant safe shutdown system train separation, and to provide sufficient operational flexibility. To assure adequate separation the licensee performed a well documented and thorough analysis, although procedures for use of the safe shutdown equipment, and operator training in this area were found to be weak. The licensee has taken action to resolve these weaknesses and has committed to demonstrate safe shutdown capability by performing a test during the power ascension program.

In summary, licensee management has taken strong action to establish and staff an effective station fire protection organization. Significant improvement in fire protection equipment material condition and fire brigade training has resulted. Licensee response during this SALP period to Appendix R issues, particularly fire barrier seal problems, was prompt and effective. Continued management attention is needed to assure prompt completion of fire barrier seal repairs, to achieve further reduction of outstanding compensatory fire watches and to provide a stable effective fire protection program.

(2) Conclusion

Rating: 2

Trend: None Assigned

4.6 Emergency Preparedness (176 hours/2 percent)

(1) Analysis

During the previous assessment period, licensee performance in this area was rated Category 2. This was based upon a renewed commitment by management for emergency preparedness and a significant improvement in performance.

During the current assessment period, one partial participation exercise was observed, two routine safety inspections were conducted, one special safety inspection specifically related to emergency classification was conducted, and changes to emergency plans and implementing procedures were reviewed.

Two routine safety inspections were conducted in November, 1987 and January, 1988. These inspections examined all major areas within the licensee's emergency preparedness program. During the November, 1987 inspection, significant changes were examined regarding the normal emergency preparedness organization. These changes resulted in essentially a completely new organization with the Emergency Preparedness Manager reporting to the Senior Vice President. Functional responsibilities are divided into on-site and off-site areas with coordinators for each. The licensee has filled the managerial positions, as well as other working positions, with personnel experienced in emergency preparedness. In addition, the licensee has contracted with several consultants to help the permanent staff.

During the January, 1988 inspection significant changes were examined regarding the Emergency Response Organization (ERO) and Emergency Action Levels (EAL's). The licensee has committed to a complete restructuring of the ERO with a three-team duty rotation. Additionally, the licensee is revising the EAL's to be symptomatic, address human factors, and has integrated them with the Emergency Operating Procedures. Significant facility changes made include the addition of a Computerized Automated Notification System to notify the ERO.

A partial participation exercise was conducted on December 9, 1987. The licensee demonstrated a satisfactory emergency response capability. Actions by plant operators were prompt and effective. Event classification, and subsequent Protective Action Recommendations, were accurate and timely. Personnel were generally well trained and qualified for their positions. No significant deficiencies were identified. Several minor weaknesses were noted including insufficient depth in some positions to support prolonged operations, dose projection discrepancies, delays in fielding onsite repair teams, and weak initial notification forms.

During the response to a loss of offsite power event in November, 1987, some weakness in coordination and communication between licensee groups was noted. While not required by the site emergency plan, the licensee eventually chose to partially activate the Technical Support Center (TSC) to aid in recovery efforts. The difficulties experienced by the licensee during the initial response and subsequent efforts to utilize the TSC indicate that licensee attention to preplanning response options to non-emergency events, such as discretionary activation of the TSC, may be appropriate.

During the February, 1988 inspection the licensee's actions in response to a declaration of an Unusual Event were examined. The licensee's classification was conservative and prompt. Mitigation activities were effective. The licensee identified several problems associated with their actions including: failure to completely follow procedures; untimely notification of event termination; and control room distractions due to the large volume of outside communications. The licensee promptly identified these issues and instituted appropriate short-term and long-term actions to prevent their recurrence.

The licensee is continuing to work closely with local and Commonwealth of Massachusetts officials to upgrade off-site emergency preparedness. The licensee has a large organization working on plan and procedure development, in conjunction with the appropriate local and Commonwealth agencies.

During this period, the licensee was granted exemptions for the 1987 full participation exercise and a deferral of the submittal of public information. These were based on the Commonwealth of Massachusetts requests to complete the local and Commonwealth emergency plans, implementing procedures and associated training prior to issuance of public information or demonstration of capabilities.

In summary, the licensee has demonstrated a commitment to emergency preparedness. Management involvement is evidenced by the major on-site program changes being supported, commitment to the offsite level of emergency preparedness, and by timely recognition of problems and subsequent corrective actions. The licensee has been responsive to NRC concerns and is continuing to make progress in these areas.

(2) Conclusion

Rating: 2

Trend: Improving

4.7 Security and Safeguards (641 hours/7 percent)

(1) Analysis

This functional area was rated as a Category 3 during the previous assessment period. NRC identified serious concerns regarding the implementation and management support of the security program. The licensee's proprietary security staff consisted of one full time and one part time member, resulting in weak oversight of the contractor. In addition, inoperable equipment contributed to a heavy reliance on long term compensatory measures. Contractor security force overtime was also poorly controlled. Toward the end of the assessment period, the licensee initiated actions to correct the problems. However, at the conclusion of the rating period the hardware upgrades were not complete and the expanded proprietary security staff organization had not been in place for an adequate time for NRC to evaluate its effectiveness.

Four routine, unannounced security inspections, one special security inspection, and one routine unannounced material control and accounting inspection were performed during this assessment period by region-based inspectors. Routine observations were also conducted throughout the assessment period.

During this assessment period, the licensee aggressively pursued a planned and comprehensive course of action to identify and correct the root causes of the previously identified programmatic weaknesses in the area of physical security. To improve the overall performance of the security organization and the security program the licensee implemented several significant actions, including a commitment by senior management to support and implement an effective security program; establishment of a licensee security management organization on-site to direct and oversee program implementation; upgrading unreliable systems and equipment to eliminate the previous heavy reliance on compensatory measures that were manpower intensive; and revising the Security, Contingency and Training and Qualifications plans, and their respective implementing procedures, to make them current and clearer.

The licensee's security management organization is now headed by a section manager who reports to the Plant Support Manager, under the Station Director. Assisting the Security Section Manager are five supervisors with specific functional areas of responsibility (operations, administration, technical, compliance and access authorization) and a staff assistant. Additionally, there are seven licensee shift supervisors who are

responsible to monitor the performance of the contract security force around-the-lock. This represents an overall increase of seven supervisors over those which were in place at the end of the last assessment period, and thirteen over that which was in place when the plant was shut down in April, 1986. (At that time there was one supervisor who reported to a group leader with other, concurrent duties.) The licensee also established a full-time corporate security position onsite. The incumbent is responsible to audit the security program on a continual basis and to provide another perspective on its implementation. In addition, the licensee established, as supervisory personnel, the alarm station operators employed by the security force contractor, and significantly improved the supervisor-to-guard ratio. This expansion of the licensee's security organization represents a significant allocation in terms of resources and provides evidence of senior management's commitment to the program.

In addition to the organizational expansion, considerable capital resources were expended throughout the assessment period to upgrade, by modification or replacement, security systems and equipment. The entire protected area barrier, assessment system, intrusion detection system and protected area lighting were significantly improved. These improvements began early in the assessment period and were, for the most part, complete at the end of the period with only minor fine tuning of the new systems and equipment still required. Additional upgrades in access control equipment and the security computer are scheduled. The improvements have already resulted in a sizable reduction in the number of compensatory posts and, therefore, a reduction in the contract guard force. The above mentioned upgrades permitted the guard force to go on a 40 hour work week rather than the 60 hour work week required during the major portion of the assessment period. In addition to the improved systems and equipment, the licensee has taken action to strengthen the security equipment corrective maintenance program and has initiated action to establish a preventive maintenance program to further ensure the continued reliability of security systems and equipment. Open maintenance requests for security equipment are also now tracked as a performance indicator by plant management. These actions and initiatives are further evidence of senior management's commitment to the program.

During the assessment period, the licensee submitted six changes to the Security Plan under the provisions of 10 CFR 50.54(p). One of these changes was a complete revision to upgrade the Security Plan and to revise the format to be consistent with NUREG 0908. In conjunction with the Security Plan upgrade, the licensee also submitted revisions to the Safeguards Contingency Plan and the Security Force Training and Qualification Plan (complete revisions of these plans were submitted during March, 1988). The complete plan revisions were comprehensive, more consistent with current NRC regulations, and provided clearer documents from which to develop and modify implementing procedures. The plan changes were adequately summarized and appropriately marked to facilitate review. Further, the licensee, prior to submitting the changes, communicated with the NRC by telephone and requested meetings in Region I and onsite to ensure that the changes were appropriate, clearly understood, and in compliance with NRC regulations.

Audits of the Security program conducted by Corporate Security personnel and the onsite QA group during the assessment period were found to be very comprehensive and corrective actions were found to be prompt and generally effective, indicating a much improved understanding of program objectives. Because of the security program weaknesses identified toward the end of the previous SALP period, the licensee assigned to the site, on a full-time basis, a member of the corporate security staff with responsibility for conducting continued surveillance and audit of the program. That initiative was reviewed and found to be a very effective management tool to provide an independent assessment of the day-to-day implementation of the security program and another input to the overall security program upgrade project.

The security force training program appears to be adequate to address the activities of the security organization. The licensee has taken actions to assure the training program remains current and reflects the changes and upgrades to the security program. For example, to ensure more comprehensive management oversight by licensee security shift supervisors, each received plant operational technical training in addition to security program and other training. This training enables these supervisors to be more effective in interfacing with other plant technical functions.

There were three apparent violations identified by the NRC during this assessment period. All of the violations were the result of degraded vital area barriers. The licensee was notified of the apparent violations and an enforcement conference and a subsequent management meeting were held. These apparent violations resulted from weak communications between the security and maintenance organizations, and a poor appreciation by maintenance personnel of security requirements. Corrective actions were implemented by the licensee and they appear to be effective.

A total of six security event reports required by 10 CFR 73.71(c) were submitted to the NRC during this assessment period. Three event reports were necessitated by the licensee's findings of degraded vital area barriers. Similar degradations were also reported in the previous assessment period. Two of the degradations reported during this period were the result of maintenance work being performed on plant systems that penetrated the barriers. The other resulted from a degraded vital area door. Another event report was necessitated by the reclassification of an area of the plant as vital. The need for reclassification was identified as a result of the licensee's Vital Area Analysis and Barrier study. Another event report involved a guard leaving his weapon unattended. The sixth event report involved the loss of a set of security keys by a member of the guard force. With the exception of the vital barrier degradations earlier in the assessment period, no adverse trend was indicated by the events which occurred during this assessment period. The licensee eventually implemented appropriate measures to prevent recurrence of the vital area barrier degradation problems. The quality of the event reports was significantly improved over the previous assessment period indicating a better understanding of program objectives and more care in their preparation. They were clear, concise and contained sufficient information to permit NRC evaluations without the need for additional information.

The licensee's program and procedures for the control and accounting of special nuclear material were also reviewed during this assessment period and were found to be adequate and generally well implemented.

In summary, the licensee has demonstrated a commitment to implement an effective security program that goes beyond minimum compliance with NRC requirements. As a result of this commitment, the licensee security organization has been expanded, significant capital resources have been expended to upgrade security hardware, and equipment and program plans have been improved. Continued senior management support and involvement in the security program is necessary to ensure that the momentum demonstrated during this assessment period is continued.

(2) Conclusion

Rating: 2

Trend: None Assigned

4.8 Engineering and Technical Support (1215 Hours/13 percent)

(1) Analysis

This functional area is intended to assess the adequacy of the licensee's technical and engineering support in the areas of plant design changes, routine operations and maintenance activities. Engineering and Technical Support was assessed as a Category 1 during the previous SALP period. Good engineering support to the site was noted in the Environmental Qualification program and the design of several significant plant hardware modifications. Technical evaluations were typically thorough and demonstrated an adequate regard for safety. The engineering approach to the Safety Enhancement Program (SEP) demonstrated an excellent appreciation for underlying safety issues. A weakness in the lack of detailed design basis documents for plant equipment was also noted during the last period.

During this assessment period, five special inspections including an Augmented Inspection Team focusing on a loss of offsite power event, an electrical system team inspection, and a maintenance team inspection were conducted and, in part, evaluated the licensee's performance in this area. The effectiveness of the onsite Systems Engineering Group, and the Nuclear Engineering Department's (NED) interactions with the site organization were routinely monitored.

Significant plant modifications were installed during this assessment period, including the reactor water level instrumentation modification, a hydrogen water chemistry system, an analog trip system, and a new plant process computer. Few problems were identified with these projects, demonstrating the strength of the engineering work. Safety evaluations required by 10 CFR 50.59 for design changes and modifications were generally thorough and conservative. Safety evaluations for SEP modifications demonstrated sufficient analysis and supporting facts to conclude that there were no unreviewed safety questions. Highly qualified engineering staff and NED management focus on safety have contributed to the licensee's performance in this area.

Offsite technical and engineering support was generally good as indicated by the successful design and implementation of significant plant hardware modifications. Continued effective use of the Design Review Board was evident during this SALP period.

This was demonstrated by high quality initial design reviews, and routine evaluations of completed modifications for synergistic effects. The expanded Field Engineering Section, the design implementation oversight arm of NED, played a vital role in coordinating activities between the site organization and the NED. Engineering management was actively involved in implementation of modifications and addressing problems. The Safety Enhancement Program, including extensive Mark I containment and station blackout modifications, were planned and implemented during this period. The engineering approach to the Mark I issues went considerably beyond NRC requirements and demonstrated a good appreciation of containment reliability issues. The NED's involvement in the development of the new Emergency Operating Procedures (EOP) demonstrated significant management attention in this area. The licensee's communications with the NRC regarding the planning and implementation of the SEP and EOP projects were generally good. In addition to these modifications, the licensee is preparing an extensive Individual Plant Evaluation (IPE) as part of the (SEP) using probabilistic and deterministic analyses. In support of these efforts, the licensee effectively managed contract engineering expertise to produce quality design changes and analyses. Throughout the development and implementation of the SEP senior management's involvement and commitment to safety was apparent.

A team inspection was conducted during this assessment period to review the licensee's implementation of a fire protection program to meet the requirements of 10 CFR 50 Appendix R. The licensee's approach to maintaining safe shutdown capability was found to assure adequate redundant safe shutdown system train separation, and to provide sufficient operational flexibility. The licensee's analyses were found to be well documented and thorough. NED's Appendix R project organization and the onsite fire protection group worked closely together to coordinate activities.

Some weaknesses in the engineering design change process were noted. In one instance inadequate technical review of a design change by NED resulted in incorrect installation of reactor water level gauges. Additionally, the plant design change document for the Standby Gas Treatment System did not specify adequate post-work testing requirements. Further, as indicated in the previous SALP, the lack of detailed design basis documents was a continuing problem this assessment period. Examples included lack of seismic qualification documents for the reactor

building auxiliary bay and for the hydraulic control units. Also, engineering failed to correctly translate containment accident temperature profiles into environmental qualification documents. However, the licensee has taken initiatives to further understand the design bases of the plant electrical distribution system as evidenced by the use of a new computer code to analyse electrical distribution equipment performance.

At times, corporate engineering support for plant maintenance activities was limited. The NRC special electrical system inspection identified that the DC battery and electrical breaker maintenance activities were not supported by NED. The licensee's initial response to the NRC's concern regarding the surveillance testing of the DC breakers was limited in scope and lacked engineering justifications on the sample size and the acceptance criteria.

The increasing involvement of the onsite Systems Engineering Group (SEG) has had a positive impact on the quality of operations event analysis, the surveillance test program, and on maintenance performance, particularly the quality of maintenance problem root cause analysis. At the beginning of the assessment period the licensee established the SEG under the Technical Section within the Nuclear Operations Department. The SEG was staffed largely with experienced contractors, but the licensee gradually expanded the group and replaced the contractors with permanent Boston Edison employees. At the end of this period, the SEG had a total technical staff of 26 including 15 senior systems engineers. The increasing involvement by the SEG has promoted better intergroup interactions as the operations and maintenance departments have begun to value and rely on the SEG's contributions.

In summary, overall strong engineering support continued throughout this period. Major plant modifications were completed with only a few minor problems, demonstrating the quality of engineering work. The increasing involvement of the SEG has contributed significantly to the quality of root cause analyses and in maintenance performance. However, overall performance in the areas of corporate engineering responsiveness and support to site maintenance initiatives appears to need further licensee evaluation and improvement. Additional management attention is needed in developing long-term programs to provide better operational and maintenance support to the site.

(2) Conclusion

Rating: 1

Trend: None Assigned

4.9 Licensing Activities

(1) Analysis

The licensing functional area is intended to assess the licensee's effectiveness in assuring a technically accurate and up-to-date licensing basis, and the licensee's responsiveness to NRC and industry concerns. During the previous assessment period licensing was evaluated as a Category 2.

During this period, the basis for this appraisal was the licensee's performance in support of licensing actions that were either completed or had a significant level of activity. These actions consisted of amendment requests, exemption requests, responses to generic letters, TMI items, and other actions.

The licensee has exhibited a high level of management involvement in major licensing initiatives; however more routine licensing actions did not always receive substantive management action. An example of a high level of management involvement and initiative is the licensee's actions to improve the Mark I containment and implement other plant safety improvements intended to cope with severe accidents as part of its Safety Enhancement Program (SEP). This program includes improvements to emergency operating procedures, modifications to containment spray nozzles, enhancements to water supplies that would be available in the event of a severe accident, the installation of a direct torus vent and the installation of a third emergency diesel generator. A number of the SEP modifications, such as the Station Blackout Diesel Generator are also useful in dealing with less significant transients and events as opposed to severe accidents.

The licensee is in the forefront of the industry in the effort to deal with severe accidents and has expended substantial resources on the SEP. The licensee has been very active in industry owner's groups involved in severe accident initiatives. Although much of the SEP effort did not involve direct licensing actions, the staff did assess the safety significance of the licensee's modifications and inspected portions of the modifications. The licensee is commended for its leadership on the SEP program. It should be noted that the staff is still continuing its assessment of some of the details of the SEP modifications.

The technical quality of more routine licensing actions (such as some Technical Specification amendments and exemption requests) has been sporadic. Several fire protection licensing actions have required numerous submittals and frequent interchanges with the staff. For example, the licensee revised its technical position twice in the determination of the appropriate basis for an exemption request involving the lack of 3-hour fire proofing for structural steel in the Reactor Building Torus Compartment. Several submittals were required, and the staff had to request detailed calculations to support the licensee's basis. In a technical specification change involving 10 CFR 50 Appendix J requirements (Amendment 113), the licensee had to make numerous submittals in response to staff concerns and was required to correct errors in previous submittals identified by both the staff and BECo. The staff identified inconsistencies in proposed changes to the technical specifications for the Standby Gas Treatment System and Control Room High Efficiency Air Filtration System (Amendment 112) and revised submittals by the licensee were required. The extensive activities and resources required to correct problems identified in Confirmatory Action Letter 86-10 and subsequent management meetings has apparently impacted the licensee's overall performance in the licensing area. These problems suggest a weakness in corporate management at the level that establishes priorities and coordinates engineering and licensing activities for the utility.

The licensee has, however, submitted, and the staff has approved, a number of technical specification changes or exemption requests that demonstrated a high level of technical quality and management involvement. Examples include the scheduler exemption for conduct of the emergency preparedness exercise, Core Reload (Amendment 105), Control Rod Block Actuation (Amendment 110), and LPCI Subsystem Surveillance (Amendment 111). Where NRC staff requests for additional information were made, the licensee responses have been prompt and comprehensive.

The licensee has usually been responsive to NRC initiatives. The licensee has been responsive to staff requests to track and control actions of mutual interest between NRR and the utility. For example, the licensee has developed a tracking system to assist in the management of licensing actions and has provided extensive resources to support NRC effort in updating the Safety Information Management System (SIMS) data base. Particularly noteworthy was the high quality of technical support provided for the staff's review of Emergency Operating Procedures.

There was evidence of improvement during the latter portion of the SALP period in the approach to the resolution of technical issues and responsiveness to NRC initiatives in the licensing area. This is in part due to recent organizational changes which have resulted in a closer relationship of the licensing and engineering groups. The overall staffing to support licensing activities is adequate and its effectiveness should be improved by the recent organizational changes. Recently a reduction has been evident in the number of cases of technical errors, lack of clarity, and incomplete information.

In summary, the licensee has exhibited strong management involvement in several major licensing actions, but attention to more routine licensing actions has been inconsistent. The licensee has shown some improvement in the licensing area during the latter portion of the SALP period. The involvement of management in routine, as well as major licensing activities, is necessary. The continued strengthening of mid-level management and increased technical capability of licensing staff are necessary.

(2) Conclusion

Rating: 2

Trend: None Assigned

4.10 Training and Qualification Effectiveness

(1) Analysis

Technical training and qualification effectiveness is being considered as a separate functional area. The various aspects of this functional area were discussed and used as one evaluation criterion within the other functional areas. The respective inspection hours have been included in each one. Consequently, this discussion is a synopsis of those assessments. Training effectiveness has been measured primarily by the observed performance of licensee personnel and, to a lesser degree, as a review of program adequacy.

This area was rated as a Category 2 during the previous assessment period. The licensed operator training and requalification programs were found to be significantly improved. Assignment of knowledgeable staff had resulted in higher quality training materials, and more plant-oriented operator training. Maintenance, contractor and radiation protection personnel training were also adequate. Fire brigade and fire watch training had been significantly weak and contributed to poor personnel performance in the plant. Four of ten licensee training programs had received accreditation from the Institute of Nuclear Power Operations (INPO).

During this assessment period, inspectors routinely reviewed ongoing training activities and their effectiveness in assuring quality personnel performance. Two sets of reactor operator and senior reactor operator license examinations were administered. An inspection to evaluate the adequacy of the nonlicensed personnel training program was also completed. Various other inspections reviewed training provided in the areas of emergency preparedness, radiation protection, security, maintenance, fire protection and modifications.

Licensed operator training effectiveness continued to improve throughout the period. Two sets of licensed operator examinations were administered to a total of two senior reactor operators and fourteen reactor operators, with all candidates successfully completing the licensing process. Newly licensed operator familiarity with plant equipment and procedures was considered a strength. Challenges facing licensee management include completion of training for the large number of new, relatively inexperienced operators. Site management is intent on assuring that time spent by newly licensed operators in the control room during startup and initial operations, is used as effectively as possible to provide the maximum training benefit.

The material developed for operator training and submitted for NRC review was generally good. However, for the first examination early in the assessment period, it was noted that some materials provided to the NRC did not reflect recent station modifications. This was because the modifications had recently been completed and previous training had focused on the original systems. It was also noted during exams and by direct discussions with licensed operators, that training conducted on recently implemented modifications, such as on the reactor water level and automatic depressurization systems, had not been fully effective. Operators were unfamiliar with the modifications, primarily because only on-watch training had been performed and because the training had been conducted prior to completion of the modifications. Licensee management took prompt action to restructure the modifications training and committed to repeat the training prior to plant restart.

The licensee completed installation of a plant specific simulator during this assessment period, and used it extensively to enhance operator training, particularly in the area of emergency operating procedures (EOP). The licensee implemented a comprehensive EOP training program including a combination of simulator and classroom instruction. Licensee management assured the effectiveness of this training by performing post-training evaluation of the operating crews on the simulator. The development of special criteria by which acceptable performance is judged was a strong point of the EOP training program. Operator performance weaknesses were identified by the licensee, and supplemental training was performed to resolve the problems. Licensee management also initiated a communications training program for operations personnel. This communications training was implemented along with the EOP training and appeared to substantially improve operator performance.

Licensed operator performance during plant events such as a loss of offsite power, and an Unusual Event due to a fire in the machine shop generally demonstrated a good command of plant equipment and procedures. However, some apparent weaknesses in operator training were evident. For example, several operational errors were made during reactor refueling despite independent verification requirements. On several occasions operators failed to properly perform routine surveillances.

The nonlicensed and contractor personnel training program appeared effective. The training staff dedicated to this function has been supplemented by the addition of contractors. The licensee initiated maintenance and radiological technician apprentice programs to assist in development of qualified lower level personnel. New training initiatives are in progress to sensitize management, workers and radiation protection personnel to the need to minimize all occupational exposure. For example, management training in ALARA for plant design changes and radiation awareness training for operations and maintenance personnel have been initiated. In addition, a Training Program Evaluation Committee was established to assure plant management involvement in ongoing development of nonlicensed training.

The licensee's program for fire brigade and fire watch training has been significantly improved. The station fire protection group and the licensee's training department have coordinated to expand the scope and enhance the quality of brigade training. A large core of qualified fire brigade members has been established.

Security force, emergency response and maintenance training appeared to be effective. No performance deficiencies directly attributable to training were identified in these areas during the period. INPO accreditation of all remaining training programs was received during the current assessment period.

In summary, licensee management has been active in improving the overall quality of the training program and has been responsive to NRC concerns. Licensed and nonlicensed training programs are effectively implemented. Of particular value is the use of the simulator, and other initiatives such as formal communications training and establishment of an apprentice program. Efforts should be continued to strengthen operator training in the area of modifications and to ensure effective completion of training for newly licensed personnel.

(2) Conclusion

Rating: 2

Trend: None Assigned

4.11 Assurance of Quality

(1) Analysis

During this assessment period, Assurance of Quality is being considered as a separate functional area. Management involvement in assuring quality continues to be discussed and assessed as an evaluation criterion in each of the other SALP functional areas. The respective inspection hours are included in each one. Consequently, this discussion is a synopsis of the assessments relating to assurance of quality in other areas. Since this is an evaluation of management's overall performance it conveys a broader scope than simply Quality Assurance (QA) department performance.

During the previous assessment period this functional area was evaluated as a category 3. Licensee management had not been effective in addressing recurring SALP concerns. Organization and staffing were considered weak. Licensee management corrective actions in response to Quality Assurance (QA) findings and NRC issues had not been timely or comprehensive. QA department performance and engineering initiatives were considered a strength.

Quality Assurance effectiveness has been assessed on a day-to-day basis. Three inspections focusing on the Quality Assurance and Quality Control (QC) programs were conducted during this period. In addition, the large number of management meetings held during the period provided an opportunity for NRC management to assess licensee management's approach to resolution of issues.

During much of the period licensee senior management continued to assess and correct organizational weaknesses through restructuring and recruitment of experienced personnel, many from outside sources. A new Senior Vice President assumed responsibility for the nuclear organization at the beginning of the period. In June, 1987 the Vice President-Nuclear Operations resigned. That position remained vacant until January, 1988 when the Site Director position was created and filled. Station management was reorganized several times, and significant personnel changes were made. Four individuals served as plant manager during the fifteen month assessment period. In addition to modifying the line organization a temporary Planning and Restart Group was created, working in parallel with the permanent plant staff to provide outage planning oversight. This group was subsequently disbanded, incorporating its functions into the permanent organization. The licensee also replaced several mid-level managers during this assessment period including the Operations Section Manager, Maintenance Section

Manager, Radiological Section Manager and the Security Group Leader. In addition to changes in the line organization several staff assistant positions reporting to the Senior Vice President were established to enhance senior management oversight of organization progress. Although actions in this area were implemented slowly, it was evident that senior licensee management took a careful and deliberate approach to establishing the permanent organization and staff. Licensee management displayed the intent to fill open positions in the organization with the most highly qualified individuals available. This approach may have delayed staffing efforts and initially slowed licensee progress in areas such as maintenance and radiological controls.

Management policies and performance standards were strengthened and are clearly understood through mid-level management. However, the new standards were not concurrently communicated or adopted at the working level in some cases. As a result extensive management involvement in routine activities is still required to assure acceptable performance.

A high level of management involvement and commitment was effective in promoting improvement in several SALP functional areas which had previously been identified as significantly weak. This is particularly evident in the areas of fire protection and security where management acted to establish, staff and support expanded oversight groups. This strong commitment is also evidenced by the organization-wide increases in permanent staff, and the general reduction in reliance on contractors for augmentation of line functions. One exception to this is in the area of maintenance where vacancies and reliance on contractors continues.

Licensee response to new NRC concerns raised during the period was sometimes narrowly focused, and did not target resolution of root causes. For example, a high level of NRC management involvement was required to assure development of a comprehensive Power Ascension Test Program, and to resolve overtime control deficiencies. Needed programmatic improvements in the area of maintenance were only implemented after prompting by the NRC. This may reflect that available licensee resources were focused on areas of previously identified weak performance and on outage completion schedules. In some instances the licensee's written replies to NRC concerns have been vague, incomplete, and did not reflect the full extent of actions which had been taken at the facility.

The licensee initiated several programs designed to upgrade personnel and plant performance. The plant Emergency Operating Procedures (EOP) were upgraded, and extensive EOP and communication training was conducted to enhance operator response capabilities during abnormal and emergency conditions. A fitness-for-duty program was also instituted and applied to all licensee and contractor personnel. In addition, implementation of the Safety Enhancement Program and the station decontamination program improved the plant physical design and condition. The decontamination effort was particularly successful, resulting in increased accessibility to plant areas and a general positive impact on personnel morale.

Licensee management took an active role in establishing long term plans to address identified weaknesses. The Restart Plan, the Material Condition Improvement Action Plan (MCIAP), and the Radiological Action Plan (RAP) are examples. In the case of the MCIAP a team of contractors was created to provide ongoing independent assessment of the plan's effectiveness in improving plant material condition and maintenance practices. In the area of radiological improvements the licensee reinstated the Independent Radiological Oversight Committee to provide senior management with feedback on RAP effectiveness. The licensee also implemented a self assessment process near the close of the period. This self assessment was intended to provide a structured method by which licensee management could evaluate the progress made, and identify remaining weaknesses.

The licensee's Quality Assurance (QA) and Quality Control (QC) department continued to become more involved in station activities. The onsite QA surveillance group was increased in size, and appeared to be actively involved in evaluating field activities. QA audit methodology was revised to enhance its effectiveness, and an aggressive audit schedule was established. The licensee made good use of technical experts during audits to supplement available departmental resources. QA department management took prompt action to focus attention on significant concerns. For example, a stop work order was issued in response to adverse trends and findings in the area of maintenance on environmentally qualified equipment. Corporate and site management response to QA findings has also improved. Both the program controls and their application were strengthened to ensure timely response to QA identified deficiencies. Overdue response to these QA deficiencies are currently tracked as a performance indicator.

Throughout most of the assessment period, the licensee's corrective action process was not always effective. A large number of problem reporting devices exist, each with a unique origination, review and disposition process. This makes use of the corrective action system cumbersome, and weakens accountability for followup and closeout. Lack of clear problem descriptions, and delays between origination and followup, hampers establishment of root cause and implementation of corrective actions. The licensee has reviewed the process and recommendations to facilitate improvements have been made. However, the recommendations were not implemented during this period.

In summary, licensee senior management has taken strong action to develop and staff a viable station organization. High quality personnel have been recruited to fill key management positions. The reorganization and staffing process was not completed until late in the SALP period. As a result, progress in some functional areas, and in forcing management philosophy changes down to the worker and first line supervisor level has been hampered. The continuing need for a high level of management participation in routine activities occasionally prevents managers from focusing on other needed program improvements. Overall, the licensee has been successful in effecting significant performance improvements in many areas. A high level of management involvement is required to ensure that the initiated improvements continue and are sustained.

(2) Conclusion

Rating: 2

Trend: None Assigned

5.0 SUPPORTING DATA AND SUMMARIES

5.1 Investigation and Allegations Review

Twenty allegations were received during this SALP period. Eleven of the allegations were investigated and found either to be unsubstantiated or to be substantiated but of no safety significance. Five allegations were investigated and substantiated, however the licensee had either already instituted appropriate corrective actions or such actions were promptly initiated in each case. Four allegations are currently under review. One of these four concerns the licensee's program for control of overtime which is the subject of ongoing reviews.

One investigation was initiated during the assessment period as a result of an allegation regarding a plant security vital area barrier. This investigation is continuing.

5.2 Escalated Enforcement Action

Confirmatory Action Letter (CAL 86-10) was issued in response to a series of operational events in April, 1986. CAL 86-10 requested submittal of technical evaluations of these events and stated that NRC Regional Administrator approval would be required prior to restart. The technical issues identified in CAL 86-10 have been resolved. The CAL however was extended in August, 1986 and remains open pending resolution of broader management concerns identified in the previous SALPs and subsequent inspection reports.

Three violations were identified during the period for failure of the licensee to ensure the integrity of security vital area barriers. These three violations have yet to be characterized by severity level, and are currently being considered for escalated enforcement action. This action is pending conclusion of the OI investigation described in Section 5.1 above.

An NRC Order issued in 1984 requiring the licensee to implement a Radiation Improvement Program was closed during the period based on the results of a special inspection and other program inspections which indicated that all terms of the Order had been satisfactorily completed.

Request for Action Under 10 CFR 2.206

On August 21, 1987, the Director of the NRC Office of Nuclear Reactor Regulation signed an Interim Director's Decision in response to the July 15, 1986, 2.206 petition filed by Massachusetts State Senator William B. Golden and others. The contentions raised in the petition

regarding containment deficiencies and inadequacies in the radiological emergency response plan were denied. A decision regarding the management deficiencies was deferred to a subsequent response. Three of the petitioners filed an appeal in federal court on October 1, 1987.

On October 15, 1987, Massachusetts Attorney General James M. Shannon filed a 2.206 petition, on behalf of his office and Governor Michael S. Dukakis, requested an order to show cause why Pilgrim should not remain shutdown until a full adjudicatory hearing resolves the issues raised in the petition. The petition cites evidence of continuing managerial, Mark I containment, and emergency planning deficiencies. An interim NRC response was issued on May 27, 1988, just after the end of the SALP period.

5.3 Management Conferences

Periodic management conferences and plant tours were conducted throughout the SALP period. NRC Commissioners toured the plant and met with licensee management on six occasions during the period. A total of nine senior management conferences were held onsite or at Region I. In addition to plant tours held in conjunction with onsite management conferences, senior NRC managers performed two plant inspections during the assessment period. NRC management participated in four public meetings in the vicinity of the plant. Two of these public meetings were sponsored by the NRC and two by local communities. Five meetings with state officials and legislative committees were attended by NRC managers. The NRC also testified before the United States Senate Labor and Human Resources Committee regarding Pilgrim at a public hearing held in Plymouth, MA in January, 1988. A chronological list of NRC management meetings and plant tours conducted during the assessment period is contained in Table 5. In addition, a summary of licensing meetings has been included in section 5.4(1).

To coordinate the planning and execution of NRC activities and to assess the results of these activities a special Pilgrim Restart Assessment Panel was formed. The panel is composed of senior members of the Region I and Headquarters staffs. This panel met bimonthly, with alternate meetings on site.

5.4 Licensing Actions(1) NRR/Licensing Meetings and Site Visits

<u>Date</u>	<u>Subject</u>
May 21, 1987	Licensing Issues, Bethesda, MD
August 4, 1987	Emergency Operating Procedure and Direct Torus Vent
September 24, 1987	Status of Pilgrim Restart/Schedule
August 19-20, 1987	Multi-Plant Action Items
August 24, 1987	Ongoing Fire Protection Reviews
December 10, 1987	Emergency Operating Procedures Upgrade
January 14, 1988	Discussion in Bethesda, MD of the in-service test program development

(2) Commission Briefings

<u>Date</u>	<u>Subject</u>
February 12, 1987	Regional Administrators' Meeting (Pilgrim Included)
December 17, 1987	Briefing on Status of Operating Reactors and fuel facilities (Pilgrim Included)

(3) Schedular Extensions Granted

<u>Subject</u>	<u>Date</u>
Emergency Preparedness (EP) Exercise	12/09/87
Emergency Preparedness (EP) Exercise	05/11/88

(4) Reliefs Granted

<u>Subject</u>	<u>Date</u>
Inservice Inspection Relief	03/26/87

(5) Exemptions Granted

<u>Subject</u>	<u>Date</u>
Duplicate Yard Lighting	10/06/87
10 CFR 50 Appendix R-Operator Action	04/14/88

(6) License Amendments Issued

<u>Amendment No.</u>	<u>Subject</u>	<u>Date</u>
98	New Design-Reactor Control Rod Blades	02/27/87
99	Analog Trip System - Surveillance Requirements	03/03/87
100	Maximum Average Planar Linear Heat Generation Rate	04/09/87
101	Control Room Ventilation System	06/23/87
102	Standby Liquid Control System 10 CFR 50.62 Rule	08/05/87
103	Administrative Changes per 10 CFR 50.4	08/05/87
104	Nuclear Safety Review and Audit Committee changes	8/25/87
105	Cycle 8, Core Reload	08/31/87

(6) License Amendments Issued

<u>Amendment No.</u>	<u>Subject</u>	<u>Date</u>
106	Automatic Depressurization System Timer	09/04/87
107	Analog Trip System - Calibration Frequency	10/28/87
108	Undervoltage Relay Requirements	10/29/87
109	High Pressure Coolant Injection and Reactor Core Isolation Cooling Requirements	10/29/87
110	Rod Block and Average Power Range Monitors Trip Functions	11/30/87
111	Low Pressure Coolant Injection Requirements	11/30/87
112	Standby Gas Treatment & Control Room Air Filter Systems	01/20/88
113	Primary Containment Isolation Values 10 CFR 50 Appendix J Requirements	01/21/88
114	Fire Protection - Appendix R to 10 CFR 50 Requirements	03/08/88
115	Security Requirements - 10 CFR 73.55	03/28/88
116	Modification of Reporting Schedule Supplemental Dose Assessment & Meteorological Summary	05/10/88

(7) Other Licensing Actions

<u>Action</u>	<u>Date</u>
Containment Leak Rate Monitor	02/19/87
10 CFR 50 Appendix J Review (Penetration X-21)	02/19/87
Generic Letter 83-08, Mark I Drywell Vacuum Breakers	02/27/87
Recirculation Flow Anomaly	02/28/87
Process Control Program (PCP) Review	03/03/88
Inservice Inspection Plan - 1986 Refueling Outage	03/16/87
Control Room Floor-Fire Seals	03/24/88
Smoke Seals - Conduit	03/24/88
Defects Westinghouse DC Circuit Breakers	04/13/88
Steam Binding - Pumps	04/15/88
Pilgrim SALP Activity	05/15/87
10 CFR 50 Appendix R Review	05/15/87
NUREG-0737 Item II.K.3.18 ADS Actuation Study	09/04/87
Offsite Dose Calculation Manual	10/28/87
Correct Performance of Operating Activities	11/16/87
Intergranular Stress Corrosion Cracking Augmented Inspection Program	11/25/87
Refueling Interlocks	12/17/87

5.5 Licensee Event Reports

(1) Overall Evaluation

Licensee Event Reports (LER) submitted during the period adequately described all the major aspects of the event, including all component or system failures that contributed to the event and the significant corrective actions taken or planned to prevent recurrence. The reports were thorough, detailed, generally well written and easy to understand. The narrative sections typically included specific details of the event such as valve identification numbers, model numbers, number of operable redundant systems, the date of completion of repairs, etc., to provide a good understanding of the event. The root cause of the event was clearly identified in most cases. Event information was presented in an organized pattern with separate headings and specific information in each section that led to a clear understanding of the event information. Previous similar occurrences were properly referenced in LERs as applicable.

The licensee updated two LERs during the reporting period. The updated LERs provided new information and the portion of the report that was revised was clearly denoted by a vertical line in the right hand margin, so the new information could be easily determined by the reactor.

However, in the past the licensee's threshold for reporting required monitoring. 4 LERs (87-021, 87-022, 87-023, and 87-024) were submitted only after an audit by Region I. One of these LERs, 87-021, was submitted 10 months after the event.

(2) Causal Analysis

A review of the LERs indicates a number of problems, some recurring. In particular, loss of offsite power has been a continuing problem at Pilgrim. In addition, Pilgrim has experienced repetitive events associated with inadequate procedures; administrative control problems associated with failure to conduct adequate reviews prior to maintenance and required surveillances and inadequate guidance and cautions for technicians.

Examples of unclear procedures included LER-87-015 which describes two events where RHR shutdown cooling was terminated by spurious isolation. One isolation was attributed to a procedure with inadequate instructions and cautions on installing jumpers; the other isolation was due to inadequate procedures which failed to describe the right number of jumpers. LER 87-016 describes an unplanned actuation of primary and secondary containment due to inadequate administrative controls for the planned replacement of a relay coil, specifically lack of appropriate precautions and guidance. Furthermore the event was compounded by supervisory error in researching drawings, wiring arrangements and assigning maintenance priorities.

Similarly, repeat problems can be illustrated by the following two LERs. LER-87-018 described a failed coil in a logic relay which caused a Reactor Water Cleanup System isolation. The licensee conducted a technical evaluation of similar coils, identifying those requiring replacement. LER-88-005 describes an actuation of the Primary Containment Isolation Control System and Reactor Building Isolation Control System due to a failure of a similar coil in another relay.

Our assessment of the 39 events in this reporting period indicates:

- 16 involved either administrative control deficiencies, inadequate instructions, or inadequate procedures.
- 7 involved errors by non-licensed personnel.
- As many as 8 may have involved design defects.
- As many as 19 may have been repeats of earlier or similar events at Pilgrim.

(Note: events may be assigned multiple causes)

In conclusion, the large number of events involving deficiencies in administrative controls, inadequate procedures and repeats of earlier, similar events points to the need for close monitoring of the effectiveness of licensee management in these areas.

TABLE 1
TABULAR LISTING OF LERs BY FUNCTIONAL AREA
PILGRIM NUCLEAR POWER STATION

<u>AREA</u>	<u>CAUSE CODE</u>						<u>TOTAL</u>
	<u>A</u>	<u>B</u>	<u>C</u>	<u>D</u>	<u>E</u>	<u>X</u>	
1. Plant Operations	1	-	1	-	-	2	4
2. Radiological Controls	-	-	-	-	-	-	0
3. Maintenance and Modifications	4	-	1	7	6	1	19
4. Surveillance	4	-	-	4	1	1	10
5. Fire Protection	-	-	-	-	-	-	0
6. Emergency Preparedness	-	-	-	-	-	-	0
7. Security and Safeguards	1	-	-	-	-	1	2
8. Engineering and Technical Support	-	4	-	-	-	-	4
9. Licensing Activities	-	-	-	-	-	-	0
10. Training and Qualification Effectiveness	-	-	-	-	-	-	0
11. Assurance of Quality	-	-	-	-	-	-	0
TOTALS	10	4	2	11	7	5	39

Cause Codes: A - Personnel Error
 B - Design, Manufacturing, Construction, or Installation Error
 C - External Cause
 D - Defective Procedure
 E - Component Failure
 X - Other

LERs Reviewed: 87-001-00 to 88-015-00 including 88-008-01 and 87-014-01

TABLE 2

INSPECTION HOURS SUMMARY (02/01/87 - 05/15/88)

PILGRIM NUCLEAR POWER STATION

	<u>Hours</u>	<u>% of Time</u>
1. Plant Operations	2178	22
2. Radiological Controls	1262	13
3. Maintenance and Modifications	2347	24
4. Surveillance	1386	14
5. Fire Protection	493	5
6. Emergency Preparedness	176	2
7. Security and Safeguards	641	7
6. Engineering and Technical Support	1215	13
9. Licensing Activities	*	-
10. Training and Qualification Effectiveness	**	-
11. Assurance of Quality	**	-
Totals	9698	

* Hours expended in facility license activities and operator license activities are not included with direct inspection effort statistics.

** Hours expended in the areas of Training and Assurance of Quality are included in the other functional areas.

Inspection Reports included: 50-293/87-06 to 50-293/88-22

TABLE 3

ENFORCEMENT SUMMARY (02/01/87 - 05/15/88)

PILGRIM NUCLEAR POWER STATION

A. Number and Severity Level of Violations

Severity Level I	0
Severity Level II	0
Severity Level III	0
Severity Level IV	21
Severity Level V	2
Deviation	0
 Total	 26*

B. Violations Vs. Function Area

<u>Functional Areas</u>	<u>Severity Levels</u>						<u>Total</u>
	<u>I</u>	<u>II</u>	<u>III</u>	<u>IV</u>	<u>V</u>	<u>Dev</u>	
1. Plant Operations	-	-	-	2	-	-	2
2. Radiological Controls	-	-	-	8	-	-	8
3. Maintenance and Modification	-	-	-	6	-	-	6
4. Surveillance	-	-	-	1	-	-	1
5. Fire Protection	-	-	-	1	-	-	1
6. Emergency Preparedness	-	-	-	1	-	-	1
7. Security Safeguards	-	-	-	-	-	-	3*
8. Engineering and Technical Support	-	-	-	1	-	-	1
9. Licensing Activities	-	-	-	-	-	-	0
10. Training and Qualification Effectiveness	-	-	-	-	-	-	0
11. Assurance of Quality	-	-	-	1	2	-	3
<hr/> <u>Totals</u>							<u>26*</u>

*Three security violations are being considered for escalated enforcement action and have not yet been categorized for severity.

TABLE 4

Pilgrim SALP History

Functional Area	Assessment Period							
	1/80- 12/80	9/80- 8/81	9/81- 6/82	7/82- 6/83	7/83- 9/84	10/84- 10/85	11/85- 1/87	2/87 5/88
Operations	2	3	3	2	2	3	2	2
Radiological Controls	3	2	2	2	3	3	3	3
Surveillance	2	2	2	1	1	2	3	2
Maintenance	2	3	2	2	1	2	2	2
Emergency Planning	3	1	1	1	3	3	2	2
Fire Protection	2	2	3	1	2	-	3	2
Security	2	2	2	2	2	2	3	2
Engineering and Technical Support	-	-	-	-	-	-	1	1
Licensing	-	-	2	1	1	1	2	2
Training Effectiveness	-	-	-	-	-	-	2	2
Assurance of Quality/QA	3	3	-	-	-	-	3	2
Outage Management	3	2	2	-	1	1	1	-

TABLE 5

MANAGEMENT MEETING AND PLANT TOUR SUMMARY

<u>DATE</u>	<u>SPONSOR</u>	<u>TOPIC</u>
02/02/87	NRC	Management meeting at Plymouth, MA to discuss the status of licensee improvement programs (IR 87-08)
02/03/87	Massachusetts Secretary of Energy	NRC Region I Administrator and other Region I managers met in Boston, MA with several Commonwealth administrators to discuss NRC activities regarding Pilgrim
03/09/87	Massachusetts Legislature	NRC Region I Administrator and other members of the staff appeared in Boston, MA before the Massachusetts Joint Committee on the Investigation and Study of the Pilgrim Station at Plymouth (IR 87-16)
03/10/87	NRC	NRC Chairman Zech toured Pilgrim accompanied by the Regional Administrator and attended a licensee presentation (IR 87-16)
04/27/87	Massachusetts Legislature	NRC Region I Administrator and other members of the staff appeared in Boston before the Massachusetts Joint Committee on the Investigation and Study of the Pilgrim Station in Plymouth (IR 87-18)
05/01/87	NRC	Management meeting at NRC Region I to discuss a surveillance program violation and program weaknesses (IR 87-23)
05/07/87	NRC	1987 SALP management meeting at Plymouth, MA
05/22/87	NRC	NRC Commissioner Carr toured the plant and attended a licensee presentation
05/27/87	Plymouth Board of Selectmen	Four NRC Region I management representatives participated in a public meeting in Plymouth, MA
06/24/87	NRC	NRC Commissioner Asselstine toured the plant and attended a licensee presentation

<u>DATE</u>	<u>SPONSOR</u>	<u>TOPIC</u>
06/29/87	NRC	Management meeting at NRC Region I to discuss the outage status, program improvements and licensee preparations for restart (IR 87-28)
07/23/87	Commonwealth of Mass.	The NRC Section Chief, Licensing Project Manager and Resident Inspectors for Pilgrim met onsite with representatives of the Commonwealth to discuss the NRC inspection process (IR 87-27)
09/09/87	NRC	Enforcement conference at NRC Region I to discuss several security violations (IR 87-30)
09/24/87	NRC	NRC Director of the Office of Nuclear Reactor Regulation, the Region I Administrator and other senior NRC managers met with the licensee in Bethesda, MD to discuss licensee activities and restart readiness (NRR meeting transcript)
09/30/87	NRC	Enforcement conference at NRC Region I to discuss several security violations (IR 87-30)
10/05/87	NRC	NRC Commissioner Bernthal toured the plant and attended a licensee presentation
10/08/87	Commonwealth of Mass.	NRC Region I Administrator and other senior NRC managers met at Region I with representatives of the Commonwealth of Mass. and two private citizens to answer questions regarding the NRC inspection process (IR 87-45)
10/29/87	Duxbury Board of Selectmen	Four NRC Region I and NRR management representatives participated in a public meeting sponsored by the Duxbury Board of Selectmen, Duxbury Emergency Response Plan Committee and the Duxbury Citizens' Committee on Nuclear Matters in Duxbury, MA
12/08/87	NRC	NRC Region I Administrator toured the plant and met briefly with licensee management to discuss tour observations (IR 87-57)

<u>DATE</u>	<u>SPONSOR</u>	<u>TOPIC</u>
01/07/88	United States Senator Kennedy	NRC Director of the Office of Nuclear Reactor Regulation and the Region I Administrator appeared before the Senate Labor and Human Resources Committee regarding Pilgrim. The public hearing was held in Plymouth, Ma.
02/18/88	NRC	NRC Region I and NRR managers conducted a public meeting in Plymouth, MA to solicit public comments on the licensee's Restart Plan
02/24/88	NRC	Management meeting at NRC Region I to discuss the licensee's self assessment process to be used for determining restart readiness (IR 88-10)
03/10/88	NRC	The NRC Director of the Office of NRR and the Region I Administrator toured the plant and interviewed licensee staff regarding the design basis for the direct torus vent modification (IR 88-07)
04/08/88	NRC	Management meeting at NRC Region I to discuss the licensee's proposed power ascension test program (Meeting Minutes 88-43)
04/22/88	NRC	NRC Commissioner Carr toured the plant and attended a licensee presentation (IR 88-12)
05/06/88	NRC	NRC Commissioner Rogers toured the plant and attended a licensee presentation (IR 88-19)
05/11/88	NRC	NRC Region I and NRR managers conducted a public meeting in Plymouth, MA to provide responses to comments and concerns on the licensee's Restart Plan raised during the 2/18/88 public meeting (Meeting transcript)



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406

SEP 07 1988

Docket No. 50-293

Boston Edison Company
ATTN: Mr. Ralph G. Bird
Senior Vice President - Nuclear
Pilgrim Nuclear Power Station
RFD #1, Rocky Hill Road
Plymouth, Massachusetts 02360

Gentlemen:

Subject: NRC Region I Inspection Report No. 50-293/88-21, Integrated
Assessment Team Inspection

This refers to the Integrated Assessment Team Inspection (IATI) led by Mr. A. Randy Blough of this office on August 8-24, 1988, at the Pilgrim Nuclear Power Station (PNPS), Plymouth, Massachusetts. The results of the inspection are documented in the enclosed inspection report. At the conclusion of the inspection, an exit interview was held with you and members of your staff to discuss the scope and the findings of the inspection.

The purpose of this inspection was to perform an independent, in-depth assessment of the readiness of management controls, programs, and personnel to support safe restart and operation of the facility. The inspection Team performed an integrated evaluation of various functional areas, including operations, maintenance, surveillance, radiation protection, security, training, fire protection, and assurance of quality. Within these areas, the inspection consisted of interviews with personnel, observations of plant activities, and selective examinations of procedures, records, and documents by the inspectors.

Within the scope of its review, the Team concluded with high confidence that Boston Edison Company (BECO) management controls, programs, and personnel are generally ready and performing at a level to support safe startup and operation of the facility. Those technical items requiring resolution or completion prior to restart are being addressed and tracked by BECO. The Team identified a relatively small number of additional items for which actions or evaluations appear appropriate; BECO has made commitments in those areas, as detailed in section 2.4 of the enclosed report. As a result of this inspection, the Team concluded that there are currently no fundamental flaws in BECO's management structure, management performance, programs, or program implementation that would inhibit its ability to assure reactor or public safety during plant operation.

~~8509140303~~ 2pp

SEP 07 1988

If your understanding of any item detailed in Section 2.4 of the enclosed report differs from that stated, please contact Mr. Blough or me promptly. The NRC will review the status of these issues prior to any restart of PNPS.

The results of this inspection will be considered during the NRC staff's deliberations as it reaches its decision regarding a PNPS restart recommendation to the NRC Commission.

No written reply to this letter is required. Your cooperation with us is appreciated.

Sincerely,


Samuel J. Collins, Deputy Director
Division of Reactor Projects

Enclosure: NRC Region I Inspection Report No. 50-293/88-21

cc w/encl:

K. Highfill, Station Director
R. Anderson, Plant Manager
J. Keyes, Licensing Division Manager
E. Robinson, Nuclear Information Manager
R. Swanson, Nuclear Engineering Department Manager
The Honorable Edward J. Markey
The Honorable Edward P. Kirby
The Honorable Peter V. Forman
B. McIntyre, Chairman, Department of Public Utilities
Chairman, Plymouth Board of Selectmen
Chairman, Duxbury Board of Selectmen
Plymouth Civil Defense Director
P. Agnes, Assistant Secretary of Public Safety, Commonwealth of Massachusetts
S. Pollard, Massachusetts Secretary of Energy Resources
R. Shimshak, MASSPIRG
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Massachusetts (2)
P. Chan, Commonwealth of Massachusetts
S. Sholly, MHB Technical Associates

U.S. NUCLEAR REGULATORY COMMISSION
REGION I

Docket No.: 50-293
Report No.: 50-293/88-21
Licensee: Boston Edison Company
Pilgrim Nuclear Power Station
RFD #1, Rocky Hill Road
Plymouth, Massachusetts 02360
Facility: Pilgrim Nuclear Power Station
Location: Plymouth, Massachusetts
Dates of Inspection: August 8-24, 1988

Inspectors: (See Attachment E)

Approved By:

Laurance T. Blough

A. Randy Blough, Chief
Reactor Projects Section No. 3B
Division of Reactor Projects

9/7/88
Date

Inspection Summary:

Areas Inspected: Integrated Assessment Team Inspection to assess the degree of readiness of licensee management controls, programs, and personnel to support safe restart and operation of the plant. The scope of the inspection is further detailed in Section 2.2.

Results:

The team concluded that licensee management controls, programs, and personnel are generally ready and performing at a level to support safe startup and operation of the facility. Results are further summarized in Sections 1.0 (Executive Summary) and 2.3 (Summary of Findings).

TABLE OF CONTENTS

	<u>Page</u>
ACRONYMS.....	iv
1.0 EXECUTIVE SUMMARY.....	1
2.0 INTRODUCTION.....	2
2.1 Background.....	2
2.2 Scope of Inspection.....	3
2.3 Summary of IATI Results.....	4
2.3.1 Overall Summary.....	4
2.3.2 Summary of Results by Functional Areas.....	5
2.4 Licensee Commitments.....	9
2.4.1 Procedure Validation and Training.....	9
2.4.2 Identifying Procedure Changes Requiring Training.....	9
2.4.3 Temporary Modifications.....	9
2.4.4 Operations Review Committee.....	10
2.4.5 Maintenance.....	10
2.4.6 Surveillance.....	10
2.4.7 Formalizing Personnel Qualification Reviews.....	11
2.4.8 Mission, Organization and Policy Manual....	11
2.4.9 Familiarizing Workers with Expected Radiological Conditions.....	11
2.4.10 Control Room Human Factors.....	11
3.0 DETAILS OF INSPECTION.....	12
3.1 Management Oversight.....	12
3.1.1 Scope of Review.....	12
3.1.2 Organization.....	12
3.1.3 Staffing.....	15
3.1.4 Qualifications.....	16
3.1.5 Administrative Policy and Procedures.....	18
3.1.6 Communications and Observations.....	19
3.1.7 Conclusions.....	20

Table of Contents (Continued)

	<u>Page</u>
3.2 Operations.....	21
3.2.1 Scope of Review.....	21
3.2.2 Conduct of Operations.....	21
3.2.3 Shift Staffing and Overtime Controls.....	23
3.2.4 Procedure Validation.....	24
3.2.5 Temporary Modification Controls.....	25
3.2.6 Required Reading Books.....	28
3.2.7 Logs.....	29
3.2.8 Timely Update of Lifted Lead/Jumper Log....	29
3.2.9 Tagouts and Operator Aids.....	31
3.2.10 Plant Tours and System Walkdowns.....	31
3.2.11 Conclusions.....	34
3.3 Maintenance.....	36
3.3.1 Scope of Review.....	36
3.3.2 Observations and Findings.....	36
3.3.3 Conclusions.....	50
3.4 Surveillance Testing and Calibration Control.....	52
3.4.1 Scope of Review.....	52
3.4.2 Observations and Findings.....	52
3.4.3 Conclusions.....	61
3.5 Radiation Protection.....	63
3.5.1 Scope of Review.....	63
3.5.2 Observations and Findings.....	63
3.5.3 Conclusions.....	73
3.6 security and Safeguards.....	75
3.6.1 Scope of Review.....	75
3.6.2 Observations and Findings.....	75
3.6.3 Conclusions.....	82

Table of Contents (Continued)

	<u>Page</u>
3.7 Training.....	83
3.7.1 Scope of Review.....	83
3.7.2 Observations and Findings.....	83
3.7.3 Conclusions.....	88
3.8 Fire Protection.....	89
3.8.1 Scope of Review.....	89
3.8.2 Observations and Findings.....	89
3.8.3 Conclusions.....	90
3.9 Engineering Support.....	91
3.9.1 Scope of Review.....	91
3.9.2 Observations and Findings.....	91
3.9.3 Conclusions.....	93
3.10 Safety Assessment/Quality Verification.....	94
3.10.1 Scope of Review.....	94
3.10.2 Nuclear Safety Review and Audit Committee..	94
3.10.3 Operations Review Committee.....	97
3.10.4 Quality Assurance Audit and Surveillance Programs.....	102
3.10.5 Corrective Action Process and Programs.....	104
3.10.6 Conclusions.....	115
4.0 UNRESOLVED ITEMS.....	117
5.0 MANAGEMENT MEETINGS.....	118
Appendix A - Entrance Interview Attendees.....	A-1
Appendix B - Exit Interview Attendees.....	B-1
Appendix C - Persons Contacted.....	C-1
Appendix D - Documents Reviewed.....	D-1
Appendix E - IATI Composition and Structure.....	E-1
Appendix F - Resumes.....	F-1
Appendix G - September 1, 1988 Letter from NRC to Commonwealth of Massachusetts.....	G-1
Appendix H - September 6, 1988 Letter from Commonwealth of Massachusetts to NRC.....	H-1

ACRONYMS

ALARA	-	As Low As Reasonably Achievable
ANSI	-	American National Standards Institute
ASME	-	American Society for Mechanical Engineers
BECO	-	Boston Edison Company
BEQAM	-	Boston Edison Quality Assurance Manual
CAS	-	Central Alarm Station
CQI	-	Commercial Quality Item
CS	-	Core Spray (System)
CST	-	Condensate Storage Tank
DC	-	Direct Current
DCRDR	-	Detailed Control Room Design Review
DG	-	Diesel Generator
DR	-	Deficiency Reports
EOP	-	Emergency Operating Procedures
EO	-	Equipment Operator
EPRI	-	Electric Power Research Institute
EQ	-	Environmental Qualification
ESF	-	Engineered Safety Feature
ESR	-	Engineering Service Request
F&MR	-	Failure and Malfunction Reports
FYI	-	For Your Information
GET	-	General Employee Training

Acronyms

HP	-	Health Physics
HPES	-	Human Performance Evaluation System
HSA	-	Housekeeping Service Assistance
IATI	-	Integrated Assessment Team Inspection
I&C	-	Instrumentation and Control
ICA	-	Immediate Corrective Actions
INPO	-	Institute of Nuclear Power Operations
IST	-	In-Service Testing
LCO	-	Limiting Condition for Operations
LL/J	-	Lifted Lead/Jumper
LSFT	-	Logic System Functional Test
M&TE	-	Measuring and Test Equipment
MCAR	-	Management Corrective Action Requests
MCIAP	-	Material Condition Improvement Action Plan
MO&AT	-	Management Oversight and Assessment Team
MOP	-	Mission, Organization and Policy Manual
MPC	-	Maximum Permitted Concentration
MR	-	Maintenance Request
MSC	-	Maintenance Summary and Control
MSTP	-	Master Surveillance Tracking Program
MWP	-	Maintenance Work Plan
NCR	-	Nonconformance Report
NED	-	Nuclear Engineering Department
NOP	-	Nuclear Organization Procedures

Acronyms

NRC	-	Nuclear Regulatory Commission
NRR	-	Office of Nuclear Reactor Regulation
NSRAC	-	Nuclear Safety Review and Audit Committee
NWE	-	Nuclear Watch Engineer
OMG	-	Outage Management Group
ORC	-	Operations Review Committee
P&ID	-	Piping and Instrument Diagram
PCAQ	-	Potential Condition Adverse to Quality
PDC	-	Plant Design Change
PI	-	Pressure Indicator
PM	-	Preventive Maintenance
PNPS	-	Pilgrim Nuclear Power Station
PCIS	-	Primary Containment Isolation System
QAD	-	Quality Assurance Department
RCIC	-	Reactor Core Isolation Cooling
RETS	-	Radiological Environmental Technical Specifications
RHR	-	Residual Heat Removal (System)
RO	-	Reactor Operator
ROR	-	Radiological Occurrence Report
RP	-	Radiation Protection
RWP	-	Radiation Work Permits
SAA	-	Simulated Automatic Actuation
SAS	-	Secondary Alarm Station

Acronyms

SBLC	-	Standby Liquid Control (System)
SDR	-	Security Deficiency Reports
SE	-	Safety Evaluations
SEG	-	Systems Engineering Group
SES	-	Senior Executive Service
SFR	-	Supplier Finder Reports
SGI	-	Safeguards Information
SI	-	Station Instruction
SRO	-	Senior Reactor Operator
STA	-	Shift Technical Advisor
SVP-N	-	Senior Vice President - Nuclear
TM	-	Temporary Modification
TS	-	Technical Specifications
VP-NE	-	Vice President - Nuclear Engineering
WIP	-	Workforce Information Program
WPRT	-	Work Prioritization Review Team

1.0 EXECUTIVE SUMMARY

In response to NRC concerns over longstanding issues regarding the management effectiveness of the Boston Edison Company (BECo) in the operation of the Pilgrim facility, the licensee agreed to maintain the plant in a shutdown condition following operational events which occurred on April 11-12, 1986. The NRC confirmed the licensee's agreement in Confirmatory Action Letter (CAL) 86-10. The CAL, as supplemented in an August 27, 1986 letter, also confirmed that the licensee would develop a comprehensive plan to address those concerns and perform an in-depth self-assessment of the effectiveness of that Plan. On June 25, 1988, the licensee reported it had completed these activities to the extent that an NRC review was appropriate. In order to assess the status and results of BECo's corrective actions, the NRC performed an independent review of the effectiveness of the licensee's management controls, programs and personnel during an Integrated Assessment Team Inspection (IATI) conducted August 8-24, 1988.

The Team consisted of an SES-level manager, a Team leader, and members of the NRC Region I and Headquarters staff. The inspection team also included two observers representing and appointed by the Commonwealth of Massachusetts. These observers had access and input to all aspects of the inspection as provided by the established protocol. The areas reviewed during the inspection included operations, maintenance, surveillance, radiation protection, security, training, fire protection and assurance of quality. The Team reported directly to the Regional Administrator of Region I.

Overall, the Team concluded with high confidence that BECo management controls, programs, and personnel were generally ready and performing at a level to support safe startup and operation of the Pilgrim Nuclear Power Station. Further, although the Team identified certain items which require licensee actions or evaluations, there were no fundamental flaws found in the licensee's management structure, management performance, programs, or program implementation that would inhibit its ability to assure reactor or public safety during plant operation.

2.0 INTRODUCTION

This report details the findings, conclusions and observations of NRC's Integrated Assessment Team Inspection conducted at the Pilgrim Nuclear Power Station (PNPS) on August 8-24, 1988. The results of this inspection are to be considered during NRC staff's deliberations as it reaches its decision regarding a restart recommendation to the NRC Commissioners.

2.1 Background

The NRC's 1985 Systematic Assessment of Licensee Performance (SALP) found programmatic weaknesses in several functional areas at the Pilgrim Nuclear Power Station and noted that, historically, the licensee could not sustain performance improvements once achieved. A special NRC Region I diagnostic team inspection was subsequently performed in February and March 1986 to evaluate facility performance. This inspection, which included monitoring plant activities on a 24-hour basis, confirmed the 1985 SALP and concluded that poor management control and incomplete staffing contributed to the poor performance.

Following several operational events, Boston Edison Company (BECO) shutdown PNPS on April 11-12, 1986. The NRC subsequently issued a Confirmatory Action Letter (CAL) on April 12, 1986, and a supplement on August 27, 1986, maintaining the plant shutdown and requiring that the licensee obtain NRC approval prior to restart. The central issues in the CAL, as supplemented, involved the effectiveness of licensee management of the facility and technical concerns.

SALP evaluations continued during the shutdown, and improvements were noted during the 1986 SALP period, although the rate of change was slow. Several factors inhibited progress, including continued management changes and prolonged staffing vacancies. Good performance was noted in four areas: emergency planning, outage management, corporate engineering support and licensed operator training. The success in these areas reflected a high level of corporate management attention and substantial resource commitments. The licensee also had made significant plant hardware improvements, including Mark I Containment performance enhancements.

Consistent with the CAL and its supplement, BECO has addressed the specific technical issues, developed and submitted the Pilgrim Nuclear Power Station Restart Plan and performed a detailed self-assessment of readiness for restart. The NRC staff reviews of these items are complete. The licensee has also submitted a Power Ascension Test Program, for which the staff review is ongoing.

NRC subsequently completed a SALP evaluation for Pilgrim covering the period February 1, 1987 to May 15, 1988. It concluded that licensee management initiatives are generally successful in correcting staffing, organization, and material deficiencies. Programmatic performance improvements were evident in areas previously identified as having significant weakness and in areas that the licensee's self-assessment process identified as warranting further management attention.

The NRC Confirmatory Action Letter (CAL) of April 1986 required the NRC to perform a review to assess BECo's corrective actions. In conjunction with an augmented inspection program and as part of a continuing effort to monitor BECo's program improvements, the NRC planned this IATI to independently measure the effectiveness and readiness of the licensee's management controls, programs and personnel to support safe restart of the facility. A Restart Readiness Assessment Report that includes staff assessment results will be prepared by the NRC in conjunction with development of an NRC staff recommendation regarding plant restart.

2.2 Scope of Inspection

The IAT inspection was performed to provide an independent, in-depth assessment of the degree of readiness of licensee management controls, programs, and personnel to support safe restart and operation of the Pilgrim Nuclear Power Station (PNPS). The inspection covered a variety of functional areas, including operations, maintenance, surveillance, radiation protection, security, training, fire protection, and assurance of quality. Particular emphasis was placed on management effectiveness and on the status of the licensee's recent program improvements in maintenance. The inspection consisted of interviews with licensee personnel, plant tours, observations of plant activities, and selective examinations of procedures, records, and documents. The Team also directly observed ongoing plant activities on all shifts from August 10-13, 1988.

The 15-member Team consisted of a senior manager, inspection team leader, five shift inspectors, and several specialist inspectors from both NRC Region I and the NRC Office of Nuclear Reactor Regulation (NRR). Two representatives from the Commonwealth of Massachusetts were also on the Team as observers throughout the inspection. The team roster and member resumes are attached as Appendices E and F to this report.

Onsite IATI preparation, which included site familiarization and plant tours, was conducted during the week of July 18, 1988. The Team was onsite full-time from August 8 through 19, 1988. Some IATI members were on site during the documentation period of August 20-24, 1988. Attendees at the entrance and exit interviews are listed in Appendices A and B, respectively. Senior licensee managers contacted during the course of the inspection are listed in Appendix C. Many other persons at all levels of the organization were also contacted or interviewed.

The licensee was not presented with any written material by the NRC during this inspection. The licensee indicated that no proprietary material was presented for review during this inspection.

2.3 Summary of IATI Results

2.3.1 Overall Summary

The Team concluded, with high confidence, that licensee management controls, programs, and personnel are generally ready and performing at a level to support safe startup and operation of the facility. Technical items requiring resolution or completion prior to restart are being addressed and tracked by the licensee. The Team identified a relatively small number of additional items for which licensee actions or evaluations appear appropriate; during the inspection, the licensee made acceptable commitments in these areas. There are currently no fundamental flaws in the licensee's management structure, management performance, programs, or program implementation that would inhibit its ability to assure reactor or public safety during plant operation.

The inspection generally confirmed the results of the SALP report for February 1, 1987 through May 15, 1988, as well as validating the general SALP conclusion that performance was improving at the end of the SALP period. Further, licensee performance appeared to be consistent or improving in all functional areas examined during the IATI, with the current level of achievement for overall safety performance equal to or better than that described in the SALP. For maintenance and radiation protection, the performance is noticeably improved.

The inspection generally confirmed the effectiveness of various licensee self-improvement programs and of the licensee's self-assessment process. The Team identified relatively few issues that had not been previously identified by the licensee. In the interest of continually improving its self-assessment process, the licensee should evaluate those cases where NRC either identified new issues or assigned a higher sense of priority than identified by the licensee.

The inspection confirmed that important organization and attitudinal changes had occurred since 1986. Of particular concern to NRC during the diagnostic inspection in 1986 were several factors inhibiting progress. These included:

- 1) Incomplete staffing, especially of operators and key mid-level supervisory personnel;
- 2) The prevailing licensee view that improvements to date had corrected the problems identified;
- 3) Reluctance by licensee management to acknowledge some problems identified by NRC; and
- 4) Dependence on third parties to identify problems rather than implementing an effective licensee program to identify weaknesses.

The Team found these inhibitors to be substantially removed, and noted that a significantly improved nuclear safety ethic exists at management levels and is developing successfully at the worker level.

Based on a review of the management structure, staffing, goals, policies and administrative controls, the Team concluded that the licensee has an acceptable organization and administrative process, with adequate management and technical resources to assure that the plant can be operated in a safe and reliable manner during normal and abnormal conditions. Further, this performance-based inspection provided an integrated look at overall management effectiveness in ensuring high standards of nuclear safety. The overall conclusions of this inspection confirm facility management effectiveness, especially its ability to perform self-assessment functions, to improve performance, and to raise nuclear safety awareness and attitudes throughout the organization.

2.3.2 Summary of Results by Functional Area

Within each functional area, conclusions were reached including the identification of various strengths and weaknesses. These are summarized below. The basis for these items, as well as the many significant observations made by the Team, are explained in Section 3 of this report.

2.3.2.1 Operations

Strengths

- Experienced and knowledgeable senior licensed operators

- Effective shift turnover
- Excellent plant housekeeping

Weakness

- Lack of thoroughness and attention to detail in validation and training of Emergency Operating satellite procedures

2.3.2.2 Fire Protection

Strengths

- Effective program staffing and supervision
- Effective prioritization, control, and tracking of fire protection equipment maintenance

Weaknesses

None

2.3.2.3 Maintenance

Strengths

- Good organization and structure
- Thorough program procedures
- Clear maintenance section internal communications and interactions
- Good control and support of field activities

Weaknesses

- Examples of poor implementation of planning for post-work testing
- Poorly controlled storage of Q-listed items at two locations outside the warehouse

2.3.2.4 Radiological Controls

Strengths

- Effective use of a maintenance health physics (HP) advisor
- A well-organized training program

Weaknesses

- Examples of a lack of continuity and proficiency in certain highly specialized jobs because of frequent technician rotation
- Indications of weak vertical communications within the HP group

2.3.2.5 Surveillance

Strength

- Management commitment to improve an already satisfactory program

Weakness

- Incomplete resolution of proper frequency and scheduling of once-per-refueling outage tests

2.3.2.6 Security

Strength

- Overall management attention

Weaknesses

None

2.3.2.7 Training

Strengths

- Excellent management support for operator training programs

- Strong relations between the plant operations and training departments

Weakness

- Lack of a defined process to assure timely identification and implementation of training needs resulting from newly approved or revised procedures

2.3.2.8 Engineering Support

- Not directly reviewed. No specific strengths or weaknesses identified

2.3.2.9 Safety Assessment/Quality Verification

Strengths

- Nuclear Safety Review and Audit Committee (NSRAC) composition, plant tour program, frequency and location of meetings, open forum, and focus of reviews
- Attitude and performance toward identifying problems
- Effective, meaningful communications between the Quality Assurance and plant Operations departments

Weaknesses

- Operations Review Committee does not perform an effective independent group review of operations and Technical Specification violations
- Multiplicity of corrective action programs without centralized tracking
- Poor tracking of Potential Condition Adverse to Quality (PCAQ) reports

2.3.2.10 Management Oversight

Strengths

- Well-defined organization, incorporating appropriate span-of-control and including highly qualified, experienced managers in key positions
- Well-defined and well-conceived corporate goals

Weaknesses

None

2.4 Licensee Commitments

During the IAT inspection, the licensee made certain commitments to the inspection Team. These commitments relate to licensee corrective or enhancement actions planned in response to Team findings or concerns. These commitments, summarized below, are discussed in more detail in subsequent sections of this report, shown in parentheses. Commitments were confirmed during the exit interview. The status of these issues will be reviewed by the NRC prior to any restart of the plant (88-21-01).

2.4.1 Procedure Validation and Training (Section 3.2.4)

By restart, the licensee will confirm effective implementation of all off-normal and EOP satellite procedures that have been substantively revised during this outage.

2.4.2 Identifying Procedure Changes Requiring Training (Section 3.7.2.1)

Before restart, the licensee will implement a process to allow more timely identification of new procedures and procedure changes which require training.

2.4.3 Temporary Modifications (Section 3.2.5)

- By restart, the licensee will either prepare a justification for operation for each active temporary modification or apply the temporary modification extension request process to all temporary modifications, including those with outstanding engineering service requests.

2.4.4 Operations Review Committee (ORC) (Section 3.10.3)

Prior to restart, in order to strengthen its operational focus, the ORC will begin to: (1) review plant incident critiques; (2) review licensee event reports before their issuance to NRC; (3) review failure and malfunction reports on a regular basis; and, (4) provide for a monthly presentation and discussion of plant operations as a specific agenda item.

2.4.5 Maintenance

- Before restart, the licensee will re-evaluate all priority 3 maintenance requests to ensure that they have been properly scheduled. (Section 3.3.2.4)
- The licensee will complete training addressing the revised post-work testing program by September 9, 1988. (Section 3.3.2.6)
- The licensee will resolve the inability to align valves in the Torus Water Makeup Line in accordance with current operating procedures and drawings prior to restart. (Section 3.3.2.4)
- The licensee will issue a procedure to provide appropriate controls for the "Q" oil storage facility by September 7, 1988, and perform an evaluation of the possible addition of "non-Q" oil to "Q" equipment and its potential effect. (Section 3.3.2.3)
- The licensee will complete, before restart, the disposition of a Potential Condition Adverse to Quality (PCAQ) identifying the need for a review of Commercial Quality Item procurement documents for consistency with approved engineering specifications. (Section 3.3.2.3)

2.4.6 Surveillance

- Before restart, the licensee will review and evaluate the once-per-refueling-outage surveillance tests to determine if they should be repeated to enhance the assurance of system operability and document the basis for its decision. (Section 3.4.2.1)
- Before restart, the licensee will provide the technical basis for the current test frequency of the Reactor Core Isolation Cooling (RCIC) System Logic System Functional Test (LSFT) on the initiation logic. (Section 3.4.2.2)

2.4.7 Formalizing Personnel Qualification Reviews

The licensee will verify before restart the qualifications of all personnel within the organization required to meet ANSI 18.1-1971; and, prior to completion of the power ascension program, will have a formalized process in-place to ensure future auditability. (Section 3.1.4)

2.4.8 Mission, Organization and Policy (MOP) Manual

The licensee will issue MOP policy instructions prior to restart and the organizational position descriptions prior to completion of power ascension. (Section 3.1.5)

2.4.9 Familiarizing Workers with Expected Radiological Conditions

Before restart, the licensee will provide training and briefings to the appropriate plant staff regarding expected radiological conditions resulting from plant operation and hydrogen addition. (Section 3.5.2.14)

2.4.10 Control Room Human Factors

The licensee will evaluate control room human factors during the power ascension program and include an update regarding the schedule and scope of "Paint, Label and Tape" items in their report to the NRC at the completion of the Power Ascension Program. (Section 3.9.2)

3.0 DETAILS OF INSPECTION

The following sections contain the scope of inspection, the detailed findings, and the conclusions for each functional area the Team assessed.

3.1 Management Oversight

3.1.1 Scope of Review

The IATI assessed the organizational structure currently in place at the Pilgrim Nuclear Power Station (PNPS). The assessment also included the administrative processes in place to control and coordinate the activities and actions affecting safe and reliable operation of the PNPS. Other areas inspected included the adequacy of staffing, qualifications of personnel, and mechanisms to enhance and promote stability in the organization's technical and managerial staff.

Several management meetings were observed by Team members to assess the interactions of managers and the effectiveness of the policies and procedures being implemented. Continual observations were made and shared by Team members to augment findings and conclusions in the effectiveness of the organization, management controls, and communications throughout the functional areas. The Team members interviewed a cross-section of personnel at all levels of the organization to determine if the overall attitude toward performance of safety-related activities has improved. These observations and interviews also provided the Team with insight into the worker perception of management policies, involvement, effectiveness and its resulting impact on safety.

3.1.2 Organization

The NRC staff noted in the most recent SALP report No. 50-293/87-99 for February 1, 1987 through May 15, 1988, that an organizational transition had taken place. The report also noted that several temporary changes, including numerous changes in personnel, had been made to strengthen planning, control and performance at PNPS. Many of these temporary changes were incorporated into a permanent reorganization in February 1988. The licensee continued to refine the new organization and control process through

July 1988, notified NRC of the reorganization, and subsequently requested an amendment in August 1988 to the administrative section of its Technical Specifications (TS) to reflect the new organization. The notification and request were in accordance with the PNPS TS, Section 6.2.C, "Changes to the Organization," which allows organizational changes to be implemented without prior NRC approval, provided notification is made and a subsequent license amendment request is submitted for NRC review and approval.

The organization assessed during this inspection is the subject of the licensee's amendment request dated August 1, 1988, and approved by the Senior Vice President - Nuclear (SVP-N) on August 4, 1988. The discussion that follows does not describe in complete detail the entire organization, focusing instead on that portion that affects the functional areas being evaluated during this inspection (See Figure 1). The results of this inspection will be considered in NRC's review of the licensee's amendment request.

The Team noted that the licensee has incorporated a balance between the number of management levels from the first-line supervisors to the SVP-N and the span of control for each functional unit. The SVP-N has the Station Director, Vice President - Nuclear Engineering (VP-NE), Emergency Preparedness Department manager and Quality Assurance Department manager reporting directly to him. The two department managers report directly to the SVP-N to assure that independence and appropriate management attention are provided based on their functional requirements and responsibilities.

The committee charged with offsite safety, the Nuclear Safety Review and Audit Committee (NSRAC), reports directly to the SVP-N. The committee for onsite safety review, the Operations Review Committee (ORC), reports directly to the Station Director. The reporting of the offsite committee to the SVP-N and the onsite committee to the Station Director are appropriate based on their responsibilities. Details on these standing committees, their functional requirements, responsibilities and accountabilities, are contained in Section 3.10 of this report.

The VP-NE has two department-level managers reporting directly to him. These departments are the Nuclear Engineering Department and the Management Services Department both of which are located offsite. The Station Director has four department-level managers reporting directly to him: the Plant Support Department, Plant Manager (Operations), Planning and Outage Department, and the Nuclear Training Department.




Figure 1. BOSTON EDISON COMPANY - PILGRIM ORGANIZATION

The senior manager of the functional areas is at the department level, which is then subdivided into section levels and division levels. The first-line supervisors, in some cases senior supervisors, report to the division managers.

The station organization, now under a Station Director who has no direct corporate (i.e., off-site) responsibilities, represents a substantial change from previous organizations. The current structure was instituted to strengthen management attention to plant activities. The narrowing of the span of direct control and responsibility of the Plant Manager allows a more focused management and control of operational activities, which should result in the enhancement of safe and reliable operation. The departments reporting to the VP-NE have been restructured for an even distribution of responsibilities.

The Team concluded that the current organizational structure provides for an appropriate distribution (span) of responsibilities and accountabilities for the activities being performed by the functional units within it. The depth (number) of managers in the functional areas should contribute to improved performance and organizational stability by providing managers with increased opportunities to participate in professional technical and management development programs and by increasing the framework for career growth.

The Team also concluded that the redistribution of functional responsibilities and increased depth in management provides the framework necessary to enhance stability and support safe and reliable operation at PNPS. The evidence for these changes thus far has been management's effectiveness in creating a much-improved nuclear safety ethic and in improving the functional areas described in the subsequent sections of this report.

3.1.3 Staffing

The most recent S&LP Report (No. 50-293/87-99) indicated that the allocated staffing levels were significantly higher than in the past. The Nuclear Organization is currently authorized a staffing level of 985. Approximately 90% of the authorized positions are filled, of which 86% are licensee personnel; the remaining 4% comprise contract personnel. Licensee personnel fill all key positions from Section Managers and above, with less than 13% of the remaining managers and first-line supervisor positions filled by contractors or licensee personnel in acting capacities.

Increased staffing in all levels of the Radiological and Maintenance Sections are examples of how the licensee has provided the necessary management attention and resources to areas that need them. The increased staffing, specifically at the craft and technician level, appears sufficient to allow for a planned and controlled preventive maintenance program that should result in overall safety enhancement. The increased staffing levels also allow for training on a routine schedule.

The Team concluded that the authorized staffing has been filled to a level acceptable for the licensee to perform all the necessary functions for all plant conditions, including operations. This finding is reinforced by the evidence of improvements in the functional areas described in the subsequent portions of this report.

3.1.4 Qualifications

The PNPS TS, Section 6.3, "Facility Staff Qualifications," requires that PNPS personnel meet the requirements of the American National Standards Institute (ANSI) N18.1-1971, "Selection and Training of Personnel for Nuclear Power Plants." The TS also requires that the Radiation Protection Manager shall meet or exceed the qualifications of Regulatory Guide 1.8, "Qualification and Training for Personnel at Nuclear Power Plants," September 1975.

The Team audited resumes and position descriptions of key managers and other selected personnel throughout the organization. Their educational and experience backgrounds were compared with the requirements delineated in ANSI N18.1-1971, with special attention on the management experience of key personnel. No deficiencies were identified relating to the qualification requirements of the ANSI standard. More significantly, the Team noted the staffing of key management positions with personnel having extensive and successful management experience.

During its review, the Team found that some resumes needed updating, and that no formal, detailed instructions or guidance in establishing qualifications were available. The Team reviewed a Quality Assurance Department (QAD) audit report of the organization's administrative controls which was conducted June 22 through July 22, 1988 and which resulted in similar findings. The report, Audit Report 88-25, "Administrative Controls," dated August 18, 1988,

indicated that personnel qualifications were audited by the QAD to determine compliance with the ANSI N18.1 requirements for the organizational positions held. No deficiencies were identified as the result of the QAD audit. The report did, however, provide a recommendation consistent with the NRC inspector's finding. Specifically, Recommendation No. 88-25-03, notes the need to update resumes, develop guidelines and procedures for documenting qualification status, and maintain retrievable files.

The licensee has committed to the Team to reverify the qualifications of all personnel within the organization to confirm they comply with ANSI N18.1-1971 prior to restart and to have a process in place prior to completion of the Power Ascension Program to ensure future auditability of personnel qualifications.

Within the scope of the NRC review, the Team determined that the licensee's personnel are generally well qualified for the positions held within the organization. The licensee's commitment to reverification of all personnel qualifications prior to restart will provide additional assurance of full compliance relating to personnel qualifications.

The results of the IATI effort in assessing the adequacy of the staffing and qualifications of the PNPS organization is consistent with the overall facility evaluation in the most recent SALP report (No. 50-293/87-99). It noted the addition of management personnel who lack extensive commercial nuclear power plant operating experience. However, as noted above, recent changes have resulted in the addition of personnel in key management positions with extensive and successful management experience, much of which is in nuclear areas. Also, many mid-level management positions are held by individuals who have extensive Pilgrim NPS (or other boiling water reactor) experience. The Team concluded that the combination of commercial nuclear power plant operating experience in the organization with the increased management capability provides the qualifications necessary to support safe and reliable operation at PNPS. In the event of a restart authorization, licensee safety performance will be closely monitored by the NRC during the Power Ascension Program.

3.1.5 Administrative Policy and Procedures

The licensee has a variety of procedures to provide policy, control and coordination of organization activities. Corporate policy is provided in the form of company Bulletins maintained in a Boston Edison Company Organizational Manual. The manual includes information about the corporate organization, its policy statements, corporate instructions, and committees which affect the entire company, including the Nuclear Organization. The corporate level policy specifically affecting the Nuclear Organization is contained in a Mission, Organization and Policy (MOP) manual.

The Nuclear Organization Procedures (NOPs) provide guidance for the control and coordination of the Nuclear Organization. They include administrative procedures affecting the entire organization, as well as procedures affecting functional portions of the organization. Each department also has procedures in place specifically for its functional areas. The Team reviewed several NOPs to assure that the guidance provided was current, reflected the organization in place, and addressed coordinating activities within the organization. The Team also reviewed department-level procedures to assure they included the current organization, goals, department function, position descriptions, qualifications required, responsibilities, and accountabilities.

The Team concluded that the procedures are, for the most part, current. They adequately identify corporate policy, organization, coordination, functional requirements, responsibilities, accountabilities, and qualifications necessary for the control and coordination of actions within the organization.

The Mission, Organization and Policy Manual (MOP) is not fully up to date; however, and is currently being revised to accurately reflect current policy and to include all the position descriptions within the organization. The licensee has identified additional refinements in the organizational position descriptions to assure consistency and to provide accurate definitions of responsibilities necessary to assure accountability. The licensee was previously aware of this and has been working to finalize the updates. The licensee committed to issue the revised MOP which

includes updated policy prior to restart and to complete the organizational position description refinements before the end of the Power Ascension Program. This commitment is acceptable, based on the status of the other procedures previously discussed which assure adequate administrative controls.

3.1.6 Communications and Observations

Corporate policy for the Nuclear Organization in the MOP manual includes, among its goals, the need to strive to raise standards of performance, for dedication to protecting the environment and public, and for rigorous adherence to procedures. The Team, through its observations and interviews, noted a positive change in the attitude toward nuclear safety throughout PNPS. This change is evident in improved performance of safety-related activities. These improvements are indicated in the most recent SALP Report (No. 50-293/87-99), and progress in the other functional areas is addressed in this inspection report. The Team also noted during interviews that the corporate goal of adherence to procedures has been conveyed to all levels of the organization. These observations attest to management's effectiveness in communicating corporate goals and management's oversight in assuring that the goals are being pursued.

The Team noted that the licensee established several mechanisms to assure adequate communications within the organization. Meetings at all levels of the organization are held on a routine basis. Plant meetings are held every morning to discuss plant status and to coordinate daily activities. Several of these meetings were observed by the Team to assess the interaction of the managers and the resulting effectiveness. The Team concluded that the meetings were effective and that safety-related activities are being planned, scheduled, and prioritized in accordance with their safety significance and plant status. These and other observations by the Team indicate that teamwork at the site is evident. There are programs in place, such as the Workforce Information Program (WIP), For Your Information (FYI), and Management Oversight and Assessment Team (MO&AT) to enhance management involvement, overall communications, and management visibility in the plant.

The licensee has also established a set of performance indicators to track performance issues, restart issues, plant condition reports, and activity status. These performance indicators are used as a management tool to measure the effectiveness and results of established programs.

The Team concluded, based on its evaluation of programs in-place, that communications throughout the organization have improved, that teamwork is evident, and that corporate goals are being conveyed to all levels of the organization.

3.1.7 Conclusions

The Team concluded that the licensee has an acceptable organization and administrative process in place with adequate management and technical resources to assure that PNPS can operate in a safe and reliable manner during normal and abnormal conditions. This conclusion is based on the details discussed above, the performance-based inspection in the functional areas covered by the IATI, the overall consistency in the findings of this inspection with the most recent SALP (No. 50-293/87-99), and the plan for a structured and controlled power ascension program prior to operation.

This performance-based inspection of a wide range of functional areas provides an integrated look at overall management effectiveness in ensuring high standards of nuclear safety. The overall conclusions of this inspection confirm facility management effectiveness, especially with respect to management's ability to perform self-assessment functions, to make performance improvements, and to raise nuclear safety awareness and attitudes within the organization.

3.2 Operations

3.2.1 Scope of Review

The Team evaluated operations by observing how supervisors, operators and staff performed in the control room and throughout the plant. The Team observed plant operations during backshifts from August 10 through August 13, 1988, and reviewed staffing levels to determine if they were sufficient to support restart with minimal reliance on overtime. The ability to implement recently written EOP satellite procedures and the quality of these procedures were evaluated through a field walkdown of a procedure. The implementation of administrative controls for operations was evaluated through inspections of overtime controls, temporary modification controls, operator-required reading, logkeeping, tagouts, and operator aids. The line-up of two safety systems was independently verified by the inspectors. Housekeeping was observed during frequent plant tours.

3.2.2 Conduct of Operations

The Team observed control room operations on all shifts. They were conducted in a formal manner, with effective communications between the operators and supervisors, including repeat backs for certain functions. There was no unnecessary traffic in the control room. Supervisors briefed shift personnel on significant functions before they occurred. Prior to energizing the recirculating pump heaters, which could have produced smoke in the drywell, the watch engineer thoroughly briefed to the reactor operator, equipment operator, and fire brigade leader.

The watch engineers, shift supervisors, and reactor operators were knowledgeable about plant conditions and ongoing work in the plant. Shift turnover briefings were thorough and were followed by control room panel walkdowns. Attendance at these briefings was inconsistent in that not all watch engineers include other shift personnel, such as health physics shift workers in the pre-shift briefing. The Team observed that the health physics shift workers receive separate briefings. The Team discussed this practice with plant management, which stated that it was their intent to include non-operations shift workers in the pre-shift briefing and that they would review its implementation.

Control room operators received good support from the shift technical advisors (STA), administrative assistants, and other departments. The STA's were used in developing failure and malfunction reports (F&MR), and in the initial followup of an EOP satellite procedure issue. The administrative assistants do much of the administrative paperwork and help to lessen traffic in the control room. There was very good support of operations from other departments in understanding and deciding the proper course of action in response to F&MR events.

The Team accompanied several non-licensed equipment operators (EO's) on their tours. The EO's performed their plant tours in accordance with Procedure 2.1.16, "Nuclear Power Operator Tour." Readings were taken and recorded, as required. The operators also checked for abnormal conditions, such as vibrations, noise, leakage, odors, and inadequate ventilation. The EO's commented that they now have more time to check general plant conditions on their rounds because the rounds are assigned to two EO's per shift. Previously, only one EO made the plant tour. The EO's showed good regard for radiological protection and ALARA practices. The operators were very familiar with the plant systems, and components, and were knowledgeable about their duties and responsibilities. The performance by these operators demonstrated the effectiveness of the non-licensed training program.

Watch engineers or operating supervisors accompany EO's on plant tours at least once per week. Operations management, including the chief operating engineer and operations manager, were observed touring the control room frequently and discussing plant status and evolutions with the watch engineer.

The Team discussed the licensee's use of NRC's NUREG-1275, "Operating Experience Feedback Report-New Plants" and verified that licensee management had reviewed NUREG-1275 recommendations for applicability. BECo had independently initiated a number of improvements related to NUREG-1275 recommendations before they reviewed the report. This action was considered by the Team as a positive example of the quality of BECo self-improvement efforts. Some self-identified improvement items include operator communications training, seminars to improve attention to detail, splitting tours and revising tour sheets to improve equipment operator performance, and doing dry run training on

the power ascension and alternate safe shutdown evolutions. Some improvement items resulting from the NUREG review include seeking a more positive method of performing on-shift instructions, repeating all logic system functional tests, and performing a comprehensive review of inadvertent emergency safety feature (ESF) actuations. The ESF actuation review has resulted in several corrective actions.

In summary, the licensee conducted operations in a professional manner. Operators are knowledgeable about their duties and plant conditions and management keeps an active and effective oversight of operations.

3.2.3 Shift Staffing and Overtime Controls

The licensee's Senior Reactor Operators (SRO) are very experienced and strengthen the operations organization. To take advantage of this experience, an extra SRO will be assigned to each shift during the Power Ascension Test Program. Only 8 Reactor Operators (RO) have unrestricted licenses because the 14 newly licensed RO's are limited pending on-watch training and reactivity manipulations during the Power Ascension Program. Therefore, the licensee will initially staff a four-shift rotation during plant restart. At an appropriate point after restart, the licensee will go to a six-shift rotation of two SRO's and two RO's per shift. There are also sufficient non-licensed equipment operators to staff six shifts. STA's will work a five-shift rotation for at least the next year. These staffing levels are considered adequate.

It should not be necessary to work operators in excess of the overtime guidelines of NRC Generic Letter 82-12. Senior plant management has been active in restricting overtime. Procedure 1.3.6.7, "Use and Control of Overtime at PNPS," adopts NRC guidelines, provides procedural controls for overtime hours, and requires advance approval of overtime. The inspector reviewed Operations Department overtime records for the period of July 6, 1988 to August 16, 1988. During this period, there were only three occasions when staff worked greater than 56 hours in a 7-day period. During this period, there was one instance of overtime in excess of NRC guidelines. This occurred August 1 and 2 when a radwaste worker worked 28 hours in a 48-hour period. This worker had approval to work up to 60 hours that week but did not have approval to exceed the 48-hour guideline. This worker is not a licensed operator and was not doing safety-related work. The licensee identified this incident and counseled the individual on overtime requirements.

3.2.4 Procedure Validation

The Team walked down Procedure 5.3.26, "Reactor Pressure Vessel Injection During Emergencies," with a non-licensed equipment operator who had been trained in the procedure. The procedure involved connecting a fire water crosstie to the residual heat removal (RHR) system. Minor procedure errors were found. A drain valve labeled 1-DR-122 in the field is referred to as 1-DR-121 and the fire water storage tank low level alarm is referred to as annunciator B-7, whereas it is actually D-3. Also, the procedure instructs the operator to "connect the local flow meter" without specifying the instrument number. The procedure was actually referring to a strainer differential pressure indicator, instrument number 33-PID-4610. The operator did not simulate connecting this instrument and when questioned by the Team, he stated that the step referred to flow meter FI 4609 which was already connected. Of more significance was confusion caused by step IV.B.2.b, which instructs the operator to install jumpers to defeat LPCI initiation and PCIS isolation signals and operate LPCI injection valves 28 and 29. The equipment operator requested the assistance of the watch engineer and the STA. These watchstanders initially felt the jumper was not needed. The jumper is not directly related to LPCI valves 28 and 29, but is needed to provide a flow path for a fire pump and to prepare for contingencies in the EOPs.

Procedure 5.3.26 was one of eight new procedures written by contractors and validated by contractors. All eight of these procedures are therefore suspect and will be revalidated by licensee operations staff before restart. All other EOP satellite procedures and other abnormal operating procedures substantially changed during this outage will also be revalidated before restart.

The licensee did not perform any QA audits or surveillances on the writing of procedures by contractors. However, the licensee has performed surveillances of the procedure validation process used on procedures other than the EOP satellite procedures. Surveillances #87-9.3-9 and #88-1.1-56 found that half of the procedures being revised and implemented in April and May 1988 were not being validated. As a result of this finding, procedure 1.3.4-4, "Procedure Validation," was issued August 15, 1988.

There were also some training aspects to this procedure issue. The equipment operator was trained on Rev. 0 of 5.3.26 which did not include the instruction to connect the local flow meter, whereas the inspector used Rev. 1. Licensed operators were trained on the control room portion of the EOP satellite procedures and equipment operators were trained in the procedural steps outside the control room. The problem with the jumpers occurred at the interface between these operators. Following the procedures revalidation discussed above, the licensee will provide additional training as needed.

During a NSRAC meeting conducted on August 2, 1988, the committee discussed an open concern on the validation and upgrade of plant procedures. NSRAC concluded that they were concerned that all of the routine operating procedures had not been validated by one of the validation processes. Following the meeting, the committee forwarded a concern to the SVP-N concerning the operating procedures necessary for long-term operation of the plant. The plant staff is scheduled to respond to NSRAC on September 14, 1988. The NRC will review this response during a subsequent inspection.

3.2.5 Temporary Modification Controls

The Team observed that current logs show that about 15 temporary modifications (TMs) are in effect, some of which date back to 1983. Fifteen is not an unusual or unmanageable number of TM's, and represents a significant reduction from previous conditions.

The Team reviewed nine TM's initiated 1987 and prior years and noted (1) only three of the nine modifications affected safety-related systems; (2) licensee safety evaluations (SE) were filed in the TM package, which demonstrated the interim configurations created were acceptable; and, (3) licensee actions to address the TM's by conversion to permanent modifications were apparently based on engineering service requests and plant design changes referenced in the TM packages. Team review of the SE's on a sampling basis did not identify any inadequacies. Further, the Team noted that reduction of the TM backlog has been a licensee priority.

Plant Procedure 1.5.9, "Temporary Modifications," allows temporary modifications to be open for six months and provides a mechanism for active TM's to be extended. However, this mechanism is typically not used. Procedure 1.5.9 does not require a review of the TM for extension of the expiration date if an engineering service request (ESR) for a permanent design change is in effect for the TM. Of seven TM's reviewed, six had ESR's and therefore did not have a current approved extension date. The inspector indicated that good engineering practice would dictate continuance of the periodic reviews for all TM's, and licensee management agreed. The licensee committed to either prepare a justification for operation for every TM that is still open prior to startup or to revise the procedure to apply the TM extension request process to all TM's, including those with outstanding ESR's.

TM 84-77 was selected for detailed followup review to assess the technical adequacy of the change on a temporary basis and to evaluate the extent and timeliness of licensee followup actions to either remove the temporary modification or convert it to a permanent change to the facility. The modification involved the replacement of an FCR-type relay in cubical 72-754 of the DC motor control center for the RCIC 1301-22 valve. The valve is in the suction path from the condensate storage tank (CST), is normally open for RCIC standby and initial operation, and will cycle closed on low level in the CST. After failure of the existing FCR relay (an open circuit coil), an HFA-type relay was installed on December 17, 1984 and made electrically equivalent to the original circuit. An HFA was used because an FCR relay was not available onsite. The change did not affect the normal function of the valve.

Engineering Service Request (ESR) 85-368, dated July 22, 1985, requested engineering to convert the change to a permanent modification, with a completion date of November 22, 1985. ESR response memorandum NED 86-1275, dated December 31, 1986, rejected the ESR request to make the change permanent because of two concerns involving the need to keep the wiring in the 72-754 cubical consistent with other DC motor control centers (MCC) and the assumed differences in the inrush and coil holding currents between the two types of relays. In rejecting the request, engineering found that the change was acceptable on a temporary basis, but recommended restoration of the original design.

A Potential Condition Adverse to Quality (PCAQ) Report (No. NED 86-110) was issued to assess the deviations. Further engineering evaluation was requested by ESR 88-080, dated January 27, 1988, with action requested by May 1, 1988. Further engineering review determined that the change would be acceptable as a permanent modification, which was made by FRN 87-80-52 to PDC 87-80 dated June 14, 1988.

The plant design change (PDC) modified the drawing to permanently document the change and addressed the seismic adequacy of the HFA relay installation. The HFA relay was not certified to be environmentally qualified since the 1301-22 valve is not on the EQ master list and environmental qualification (EQ) is not required. The PDC also addressed the adequacy of the inrush and holding current characteristics of the HFA relay. The second engineering review found the HFA current characteristics to be better than those of the FCR relay.

The Team discussed the bases for the original and final engineering determinations via telephone on August 17, 1988 with engineering (NED). The Team noted that engineering initially rejected the proposed design change based on information indicating larger power consumption by the HFA relays, and based on a concern that, if replacement of the FCRs with HFAs became a general practice, a problem could result in the increase in DC loads. Those concerns were not realized since the FCR failure was a random one, and the operating current characteristics of the HFAs are better than initially assumed.

Based on the above, the Team identified no technical concerns with the licensee's dispositioning of the adequacy of the modification.

The Team noted that licensee action on the original 1985 ESR was not timely in either the preparation of the original ESR or the followup actions by NED in response to the site request. However, the actions to respond to ESR 88-80 and disposition the issue in 1988 were greatly improved.

The Team audited the six tag outs for TM 84-22 and found that MCC B25 was missing two TM tags. Since this is a non safety-related modification which is about to be withdrawn, this was not considered by the Team to be of safety significance. It does indicate; however, the need to periodically recheck TM tagouts.

An additional concern is that in the following example the licensee performed a TM without implementing the formal review and approval process. During a tour of the reactor building on August 8, 1988, the Team noted that reactor pressure boundary leak detection system monitors C-19A and C-19B had their doors propped open, and each monitor had a large fan tied to the opening. Investigation identified that no temporary modification had been processed to evaluate and authorize this alteration. The licensee stated that elevated temperatures in the cabinets result in failure of the monitor electronics and have been a long-standing problem. Engineering response to Engineering Service Request (ESR) 85-462 implemented a reduction in system heat-tracing temperature. This alteration did not resolve the problem, and on August 6, 1988, the licensee initiated ESR 88-558 requesting further engineering review. Monitors C-19A and C-19B are required to be operable by Technical Specifications during power operations so that some short-term action and long-term resolution are needed. Since the monitors are not currently required to be operable, the licensee has de-energized them and removed the fans pending evaluation.

In summary, even though the licensee has been aggressive in reducing the number of TM's, there have been some lapses in their control of temporary modifications. This indicates a need for continued licensee management attention to this area.

3.2.6 Required Reading Books

The Team reviewed the "Required Reading" books in the control room. The books consist of three large binders that contain procedure changes. They provide a method for promptly updating operators on plant and procedure changes. Each piece of information in the book had a sign-off sheet to ensure that all operations personnel read the material. The Team noted that information in the books dated back to April 1988 and many of the procedure changes had not been signed off as read by all personnel. This appears to indicate that the program is not being monitored routinely by operations management. Material remaining in the book for long periods defeats the purpose of providing timely information on changes to the operators. Conversely, if the changes are not important to operations personnel, it may not be necessary to put them in the books.

The Team discussed these observations with the Plant Operations Section Manager. Some improvement was noted later during the IAI inspection, as a result.

3.2.7 Logs

The Team reviewed the implementation of the Technical Specification Limiting Condition for Operations (LCO) log, the Disabled Annunciator Alarm Log, and the operations supervisor log procedures. The LCO log was implemented August 18, 1988, by Procedure SI-OP.0008, "Limiting Conditions for Operations Log," dated July 25, 1988, and was being used on a trial basis from August 8 to August 18, 1988. The only LCO entered after the log was implemented, LCO A-88-002, was properly entered, tracked, and cleared. Procedure SI-OP.008 is being revised to incorporate lessons learned in its initial implementation.

The Disabled Annunciators Alarm Log is controlled by Procedure 2.3.1, General Action Alarm Procedures, Item VII. The inspector observed eight disabled annunciator tags on control room annunciators. All eight were properly logged. However, only two of the eight annunciators had a maintenance request (MR) issued. The shift supervisor informed the Team that disabled annunciators without MRs occurred due to plant conditions and will be returned to service before startup. The licensee audits disabled annunciators monthly under preventive maintenance (PM) Procedure 8.A.24, "Audit of Control Room Annunciators and Instruments," which should assure that these annunciators are returned to service before startup.

There was little activity in the control room during this inspection, but the Team did observe the following items properly logged in the operations supervisor's log: LCO's, Failure and Malfunction Reports, a fire drill, and spent fuel pool temperatures while the fuel pool pumps were out of service for maintenance. However, as discussed in Section 3.2.8 below, changes in jumpers or lifted leads were not logged in the operations supervisor's log.

The Team concluded that log keeping practices are generally adequate.

3.2.8 Timely Update of Lifted Lead/Jumper Log

During a review of the Lifted Lead/Jumper (LL/J) procedure and program implementation on August 16, 1988, the Team identified that the log was not being maintained completely up-to-date. Eight entries in the LL/J log involved lifted leads or jumpers installed on July 14, 1988, to perform main station battery work and testing per Maintenance Work Plan (MWP) 87-46-173. All eight requests were associated with the same MWP. All log entries showed the LL/J request

was still active on August 16, 1988. The Team found that the batteries had been returned to normal and LL/J request was closed out on July 29, 1988, and that Maintenance Request 87-46-173 was completed on August 1, 1988, inclusive of the post-work testing. Step 5.3.1.5 of Station Procedure 1.5.9.1, "Lifted Leads and Jumpers," states that the person performing the LL/J request is to notify the Watch Engineer when the system is returned to normal by removing the jumpers or landing the lifted leads. The Watch Engineer is responsible for updating the LL/J log. The findings were referred to operations personnel on August 16, 1988 for followup.

Licensee followup review confirmed that the work had been completed and the log should have been updated. The log was updated to show the correct status on August 16, 1988. In response to the inspector's findings, the licensee conducted an audit of the log. The licensee's audit identified (1) two instances where the log had not been updated, and (2) that operations personnel were not making entries in the Operation's Supervisor log when LL/J log entries were made. These matters were referred to the Operations Section for followup and corrective action. QA followup and trending will be covered by QA Surveillance Report 88-94-61.

The licensee reported that the cause of the discrepancy was the failure of maintenance personnel to inform operations that the jumpers and lifted leads were cleared when the systems were returned to normal. Inspector interviews with the Maintenance Supervisor responsible for MR 87-46-173 noted that he failed to discuss the closeout action on the LL/J request as a result of a misunderstanding on the status of the work package closeout during shift turnover with another maintenance supervisor.

Team review concluded the inaccurate LL/J log had minimal significance and no impact on safe plant operations for these cases. There was no loss of control of the physical plant configuration. Plant operators would have reviewed the LL/J log as a prerequisite to plant restoration and startup. This review would have identified the open log entries and the completed closeout actions. Further, licensee followup to the discrepancies identified by the Team were prompt and appropriate. Based on the above, and in recognition that the jumper and lifted lead log is a new tracking system, no further NRC action is warranted at this time. This area will receive further review during subsequent routine NRC inspections.

3.2.9 Tagouts and Operator Aids

The Team reviewed the licensee's administrative controls for use of protective tagging at PNPS. The Team reviewed Procedure No. 1.4.5, "PNPS Tagging Procedure," Revision 23, which is to be implemented September 1, 1988, and noted that this procedure was revised to address concerns with tag controls identified during the licensee's self-assessment. Specifically, the procedure limits the use of Nuclear Watch Engineer (NWE) tags; prohibits the use of danger (red) tags for identification purposes on lifted leads; and requires documented monthly reviews, including field verification, of NWE, Caution and Master Danger tags and tagout sheets. The Team reviewed the NWE and caution tag logs and independently verified that several NWE, caution, danger, and master danger tags were properly filled out, properly hung, and positioned as required on the components. No discrepancies were identified. Based on this review, the Team concluded that the licensee's control of protective tagging was adequate and properly implemented.

The Team also reviewed the licensee's control of operator aids as established by Procedure No. 1.3.34, "Conduct of Operations." An operator aid is information in the form of sketches, notes, graphs, instructions, or drawings used by personnel authorized to operate plant equipment. The Team reviewed the operations and chemistry operator aid log and determined that it was maintained in accordance with the procedure. The Team noted that periodic licensee reviews and verification of the need for and placement of operator aids were documented. The Team independently verified proper posting of selected operator aids, and no unauthorized aids were identified during the Team's plant tours. Based on this review, the Team concluded that the licensee's control of operator aids was adequate.

3.2.10 Plant Tours and System Walkdowns

3.2.10.1 Miscellaneous Tour Observations

The IATI Team made frequent plant tours. The overall material condition of rooms and equipment was excellent. Particularly notable was cleanliness, fresh paint, and obvious decontamination efforts to make major portions of plant and equipment accessible. Component labeling and tagging was very good.

The Team observed activities in progress. Persons interviewed on tour (HP, security, operations contractor) had experience in their positions and were knowledgeable about their work and duties. HPs were cognizant of work activities in progress. Housekeeping controls were being maintained during work in progress.

The Team reviewed the status of indicators and controls on selected local panels. Controls and indications were operable and no deficiencies were noted. Operating procedures required to be posted at the local panels were available and adequate, based on Team review.

The Team observed loose cable tray covers including one that was laying on top of an in-place cover. The licensee reviewed this finding and documented the review and corrective actions in an engineering "white paper." This review determined that loose covers do not compromise the design but that covers laying on top of in-place cable tray covers could be a seismic concern. The misplaced cover found by the Team was determined to not be needed. The licensee surveyed cable trays throughout the process buildings and found additional loose covers but no more that were completely unfastened and laying on top of other covers. Corrective actions completed include refastening the loose covers, removing the misplaced cover, revising procedure SI-SG.1010, "Systems Group System Walkdown Inspection Guideline," to use periodic walkdowns by the system engineering division to identify seismic concerns, such as misplaced tray covers, and preparing F&MR No. 88-200, which will be used to determine how to keep future maintenance and modification work from creating loose or misplaced covers. The Team concluded that the licensee's response to this issue was thorough and adequate. The Team considers this issue resolved.

3.2.10.2 Diesel Generator Walkdown

A walkdown of the 'A' diesel generator (DG) was completed on August 15, 1988, to verify operability and standby readiness of the emergency power supply, and to observe the general conditions in the DG area. The valve checkoff lists of Procedure 2.2.8, "Standby AC Power System (Diesel Generators)," were used as acceptable criteria to establish the proper system valve

positions. The procedure checklists were also reviewed for adequacy against Drawings M219 and M224, and by comparison with the physical plant during a walkdown of the diesel skid and room. Proper valve lineup was verified for the DG fuel oil and air start systems. This review confirmed that the 'A' DG was operable in the standby mode.

Cleanliness and the general condition of equipment and components in the diesel rooms were excellent. Valve and component identification (tags) and labeling were very good and showed significant improvement in performance in comparison to past reviews. Several minor discrepancies were noted, as follows: (1) identification tags were missing on valves 104C and 118, and the tag was loose on valve 105C; (2) valve 118 was required to be locked in the closed position and a chain and padlock were provided for this purpose; however, the chain was sufficiently loose that the Team would have been able to defeat the lock and thereby move the valve; (3) the inner fire door granting access to the 'A' DG skid had worn and damaged gaskets along the closing surface and the door latching mechanisms (dogs) were misaligned with the position indicators; (4) no permanent lighting was installed in the 'A' and 'B' diesel day tank rooms -- lighting, if installed, would aid operator reviews during plant tours; and, (5) two isolation valves for pressure switches 4555A and 4556A were not labeled with an ID tag in the plant and were not identified on system drawings or procedures. The valves were properly positioned. Additionally, proper valve position is demonstrated indirectly during the monthly functional test of the diesel air start system.

These discrepancies were noted by the Nuclear Plant Operator accompanying the Team and were discussed with the duty Watch Engineer. Actions were taken to document and correct the discrepancies, including the issuance of Maintenance Request 88-61-83 for the fire door. Inspector followup review on August 16, 1988 confirmed that actions were in progress and had been completed to correct the tag on valve 105C and to properly lock valve 118. Licensee response to the Team's findings was appropriate and timely. No other inadequacies were noted.

3.2.10.3 Standby Liquid Control System Walkdown

The Team walked down the standby liquid control (SBLC) system using the valve checklist in Procedure No. 2.2.24, "Valve Lineup for Standby Liquid Control System," and piping and instrument diagram (P&ID) M-249. This review was performed to verify the adequacy of the procedure checklist and P&ID, evaluate the valve labeling, evaluate the control of locked valves, verify the operability of instrument and support systems, and assess the overall material condition of the system and general cleanliness of the area. The Team noted that the checklist control of vent and drain capped connections differed from other safety system procedures, such as those for the residual heat removal (RHR) and core spray (CS) systems. For example, an outboard vent valve on the CS checklist would be "locked, closed and capped." The SBLC procedure only checks "locked, closed." No deficiencies with capped connections were noted, however. The Team also noted that the vent valve for pressure indicator (PI) 1159 was not on the valve checklist. The licensee agreed to review these observations to determine if the procedure needed to be revised. No other deficiencies or concerns were noted.

Overall, the Team found the valve labeling, material condition, and general cleanliness to be excellent.

3.2.11 Conclusions

The operations staff conducted their activities in a professional manner. Operators were knowledgeable about their duties and about plant status. The depth of experience and knowledge of senior licensed operators is a strength and will be a major asset during restart. Shift turnover briefings by individual operators and for the shift are thorough; however, non-operations shift workers do not routinely attend these briefings. Site management involvement in operations was evident by their frequent presence in the control room. Shift staffing levels are adequate and plant housekeeping was excellent.

A weakness was noted in the validation and/or training of EOP satellite procedures. The licensee's commitment to confirm effective implementation of EOP satellite and off-normal procedures before restart is responsive to NRC concerns. Administrative controls and log-keeping practices are generally adequate, although required reading materials are not being reviewed by all personnel on a timely basis. There are lapses in the licensee's control of temporary modifications, particularly the absence of periodic reviews and scheduled completion dates for temporary modifications covered by an engineering services request.

3.3 Maintenance

3.3.1 Scope of Review

The licensee's maintenance program has undergone significant change during the past several months. Weaknesses had been identified during the SALP period ending May 15, 1988, and by Special NRC Maintenance Team Inspection 50-293/88-17. During the present inspection, the licensee's maintenance policies and program procedures were reviewed. Maintenance activities were evaluated during the planning, implementation, post-work testing and closeout stages. Emphasis was placed on direct observation of ongoing work in the field. Interviews were conducted with personnel at each level within the maintenance department to determine their depth of understanding of program goals. The Team also assessed the size and significance of the licensee's maintenance backlog, and reviewed established licensee performance indicators.

3.3.2 Observations and Findings

3.3.2.1 Management Policies and Goals

The Team reviewed the licensee's Mission Organization and Policy Manual, Nuclear Operations Procedures Manual, and Maintenance Section Manual. These documents describe the licensee's policy and performance goals for the maintenance program. The licensee has also established the Material Condition Improvement Action Plan (MCIAP). The MCIAP, which is described in the licensee's Restart Plan, is designed to achieve long-term improvement in the maintenance program. In addition, maintenance performance indicators are being used by the licensee to evaluate the success of recent program changes and the allocated maintenance staff has been increased significantly. Interviews with maintenance personnel at various levels within the department indicate that the organization and management policies are generally well understood.

3.3.2.2 Organization and Staffing

The maintenance organization and staffing levels were reviewed. Interviews were conducted with division supervisors and staff personnel to determine whether organizational relationships were well understood. The current staffing status was evaluated, particularly in the supervisor, maintenance engineer, and planning positions, to determine whether staffing levels were adequate, responsibilities clearly defined, and resources effectively used.

The maintenance section consists of three production divisions (electrical, instrumentation and control and mechanical), plus a planning division and an engineering group. All division manager positions and all first-line supervisor positions in the production divisions are filled with licensee employees, except for two positions in the equipment tool room, which are presently filled by contractors. Increased staffing at the craft level in the production divisions has been authorized. Instrumentation and Control (I&C) will increase from 22 to 30 positions; Electrical Maintenance will increase from 14 to 18 positions; and Mechanical Maintenance will increase from 27 to 33 positions. Staffing of the planning division has not been completed. Twelve contractor personnel are presently being used to perform the planning function, with assistance from the licensee's outage management group. This arrangement is performing acceptably, as described in Section 3.3.2.4.

Team interviews with supervisors and craft employees showed that personnel clearly understand the new program and their area of responsibility. The interviews covered personnel with a wide range of experience in their positions, including those newly assigned. The Team noted; however, that the recently revised job descriptions for the section have not been disseminated to the staff. The Maintenance Manager stated that they would be issued in the near future.

Two positions in the new maintenance section organization, the Deputy Manager and the Radiological Advisor, are effectively being used. The Radiological Advisor is a permanent staff position and provides a focus for interface with the Radiological Protection Group. Team observations indicated that the Deputy Manager was effective in scheduling and coordinating activities through his interface with other sections.

The Team's review indicated that licensee staffing is ample to meet targeted production goals without reliance on the use of excessive overtime. While some variations occur, the percent of overtime worked has been at or slightly above the operating goal of 20%, which equals a 48-hour work week. Work schedules for craft and supervisory personnel provide 1 day off in a 7-day period. The maintenance staff is working primarily on the day shift, with night shift coverage provided for certain critical jobs in progress. The licensee plans to provide around-the-clock 8-hour shifts that will match the Operations Section rotating shift schedule, beginning with plant startup. Maintenance shift coverage will continue through the power escalation sequence and on a reduced scale afterwards. Licensee staffing is sufficient to staff the shift schedule without reliance on excessive overtime.

New personnel assigned to the division manager and production supervisor positions have adequate prior experience in related assignments. The Team's observations of the first- and second-line supervisors in conducting their daily activities showed that the supervisory, oversight, and control functions were effectively performed. Based on these observations, the Team concluded that the newly hired supervisory staff does not have a negative impact on the quality of control over maintenance activities.

In summary, identified strengths in the present maintenance section organization include the use of the Deputy Manager and the Radiological Advisor. The increase in supervisory positions in the production divisions has been effective in increasing oversight and control of work activities. While temporary staffing of the planning division with contractors is sufficient and provides for an effective planning function (as measured by the quantity and quality of maintenance packages produced), plans to staff these positions with permanent licensee employees by October 1988 should remain a management priority to assure timely integration of the planning and scheduling functions. Management has controlled overtime for the craft and supervisory positions. Plans to provide for maintenance staffing during and after restart on an 8-hour rotating shift basis should provide continued effective overtime control.

3.3.2.3 Communications and Interfaces

Communication between the maintenance department and other portions of the organization, particularly operations and radiation protection, had previously been a weakness. The licensee has taken successful steps towards improving communication, both internal to the maintenance department and with other station groups.

The Team attended a variety of maintenance department status and turnover meetings. Based on observation of these meetings and interviews with maintenance personnel at each level of the organization, the Team concluded that communications internal to the maintenance staff are effective. Maintenance department managers were cognizant of the status of activities and of emerging problems.

The licensee has initiated several programs directly addressing the past weaknesses in interdepartment communications. In an effort to improve the interface with radiation protection and to raise worker sensitivity to health physics issues, the licensee created and staffed the maintenance Radiological Advisor position. Interviews with a spectrum of individuals indicated that this effort has had a positive impact on

day-to-day working relationships and performance. The licensee also formed the Work Prioritization Review Team (WPRT), composed of representatives of various station departments. The WPRT provides a forum for discussion of the relative importance of each maintenance item as it arises. The WPRT has been effective in improving operation's department involvement with the maintenance process. The maintenance department is also involved in daily and weekly meetings intended to ensure coordination between station groups. Meetings attended by the Team were generally effective.

The need for continued efforts to improve communications and interfaces were noted in some areas. The licensee's Stores Department practices are not always fully supportive of specific maintenance department needs. For example, lubricating oil can only be withdrawn in bulk quantities, such as a 55-gallon drum. Typical maintenance activities require use of only a fraction of this amount. Similar restrictions apply to materials routinely used by the I&C, electrical, and mechanical maintenance divisions. This policy places the burden for control and storage of unused material on the individual requesting the withdrawal. The Team noted that maintenance personnel were routinely using a cabinet in the maintenance shop to store unused "Q" materials. No procedure existed to specify the appropriate controls for the storage area. The need for establishment of the storage cabinet had been discussed previously between the Quality Assurance Department (QAD) and maintenance. QAD believed that the cabinet was not currently in use, while maintenance personnel believed that QAD had concurred in its creation, demonstrating a lapse in interdepartment communications. The licensee subsequently performed an inventory of the materials in the cabinet, and removed all non-Q and suspect materials. Procedure J.M.1-32, "Control of 'Q' Hold Area," was subsequently issued to provide appropriate controls and surveillance of the cabinet.

The Team also noted that partially used drums of both Q and non-Q lubricating oil and grease were being kept in a storage shed outside the process building. Several of the drums were not properly sealed. No procedure addressing this storage area existed. Discussions with operations personnel indicated that the difference between Q and non-Q drums of material was not clearly understood. Routine withdrawals and their equipment application were not recorded. In response, the licensee removed all non-Q materials and committed to issue a procedure to establish appropriate controls by September 7, 1988, including provisions to ensure that the lubricants are traceable to their application in the field. In addition, the licensee committed to evaluate the possible addition of non-Q oil to Q equipment and its potential significance.

During followup to this issue, the Team reviewed Engineering Specification M-547, which documents the procurement and receipt inspection requirements for the purchase of lubricants as a Commercial Quality Item (CQI). The Team noted that M-547 requires sampling and testing of each batch of material purchased as a CQI. At the Team's request, the licensee reviewed records and identified two cases in which a CQI procurement order had been issued which did not invoke this sampling requirement. The licensee subsequently issued a Potential Condition Adverse to Quality (PCAQ) to initiate a review of CQIs issued for consistency with approved engineering specifications. The licensee committed to disposition this PCAQ prior to restart.

Overall communications between the maintenance department and other groups within the organization are effective. However, the interface problems discussed above, among the Stores Department, QAD, and the Maintenance Department, indicate that continued attention is needed.

3.3.2.4 Maintenance Planning and Prioritization

The licensee has established a Maintenance Planning Division within the Maintenance Department. The role of the Planning Division is clearly delineated in approved maintenance procedures and the licensee's Maintenance Section Manual. The Planning Division Manager position has been filled and the licensee is actively pursuing candidates for the eight allocated staff positions. When staffing efforts are complete, the division will consist of a work package planning group and a scheduling group. In the interim, the licensee is utilizing twelve contractor personnel to perform the package planning function. The licensee's Outage Management Group (OMG) is currently providing scheduling guidance. The licensee expects to complete the staffing effort by October 1988. Team reviews indicate that the present staff of contractors, in conjunction with OMG assistance, is functioning well.

Implementation of the revised maintenance work process, particularly the need to generate detailed job-specific maintenance work plans (MWP) for each maintenance request (MR), has resulted in a heavy emphasis on the planning function. The Team reviewed a large sample of completed MWP's, and MWL's in the field. Interviews with craft personnel and first-line supervisors indicated that these individuals were knowledgeable about the new maintenance process requirements and considered MWP's issued by Planning to be of generally good quality. One weakness was noted in the area of post-work testing specification, as discussed in Section 3.3.2.6.

The Team noted that the completion of job planning, and approval of the MWP are typically restraints to commencement of the activity. This results in the need to expedite the review process, making scheduling difficult. It appears that this is primarily attributable to the newness of both the program and the Planning staff. Other factors also contribute. For example, the licensee's procedures currently do not provide a simplified process for non-intent changes to the

MWP after issuance. MWP's require a complete re-review to incorporate minor changes. The licensee stated that a revision to the program to include provisions for non-urgent changes is planned for the future. The licensee's engineering department is presently reviewing each MR/MWP and approving the use of any replacement materials. This practice provides positive control of all materials, but delays issuance of the MWP and is a significant drain on engineering resources. While these factors inhibit efficient planning, no instance of inadequate planning was identified.

The licensee has created a WPRT to assist in the assignment of the proper priority to each MR. The WPRT meets daily and is composed of representatives of various station groups, including maintenance, operations, outage management, construction management, and fire protection. It performs a multi-disciplined review of new maintenance items to identify potential plant impact. The IATI Team attended a WPRT meeting and observed that discussions were properly focused and priorities were assigned appropriately.

The Team also independently reviewed outstanding maintenance requests for the RHR system and the electrical distribution system. This review focused on MR's not designated for completion before restart. The Team noted that MR 88-10-105 documented electrical ground and potential cable insulation damage in the circuit for pressure switch PS-1001-93A. This switch is environmentally qualified (EQ) and provides a safety-related interlock function for the automatic depressurization system. The MR had been scheduled for work after restart, leaving the switch EQ in an indeterminate state. In response to the Team's question, the licensee rescheduled the MR for completion prior to restart.

The Team also noted that MR 38-10-26 documents that valve AO-8001 is currently open and cannot be closed using the hand switch. AO-8001 is installed in series with a check valve in the torus fill line. The check valve satisfies the primary containment isolation function for the line. While AO-8001 is not required for containment isolation operability, it does serve as a redundant isolation valve immediately adjacent to the check valve. AO-8001 was originally designed to receive an automatic open signal on sensed low torus level. Because normal torus level is now maintained below the instrument low level set-point, the valve continuously receives an open signal, thus preventing manual closure. This condition has existed for at least several years. The licensee has relied on closure of a manual block valve located in the turbine building to compensate for the problem. The Team expressed concern that the distance between the containment isolation check valve and the redundant isolation valve have been unnecessarily extended outside the reactor building. In addition, a lineup that is inconsistent with the design drawings and operating procedures resulted. The WPRT had designated this MR as post-restart. In response to the Team's concerns, the licensee initiated an Engineering Service Request (ESR) to identify an acceptable repair. The licensee committed to resolve this item prior to restart.

These two examples of misscheduled MR's were discussed by licensee management with the WPRT. In addition, the licensee committed to re-evaluate all priority 3 MR's before restart. The licensee's process for review and prioritization of MR's is thorough, and with the exception of the two instances described above, appears well implemented. The effectiveness of the licensee's planning and prioritization program is demonstrated by the overall decrease in the number of outstanding maintenance tasks, their average age, and their significance.

The licensee tracks several maintenance performance indicators which are indicative of backlog status. Those performance indicators generally display a favorable trend. The Performance Indicator Report for August 9, 1988, shows a total backlog of 2177 open MR's, of which 746 are in a test/turnover status. Of these, 220 cannot be tested until the plant system becomes operable during startup. Of the 1431 remaining open MR's, the licensee has identified 652 required for restart. The physical work had yet to be done for 145 of these 652 MR's. Based on the above, and an average closeout rate of about 25 packages per week, elimination of the restart backlog within 6 to 7 weeks appears to be manageable effort. The licensee's goal, in addition to addressing the restart MR's, is to reduce the total number of open MR's from 1431 to less than 1000 by plant restart. The Team noted that this would constitute an acceptable open MR backlog for an operating plant, and that the licensee's goal was reasonable.

3.3.2.5 Control and Performance of Maintenance

Inspection in this area was performed to determine whether maintenance activities are being properly controlled through established procedures, and the use of approved technical manuals, drawings and job-specific instructions. Maintenance activities were observed to determine how well the new program was being implemented.

The new maintenance program is primarily defined in Procedures 1.5.3, "Maintenance Requests," and 1.5.3.1, "Maintenance Work Plan," which were implemented on June 20, 1988. The procedures were reviewed and found to provide strong controls for identification, planning, performance, and closeout of maintenance tasks. Issuance and control of materials used for replacement/repair assure that requisite quality requirements are maintained. Supervisory oversight of work in progress and the final review of work packages for completeness is a strength. Based on its review of the above procedures and observations of work in progress, the Team concluded that the newly defined program provides excellent control and documentation of activities.

The new program and procedures formalize controls that were previously in place, but inconsistently applied and not recognized by procedures. The procedures now require better documentation of the initial problem description, the repairs made, and the post-work test requirements. They require detailed work instructions, which should provide for consistent high quality in maintenance work packages. An additional improvement in the maintenance procedures is that the maintenance work plan now provides for detailed documentation of installation and removal of lifted leads and jumpers (LL/J). This documentation assures proper performance of the task and is supplemented by the tracking provided in the LL/J Log initiated by the Operations Department per Procedure 1.5.9.1.

To eliminate a previously identified weakness, the licensee has stopped using Procedure 3.M.1-11, "Routine Maintenance," which was found to be too general to adequately control work activities. Instead, detailed work instructions are provided by the work plans prepared in accordance with Procedure 1.5.3.1. Further, the licensee has stopped using the Maintenance Summary and Control (MSC) form. The documentation provided by the form has been replaced by the detailed work plans, maintenance logs, and special process control sheets now required by Procedures 1.5.3 and 1.5.3.1.

The maintenance activities and packages listed in Appendix D of this report were reviewed to verify proper implementation of program requirements. The Team found that detailed work packages were prepared and in use in the field with adequate job specific instructions to accomplish the assigned tasks. No ad-hoc changes of the work scope were observed. Pre-job briefings were conducted and were appropriate to outline the activities planned. Coordination and in-process communications with operations personnel were proper and assured good control of plant equipment.

Maintenance personnel, including contractors, have been trained in and were knowledgeable about the new program and procedure requirements. Although the new controls were deemed cumbersome by some, overall worker attitudes about the new procedures were positive. There is a general acceptance of the present program and a desire to "do the work right." Personnel performing the work were qualified, as verified by the training and qualification status board maintained in the maintenance shop.

The licensee has made progress in filling vacancies in the first-line supervisor positions with personnel having the requisite experience and expertise in the associated disciplines. The present supervisory staffing is adequate to cover work production schedules and provides adequate oversight. In an additional program improvement, supervisor review of work packages is now required by procedure to assure management review of packages for completeness. First-line supervisors were routinely observed in the field directing work in progress. Supervisory involvement was effective to assure completion of work correctly, to help resolve technical problems, and to coordinate engineering support, as required. The oversight function has been enhanced by the larger number of first-line supervisors who have been relieved of the excessive administrative burden associated with planning and package preparation.

The effectiveness of maintenance staff engineers and system engineers in supporting field activities was particularly noted in the repairs for the fuel pool cooling pump and the repair of RHR discharge valve 28B. The engineers are also used in the root cause analysis of component failures. The repair of valves 28A and B involved the fabrication of new valve yokes, which resulted in a large and complicated work control process that was appropriately broken down into several work packages. Oversight and control of these jobs, which spanned several weeks, were notable. The quality of the final product was evident, as was the welding of the yoke subparts. Good inprocess

controls resulted in an acceptable root weld on the first attempt for valve 28B. Although a problem was encountered in the fabrication of the yokes (short by 3/8 inches), this item, considered minor, was properly dispositioned by the licensee through Nonconformance Report (NCR) 88-99.

3.3.2.6 Post-Maintenance Testing Program

The licensee's program for identification and implementation of post-maintenance testing was considered weak during previous inspections. During the current period, the Team reviewed the licensee's post-maintenance testing program procedures and other approved test technical guidance. A sample of maintenance tasks was reviewed to determine if planned testing adequately demonstrated correction of the cited deficiency. Testing was observed in the field, and completed test documentation was reviewed for thoroughness.

The licensee recently implemented a major revision to Procedure 3.M.1-30, "Post-Work Testing Guidance." The current revision establishes a conservative philosophy designed to ensure that prescribed testing verifies correction of the original deficiency, as well as potential problems which could have resulted from performance of the task. Organizational and individual responsibilities are clearly defined. Procedure 3.M.1-30 incorporates by reference Station Instruction SI-MT.0501, "Post-Work Test Matrices and Guidelines." SI-MT.0501 serves to further define the method by which post-work testing is to be specified and documented. It includes an individual matrix for each type of component describing the possible maintenance tasks and the corresponding post-work test requirement. Each matrix references an appropriate data sheet which provides more detailed testing guidance. Procedure 3.M.1-30, in conjunction with SI-MT.0501, is to be used by the Maintenance Planning Division, with needed technical input from other maintenance department and systems engineering department personnel, to establish comprehensive testing requirements for each maintenance request. The testing program as described in these documents is well conceived and is considered a strength.

The Team reviewed a sample of ongoing maintenance tasks and evaluated the technical adequacy of prescribed testing. In three of the examples reviewed, the planned testing was not adequate to ensure proper performance of the task and complete correction of the problem:

- (1) Testing identified for the replacement of the fuel pool cooling pump and motor under MR 86-109, included only motor current and vibration monitoring. No pump head/flow test was specified.
- (2) The package for replacement of a safety-related 4160-VAC bus lockout relay under MR-88-110 initially contained only the general guidance which should have been used for development of detailed testing. Subsequently, suggested testing verified only a portion of the lockout relay functions.
- (3) Post-maintenance testing following repair of a motor operated valve limit switch under MR 88-10-179 was also not adequate to ensure that the problem had been completely corrected.

In response to the Team's findings, the licensee Maintenance Section Manager audited task-ready MR packages and identified one additional case of inadequately specified testing. In each of the above instances, the licensee subsequently developed and performed adequate post-work tests. Discussion with the personnel involved and maintenance department management revealed that no training on the newly developed post-work testing procedures and guidance had been conducted. The licensee immediately briefed appropriate supervisors and workers on the program, and committed to complete formal training in this area by September 9, 1988. A second potential contributor to the problem in planning post-work tests is the press of business, particularly in the planning area, in that the planners are currently just able to keep pace with the schedule for field activities. Licensee management appeared to be sensitive to this issue. The Team reviewed an additional sample of in-process and completed MR's and did not identify any further problems.

Overall, the Team concluded that the licensee has established a thorough post-work testing program demonstrating a sound safety perspective. Although the program is generally well implemented, some problems were noted. The newness of the program, the current press of business, and some weakness in personnel training appear to be affecting its implementation. Therefore, this area requires continued licensee attention.

3.3.3 Conclusions

The licensee has established a viable maintenance organization. Allocated staffing levels have been substantially increased and are sufficient to support routine maintenance activities. Of particular significance is the addition of first-line supervisory positions, and the creation of an expanded maintenance planning and scheduling division. The licensee has been largely successful in filling previously vacant positions. One exception is the staffing of the maintenance planning division. While none of the permanent staff in this area is in place, the licensee is effectively utilizing contractors to perform the function. Full staffing and training of the planning division is important to improving its overall effectiveness. Aggregate management and supervisory qualifications were also found to be adequate.

Newly revised maintenance and post-work testing program procedures provide significantly improved control and documentation of field activities. They also result in an increased emphasis on detailed job planning. Observations by the Team indicate that implementation of the program is generally effective. Some implementation problems are evident; however, the problems affect production and not the quality of completed work. Additional attention to post-work test program application by the licensee is needed.

The licensee appears to have identified and properly prioritized outstanding maintenance tasks, with only minor exceptions noted. A process to ensure continued proper prioritization has been established. Both licensee senior management and maintenance section management are using a set of indicators to monitor performance.

In summary, the licensee's current maintenance staff and program are adequate to support plant operations. Continued close licensee management monitoring of the newly implemented program will be required until additional experience is gained. The long-term support programs, such as preventive maintenance, will require licensee enhancement to further strengthen performance.

3.4 Surveillance Testing and Calibration Control

3.4.1 Scope of Review

The Team reviewed the licensee's administrative controls and implementation of the surveillance testing and calibration control program to assess its adequacy. As part of this review, the Team examined the licensee's corrective action to address past problems which included: effectiveness of test scheduling; the technical adequacy of procedures; and lack of centralized control of the program. The inspection consisted of a review of various procedures, drawings, and records; observations of testing in progress; and personnel interviews.

3.4.2 Observations and Findings

3.4.2.1 Master Surveillance Tracking Program

The Team reviewed the licensee's program for the control and evaluation of surveillance testing and calibration required by the Technical Specifications (TS), inservice testing (IST) of pumps and valves required by 10 CFR 50.55.a(g), and calibration of other safety related instrumentation not specified in TS. The program is prescribed by Procedure No. 1.8, "Master Surveillance Tracking Program." The Systems Engineering Division Manager has overall administrative responsibility for the Master Surveillance Tracking Program (MSTP). A plant Surveillance Coordinator has been assigned within the Systems Engineering Division to implement the program, which includes reviewing and approving the various lists, schedules, and reports generated by the MSTP, and maintaining the MSTP data base. Each division has appointed a Division Surveillance Coordinator to interface with the plant Surveillance Coordinator. The plant Surveillance Coordinator meets weekly with the Plant Manager to review the status of the surveillance program.

The purpose of the MSTP is to ensure the timely performance of all surveillance testing. The MSTP data base contains information such as: commitment reference (TS, preventive maintenance, regulatory commitment, etc.); the applicable procedure number and title; scheduler interval and basis; the group responsible for performing

the test/calibration; and the date last performed, the next due date, and the last date by which the surveillance test must be completed (plus 25% date). Completed tests are rescheduled to ensure the combined grace period for any three consecutive tests does not exceed 3.25 times the specified surveillance interval. The accuracy of the data base was verified by a contractor during the current outage. Procedure No. 1.8 contains specific controls on changing any of the data fields in the MSTP data base to maintain its accuracy. In addition, a second contractor verification of the MSTP data base is scheduled to be performed in the near future. The Team selected several TS-required surveillance tests to ensure that they are in the MSTP data base, that approved procedures existed, and that the test frequency was proper. No discrepancies were identified with the data base during the Team's review; however, the Team was concerned with a potential problem involving the scheduling of once-per-operating-cycle versus once-per-refueling-outage tests, as discussed below.

As part of its review, the Team examined the process established by Procedure No. 1.8 to determine its adequacy in ensuring that surveillance tests were properly scheduled and performed within the required time period. A "Division List" is issued to each division and to the Control Room Annex each Friday which provides a schedule of tests due for performance the following week. A "Monthly Forecast" is also issued weekly to assist the Section Managers in planning and scheduling resources. When a surveillance test is satisfactorily completed, the Control Room Annex copy of the Division List is signed off. Daily, the Planning and Scheduling Division transcribes the completion dates and updates the MSTP data base. A "Surveillance Day File Report" is issued daily to identify all changes made to the MSTP data base since the last time the report was issued. This report is reviewed by the Plant Surveillance Coordinator and used to verify proper transcription and data entry. "Variance Reports" are issued weekly to Section Managers to

identify those surveillance tests that were scheduled, but not performed. A written explanation as to why the tests were not performed within the required time and why it's acceptable not to perform the test is sent to the surveillance coordinator within 24 hours of receipt of the Variance Report. A "Priority Notice" is issued for any surveillance test that has reached its deadline date (plus 25% date) and that has not been performed by that date to assist in the prevention of TS violations. Failure to perform a TS-required surveillance test on the deadline date requires submission of a Failure and Malfunction Report. The Team reviewed samples of each of the above reports, and their responses, and concluded that the program was adequate and contained sufficient checks to ensure that surveillance tests were completed within the required time.

Although the Team found the administrative control and implementation of the MSTP to be adequate, it noted a commitment by licensee management to improve the program. These improvements include: replacing the Division Lists with task cards to reduce the potential for transcription errors; adding an alert notice when a scheduled test is not performed; improving the scheduling of conditional surveillances; planning for the addition of a full-time surveillance engineer; and instituting an equipment history computer program capable of trending surveillance/calibration results on individual components.

The Team identified one concern during its review related to the scheduling of once-per-operating-cycle versus once-per-refueling-outage surveillance tests. The Pilgrim Technical Specifications define an operating cycle as the interval between the end of one refueling outage and the end of the next subsequent refueling outage. A refueling outage is the period of time between the shutdown of the unit prior to refueling and the startup of the plant after that refueling. The TS contains some surveillance requirements that are specified to be performed once per operating cycle, while there are others, such as testing the drywell-to-suppression-chamber vacuum breakers, which are to be performed during each

refueling outage. Also, all the safety-related instruments not specified in the TS are calibrated once per refueling outage. As part of a previously identified issue, the licensee has defined once-per-operating-cycle to be 18 months; however, no clarification has been provided for once-per-refueling-outage. As a result, there are several once-per-refueling-outage tests/calibrations which were performed in 1986 and 1987 which are currently scheduled on the MSTP for the "next refueling outage," which is projected for some time in 1991.

Therefore, by strictly interpreting the definitions, the interval for some of the once-per-refueling-outage surveillance tests could be as long as four or five years. The Team pointed out that this appears to be beyond the intent of the TS. The Team also noted that a licensee task force established to determine system operability prior to restart had also identified this issue and recommended that evaluations be performed on the once-per-refueling-outage surveillance tests to determine if and when they should be reformed. The licensee committed to evaluate the status of the once-per-refueling-surveillance tests and provide justification for those tests not rescheduled, prior to restart.

3.4.2.2 Logic System Functional Test and Simulated Automatic Actuation Procedures

The Team reviewed the procedures listed in Appendix D of this report to determine the adequacy of the licensee's performance of logic system functional tests (LSFT) and simulated automatic actuations (SAA). The review consisted of the indicated channel/train of the primary containment isolation system (PCIS) and the reactor core isolation cooling (RCIC) system LSFT and SAA, and the diesel generator (DG) initiation LSFT. The procedures were reviewed against the system drawings to ensure that they were technically adequate, that all relays and contacts were tested, that the procedures were properly approved, and that the tests were performed at the required frequency. The licensee uses a series of overlapping tests to satisfy the LSFT

and SAA. The Team noted that the licensee had a contractor review the adequacy of the LSFT and SAA tests during this outage. The contractor identified several deficiencies, which were corrected. The Team found that each procedure reviewed was technically adequate and that the testing sequence satisfied the Technical Specification LSFT and SAA frequency and scope requirements. The Team also noted that the format of the procedures was adequate and included: environmental qualification quality control (QC) witness points on transmitter calibrations; double verification on lifting and landing leads; fuse holder fit checks; and I&C management review upon test completion prior to the NWE review.

During the review of the RCIC isolation subsystem LSFT, the Team questioned why there was no LSFT on initiation logic. The Team acknowledged that it was not required by TS Table 4.2.8, nor was credit taken for it in the FSAR. However, TS 3.5.D.1 requires RCIC be operable (with reactor pressure greater than 150 psig and coolant temperature greater than 365 degrees F) and the TS definition of system operability requires that all subsystems also be operable. This would include the RCIC initiation logic. Also, the guidance provided by the Standard Technical Specifications indicates that an LSFT on the RCIC initiation logic should be performed every six months. The Team noted that Procedure Nc. 8.M.2-2.6.7, "RCIC Simulated Automatic Actuation," actually performs an initiation logic LSFT; however, it is scheduled at a once-per-18-month frequency, while TS-required LSFT's have a frequency of once per 6 months. This item is unresolved pending a licensee evaluation of the adequacy of the RCIC initiation logic LSFT frequency (88-21-02). The licensee committed to provide, before restart, the technical basis for the surveillance frequency.

3.4.2.3 Calibration Procedures

The Team noted that the licensee established a series of procedures, known as the 8.E series, to calibrate the safety-related instrumentation not specified in the Technical Specifications. This

instrumentation is normally used to record data necessary to complete IS-required surveillance tests or inservice testing of pumps and valves. The 8.E procedures are scheduled on a once-per-refueling-outage interval.

The Team performed a detailed review of Procedures No. 8.E.11, "Standby Liquid Control System Instrument Calibration," and 8.E.13, "RCIC System Instrument Calibration." Overall, the Team found the technical content and format to be adequate; however, two discrepancies were identified. Procedure No. 8.E.11 does not calibrate pressure indicator (PI) 1159. This PI was installed during the current outage and is used in the performance of Procedure No. 8.4.1, "Standby Liquid Control Pump Operability and Flow Rate Test." The Team also noted that Procedure No. 8.E.13 does not calibrate PI 1340-2. This PI is used in the performance of Procedure No. 8.5.5.1, "RCIC Pump Operability Flow Rate and Valve Test @ 1,000 psig." PI 1340-2 was installed and last calibrated during the 1984 outage when pressure transmitter 1360-19 was replaced with a Rosemount Transmitter. The licensee indicated that the procedures would be revised to correct the deficiencies.

3.4.2.4 Surveillance Test Observations

On August 16, 1988, the Team observed a portion of the performance of Procedure No. 8.M.2-2.10.1-5, "Core Spray System 'B' Logic Functional Test," Revision 13. The test was performed as part of the restoration of the "5" Core Spray System and as post work testing of relay 14A-K20B. The test was observed to ensure it was performed in accordance with a properly approved and adequate procedure. During the test, the Team noted that the technicians' performance was adequate. They conducted the test in a slow and deliberate manner and stopped when questions arose concerning mislabelled nameplates and the identification of some relay coil leads. In both cases, the questions were resolved before they proceeded. The Team noted that the I&C first-line supervisor monitored portions of the test. The test was also monitored by QA personnel as part of the surveillance monitoring program. QA personnel indicated that they observe approximately one surveillance test a week.

The test was stopped at Step 25 when the test results did not agree with the expected results delineated in the procedure. The step was supposed to verify the instantaneous pickup of the core spray pump start relay 14A-K12B. Subsequent licensee investigation revealed that the instantaneous pickup was removed as part of the degraded grid voltage modification (Plant Design Change (PDC) 88-07). The Team noted that PDC 88-07 had not yet been closed; however, an impact review performed prior to installing the modification failed to identify Procedure 8.M.2-2.10.1-5 as being affected by the PDC.

The Team noted that one of the licensee's self-assessment action items was to review the impact of PDC's (installed since October 1987) on LSFT's. The licensee's review began on October 1987 because this was the completion date of the contractor review noted above which verified the adequacy of LSFT/SAA tests. The Team noted that the contractor review produced an LSFT/SAA data base which cross references the safety-related components tested to the applicable LSFT/SAA test. This data was being used during the licensee's review. Four of the five PDC's involved in the licensee's review of impact on LSFT's have been completed. The remaining PDC (88-07) was under review when the problem with the core spray LSFT was noted. Twenty-one procedures have been identified as possibly being affected by the PDC and are currently under review. The CS functional test appears to be the only affected test run prior to completion of the PDC-procedure review.

The licensee indicated that a possible future improvement will be to use the LSFT/SAA data base to determine the impact of a PDC on procedures before implementing the modification.

3.4.2.5 Measuring and Test Equipment

The Team reviewed records, interviewed personnel, and toured storage areas to determine the adequacy of the licensee's program for control of measuring and test equipment (M&TE). Administrative control of the program is established by Procedure No. 1.3.36, "Measurement and Test Equipment."

The licensee has implemented a computerized system to issue and track M&TE. This system will only allow issuance equipment to authorized personnel, will limit the checkout period to only 24 hours, and will not issue M&TE if the sticker calibration date does not match the calibration date in the computer. The system also issues a M&TE traveler form to the user to identify usage on each plant device tested and each M&TE range used. This data is later entered into the computer to assist in evaluations if and when a piece of M&TE is found to be out of calibration. The Team reviewed two cases where M&TE was out of calibration and noted that the evaluations performed were documented in accordance with procedures and appeared thorough. Thus far, only electrical I&C and electrical M&TE are on the new computerized system; however, similar controls are being manually implemented for mechanical equipment until it is incorporated into the new system.

The licensee currently has two storage areas for M&TE: one for electrical/I&C and one for mechanical equipment. The Team toured each area and noted that the equipment was identified by a unique number and indicated calibration status. The Team found that the equipment was properly stored and that M&TE, out-of-calibration, on hold for repairs, or new equipment not yet in the system, were properly identified and segregated. The licensee indicated plans to go to only one storage area and to increase the number of staff issuing and controlling the M&TE.

The Team also reviewed the system for recalling equipment for calibration. The recall tracking is performed in accordance with Procedure No. 1.3.2, "PM Tracking Program." The Team reviewed several equipment calibration stickers during its tour of the storage areas and during observations of ongoing surveillance and maintenance activities. No equipment past its calibration due date was identified.

The Team found the licensee's control of measuring and test equipment to be adequate.

3.4.2.6 Inservice Testing of Pumps and Valves

The Team reviewed the status of the licensee's program for inservice testing of pumps and valves in accordance with the ASME Boiler and Pressure Vessel Code, Section XI.

The licensee submitted Revision 1A to the inservice test (IST) program on October 24, 1985. A meeting was held between BECo and the NRC on January 14, 1988, to discuss the licensee's proposed Revision 2 to the IST program. To minimize impact on the NRC review cycle, the licensee submitted an interim IST program, Revision 1B, on March 14, 1988, to address concerns identified by the NRC during review of Revision 1A. The licensee plans to submit Revision 2 after the Safety Evaluation Report on Revision 1B is issued. Revision 2 is to maintain the upgrades made to the program in Revision 1B and increase the program scope by adding more components (e.g., relief valves).

Control of the IST Program is established by Procedure No. 8.I.1, "Administration of Inservice Pump and Valve Testing." The Team reviewed the procedure and noted that while it defines the methodology for compliance to the IST program for pumps and valves, including analysis of test data, direction on corrective action, and establishment of reference values (additional guidance is contained in Procedure No. 8.I.3, "Inservice Test Analysis and Documentation Methods"), the organizational responsibilities and referenced IST program revision need to be updated. For example, the pump and valve testing is now scheduled through the MSTP instead of the compliance group, and a Senior ASME Test Engineer has been hired to implement the program. The licensee acknowledged the Team's comments and showed it a draft revision to Procedure 8.I, which is scheduled to be implemented when Revision 2 is submitted. The Team reviewed the draft procedure and noted that it provided additional detail on:

responsibilities, definitions, test requirements, compliance requirements, evaluation, disposition, post-maintenance testing, and administration and records maintenance. The draft procedure also provides a listing of the pumps and valves currently within the testing program and includes a cross-reference for individual test requirements to the approved PNPS procedure.

The Team noted that other improvements (planned or in progress) to the IST program include revising all the implementing procedures to upgrade them to Revision 2 and creating a position for a second ASME test engineer.

The Team reviewed several pump and valve test results for the standby liquid control, core spray, salt service water and low pressure coolant injection systems to verify that the acceptance criteria were met, that the results were properly evaluated and trended, and that the frequency of testing was increased when required. The Team noted that Procedure No. 8.I contains controls to change the MSTP data base test frequency when the deviations fall within the alert range. The Team reviewed changes to various pump reference values to ensure that they were justified and documented. The Team also checked the reactor building closed cooling water, salt service water, and standby liquid control system pumps to ensure that the IST vibration data point was properly marked. No deficiencies were identified during this review.

3.4.3 Conclusions

Based on observations, personnel interviews, and the review of procedures and records noted above, the Team concluded that:

1. The licensee has established and is implementing an adequate and effective program to control all surveillance activities at PNPS.
2. Responsibility for implementing the MSTP has been placed in a centralized, strong, forward-looking division.

3. The licensee was adequately implementing the IST program for pumps and valves. The Team noted that there are several planned improvements to the program involving administrative and implementing procedures and staffing to upgrade the IST program.
4. Licensee management is committed to improve the surveillance program, as evidenced by the upgrades planned or in progress in each area examined. These include: contractor data base reviews; increasing the scope of the IST program, increasing staffing; improved control over issuing and tracking M&TE; establishing an equipment history computer program; replacing the MSTP division lists with task cards; and improving conditional test scheduling.
5. With the exception of the few deficiencies noted above, the procedures were technically adequate.
6. The one concern identified was the licensee's need to resolve the once-per-refueling-outage scheduling deficiency.

3.5 Radiation Protection (RP)

3.5.1 Scope of Review

The Team reviewed various aspects of the radiation protection program during the inspection, with emphasis on the licensee's ability to safely support plant startup. Performance was determined from: observation of work in progress; periodic tours of plant areas; interviews with managers, supervisors, and technicians; and review of selected documents. The areas reviewed are as follows:

- 1) Organization and staffing;
- 2) Training, qualification and continuing education of RP technicians;
- 3) General employee training;
- 4) ALARA programs;
- 5) Control and oversight of work in radiological areas;
- 6) Control of locked high radiation areas;
- 7) Adequacy of laboratory (count room) equipment;
- 8) Availability and adequacy of portable RP survey equipment;
- 9) Adequacy of gaseous and liquid release monitoring systems;
- 10) Clarity and consistency of RP policies and procedures;
- 11) Audits.

3.5.2 Observations and Findings

3.5.2.1 Organization and Staffing

The organization of the radiation protection (RP) department has remained stable since the significant changes which were made early in 1988. The staffing level has remained constant and is adequate to support plant operations. The RP section manager described various enhancements

planned for the supervisory staff. An outline for qualification as Radiation Protection Manager, per Regulatory Guide 1.8, has been approved. One or two division managers within the RP section will be expected to qualify as Radiation Protection Manager to provide depth in the organization. Incentives have been approved for achieving this qualification. In addition, the three division managers will rotate assignments for cross-training purposes, and all will be encouraged to pursue advanced scholastic degrees. These efforts are expected to begin in the near future.

The Team observed some indications of isolated morale problems at the technician and first-line supervisor level which were attributed to several causes. Contributors include personnel and assignment changes within the organization resulting from rotation of radiation protection shift supervisors, an influx of new technicians, impending implementation of a new rotating work schedule, and a perceived lack of management presence in the field. In addition, weaknesses may exist in communications within the RP organization as evidenced by technician perceptions of a lack of technician input or review during the development or revision of RP policies and procedures. In summary, and in spite of these difficulties, the Team observed that the technicians and supervisors were generally enthusiastic and competent.

Another potential weakness results from the practice of rotating technicians through job assignments each three to six months. Although this practice may have merit for familiarization and job exposure purposes it may prevent or significantly delay the development of a high proficiency level in certain specialized technical areas, a concern particularly evident in the instrument repair and calibration facility. Here the RP technician is assigned to repair and calibrate a wide range of instrumentation, including gas flow detector cells, sophisticated computer-controlled automatic friskers, air pumps, and all alpha, beta, gamma and neutron survey meters. The area supervisor stated that he was attempting to resolve this problem by requesting an extension of the rotation cycle.

The RP section has 42 technicians, of whom 36 are ANSI 18.1 qualified. Only 21 have commercial experience. The section manager provided a shift staffing schedule for power ascension testing that will ensure that the experience will be adequately distributed among the individual shift crews.

3.5.2.2 RP Technician Training

The RP technician training and qualification program is certified by the Institute of Nuclear Plant Operations (INPO), uses INPO guidelines for development of instructional material, and uses the INPO exam question bank. The training is conducted in three phases over a period of two years or less, depending on experience. Upon completion of Phase 2, the technician is considered to be ANSI qualified and can issue radiation work permits. The third phase includes specialty tasks such as operation of the whole body counter and respirator fit testing.

Classroom training is provided at the offsite facility. The training facilities were adequate, well lighted, comfortable and equipped with practice equipment. The Team observed that most of the basic survey instruments were available, but laboratory-type gamma spectroscopy equipment, as well as ALARA mock-ups, were not available. This is typical of a single unit station. Most presentations appeared to rely on lectures with minimal use of audio-visual equipment. A review of selected lesson plans showed adequate technical content.

Classroom training is followed by an in-plant phase where the technician receives on-the-job training and demonstrates proficiency at various tasks. This is documented in a qualification folder. Qualified technicians will be provided with ongoing training on a six-week schedule. This will be contingent on implementation of a new six-section rotating work schedule. The

training department has begun drafting lesson plans which will cover a broad range of topics, including interpersonal skills training. The instructors must also complete formal qualifications. They were recently required to begin spending a certain number of hours in-plant between training cycles. This keeps them abreast of changes occurring in the plant.

The Team concluded that this program is well-controlled and documented and is aided by a dynamic first-line supervisor. The implementation and effectiveness of cycle training will be evaluated in the future. The licensee's current efforts are directed at completing initial qualification for the entire staff.

3.5.2.3 General Employee Training (GET)

All general employee training and in-processing is conducted at the on-site training center over a three-day period. Classrooms were spacious, comfortable, and well equipped. Ample training aids, as well as audio-visual equipment, were in evidence. A comprehensive student manual is given to each trainee along with copies of appropriate regulations and regulatory guides. Basic training involves 20 contact hours, while radiation workers receive an additional 3 hours. Respirator fit testing is also provided.

The two instructors associated with GET had completed the formal Staff Development program. Both have extensive experience and are well qualified. Although their teaching techniques could not be observed since no classes were in session during the week of this review, the Team concluded that the training content provided adequate direction to attendees. Both instructors spend time in the plant weekly to assess staff training needs.

The GET training is INPO certified. In addition, the training center offers five courses to all new supervisors. A new industrial safety training program is under development. An instructor has been hired and will begin providing training in occupational safety during the first quarter of 1989.

The Team concluded that management support of GET training was good, that the training was effectively conducted, and that it made a positive contribution to safety.

3.5.2.4 ALARA Programs

ALARA performance at this station had been a persistent weakness over several past SALP report periods.

The Team noted recent apparent improvement in upper management support for ALARA programs. Examples of this support are reflected in the re-evaluation of the 1988 ALARA goal from 600 to 390 manrem and formulation of several plans to reduce exposures. Also, the licensee is assigning an experienced manager to survey INPO, Electric Power Research Institute (EPRI), and several other nuclear stations to make a list of cost-effective exposure source term reduction techniques. The Station Director will then formulate a long-term program based on the findings of this survey. Another plan is to begin removal of abandoned in-place systems in 1989 which should remove unnecessary sources of exposure. A third project is underway to identify hot spots in plant piping and determine which of these could be reduced by flushing.

The ALARA staff also has plans to attend a training course and visit other stations to observe effective techniques. This staff is in the process of filling its final vacancy.

ALARA performance at the working level remains mixed. Licensing personnel developed a technique for conducting remote inspections of fire barrier penetrations using a flashlight mounted on a telescope. This concept may be applied in numerous situations and has the potential for significant dose savings. On the other hand, instances of failure to effectively use low-dose waiting areas were observed during work. The ALARA division manager is working to increase the sensitivity of all workers and technicians to ALARA practices.

The Team concluded that licensee attention to ALARA programs has significantly improved in recent months. The effectiveness and implementation of ALARA plans will be assessed in future NRC inspections.

3.5.2.5 Control of Work

During closure of a Confirmatory Order in the fall of 1987, NRC noted some improvement in the relations between the RP section and the other sections performing work. However, poor planning and lack of work control continued to be observed. During this assessment, further improvement in resolving these weaknesses was observed.

One indicator of poor planning is the number of radiation work permits (RWP) issued but not used. A review found that only a small fraction of RWP's issued are now unused. In addition, the use of "A" priority maintenance work requests by the Operations Department to expedite work has decreased significantly.

The use of a Radiation Protection Advisor assigned to the Maintenance department continues to be effective. This position was recently assumed by an experienced RP technician. He has introduced innovations, including frequent work group training sessions and installation of permanently situated boxes in the plant for contaminated tools.

The Planning Division is developing improved procedures for planning work. This section is responsible for coordinating with the RP and ALARA groups during the early phases of work planning. This allows adequate time for RWP preparation and ALARA reviews. Responsible section managers stated that this early maintenance-HP contact will be proceduralized in September 1988.

The Team observed that on-the-job cooperation between workers and RP technicians was good. A minor problem was noted in that RP technicians in the controlled area appeared unprepared to deal with a minor first-aid injury. Technicians were

uncertain in dealing with a worker with abrasions to his nose that caused bleeding. This was attributed by the Team to a lack of training and clear policies. On the other hand, technicians appeared well prepared to handle more serious emergencies.

3.5.2.6 Control of Locked High Radiation Areas

The licensee has previously incurred several violations for failure to properly control locked high radiation areas. This issue has been tracked as a NRC outstanding item (87-57-01). The licensee organized a task force to determine which lasting corrective actions would prevent a recurrence of these problems. Based on the findings of the task force, the control procedures were revised to place basic responsibility on the RP technician who signs out the door key. Further controls are provided by shift tours of all locked areas and by upgrading locking devices. Based on these actions, the Team concluded the licensee had appropriately addressed concerns in this area.

3.5.2.7 Laboratory Equipment

The adequacy and availability of RP laboratory equipment to support plant startup was reviewed. The licensee has available two multichannel analyzers (Nuclear Data 6700), several beta counters (BC4), and several alpha counters (SAC 4). The radiochemistry laboratory has redundant equipment for backup. This equipment is required to perform isotopic analysis of air samples for maximum permitted concentration (MPC) calculations, detection of degraded fuel conditions, and to support radwaste analysis. Procedures for the use of the equipment are available in the laboratory.

The Team noted that, at the time of the inspection, several pieces of laboratory equipment were awaiting repair or calibration. Only one BC-4 and one SAC-4 were operational in the lab. Both multichannel analyzers were awaiting repair parts. The supervisor in charge attributed this to the lack of proficiency of the technicians due to the rotating work assignment policy. This issue was discussed in Section 3.5.2.1.

3.5.2.8 Survey Equipment

The availability of properly calibrated survey equipment was reviewed. Survey equipment is used by RP technicians to measure dose rates, and surface and airborne contamination levels. Included in the review were the automatic personnel contamination detectors.

All equipment is calibrated and repaired in a facility on site, except for neutron survey meters. RP technicians are trained to perform all functions in the facility. The facility appeared to be adequately equipped to perform its task.

Stocks of equipment ready for issuance appeared ample and the calibration/repair backlog was minimal. This readiness may have been aided somewhat by reduced outage activity. The Team noted an improvement in that the new manager of the group has recently implemented a computer program that shows the status of each piece of equipment, the data base for which is updated each time an instrument is issued. Information that is captured includes users of the meter, calibration due date, and failure mode if placed out of service.

The Team concluded that an adequate supply of calibrated instruments is on hand to support routine operations and abnormal conditions.

3.5.2.9 Monitoring Environmental Releases

The operability of the environmental release monitors was verified. The two paths for a gaseous release are the main stack and the reactor building vent. The monitors were found to be operational and properly calibrated, with approved procedures available. The equipment is maintained by the Chemistry Group while the calculations of offsite doses required by the revised Radiological Environmental Technical Specifications (RETS) are performed by the RP section.

The single liquid release path monitor was operational. Due to elevated background radiation levels at the sodium iodide monitor, a new system has been installed parallel to the old system. The new system will offer increased sensitivity and will be brought on line in the near future.

3.5.2.10 Policies and Procedures

A sampling of RP procedures indicates that they are generally clear. The number of procedures controlling the RP department activities is extensive. However, the format varies from step-by-step instructions to a more general format. The RWP procedure is currently being revised to make the process less cumbersome and more useful. In general, the RP technicians did not feel adequately consulted during the revision of procedures. This issue was discussed in Section 3.5.2.1.

The Team concluded that the RP procedures were adequate to support startup.

3.5.2.11 Audits

Previous inspections found the licensee's internal audits and assessments of the RP program were primarily compliance-oriented. Currently, these audits are completed in several ways. Several peer evaluators were trained to make on-the-job observations. A Radiological Assessor is permanently assigned to the staff reporting to the Senior Vice President. The Management Oversight and Assessment Team (MO&AT) does monthly plant tours. Also, the QA Department recently transferred in two experienced RP personnel. In addition to the above audits and reviews, the Radiological Occurrence Report (ROR) system provides a method to capture input from workers and RP technicians.

A review of these efforts shows that a moderate level of success has been achieved in finding program weaknesses. However, the results have not been commensurate with the effort involved. The RP section manager stated that an effort is

underway to shift the emphasis of these audits to performance rather than compliance. The audit performed by QA in November 1987 is being used as a model. Licensee efforts in this regard are expected to be long term and are adequate at this time to support plant startup.

3.5.2.12 Control of Radiological Shielding

The Team reviewed the licensee's program for the installation, control, and removal of radiation shielding. This review concluded that the licensee's program for control of radiation shielding is well documented and that implementation is good.

The program guidelines are contained in PNPS Procedure 6.10-008, "Installation and Removal of Shielding." Responsibility for implementation of the procedural requirements fall under the auspices of the Radiological Technical Support Division. The procedural requirements for controlling this process appear well defined and comprehensive. Licensee personnel responsible for implementation of the procedure were well versed on procedural requirements and current field installations. Licensee records of field installations were current, had been reviewed at the required intervals, and were accurate.

3.5.2.13 Health Physics Training

The Team observed licensee personnel during a contamination control training exercise. The exercise simulated a spill of highly radioactive (3 Rem on contact) resin during transfer operations. The scenario document was well defined and included detailed timelines and instructions to the exercise controllers. The entire exercise was videotaped and replayed during the debriefing of participants. The exercise was well controlled and interviews with participants indicated that the individuals involved considered it to be an effective training device. Lessons learned and feedback from participants appeared to be well disseminated.

3.5.2.14 Hydrogen Water Chemistry System

The licensee has installed a system to inject hydrogen gas into the feedwater to reduce the potential for corrosion of reactor internal piping. This process will result in increased radiation levels onsite from increased radioactive nitrogen isotope levels in the system. A review of the impact analysis showed that a comprehensive plan to control exposures has been developed. A test run in 1985 resulted in the installation of a 16-foot high 20-inch thick concrete shield around the turbine. Moreover, special controls are programmed into the computer that controls the hydrogen injection. The cognizant engineer stated that these controls are designed to prevent increased exposure either onsite or offsite. Team review of these calculations showed that doses may in fact be lowered.

The Training Department is developing a training program for the RP technicians to review the change in radiation levels that occur with operations. This program was developed to refresh the RP technicians because of the extended shutdown and the increased levels of radiation in the shielded areas resulting from the addition of hydrogen. The RP section manager stated that a condensed revision of these presentations will also be given to all maintenance and operations personnel prior to startup.

3.5.3 Conclusions

The Team determined that progress has been made, that adequate staff and management oversight is in-place to achieve further progress, and that performance is adequate to support plant startup.

Licensee strengths include a well-controlled and well-organized training program for general employees and RP technicians. The use of an RP Advisor in the Maintenance Section, which had been effective in improving working relationships, has led to further initiatives in training and control of contaminated tools. The addition of this position has also resulted in improved planning and control of work.

Notable progress was observed regarding upper management support and emphasis on ALARA. This attention is expected to result in improving levels of performance over the next few years. Staff development programs for all levels of personnel, from technicians through managers, should considerably improve their level of performance. Control of technical problems, such as the radiological impact of hydrogen water chemistry and calibration status of survey meters, has improved.

A weakness was observed as a result of the rotational assignment of RP technicians that may affect their proficiency in performing certain highly specialized jobs. An additional weakness concerns the perception of poor vertical communications between management and RP technicians and workers. Although this issue has led to some incomplete understanding of policies and some morale problems, it has not significantly affected safety performance.

Additionally, vertical communications within the RP organization appeared somewhat weak. The Team detected a perception on the part of technicians that they have not been adequately involved in the changes being made in the RP Department policies and procedures. This perception apparently has resulted from RP management not effectively communicating the bases for these changes to the staff. There is also a perception that RP management is remote and not easily accessible. However, the Team determined that, despite this weakness, the attitude and safety approach of the RP Department staff has significantly improved and is adequate to support plant operations.

The licensee advised that a training program is being developed to refresh RP technicians concerning the change in radiological conditions on plant startup and the unique conditions to be created by the addition of hydrogen. A condensed version of this training will be provided to other radiation workers. Completion of this effort will be reviewed in a future NRC inspection.

3.6 Security and Safeguards

3.6.1 Scope of Review

Prior to the plant shutdown in April 1986, NRC had identified serious concerns regarding the implementation and management support of the security program at Pilgrim. The licensee has been aggressively pursuing a comprehensive course of action to identify and correct the root causes of the programmatic weaknesses in physical security. The most recent SALP (50-293/87-99) covering the period February 1, 1987 to May 15, 1988, determined that the licensee has demonstrated a commitment to implement an effective security program. The licensee's security organization has been expanded with the addition of experienced personnel in key positions, significant capital resources have been expended to upgrade security hardware, and equipment and program plans have been improved.

During the IAT inspection, all phases of the security program, including management support, staffing, organization, and hardware maintenance, have been reviewed to assess the effectiveness of the program implementation. The results of the review are described below in general terms to exclude any safeguards information.

3.6.2 Observations and Findings

3.6.2.1 Review of Security Program Upgrades

The Team reviewed the progress made to date on the security program improvements committed to by the licensee as a result of previous NRC enforcement action. The licensee was advised by the Team that progress on these improvements will continue to be monitored during future NRC inspections. Those commitments and their status are as follows.

<u>Project</u>	<u>Status</u>
Protected Area Perimeter	The upgrades of the perimeter barrier, intrusion detection system, and assessment aid system are complete.

<u>Project</u>	<u>Status</u>
Protected Area and Perimeter Lighting	Installation of upgraded lighting is approximately 95% complete. Four light stanchions remain to be installed. The lighting system as installed meets regulatory requirements.
Main and Alternate Access Control Points	The designs for the new (upgraded) access control points are complete and new package search equipment is on site. Installation of new package and personnel search equipment and full length turnstiles is scheduled for completion on September 28, 1988, in the site's main access point. Installation of new package search equipment in the site's alternate access point is also scheduled for September 28, 1988.
Vital Area Analysis	The vital area analysis, including walkdown of all vital areas to verify barrier integrity, and issuance of the report, is complete.
New Security Computer	The selection of the new computer has been made and a purchase order for the computer has been issued. The licensee is currently working with the vendor on software options. The delivery of the new computer is scheduled for the first quarter of 1989, with installation to follow.

3.6.2.2 Followup on Previously Unresolved Item

(Closed) Unresolved Item (50-293/87-44-01): Neighborhood checks for licensee employees being assigned to the site were not being consistently conducted as part of the access control program. The neighborhood checks were not a regulatory requirement and it is a licensee-identified issue. During this inspection, the Team verified that the licensee has conducted a review and identified all site personnel who had not been subjected to neighborhood checks. For those employees with less than three years of service with the licensee, neighborhood checks were subsequently conducted. For employees with more than three years with the company, a review of the personnel file was conducted and a memorandum was put into the file to indicate that the review was being made in lieu of the neighborhood check. The acceptability of this alternative to the neighborhood checks was reviewed by NRC prior to its implementation and was found satisfactory.

3.6.2.3 Security Plan and Implementing Procedures

The Team met with licensee representatives and discussed the NRC-approved Security Plan (the Plan). As a result of these discussions, and a review of the Plan and its implementing procedures, the Team found that the implementing procedures adequately addressed the Plan's commitments. In addition, all security personnel interviewed demonstrated familiarity with the Plan, implementing procedures, and NRC's security program performance objectives.

3.6.2.4 Management Effectiveness - Security Programs

An in-depth review of the licensee's management effectiveness was conducted by NRC in April and May 1988 and documented in Inspection Report No. 50-293/88-18. During that inspection, the Team concluded that the licensee has continued with its initiatives and taken significant actions to further improve the effectiveness of the security organization. It was also concluded that the existing organization should provide the capability to monitor the program properly.

During its inspection, the Team independently concluded that there is a strong management team in place based on the experience of the expanded proprietary security organization, the effective interaction both between members of the security organization and with other departments, and the effective oversight of the contract security organization.

3.6.2.5 Security Organization

On August 16, 1988, at 10:00 p.m., the security contractor for PNPS was changed from Globe Security Systems to the Wackenhut Corporation. The Team reviewed the licensee's and the contractor's transition plans, and interviewed numerous management and union security personnel prior to the transition. Also, the Team was onsite during the transition for direct observations. The transition was somewhat simplified by the fact that all Globe employees that applied for positions were retained by Wackenhut. The Team determined that, because of comprehensive transition planning, the change in the contract security force was accomplished without any compromise of security and with minimal disruption to security operations.

3.6.2.6 Security Program Audit

The Team reviewed the monthly corporate audit reports. These audit reports were of good quality and were generated as a result of corporate oversight of the site security program. The findings in these reports were minor and not indicative of any major programmatic problems. The corrective actions were appropriate for the findings.

3.6.2.7 Records and Reports

The Team reviewed various security records, logs, and reports, including patrol logs, central alarm station (CAS) logs, visitor control logs, and testing and maintenance records. All records, logs, and reports reviewed were complete and maintained as committed to in the Plan.

3.6.2.8 Testing and Maintenance

The Team reviewed the testing and maintenance records and procedures. The review disclosed that the preventive maintenance procedures were comprehensive and that the licensee now has in place a program that provides for prioritization of security maintenance by the security department. The maintenance support to the security department has improved as a result of the security department assigning priority to the maintenance work. The use of compensatory measures for inoperative equipment is minimal.

3.6.2.9 Locks, Keys and Combinations

The Team reviewed the installation, storage, rotation and related records for all locks, keys and combinations and determined that the licensee was meeting the commitments in the Plan and its implementing procedures.

3.6.2.10 Physical Barriers - Protected Areas

The Team physically inspected the protected area barriers. It was determined by observations that the barriers were installed and maintained as described in the Plan. Progress on upgrading the barriers is addressed in Section 3.6.2.1 of this section.

3.6.2.11 Physical Barriers - Vital Areas

The Team physically inspected the vital area barriers and determined that the barriers were installed and maintained as described in the Plan.

3.6.2.12 Security System Power Supply

The Team reviewed the security system power supply system and determined that it was in accordance with Plan requirements. The Team noted that as a result of the approval of a recent Plan revision, improvements for protecting the security power supply are underway, with work expected to be completed by September 28, 1988.

3.6.2.13 Lighting

The Team observed lighting within the protected area. All areas were lighted in accordance with commitments in the Plan. Progress on upgrading the lighting is addressed in Section 3.6.2.1.

3.6.2.14 Compensatory Measures

The Team reviewed the licensee's compensatory measures and determined that their use to be consistent with the commitments in the Plan. As a result of the security program upgrades addressed in Section 3.6.2.1, the need for compensatory measures for degraded security equipment has been dramatically reduced. Further reductions in the use of compensatory measures will occur as project upgrades are completed.

3.6.2.15 Assessment Aids

The Team reviewed the licensee's use of assessment aids and determined by observation that the assessment aids are installed, functioning and maintained as committed to in the Plan. Progress on upgrading the assessment aids is addressed in Section 3.6.2.1.

3.6.2.16 Access Control - Personnel and Packages

The Team reviewed the access control procedures for personnel and packages and determined that they are consistent with commitments in the Plan. This determination was made by observing personnel access processing during shift changes, visitor access processing, and by interviewing security personnel about package access procedures. The status of upgrades in the access control points is addressed in Section 3.6.2.1.

3.6.2.17 Access Control - Vehicles

The Team reviewed vehicle access control procedures and observed vehicle searches at the Main Vehicle Gate. It was determined that vehicle searches were being conducted consistent with commitments in the Plan.

3.6.2.18 Detection Aids - Protected Area

The Team observed penetration tests of approximately 25% of the licensee's intrusion detection system on August 17, 1988. The remaining 75% was not tested during this inspection; however, previous test records were reviewed and the records indicated that the system was operating as described in the Plan and implementing procedures.

3.6.2.19 Detection Aids - Vital Area

The Team observed the testing of intrusion detection aids in selected vital areas and determined that they were installed and functioning as committed to in the Plan.

3.6.2.20 Alarm Stations

The Team observed the operation of both the Central Alarm Station (CAS) and the Secondary Alarm Station (SAS) and found them to be in accordance with Plan commitments. During the previous inspection (50-293/88-16), a concern was identified that the licensee was diverting an alarm station monitor from security duty to respond to fire protection system and health physics alarms. During the IAT inspection, the Team noted improvements in that there is a marked decrease in the number of nuisance alarms, as a result of the removal of the fire door and health physics doors from the security alarm system.

3.6.2.21 Communications

The Team observed tests of all communication capabilities in both the CAS and the SAS. The Team also reviewed testing records for the various means of communications available to security force members and found them to be as committed to in the Plan.

3.6.2.22 Training and Qualification - General Requirements

The Team reviewed the licensee's Training and Qualification Plan and implementing procedures and determined that they were being implemented as committed to in the Plan.

3.6.2.23 Safeguards Contingency Plan Implementation Review

The Team reviewed the licensee's Contingency Plan and implementing procedures and determined that all exercises were being performed by the security organization as committed to in the Plan.

3.6.2.24 Protection of Safeguards Information

The Team reviewed the protection and handling procedures for Safeguards Information (SGI) and determined that the licensee had completed an inspection of each office onsite that handled and stored SGI. The inspection results indicated that the SGI assigned to each office was accounted for and was being stored in accordance with established licensee procedures.

3.6.3 Conclusions

A comprehensive review of the licensee's security program determined that the licensee has established and is implementing a significantly improved security program over that which existed when the station was shutdown in April 1986. Upgrades to the security program include a greatly expanded proprietary security organization, major installation of state-of-the-art equipment, improved security maintenance support, and upgrades to plans and procedures.

3.7 Training

3.7.1 Scope of Review

The Team assessed the scope, quality, and effectiveness of the licensee's training programs. Included in this review were the licensed and non-licensed operator training programs and the programs for technical and general training of the plant staff.

3.7.2 Observations and Findings

3.7.2.1 Operations Training

Operations Training Programs are outlined in PNPS Nuclear Training Manual, T-001, Part 3, and have received INPO accreditation. The Operations Training Programs include initial and requalification training for licensed operators, initial and continuing training for non-licensed operators, Shift Technical Advisor (STA) training, and SRO certification training. The Team reviewed these programs and discussed various aspects of the programs with members of the licensee's training and operation's staff. The Team reviewed eight Operator and Senior Reactor Operator training records to verify compliance with Section 3.5.5 of the Training Manual. To evaluate the effectiveness of the training programs, the Team observed classroom and simulator training; interviewed licensed operators and senior operators, non-licensed operators and STAs; reviewed several training evaluation and feedback forms from classroom and simulator training conducted during the current requalification cycle; and observed ongoing operations in the plant.

Overall, the Team determined that the Operations Training Programs are adequate and effective. Classroom and simulator training observed appeared to be effective. Instructor preparation was good and the lesson plan content was complete. During observations of classroom training for PDC 88-07 involving the degraded voltage modification, the Team noted that the depth of knowledge being presented was adequate and student participation was encouraged. After observing the conduct of the annual simulator operating exam, the Team noted improved communications

between members of the operating crew. In addition, the Team noted the simulator examination was also being observed by licensee upper management. Discussions with training and operations personnel confirmed that strong upper management attention and support for all aspects of the licensed training programs is evident. Interviews with licensed operators indicated that overall they are very satisfied that training programs are well-suited to their needs, and that the programs are responsive to their feedback. Operators indicated that the training program has greatly improved over the past year with the incorporation of simulator training into the requalification program.

Discussions with Operations Training staff indicated sufficient staffing to conduct training programs. Thirteen instructors are currently receiving Senior Reactor Operator (SRO) certification training and are expected to be fully certified by the end of 1988. The use of experienced PNPS instructors instead of contractors for the operations training programs should enhance the quality of the licensee's programs as well as contribute to the depth of in-house operational expertise.

Recent additions to the licensed requalification program include the incorporation of Emergency Operating Procedure (EOP) proficiency training. This includes at least 4 hours devoted to EOP review in the classroom and/or simulator during each 32-hour segment of the program. (Each operator normally receives one segment of requalification training every five weeks.) Also, the exam structure at the end of each session has been modified to include written and simulator operating exams, which will aid the training staff in determining the effectiveness of the programs on a more frequent basis. In addition, the training staff appears to carefully track attendance in requalification training to assure that everyone required to attend is trained in each module of the requalification program.

The operation's training staff appears to have a very effective working relationship with the operations department. They meet to discuss training needs on a frequent basis. Through these meetings, the training department appears able to sufficiently track and schedule the licensed training either required or requested to be completed prior to restart. In addition, the operation's department often provided support during simulator examinations.

The Team reviewed the licensee's special training program for the sixteen licensed operators (14 RO's and 2 SRO's) who currently hold NRC licenses which are limited pending on-watch training during the Power Ascension Program. The Team discussed various aspects of the program with members of the licensee's training and operations staff. The Team noted that the licensee has established a structured and supervised program to assure completion of NRC requirements to allow removal of the individuals' license limitations. Following a discussion with the Team regarding plans for ensuring that each operator performs a sufficient number of reactivity manipulations, the licensee representative stated that an attachment to the special program would be added to further clarify what constitutes an acceptable manipulation.

The Team observed the operations department staff on four days of consecutive shift rotation. These observations verified the overall effectiveness of training. For example, on-shift communications, an area of emphasis in simulator training, was formal and effective. However, during a walk-through with an equipment operator (non-licensed) of EOP Satellite Procedure 5.3.26, the Team noted several discrepancies in the procedure. It also noted that the EO and an SRO misunderstood a step in the procedure. Upon investigation of these problems, the licensee determined that a decision to train only the EO's and not the licensed operators on the field portion of the satellite procedures contributed to the misunderstanding. These issues are discussed in detail in Section 3.2.4.

Additional Team followup of the problems found during the above-mentioned procedure walk-through identified a weakness in the licensee's method of determining the need for additional training on new procedures and procedure changes. The licensee's current method incorporates review of ORC meeting minutes to determine newly approved procedures or procedure changes requiring training. However, a delay of 30 to 45 days is not unusual between the meeting and the distribution of formal minutes. For example, Procedure 5.3.26 had been revised since equipment operator training was conducted in March and April 1988. The ORC meeting minutes which addressed this procedure change had not been received by the training department as of August 18, 1988, 42 days after the ORC meeting on July 6, 1988.

The Team discussed the issue with a licensee training department representative who stated that the department recognized this concern and was preparing to implement, in October 1988, a more timely method for determining the needed training.

During the inspection, the licensee committed to accelerate implementation of certain features of the improved program, such that the training department will become aware of procedure changes within approximately one day following the ORC meeting. This will allow the training staff the opportunity to review the procedure changes and determine the need for training prior to issuance of the approved procedure. If the training department determines that training is required prior to issuance of the procedure, the department will have the ability to delay the procedure issuance. The licensee representative stated that an internal work instruction detailing this process was being written and would be approved by ORC within about a week. In addition, the training staff will review their backlog of ORC meeting minutes to determine which procedure changes have not been addressed and will take appropriate action. These actions planned by the licensee appeared very responsive to the Team's concerns.

3.7.2.2 Technical and General Training

Nuclear Training Manual, T-001, Parts 4 and 5, outline the licensee's technical and general training programs. Included are training programs in maintenance, health physics, chemistry, fire brigade, emergency plan, supervision, and technical training for staff and managers. The Team reviewed these programs and discussed various aspects of them with members of the licensee's training, technical, and supervisory staff. To evaluate the effectiveness of the training programs, the Team observed classroom instruction; interviewed radiological controls and radiological chemistry (radchem) technicians, QA engineers and first-line supervision; reviewed classroom training evaluation and feedback forms; and observed ongoing work in the plant.

Overall, the licensee's training programs were found to be adequate. Classroom training observed appeared to be effective and student participation was strongly encouraged. In-house staffing for those training programs appeared more than sufficient. The following relatively new training programs are indicative of licensee initiatives to develop employee skills:

- apprentice programs for maintenance, health physics, and rad chem technicians; and,
- technical training for newly assigned supervisors.

Additional training programs currently being developed in industrial safety and safety awareness, along with the licensee's CPR program, show the licensee's positive attitude in those areas.

The Team's observations of work in the plant during this inspection verified the overall training effectiveness. However, inadequacies in maintenance post-work testing appeared to be the result of lack of training for the maintenance planning group and first-line supervisors on the post-work testing portion of the new maintenance program (See Section 3.3.2.6).

3.7.3 Conclusions

The licensee's training programs appear to be very good. Team findings in all functional areas indicated overall effectiveness of the training implemented. Examples of areas where training may have needed to be conducted sooner include EOP satellite procedures and the post-work testing program. A weakness was identified in the licensee's method of determining training needed for new procedures and procedure changes.

The licensee appears to have made a strong commitment in the area of licensed operator training, as exemplified by increased staffing, simulator use in requalification training, strong interface between training and operations management, and increased attention and support from upper management. In addition, the creation of new programs for supervisors and apprentices reflects an effort by the licensee to effectively promote employee development.

3.C Fire Protection

3.8.1 Scope of Review

The Team's evaluation of the fire protection program focused on the maintenance of fire protection equipment, the reliance on compensatory measures for degraded equipment, and the performance of personnel on the fire brigade and standing fire watches.

3.8.2 Observations and Findings

Licensee senior management established a station goal of reducing the number of open fire protection corrective maintenance requests (MR's) to 40 from a high of 300. This goal was reached in June 1988. This reduction is indicative of the overall improvement of the material condition of fire protection equipment and systems. The number of MR's began climbing two weeks before the IAT inspection, and reached 63 during the second week of this inspection. The increase was mainly for low-priority MR's.

Fire protection MR's are tracked as a station performance indicator and this increasing trend received prompt senior management attention. The licensee is currently contracting to bring in additional fire protection maintenance support by the end of August 1988. The fire protection manager meets daily with operations, maintenance and planning sections to schedule MR's and develop the station's work plan. The Team concluded that the licensee is giving proper management attention to fire protection MR's.

There are over 5,000 fire barrier penetration seals at PNPS. The licensee's tagging system has been effective in identifying these penetrations, with no untagged penetrations or degraded penetration seals observed by the Team.

The number of fire watch postings has been reduced from 145 a year ago to 45 prior to this inspection. Fifteen of these remaining postings will be eliminated by changes to the fire protection program which are currently being reviewed by NRC. Another twelve will be eliminated when the licensee completes Engineering Services Request (ESR) 88-339, "Alarm delays on non-vital CAS alarms." This ESR will provide a means to electronically monitor fire doors without undue distraction of security personnel from their primary function. The remaining 18 fire watch postings are due to degraded equipment for which repairs are currently being planned.

Because TS's allow one individual to rove and cover more than one fire watch posting, the number of people on shift committed to fire watch activities is substantially lower than 45. Two personnel per shift are assigned to cover these fire watches. In discussions with the Team, the fire watches appeared knowledgeable about their duties. The Team reviewed several fire watch postings in the plant and identified no concerns. All fire watch rounds were completed on schedule.

The Team observed the on-shift fire brigade respond to an unannounced fire drill. The drill scenario was a simulated main transformer fire with a concurrent failure of the deluge system. The brigade leader developed a successful fire fighting strategy. The brigade members responded promptly in full fire fighting gear. Communications between the brigade and the control room appeared to be adequate. The fire brigade's first-line supervisors observed the drill on their own initiative. The fire protection training instructor was also found to be knowledgeable and enthusiastic about the training program.

3.8.3 Conclusions

Effective management by the fire protection manager and support by senior management are shown by the attention given to the material condition of fire protection equipment and reduced reliance on compensatory measures for degraded equipment. Completion of licensing actions and an ESR will further reduce the number of fire watch postings. There is good identification and control of fire barriers. Personnel assigned fire watch and fire brigade duties are knowledgeable about their duties and perform them properly. The fire protection division is well staffed to meet program needs.

3.9 Engineering Support

3.9.1 Scope of Review

NRC found licensee engineering support to be strong in the past two SALP reports. Because of this history of good performance, engineering support was not selected as a specific area of focus for this inspection. Instead, observations relative to engineering support were made by the Team while it inspected the other functional areas.

3.9.2 Observations and Findings

The Team found that engineering support to the facility is generally very effective. In particular, the Systems Engineering Division functions well to meet plant needs. Also, engineering support to maintenance has improved and is enhanced by the improved maintenance work process and the effective performance of the maintenance engineers.

The Team noted that a number of technical issues, including some NRC open items, as well as licensee-identified items, require NED resolution before plant restart. They are being tracked and pursued for resolution by NED.

During tours of the control room, the Team noted the minimal use of certain human engineering features, such as color-codes, meter "banding" (e.g., marking of normal, alert, and fail positions on meter and gauge faces), and system lineup memory aids. Based on discussions with NED personnel, the Team determined that the licensee performed a detailed control room design review (DCRDR) and received comments on it from the NRC Office of Nuclear Reactor Regulation. A supplemental licensee DCRDR report is required four months after the end of the current outage.

Currently, the licensee's DCRDR project has identified about 140 proposed human engineering improvements which are being evaluated and prioritized. A few were incorporated into design changes this outage. The Team noted that some of the remaining improvements were relatively simple, from an engineering perspective, but could significantly enhance control room human factors. The Team asked whether implementation of some of these items could be accelerated relative to the other, more complex items which may require more detailed engineering and a plant outage to install.

The licensee indicated that these simple improvements, categorized by the licensee as "Paint-Label-Tape," are included in the current 1989 budget. The licensee also committed to evaluate control room human factors during the Power Ascension Program and to include an update regarding the schedule and scope of these "Paint-Label-Tape" items in their report to NRC at the completion of the Power Ascension Program. The licensee was very responsive on this issue. The Team noted that (1) licensee personnel have performed well in the simulator under NRC observation, and (2) there has not been any pattern of performance problems traceable to control room human factors. Thus, the Team concluded that the licensee's approach to this issue is acceptable.

The Team reviewed the licensee's program for the control of transient materials. This review included the licensee's methods for identifying, tracking and removing non-permanent equipment such as tools, gas bottles, and scaffolding located in plant areas where safety-related equipment is housed. The licensee currently assigns responsibility in this area to the Systems Engineering Group (SEG). Station Instruction SI-SG.1010, "Systems Group Systems Walkdown and Area Inspection Guidelines," details the licensee's program for controlling transient materials. Materials so identified during weekly walkdowns by system engineers are documented and are either removed or their presence justified in writing. If the material is allowed to remain in the process building, a seismic missile hazard analysis is performed under Station Instruction SI-SG.1015, "Potential Seismic Missile Hazard," and appropriate measures are implemented to ensure that the materials are properly secured. The licensee is compiling a data base which identifies transient materials which must be removed prior to startup. The program appears to be comprehensive and adequate.

During plant tours, the Team questioned the licensee concerning the installation of splash shields and personnel barriers in the areas of safety-related instrumentation. Specifically, the Team questioned the seismic response of the structures and the effect they may have on safety-related structures.

The fire water spray shield was installed during the current outage. This plant design change was processed under current licensee procedures which require a seismic response analysis prior to modification approval. Personnel barriers installed during the mid-1970's recently had seismic analyses performed on their current configurations. These analyses found them satisfactory.

Based on this information and on a review of licensee documentation, the Team had no further questions.

3.9.3 Conclusions

The Team concluded that engineering support continues to be effective and identified no weaknesses. The licensee has committed to evaluate potential near-term improvements in control room human engineering during power ascension testing.

3.10 Safety Assessment/Quality Verification

3.10.1 Scope of Review

The objective of this inspection was to evaluate the effectiveness of the licensee's self-assessment programs. The inspection focused on determining whether these programs contribute to the prevention of problems by monitoring and evaluating plant performance, providing assessments and findings, and communicating and following up on corrective action recommendations. The inspection consisted of a documentation review, personnel interviews, and observations of meetings and work.

3.10.2 Nuclear Safety Review and Audit Committee

The Nuclear Safety Review and Audit Committee (NSRAC) is an independent body responsible for performing senior-management-directed reviews of activities affecting nuclear safety. The NSRAC reports to the Senior Vice President - Nuclear (SVP-N). Membership on the committee is composed of senior licensee management personnel augmented by consultants.

The Team reviewed the NSRAC procedures manual, Technical Specification 6.5.B, meeting minutes, audit reports, and associated NSRAC reports and correspondence. The Team also attended a full NSRAC meeting at the station on August 2, 1988.

A review of the committee meeting minutes for the period between January 1987 and June 1988 verified that Technical Specification requirements have been met with respect to the composition, duties, meeting frequencies, and responsibilities of the committee. The composition and charter of the committee was significantly revised in February 1988.

The selection process for members was designed to assure a broad-based, independent review of facility activities and to minimize the potential for cost and schedule pressures to influence the committee's reviews and findings. The current committee is made up of ten members appointed by the SVP-N. Of the ten members, five are consultants, including the Committee Chairman. Only two members of the committee hold line responsibility for operation of the plant. Only one member, also a consultant, belonged a year ago. To enhance the perspective of the new members, the licensee implemented an annual training program. The Team was provided with a matrix indicating the experience of

current committee members relative to Technical Specification requirements and verified the committee collectively possesses a broad based level of experience and competence. The committee charter, as detailed in NSRAC Procedure 101-1, also does not allow the use of alternate members, although these are allowed by the Technical Specifications. After a review of recent membership changes, and discussions with the NSRAC Coordinator, the Team verified that the collective competence of the committee membership has been maintained as changes were made.

NSRAC currently conducts meetings approximately once a month. Since the beginning of 1988, seven meetings have been conducted, six of which were held at the site. This is significantly more than the once-per-six-months minimum required by the Technical Specifications. Three additional meetings are scheduled for 1988. In addition, individual subcommittees may hold additional meetings at the site. NSRAC also intends to meet at the site in September with several key members of station management to review restart preparations and plans to provide its own independent recommendations for restart readiness.

NSRAC uses subcommittees effectively to review specific areas of interest. Currently, six subcommittees are established: (1) safety evaluations; (2) operations/maintenance; (3) training/security/fire protection; (4) radiation control/chemistry/emergency preparedness; (5) quality overview; and, (6) engineering/technical. Each subcommittee is chaired by a NSRAC member, and is composed of additional personnel appointed by the committee. The subcommittees provide reports to the full committee during their scheduled meetings. The subcommittees are especially useful in performing documentation review to allow more time for open discussions at the meetings.

A stronger NSRAC involvement in station activities is evident not only in the recent site meetings and effective use of subcommittees, but also in scheduled site tours and audit participation. The NSRAC has established a schedule for individual committee members to perform station tours and report the results to the full committee. NSRAC has also designated individual members to participate in selected QA audits throughout the year.

The Team reviewed selected audits conducted under the cognizance of NSRAC, which are required by Technical Specifications. The audits reviewed were thorough, timely, and the noted deficiencies have been corrected or are being tracked. The audit reports reviewed included a third party assessment of the adequacy of the QA program, and QA audits

of Technical Specifications, administrative controls, operations, chemistry, radiation protection, and inservice testing. In addition, special audits were recently conducted concerning shutdown from outside the control room, the salt service water system, and NSRAC activities.

The current committee has an effective formal tracking system for all "concerns" forwarded to management and committee followup items. The "concerns" reviewed were clearly transmitted to the SVP-N. However, review of recent meeting minutes by NRC revealed that a number of "recommendations" had been forwarded to the SVP-N, but a formal response had not been received. The committee also did not formally track resolution of these recommendations. Further investigation by the NSRAC Coordinator determined that although the items had not been tracked, the specific recommendations had been implemented, or were incorporated into another corrective action process.

During NSRAC Meeting 88-04, conducted on May 24, 1988, the Operations and Maintenance Subcommittee presented a report on the conduct of the Operations Review Committee (ORC). NSRAC raised concerns over whether the ORC was fully meeting the intent of its duties required in the Technical Specifications. The report identified four specific findings of deficiency. They included:

- Inadequate method of reviewing changes to safety-related procedures;
- Lack of ORC-prepared reports resulting from ORC investigation of a Technical Specifications violations;
- Lack of specific review and reports of facility operations by ORC; and,
- Lack of formality in the conduct of ORC meetings.

After the discussion, NSRAC concurred that the ORC performance issues should be formally raised as a concern to the SVP-N. The NSRAC concern (88-04-01) was transmitted to the SVP-N on May 27, 1988. The concern stated that NSRAC's overall assessment was that ORC's conduct and administration needed substantial improvement. Specifically, the concern stated that the established process did not appear to foster adequate depth and discipline for substantive independent reviews. In addition, NSRAC noted that of the 40 meetings conducted in 1988 prior to the review, neither the Station Director nor the Plant Manager had attended, based on its review of the meeting minutes.

The NSRAC concern was responded to on June 22, 1988. In response, the Station Director initiated revisions to the ORC Charter and Procedure 1.3.4, "Procedures," to accurately describe the specific methods by which ORC met the procedure and operations review requirements. In addition, the Station Director attended an ORC meeting on June 22, 1988, and is considering additional initiatives to improve the conduct and administration of ORC activities. NSRAC closed the concern at the August 2, 1988 meeting, but initiated a followup item to continue to monitor ORC performance. In addition, NSRAC members were encouraged to attend ORC meetings as observers. NRC's review of ORC performance identified similar deficiencies and concluded that additional actions to strengthen some ORC functions were warranted (See Section 3.10.3).

Based on meeting attendance and review of recent meeting minutes, the Team noted that the NSRAC reviews have been thorough and focused on improving performance in areas important to safety. During the August 2, 1988 NSRAC meeting, the Team noted that the discussions were frank and open, with the reviews concentrated on recurring and emerging issues. The areas of emphasis have included 50.59 reviews, ORC performance, corrective action programs, procedure adequacy, and management depth.

Due to the limited number of "concerns" issued by NSRAC since revision of the committee in February 1988, the Team could not reach a conclusion on the responsiveness of the station organization to NSRAC. It appears at least in one case pertaining to ORC performance, that the response was not comprehensive. However, all other "concerns" reviewed were responded to adequately.

3.10.3 Operations Review Committee

The function, composition, and responsibilities of the Operations Review Committee (ORC) are described in PNPS Technical Specification 6.5.A. In addition, PNPS Procedure 1.2.1, "Operations Review Committee," describes in greater detail the authority and responsibility of the ORC at the Pilgrim Station. For this inspection, the Team reviewed the minutes of ORC meetings 88-40 through 88-60 (April 1, 1988 through July 5, 1988) and observed the conduct of three regularly scheduled and two special ORC meetings (ORC Meetings 88-80, 81, 82, 83 and 86). In addition, the Team interviewed various ORC members and alternates.

The inspection focused on whether ORC operations satisfied current Technical Specification requirements; whether the ORC was meeting its responsibilities identified in PNPS Procedure 1.2.1, and whether the ORC was responsive to recommendations for improvements identified during NSRAC and QA audits of its operations.

3.10.3.1 Compliance with Technical Specifications and Procedures

By reviewing existing documentation, and through direct observation of ORC meetings, the Team has determined that the Technical Specification requirements for the ORC composition, quorum, meeting frequency, authority, and records are being satisfied. During the period reviewed, the Team noted that the ORC reviewed plant procedure changes, plant design changes (PDCs), Field Revision Notices (FRNs), and Licensee Event Reports (LERs), as well as proposed revisions to the security plan, to the inservice inspection program, to the emergency plan and to fire protection program implementing procedures. The ORC members and alternates are appointed by memorandum from the Station Director and cannot serve on the committee until they have successfully completed the station ORC training course. There is also a required reading review program used by the Training Department as a retraining program for ORC members and alternates. The Team reviewed the training course material and determined that it had an appropriate emphasis on assuring safe operation as well as on regulatory requirements.

The ORC at Pilgrim Station has been meeting regularly every Wednesday and has a scheduled "special" meeting every Friday on an as-needed basis. The ORC met an average of about twice a week, which is well above Technical Specification requirements.

While there was evidence in the minutes of discussions about LERs, PDCs or FRNs, the preponderance of the minutes described changes to procedures. The Team saw no reference of ORC reviews of Failure and Malfunction Reports. The ORC has a system for following issues identified during discussions which requires a formal response to the ORC and a review of the response by the ORC to assure that the response resolved the initial concerns.

The Team reviewed the closeout process for ORC followup items and determined that, in one case, an item (88-58-01) may have been closed prematurely. During a discussion among the Team, the ORC Chairman, the Design Section Manager, and the Construction Division Manager, the ORC Chairman agreed that the item should be reopened for additional review. During ORC Meeting 88-82, the item was reopened.

By observing the ORC, the Team concluded that the committee members and alternates are concerned with assuring the safe operation of the facility. Discussions focused on the impact of items on safety systems, as well as whether the items being discussed met regulatory requirements or constituted unreviewed safety questions. The Station Director also attended one of the regularly scheduled ORC meetings during the inspection period.

- During its review, the Team identified two weaknesses in the operation of the ORC. They are the Technical Specification (TS) review of plant operations (T.S. 6.5.A.6.e) and the TS requirement to investigate violations and prepare a report covering the evaluation and recommendations to prevent a recurrence (T.S. 6.5.A.6.i). TS 6.5.A.6.e states that the ORC is responsible for the review of facility operations to detect potential safety hazards while TS 6.5.A.6.i states that the ORC is responsible for investigating all TS violations and for preparing a report covering the evaluation and recommendations to prevent a recurrence.

The Team noted that ORC routinely uses the review of LERs and Failure and Malfunction Reports (F&MRs) to satisfy the TS required review of plant operations and TS violations. The Team also noted that the ORC has appointed the Compliance Division as a subcommittee to the ORC and assigned it the responsibility of presenting selected Failure and Malfunction Reports as well as the preparation of all LERs, including any

involving TS violations. Copies of all LERs are provided to the ORC as a means of satisfying the TS requirements. Further, PNPS Procedure 1.2.1 permits the ORC Chairman to set the timeliness of subcommittee reports to the full ORC.

While the use of subcommittees to support ORC activities is acceptable, the Team believes that the method used by ORC in fulfilling its responsibilities as defined by TS 6.5.A.6.e and f needs improvement. In particular, the Compliance Division has been issuing all LERs, including those discussing TS violations, prior to any ORC review of the product prepared. A review of 10 LERs disclosed that ORC review of the LER occurs usually a week to two weeks after the LER was formally sent to the NRC. While this may satisfy the timeliness requirements of PNPS Procedure 1.2.1, it does not appear that the corrective actions proposed to prevent recurrence receives the full benefit of a timely multi-disciplinary review, as is intended by the composition and responsibilities of the ORC. The formal release of the LER involving a TS violation by the ORC subcommittee without a formal review by the complete ORC is a weakness in meeting the requirements of TS 6.5.A.6.f.

During a review of F&MRs, which had not yet been reviewed by ORC, the Team noted that F&MR 86-266, which discussed a TS violation, had not yet been reviewed by ORC.

In this case, the violation was against an administrative requirement in TS Section 6.8, and was not reportable as an LER. Therefore, the F&MR did not result in an LER or a special report. The event occurred in September 1986, and no reports have yet been submitted to ORC as required by the TS. The licensee stated that the F&MR was still open pending completion of the remaining corrective action, and that then a report would be issued.

Both of these findings indicate that the ORC is not actively participating in the timely review of plant operations and does not appear to provide meaningful input into the process.

3.10.3.2 Responsiveness to Audit Recommendations

The Team reviewed both quality assurance (QA) audit findings and NSRAC recommendations to determine ORC responsiveness to recommendations for improvements to its operations. In QA Audit Report 87-37, QA listed two recommendations accepted by the ORC. PNPS Procedure 1.2.1 was reviewed and the Team determined that PNPS Procedure 1.2.1, Revision 21, contained the QA recommendations. The ORC was also audited by QA from May 22 through June 22, 1988. The audit generated one recommendation concerning the cross-referencing of ORC meetings with document references. Based upon discussions between the QA auditor and the Team, ORC has also accepted this recommendation.

In May 1988, the ORC received a list of four concerns from NSRAC based upon an audit review of the ORC. While the nature of the specific concerns are discussed in detail in Section 3.10.3 above, they are summarized here. Specifically, the NSRAC expressed concerns about the following areas: (1) the ORC review of changes to safety-related procedures, (2) ORC investigation of TS violations, (3) ORC review of facility operations, and (4) conduct of ORC meetings.

The concerns related to the ORC's investigation of TS violations and its review of plant operations are paralleled by the Team's findings discussed in Section 3.10.3.1 above.

The NSRAC concern with ORC procedure reviews is being evaluated for long-term improvements but no definitive action is currently planned by the licensee. As for NSRAC concern #4, the meetings observed by the Team, were conducted in a manner permitting formal and informal discussions of specific issues. A meeting agenda for regular ORC meetings was prepared and followed. The Team concluded that the meetings were conducted acceptably.

Based on the above, the Team has determined that, in general, the ORC has been receptive to recommendations for improvement. However, the fact that the NSRAC concerns remain unresolved suggests that the ORC may have difficulty addressing more complex recommendations.

The Team also observed that the quality of the meeting minutes could be improved by providing more discussion of the issues by the various ORC members as opposed to providing abstracts of the documents discussed.

Based upon a review of the ORC activities, the Team determined that there are weaknesses in the implementation of responsibilities assigned to the ORC. In particular, the Team determined that weaknesses exist in the review of plant operations and the investigation of TS violations. The Team has concluded that improvements in these two specific areas would result in a more effective ORC. In response to the Team's concerns, the licensee agreed to take certain actions prior to restart to strengthen the operational focus of ORC. These actions are: (1) to review plant incident critiques; (2) to review LER's prior to their submittal to NRC; (3) to review F&MR's on a regular basis; and, (4) to provide for a monthly presentation and discussion of plant operations as a specific agenda item. The Team found these licensee commitments responsive to its concerns.

3.10.4 Quality Assurance Audit and Surveillance Programs

The Team reviewed selected QA audit and surveillance reports, selecting specific findings, discrepancies, and observations for followup of the licensee's corrective action process. QA personnel, including the QA Department (QAD) manager, and other station managers and engineers, were interviewed regarding the audit and surveillance program objectives and overall conclusions which can be drawn from the audit and surveillance findings. The Team also reviewed the quarterly QAD Trend Analysis report, and attended several QA interface meetings. Portions of the Boston Edison Company Quality Assurance Manual (BEQAM) and applicable station procedures were also reviewed.

The technical content and quality of the issues raised in the selected audit reports were excellent. The conduct of a performance-based radiological controls audit by outside consultants was noteworthy. Specifically, the Team reviewed audits required under the cognizance of NSRAC, in accordance with the TS, and found that they are being performed as required. The Team determined that all deficiencies identified in the audits were either closed or adequately tracked by a formal system.

During the conduct of audits and surveillances, deficiency reports (DR) are issued by QA for conditions contrary to management policies and procedures, regulatory requirements, or licensee commitments. A DR which reports a deficiency identified during a QA audit is issued at the time of the audit exit interview. The licensee has an effective system of requiring a written response to the DR within a specified period, dependent on its significance, and for subsequent followup of corrective action. A system also exists for granting extensions through an escalation process to upper management.

QA prepares a monthly status report, including DR status, which is forwarded to senior management for appropriate actions. Review of the most recent QA trend report indicated a decline in the DR backlog, an increase in the number of DR's completed on time, and few extensions needed for DR closeout. The number of deficiencies reported by QA remained fairly constant. These are all indicators that licensee management attention to the corrective action process has had a positive impact.

The licensee also effectively trends Immediate Corrective Actions (ICA), which are identified in audit and surveillance reports. These report conditions which could lead to a DR, but which are corrected prior to the end of the audit or surveillance. They also are tracked along with the DR's. The Team also found the tracking of recommendations from the audits and surveillances to be effective.

Approximately 45 QA surveillance reports concerning observations of surveillance testing were reviewed. The reports were well planned, well documented, and thorough. Again, the tracking and followup of identified deficiencies were adequate. A minor concern of the Team involved QA followup to identified procedural inadequacies during surveillances. In ten of the surveillance activities reviewed by NRC, technical procedure deficiencies were identified by QA, but since the technicians being observed halted the test and pursued a procedure change, no deficiency reports were issued. Further review found that the majority of the procedure deficiencies were identified prior to implementation of new procedure validation program, and that QAD has an open DR on the procedure validation process. QAD is continuing to monitor the process. The Team had no further concerns.

Two QA Interface meetings were attended during the inspection. The meeting attendees include representatives from QA, plant staff, and engineering. They meet weekly to review the status of various corrective action items, including DR's, Management Corrective Action Requests (MCARs) and Potential Conditions Adverse to Quality Reports (PCAQ's). The meetings have improved communications among the organizations and have contributed to the more timely resolution of corrective action items.

3.10.5 Corrective Action Process and Programs

The Team reviewed the licensee's programs currently in place to identify, follow, and correct safety-related problems. A newly formulated Corrective Action Program "Clearinghouse," and proposed revisions to corrective action process procedures were also evaluated with respect to the current objectives and planned initiatives to improve corrective action program effectiveness. Samples were chosen from each of the programmatic areas where problem identification is routine and implementation of corrective measures is required. Each of these programs is discussed below. The Team interviewed licensee personnel responsible for individual program management and implementation, as well as the technical personnel accountable for problem disposition and corrective action adequacy.

For all of the areas evaluated, the Team sought to determine the effectiveness of the licensee's process for root cause analysis of problems, investigation of problems and causes for their generic applicability, and trending of findings to prevent their recurrence. Selected issues were analyzed to understand the technical problems, check how they were programmatically handled, and to determine whether the corrective measures were appropriate to the specific cases. The examples are cited in the following subparagraphs not only to illustrate the scope of licensee activities inspected, but also to support the conclusions reached regarding the corrective action program effectiveness.

3.10.5.1 Failure and Malfunction Reports

The Failure and Malfunction Report (F&MR) is a process by which failures, malfunctions, and abnormal operating events are reported, evaluated and corrected to preclude repetition. The process is described in: Nuclear Organization

Procedure (NOP) 8305, the "Failure and Malfunction Report Process;" PNPS Procedure Number 1.3.24, "Failure and Malfunction Reports;" and PNPS Work Instruction N8-3.2.12, "F&MR Trend Analysis."

Team review of licensee procedures verified that responsibilities are established for the F&MR process; reports are prioritized by safety significance; underlying root causes are evaluated; reports are tracked for completion of corrective action; and, trending for repetitive problems is performed. A report may be initiated by any licensee staff member for failures, malfunctions, and abnormal operating events identified during station operation. The Nuclear Watch Engineer ensures that adequate compensatory measures are implemented and the required notifications are performed. The Compliance Division Manager then recommends a lead group to perform the investigation and performs a reportability review. The appropriate department manager is responsible to ensure that the identified deviations are properly resolved and that corrective actions are planned and effectively implemented in a timely manner. The department manager is also responsible for the review and approval of the reportability, root cause analysis, corrective action plans, disposition, and final closeout. A root cause analysis is performed for those F&MR's determined to be significant. The term "significant" applies to a condition adverse to quality which merits further evaluation for cause and requires management attention to preclude recurrence. The nonsignificant deviations are evaluated in a periodic trend analysis.

The Team identified several discrepancies in the administration of the F&MR process. Procedure 1.3.24 states that the Compliance Division Manager is responsible to present F&MR's that are designated significant or important to ORC. As discussed in Section 3.10.2, the Team noted that the ORC meeting minutes for the previous six months did not record the review of any F&MR's. Further Team review found that a backlog of over

existed, and that no F&MRs had been submitted to ORC since February 3, 1988, except for those associated with an LER. Some of the F&MR's involved events which occurred in 1986. The licensee stated this was caused by personnel resource constraints. The Team also found two closed F&MR's which appeared to meet the criteria established in Procedure 1.3.24 for being submitted to ORC, but which had not been submitted prior to closure. F&MR's 88-127 and 88-76 were not reviewed by ORC, but involved recurring conditions, which is a criterion for ORC review. In addition, many of the closed safety-related F&MRs were denoted not safety-related by the Watch Engineer during the initial review process. This mis-classification; however, did not affect the processing and evaluation of the associated events for those F&MR's inspected.

The Team reviewed a listing of open and closed F&MR's and evaluated a sampling of closed reports to determine the completeness and effectiveness of the corrective actions. The total number of F&MR's initiated has been increasing over the last few years. The licensee has attributed this increase to a heightened sensitivity of personnel to critical self-assessment and to the identification of potentially reportable or significant events to management. The total number of open F&MR's has significantly decreased over the last year.

The root cause analyses performed for the F&MR's reviewed were found to be of excellent quality. Each analysis included an event description, probable cause, actions completed, recommended actions, and safety significance. The Systems Engineering Group's impact on this important process has been positive.

The Team reviewed the latest F&MR Trend Analysis Report, which covered the period July through December 1987, and the applicable procedures. The Team noted that the station's Technical Sections did not specifically assign responsibility for the report's proposed recommendations. Further review found that this program deficiency had been previously identified by the licensee and the NRC and that the licensee had initiated corrective action. Specifically, a review of all previous trend report recommendations was performed by the licensee to determine their status.

The review was completed in July 1988, and 74% of the recommendations were corrected. The remaining items are currently being dispositioned by the licensee to ensure effective long-term corrective action. In addition, the licensee has revised the F&MR procedures to include use of the Management Corrective Action Report (MCAR) as a vehicle for the Technical Section to report and correct negative trends identified in the reports. The most recent trend report resulted in the issuance of two MCAR's, which the Team reviewed.

The Team also noted that the trend report focused its discussions primarily on individual problems rather than trend patterns and recurring failures. The Team observed that the Technical Section would be more effective if it thoroughly evaluated trends and patterns, since the individual F&MR itself is adequate to evaluate isolated problems. In addition, the report did not provide any detailed discussion of personnel errors or procedural failures, although there were a large number in the report.

3.10.5.2 Potential Conditions Adverse to Quality

As described by PNPS Nuclear Organization Procedure (NOP) 83A9, "Management Corrective Action Process," the potential conditions adverse to quality (PCAQ) report can be used by any licensee member to document and report any actual or suspected conditions adverse to quality not reported by other report forms such as NCRs, DRs, and F&MRs. In short, it is a process for anyone to elevate a concern to management to assure that the concern will be evaluated and resolved.

As implemented, PCAQs are written from one department to another or from one section to another within a department. For example, Operations (NOD) could send a PCAQ to Engineering (NED) asking for an evaluation of a specific plant condition. In each case, the originating department is responsible for tracking each item to resolution. According to NOP 83A9, a PCAQ is not formally closed until the originating department is satisfied with the proposed corrective action and the corrective action has been implemented.

The Team reviewed a listing of open and closed PCAQ's and also reviewed a sampling of individual PCAQ's to determine the completeness and effectiveness of corrective actions. As of August 19, 1988, there were about 250 PCAQ's awaiting resolution. There is currently no central tracking system for all PCAQ's, although licensee management has begun initiatives in that area. In June 1988, the licensee began an effort to reduce the number of open PCAQ's and to establish a central tracking system for PCAQ's with the QAD. As part of this effort, each department is reviewing unresolved PCAQ's to evaluate each one's significance and its potential impact on restart. Based on discussions with responsible managers, the Team learned that QAD has completed its review and concluded that none of the unresolved PCAQ's concern equipment operability issues or are of a significance level that requires action before restart. NOD has not completed its evaluation but expects to be finished within two weeks. NED has been implementing a routine review of each unresolved PCAQ and has been maintaining a list of PCAQ's needed to be resolved prior to restart. The review of outstanding PCAQ's is an item on the restart checklist maintained by the plant. Subsequent checklist review by ORC also provides a decision point in the process to assure that all necessary evaluations have been completed.

Based on the above, the Team has concluded that the licensee is assuring that each PCAQ is being evaluated for its nuclear safety and equipment operability impact relative to the planned restart of the plant and that all PCAQ's needed for resolution before restart will be identified. The ORC review of the PCAQ's on the restart checklist will provide another check to assure that resolution of PCAQ's needed for restart has occurred.

The Team selected several closed PCAQ's to determine whether the proposed corrective action had satisfied the originating department's concerns and whether the corrective action was completed as required by station procedures. In general, all identified corrective actions described on the PCAQ's were completed; however, the documentation of the completed activity was, in many cases, limited and specific references were not provided. The Team stated that additional guidance on the level of documentation to be provided on the closeout portion of the PCAQ form could enhance clarity and auditability of the closure process. The Team also noted that the PCAQ system can allow ambiguity of PCAQ status in cases where a proposed action has been rejected by the originating office. For example, NED rejected the response prepared by NOD to PCAQ NED-88-087. A review of the NOD log showed the issue resolved (July 22, 1988), but further investigation with persons affected indicated that the response was being rewritten and further corrective action was to be performed. The formal closeout process and status tracking for the PCAQ's needs improvement. This finding parallels a similar finding of the QA Department contained in QAD 88-609, dated May 23, 1988.

3.10.5.3 Management Corrective Action Request

The BEQAM and NOP 83A9, "Management Corrective Action Process," describe the purpose of the Management Corrective Action Request (MCAR). The MCAR is a two-part corrective action document used to: (1) perform a root cause analysis of significant conditions adverse to quality and develop preventive action plans; and (2) request management to implement selected action plans to prevent recurrence of a problem. In lieu of a Deficiency Report, an MCAR may be used to report and resolve deficiencies involving process or policy issues which affect more than one department and for which management attention and direction is required. An MCAR may also be used for tracking long-term corrective actions related to nonconformance reports (NCRs) and PCAQ's or for identification of adverse trends identified through trend analysis programs.

QAD is assigned administrative control for the MCAR process. QAD logs the status, distributes copies, reports on delinquent MCAR's, and performs the closeout. QAD also reviews each MCAR where the responsible department is different from the issuing department to verify that the assignment of the responsible department is appropriate.

The Team reviewed the current status of open MCAR's and the administrative controls in place to track and promptly resolve MCAR's. The latest monthly status report, issued to the SVP-N on August 1, 1988, from the QAD Manager listed 30 open MCAR's. This list included two 1985 MCAR's and eight 1986 MCAR's. Approximately 40% of the MCAR's initiated since 1984 remain open.

The licensee has previously observed that increased management attention is required to close out MCAR's in a timely manner. For example, the most recent QAD trend analysis report, issued on May 23, 1988, recommended that the SVP-N initiate action to closeout MCAR's QAD 85-2 and QAD 87-2, which address the large number of quality problem reports issued for "failure to follow procedures" and "inadequate procedures."

Team attendance at several QA Interface meetings also noted that there is clearly increased management attention being directed to closeout the longstanding MCAR's.

The Team reviewed two open MCAR's to evaluate the effectiveness of the process. MCAR 86-06, issued in November 1986, involved recurring failures of the salt service water (SSW) pumps. The MCAR was issued as a result of an F&MR trend report finding. The MCAR resulted in a detailed root cause analysis by a consultant and the development of a long-term corrective action plan, which is not yet complete. MCAR 88-02, issued in June 1988, concerned programmatic inefficiencies in the PCAQ process. The licensee is actively working on developing an integrated list of the approximately 250 open PCAQ's with a current status (see Section 3.10.4.2). This list is to be utilized to increase emphasis on closeouts. Review of these MCAR's did not identify any discrepancies in the process.

3.10.5.4 Clearinghouse Process

The current procedure describing the corrective action process is NOP 83A9, "Management Corrective Action Process." This procedure discusses the responsibilities of the station departments in resolving identified deficiencies and reporting the trends observed. The procedure also describes the various types of reports or documents available to station personnel and specifically defines their use.

As a result of the self-assessment evaluations and performance improvement plans, the licensee determined that the existing corrective action processes were very complicated and that a streamlined process was needed that would provide an easy means of raising any concerns to management for resolution. A need was also identified for a specific entity which could monitor the performance of the station organization in implementing self-improvement recommendations, as well as provide the focal point for identified issues to be placed into the appropriate plant corrective action process.

In June 1988, the "Clearinghouse" was established to serve a number of needs. It was developed to assure that the licensee's restart assessment team observations had been entered into the regular corrective action process and, when necessary, that all necessary paperwork was prepared for the resolution of any outstanding items. As of this inspection, 69 assessment items remain unresolved but have schedules identified for their completion. Responses for approximately 69 additional items have not been received from the station organization. The balance of the original 449 items have been listed as closed. The Team did not evaluate the closeout process for any completed or closed items.

A second responsibility of the Clearinghouse was to streamline the corrective action process. As of this inspection period, revisions to the station procedures for improvements in corrective action processes have not been made. The current estimate for completion of the necessary procedure revisions was the end of August.

While subject to revision during the required station procedure review process, the following is a discussion of the current licensee philosophy concerning potential modification of the corrective action processes. The Team did not evaluate the effectiveness of these proposed changes in the overall corrective action programs.

The Clearinghouse is currently revising three existing NOPs, creating a new NOP, and revising the BEQAM. The new NOP would define the role and responsibilities of the Clearinghouse, establish a new form for identifying real or potential plant problems, as well as for reporting employee-identified concerns or self-assessment recommendations for plant improvements. The new form would provide a simple method for raising issues, concerns, or recommendations to station management. Upon receipt of this form, the Clearinghouse would review the issue described and integrate the issue into the regular plant corrective action processes for resolution.

Another proposed change is a categorization of all the existing corrective action processes identified in NOP B3A9 into three groups. One group, identified as corrective action processes, would include deficiency reports (DR), non-conformance reports (NCR), management corrective action requests (MCAR), failure and malfunction reports (F&MR), radiological occurrence reports (ROR), security deficiency reports (SDR), and supplier finder reports (SFR). These processes are used to identify and document plant deficiencies and to provide a means of tracking the resolution of identified problems.

A second group of controls would be categorized as normal work control processes. This group would potentially include maintenance requests (MR), housekeeping services assistance (HSA), procedure change notices (PC), and engineering services requests (ESR).

The last group currently being proposed includes all recommendations or findings from the existing self-assessment programs. The information to be tracked in this group are recommendations for improving performance and would not be used to identify programmatic deficiencies. Any identification of deficiencies would be tracked using one of the processes described in the first group above. Examples of the types of recommendations to be tracked would be quality assurance audit findings and peer evaluator reports.

Changes would also be required for NOP 84E1, "Engineering Service Request (ESR) Process," and NOP 84A7, "Drawing Control," as well as the quality assurance manual, in order to fully implement the revised program.

The licensee anticipates that all necessary changes to station procedures would be completed by the end of August, with formal implementation of the program changes within an additional 30 days.

3.10.5.5 Management Oversight and Assessment Team (MO&AT)

In addition to the plant operations oversight provided by the ORC, the MO&AT also provides an oversight review of plant operations by the nature of its responsibilities for overview of restart activities. The MO&AT is composed of eight senior managers, which includes the Station Director, Director of Special Projects and Vice President Nuclear Engineering. The SVP-N acts as the Chairman of the team. Further, three MO&AT members had been licensee managers prior to the arrival of the SVP-N, while the remaining managers joined the licensee subsequent to February 1987.

The MO&AT maintains its oversight of restart-related activities and associated plant operations through several self-assessment programs. These programs include but are not limited to the peer evaluator and management monitoring programs. The Team noted that these programs were effective in evaluating plant activities.

The Team determined that, in some ways, the responsibilities of the MO&AT parallels some of the responsibilities to review plant operations assigned to the ORC. In addition, the Team determined that the current role of the MO&AT is not credited by the ORC as a means of fulfilling its responsibilities to review plant operations, but it does provide a second, independent look at plant operations.

3.10.5.6 Engineering Service Requests (ESR's)

ESRs are tracking forms used by any licensee department to request engineering assistance from the Nuclear Engineering Department (NED). Standard practice within NED is to attach an ESR to all requests for assistance which may be already tracked under another corrective action tracking system, such as DR's, PCAQ's, etc. This is done to provide a means for the NED to track and monitor the progress of its work. When an ESR is opened or received, NED is to review the concern, determine a plan for resolution of the item, which would include an evaluation relative to plans for plant restart. Unless the issue can be resolved within 30 days, a response to the originating department is to be provided within 30 days which describes the above. In discussions with the Team, a management representative of NED indicated that this practice has not always worked as planned and that additional emphasis is being placed on assuring that the 30-day responses are being sent in a timely fashion.

NED tracks all existing ESR's, determines what actions are required prior to restart, and routinely evaluates the potential impacts of outstanding ESR's on the planned restart of the plant. In each case where NED determines that resolution of an ESR is not required to support restart, NED prepares documentation to support that position. This documentation undergoes several levels of review, including the Section Manager, Department Manager and the Vice President - Nuclear Engineering. Any open ESR associated with unresolved PCAQ's or MCAR's is also reviewed by the ORC as part of its assigned restart checklist review.

Based upon discussions with NED personnel, the Team concluded that ESR's are adequately tracked and that upper management is routinely informed of potential problems in a timely fashion.

3.10.5.7 Human Performance Evaluation System

The Team inquired as to the licensee's intentions in participating in the Institute for Nuclear Power Operations (INPO) Human Performance Evaluation System (HPES) program. The program is intended to assist licensees in the reduction of human error by encouraging personnel to report actual or potential situations which keep a person from outstanding performance. The licensee has designated an HPES coordinator, who is in the Training Department. The coordinator has been trained by INPO and is currently preparing to implement the program. The coordinator has already become involved in the Incident Investigation and Critique process, and has reviewed the recent findings from the licensee's ESF Actuation Task Force report. This program, once fully implemented, should provide additional valuable input into the corrective action process.

3.10.6 Conclusions

Overall, the Team determined the licensee's programs for safety assessment/quality verification to be adequate and improving. Based upon the areas inspected and examples raised, the Team concluded that:

1. The Nuclear Safety Review and Audit Committee is actively involved in the oversight of facility operations. The committee is composed of experienced managers with diverse experience and provides clear and valid input to the SVP-N on safety-related activities.
2. Plant problems and deficiencies are being identified and entered into the appropriate corrective action system.

3. There are effective, meaningful communications between the QA and plant operations departments, as well as good systems engineering involvement in evaluation and resolution of problems.
4. The weekly QA interface meeting has enhanced communications at the station and improved the process of resolving open issues.
5. The Operations Review Committee (ORC) has not been reviewing plant operations effectively so that meaningful input to licensee management is being consistently provided. Recently, heavy emphasis has been placed on administrative reviews of procedure changes and modifications, rather than reviewing plant operations. Also, ORC review of plant failure and malfunction reports has neither been timely nor included all appropriate reports.
6. Multiple corrective action processes and multiple tracking systems detract from efficient functioning of the system. This has been identified by the licensee and programs are being established to correct the known deficiencies.
7. The tracking and closeout of PCAQ's and MCAR's have not been effective in the past. Also, a relatively large number of open PCAQ's exists. The licensee is taking action to resolve these problem.

4.0 UNRESOLVED ITEMS

An unresolved item is an item for which additional information is required in order to determine whether the item is acceptable, a violation, or a deviation. An unresolved item is discussed in section 3.4.2.2 of this report.

5.0 MANAGEMENT MEETINGS

At periodic intervals during the inspection period, the Team Leader held meetings with senior facility management to discuss the inspection scope and preliminary findings. A final exit interview was conducted on August 24, 1988. Attendees are listed in Appendix B. At the exit meeting, the Team Leader described the preliminary inspection findings, including both the preliminary overall conclusions and the preliminary findings and observations in each functional area. The Team Leader also confirmed licensee commitments at the exit meeting. Then the Team Manager discussed how the Team findings will be used in NRC Restart Assessment Panel activities. Also, the Regional Administrator outlined the remaining step in the NRC staff process of evaluating Pilgrim restart readiness and developing staff recommendation.

APPENDIX A

Entrance Interview Attendees

August 8, 1988

Boston Edison Company

J. Alexander, Plant Operations Section Manager
R. Anderson, Plant Manager
H. Balfour, Training Section Manager
R. Bird, Senior Vice President - Nuclear
F. Famulari, Quality Assurance Department Manager
D. Gillispie, Nuclear Training Department Manager
R. Grazio, Regulatory Section Manager
P. Hamilton, Compliance Division Manager
K. Highfill, Station Director
J. Jens, Radiological Section Manager
E. Kraft, Plant Support Department Manager
R. Ledgett, Director Special Projects
D. Long, Security Section Manager
A. Morisi, Planning and Outage Department Manager
E. Robinson, Corporate Communication Information Division Head
L. Schmeling, Program Manager
J. Seery, Technical Section Manager
R. Sherry, Plant Maintenance Section Manager
R. Swanson, Nuclear Engineering Department Manager
E. Wagner, Assistant to Senior Vice President - Nuclear
F. Wozniak, Fire Protection Division Manager

United States Nuclear Regulatory Commission

F. Akstulewicz, Senior Technical Assistant, Policy Development and
Technical Support Branch, Office of Nuclear Reactor Regulation (NRR)
R. Blough, Chief, Reactor Projects Section No. 3B, Division of Reactor
Projects (DRP), Region I (RI)
S. Collins, Deputy Director, DRP, RI
L. Doerflein, Project Engineer, DRP, RI
T. Dragoun, Senior Radiation Specialist, Division of Radiation Safety
and Safeguards (DRSS)
M. Evans, Operations Engineer, Division of Reactor Safety (DRS), RI
J. Lyash, Resident Inspector, Pilgrim Nuclear Power Station, DRP, RI
D. McDonald, Project Manager, Project Directorate I-3, NRR
L. Plisco, Senior Operations Engineer, Division of License Performance
and Quality Evaluation, NRR
W. Raymond, Senior Resident Inspector, Millstone Point, DRP, RI
L. Rossbach, Senior Resident Inspector, Indian Point Unit 2, DRP, RI
G. Smith, Safeguards Specialist, DRSS, RI
C. Warren, Senior Resident Inspector, Pilgrim Nuclear Power Station, DRP, RI

Commonwealth of Massachusetts

P. Agnes, Assistant Secretary of Department of Public Safety
P. Chan, Observer
S. Sholly (MHB Technical Associates, Inc.), Observer

APPENDIX B

Exit Interview Attendees

August 24, 1988

Boston Edison Company

J. Alexander, Plant Operations Section Manager
R. Bird, Senior Vice President - Nuclear
F. Famulari, Quality Assurance Department Manager
D. Gillispie, Nuclear Training Department Manager
R. Grammont, Deputy Maintenance Section Manager
R. Grazio, Regulatory Section Manager
P. Hamilton, Compliance Division Manager
K. Highfill, Station Director
J. Jens, Radiological Section Manager
E. Kraft, Plant Support Department Manager
R. Ledgett, Director Special Projects
D. Long, Security Section Manager
E. Robinson, Corporate Communication Information Division Head
L. Schmeling, Program Manager
J. Seery, Technical Section Manager
R. Sherry, Plant Maintenance Section Manager
R. Swanson, Nuclear Engineering Department Manager
S. Sweeney, Chief Executive Officer and Chairman of the Board
E. Wagner, Assistant to Senior Vice President - Nuclear
F. Wozniak, Fire Protection Division Manager

United States Nuclear Regulatory Commission

F. Akstulewicz, Senior Technical Assistant, Policy Development and
Technical Support Branch, Office of Nuclear Reactor Regulation (NRR)
R. Blough, Chief, Reactor Projects Section No. 3B, Division of Reactor
Projects (DRP), Region I (RI)
B. Boger, Assistant Director for Region I Reactors, NRR
S. Collins, Deputy Director, DRP, RI
L. Doerflein, Project Engineer, DRP, RI
W. Little, Office of Special Projects, RII
J. Lyash, Resident Inspector, Pilgrim Nuclear Power Station, DRP, RI
D. McDonald, Project Manager, Project Directorate (PD) I-3, NRR
W. Raymond, Senior Resident Inspector, Millstone Point, DRP, RI
L. Rossbach, Senior Resident Inspector, Indian Point Unit 2, DRP, RI
W. Russell, Regional Administrator, RI
C. Warren, Senior Resident Inspector, Pilgrim Nuclear Power Station, DRP, RI
R. Wessman, Director, PD I-3, NRR

Commonwealth of Massachusetts

- P. Agnes, Assistant Secretary of Department of Public Safety
- P. Chan, Observer
- G. Minor (MHB Technical Associates, Inc.), Observer

APPENDIX C

Persons Contacted

R. Anderson, Plant Manager
R. Bird, Senior Vice President - Nuclear
F. Famulari, Quality Assurance Department Manager
K. Highfill, Station Director
E. Howard, Vice President - Nuclear Engineering
E. Kraft, Plant Support Services Manager
A. Morisi, Planning and Outage Manager
R. Swanson, Nuclear Engineering Department Manager
S. Sweeney, Chairman of the Board and Chief Executive Officer

In addition, the Team interviewed a large number of managers (including virtually all section and division managers), engineers, supervisors, and craft personnel in each inspection area.

APPENDIX D

Documents Reviewed

- PNPS, Nuclear Training Manual, T-001, Parts 3, 4 and 5
- PNPS, Special First-Startup Training Program, Approved August 9, 1988
- PNPS Technical Specifications
- Boston Edison Company, Nuclear Mission, Organization and Policy Manual
- Nuclear Operating Procedures
- Material Control and Implementation Action Plan
- Boston Edison Quality Assurance Manual
- Audit Reports -- Sampling review including the following: 87-40, 88-02, 87-63, 88-10, 88-20, 87-37, 87-49, 88-04, and 88-17
- Potential Conditions Adverse to Quality (PCAQ) Reports -- Sampling review including NOD 87-03, NED 86-71, BGD 87-255, SO 88-57, SO 88-58, SO 88-48, NOD 87-02, NOD 87-29, NED 88-067, SO 88-59, SO 88-12, NOD 88-120, NED 88-90, SO 87-56, and SO 88-22
- Management Corrective Action Requests (MCAR's) -- Sampling review including QAD 85-2, QAD 87-2, 85-06, and 88-02
- Licensee Event Reports (LER's) -- Sampling review including 87-21, 88-008 thru 88-014, 88-016, and 88-017
- Maintenance Requests (MR's) -- Sampling review including 88-11-6, 88-110, 88-10-179, 88-46-300, 88-14-16, 88-45-183, 88-45-181, 88-46-194, 88-10-26, 88-10-105, 88-10-69, 88-10-71, 88-10-80, 88-10-141, 87-10-282, and 87-10-283
- Maintenance Activities/Packages -- Sampling review including 88-3-26, 88-19-109, 88-46-213, 88-10-86, 87-46-173, 88-13-20, 88-46-438, 88-2-12, 86-20-47, 88-45-152, 88-45-176, 88-3-62, 88-63-276, 88-45-190, 88-1-31, 88-14-16, 88-46-194, and 88-10-114
- Meeting Minutes for ORC Meetings 88-40 through 88-63
- Failure and Malfunction Report 86-266
- NED Procedure 16.03, "Corrective Action Program"

- QAD Trend Analysis Report for the First Quarter of 1988 - QAD 88-609
- PNPS Work Instruction N8-3.2.12, F&MR Trend Analysis
- Memo from J. Seery to R. Grazio, Appointment of Compliance Division as ORC Subcommittee, June 23, 1988
- Memo from R. G. Bird to K. L. Highfill, NSRAC Concern from May 24, 1988 NSRAC Meeting - May 27, 1988
- Memo from K. L. Highfill to R. G. Bird, Response to NSRAC Action Item 88-04-01 - June 22, 1988
- Memo from J. A. Seery to R. Flannery, ORC Meeting Minutes Distribution List - dated May 6, 1988
- Procedure 1.2.1, Operation Review Committee
- Procedure 1.3.24, Failure and Malfunction Reports
- Procedure 1.3.2.6, Response to Deficiency Reports
- Procedure 1.3.4, Procedures
- Procedure 1.3.33, Operating Experience Review
- Procedure 1.3.37, Post Trip Reviews
- Procedure 1.3.38, Plant Performance Monitoring Program
- Procedure 1.3.63, Conduct of Critiques and Incident Investigations
- Procedure NOP 83A9, Management Corrective Action Process
- Procedure NOP 83A13, Deficiency Report Process
- Procedure NOP 83A14, Nonconformance Report Process
- Procedure NOP 84A1, Surveillance Monitoring Program
- Procedure NOP 84A11, Annual Independent Review of BECo's Quality Assurance Program
- Procedure NOP 85A1, Nuclear Organization Performance Monitoring and Management Information Program
- Procedure NOP 88A1, Performance Standards and Evaluation Guidelines for Pilgrim Station

- Procedure NOP 8305, The Failure and Malfunction Report Process
- Procedure NOP 8401, Operating Experience Review Program
- Procedure 1.4.5, PNPS Tagging
- Procedure 1.5.3, Maintenance Requests
- Procedure 1.5.3.1, Maintenance Work Plan
- Procedure 1.5.7, Emergency Maintenance
- Procedure 3.M.1-30, Post-Work Testing Guidance
- Procedure SI-MT.1000, Maintenance Section Manual
- Procedure SI-MT.0501, Post-Work Test Matrices and Guidelines
- Procedure 3.M.1-11.1, EQ Maintenance Process: Repair/Replacement
- Procedure 3.M.3-1, A5/A5 Buses 4KV Protective Relay Calibration/Functional Test and Annunciator Verification
- Procedure 3.M.3-8, Inspection/Troubleshooting Electrical Circuits
- Procedure TP 88-40, 480 VAC Contactor Testing
- Procedure TP 88-22, Pre-Operational Test of the New Degraded Voltage Relays and Modified Load Shedding Logic
- Procedure PW TMI-1, Post Work Test Matrix and Guidelines, Revision A
- Procedure 3.M.4-14, Rotating Equipment Inspection, Assembly and Disassembly, Revision 6, dated April 4, 1988
- Procedure 8.Q.3.4, 125/250V DC Motor Control Center Testing and Maintenance
- Procedure 2.2.85, Fuel Pool Cooling System
- Procedure 3.M.1-15, Vibration Monitoring for Preventive Maintenance and Balancing, Revision 5, dated June 12, 1988
- Procedure 2.2.8, Standby AC Power System (Diesel Generators), Revision 20, dated January 13, 1988
- Procedure ARP, Panel C39, Fuel Pool Cooling System, Revision 0, dated January 30, 1988
- Procedure 2.2.83, Reactor Cleanup System, Revision 22, dated June 20, 1988

- Fire Watch Computer Listing, dated August 4, 1988
- Fire Protection Maintenance Request Computer Listing, dated August 9, 1988
- Pilgrim Station Performance Indicators, dated August 10, 1988 and August 17, 1988
- Procedure 8.B.29, "Inspection of Fire Barriers," Revision 1
- Temporary Modification Log
- Temporary Modification Status Report to R. Anderson from F. Mastrangelo, dated August 4, 1988
- Procedure 1.5.9, "Temporary Modifications," Revision 12
- Procedure 1.5.9.1, "Lifted Leads and Jumpers," Revision 0
- Procedure 1.3.34, "Conduct of Operations"
- Procedure 2.1.16, "Nuclear Power Plant Operator Tour," Revision 54
- Overtime Book
- Procedure 1.3.67, "Use and Control of Overtime at PNPS"
- Advance Overtime Requests for Week Ending August 6, 1988
- PNPS 1-ERHS-VIII.B-4-0, Turbine Building Shield Wall Design
- Confidential Memo #13, to J. P. Jens from K. L. Highfill, dated July 19, 1988, "Training Program for Radiation Protection Manager"
- Procedure 6.1-209, "Radiological Occurrence Reports"
- Radiological Work Plan for A and B Recirculation Pump Seal Welds
- Procedure 6.1-012, "Access Control to High Radiation Areas"
- Selected RP Technician Training and Qualification Folders, Lesson Plan, Quizzes and Training Guides
- Selected Radiation Work Permits: from March 1988 to August 1988
- Maintenance Request 87-20-84

- Procedure 8.M.2-1.5.3.4, "Primary Containment Isolation Logic Channel Test - Channel B2," Revision 8, dated September 24, 1987
- Procedure 8.M.2-1.5.7, "Group I Primary Containment Isolation Valve Testing," Revision 5, dated November 7, 1987
- Procedure 8.M.2-8.2, "Calibration of ATS Transmitters Rack C2206," Revision 2, dated June 30, 1988
- Procedure 8.M.1-32.4, "Analog Trip System - Trip Unit Calibration - Cabinet C2229-B2," Revision 5, dated April 4, 1988
- Procedure 8.M.2-2.10.8.5, "Diesel Generator 'A' Initiation By Loss of Off-Site Power Logic," Revision 8, dated November 6, 1987
- Procedure 8.M.2-2.10.8.3, "Diesel Generator 'A' Initiation By Core Spray Logic," Revision 12, dated April 9, 1988
- Procedure 3.M.3-1, "A5/A6 Buses 4KV Protective Relay Calibration/Functional Test and Annunciator Verification," Revision 23, dated August 13, 1988
- Procedure 8.M.2-2.6.7, "RCIC Simulated Automatic Actuation," Revision 6, dated February 5, 1988
- Procedure 8.5.5.1, "RCIC Pump Operability and Flow Rate Test at 1000 psig," Revision 24, dated June 4, 1988
- Procedure 8.M.2-2.10.7, "RCIC Automatic Isolation System Logic," Revision 1, dated November 7, 1987
- Procedure 8.M.2-2.6.1, "RCIC Steam Line Hi Flow," Revision 13, dated June 9, 1988
- Procedure 8.M.2-2.6.3, "RCIC Steam Line Hi Temperature," Revision 12, dated July 17, 1987
- Procedure 8.M.2-2.6.4, "RCIC Steam Line Low Pressure," Revision 16, dated June 20, 1988
- Procedure 8.M.1-32.5, "Analog Trip System - Trip Unit Calibration Cabinet C2233A, Section A," Revision 2, dated December 7, 1987
- Procedure 8.E.11, "Standby Liquid Control System Instrument Calibration," Revision 9, dated September 2, 1987
- Procedure 8.E.13, "RCIC System Instrument Calibration," Revision 14, dated June 26, 1988

- Procedure 8.4.1, "Standby Liquid Control Pump Operability and Flow Rate Test," Revision 19, dated April 9, 1988
- Procedure 1.8, "Master Surveillance Tracking Program," Revision 9, dated August 15, 1988
- Procedure 1.3.36, "Measurement and Test Equipment," Revision 4, dated March 9, 1988
- Procedure 8.I.1, "Administration of Inservice Pump and Valve Testing," Revision 4, dated August 15, 1986
- Procedure 8.I.3, "Inservice Test Analysis and Documentation Methods," Revision 6, dated May 11, 1988

Drawings

- PNPS Elementary Diagram MIN 34-9 (Revision E1): Primary Containment Isolation System
- PNPS Elementary Diagram MIN 28-12 (Revision E14): Primary Containment Isolation System
- PNPS Elementary Diagram MIN 36-7 (Sh. 10, Revision E7): Primary Containment Isolation System
- PNPS Elementary Diagram MIN 36-7 (Sh. 11, Revision E5): Primary Containment Isolation System
- PNPS Elementary Diagram MIN 41-10 (Revision E2): Primary Containment Isolation System
- PNPS Elementary Diagram MIN 38-11 (Revision E2): Primary Containment Isolation System
- PNPS Elementary Diagram MIN 35-7 (Revision E4): Primary Containment Isolation System
- PNPS Elementary Diagram MIG 11-11 (Revision E11): RCIC System
- PNPS Elementary Diagram MIG 12-12 (Revision E5): RCIC System
- PNPS Elementary Diagram MIG 14-9 (Revision E5): RCIC System
- PNPS Elementary Diagram MIG 15-9 (Revision E8): RCIC System
- PNPS Elementary Diagram MIG 16-7 (Revision E5): RCIC System
- PNPS Elementary Diagram MIK 4-11 (Revision E10): Core Spray

- PNPS Schematic Diagram E-548 (Revision E0): Containment Atmosphere Isolation Control
- PNPS Schematic Diagram E-38 (Revision E6): 4160V System Breakers 152-504 and 152-604
- PNPS Schematic Diagram E-35 (Revision E3): 4160V Auxiliary Relays and Miscellaneous Schemes
- PNPS Schematic Diagram E-27 (Revision E7): Diesel Generator
- PNPS Schematic Diagram E-17 (Revision E7): Schematic Meter and Relay Diagram 4160 Volt System
- PNPS Schematic Diagram M6-22-14 (Sh. 1, Revision E11): Diesel Generator "A" X107A Engine Control
- PNPS Relay Setting Drawing E5-200 (Sh. 1, Revision E3): 4160 Volt Switchgear Relay Settings
- PNPS Relay Setting Drawing E5-200 (Sh. 3, Revision E2): 4160 Volt Switchgear Relay Settings
- PNPS P&ID M245 (Revision E13): RCIC System, Sh. 1
- PNPS P&ID M246 (Revision E10): RCIC System, Sh. 2
- PNPS P&ID M249 (Revision E12): Standby Liquid Control System

APPENDIX E

IATI Composition and Structure

Team Manager	Samuel J. Collins
Team Leader	A. Randy Blough
Technical Assistant	Clay C. Warren
Administrative Assistant	Mary Jo DiDonato
Operations	Lawrence W. Rossbach (Lead)
Shift Inspectors	Lawrence W. Rossbach William J. Raymond Loren R. Plisco Lawrence T. Doerflein Francis M. Akstulewicz
Radiological Controls	Thomas F. Dragoun
Maintenance	Jeffrey J. Lyash William J. Raymond
Surveillance	Lawrence T. Doerflein
Security	Gregory C. Smith
Fire Protection	Lawrence W. Rossbach
Assurance of Quality	Loren R. Plisco Francis M. Akstulewicz
Training and Management Effectiveness	Daniel G. McDonald Michele G. Evans
Report Coordinator	Tae K. Kim
Commonwealth of Massachusetts (Observers)	Steven C. Sholly Pamela M. Chan

APPENDIX F

NRC Integrated Assessment Team Inspection (IATI)
Members Resumes

This appendix shows IATI summary resumes of the team members and Commonwealth of Massachusetts observers. The resumes outline the nuclear experience of team members.

NAME: FRANCIS M. AKSTULEWICZ

ORGANIZATION: United States Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Policy Development and Technical Support Branch

TITLE: Senior Technical Assistant

EDUCATION: B.S., Nuclear Engineering

EXPERIENCE: Fourteen Years of Nuclear Experience as Follows:

Two and One-Half Years - Shielding Engineer - Bechtel Power Corporation

One Year - Technical Analyst - Office of Material Safety and Safeguards (NRC)

Eight Years - Nuclear Engineer - Office of Nuclear Reactor Regulation (NRC)

Two Years - Project Manager - Haddam Neck Plant, Office of Nuclear Reactor Regulation (NRC)

One-Half Year - Present Position

SPECIAL QUALIFICATIONS: Completion of NRC Fundamental and Advanced BWR Systems Training Course and BWR Simulator Course

SPECIAL ASSIGNMENTS: Member of Fire Protection, Health Physics and Diagnostic Team Inspection at Haddam Neck

NAME: A. RANDOLPH BLOUGH
ORGANIZATION: United States Nuclear Regulatory Commission, Region I
 Division of Reactor Projects
TITLE: Chief, Reactor Projects Section No. 3B
EDUCATION: B.S., U.S. Naval Academy, 1973 (Graduated with Honors)
 Navy Nuclear Engineer Officer Course, 1977
 NRC Inspector Technical Training Program, 1980
 Various technical and management courses in USN and USNRC,
 such as QA, Reactor Engineering, Reactor Safety, Supervising
 Human Resources, EEO, Management Workshops
EXPERIENCE: Fifteen Years Nuclear Experience as Follows:
 1985-Present United States Nuclear Regulatory Commission (USNRC) --
 Reactor Projects Section Chief. Manage safety inspection
 programs for three commercial reactor facilities. Super-
 vise nine nuclear engineers. Provide formal assessments of
 utility management effectiveness and safety performance.
 1982-1985 USNRC -- Senior Resident Inspector at operations phase and
 preoperational phase nuclear power plants. Planned, super-
 vised, and performed inspections of management controls and
 activities important to nuclear safety. Coordinated
 specialist inspector efforts. Formally reported findings
 and recommended appropriate enforcement.
 1972-1982 USNRC -- Resident Inspector. Planned, performed, and docu-
 mented inspections of all functional areas at a dual-unit
 operating reactor site.
 1973-1979 U. S. Navy Nuclear Power Program. Duties included super-
 visory positions in nuclear plant operations, maintenance
 and training. Performed audits and coordinated plant self-
 assessment. Was responsible for a complex, in-plant
 nuclear training program for up to 300 students. Shipboard
 duties included Main Propulsion Assistant: responsible for
 all reactor and main propulsion systems, all radiological
 controls and plant chemistry. Collateral duties included
 QA Officer, and Nuclear Weapons Safety/Security Officer.
**SPECIAL
 QUALIFICATIONS:** Qualified BWR Inspector, NRC Region I, 1980
 Qualified Nuclear Engineer Officer, Naval Reactors, 1977
**SPECIAL
 ASSIGNMENTS:** Team Leader, NRC Integrated Performance Assessment Team
 Inspection, Oyster Creek, 1987
 Team Leader, NRC Team Inspection of Oyster Creek Contain-
 ment Vacuum Breakers Event, 1987
 Participated in various other plant readiness inspections,
 1984-1985

NAME: PAMELA M. CHAN

ORGANIZATION: Massachusetts Energy Facilities Siting Council (Since 12/87)

TITLE: Engineer/Utility Analyst

EDUCATION: B.S. M.E. Pennsylvania State University

EXPERIENCE: Five Years Nuclear Experience as Follows:

1987 United States Nuclear Regulatory Commission, Region III,
Reactor Inspector

1985-1987 Nuclear Power Services - Construction

1984-1985 Combustion Engineering - Nuclear Systems Services; Field
Service Engineer

1982-1984 Stone & Webster Engineering Corporation - Power Division
System Engineer - Turbine Plant Systems

SPECIAL
QUALIFICATIONS: Background in Maintenance and Quality Assurance

SPECIAL
ASSIGNMENTS: Participated in several team inspections while at NRC
Region III

NAME: SAMUEL J. COLLINS

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Reactor Projects

TITLE: Deputy Director

EDUCATION: Bachelor of Science, Maine Maritime Academy
Business Program, Southern Vermont College

EXPERIENCE: Seventeen Years Nuclear Experience in Design, Construction,
Operations, Inspection and Management as Follows:

1987 - Present Deputy Director: Division of Reactor Projects, USNRC,
Region I

1986 - 1987 Deputy Director (Detail): Division of Reactor Projects,
USNRC, Region I

As a member of the Senior Executive Service, responsible
for division management; the conduct of inspections and
evaluations of assigned NRC programs for all power and
non-power reactors within Region I.

1985 - 1986 Branch Chief: Reactor Projects Branch No. 2, USNRC,
Region I

Responsible for project management, staffing and budget
considerations, including inspections, implementation of
SALP, resident inspection and enforcement for eleven
assigned power reactor sites in operation and under
construction.

1984 - 1985 Section Chief: Reactor Projects Section No. 2C, USNRC,
Region I

Responsible for implementation of the routine and reactive
inspection program at six assigned power reactors during
new construction, testing and operation.

1983 - 1984 Senior Resident Inspector: Operations, Yankee Nuclear
Power Station, DRP, USNRC, Region I

Supervised; inspection and event response program at opera-
ting Westinghouse PWR power reactor facility.

1980 -1983 Resident Reactor Inspector: Operations, Vermont Yankee
Nuclear Power Station, DRP, USNRC, Region I. Field
inspector at operating General Electric BWR power reactor
facility.

Private Industry:

1971 - 1980 Tenneco Corporation, Newport News Shipbuilding. Various positions as contractor to U.S. Navy Nuclear Program including:

Project Manager - S5W Steam Generator Chemical Cleaning Project

Chief Test Engineer - Chairman and NNS representative to Joint Test Group for S5W overhaul and construction

Shift Test Engineer - Shift supervisor for reactor overhaul and refueling

Shift Test Engineer - Shift supervisor for reactor new construction

Mechanical Test Engineer - Shift mechanical test for reactor new construction

Reactor Design Engineer - Design support for reactor new construction

SPECIAL
QUALIFICATIONS:

Senior Executive Service Candidate Development Program, USNRC, 1986 - 1987

Qualified BWR Resident Inspector

Qualified PWR Resident Inspector

Qualified S5W Shift Test Engineer

Third Engineer License, USCG

SPECIAL
ASSIGNMENTS:

1988 - Team Manager, Pilgrim Integrated Assessment Restart Team Inspection

1987 - 1988 - Chairman, Pilgrim Restart Assessment Panel

1987 - 1988 - Region I Representative, NRC Training Advisory Group

1987 - Chairman, Differing Professional Opinion Peer Review Group

1987 - Chairman, Comanche Peak Task Force Review Group

1986 - Team Leader, Nine Mile Point 1 and 2 Diagnostic Team Inspection

1985 - Team Leader, Peach Bottom 2 and 3 Diagnostic Team Inspection

NAME: LAWRENCE T. DOERFLEIN

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Reactor Projects

TITLE: Project Engineer

EDUCATION: BS Electrical Engineering
US Naval Academy, 1973

EXPERIENCE: Fifteen Years Nuclear Experience as Follows:

Aug. 1985-Present Project Engineer

Oct. 1983-July 1985 Senior Resident Inspector, FitzPatrick Nuclear Power Plant

Nov. 1980-Oct. 1980 Resident Inspector, FitzPatrick Nuclear Power Plant

June 1973-Oct. 1980 US Navy

SPECIAL
QUALIFICATIONS: Certified NRC BWR Inspector
Qualified Chief Naval Nuclear Engineer

SPECIAL
ASSIGNMENTS: Limerick Readiness Assessment Team
Pilgrim Augmented Inspection Team

NAME: THOMAS F. DRAGOUN

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Radiation Safety and Safeguards

TITLE: Senior Radiation Specialist

EDUCATION: Rensselaer Polytechnic Institute, and Union College
DOD Staff College, Battle Creek, Michigan

EXPERIENCE: Twenty-Three Years of Nuclear Experience as Follows:

1983-Present NRC - Senior Radiation Specialist

1983-1969 General Electric Company, which included the following:

- Qualified s Operations Engineer and EOOW at Navy Prototype (3 Years)
- Senior Engineer on Trident Prototype Construction Project (5 Years)
- Health Physicist responsible for service work, both domestic and foreign by Large Steam Turbine Division (6 Years)

1965-1969 Cornell University - Taught Radiation Protection Subjects

NAME: MICHELE G. EVANS

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Reactor Safety

TITLE: Operations Engineer

EDUCATION: B.S., Chemical Engineering, University of Pennsylvania

EXPERIENCE: Four Years of Nuclear Experience as Follows:

Aug 1987-Present Operations Engineer, Boiling Water Reactor Section - Conduct review and inspection of Power Ascension Programs at Pilgrim and Nine Mile Point 2. Currently in training to qualify as BWR Operator Licensing Examiner

July 1984-Aug 1987 Reactor Engineer, Test Programs Section - Conducted review and inspection of preoperational test programs at Hope Creek and Nine Mile Point 2, and Startup Testing Programs at Limerick 1, Shoreham, Hope Creek and Nine Mile Point 2.

SPECIAL QUALIFICATIONS: USNRC Certified BWR Inspector

Engineer in Training (State of Pennsylvania)

SPECIAL ASSIGNMENTS: Currently participating in the Women's Executive Leadership Program for Management Development

NAME: JEFFREY J. LYASH

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Reactor Projects

TITLE: Resident Inspector - Pilgrim Nuclear Power Station

EDUCATION: B.S., Mechanical Engineering, Drexel University

EXPERIENCE: Six Years Nuclear Experience as Follows:

Two and One-Half Years - NRC Resident Inspector - Pilgrim
Nuclear Power Station

One Year - NRC Resident Inspector - Hope Creek Generating
Station

One Year - NRC Reactor Engineer - Region I

One and One-Half Years - Pennsylvania Power and Light
Company - Test Engineer - Susquehanna Steam Electric
Station

SPECIAL
QUALIFICATIONS: Meritorious Service Award as NRC Resident Inspector of the
Year 1987-1988

NAME: DANIEL G. MCDONALD, JR.

ORGANIZATION: United States Nuclear Regulatory Commission (USNRC)
Office of Nuclear Reactor Regulation

TITLE: Senior Project Manager

EDUCATION: B.S., Management, Shenandoah College
A.A., Engineering, Solano College

EXPERIENCE: Thirty-One Years Nuclear Experience as Follows:

1982-Present Senior Project Manager - Manage and coordinate all NRC licensing functions on assigned operating reactor facilities which have difficulties or complexities with management and operation. (NRC)

1982 (3 Months) Reactor Engineer (Instrumentation) - Technical evaluations of instrumentation and control systems or licensee applications and operating reactor modifications. Assist in developing regulatory requirements and establishing staff policy. (NRC)

1980-1982 Staff Member - Conduct, direct and coordinate assessments of critical technologies in the context of national security. Provide technical support to the Nuclear Regulatory Commission. (Los Alamos National Laboratory)

1979-1980 Reactor Inspector (Electrical) - Inspects reactors under construction and in operation. (NRC)

1978-1979 Senior Electrical Engineer - Technical evaluations of electrical, instrumentation and control systems. Assist in developing staff policy. (NRC)

1973-1978 Reactor Engineer (Instrumentation) - Technical evaluation for license applications and operating reactors. (NRC)

1966-1973 Senior Technical Associate - Field engineer in nuclear weapons test programs. (Lawrence Livermore Laboratory (LLL))

1964-1966 Senior Electronic Engineering Coordinator - Design of control, interlock and instrumentation systems for critical assembly machines, test reactors and containment vaults. (LLL)

1960-1964 Electronics Designer - Design of communication, personnel warning, closed circuit TV and radiation monitoring systems. (LLL)

- 1957-1960 Senior Electronic Technician - Fabricated and assisted in the design and development of prototype electrical and electronics equipment. (LLL)
- 1953-1957 Electrical Specialist - Four year apprenticeship with Department of Navy. (Mare Island Shipyard)

NAME: LOREN R. PLISCO

ORGANIZATION: United States Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Division of Licensee Performance and Quality Evaluation

TITLE: Senior Operations Engineer

EDUCATION: B.S., Systems Engineering, U.S. Naval Academy

EXPERIENCE: Eleven Years Nuclear Experience as Follows:

1987-1988 Senior Operations Engineer, NRC:NRR

1986-1987 Senior Resident Inspector - Susquehanna Steam Electric Station

1983-1986 Resident Inspector - Susquehanna Steam Electric Station

1982-1983 Reactor Engineer, Region I

1977-1982 US Navy Nuclear Power Program

SPECIAL QUALIFICATIONS: Certified NRC BWR Inspector
Qualified Naval Nuclear Engineer Officer

SPECIAL ASSIGNMENTS: Susquehanna 2 - Operational Readiness Assessment Team Inspection
Limerick 1 - Operational Readiness Assessment Team Inspection
Hope Creek - Operational Readiness Assessment Team Inspection
Salem - ATWS Inspection
TMI-1 - Management Integrity Inspection

NAME: WILLIAM J. RAYMOND

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Reactor Projects

TITLE: Senior Resident Inspector - Millstone Nuclear Power Station

EDUCATION: B.S. Physics
M.S. Nuclear Science and Engineering

EXPERIENCE: Eighteen Years Nuclear Experience as Follows:

1975-1988 NRC Reactor Operations Inspector

- SU&T, Core Physics, Refueling, Pre & SU&T for BV, CC1, IP3, MP2
- Project Inspector - Beaver Valley, Ginna and Susquehanna
- TMI Recovery Team - Accident Response and Containment Entry
- Senior Resident Inspector - Vermont Yankee and Millstone

1972-1975 Startup Engineer, Babcock & Wilcox, Oconee 1 and 2 and Three Mile Island, Unit 1

1970-1972 Reactor Operator, VPI Research Reactor

SPECIAL QUALIFICATIONS: VPI Reactor Operator License
Certified NRC Licensed Operator Examiner - 1986

SPECIAL ASSIGNMENTS: IAEA Assist Visit to Brazil CNEN - 1981
Team Leader Salem ATWS Event - NRC Fact Finding - 1983
Salem ATWS Generic Issue Review Team - 1983
NRC Response to Crystal River Event - 1981
Assist Visit to Region V - WNP2 Startup Readiness - 1982
Team Inspections - Shoreham 1982 and Pilgrim 1986
Operator Briefings of TMI Event - 1979

NAME: LAWRENCE ROSSBACH

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Reactor Projects

TITLE: Senior Resident Inspector - Indian Point Unit 2

EDUCATION: B.S., Nuclear Engineering

EXPERIENCE: Sixteen Years of Nuclear Experience as Follows:

- Six Years, NRC Resident Inspector and Senior Resident Inspector
- Two and One-Half Years, Program Manager for NRC's preparation to review a high level waste repository license application
- Two and One-Half Years, NRC Project Manager and Reviewer for Uranium Mills
- Five Years, Systems Design Engineer at Architectural Engineering (AE) Company

NAME: STEVEN C. SHOLLY

ORGANIZATION: MHB Technical Associates (Observer for the Commonwealth of Massachusetts)

TITLE: Associate Consultant

EDUCATION: B.S. in Education (1975); Graduate Course Work in Geo-environmental Studies (1976-1977)

EXPERIENCE: Seven and One-Half Years Nuclear Experience as Follows:

1985-Present MHB Technical Associates, San Jose, CA - Work in Risk Assessment, Quality Assurance, Operating Events Analysis, and Design and Construction Assessment

1981-1985 Union of Concerned Scientists, Washington, D.C. - Work in generic safety issues, risk assessment and emergency planning

SPECIAL ASSIGNMENTS:

- Member of NRC Peer Review Group, NUREG-1050 (1984)
- Participated in NRC Containment Performance Design Objective Workshop (1986)
- Participated in NRC/LLNL Workshop on Safety Goals Implementation, Presentation on Seismic Risk Assessment (1987)

NAME: GREGORY C. SMITH

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Radiation Safety and Safeguards

TITLE: Safeguards Specialist

EDUCATION: B.S. Education, California State College

- Various additional courses including: Technical Writing, Quality Assurance Auditing, Statistics, Reactor Design and Layout, Radiological Accident Assessment, Radiological Emergency Response, BWR Technology, Transportation of Radioactive Materials, Advanced Neutron Nuclear Materials Assay, Safeguards Chemical Analysis of Nuclear Materials, Nondestructive Assay of Nuclear Materials, Nondestructive Assay of Fissionable Material, Accident/Incident Investigation and Intrusion Detection Systems

EXPERIENCE: Twenty-Two Years Nuclear Industry Experience as Follows:

1977-Present Safeguards Specialist, Physical Protection Inspector and Safeguards Auditor (USNRC)

1966-1977 Westinghouse Electric Corporation, Bettis Atomic Power Laboratory - Production Engineer, Nuclear Materials Auditor, Nuclear Materials Analyst, Reactor Development Technician

NAME: CLAY C. WARREN

ORGANIZATION: United States Nuclear Regulatory Commission, Region I
Division of Reactor Projects

TITLE: Senior Resident Inspector - Pilgrim Nuclear Power Station

EDUCATION: B.S., Natural Sciences, Louisiana State University

Industrial:

- 1986 - USNRC Inspector Qualification Program
- 1985 - Training Program on the General Electric BWR-6 product line and received NRC Senior Reactor Operator License
- 1982 - GE Boiling Water Reactor (BWR) Senior Reactor Operator Certification training at the General Electric BWR Training Center
- 1980 - Shift Test Engineer training program at General Dynamics Corporation, Electric Boat Division. Successfully completed the Naval Engineering Officer exam administered by Naval Reactors.

Military:

- Navy Nuclear Prototype Training
- Navy Nuclear Power School
- Electronics Technicians School

EXPERIENCE: Fifteen Years Nuclear Experience as Follows:

- Jan 1987-Present United States Nuclear Regulatory Commission, Senior Resident Inspector
- Jan 1986-Jan 1987 Resident Inspector
- June 1984-Jan 1986 Shift Supervisor, Gulf States Utilities Company, River Bend Nuclear Station
- Jan 1981-June 1984 Control Operating Foreman, Gulf States Utilities Company, River Bend Nuclear Station
- June 1979-Dec 1980 Shift Test Engineer, General Dynamics Corporation, Electric Boat Division
- Jan 1971-June 1979 Electronics Technician - Reactor Operator, United States Navy

SPECIAL QUALIFICATIONS: USNRC Senior Reactor Operators License

SPECIAL
ASSIGNMENTS:

Nine Mile Point 2 Operational Readiness Assessment Team
Inspection

Peach Bottom - Special Team Inspection March 1986



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406

01 SEP 1988

The Commonwealth of Massachusetts
Executive Office of Public Safety
ATTN: Mr. Charles V. Barry
One Ashburton Place
Boston, Massachusetts 02108

Dear Mr. Barry:

This refers to our letter of July 13, 1988, regarding the Commonwealth of Massachusetts' participation in the Integrated Assessment Team Inspection (IATI) conducted at the Pilgrim Nuclear Power Station.

As the NRC Senior Manager responsible for the inspection, I would like to acknowledge the conduct of the designated state representatives Ms. Pamela J. Chen and Mr. Steven C. Sholly as being professional and contributing to the performance of the inspection.

The established protocol (enclosed) provided to you on June 1, 1988, clarified by our letter of July 13, 1988, and discussed directly by myself with Mr. Peter Agnes of your staff on August 9, 1988, provides for collection and coordination of the concerns from the various interests within the Commonwealth. As stated in our July 13, 1988 letter, the NRC placed the burden on the Commonwealth's representative to present the many views, be they from the local governments or from the State's Attorney General's office, to the NRC for consideration during development of the inspection scope. In this regard, we understand that Mr. Agnes conducted a public meeting on August 4, 1988, with a designated state representative to the IATI present.

On August 9, 1988, having received no issues from the Commonwealth as an additional input to the existing inspection plan, I contacted the Assistant Secretary of Public Safety directly and was assured that: no formal input to the IATI inspection plan would be submitted by the Commonwealth, the Commonwealth would work through the designated representatives for any issues and that issues brought to the Commonwealth's attention were no different than those previously noted. Also, the team leader has notified me that at no time during the inspection did he receive immediate notification of any different state observation or conclusion as would be called for under Protocol Guideline 3 if any such differences were identified during the inspection.

Since the IATI exit meeting conducted on August 24, 1988 which was attended by Mr. Agnes and Ms. Chen, the Commonwealth has expressed on several occasions both to the media and at public meetings that technical issues and management concerns continue to exist. These statements appear inconsistent with the Commonwealth's response to repeated NRC requests for IATI inspection scope input and moreover inconsistent with the Commonwealth views expressed at the IATI exit meeting.

In order to better understand and address the areas of concern, the NRC requests that in accordance with the protocol agreement accepted by the Commonwealth, as provided for by Guideline 3, that the Commonwealth make available in writing those conclusions or observations that are substantially different from those of the NRC inspectors in order that the NRC can take the necessary actions to meet its regulatory responsibilities.


Mr. Charles V. Barry

2 01 SEP 1988

It is necessary that the Commonwealth's response be provided to the NRC Region I by September 6, 1988, to be considered in conjunction with the documentation of the results of the recently completed IATI. This request was discussed with Mr. P. Agnes of your staff on August 26 and August 31, 1988.

If you have any questions regarding the above matters, please contact me at (215) 337-5126 or the State Liaison Officer for Region I, Ms. Marie Miller at (215) 337-5246.

Sincerely,


 Samuel J. Collins, Deputy Director
 Division of Reactor Projects

Enclosure: As Stated

cc w/encl:

R. Bird, Senior Vice President - Nuclear
 K. Highfill, Station Director
 R. Anderson, Plant Manager
 J. Keyes, Licensing Division Manager
 E. Robinson, Nuclear Information Manager
 R. Swanson, Nuclear Engineering Department Manager
 The Honorable Edward J. Markey
 The Honorable Edward P. Kirby
 The Honorable Peter V. Forman
 B. McIntyre, Chairman, Department of Public Utilities
 Chairman, Plymouth Board of Selectmen
 Chairman, Duxbury Board of Selectmen
 Plymouth Civil Defense Director
 P. Agnes, Assistant Secretary of Public Safety, Commonwealth of
 Massachusetts
 S. Pollard, Massachusetts Secretary of Energy Resources
 R. Shmshak, MASSPIRG
 Public Document Room (PDR)
 Local Public Document Room (LPDR)
 Nuclear Safety Information Center (NSIC)
 NRC Resident Inspector
 Commonwealth of Massachusetts (2)

brc w/encl:

Region I Docket Room (with concurrences)
 S. Collins, DRP
 J. Wiggins, DRP
 R. Blough, DRP
 L. Doerflein, DRP
 R. Bores, DRSS
 D. McDonald, PM, NRR

ENCLOSUREGuidelines for Accompaniment on the Integrated Assessment Team Inspection

The following are guidelines for accompaniment during NRC's Pilgrim Integrated Assessment Team Inspection.

1. The observer is to make arrangements with the licensee for site access training and badging.
2. The observer shall be available throughout the inspection and will accompany NRC inspectors. Communication with the licensee will be through the appropriate NRC team member, preferably the team leader.
3. When the conclusions or observations made by the Commonwealth of Massachusetts observer are substantially different from those of the NRC inspectors, Commonwealth of Massachusetts will make its observations immediately known to the inspection team leader and available in writing to the NRC and the licensee, in order that NRC can take the necessary actions to meet its regulatory responsibilities. These communications will be publicly available, similar to NRC inspection reports.
4. NRC inspectors are authorized to refuse to permit continued accompaniment by the Commonwealth of Massachusetts observer if his conduct interferes with a fair and orderly inspection.
5. The Commonwealth of Massachusetts observer in accompanying NRC inspectors will not normally be provided access to proprietary information. No license material may be removed from the site or licensee possession without NRC approval.
6. The Commonwealth of Massachusetts observer in accompanying the NRC inspectors pursuant to these guidelines does so at his own risk. The NRC will accept no responsibility for injuries and exposures to harmful substances which may occur to the accompanying individual during the inspection and will assume no liability for any incidents associated with the accompaniment.



Michael S. Dukakis
Governor

Charles V. Barry
Secretary

The Commonwealth of Massachusetts
Executive Office of Public Safety
One Ashburton Place
Boston, Massachusetts 02108

APPENDIX 11

September 6, 1988

Samuel J. Collins, Deputy Director
Division of Reactor Projects
N.R.C. Region One
475 Allendale Road
King of Prussia, Pa. 19406

Dear Mr. Collins:

This is in reply to your letter dated September 1, 1988, regarding the Commonwealth's participation in the recently completed IATI inspection at Pilgrim Station.

The Commonwealth's observers, Mr. Sholly and Ms. Chan, generally concur with the findings of the IATI team. The Commonwealth's observers followed the prescriptions of paragraph three of the "Guidelines For Accompaniment On The Integrated Assessment Team Inspection" by communicating their observations, concerns and comments about matters considered during the inspection to appropriate N.R.C. personnel during the inspection. The only additional comment we wish to add about the IATI at this time is a recommendation by Mr. Sholly, that in view of the difficulty in one case with implementation of a satellite EOP, that there should be an effort to validate all new plant procedures before restart. Any specific reaction we may have to the written IATI report will, of course, have to await our review of the document.

However, as I pointed out during the recent S.A.L.P. meeting, the Commonwealth reserves the right to disagree with the conclusions drawn by the N.R.C. or the licensee about the IATI findings. For example, notwithstanding what might be considered unmistakable evidence of progress by Boston Edison Company, the Commonwealth remains skeptical of the licensee's readiness to restart at this time. In addition to our concerns about offsite emergency preparedness which have been outlined recently in letters to Mr. Henry Vickers of P.E.M.A., Regional Administrator William Pussell, and to the A.C.R.S. Ad Hoc Subcommittee on the restart of Pilgrim, the Commonwealth is concerned that mediocre scores by the licensee during the last

850940206 299


Samuel Collins, N.R.R.
September 6, 1988
Page Two

S.A.L.P. period coupled with a history of poor performance by the licensee have not been taken seriously enough in the staff's evaluation of readiness to restart. If the licensee is unable to achieve S.A.L.P. scores that even equal the national average for licensed commercial nuclear power plants in this country while Pilgrim remains shutdown, why should we believe that the plant is ready to restart?

Some of our other concerns, which transcend the scope of the [redacted] outlined in our letter to the A.C.R.S., a copy of which [redacted] forwarded to you tomorrow.

We appreciate your acknowledgment of the professionalism exhibited by Mr. Sholly and Ms. Chan during the IATI and the cooperation extended to them by the team members and the licensee.

Sincerely,



Peter W. Agnes, Jr.
Assistant Secretary
of Public Safety

PWA/cas




THE COMMONWEALTH OF MASSACHUSETTS

DEPARTMENT OF THE ATTORNEY GENERAL

JOHN W. MCCORMACK STATE OFFICE BUILDING
ONE ASHBURTON PLACE, BOSTON 02108-1698

JAMES M. SHANNON
ATTORNEY GENERAL



October 15, 1987

FEDERAL EXPRESS

Director of the Office of Nuclear
Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC. 20555

RE: Enclosed 10 C.F.R. § 2.206 Petition concerning the
Pilgrim Nuclear Power Station

Dear Sir:

Enclosed is the Petition of Michael S. Dukakis, Governor and James M. Shannon, Attorney General for the Institution of a Proceeding Pursuant to 10 C.F.R. § 2.202 to Modify, Suspend, or Revoke the Operating License Held by the Boston Edison Company For The Pilgrim Nuclear Station, which I am filing on behalf of myself and Governor Michael S. Dukakis.

Very truly yours,

James M. Shannon
Attorney General

~~8710100234~~ 871015
PDR ADOCK 05000293
G PDR

8710160234 sp

1987 SEP - 5 A 9 55
USHRC-DS

YE03
1/3

UNITED STATES OF AMERICA
BEFORE THE NUCLEAR REGULATORY COMMISSION

PETITION OF MICHAEL S. DUKAKIS, GOVERNOR AND
JAMES M. SHANNON, ATTORNEY GENERAL FOR THE
INSTITUTION OF A PROCEEDING PURSUANT TO
10 C.F.R. §2.202 TO MODIFY, SUSPEND, OR
REVOKE THE OPERATING LICENSE HELD BY
THE BOSTON EDISON COMPANY FOR THE
PILGRIM NUCLEAR STATION

Dated: October 15, 1987

~~871015~~ 871015
PDR ADOCK 05000293
G PDR

~~8710160293~~ 95pp

UNITED STATES OF AMERICA
BEFORE THE NUCLEAR REGULATORY COMMISSION

PETITION OF MICHAEL S. DUKAKIS, GOVERNOR AND
JAMES M. SHANNON, ATTORNEY GENERAL FOR THE
INSTITUTION OF A PROCEEDING PURSUANT TO
10 C.F.R §2.202 TO MODIFY, SUSPEND, OR
REVOKE THE OPERATING LICENSE HELD BY
THE BOSTON EDISON COMPANY FOR THE
PILGRIM NUCLEAR STATION

Dated: October 15, 1987

TABLE OF CONTENTS

I.	<u>INTRODUCTION</u>	1
II.	<u>EVIDENCE OF SERIOUS MANAGERIAL DEFICIENCIES</u>	3
	A. OVERVIEW	3
	B. BECo'S PAST PERFORMANCE	4
	BECo'S SALP Evaluations	5
	BECo'S Regulatory Violations	7
	C. RECENT INDICIA OF BECo'S PERFORMANCE LEVEL	9
	BECo'S 1987 SALP Report	10
	Recent Reports of Violations	12
III.	<u>EVIDENCE THAT INDICATES THAT A PLANT SPECIFIC PRA FOLLOWED BY IMPLEMENTATION OF ANY INDICATED SAFETY MODIFICATIONS SHOULD BE REQUIRED PRIOR TO PILGRIM'S RESTART</u>	12
IV.	<u>EVIDENCE OF INADEQUATE EMERGENCY PREPAREDNESS</u>	15
V.	<u>CONCLUSION</u>	21

UNITED STATES OF AMERICA
BEFORE THE NUCLEAR REGULATORY COMMISSION

PETITION OF MICHAEL S. DUKAKIS, GOVERNOR AND
JAMES M. SHANNON, ATTORNEY GENERAL FOR THE
INSTITUTION OF A PROCEEDING PURSUANT TO
10 C.F.R. §2.202 TO MODIFY, SUSPEND, OR
REVOKE THE OPERATING LICENSE HELD BY
THE BOSTON EDISON COMPANY FOR THE
PILGRIM NUCLEAR STATION

I. INTRODUCTION

Governor Michael S. Dukakis and Attorney General James M. Shannon, pursuant to 10 C.F.R. §2.206, hereby request that the Director of the Office of Nuclear Reactor Regulation institute a proceeding pursuant to 10 C.F.R. §2.202 to modify, suspend, or revoke the operating license held by Boston Edison Company ("BECO." or "the Company") for the Pilgrim Nuclear Power Station ("Pilgrim") in Plymouth, Massachusetts. This petition is filed on behalf of the Commonwealth of Massachusetts and its citizens. The Governor and the Attorney General base this request on evidence of continuing serious managerial deficiencies at the plant, on evidence that a plant specific probabilistic risk assessment ("PRA") as well as the implementation of any safety modifications indicated thereby should be required prior to Pilgrim's restart, and on evidence that the state of emergency preparedness does not provide reasonable assurance that adequate protective measures can and

will be taken in the event of a radiological emergency during operations at the Pilgrim plant. The Governor and the Attorney General submit that this evidence, as set forth below, demonstrates the necessity of Nuclear Regulatory Commission ("NRC") action pursuant to 10 C.F.R. §2.202.

Further, the Governor and the Attorney General believe that the public interest requires that the NRC exercise its authority under 10 C.F.R. §2.202(f)^{1/} so that BECo. is prevented from proceeding any further with the restart of Pilgrim^{2/} until a formal adjudicatory hearing has been held and findings of fact are made concerning the safety questions surrounding the continued operation of the Pilgrim plant. In particular, the Governor and the Attorney General request that the NRC issue an order, effective immediately, modifying BECo's operating license to preclude BECo. from taking any steps in

^{1/} 10 C.F.R. 2.02(f) provides:

When the Executive Director for Operations, during an emergency as determined by the EDO, or the Director of Nuclear Reactor Regulation, Director of Nuclear Material Safety and Safeguards, Office of Inspections and Enforcement, as appropriate, finds that the public health, safety, or interest so requires or that the violation is willful, the order to show cause may provide, for stated reasons, that the proposed action be temporarily effective pending further review.

^{2/} At each step of BECo's so-called "power ascension" program there is an increase in the probability of an accident at Pilgrim as well as in the potential consequences of such an accident. See Affidavit of Steven C. Sholly (attached hereto as Attachment 1).

it. power ascension program until the hearing is held and the findings are made.

II. EVIDENCE OF SERIOUS MANAGERIAL DEFICIENCIES

Recent events at Pilgrim indicate that BECo. has not corrected the long-standing managerial shortcomings that have plagued the plant. In the areas of security, radiological controls, personnel management, and corporate culture, the management of Pilgrim continues to be seriously flawed. As a result, Pilgrim poses an unreasonable risk to public health and safety. Its continued operation under the present circumstances is inimical to public health and safety.

A. OVERVIEW

Pilgrim commenced commercial operation in June, 1972, when BECo. received an operating license for the plant. During the intervening fifteen year period of operation by BECo., Pilgrim has had a capacity factor of approximately 50 percent,^{3/} which compares quite unfavorably with the average for all New England nuclear plants of approximately 67 percent.^{4/}

^{3/} The "capacity factor" for a plant is a measure of performance in terms of the power it has actually delivered over a period of time relative to the power it was capable of delivering over that same period of time. It is calculated by dividing the actual number of kilowatt hours produced by the plant in the period of measurement by the product of the plant's rated kilowatt capacity and the number of hours in the period.

^{4/} electric Council of New England, New England Nuclear News, (June, 1987) (Attached hereto as Attachment 2).

B. BECo's PAST PERFORMANCE

The plant has been out of service since April, 1986, when the NRC, in Confirmatory Action Letter 86-10, ordered a shutdown after recurring operational problems at the plant.^{5/}

Pilgrim has been beset with managerial problems from the outset. BECo. has consistently received low ratings in the NRC's Systematic Assessment of Licensee Performance ("SALP") reports. Pilgrim has been identified by the NRC as one of the worst run and least safe plants in the country^{6/} and BECo. was ordered to initiate performance/management improvement programs in 1982 and 1984.^{7/} BECo. has been the subject of a long line of enforcement actions as a result of regulatory violations. While the NRC's efforts to spur BECo. to a higher level of performance have, on occasion, met with some initial success, a review of BECo's performance record, however, shows that all such successes have been short lived. Indeed, BECo.

^{5/} Confirmatory Action Letter 86-10 was clarified and expanded in an subsequent letter, dated August 27, 1987, from the NRC Region 1, Regional Administrator to BECo's Chief Operating Officer. (attached hereto as Attachment 3). In this letter, BECo. was informed that:

In light of the number and scope of the outstanding issues, I (the Regional Administrator) am not prepared to approve restart of the Pilgrim facility until you (BECo.) provide a written report that documents BECo's formal assessment of the readiness for restart operation.

^{6/} Boston Globe, May 28, 1986.

^{7/} Order Modifying License Effective Immediately, 47 Fed. Reg. 4171 (January 28, 1987).

appears to have an organic inability to manage Pilgrim in an effective and safe manner.^{8/}

**** BECo's SALP Evaluations ****

BECo. has consistently received low ratings in SALP reports.^{9/}

8/ Although it is the failings of BECo's management of the Pilgrim plant which are the subject of this petition, it is significant that findings have been made in other settings that confirm BECo's managerial deficiencies and indicate that they extend to the other aspects of its business. See e.g., Boston Edison Company, Massachusetts Department of Public Utilities Docket No. 87-1A-A (1987) (imprudence in operation of oil fired generating unit). Of particular relevance to the notion that BECo. responds to the identification of deficiencies with half-hearted (although sometimes quite showy), short-term solutions that treat the symptoms, not the disease, is the series of decisions by the Massachusetts Department of Public Utilities that address BECo's need to consider and develop new sources of power in the aftermath of the 1981 cancellation of the construction of the Pilgrim II nuclear unit. Boston Edison Company, MDPU 906 (1982) (ordering BECo. to develop a new plan to meet its future power needs); Boston Edison Company, MDPU No. 86-270 (found reason to believe BECo lacked commitment and/or skill to fulfill public service obligation).

9/ The SALP process is the mechanism by which the NRC on a periodic basis systematically assesses the overall performance of a licensee. For each assessment period (generally 12 to 18 months) a Board of NRC officials evaluates, in accordance with preestablished attributes and rating guidance, the licensee's performance for each of the various, preestablished functional areas and rates the licensee's performance in each area. The Board also compares the licensee's performance for the current period with that of the previous assessment period and identifies, for further followup and inspection, any areas where the licensee's corrective action to improve performance has not been fully effective.

Arizona Public Service Company, (Palo Verde Nuclear Generating Station, Unit 2), DD-86-8, 24 NRC 151, 156 (1986).

In 1980, BECo. received ratings indicating significant weakness in three of the nine functional areas evaluated. The most recent SALP Report, seven years later, indicates that conditions have not improved but rather have worsened. BECo. received ratings indicating significant weaknesses in five of the twelve functional areas evaluated. It has only once received a SALP Report without a rating indicating a significant weakness. On all other occasions, it has received reports indicating significant weaknesses in at least two functional areas. (See Appendix I: BECo. SALP History Tabulation)

Of particular significance, every time Quality Assurance has been assessed as a separate functional area during a SALP review, BECo. has received the lowest possible rating. These findings are indicative of the ineffectiveness of BECo's management. They are a measure of its inability and/or its lack of commitment to run the plant in a effective and safe manner.

Although BECo. has at one time or another received the lowest possible rating in all but three of the twelve functional areas covered by the NRC's SALP process, these individual poor SALP ratings are not the most troubling aspect of BECo's SALP record. Instead, the most troubling and telling facet of BECo's SALP record is the Company's distinct inability to maintain any period-to-period performance improvements. BECo. has at one time or another improved its SALP performance

in eight functional areas. However, it has not been able to sustain the increased level of performance in seven of those eight areas. In all but one instance, BECo's improved performance proved to be short-lived and its performance subsequently fell back to lower levels. This is not surprising as an ever recurring theme in NRC evaluations of BECo's performance is that NRC oversight and prompting is necessary at every stage of Pilgrim's operation.^{10/} The increased NRC attention (i.e., oversight and prompting) that a "3" rating calls for has, on occasion, produced better performance by BECo. However, when that level of attention returns to that norm, BECo's performance falls below the norm. BECo's SALP track record is proof of the proposition that BECo, by itself has not effectively operated Pilgrim and that the short-term solutions it has adopted in response to criticism have invariably permitted the reoccurrence of the original problems.

** BECo's Regulatory Violations **

BECo., an enforcement action record that is a mirror of its SALP Report record. It has had at least one Severity Level III violation during each of the past six years.^{11/} (See

^{10/} E.g., 1987 SALP Review at 8; 1986 SALP Review at 7.

^{11/} As set forth in 10 C.F.R. Part 2, Appendix C; General Statement of Policy and Procedure for NRC Enforcement Actions, regulatory violations are categorized into five descending levels of severity. Level III corresponds with "violations that are cause for significant concern."

Appendix II: BECO. VIOLATIONS TABULATIONS - SEVERITY LEVEL III VIOLATIONS) In the area of Security and Safeguards, BECo. had a Severity Level III violation in all but one of the years between 1981 and 1986. In 1982, a civil penalty in the amount of \$550,000 -- at the time the largest penalty to have ever been assessed by the NRC -- was levied against BECo. for serious plant operations violations and for submitting false information to the NRC.^{12/} While the number of such Severity Level III violations discovered at Pilgrim has not exceeded two in any single year since 1981, the number of Severity Level IV violations per year has more than doubled in the past few years.

BECO's enforcement action record also mirrors its SALP Report record in demonstrating BECo's chronic recidivism. It has been cited five times for Radiological Controls violations involving waste shipment packaging requirements.^{13/}

It has been cited five times for Security and Safeguards violations involving the control of sensitive material such as keys to vital areas, security plans, and firearms.^{14/}

^{12/} U.S. General Accounting Office, Report to the Honorable Alfonse M. D'Amato, U.S. Senate: Nuclear Regulation Efforts to Ensure Nuclear Power Plant Safety Can Be Strengthened (GA/RCED-87-141 August, 1987), pp. 36-37.

^{13/} See NRC Enforcement Summary Tables taken from various SALP Reports (attached hereto as Attachment 4).

^{14/} Id.

C. RECENT INDICIA OF BECO'S PERFORMANCE LEVEL

The most recent indicia of the level of BECO's performance in managing Pilgrim are consistent with its past performance. They confirm the notion that BECO. appears to be organically incapable of managing a nuclear facility. Notwithstanding the frequent incantation by senior management of a program for the "pursuit of excellence," the addition of new personnel and the expenditure of large sums of money,^{15/} the available evidence indicates that BECO. has not changed. Its 1987 SALP Report shows that the Company continues to merit the lowest possible ratings in many functional areas. BECO. continues to be incapable of maintaining performance gains. On the basis of news reports, it appears that BECO's management of the Security and Safeguards function is deteriorating, not improving. Further, on the basis of statements made by NRC officials at a recent meeting, the NRC has received and is investigating allegations that the company may be compromising safety by overworking its or its contractors' employees in an effort to return the plant to service soon. This evidence suggests that BECO's claim to be approaching readiness for restart may

^{15/} E.g., NRC Docket No. 50-293, Official Transcript of NRC Office of Nuclear Reactor Regulation, "Meeting With Boston Edison Re: Pilgrim Status and Activities Leading to Restart Readiness," pp. 13-14, 18-20 (September 24, 1987) (hereinafter "9/24/87 NRC/BECO. Readiness Meeting"). (Testimony submitted by Stephen J. Sweeney, President and Chief Executive Officer, Boston Edison Company, to the U.S. House of Representatives, Subcommittee on Energy Conservation and Power of the Committee on Energy and Commerce July 16, 1986, pp. 4-5 (attached hereto as "Attachment 5").

be hasty and misleading.^{16/}

**** BECo's 1987 SALP Report ****

On April 8, 1987, the NRC released a SALP Report for BECo. which was based on the results of various inspections and evaluations conducted at Pilgrim over the period from November 1, 1985 through January 31, 1987. Ratings were given for BECo's performance in twelve functional areas. In keeping with its past record, BECo. received the lowest possible ratings in five of the twelve functional areas.^{17/} It received the highest possible rating in only two functional areas.^{18/} The picture painted in the SALP report is one of a plant with "(p)oor management control," an "obscured ... chain of command and weakened accountability," and "(s)ignificant recurring program weakness ... in some functional areas, showing the effect of ... long-term problems."^{19/}

^{16/} BECo's claim of readiness should be measured against its adoption of 9/24/87 NRC/BECo. Readiness Meeting, p. 43. This tendency to ignore reality in the operation of the plant has been previously found to be undesirable. See Boston Edison Company, MDPU NO. 1009-F (1982) (BECo. denied where evidence established that it had imprudently underestimated the necessary time required to perform outage tasks).

^{17/} The five areas were: Radiological Controls, Surveillance, Fire Protection, Security and Safeguards, and Assurance of Quality.

^{18/} The two areas were: Outage Management, Modifications, and Technical Support Activities and Engineering and Corporate Technical Support.

^{19/} 1987 SALP REPORT at 8.

Of particular importance to this Petition, were SALP ratings in three areas where BECo. had previously improved its performance. In the functional areas of Surveillance, Fire Protection, and Licensing Activities, BECo. had in the past improved its ratings between periods -- in fire protection, it had gone from a "3" to a "1" between its third and fourth SALP Reports -- but by the time of the review for the 1987 SALP Report, its performance had fallen back to earlier levels.

With respect to the functional area of Security and Safeguards, the 1987 SALP Report discussed continuing hardware problems, BECo's excessive reliance upon contractors, and management's failure to give this area sufficient attention.^{20/} The report noted that BECo's corrective actions for deficiencies in this area had not generally been effective and referenced three degradations in vital area barriers that had occurred during the evaluation period.^{21/}

^{20/} Id. at 31-34.

^{21/} The Commission's regulations define a "vital area" as any area which contains:

any equipment, system, device, or material, the failure, destruction, or release of which could directly or indirectly endanger the public health and safety by exposure to radiation. Equipment or systems which would be required to function to protect public health and safety following such failure, destruction, or release are also considered vital areas. 10 C.F.R. §73.2(h) and (i) (emphasis added). Such areas are to "be located within a protected area such that access to vital equipment requires passage through at least two physical barriers." 10 C.F.R. §73.50(b)(1). Access into a protected area is to be controlled through the checking of authorization and identity at entry control points to which barriers surrounding the protected area "channel persons and material." 10 C.F.R. §73.45(b)(1)(i) and 73.50(c).

** Recent Reports of Violations **

On the basis of news reports and statements made by NRC officials at a recent meeting, it appears that BECo. has suffered from at least four significant Security and Safeguards lapses in the past six months: a misplaced gun; a misplaced set of sensitive keys; a "serious degradation in a vital area barrier;" and ineffective identification cards.^{22/} While all four alleged lapses would be significant, the latter three would be a particularly strong indication of BECo's failure to learn from its past mistakes -- nearly identical lapses have occurred in the past.^{23/}

Further, allegations have recently been made which NRC stated at a recent meeting that they are investigating that BECo. may be compromising worker and/or plant safety by requiring excessive overtime.^{24/}

III. EVIDENCE THAT INDICATES THAT A PLANT SPECIFIC PRA FOLLOWED BY IMPLEMENTATION OF ANY INDICATED SAFETY MODIFICATIONS SHOULD BE REQUIRED TO PILGRIM'S RESTART.

Pilgrim is a GE Mark I design plant. As such, it has a primary containment which, by nearly unanimous agreement, has an extremely high probability of failure in the event of

^{22/} Boston Globe, September 4, 1987, p. 1; Boston Globe, September 9, 1987, p. 21; Boston Herald, September 10, 1987, p. 24.

^{23/} See 1985 SALP Report, p. 40; 1983 SALP Report, pp. 41-43; 1982 SALP Report, p. 38 (included in Attachment 3 hereto).

^{24/} Boston Globe, September 29, 1987, p. 21.

certain accidents.^{25/} This characteristic is especially critical since Mark I design reactors, such as Pilgrim, do not have the backup of a secondary containment structure which can withstand any significant position pressure. ("PWRs").^{26/} In fact, Pilgrim's so-called "containment building" is not really designed to perform a backup function. It has "blow panels" which in some design and most severe accidents would activate and create a ready path for hazardous radioactive materials to escape into the environment.^{27/} The combination of an extremely vulnerable primary containment structure, a secondary containment not designed to provide an effective backup, and the large population in the immediate vicinity of Pilgrim^{28/} compel the Governor and the Attorney General to request that the NRC modify the Pilgrim operating license to bar restart until a plant specific probabilistic risk assessment ("PRA") is performed for Pilgrim and all indicated safety modifications are implemented. Until this occurs, the operation of the plant would pose an unreasonable threat to public health and safety.^{29/}

^{25/} See NUREG-1150, Reactor Risk Reference Document, Draft for Comment, Feb. 1987, at 4-33, 4-39.

^{26/} Affidavit of Steven C. Sholly (attached hereto as Attachment 1).

^{27/} Id.

^{28/} Id.

^{29/} Id.

The Governor and the Attorney General are aware that the NRC has to date declined to order mitigative modifications for Mark I design plants.^{30/} They submit, however, that the evidence presented here -- the combination of extremely vulnerable containment structures and a large population surrounding the plant -- precludes application of NUREG-1150's finding that the probability of a large reactor accident with early fatalities is extremely remote. The NUREG-1150 findings do not reflect the amalgam of risks posed by Pilgrim.

BECO. has proposed a number of modifications as remedial actions for the plant's design deficiencies.^{31/} These actions do not, however, address the inherent defects of the plant's design in any real way. The Governor and the Attorney General do, however, submit that through its so-called "safety enhancement program," BECO. has put the question of the appropriate modifications to be made to remedy the defects of the Mark I design in issue.

^{30/} E.g., Boston Edison Company (Pilgrim Nuclear Station), DD-87-14, ___ NRC ___ (1987) (slip at 31-32).

^{31/} Letter with enclosures dated July 8, 1987, from Mr. Ralph G. Bird, Senior Vice President-Nuclear, Boston Edison Company, to Mr. Steven A. Varga, Director, Division of Reactor Projects, I/II, Nuclear Regulatory Commission (attached hereto as Attachment 6).

IV. EVIDENCE OF INADEQUATE EMERGENCY PREPAREDNESS

Within the past twelve months, two authoritative assessments have been made of the Pilgrim Radiological Emergency Response Plan and the state of emergency preparedness within the Emergency Planning Zone ("EPZ") for Pilgrim.^{32/} Both conclude that the plan and the state of preparedness "are not adequate to protect the health and safety of the public in the event of an accident at the Pilgrim Nuclear Power Station."^{33/} Both also concluded that the plan and the state of preparedness have significant deficiencies and suggest potential remedies for those deficiencies that will require a substantial commitment of time, resources and cooperation.^{34/} BECo. has not quarreled with these conclusions.^{35/} The Governor and the Attorney General submit that these conclusions compel immediate action by the NRC. The

^{32/} FEMA, "Self-Initiated Review and Interim Finding for the Pilgrim Nuclear Power Station, Plymouth, MA" (August 4, 1987) (hereinafter "FEMA Self-Initiated Review"); Secretary of Public Safety, "Report to the Governor on Emergency Preparedness for an Accident at the Pilgrim Nuclear Power Station" (December 16, 1986) (hereinafter "Barry Report").

^{33/} FEMA Self-Initiated Review at 1-2; Barry Report at 74.

^{34/} FEMA Self-Initiated Review, pp. 12-13, 19, 22, 29-32, 43-44; Barry Report, pp. 47-55.

^{35/} 9/24/87 NRC/BECo Readiness Meeting", pp. 49-54.

authoritative expert agencies^{36/} agree that there is no reasonable assurance that the public can or will be protected in the event of an accident at Pilgrim. It is, thus, incumbent upon the NRC to take action immediately to insure that no steps are taken by BECo. which could increase the likelihood or the consequences of an accident.^{37/}

A. THE PLANNING AND PREPAREDNESS DEFICIENCIES IDENTIFIED BY FEMA AND THE MASSACHUSETTS EXECUTIVE OFFICE OF PUBLIC SAFETY

The deficiencies of the Radiological Emergency Response Plans for Pilgrim are manifold. Although the analyses of FEMA and the Massachusetts Executive Office of Public Safety do not reach the same conclusions on all issues, the following areas of substantial deficiency have been identified by both agencies:

1. the lack of any articulated evacuation plans for public and private schools as well as day care centers;
2. the lack of any articulated evacuation plans for the special needs population;

^{36/} FEMA is explicitly recognized by the Commission as the expert Federal authority on questions of nuclear power plant offsite emergency preparedness (Memorandum of Understanding, 50 Fed. Reg., No. 75, 15,486 (April 18, 1985) and the Commission is expressly required to base its findings on off-site emergency issues on FEMA's conclusions concerning such issues. 10 C.F.R. §50.47(s)(3). The Massachusetts Secretary of Public Safety oversees the Massachusetts Civil Defense Agency and Office of Emergency Planning, which pursuant to M.G.L. c. 147, §1 is responsible for the Commonwealth's emergency activities.

^{37/} Each step of BECo's power ascension plan corresponds with a substantial increase in the probability of an accident at Pilgrim. Affidavit of Steven C. Sholly (attached hereto as Attachment 1).

3. the lack of any articulated evacuation plans for the transport dependent population;
4. the lack of identifiable public shelters for the beach population;
5. the lack of a reception center, as required in the plan, for people evacuating by the northern route;
6. the lack of real progress in planning and the diminution in the state of emergency preparedness.^{38/}

These are critical deficiencies. The plans do not even purport to provide any measure of protection for significant numbers of people: pre-school and school age children; those who require special measures to transport; and those without ready access to private transportation. They fail to address the significant beach population in an adequate fashion. They do not incorporate current or reliable evacuation time estimates ("ETEs"). Nor do they incorporate a delineated inventory of identified and identifiable shelters which are accessible to the public. Moreover an integral component of the current plans -- a northern reception center^{39/}

^{38/} FEMA Self-Initiative Review, pp. 12-13, 19, 22, 29-32, 43-44; Barry Report, pp. 47-55.

^{39/} The lack of a reception center for those evacuating to the north is as worrisome as the more general planning failures. The lack of a northern reception center indicates that even if evacuation from the EPZ were successful -- a heroic assumption in light of the assorted planning deficiencies -- those who received and followed instructions to evacuate to the north would find no facilities available at their designated destination. According to FEMA, approximately 60,000 people would be left without facilities at which to register, be monitored and decontaminated if necessary. FEMA Self-Initiated Review at 19.

-- is missing altogether. Finally, offsite exercises and drills -- the most effective means of assuring preparedness -- have not been held in years.

B. THE CURRENT STATUS OF PLANNING AND PREPAREDNESS

The specific functional deficiencies in the first four areas enumerated above, as well as the functional areas in which work must be done before any determination can be made if adequate plans can be developed, encompass the entire set of tasks required for adequate planning and preparedness:

1. Identification/Estimation of populations;
2. Identification/Estimation of resources;
3. Develop plans for emergency actions to be taken for each population with potentially available resources;
4. Obtain commitments for required resources;
5. Provide education/information to public;
6. Conduct exercises/drills.

At present, it appears that the school/daycare population has been identified but that the special needs and transport dependent populations have not.^{40/} Preliminary estimates of the resources potentially available to evacuate these populations have now been obtained, but neither plan development nor obtaining commitments of resource availability can proceed in the absence of reliable ETEs.^{41/}

^{40/} Executive Summary of the Report on Emergency Preparedness For an Accident at Pilgrim Power Station (October 15, 1987) (hereinafter "Barry Report Update"), p. 2.

^{41/} Id. at 2.

While BECo. has recently -- August 18, 1987 -- delivered an ETE study to the Commonwealth's public safety officials,^{42/} the document is still being reviewed by those officials and preliminary analysis has uncovered shortcomings that will necessitate further work. It is, thus, unlikely that final ETEs will be available within the immediate future for use in developing specific plans.^{43/} This shortcoming is critical. A consequence of the unavailability of reliable ETEs is that emergency planning is effectively on hold. Even when the task of identifying/estimating populations and resources is completed, radiological emergency planning cannot in any real sense proceed without reliable ETEs and a traffic management plan. As FEMA and the NRC well recognize, a realistic set of ETEs is an essential element of a workable emergency plan. See Cincinnati Gas & Electric Company (Wm. H. Zimmer Nuclear Power Station, Unit No. 1), ALAB-727, 17 NRC 760, 770-71 (1983).

With respect to the beach population, preliminary population estimates and sheltering data have been provided to the Commonwealth's public safety officials but, at least in the case of the sheltering survey, these materials have been found

^{42/} KLD Associates, Pilgrim Station Evacuation Time Estimates and Traffic Management Plan Update (Final Draft for Review) August 18, 1987.

^{43/} Barry Report Update, p. 2.

to be inadequate for planning purposes.^{44/}

Again, plan development and resource availability commitments, much less public education/information efforts and exercises/drills, cannot proceed usefully without reliable final ETEs and sheltering data.^{45/}

No replacement site for a northern reception center has been found^{46/} and no determination has yet been made whether an emergency plan incorporating only two reception centers would provide an adequate assurance of protection.^{47/}

44/ Barry Report Update, p. 2; Letter with enclosures from Robert J. Boulay, Director, Massachusetts Civil Defense Agency, dated September 18, 1987, to Ralph C. Bird, Executive Vice President-Nuclear, Boston Edison Company (attached hereto as Attachment 7)

45/ Barry Report Update, p. 2; See also FEMA Self-Initiated Review at 26-27:

Before FEMA and the RAC can make a determination on this (whether protective actions for the beach population are or readily can be made adequate) it must receive the following information:

1) an updated geographical description of the beaches and their capacity; 2) a detailed analysis of the beach population, including the number of permanent and temporary residents and the number of day visitors, together with their geographical dispersion; 3) an updated estimate of the length of time it would take to evacuate the beach population; and 4) a list of suitable buildings available for sheltering the beach population at each beach, including the capacities of these buildings and their distances from the beaches. If these buildings are not open to the public, the plans must clearly state how they will be made accessible and letters of agreement must be obtained as appropriate.

46/ Id.

47/ 9/24 NRC/BECO. Readiness Meeting, p. 52. But see FEMA Self-Initiated Review at 19 (The use of only two reception centers "is not likely to be logistically feasible.")

Finally, in the absence of new plans, public information/education efforts and exercises/drills cannot, by definition, occur. There are no plans to inform the public of exercises, much less to exercise. Although the provisions of 10 C.F.R. Part 50, Appendix E, Section IV.F. require that a full participation biennial emergency preparedness exercise for Pilgrim be held this year, the NRC is presently considering a request from BECo. for a one-time exemption from that requirement to allow the exercise to be postponed to the second quarter of 1988.^{48/}

IV. CONCLUSION

In light of all of the foregoing deficiencies of the current state of emergency planning and preparedness, as well as the substantial questions raised herein concerning the managerial ability of the licensee, BECo., and the safety of the Pilgrim reactor, the Governor and Attorney General submit that the NRC must take action pursuant to 10 C.F.R. 52.202 to insure that BECo. does not take any action that could increase either the risk or the consequences of an accident at Pilgrim.

Since that Pilgrim is a GE Mark I design reactor, and the EPZ population at this plant is among the highest in the country, it is evident that the deficiencies in emergency planning and preparedness are significant for Pilgrim. These

^{48/} Letter with enclosures dated September 18, 1987, from Mr. Ralph G. Bird, Senior Vice President-Nuclear, Boston Edison Company, to NRC (attached hereto as Attachment 8).

deficiencies are so substantial and their potential ramifications are so significant, that it is impossible to conclude that any interim compensating actions have or can be taken. The NRC's regulations leave it no course other than issuing an order modifying BECo's license to extend the current shut down pending the outcome of a full hearing on the significant outstanding safety issue and the development and certification by the Governor of adequate emergency plans.^{49/}

Respectively submitted,

James M. Shannon
Attorney General
Commonwealth of Massachusetts

Michael S. Dukakis
Governor
Commonwealth of Massachusetts

Dated: October 15, 1987

49/ Compare 10 C.F.R. §50.54(s)(2)(ii):

... In determining whether a shutdown or other enforcement action is appropriate, the Commission shall take into account, among other factors, whether the licensee can demonstrate to the Commission's satisfaction that the deficiencies in the plan are not significant for the plant in question, or that adequate interim compensating actions have been or will be taken promptly, or that there are other compelling reasons for continued operation.

APPENDIX I: BECO. SALP HISTORY TABULATION

<u>Inspec. Period</u>	<u>Plant Oper.</u>	<u>Radiol. Control</u>	<u>Maint.</u>	<u>Surveil.</u>	<u>Fire Prot.</u>	<u>Emergen. Prepared</u>
01/01/80 12/31/80	2	3	2	2	2	2
09/01/80 08/31/81	3	2	3	2	2	1
09/01/81 06/30/82	3	2	2	2	3	1
07/01/82 06/30/83	2	2	2	1	1	1
07/01/83 09/30/84	2	3	1	1	2	3
10/01/84 10/31/85	3	3	2	2	-	3
11/01/85 01/31/87	2	3	2	3	3	2

<u>Inspec. Period</u>	<u>Secur. Safegds</u>	<u>Out.Mgt. Mod.Act</u>	<u>Licen. Activ.</u>	<u>Eng/Corp Tech.Sup</u>	<u>Train Qual.Ef</u>	<u>Quality Assuran</u>
01/01/80 12/31/80	2	3	-	-	-	3
09/01/80 08/31/81	2	2	-	-	-	3
09/01/81 06/30/82	2	2	2	-	-	-
07/01/82 06/30/83	2	-	1	-	-	-
07/01/83 09/30/84	2	1	1	-	-	-
10/01/84 10/31/85	2	1	1	-	-	-
11/01/85 01/31/87	3	1	2	1	2	3

APPENDIX II: BECO. VIOLATIONS TABULATIONS

SEVERITY LEVEL III VIOLATIONS: 9/1/81-1/31/87

Functional Area	1981	1982	1983	1984	1985	1986	1987
Plant Operations	3						
Radiological Controls	1			2		1	
Maintenance							
Surveillance							
Fire Protection							
Emergency Preparedness		1					
Security/Safeguards	1	1	1		1		?
Outage Mgt ...							
Licensing Activities							
Training ... Efficiency							
Assurance of Quality							
Engineer-/Corp. Support							

BECO. VIOLATIONS BY SEVERITY LEVEL: 9/1/81-1/31/87

Severity Level	81/82	82/83	83/84	84/85	85/87
I					
II					
III	7	1	1	2	1
IV	9	9	18	17	21
V	20	20	6	5	6
VI	2				
Deviations	2	3	1	3	1
Total Violations	40	33	26	27	29

UNITED STATES OF AMERICA
NUCLEAR REGULATORY COMMISSION

BEFORE THE COMMISSION

In the matter of

BOSTON EDISON COMPANY

(Pilgrim Nuclear Power Station, Unit 1)

Docket No. 50-293

AFFIDAVIT OF STEVEN C. SHOLLY

Steven C. Sholly, being on oath, deposes and says as follows:

1. I am an Associate Consultant with MHB Technical Associates, 1723 Hamilton Avenue, Suite K, San Jose, California, 95125. A statement of my professional qualifications is attached hereto and marked Attachment A. In brief, I have more than six years experience in the review, analysis, interpretation, and application of probabilistic risk assessment to the analysis of safety issues related to commercial nuclear power plants, including issues related to radiological emergency planning. I have served as a member of the peer review group for the NRC publication NUREG-1050 (1984) (Probabilistic Risk Assessment (PRA) Reference Document, September 1984), and have more recently served as a member of the Containment Performance Design Objective Workshop, the Panel on ACRS Effectiveness (1985), and the Severe Accident Policy Implementation External Events Workshop (1987). I have previously testified as an expert witness on probabilistic risk assessment and emergency planning matters in NRC proceedings on the Catawba Units 1 and 2, Indian Point Units 2 and 3, and Shoreham Unit 1 nuclear plants, and also in the Public Inquiry regarding the proposed Sizewell-B nuclear plant in the United Kingdom. In addition, I have co-authored two major reviews of source term

and risk estimate issues published in NRC reports NUREG-0956 and NUREG-1150. I have also performed reviews of various technical aspects of the Shoreham, Limerick, Indian Point, Sizewell, Zion, Seabrook, Millstone-3, and Oconee-3 probabilistic risk assessments and the Vermont Yankee Containment Safety Study.

2. MHB Technical Associates ("MHB") has been requested by the Nuclear Safety Division, Department of the Attorney General, The Commonwealth of Massachusetts, to evaluate the increase in risk resulting from a startup program for return to power from the current refueling and modifications outage for the Pilgrim Nuclear Power Station, Unit 1 (PNPS-1).
3. In its current configuration (refueled) and considering the duration of the current shutdown, Pilgrim currently poses very little risk to the public health and safety. This is due to the multiplicity of systems theoretically available to inject water into the reactor vessel and due to the low decay heat level present in the fuel. In the event of a core heatup transient with the plant in its current configuration, considerable time would elapse between initiation of coolant loss and the onset of fuel damage, time during which measures could be taken to initiate coolant makeup and/or other recovery and mitigative actions. Moreover, in theory a longer time period is available within which to implement offsite protective actions due to the slower accident progression time compared with accidents at higher power levels.
4. Boston Edison Company (BECO), the licensee for Pilgrim, currently envisions restart power ascension program with a minimal number of hold points. In brief, BECO proposes to institute holds on restart (pending approval from NRC in accord with Confirmatory Action Letter No. 86-10), recovery from reactor mode switch testing prior to conducting a test for shutdown from outside the control room, and prior to movement of the scram set point above 95% power. [See Boston Edison Company, Pilgrim Nuclear Power Station Restart Plan, pages IV-29 to IV-31.] The details of the power ascension program in Attachment 13 of the Pilgrim Nuclear Power Station Restart Plan have not yet been provided.

5. My current understanding of the BECO power ascension program is that the program would result in a relatively rapid ascension from the current shutdown condition to full-power operation. In so doing, the risk to the public health and safety posed by operations at the Pilgrim plant will be increased markedly.

6. The Commission has concluded generally that the risks from 5% power operation are negligible. [See, for example, SECY-84-155, 12 April 1984, and attachments; and letter dated 15 June 1984 from Nunzio J. Palladino to Hon. Edward J. Markey, and attachments.] The evaluations upon which the Commission has drawn these conclusions, however, were for plants with very little operating history and no spent fuel pool inventory. Clearly, Pilgrim is different in this regard, with a substantial long-half-life fission product inventory present in both the refueled reactor core and the spent fuel pool. Moreover, these evaluations did not consider the unique risks posed by accidents resulting from externally-initiated events (specifically, in this case, seismic events). In my opinion, the presence of more than 1100 spent fuel assemblies, prior operation of two-thirds of the core at equivalent full power for most of an operating cycle, and the matter of external events render the circumstances at Pilgrim sufficiently different from those previously evaluated for 5% power operation that the previous evaluations understate, perhaps significantly, the risk posed by operation of Pilgrim at 5% of full power. This conclusion is further supported by the likelihood that the primary containment will not be inerted until operation above 5% power is commenced. In my opinion, virtually any severe accident at 5% power with the containment de-inerted will result in early containment failure (due to hydrogen burn or hydrogen detonation in the primary containment, and/or other causes).

7. As power level increases, risk to the public increases. This is due to several factors, including a marked increase in volatile fission product inventory and a marked increase in decay heat level, which results in accident progression times which are much shorter than at low power levels. This reduces the amount of time available for implementation of recovery and/or mitigation

actions and reduces the amount of time available to implement offsite protective measures.

8. A full-scope probabilistic risk assessment for the Pilgrim plant has been in progress for several years. It is my understanding that this study is nearly completed. It is my expectation that this study will identify seismic initiating events as a significant contributor to core melt frequency (i.e., contributing 10% or more to core melt frequency from all causes). This expectation is based on my familiarity with seismic risk assessments performed on similar designs and performed on other plants in the general region of Pilgrim (e.g., Shoreham, Seabrook Units 1 and 2, Millstone Unit 3, and Limerick Units 1 and 2). Seismically-initiated accident sequences are accompanied by potentially severe impacts on offsite emergency response even when there are fully-approved and operational emergency plans. In the case of Pilgrim, the current status of emergency planning is such that there is not adequate assurance that protective actions can and will be taken in the event of an accident. Given the more severe conditions of a seismically-initiated accident scenario, this conclusion is all the more applicable.
9. A study of risk at 25% power for the Shoreham nuclear plant, which possesses a nuclear steam supply system which is grossly similar to Pilgrim, indicates that the core melt frequency for operations at up to 25% of full power may not differ dramatically from the core melt frequency at full power. The 25% power PRA estimates a core melt frequency of 2.8×10^{-5} per reactor-year. [See, E.T. Burns, S. Mays, and T. Mairs, Probabilistic Risk Assessment of the Shoreham Nuclear Power Station: Initial Power Operation Limited to 25% of Full Power, Delian Corporation, prepared for Long Island Lighting Company, April 1987, page 4-12.] The full power PRA analyses for Shoreham estimated a core melt frequency of about 6.5×10^{-5} per reactor-year. [See, Science Applications, Inc., Final Report: Probabilistic Risk Assessment, Shoreham Nuclear Power Station, prepared for Long Island Lighting Company, 24 June 1983, page 4; and V. Joksimovich, et al., Major Common-Cause Initiating Events Study: Shoreham Nuclear Power Station, NUS Corporation, NUS Report No. NUS-4617, prepared for Long Island Lighting Company, February 1985, page 1-8]

This represents less than a factor of three difference in the likelihood of a core melt accident at 25% power versus full power. Although this assessment is for Shoreham and not for Pilgrim, it suggests that the likelihood of an accident is not markedly different for 25% power versus 100% power.

10. Further, a limited-scope PRA of Shoreham at 5% power was prepared for LILCO. This study, which did not include external events, concluded that the core melt frequency for 5% power operation was about 4.9×10^{-6} per reactor-year. [See, Delian Corporation and Science Applications, Inc., *Probabilistic Risk Assessment, Shoreham Nuclear Power Station, Low Power Operation Up to 5% of Full Power*, prepared for Long Island Lighting Company, draft, May 1984, page 78.] This indicates that core melt frequency at 5% power is significantly reduced from 25% power or full power, by a factor of roughly 20, but not nearly as significantly reduced as previously predicted by the NRC staff, which predicted a reduction factor of 1,000 or more. ^{1/} Moreover, the 5% power reduction factor of 20 is an underestimate since the 5% power estimates do not include external events.
11. The 5%, 25%, and 100% power PRA studies for Shoreham indicate, in my opinion, that the core power level for Pilgrim will have at best a moderate impact on the likelihood of an accident. Considering the uncertainties involved, the likelihood of an accident may be nearly indistinguishable at the various power levels indicated above. Moreover, the Shoreham results are lower than the core melt frequency estimates for many other plants. A Brookhaven National Laboratory review of the Shoreham PRA for internal events only estimated a core melt frequency of 1×10^{-4} per reactor-year. An average value for full-scope PRAs completed to date is of the order of 3×10^{-4} per reactor-year.

^{1/} The NRC staff, in SECY-84-156, predicted core melt frequency reduction factors for various classes of BWR accidents ranging from 1,000 to 100,000. [See, SECY-84-156, Enclosure 1, "Staff Review Process for 5 Percent Power Operation", page 2.] Thus, in the aggregate, the NRC staff would have expected a core melt frequency reduction of at least 1,000, compared with the Shoreham value of 20. The results for Shoreham indicate a reduction factor approximately 50 times less than the NRC staff expected based on engineering judgment.

12. These results are especially significant for a plant with a containment design similar to Pilgrim. Pilgrim employs a steel Mark I pressure suppression containment. Such containments have been estimated in a variety of studies sponsored by IDCOR, NRC, and utilities to have an early containment failure probability -- given a severe accident -- in a range from 10-90%. This means that there is a significant chance that, given a severe accident, the accident will be accompanied by a large early release of radioactivity to the environment.

13. The Pilgrim plant, like all Mark I containment design plants, also employs a secondary containment, usually referred to as a reactor building. This structure is not designed to withstand the high internal pressures which would accompany a severe accident, and is unlikely to survive in a leak-tight condition following primary containment failure. High pressure in the secondary containment due to a severe accident would be produced by a combination of blowdown due to primary containment failure, primary containment leakage, primary containment venting, and burning of combustible gases. Indeed, Mark I plants are designed with both internal and external "blow-out panels" which are designed to relieve pressure. In the case of Pilgrim, there are blow-out panels at the refueling deck elevation which relieve pressure directly to the environment. In my opinion, there is little basis for assuming that releases from the primary containment will be significantly mitigated by the presence of the secondary containment.

13. Based on the above considerations, it is my opinion that Pilgrim Unit 1 should not be restarted until the offsite emergency response plans are upgraded and evaluated to adequately protect the public health and safety. Further, it is my recommendation that BECO be required to promptly submit the Pilgrim probabilistic risk assessment study to the NRC for public review and evaluation prior to restart. The review of such a study should indicate whether there

remain significant operational risks which must be ameliorated in order to provide adequate protection to the public health and safety.

Steven C. Sholly
Steven C. Sholly
Associate Consultant

GENERAL ACKNOWLEDGMENT

State of California
County of Santa Clara } SS.

On this the 14th day of October, 1987, before me,

Myrna L. Barry
the undersigned Notary Public, personally appeared

Steven C. Sholly

personally known to me
 proved to me on the basis of satisfactory evidence
to be the person(s) whose name(s) LS subscribed to the
within instrument, and acknowledged that he executed it.
WITNESS my hand and official seal.



Myrna L. Barry
Notary's Signature

ATTACHMENT A

PROFESSIONAL QUALIFICATIONS OF STEVEN C. SHOLLY

STEVEN C. SHOLLY
MHB Technical Associates
1723 Hamilton Avenue
Suite K
San Jose, California 95125
(408) 266-2716

EXPERIENCE:

September 1985 - PRESENT

Associate - MHB Technical Associates, San Jose, California

Associate in energy consulting firm that specializes in technical and economic assessments of energy production facilities, especially nuclear, for local, state, and federal governments and private organizations. MHB is extensively involved in regulatory proceedings and the preparation of studies and reports. Conduct research, write reports, participate in discovery process in regulatory proceedings, develop testimony and other documents for regulatory proceedings, and respond to client inquiries. Clients have included: State of California, State of New York, State of Illinois.

February 1981 - September 1985

Technical Research Associate and Risk Analyst - Union of Concerned Scientists, Washington, D.C.

Research associate and risk analyst for public interest group based in Cambridge, Massachusetts, that specializes in examining the impact of advanced technologies on society, principally in the areas of arms control and energy. Technical work focused on nuclear power plant safety, with emphasis on probabilistic risk assessment, radiological emergency planning and preparedness, and generic safety issues. Conducted research, prepared reports and studies, participated in administrative proceedings before the U.S. Nuclear Regulatory Commission, developed testimony, analyzed NRC rule-making proposals and draft reports and prepared comments thereon, and responded to inquiries from sponsors, the general public, and the media. Participated as a member of the Panel on ACRS Effectiveness (1985), the Panel on Regulatory Uses of Probabilistic Risk Assessment (Peer Review of NUREG-1050; 1984), Invited Observer to NRC Peer Review meetings on the source term reassessment (BMI-2104; 1983-1984), and the Independent Advisory Committee on Nuclear Risk for the Nuclear Risk Task Force of the National Association of Insurance Commissioners (1984).

January 1980 - January 1981

Project Director and Research Coordinator - Three Mile Island Public Interest Resource Center, Harrisburg, Pennsylvania

Provided administrative direction and coordinated research projects for a public interest group based in Harrisburg, Pennsylvania, centered around issues related to the Three Mile Island Nuclear Power Plant. Prepared fundraising proposals, tracked progress of U.S. Nuclear Regulatory Commission, U.S. Department of Energy, and General Public Utilities activities concerning cleanup of Three Mile Island Unit 2 and preparation for restart of Three Mile Island Unit 1, and monitored developments related to emergency planning, the financial health of General Public Utilities, and NRC rulemaking actions related to Three Mile Island.

July 1978 - January 1980

Chief Biological Process Operator - Wastewater Treatment Plant, Derry Township Municipal Authority, Hershey, Pennsylvania

Chief Biological Process Operator at a 2.5 million gallon per day tertiary, activated sludge, wastewater treatment plant. Responsible for biological process monitoring and control, including analysis of physical, chemical, and biological test results, process fluid and mass flow management, micro-biological analysis of activated sludge, and maintenance of detailed process logs for input into state and federal reports on treatment process and effluent quality. Received certification from the Commonwealth of Pennsylvania as a wastewater treatment plant operator. Member of Water Pollution Control Association of Pennsylvania, Central Section, 1980.

July 1977 - July 1978

Wastewater Treatment Plant Operator - Borough of Lemoyne, Lemoyne, Pennsylvania

Wastewater treatment plant operator at 2.0 million gallon per day secondary, activated sludge, wastewater treatment plant. Performed tasks as assigned by supervisors, including simple physical and chemical tests on wastewater streams, maintenance and operation of plant equipment, and maintenance of the collection system.

September 1976 - June 1977

Science Teacher - West Shore School District, Camp Hill, Pennsylvania

Taught Earth and Space Science at ninth grade level. Developed and implemented new course materials on plate tectonics, environmental geology, and space science. Served as Assistant Coach of the district gymnastics team.

September 1975 - June 1976

Science Teacher - Carlisle Area School District, Carlisle, Pennsylvania

Taught Earth and Space Science and Environmental Science at ninth grade level. Developed and implemented new course materials on plate tectonics, environmental geology, noise pollution, water pollution, and energy. Served as Advisor to the Science Projects Club.

EDUCATION:

B.S., Education, majors in Earth and Space Science and General Science, minor in Environmental Education, Shippensburg State College, Shippensburg, Pennsylvania, 1973.

Graduate coursework in Land Use Planning, Shippensburg State College, Shippensburg, Pennsylvania, 1977-1978.

PUBLICATIONS:

1. "Determining Mercalli Intensities from Newspaper Reports," Journal of Geological Education, Vol. 25, 1977.
2. A Critique of: An Independent Assessment of Evacuation Times for Three Mile Island Nuclear Power Plant, Three Mile Island Public Interest Resource Center, Harrisburg, Pennsylvania, January 1981.
3. A Brief Review and Critique of the Rockland County Radiological Emergency Preparedness Plan, Union of Concerned Scientists, prepared for Rockland County Emergency Planning Personnel and the Chairman of the County Legislature, Washington, D.C., August 17, 1981.
4. The Necessity for a Prompt Public Alerting Capability in the Plume Exposure Pathway EPZ at Nuclear Power Plant Sites, Union of Concerned Scientists, Critical Mass Energy Project, Nuclear Information and Resource Service, Environmental Action, and New York Public Interest Research Group, Washington, D.C., August 27, 1981. *
5. "Union of Concerned Scientists, Inc., Comments on Notice of Proposed Rulemaking, Amendment to 10 CFR 50, Appendix E, Section IV.D.3," Union of Concerned Scientists, Washington, D.C., October 21, 1981. *
6. "The Evolution of Emergency Planning Rules," in The Indian Point Book: A Briefing on the Safety Investigation of the Indian Point Nuclear Power Plants, Anne Witte, editor, Union of Concerned Scientists (Washington, D.C.) and New York Public Interest Research Group (New York, NY), 1982.
7. "Union of Concerned Scientists Comments, Proposed Rule, 10 CFR Part 50, Emergency Planning and Preparedness: Exercises, Clarification of Regulations, 46 F.R. 61134," Union of Concerned Scientists, Washington, D.C., January 15, 1982. *

8. Testimony of Robert D. Pollard and Steven C. Sholly before the Subcommittee on Energy and the Environment, Committee on Interior and Insular Affairs, U.S. House of Representatives, Middletown, Pennsylvania, March 29, 1982, available from the Union of Concerned Scientists.
9. "Union of Concerned Scientists Detailed Comments on Petition for Rulemaking by Citizen's Task Force, Emergency Planning, 10 CFR Parts 50 and 70, Docket No. PRM-50-31, 47 F.R. 12639," Union of Concerned Scientists, Washington, D.C., May 24, 1982.
10. Supplements to the Testimony of Elynn R. Weiss, Esq., General Counsel, Union of Concerned Scientists, before the Subcommittee on Energy Conservation and Power, Committee on Energy and Commerce, U.S. House of Representatives, Union of Concerned Scientists, Washington, D.C., August 16, 1982.
11. Testimony of Steven C. Sholly, Union of Concerned Scientists, Washington, D.C., on behalf of the New York Public Interest Research Group, Inc., before the Special Committee on Nuclear Power Safety of the Assembly of the State of New York, hearings on Legislative Oversight of the Emergency Radiologic Preparedness Act, Chapter 708, Laws of 1981, September 2, 1982.
12. "Comments on 'Draft Supplement to Final Environmental Statement Related to Construction and Operation of Clinch River Breeder Reactor Plant'," Docket No. 50-537, Union of Concerned Scientists, Washington, D.C., September 13, 1982. *
13. "Union of Concerned Scientists Comments on 'Report to the County Commissioners', by the Advisory Committee on Radiological Emergency Plan for Columbia County, Pennsylvania," Union of Concerned Scientists, Washington, D.C., September 15, 1982.
14. "Radiological Emergency Planning for Nuclear Reactor Accidents," presented to Kernenergie Ontmanteld Congress, Rotterdam, The Netherlands, Union of Concerned Scientists, Washington, D.C., October 8, 1982.
15. "Nuclear Reactor Accident Consequences: Implications for Radiological Emergency Planning," presented to the Citizen's Advisory Committee to Review Rockland County's Own Nuclear Evacuation and Preparedness Plan and General Disaster Preparedness Plan, Union of Concerned Scientists, Washington, D.C., November 19, 1982.
16. Testimony of Steven C. Sholly before the Subcommittee on Oversight and Investigations, Committee on Interior and Insular Affairs, U.S. House of Representatives, Washington, D.C., Union of Concerned Scientists, December 13, 1982.
17. Testimony of Gordon R. Thompson and Steven C. Sholly on Commission Question Two, Contentions 2.1(a) and 2.1(d), Union of Concerned Scientists and New York Public Interest Research Group, before the U.S. Nuclear Regulatory Commission Atomic Safety and Licensing Board, in the Matter of Consolidated Edison Company of New York (Indian Point Unit 2) and the Power Authority of the State of New York (Indian Point Unit 3), Docket Nos. 50-247-SP and 50-286-SP, December 28, 1982. *

18. Testimony of Steven C. Sholly on the Consequences of Accidents at Indian Point (Commission Question One and Board Question 1.1, Union of Concerned Scientists and New York Public Interest Research Group, before the U.S. Nuclear Regulatory Commission Atomic Safety and Licensing Board, in the Matter of Consolidated Edison Company of New York (Indian Point Unit 2) and the Power Authority of the State of New York (Indian Point Unit 3), Docket Nos. 50-247-SP and 50-286-SP, February 7, 1983, as corrected February 16, 1983. *
19. Testimony of Steven C. Sholly on Commission Question Five, Union of Concerned Scientists and New York Public Interest Research Group, before the U.S. Nuclear Regulatory Commission Atomic Safety and Licensing Board, in the Matter of Consolidated Edison Company of New York (Indian Point Unit 2) and the Power Authority of the State of New York (Indian Point Unit 3), Docket Nos. 50-247-SP and 50-286-SP, March 22, 1983. *
20. "Nuclear Reactor Accidents and Accident Consequences: Planning for the Worst," Union of Concerned Scientists, Washington, D.C., presented at Critical Mass '83, March 26, 1983.
21. Testimony of Steven C. Sholly on Emergency Planning and Preparedness at Commercial Nuclear Power Plants, Union of Concerned Scientists, Washington, D.C., before the Subcommittee on Nuclear Regulation, Committee on Environment and Public Works, U.S. Senate, April 15, 1983, (with "Union of Concerned Scientists' Response to Questions for the Record from Senator Alan K. Simpson," Steven C. Sholly and Michael E. Faden).
22. "PRA: What Can it Really Tell Us About Public Risk from Nuclear Accidents?," Union of Concerned Scientists, Washington, D.C., presentation to the 14th Annual Meeting, Seacoast Anti-Pollution League, May 4, 1983.
23. "Probabilistic Risk Assessment: The Impact of Uncertainties on Radiological Emergency Planning and Preparedness Considerations," Union of Concerned Scientists, Washington, D.C., June 28, 1983.
24. "Response to GAO Questions on NRC's Use of PRA," Union of Concerned Scientists, Washington, D.C., October 6, 1983, attachment to letter dated October 6, 1983, from Steven C. Sholly to John E. Bagnulo (GAO, Washington, D.C.).
25. The Impact of "External Events" on Radiological Emergency Response Planning Considerations, Union of Concerned Scientists, Washington, D.C., December 22, 1983, attachment to letter dated December 22, 1983, from Steven C. Sholly to NRC Commissioner James K. Asselstine.
26. Sizewell 'B' Public Inquiry, Proof of Evidence on: Safety and Waste Management Implications of the Sizewell PWR, Gordon Thompson, with supporting evidence by Steven Sholly, on behalf of the Town and Country Planning Association, February 1984, including Annex G, "A review of Probabilistic Risk Analysis and its Application to the Sizewell PWR," Steven Sholly and Gordon Thompson, (August 11, 1983), and Annex O, "Emergency Planning in the UK and the US: A Comparison," Steven Sholly and Gordon Thompson (October 24, 1983).

27. Testimony of Steven C. Sholly on Emergency Planning Contention Number Eleven, Union of Concerned Scientists, Washington, D.C., on behalf of the Palmetto Alliance and the Carolina Environmental Study Group, before the U.S. Nuclear Regulatory Commission Atomic Safety and Licensing Board, in the Matter of Duke Power Company, et. al. (Catawba Nuclear Station, Units 1 and 2), Docket Nos. 50-413 and 50-414, April 16, 1984. *
28. "Risk Indicators Relevant to Assessing Nuclear Accident Liability Premiums," in Preliminary Report to the Independent Advisory Committee to the NAIC Nuclear Risk Task Force, December 11, 1984, Steven C. Sholly, Union of Concerned Scientists, Washington, D.C.
29. "Union of Concerned Scientists' and Nuclear Information and Resource Service's Joint Comments on NRC's Proposal to Bar from Licensing Proceedings the Consideration of Earthquake Effects on Emergency Planning," Union of Concerned Scientists and Nuclear Information and Resource Service, Washington, D.C., Diane Curran and Ellyn R. Weiss (with input from Steven C. Sholly), February 28, 1985. *
30. "Severe Accident Source Terms: A Presentation to the Commissioners on the Status of a Review of the NRC's Source Term Reassessment Study by the Union of Concerned Scientists," Union of Concerned Scientists, Washington, D.C., April 3, 1985. *
31. "Severe Accident Source Terms for Light Water Nuclear Power Plants: A Presentation to the Illinois Department of Nuclear Safety on the Status of a Review of the NRC's Source Term Reassessment Study (STRS) by the Union of Concerned Scientists," Union of Concerned Scientists, Washington, D.C., May 13, 1985.
32. The Source Term Debate: A Review of the Current Basis for Predicting Severe Accident Source Terms with Special Emphasis on the NRC Source Term Reassessment Program (NUREG-0956), Union of Concerned Scientists, Cambridge, Massachusetts, Steven C. Sholly and Gordon Thompson, January 1986.
33. Direct Testimony of Dale G. Bridenbaugh, Gregory C. Minor, Lynn K. Price, and Steven C. Sholly on behalf of State of Connecticut Department of Public Utility Control, Prosecutorial Division and Division of Consumer Counsel, regarding the prudence of expenditures on Millstone Unit III, February 18, 1986.
34. Implications of the Chernobyl-4 Accident for Nuclear Emergency Planning for the State of New York, prepared for the State of New York Consumer Protection Board, by MHB Technical Associates, June 1986.
35. Review of Vermont Yankee Containment Safety Study and Analysis of Containment Venting Issues for the Vermont Yankee Nuclear Power Plant, prepared for New England Coalition on Nuclear Pollution, Inc., December 16, 1986.

36. Affidavit of Steven C. Sholly before the Atomic Safety and Licensing Board, in the matter of Public Service Company of New Hampshire, et al., regarding Seabrook Station Units 1 and 2 Off-site Emergency Planning Issues, Docket Nos. 50-443-OL & 50-444-OL, January 23, 1987.
37. Direct Testimony of Richard B. Hubbard and Steven C. Sholly on behalf of California Public Utilities Commission, regarding Diablo Canyon Rate Case, PG&E's Failure to Establish Its Committed Design QA Program, Application Nos. 84-06-014 and 85-08-025, Exhibit No. 10,935, March, 1987.
38. Testimony of Gregory C. Minor, Steven C. Sholly et. al. on behalf of Suffolk County, regarding LILCO's Reception Centers (Planning Basis), before the Atomic Safety and Licensing Board, in the matter of Long Island Lighting Company, Shoreham Nuclear Power Station Unit 1, Docket No. 50-322-OL-3, April 13, 1987.
39. Rebuttal Testimony of Gregory C. Minor and Steven C. Sholly on behalf of Suffolk County regarding LILCO's Reception Centers (Addressing Testimony of Lewis G. Hulman), Docket No. 50-322-OL-3, May 27, 1987.
40. Review of Selected Aspects of NUREG-1150, "Reactor Risk Reference Document," prepared for the Illinois Department of Nuclear Safety by MHB Technical Associates, September 1987.

* Available from the U.S. Nuclear Regulatory Commission, Public Document Room, Lobby, 1717 H Street, N.W., Washington, D.C.



CONNECTICUT YANKEE

On April 16, the plant shutdown because of problems with turbine control valve #4. After chemistry holds and a load runback, the plant reached full power (94%) on April 21st. The Institute for Nuclear Power Operations (INPO) will conduct its annual critique of plant operations beginning on June 8th.

MAINE YANKEE

Maine Yankee shutdown for refueling is proceeding generally according to schedule with startup expected in early June. Very small cracks found in the disks of both low pressure turbine rotors have necessitated the replacement of one and the repair of the other.

YANKEE

Yankee began its 18th refueling on May 2nd. The 15st cycle of the plant produced more than 2 million megawatt-hours over a 17 month period with a capacity factor of 93 percent.

PILGRIM

Pilgrim remained off-line during the month.

VERMONT YANKEE

On April 4, Vermont Yankee came down in power and took the turbine off-line to repair a small steam leak in a main steam drain line. The plant came back on-line the same day and operated at full power for the remainder of the month.

MILLSTONE 1 & 2

Millstone Unit 1 operated routinely for the month of April. A scheduled refueling outage will begin in mid-June and last for approximately 10 weeks. Millstone Unit 2 operated routinely except for a trip on April 16 due to a generator exciter field circuit breaker opening on presumed bistable transformer fault indication. Instruments in place to monitor the suspect bistable. The unit returned to service after a 20 hour outage on April 18.

MILLSTONE 3

Millstone Unit 3 returned to service after a scheduled outage. After startup on April 11, the unit tripped on the next day while at 10 percent power level due to steam generator low level when turbine driven feed pump oscillated. Feedwater regulating control valve failed to open on demand due to a control air leak. The unit returned to service on April 14 after being out for 29 hours.





UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
801 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19403

AUG 27 1986

Docket No. 50-293

Boston Edison Company M/C Nuclear
ATTN: Mr. James M. Lydon
Chief Operating Officer
800 Boylston Street
Boston, Massachusetts 02199

Gentlemen:

Subject: Confirmatory Action Letter 86-10

This letter is to provide further guidance on the requirements we expect to be met prior to the restart of the Pilgrim plant. We acknowledge receipt of Boston Edison Company's (BECO) letter of June 16, 1986, in response to Confirmatory Action Letter (CAL) 86-10. Your actions with regard to the issues in CAL 86-10 appear to be thorough and technically sound. My staff has a few remaining questions, which have been discussed with your staff and which will be documented in Inspection Report 50-293/86-25.


In addition to the specific plant hardware issues involved with CAL 86-10, several other issues have been identified that require resolution prior to restart of the Pilgrim plant. Specific technical issues of concern include: overdue surveillances, malfunction of recirculation motor generator set field breakers, seismic qualification of emergency diesel generator differential relays, and completion of Appendix R modifications. Please be prepared to discuss these issues at our next management meeting at the plant on September 9, 1986. We would also like to hear at this meeting the scope and status of all your programs related to restart of Pilgrim. These include (a) the results of your six week action plan for improvements, (b) the role of BECO safety review committees, including the Program For Excellence Task Force, in assessing readiness for restart, and (c) the readiness of the plant and corporate staff to support plant startup, testing, and operations.

In light of the number and scope of the outstanding issues, I am not prepared to approve restart of the Pilgrim facility until you provide a written report that documents BECO's formal assessment of the readiness for restart operation. This assessment should include your detailed check list for assuring that all outstanding items have been satisfactorily resolved and that plant systems have been restored and prepared for operation. A formal restart program and schedule should also be submitted for NRC review and approval. This program should include hold points at appropriate stages such as criticality, completion of mode switch testing, and at specific milestones during ascension to full power. Authorization to proceed beyond each hold point will be contingent upon my approval and will be based on my staff's evaluation of the operational performance of the plant. We will have substantially augmented NRC inspection coverage during this restart period.

Please plan to submit your readiness assessment and restart program and schedule at least forty-five days before your planned startup from the current outage. My decision on restart will be based in part on our review of these documents.

Your cooperation is appreciated.

Sincerely,



Thomas E. Murley
Regional Administrator

cc:

L. Oxsen, Vice President, Nuclear Operations
A. E. Pedersen, Station Manager
Paul Levy, Chairman, Department of Public Utilities
Edward R. MacCormack, Senior Regulatory Affairs and Program Engineer
Chairman, Board of Selectmen
Plymouth Civil Defense Director
The Honorable E. J. Markey
J. D. Keyes
Senator Edward P. Kirby
The Honorable Peter V. Forman
Sharon Pollard
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
Commonwealth of Massachusetts (2)



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
801 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19108

APR 08 1987

Docket No. 50-293

Boston Edison Company M/C Nuclear
ATTN: Mr. Ralph Bird
Senior Vice President - Nuclear
800 Boylston Street
Boston, Massachusetts 02199

Gentlemen:

Subject: Systematic Assessment of Licensee Performance (SALP) Report
No. 50-293/86-99

The Region I SALP Board has reviewed and evaluated the performance of activities at the Pilgrim Nuclear Power Station for the period November 1, 1985 through January 31, 1987. The results are presented in the enclosed report. A meeting to discuss this assessment will be scheduled for a mutually acceptable date. The meeting will be held on or near the site so that appropriate senior corporate management and plant officials can discuss with us the strengths and weaknesses noted. It is our intent that this meeting be combined with the periodic management meeting to review improvement program status.

The SALP Board identified significant recurring program weaknesses in some functional areas. Improvements, such as in the area of emergency preparedness, were also noted. However, the SALP Board found the rate of such change was slow during most of the assessment period.

We recognize that the Boston Edison Company (BECO) has made significant staffing and hardware commitments to improve performance at the Pilgrim Station and we believe they are beginning to have a positive impact. As you are aware, the NRC is looking for progress in correcting the previously identified long term problems at the Pilgrim Station prior to plant restart, particularly in those functional areas with a Category 3 rating.

In preparation for the SALP meeting, please be prepared to discuss your evaluation of our assessment and the status of your performance improvement programs. Any comments you may have regarding our report may be discussed at the meeting. Additionally, you may provide written comments within 30 days after the meeting. Following our meeting and receipt of your written response, the enclosed report, your response, and a summary of our findings and planned actions will be placed in the NRC Public Document Room.

TABLE 4
ENFORCEMENT SUMMARY (11/01/85 - 01/31/87)
PILGRIM NUCLEAR POWER STATION

A. Number and Severity Level of Violations

Severity Level I	0
Severity Level II	0
Severity Level III	1
Severity Level IV	21
Severity Level V	6
Deviation	1
Total	29

B. Violations Vs. Functional Area

Functional Area	Severity Levels					Total	
	I	II	III	IV	V		
1. Plant Operations	-	-	-	-	1	1	
2. Radiological Controls	-	-	1	3	-	4	
3. Maintenance	-	-	-	1	-	1	
4. Surveillance	-	-	-	6	3	9	
5. Fire Protection	-	-	-	5	1	6	
6. Emergency Preparedness	-	-	-	-	-	0	
7. Security Safeguards	-	-	-	1	1	2	
8. Outage Management and Modification Activities	-	-	-	1	1	2	
9. Licensing Activities	-	-	-	-	-	0	
10. Training and Qualification Effectiveness	-	-	-	-	-	0	
11. Assurance of Quality	-	-	-	4	-	4	
12. Engineering and Corporate Technical Support	-	-	-	-	-	-	
Totals	0	0	1	21	6	1	29

TABLE 4 (Continued)

C. Summary

Inspection Report Number	Severity Level	Functional Area	Violation
85-32	V	Surveillance	Instrument channel tests were not being performed monthly for the reactor building vent and stack waste gas monitors.
85-32	V	Security Safeguards	Failure to perform a proper search of a package brought into the protected area.
86-01	V	Plant Operations	Post trip review 86-01 and 86-02 lacked required recorder charts. Inadequate control room log entries on disabled annunciators.
86-04	III	Radiological Controls	A waste shipment of solid metallic oxides on non-compacted trash lacked required strong packaging and quality control measures.
86-06	IV	Surveillance	Replacement squib charges were installed in the standby liquid control system from a batch that had not been tested during a manual initiation of the Standby Liquid Control System.
86-10	IV	Radiological Controls	Radiation surveys of packaged irradiated reactor components were not documented on appropriate radiation survey forms and maps.
86-10	IV	Assurance of Quality	Quality control measures were not taken in transferring radioactive waste shipments

TABLE 4 (Continued)

C. Summary

Inspection Report Number	Severity Level	Functional Area	Violation
86-14	IV	Assurance of Quality	Previously identified inadequacies involving surveillance testing of the high pressure coolant injection system were not corrected for six months.
86-14	V	Surveillance	Failure to properly control measuring and test equipment.
86-21	IV	Surveillance	Battery rated load discharge Test procedure was not updated to reflect system alterations and restorations.
86-25	IV	Assurance of Quality	Failure and Malfunction Report was not completed by engineering personnel after they identified deficient station fire barriers.
86-25	V	Surveillance	Surveillance tests were performed without independent verification of system response and system restoration.
86-25	Deviation	Fire Protection	Failure to comply with the commitment to conduct quarterly fire brigade drills for all fire brigade members.
86-34	IV	Security Safeguards	Improper package search and inadequate follow up.
86-36	IV	Fire Protection	Fire brigade members had not received the required training.
86-36	IV	Fire Protection	Fire watches failed to perform the required hourly patrol of the motor generator set room.

TABLE 4 (Continued)

C. Summary

Inspection Report Number	Severity Level	Functional Area	Violation
86-37	IV	Fire Protection	Inadequate fire brigade drill.
86-37	IV	Modifications	Safety-related modifications were not performed in accordance with applicable design requirements.
86-38	IV	Fire Protection	Adequate procedures and drawings had not been established for the station fire water system.
86-44	IV	Radiological Controls	Failure to implement a radiological control procedure for checking vehicles leaving the site.
87-01	IV	Surveillance	Failure to adhere to the procedure governing surveillance testing of the Post Accident Sampling System (PASS) system.
87-01	IV	Maintenance	Lack of procedure guidance on maintenance of the heat tracing control circuit relays for the PASS system.
87-03	IV	Fire Protection	Failure to take required action for inoperable fire protection equipment.
87-03	IV	Radiological Controls	Failure to control a master key to all locked high radiation areas.
87-03	IV	Assurance of Quality	Failure and Malfunction Report not completed after a safety-related bus transfer did not occur during a surveillance test.

TABLE 4 (Continued)

C. Summary

Inspection Report Number	Severity Level	Functional Area	Violation
87-04	IV	Surveillance	A surveillance test on Standby Gas Treatment System failed to meet the intent of the Tech Spec requirements.
87-04	IV	Surveillance	Failure to calibrate measuring and test equipment.
87-04	V	Modification	Performing post-modification test on the refuel bridge without approved procedure changes.
87-04	IV	Surveillance	Master test program procedures do not adequately address surveillance test and post modification test programs.



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
831 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

MAY 23 1986

RECEIVED

MAY 30 1986

E. P. D.

Docket No. 50-293

Boston Edison Company M/C Nuclear
ATTN: Mr. William D. Harrington
Senior Vice President, Nuclear
800 Boylston Street
Boston, Massachusetts 02199

Gentlemen:

Subject: Systematic Assessment of Licensee Performance (SALP)
Report No. 50-293/85-99

This letter refers to the Systematic Assessment of Licensee Performance (SALP) of the Pilgrim Nuclear Power Station for the period of October 1, 1984 through October 31, 1985, initially forwarded to you by our February 18, 1986 letter (Enclosure 1). This SALP evaluation was discussed with you and your staff at a meeting held in Plymouth, Massachusetts on March 5, 1986 (see Enclosure 2 for attendees). We have reviewed your March 26, 1986 written comments (Enclosure 3) and herewith transmit the final report (Enclosure 4).

Overall, your performance in the operation of the facility was found acceptable although some areas were only minimally acceptable.

As projected in our letter of February 18, 1986, a special in-depth team inspection was conducted from February 18 to March 7, 1986 (Inspection Report No. 50-293/86-06) to determine the underlying reasons for the poor performance discussed above. The team found that improvements were inhibited by (1) incomplete staffing, in particular operators and key mid-level supervisory personnel, (2) a prevailing view in the organization that the improvements made to date have corrected the problems, (3) reluctance, by management, to acknowledge some problems identified by the NRC, and (4) dependence on third parties to identify problems rather than implementing an effective program for self-identification of weaknesses. We believe these findings confirmed the SALP Board conclusions.

We acknowledge your discussion of program and staffing improvements in plant operations, radiological controls and emergency preparedness. However, we believe that the success of your programs depends upon resolution of the four principal factors inhibiting improvement noted above which, in turn, depends heavily on management attitudes and aggressive followup. In this regard we request that you be prepared to discuss the scope, content and schedule of each improvement program at a management meeting scheduled for 1:00 p.m. on June 12, 1986 at the NRC Region I Office.

TABLE 4

ENFORCEMENT SUMMARY (10/1/84 - 10/31/85)PILGRIM NUCLEAR POWER STATION

<u>FUNCTIONAL AREAS</u>	<u>Severity Levels</u>						<u>Total</u>
	<u>I</u>	<u>II</u>	<u>III</u>	<u>IV</u>	<u>V</u>	<u>DEV</u>	
A. Plant Operations	-	-	-	4	2	-	6
B. Radiological Controls	-	-	1	1	1	2	5
C. Maintenance & Modifications	-	-	-	1	-	-	1
D. Surveillance	-	-	-	9	2	1	12
E. Emergency Preparedness	-	-	-	2	-	-	2
F. Security & Safeguards	-	-	1	-	-	-	1
G. Refueling & Outage Management	-	-	-	-	-	-	0
H. Licensing Activities	-	-	-	-	-	-	0
Totals by Severity Level	0	0	2	17	5	3	27

TABLE 5
ENFORCEMENT DATA

PILGRIM NUCLEAR POWER STATION

<u>Insp. No.</u>	<u>Insp. Date</u>	<u>Severity Level</u>	<u>Functional Area</u>	<u>Violation</u>
84-36	11/1-11/85	IV	Plant Operations	Failure to conduct an adequate shift turnover for control room personnel during refueling
		IV	Plant Operations	Failure to continuously monitor source range monitors during refueling
84-39	11/21-12/31/84	IV	Surveillance	Failure to promptly identify conditions adverse to quality (i.e. failure to initiate Failure and Malfunction Reports)
84-41	12/10-13/84	IV	Emergency Preparedness	Failure to disseminate emergency planning information
		IV	Emergency Preparedness	Failure to update the emergency plan and procedures
84-44	12/18-19/84	III	Radiological Controls	Failure to follow radiation work permit instructions and failure to establish a procedure for a remote reading teledosimetry system
85-01	1/1-31/85	V	Plant Operations	Failure to maintain control room staffing at levels required by 10 CFR 50.54
		IV	Surveillance	Failure to test the containment cooling subsystem immediately when the low pressure coolant injection system was inoperable
85-03	2/1/85-3/4/85	IV	Surveillance	Failure to conduct surveillance tests for the reactor protection system (six examples)
		IV	Surveillance	Failure to conduct rod block surveillance tests (five examples)

<u>Insp. No.</u>	<u>Insp. Date</u>	<u>Severity Level</u>	<u>Functional Area</u>	<u>Violation</u>
		IV	Plant Operations	Failure to promptly correct conditions adverse to quality (i.e. failure to take timely action on Quality Assurance surveillance findings)
		V	Surveillance	Failure to use the most current revision of the surveillance test procedure
		V	Surveillance	Failure to calibrate test equipment within the calibrated period
85-06	3/5/85- 4/1/85	V	Plant Operations	Failure to maintain an uncalibrated local power range monitor in a bypassed state
		IV	Maintenance	Failure to conduct a dioctyl phthalate test of HEPA filters for maintenance on the sta. treatment system
85-13	5/20-24 '85	V	Radiological Controls	Failure to have the Operations Review Committee (ORC) review two radiological procedures and failure to control work in the fuel pool with a maintenance request
		Deviation	Radiological Controls	Failure to conduct an adequate review of systems that could generate an uncontrolled, unmonitored radioactive effluent release, as recommended in IE Bulletin 80-10
85-17	6/13/85- 7/15/85	IV	Surveillance	Failure to conduct a surveillance test of the 250 V battery system required by the technical specification and to follow station procedures for additional battery tests
		IV	Radiological Controls	Failure to specify high radiation area surveillance frequencies on radiation work permits

<u>Insp. No.</u>	<u>Insp. Date</u>	<u>Severity Level</u>	<u>Functional Area</u>	<u>Violation</u>
		Deviation	Surveillance	Failure to conduct inservice tests as specified in an NRC submittal
85-20	7/16/85- 8/19/85	IV	Surveillance	Failure to maintain the trip level setting for the "B" and "C" main steam-line high radiation monitors within technical specification limits
85-21	7/16/85- 7/30/85	IV	Surveillance	Failure to maintain secondary containment
		IV	Surveillance	Failure to test alternate safety system when an emergency diesel generator was found to be inoperable
		IV	Surveillance	Failure to initiate Failure and Malfunction Reports as required by station procedures
85-24	8/6-8/85	III	Security	Failure to maintain an adequate vital area barrier
85-26	8/20/85- 9/23/85	IV	Plant Operations	Failure to properly authorize excessive licensed operator overtime as required by station procedures (thirty-five instances)
85-27	9/16/85- 9/20/85	Deviation	Radiological Controls	Failure to install a protective conduit



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
430 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19403

Docket No. 50-293

JUN 19 1985

Boston Edison Company M/C Nuclear
ATTN: Mr. William D. Harrington
Senior Vice President, Nuclear
800 Boylston Street
Boston, Massachusetts 02199

RECEIVED
JUN 20 1985
W.D.H.

Gentlemen:

Subject: Systematic Assessment of Licensee Performance (SALP) Report No. 50-293/
84-34 and Your Reply Letter BECo 85-031 Dated February 12, 1985

Thank you for your reply to SALP Report No. 50-293/84-34. In your letter you presented additional information concerning assessments and requested we reconsider some of the assessments to better account for the assessment period's extraordinary circumstances (i.e., the extended outage for piping replacement).

Based on our discussions with you at the January 23, 1985 management meeting and the information presented in your reply letter, the SALP Board found it appropriate to revise the declining trend of the Category 2 rating for fire protection/housekeeping to a Category 2 rating with a consistent trend. We feel this is appropriate as we may not have properly accounted for the extended outage in our evaluation for trend. However, we continue to feel that the extent of contamination that existed throughout the plant was inconsistent with a Category 1 rating. The enclosed SALP Report has been supplemented to reflect this change. The SALP Board also found that the other ratings should remain unchanged.

With regard to the current status of your operations, we acknowledge the improving trend of your performance in the plant operations and maintenance areas and encourage you to continue your efforts in these areas. Further, we note the progress being made in implementing your recently established Radiological Improvement Program and encourage your efforts to decontaminate the plant, to reduce plant radiation levels, to enhance oversight of the radiation protection program, and to establish support for the program by plant personnel.

Your cooperation with us is appreciated.

Sincerely,

Thomas E. Murley
Regional Administrator

TABLE 2
VIOLATION SUMMARY (7/1/83 - 9/30/84)
PILGRIM NUCLEAR POWER STATION

A. Number and Severity Level of Violations

Severity Level I	0
Severity Level II	0
Severity Level III	1
Severity Level IV	18
Severity Level V	6
Deviation	<u>1</u>
Total	26*

B. Violations Vs. Functional Area

<u>Functional Areas</u>	<u>Severity Level</u>					
	<u>I</u>	<u>II</u>	<u>III</u>	<u>IV</u>	<u>V</u>	<u>DEV</u>
A. <u>Plant Operations</u>				2	5	
B. <u>Radiological Controls*</u>			1	7	1	1
C. <u>Maintenance</u>				2		
D. <u>Surveillance</u>				1		
E. <u>Fire Protection and Housekeeping</u>						
F. <u>Emergency Preparedness</u>						
G. <u>Security and Safeguards</u>				6		
H. <u>Refueling and Outage Management</u>						
I. <u>Licensing Activities</u>						
<u>Totals*</u>			1	18	6	1

*Totals do not include three apparent violations and one apparent deviation in the area of radiological controls that were identified during inspection 84-25. NRC enforcement action was under review at the end of the assessment period.

C. Summary

<u>Inspection Report No.</u>	<u>Inspection Date</u>	<u>Severity Level</u>	<u>Functional Area</u>	<u>Violation</u>
83-19	8/16-10/3/83	V	A	Failure to review and update special orders
		V	A	Failure to vent piping from the high point in the core spray system
83-20	8/8-12/83	IV	B	Failure to follow a Radiation Work Permit
83-21	8/22-24/83	V	A	Failure to schedule external audits
		V	A	Failure to document deficiencies in deficiency reports
83-23	10/4-11/7/83	IV	D	Failure to conduct an in-service test on a high pressure coolant injection (HPCI) valve
		IV	C	Failure to review a procedure for procuring safety-related items.
83-24	11/8-12/31/83	IV	A	Failure to record reactor vessel cool down rate
84-03	1/20-27/84	III	B	Failure to label a container of licensed material, use extremity dosimetry, and instruct workers on radiation levels
84-04	2/7-3/12/84	IV	A	Failure to maintain a procedure for the proper operation of the containment atmospheric dilution system
84-06	2/13-17/84	IV	B	Failure to follow a radiation work permit

<u>Inspection Report No.</u>	<u>Inspection Date</u>	<u>Severity Level</u>	<u>Functional Area</u>	<u>Violation</u>
84-11	4/23-27/84	IV	C	Failure to maintain a procedure for controlling welding slag
84-13	4/24-27/84	IV	B	Failure to properly review and approve contractor procedures involving transportation of radioactive materials
		IV	B	Failure to comply with the requirements of a Certificate of Compliance for a transport package
		V	B	Failure to properly document a quality assurance program for transport packages
		DEV	B	Failure to fulfill a transportation training commitment
84-14	5/9-11/84	IV	B	Failure to instruct workers on the presence of radioactive materials
		IV	B	Failure to survey radiation hazards
		IV	B	Failure to implement procedures consistent with 10 CFR 20
84-22	7/16-20/84	IV	G	Failure to control a security key card
		IV	G	Failure to maintain photo ID badges
		IV	G	Failure to respond to two vital area alarms
		IV	G	Failure to maintain one guard radio and one offsite communications net operable

<u>Inspection Report No.</u>	<u>Inspection Date</u>	<u>Severity Level</u>	<u>Functional Area</u>	<u>Violation</u>
		IV	G	Failure to maintain effective compensatory measures.
		IV	G	Failure to maintain effective compensatory measures.
84-25	8/6-10/84	*	B	Failure to perform radiation surveys
		*	B	Failure to instruct workers on radiation hazards
		*	B	Failure to properly approve procedures
		*	B	Failure to implement recommendations in Regulatory Guide 8.8
84-26	8/28-10/8/84	V	A	Failure to properly approve QA program related procedures

*Apparent violations and deviations. Enforcement action was under review at the end of the assessment period.



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
431 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

SEP 14 1983

Docet No. 80-293

Boston Edison Company M/C Nuclear
ATTN: Mr. William D. Harrington
Senior Vice President, Nuclear
400 Boylston Street
Boston, Massachusetts 02199

RECEIVED

SEP 15 1983

Gentlemen:

W. D. H.

SUBJECT: SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE (SALP)

The NRC Region I SALP Board conducted a review on August 25, 1983, and evaluated the performance of activities associated with the Pilgrim Nuclear Power Station. The results of this assessment are documented in the enclosed SALP Board Report. A meeting has been scheduled for September 21, 1983, at Braintree, Ma. to discuss this assessment.

At the meeting, you should be prepared to discuss our assessment and your plans to improve performance. Any comments you may have regarding our report may be discussed at the meeting. Additionally, you may provide written comments within 20 days after the meeting.

Following our meeting and receipt of your response, the enclosed report, your response, and a summary of our findings and planned actions will be placed in the NRC Public Document Room.

Your cooperation is appreciated.

Sincerely,


Richard W. Searostecki
SALP Board Chairman, Director
Division of Project and
Resident Programs

Enclosure: As Stated

cc w/encl:
A. V. Morisi, Manager, Nuclear Operations Support
C. J. Mathis, Station Manager

TABLE 4
VIOLATIONS (7/1/82 - 6/30/83)
PILGRIM NUCLEAR POWER STATION

A. Number and Severity Level of Violations

Severity Level I	0	
Severity Level II	0	
Severity Level III	1	
Severity Level IV	9	
Severity Level V	20	
Deviations	3	
Total Violations	30	Total Deviations 3

B. Violations Vs. Functional Area

FUNCTIONAL AREAS	<u>Severity Levels</u>					
	I	II	III	IV	V	DEV
1. Plant Operations				4	8	
2. Radiological Controls				1	7	1
3. Maintenance				1		1
4. Surveillance						
5. Fire Protection/Housekeeping					3	1
6. Emergency Preparedness						
7. Security and Safeguards			1	3	2	
8. Refueling						
9. Licensing Activities						
Totals	0	0	1	9	20	3

Total Violations = 30

Total Deviations = 3

TABLE 4 (Continued)

<u>Summary</u>	<u>Inspection No1</u>	<u>Inspection Date</u>	<u>Subject</u>	<u>Require- ments</u>	<u>Severity</u>	<u>Area</u>
	82-19	June 14 - August 1	Blocking open a fire door without proper controls	T.S.	V	5
			Failure to evaluate fire loading prior to moving combustibles into safety related area	T.S.	V	5
			Failure to translate design bases into drawings	10CFR50 App. B	V	1
			Failure to perform an adequate safety evaluation prior to changing a station valve lineup procedure	10CFR50.59	V	1
			Failure to maintain a fire door position continuously annunciated	T.S.	V	5
			Failure to perform daily checks of non-alarmed fire doors as committed to the NRC	Fire Protection Review	D	5
	82-22	August 2 -	Failure to make a prompt notification	T.S.	IV	1
			Failure to make a 50.72 notification	10CFR50	V	1
			Failure to perform a leak rate test required by the LCO for an inoperable Vacuum Breaker Alarm System	T.S.	IV	1

TABLE 4 (Continued)

Summary

<u>Inspection No.</u>	<u>Inspection Date</u>	<u>Subject</u>	<u>Requirements</u>	<u>Severity</u>	<u>Area</u>
82-24	September 7 - October 18	Failure to revise procedures for radioactive discharges as committed to the NRC	Licensee Response to Violation 81-19-01	0	2
82-29	October 19 - November 15	Improper equipment tagging	T.S.	V	1
		Failure to properly set a main steam safety valve			
		Failure to properly control distribution of the Q-List	10CFR50 App. B	IV	1
		Failure to use proper methods of access control	Security Plan	V	7
		Failure to prevent unauthorized entry into vital area or followup on a security deficiency	Security Plan	IV	7
N/A(1)	January 31, 1983	Safeguards information not properly controlled resulting in a loss of copy of the site physical Security Plan	10CFR73.21	III	7
83-03	January 25 February 28	Failure to perform chemistry samples	T.S.	V	2(1)*
		Failure to assure that training certification forms were completed prior to watch assignment	10CFR50 App. B	V	1
		Failure to properly control high pressure gas cylinders	T.S.	V	1(5)*

TABLE 4 (Continued)

<u>Summary</u>					
<u>Inspection No.</u>	<u>Inspection Date</u>	<u>Subject</u>	<u>Requirements</u>	<u>Severity</u>	<u>Area</u>
83-07	March 22- April 18	Failure to implement a station procedure for inspection and cleaning of the SBT System inlet plenum	T.S.	V	2(3)*
83-08	May 9 - May 13	Failure to conduct an audit of the Radiological Environmental Monitoring Program report when required	T.S.	V	2
83-09	April 4 - May 3	Accepting, in receipt inspection, material not in conformance with the P.O. Requirements	10CFR50 App. B	V	1
		Failure to maintain the Q-List	10CFR50 App. B	IV	1
		(2) Failure to update the FSAR	10CFR50.71(e)	V	1
		Failure to perform preventive maintenance as committed to the NRC	IEB 79-09 Commitment	D	3
83-10	April 19 - May 23	Safeguards information not properly controlled	10CFR73.21	IV	7
		Security access card key not properly controlled	Security Plan	IV	7



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 MARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

NOV 15 1982

Docket No. 50-293

Boston Edison Company M/C Nuclear
ATTN: Mr. William D. Harrington
Senior Vice President, Nuclear
800 Boylston Street
Boston, Massachusetts 02199

Gentlemen:

Subject: Systematic Assessment of Licensee Performance (SALP)

This letter and its enclosures document NRC's assessment of the performance of licensed activities at the Pilgrim Nuclear Power Station for the period September 1, 1981, to June 30, 1982. The enclosed SALP Report, dated August 12, 1982, includes performance assessments for each of the nine functional areas which were evaluated. These individual assessments were discussed with you and your staff by Mr. R. W. Starostecki of this office on September 1, 1982, at the Boston Edison Company offices in Braintree, MA.

Our overall assessment of the performance of NRC licensed activities at the Pilgrim facility is that improvement has occurred since the organizational and personnel changes which took place earlier this year. There now appears to be a satisfactory level of management attention and involvement in plant safety matters. This has enhanced the plant's performance with respect to operational safety. We recognize that efforts are underway to improve the management systems and utilization of resources at the Pilgrim facility. These changes and plans are documented in the Performance Improvement Plan which were submitted to the NRC on July 30, 1982. However, we also realize that it will be several months before some of these improvements will be completed. Although performance has improved recently, some shortcomings have been noted and we have included them in this report. In particular, we believe additional attention is warranted on your part in the areas of day-to-day plant operations and fire protection/prevention activities. We will be increasing our attention to these areas to ascertain if identified weaknesses are being corrected.

In the meeting of September 1, 1982, the NRC staff benefited from your comments concerning the SALP Program and the functional area performance assessments. I have also reviewed your letter of September 20, 1982 and have included responses to your comments in this package. The SALP Board also considered your concerns and I had the benefit of their input. The results of these considerations are presented below.

TABLE 5
VIOLATIONS (9/1/81 - 6/30/82)
PILGRIM NUCLEAR POWER STATION

A. Number and Severity Level of Violations

a. Interim NRC Policy Severity Level (September 1, 1981 - March 9, 1982)

Severity Level I	0
Severity Level II	0
Severity Level III	6
Severity Level IV	5
Severity Level V	17
Severity Level VI	2
Deviation	1

b. NRC Policy Severity Levels (March 10, 1982 - June 30, 1982*)

Severity Level I	0
Severity Level II	0
Severity Level III	1
Severity Level IV	4
Severity Level V	3
Deviation	1

Total Violations 38 Total Deviations 2

B. Violations Vs. Functional Area

(1) September 1, 1981 - March 9, 1982

FUNCTIONAL AREAS	Severity Levels						
	I	II	III	IV	V	VI	DEV
1. Plant Operations	0	0	3	3	6	0	0
2. Radiological Controls	0	0	1	1	3	0	1
3. Maintenance	0	0	0	0	2	0	0
4. Surveillance	0	0	0	1	1	1	0
5. Fire Protection	0	0	0	0	5	0	0
6. Emergency Preparedness	0	0	1	0	0	0	0
7. Security & Safeguards	0	0	1	0	0	0	0
8. Refueling	0	0	1	0	0	0	0
9. Licensing Activities	0	0	0	0	1	0	0
TOTAL	0	0	6	5	17	2	1

TABLE 5 (Continued)

8. Violations Vs. Functional Area

(2) March 10, 1982 - June 30, 1982*

FUNCTIONAL AREAS	Severity Levels					
	I	II	III	IV	V	DEV
1. Plant Operations	0	0	0	1	1	1
2. Radiological Controls*	0	0	0	1	0	0
3. Maintenance	0	0	0	1	0	0
4. Surveillance	0	0	0	0	2	0
5. Fire Protection*	0	0	0	0	0	0
6. Emergency Preparedness	0	0	0	0	0	0
7. Security & Safeguards	0	0	1	0	0	0
8. Refueling	0	0	0	1	0	0
9. Licensing Activities	0	0	0	1	0	0
Totals	0	0	1	4	3	1

Total Violations = 38
Total Deviations = 2

* Does not include the following reports, not yet issued:

- 82-19 - Resident Inspector
- 82-20 - Special Health Physics

TABLE 5 (Continued)

G. Summary

Inspection No.	Inspection Date	Subject	Req.	Sev.	Area
81-18	June 15 - Sept. 30	Failure to have an operable combustible gas control system (multiple examples of design errors, procedural and drawing errors, and inadequate safety reviews)	10 CFR 50.44	III	1 (9)*
81-18	June 15 - Sept. 30	Failure to inform the NRC of the erroneous statement that an installed system met the requirements of 10 CFR 50.44 - Material False Statement	T.S.	III	1 (9)*
81-19	August 18 - Sept. 30	Failure to follow station procedure	T.S.	V	1
81-19	August 18 - Sept. 30	Failure to perform a safety evaluation prior to disabling protection for an RHR pump	10 CFR 50.59	IV	1
81-21	August 31 - Oct. 2	Failure to post a high radiation area	T.S.	IV	2
81-21	August 31 - Oct. 2	Failure to adhere to radiation protection procedures for radiation work permits.	T.S.	V	2
81-21	August 31 - Oct. 2	Failure to post copies of WOV's involving radiation protection	10 CFR 19	V	2
81-22	Sept. 16 - Sept. 17	RCIC containment isolation valves were left open when their control instrumentation was inoperable	T.S.	III	1
81-24	Dec. 1, 1981- Jan. 18, 1982	Operation at drywell temperatures above FSAR description without adequate safety evaluations	10 CFR 50.59	IV	1
81-24	Dec. 1, 1981- Jan. 18, 1982	Failure to adequately prepare and implement procedures for coping with high drywell temperatures	T.S.	V	1(4)*

TABLE 5 (Continued)

C. Summary

Inspection No.	Inspection Date	Subject	Reg.	Sev.	Area
81-24	Dec. 1, 1981- Jan. 18, 1982	Failure to promptly evaluate and correct conditions adverse to quality	10 CFR 50 App B	V	1
81-24	Dec. 1, 1981- Jan. 18, 1982	Security access card keys not properly controlled	Security III Plan		7
81-24	Dec. 1, 1981- Jan. 18, 1982	Combustibles were not removed from area near hot work	T.S.	V	5
81-24	Dec. 1, 1981- Jan. 18, 1982	Improper equipment tagging	T.S.	V	1 (3)
81-25	Oct. 15 - Oct. 17, 1981	Failure to have all ORC members present at a pre-refueling meeting	T.S.	V	8
81-25	July 20, 1981	Transported radioactive materials with liquid in drums	10 CFR 30.41	III	2
81-35	Nov. 1 - Nov. 30	Control/Storage of combustible gas cylinders was not in accordance with station procedures	T.S.	V	5
81-35	Nov. 1 - Nov. 30	Failure to establish and implement procedures for the control of combustible scrap, waste, debris	T.S.	V	5
81-35	Nov. 1 - Nov. 30	Failure to establish and implement procedures for the control of combustible oil	T.S.	V	5
81-35	Nov. 1 - Nov. 30	Control of foreign material during repairs to MSIV's was not in accordance with procedure	T.S.	V	3
81-36	Nov. 30, 1981- Dec. 4, 1981	A master surveillance schedule was not established	T.S.	VI	4
81-36	Nov. 30, 1981- Dec. 4, 1981	T.S. Amendments were not properly entered into controlled volumes	T.S.	VI	9 (1)

TABLE 5 (Continued)

C. Summary

Inspection No.	Inspection Date	Subject	Req.	Sev.	Area
81-36	Nov. 30, 1981- Dec. 4, 1981	Program and procedures were not established for housekeeping and system cleaning that meet the standards stated in the QA Manual	10 CFR 50 App B QAM	V	3 (5) *
82-01	Jan. 18, 1982- Feb. 28, 1982	Workers were not properly instructed of the storage and transfer of radioactive resins	10 CFR 19.12	V	2
82-01	Jan. 18, 1982- Feb. 28, 1982	Procedures were not adequately established and implemented to provide required numbers of SCBA units for fighting fires	T.S.	V	5
82-02	Jan. 1 - Jan. 15, 1982	Uncalibrated brush recorders were used during RPS surveillance	10 CFR 50 App B	V	4
82-02	Jan. 1 - Jan. 15, 1982	Maintenance activities were performed without using approved procedures	T.S.	IV	3
82-02	Jan. 1 - Jan. 15, 1982	Instrumentation was not calibrated at frequency specified in station procedures	T.S.	V	4
82-02	Jan. 1 - Jan. 15, 1982	Improper control of access to Vital Areas	Security III Plan		7
82-04	Jan. 25 - Jan. 29, 1982	Failure to implement procedures for LLRT and drawing change revisions	T.S.	V	4 (1) *
82-04	Jan. 25 - Jan. 29, 1982	Drawings and procedures did not identify the as-built condition of valves in piping systems	10 CFR 50 App B	IV	1
82-05	Feb. 1 - Feb. 5, 1982	Untimely corrective action to internal QA Audit Deficiency Reports	10 CFR 50 App B	V	1
82-06	Feb. 10 - Feb. 12, 1982	Training and requal. program for personnel who operate and process radioactive waste not implemented as committed	Commitment DEV IEB 79-19		2



TABLE 5 (Continued)

C. Summary

Inspection No.	Inspection Date	Subject	Reg.	Sev.	Area
N/A	Feb. 12, 1982	Prompt Notification System (sirens) not installed by February 1, 1982	10 CFR 50.54	III	6
82-10	March 1 - April 4, 1982	Performed maintenance on valve with red tag attached	T.S.	V	1 (3) *
82-10	March 1 - April 4, 1982	Plant shielding study mod. (truck lock door panel) not completed as stated in response to NRR	NUREG 0737	DEV	6
82-11	Feb. 25 - Feb. 28, 1982	An unauthorized adjustment was made to a leaking flange during the conduct of the PCILRT	10 CFR 50 App J	IV	4
82-12	April 5 - May 9, 1982	Failure to follow actions required by T.S. with inoperable reactor vessel water level instrumentation	T.S.	IV	1
82-13	April 12 - April 16, 1982	Inadequate design control, for interfaces and verification	10 CFR 50 App B	IV	9 (5) *
82-16	May 10 - June 13, 1982	Failure to lock or control access to a high radiation area (stuck TIP drive)	T.S.	IV	2

() secondary area involved

Testimony Submitted by
Stephen J. Sweeney
President and Chief Executive Officer
Boston Edison Company
to the
U.S. House of Representatives
Subcommittee on Energy Conservation and Power
of the
Committee on Energy and Commerce
July 16, 1986

Sperry
6/23/86 - 14.5

INTRODUCTION

Boston Edison Company appreciates the opportunity to address a number of issues involving the Pilgrim Nuclear Power Station which are of concern to this committee, the Nuclear Regulatory Commission and to me personally. At the outset let me stress that most of the issues raised by the NRC in various reports and by this committee were of concern to me more than a year ago and that corrective actions were underway as early as September 1985. As discussed in the following pages, those actions are meeting with success.

In today's environment, public concern about nuclear power is heightened substantially. Public confidence in the technology and the institutions involved with it is at a low point.

Boston Edison Company has a great deal of work to do in this environment to gain public confidence in our ability to manage and run Pilgrim Station. I personally will not be satisfied until we have achieved a level of public and regulatory confidence that allows Pilgrim Station to place among the best. We have made an internal commitment to measure ourselves against the best, which is a significant change in how we are approaching our current problems.

As will be evident in reviewing our testimony, we were historically plagued by not looking outside to measure our success and to undertake the intensive self-criticism necessary to assess performance honestly and objectively. That has changed. We are moving in a new direction, one based on rising standards of excellence which are set, not by regulation, but by the performance of those plants judged to be among the best.

It should be noted that the concerns we are addressing today are different from those for which we were fined in 1982. The issues then were safety-related and failure to comply with regulations. Today, the issues are not directly related either to compliance or to safety. They instead involve a rising standard of performance going far beyond mere compliance with rules to a much broader dimension in the regulatory process. That new dimension is one that dictates comparisons and success is measured by relative performance. We endorse it.

Before discussing our current activities, let me offer perspectives on three time frames.

The first time frame is 1972 to 1979 and Three Mile Island. Our major management shortcoming then was the failure to recognize fully that the operational and managerial demands placed on a nuclear power plant are very different from those of a conventional fossil-fired power plant. Boston Edison structured its nuclear organization as part of a traditional operating arm. While many members of the Pilgrim Station organization recognized the differences in the technologies, they had limited success in arguing for the resources necessary to meet a set of standards that already were rising fairly rapidly. This was also a period of poor quality fuel which resulted in significant internal radiological problems that affected the plant for years.

Then came Three Mile Island. From March 1979 until early 1982 the same structure, under one vice president, attempted to deal with the post-TMI demands on operations and engineering, while at the same time pursuing a construction permit for a second unit at Pilgrim Station. The staff increased dramatically to 200, 300 and then 400 people. It was an unreasonable workload for the structure and we paid a costly penalty for not recognizing it -- \$550,000 in early 1982.

From 1982 until mid-1985, we operated with a new and improved management structure that recognized the unique nature of nuclear power plants and the demands of the post-TMI period. We committed the financial and human resources necessary to upgrade equipment and hardware and to install various improvement programs to meet NRC concerns. More than \$300 million went into hardware improvements, the staff grew from 400 to nearly 600 people and the organization was restructured under a senior vice president and two vice presidents. We achieved a significant measure of success for which we were recognized by the NRC and in the plant's outstanding operating performance in both 1983 and 1985.

But in managing the equipment improvements and the new management systems and programs we put in place, we didn't focus enough on what was going on outside the company in the industry and within the NRC. What we didn't see because we were so internally focused was the fact that the industry itself and the NRC were looking under, behind and around all of the hardware and management programs reaching for excellence.

In our case, not seeing that put us in a defensive posture. We weren't identifying weaknesses that were inhibiting continued improvement ourselves. We weren't being self-critical, others had to tell us what was wrong. We weren't holding managers accountable enough for the end result of an action or inaction. We weren't working well enough together.

Those problems were very real, very serious and of great concern to me and to the Board of Directors. I became particularly concerned about management performance, not management systems and programs, but the results of those systems and programs as measured by effectiveness. In mid-1985, I asked the Vice President of Nuclear Operations to investigate my concerns, which he shared, and issue a report. As he progressed through the study, he

and other managers began identifying needs. In September 1985, we increased the operator staff by a third. In December, we reorganized plant management to improve reporting relationships and build in greater accountability.

In February 1986, the NRC issued their report. They said the same thing: We had attitude problems that were seriously interfering with our ability to get the results we should be seeing given our financial and human resource commitments.

By March, we had taken a number of other actions, all of which are detailed in the following pages. We began eliminating those old attitudes that were not serving us well and began to inject the nuclear organization with the skills and perspectives necessary to achieve a measure of performance which would place us among the best. In the same time frame we made further human resource commitments. We increased our emergency planning complement five-fold, we increased the number of radiological technicians 35 percent and we implemented an apprentice program for the long-term development of skilled personnel.

The shutdown on April 12 gave us an opportunity to accelerate that change. A different approach to problem solving was taken. It stressed a more deliberative and integrated effort at identifying root causes and taking corrective action. In early May, a new plant manager and a new operations section head were brought on board, nearly rounding out a new 16 member plant management team. Of the 16, 11 were new in their positions in the past 8 months and 5 were new to the company. We have new perspectives. We have people with strong nuclear navy backgrounds, people with NRC inspection experience and people who grew up professionally not in conventional fossil-fired power plants, but in nuclear plants.

On May 27, having accepted that management is just as important as equipment, we took the unprecedented step of giving the new plant manager and his new team additional time, while the unit was shut down, to become familiar with the issues, to accelerate the development of new programs and, most importantly, to infuse the organization with attitudes and behavior that will make those programs work. These are attitudes that demand self-criticism, demand accountability, demand teamwork and demand results which go far beyond mere compliance with a set of rules, regulations and technical specifications.

Excellence is our goal. But excellence is, after all, an attitude which accepts nothing less. Achieving excellence will not be easy; we know that. We know our problems. We have made the human resource and financial commitment to solve them. We know what has to be done and we are doing it. As a result, I am confident we will, in time, demonstrate to you, to the Nuclear Regulatory Commission and the public that we have responded effectively to the concerns which are shared by all of us.


As a final point, I know that an important question on the minds of many people is "why should Boston Edison be believed today given the problems over the years at Pilgrim Station?"

I hope I already answered that question in part. It is perhaps the most difficult question and can only be answered fully by performance over time. But in closing I would underscore two major differences today from the past. The first is our forceful acceptance of the need for us to measure our performance against an ever increasing set of standards set by those plants judged by industry and the NRC to be among the best.

The second is the fact that we have adopted the basic principles and criteria for good management that are applied to the nuclear navy. They are the same principles and criteria that are in evidence at all of the top rated plants.

This is a demanding industry with a vital role in the social and economic health of the country. It operates in a demanding regulatory climate as evidenced by this hearing today. For us as a company with a single unit to succeed in this environment means that we must impose on ourselves the highest standards of performance found in the industry. We are doing just that.

The balance of this filed testimony is arranged in the order of the six sections on which you requested information in your letter of July 2, 1986. We have repeated your request at the beginning of each section.


BOSTON EDISON
Executive Offices
810 Summer Street
Boston, Massachusetts 02109

Ralph G. Bird
Senior Vice President - Nuclear

July 8, 1987

BECO Ltr. 87-111

Mr. Steven A. Varga, Director
Division of Reactor Projects, I/II
United States Nuclear Regulatory Commission
Washington, D. C. 20555

License DPR-35
Docket 50-293

INFORMATION REGARDING PILGRIM STATION
SAFETY ENHANCEMENT PROGRAM

Reference: NRC Letter, Proposed Enhancement to the Mark I Containment -
Pilgrim Station, dated April 30, 1987

Dear Mr. Varga:

As agreed during July 1, 1987 discussions between Frank Miraglia, USNRC, and John Fulton, Boston Edison Company (BECO), we are submitting this response to your letter to BECO dated April 30, 1987. Enclosed for your information is a detailed description of the Safety Enhancement Program (SEP) hardware changes that BECO has voluntarily elected to implement for Pilgrim Nuclear Power Station (PNPS). The description of procedural changes and personnel training will be furnished under separate cover. A current implementation schedule for the SEP modifications will also be furnished separately. A condition is that the modifications scheduled during the current outage do not require prior governmental approval. Should this condition not be met for any of these voluntary modifications, with the result that the current implementation schedule must be extended, then BECO will be unable to implement the affected modifications during the current outage.

Additional documentation will be available for review by the NRC Staff at BECO's Braintree offices or the PNPS site. Cognizant BECO personnel will be available at those locations for discussion with the Staff.

Current evaluations of the benefit from the SEP modifications are based primarily upon extensive, although still preliminary, analyses and qualitative engineering judgments. Final quantitative analysis must, in accordance with the stated long term goal of the SEP, await final identification of modifications and completion of the Individual Plant Evaluation (IPE). BECO understands that the NRC intends to issue later this year a generic letter requiring all plants to perform an IPE as part of the


Mr. Steven Langa

-2-

July 8, 1987

closure of the Commission's Severe Accident Policy Statement. When that requirement is issued, BCCo expects to complete the IPE and promptly make the results available in accordance with the review process prescribed by the generic letter.

Please feel free to contact me or Edward Howard, of my staff at (617) 349-3900 if you have any questions concerning the matter addressed in this response.


R. G. Bird

Enclosures

cc: Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

Senior NRC Resident Inspector
Pilgrim Nuclear Power Station

Mr. R. H. Wessman, Project Manager
Division of Reactor Projects, I/II
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
7920 Norfolk Avenue
Bethesda, MD 20814



Michael S. Dukakis
Governor

Charles V. Barry
Secretary

The Commonwealth of Massachusetts

Executive Office of Public Safety

One Ashburton Place

Boston, Massachusetts 02108 (617) 727-7775

EXECUTIVE SUMMARY OF THE PROGRESS REPORT ON EMERGENCY PREPAREDNESS FOR AN ACCIDENT AT PILGRIM NUCLEAR POWER STATION

I. EXECUTIVE SUMMARY

On December 16, 1986, I transmitted to the Governor a comprehensive report on safety at Pilgrim Nuclear Power Station. This is a progress report about the activities by state and local government, the Boston Edison Company, the U.S. Nuclear Regulatory Commission and the Federal Emergency Management Agency since that time to address the concerns we found.

In April of 1986, operation of Pilgrim Station was halted because of several mechanical problems. The U.S. Nuclear Regulatory Commission has ordered that the Boston Edison Company keep the plant shut until a variety of corrections regarding the management and operation of Pilgrim Station have been made. As of this date, Pilgrim remains closed, although Boston Edison has asked the NRC for permission to restart the facility.

In my December, 1986 report, I concluded that Radiological Emergency Response Plans for the Pilgrim facility were not adequate to protect the public health and safety. I further identified serious problems regarding the management of the power plant and the engineering safety of the reactor. In my view, these three issues -- emergency planning, plant management, and reactor safety -- were so serious and the weaknesses and deficiencies so severe that I recommended that the plant should not be allowed to restart unless and until these concerns had been satisfactorily addressed.

There has been a considerable amount of activity at all levels to address these concerns since my report was issued. In some cases substantial progress has been made. In particular, the Massachusetts Civil Defense Agency and Office of Emergency Preparedness has devoted all available staff and resources to the effort of developing the best possible emergency response plans.

MCDA/OEP has instituted a planning process at the state and local level and revisions are well under way. In addition, a new system has been installed for off-site notification in the event of an accident at Pilgrim Station. We now have the advantage of a new Nuclear Safety Emergency Preparedness Program and a professional staff which for the first time is dedicated to off-site emergency preparedness and planning. This new program and staff are the result of the Governor's initiative in the Fiscal Year 1988 budget. The Governor has requested additional funds for the new program as a supplementary appropriation for the current fiscal year.

Nonetheless, I continue to make the finding that adequate plans for response to an accident at Pilgrim Station do not exist, and I reaffirm my earlier position that the Pilgrim facility should not be allowed to restart until such plans have been fully developed and have been demonstrated to be workable and effective through a graded exercise of all plans and facilities.

This finding is based on the fact that in every critical area in which I found a deficiency to exist in my December, 1986 report substantial work remains to be done before a determination of adequacy can be made. For example, analysis of a new Evacuation Time Estimate and Traffic Management Study by state and local authorities is still underway. The ETE is one of the most critical pieces of information in the entire process and the foundation of effective emergency planning. Our preliminary review of the ETE suggests that more resources are required to successfully implement the traffic management plan. The shelter survey which was prepared by Boston Edison has been returned to the company for further study because it was found to be woefully inadequate.

Plans and implementing procedures for special needs populations remain incomplete, and it may be necessary to undertake an additional survey of people who would need assistance in emergency response or to do further statistical analysis of this matter. The development of implementing procedures and the identification of resources to care for school age populations also requires additional work. In regard to the adequacy of reception centers, the question of need for a facility to serve people in the northern portion of the EPZ remains open. We cannot make decisions on the need for or identification of a third reception center until Boston Edison has provided us with an analysis of the adequacy of the existing two reception facilities.

With regard to plant management, we have seen numerous changes in Boston Edison's personnel and organization for management of Pilgrim Station. The most notable change is the appointment of Mr. Ralph G. Bird as Senior Vice President, Nuclear, who directly reports to the company's chief executive officer. Yet despite these changes, I cannot say at this time that the management problems have been fully resolved. For example, we are concerned about recent incidents including violation of NRC regulations in the area of plant security, and allegations of excessive overtime worked by utility employees. We are also concerned by Boston Edison's action to refuel Pilgrim Station without having responded to my objections and the objections of several state legislators.

The Systematic Assessment of Licensee Performance (SALP) performed by the NRC is the most comprehensive study and report on nuclear management at Pilgrim Station. The last SALP report was issued on April 8, 1987 and it showed deterioration in several aspects of nuclear management since the last report. Until a similarly comprehensive analysis of management under the new organization has been conducted and the above concerns resolved, I cannot say that our management concerns have been addressed.

With regard to reactor safety issues, we have carefully reviewed Boston Edison's "Safety Enhancement Program" (SEP). The SEP has been undertaken since the issuance of a "Draft Generic Letter" from Mr. Robert Bernero of the NRC concerning safety at Mark I containment structures such as the Pilgrim containment. We have two major concerns in the area of reactor safety.

First, despite the fact that the NRC letter was prompted by a finding that there was a high probability of Mark I containment failure during certain severe accident scenarios, the NRC has yet to adopt an official position regarding safety enhancement. Moreover, according to NRC Region I Administrator William Russell, with whom my staff and other state officials met at NRC's regional offices in King of Prussia, Pennsylvania on October 8, 1987, enhancement of the Mark I containment at Pilgrim is not an issue that the NRC believes must be finally resolved before restart.

Our second concern is the uncertainty that continues to exist about at least one feature of the Boston Edison SEP, the direct torus vent. No consensus has been reached on whether installation of the torus vent creates unreviewed

safety issues or if the torus vent is authorized, how it will be used in the event of a severe nuclear accident.

The findings of my December, 1986 report have been strengthened by two other analyses of safety at Pilgrim Station. The Special Joint Legislative Commission to Study Pilgrim Station has issued its report which further studies and documents many of the same safety concerns. In addition, the Federal Emergency Management Agency has issued a Self-Initiated Review of plans for response to an accident at Pilgrim Station. Based on several of the issues raised in my report FEMA has changed its interim finding and now agrees that the off-site plans for an accident at Pilgrim are not adequate.

FEMA has transmitted their new finding to the Nuclear Regulatory Commission. However, the NRC has yet to indicate whether or not development of adequate off-site plans will be a condition to the restart of Pilgrim. We are not satisfied with the view recently expressed by the NRC Region I staff that emergency planning problems must be "addressed" before restart. Such problems must be satisfactorily resolved before restart. Off-site response plans are just as important as nuclear management and reactor safety in protecting the public from an accidental release of radiation.

Therefore, for these reasons -- the absence of adequate emergency response plans, lack of demonstrable assurance that management problems have been solved, and uncertainty about the safety of the Mark I containment structure -- I continue to find that Boston Edison has not met the heavy burden of showing readiness to restart the Pilgrim Nuclear Power Plant. I also continue to believe that it remains to be seen if adequate emergency response plans can be developed and if all other safety issues can be resolved to our satisfaction.

Finally, I recommend that in light of the number of outstanding issues and their complexity, and Boston Edison's evident determination to press ahead with the effort to restart, that there should be a full scale public hearing by the NRC before any decision is made regarding the restart of Pilgrim Station.

October 14, 1987

CHARLES V. BARRY
SECRETARY OF PUBLIC SAFETY



MICHAEL S. DUKAKIS
GOVERNOR

THE COMMONWEALTH OF MASSACHUSETTS
EXECUTIVE DEPARTMENT

CIVIL DEFENSE AGENCY AND OFFICE OF EMERGENCY PREPAREDNESS
400 WORCESTER ROAD
P.O. BOX 1498
FRAMINGHAM, MASS. 01701-0317



ROBERT J. BOULAY
DIRECTOR

September 18, 1987

Mr. Ralph Bird
Senior Vice President
Boston Edison Company
800 Boylston Street
Boston, Massachusetts

Dear Mr. Bird:


My staff has reviewed the August, 1987 "Study to Identify Potential Shelters in EPZ Coastal Region of the Pilgrim Nuclear Power Station," which was prepared for you by Stone and Webster.

We find that this study is deficient in several respects and that additional work is required to provide information to local officials which is sufficient to support development of implementable shelter utilization plans. I have attached a copy of a memorandum prepared by my staff which details our specific concerns regarding this study.

If you have any questions or observations regarding our evaluation, please contact Buzz Hausner of my staff.

Thank you for your cooperation in this matter.

Sincerely,


Robert J. Boulay
Director

cc: Assistant Secretary, Peter W. Agens, Jr.
Deputy Director, John L. Lovering
Mr. Buzz Hausner



CHARLES S. DUKAKIS
GOVERNOR

THE COMMONWEALTH OF MASSACHUSETTS
EXECUTIVE DEPARTMENT

CIVIL DEFENSE AGENCY AND OFFICE OF EMERGENCY PREPAREDNESS
400 WORCESTER ROAD
P.O. BOX 1498
FRAMINGHAM, MASS. 01701-0517



ROBERT J. BOULAY
DIRECTOR

TO: DIRECTOR BOULAY
FROM: BUZZ ~~HAUSNER~~
IN RE: SHELTER SURVEY OF PILGRIM EPZ PREPARED BY BOSTON EDISON
COMPANY
DATE: SEPTEMBER 11, 1987

We have made a preliminary review of the shelter survey of the Pilgrim EPZ which was prepared by the Boston Edison Company and its consultants. While this document compiles some very useful data, we feel that more work must be done to estimate the effectiveness of shelter as a protective action.

Our principal concern is that we must be able to put data in the hands of local officials which are sufficient for the development of shelter utilization plans for all areas of all five communities within the Pilgrim EPZ. With this in mind, we have the following comments.

- The survey only covers an area approximately one mile wide along the coast. The shelter capabilities of the entire EPZ must be surveyed and reported.
- The survey does not separate out those structures which could "most reasonably" be used as shelters from those where shelter is less appropriate.

For instance, it would help to have a separate list of public buildings and facilities for each town, including an estimation of the actual useable shelter space and protective factors for shelter under government authority.

- Many of the shelters listed, such as jewelry stores and pharmacies are clearly not suitable for public shelter. In a severe emergency, every available resource will of course be put to use. However, to develop an implementable shelter utilization plan, local officials must be able to match estimated needs with the most appropriate resources available.

- Regarding protection of the beach population, the survey identifies shelters within a mile of the coast but does not indicate the distances that beach goers would have to travel to find shelter. In addition, the survey must demonstrate that adequate proximate shelter is available for the total population at the individual beaches.

For instance, Duxbury beach is about seven miles long and the survey should indicate the distance people at Saquish Head are required to travel to reach adequate shelter. Further, an implementable shelter utilization plan must demonstrate that the nearest shelter would not be full to capacity before the people at the most remote points of the beaches arrived.
- The survey must identify adequate shelter which is handicapped accessible.
- The survey does not distinguish between available space and usable space. For instance, residents of Plymouth have indicated to us that some basements listed in the survey are no more than crawl spaces. Crawl spaces cannot be considered for public shelter. Further, in most buildings, a good deal of floor area will be occupied by machinery, counters, office furniture, et cetera. The survey must identify accurately the actual useable shelter space available in each structure.
- Stone and Webster uses a FEMA nuclear attack value of ten square feet per person to estimate the potential population which can be sheltered. Local Civil Defense Officials may wish to allocate more space -- up to twenty square feet per person -- in their utilization plans. The value used in the survey overestimates the potential capacity of various buildings. We doubt that 17,000 people can be sheltered at Duxbury High School, or that 89,700 can be sheltered at the 5 Cordage Park Buildings.
- The survey must demonstrate that public shelters are free from asbestos and other environmental hazards.
- The report estimates residential "sheltering capability" in individual communities as between 53% and 81%. These figures indicate that a significant number of residents do not have adequate domestic shelter and emphasize the need for a full study of public shelter capacities throughout the entire EPZ.

Further, even if it can be established that the vast majority of residences offer adequate shelter, local officials must be prepared to offer public shelter of a known protective capability to residents who demand assistance.

- This report makes no definitive statement of what constitutes adequate shelter to protect people from the effects of a radiological release from Pilgrim Station. This is necessary to determine what facilities are most appropriate for a local shelter utilization plan and to determine the public shelter needs of each community.

In summary, we would say that this survey is a useful beginning but that much more work is required before we can assess our ability to develop implementable shelter utilization plans consistent with the public safety concerns in Secretary Barry's report to the Governor.

cc: Assistant Secretary Peter W. Agnes, Jr.
Deputy Director John L. Lovering



BOSTON EDISON
Executive Offices
800 Boylston Street
Boston, Massachusetts 02199

Ralph G. Bird
Senior Vice President — Nuclear

September 17, 1987
BECo Ltr. #87-146

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Docket 50-293
License No. DPR-35

Subject: Boston Edison Company Request for
Exemption from 10 CFR Part 50,
Appendix E, Section IV.F.

Dear Sir:

In accordance with 10 CFR section 50.12(a), Boston Edison Company requests that the Nuclear Regulatory Commission (NRC) grant a one-time exemption from the requirements of 10 CFR Part 50, Appendix E, Section IV.F., that would authorize the next biennial full participation emergency preparedness exercise for the Pilgrim Nuclear Power Station (Pilgrim) to be conducted in the second quarter of 1988. The schedule for future biennial exercises will not be affected by this one-time exemption, but rather will continue to provide that such exercises will be conducted every second year (i.e., the following biennial exercise will be held in 1989).

The proposed deferral of the full participation exercise has been discussed with the Commonwealth of Massachusetts (Commonwealth) and local emergency response officials. All of the parties have indicated that they support the proposal.

The request will not affect the onsite exercise at Pilgrim planned for December 9, 1987.

The requested exemption is necessary because the Commonwealth, the local governments within the ten-mile plume exposure pathway emergency planning zone (EPZ) and the two emergency reception center communities are at present engaged in implementing numerous improvements in their offsite emergency preparedness programs, with the assistance of Boston Edison. These improvements include revision of the emergency plans of the local governments, revision of the Massachusetts Civil Defense Agency (MCDA) Area II plan as well as the Commonwealth's state-wide plan, the development of revised related procedures, the development and implementation of training programs for officials and emergency personnel, and the upgrading of Emergency Operation Centers (EOC's). A substantial commitment of resources and time has been made to accomplish these improvements, and the work is expected to continue through the remainder of the year and early 1988.

In view of these extensive ongoing efforts, the Commonwealth and the local governments have indicated that they are not able to participate in an exercise during calendar year 1987. Moreover, it is apparent that under these circumstances, conduct of the full participation exercise will be much more effective after the ongoing improvements have been implemented. In granting one-time exemptions authorizing deferral of exercises for licensed plants in the past, the NRC has recognized that the most effective and beneficial exercises are those which include the full-scale participation of State and local governments and that it is appropriate to defer an exercise until program revisions or facility improvements have been completed.

Since the last full participation biennial exercise at Pilgrim, Boston Edison has held an onsite exercise at Pilgrim in December 1986; has held quarterly onsite drills in March, June and August of 1987; and has scheduled its annual onsite exercise for December 9, 1987 (in which the Commonwealth will exercise various offsite objectives as described in BECo Ltr. #87-147 "Scheduling of Pilgrim Onsite Exercise"). The previous exercise and drills have included limited participation by the Commonwealth, and the March and June 1987 drills included limited participation by several of the towns. The towns within the EPZ have also cooperated in the full scale siren test reviewed by FEMA, which was conducted on September 29, 1986. In addition to its activities involving Pilgrim, the Commonwealth has also participated in full participation exercises at the Yankee Nuclear Power Station in June 1986 and is scheduled to participate in a full participation exercise at the Vermont Yankee Nuclear Generating Station during the week of November 29, 1987.

This request meets a number of the special circumstances listed in Section 50.12(a)(2)

First, granting the request will provide only temporary relief from the applicable regulation and the licensee has made good faith efforts to comply with the regulation. Over the past year, Boston Edison has assisted Commonwealth and local authorities in a variety of ways to accomplish as many improvements as possible in their offsite emergency response programs. For example, Boston Edison has developed substantive information for the enhancement of those programs. The major products of this effort include the "Pilgrim Station Evacuation Time Estimates and Traffic Management Plan Update" (August 18, 1987) prepared by KLD Associates, Inc. and "A Study to Identify Potential Shelters in the EPZ Coastline Region of Pilgrim Nuclear Power Station" (August 1987) prepared by Stone & Webster Engineering Corporation, as well as information generated in surveys to identify the special needs and transportation dependent populations within the EPZ.

In addition, Boston Edison is providing assistance to the local governments in their offsite emergency program enhancement efforts in accordance with the Massachusetts Civil Defense Act of 1950 (Chapter 639, Section 15, Acts of 1950 as amended). This assistance includes the provision of two professional planners to work under the direction of the officials of each town within the EPZ in upgrading its plan, procedures and training; one

professional planner to assist each reception center community; and four professional planners working under the direction of MCDA in the upgrading of the MCDA Area II and Commonwealth program. In the first half of 1987, Boston Edison provided introductory emergency training to about 350 personnel within the five towns in the EPZ and enhanced introductory training modules are currently being prepared for review by the MCDA prior to further implementation. The planners provided by Boston Edison have also begun to prepare task-based modules for training of specific categories of emergency personnel and will be available to participate in the training programs. In addition, Boston Edison is executing agreements with each of the five towns within the EPZ, as well as the two reception center communities, for assistance in the renovation of their EOC's. Moreover, four of the five EPZ towns and both reception center communities, to date, have accepted BECo's offer of funding support for full-time civil defense staff positions.

Second, literal compliance with the regulation would not serve its underlying purpose and would result in undue hardship to Commonwealth and local emergency response agencies by requiring an exercise of portions of the offsite emergency plans that are in the process of significant revision and improvement. This would necessarily involve disruption of the ongoing process of implementing these changes, and consequently, the imposition of additional costs and delay in accomplishing the planned improvements. The NRC's emergency exercise requirements clearly were not intended to disrupt the orderly implementation of improvements in such manner.

Finally, because granting the request will allow work to proceed without disruption, it will result in a net benefit to the public health and safety. The NRC has acknowledged that flexibility is appropriate in applying emergency planning requirements. This flexible approach is especially appropriate in this case, where granting the request will facilitate more prompt and effective implementation of improvements.

For all these reasons, Boston Edison asks that NRC grant the requested exemption. In accordance with 10 CFR §170.12(c), a fee of one hundred and fifty dollars (\$150.00) will be electronically mailed to your offices. If you should require any additional information in connection with this request, please contact either myself or Mr. Ron Varley of my staff (telephone: 617 - 424-3832).


Ralph G. Bird

RAL/dlw

cc: Dr. Thomas E. Hurley, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
The Phillips Building
Washington, D.C. 20555

Mr. R.H. Hessman, Project Manager
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
7920 Norfolk Avenue
Bethesda, MD 20814

Mr. Richard Krimm, Assistant Associate Director
FEMA
500 C Street - Federal Plaza
Washington, D.C. 20472

Mr. Edward Thomas
FEMA - Region 1
J. W. McCormack Post Office and Court House
Boston, MA 02109

Mr. Peter Agnes, Jr.
Commonwealth of MA
Assistant Secretary of Public Safety
1 Ashburton Place - Room 2133
Boston, MA 02108

U. S. Nuclear Regulatory Commission
Region 1 - 631 Park Avenue
King of Prussia, PA 19406

Senior NRC Resident Inspector
Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, MA 02360

Henry Vickers, Regional Director
FEMA - Region 1
J.W. McCormack Post Office and Court House
Boston, MA 02109