

September 25, 1998

Mr. L. Joseph Callan Executive Director for Operations United States Nuclear Regulatory Commission Washington, DC 20555-0001

SUBJECT: PETITION PURSUANT TO 10 CFR 2.206, RIVER BEND STATION

Dear Mr. Callan:

The Union of Concerned Scientists submits this petition pursuant to 10 CFR 2.206 requesting that the River Bend Station be immediately shut down and its operating license suspended or modified until such time that the facility's design and licensing bases are properly updated to permit operation with failed fuel assemblies or until all failed fuel assemblies are removed from the reactor core.

Background

On April 2, 1998, UCS provided the Nuclear Regulatory Commission with a copy of our report titled "Potential Nuclear Safety Hazard / Reactor Operation with Failed Fuel Cladding." We concluded:

UCS considers nuclear plants operating with fuel cladding failures to be potentially unsafe and to be violating federal regulations.

NRC Daily Event Report No. 34815 dated September 21, 1998, provided the following information about an event notification received from the River Bend Station licensee:

The licensee notified the Louisiana Department of Environmental Quality of a possible defect in fuel cladding. The notification is required by plant procedures. The possible clad defect was identified by the offgas pretreatment radiation monitor. The monitor is located upstream of offgas treatment equipment and indicated a small increase from 80 to 100 millirem per hour followed by a subsequent rise to about 300 millirem per hour. The level since then has been slowly decreasing.

There has been no measurable increase in radioactive releases from the blant and radioactive releases remain well below the limits of the technical requirements manual and 10CFR20. Plant personnel are implementing site procedures to address the issue and taking appropriate actions.

On September 22, 1998, UCS reviewed the latest Updated Final Safety Analysis Report (UFSAR) available in the NRC's Public Document Room and confirmed that the generic concerns documented in our April 1998 report appear to apply to the River Bend Station.

9811040223 981029 PDR ADOCK 05000-58 G PDR

 Washington Office:
 1616 P Street NW Suite 310
 Washington DC
 20036-1495
 202-332-0900
 # FAX:
 202-332-0905

 Cambridge Headquarters:
 Two Brattle Square
 + Cambridge MA
 02238-9105
 • 617-547-5552
 • FAX:
 617-864-9405

 California Office:
 2397
 Shattuck Avenue Suite 203
 • Berkeley CA
 94704-1567
 • 510-843-1872
 • FAX:
 510-843-3785

UFSAR Section 15A.2.8, "General Nuclear Safety Operational Criteria," stated:

The plant shall be operated so as to avoid unacceptable consequences.

UFSAR Table 15A.2-4, "Unacceptable Consequences Criteria Plant Event Category: Design Basis Accidents," defined 'unacceptable consequences' as follows:

- 4-1 Radioactive material release exceeding the guideline values of 10CFR100.
- 4-2 Failure of the fuel barrier as a result of exceeding mechanical or thermal limits.
- 4-3 Nuclear system stresses exceeding that allowed for accidents by applicable industry codes.
- 4-4 Containment stresses exceeding that allowed for accidents by applicable industry codes when containment is required.
- 4-5 Overexposure to radiation of plant main control room personnel.

The current operating condition at the River Bend Station apparently violates the spirit, if not the letter, of Criterion 4-2 since the fuel barrier has already failed, albeit to a limited extent. This UFSAR text does not accept a low level of fuel barrier failure based on meeting the offsite and onsite radiation protection limits. Integrity of the fuel barrier is an explicit criterion in addition to the radiation requirements.

UCS reviewed the UFSAR Chapter 15 description of accident analyses performed for the River Bend Station. UFSAR Section 15.1.1.4, "Barrier Performance," for the loss of feedwater heating event stated:

The consequences of this event do not result in any temperature or pressure transient in excess of the criteria for which the fuel, pressure vessel, or containment are designed; therefore, these barriers maintain their integrity and function as designed.

UFSAR Sections 15.1.2.4 for the feedwater controller failure – maximum event, 15.1.3.4 for the pressure regulator failure – open event, and 15.2.1.4 for the pressure regulator failure – closed event all contain comparable statements that barrier performance was not performed because the fuel remained intact.

These analyzed events appear to be valid only when the River Bend Station is operated with no failed fuel assemblies. Operation with pre-existing fuel failures (i.e., the current plant configuration) appear to be outside of the design and licensing bases for these design bases events.

UFSAR Section 15.4.2.5, "Radiological Consequences," for the control rod withdrawal error at power event stated:

An evaluation of the radiological consequences was not made for this event since no radioactive material 1s released from the fuel.

UFSAR Section 15.4.5.5, "Radiological Consequences," for the recirculation flow control failure with increasing flow event stated:

An evaluation of the radiological consequences is not required for this event since no radioactive material is released from the fuel.

These analyzed events also appear valid only when the River Bend Station is operated with no failed fuel assemblies. Operation with pre-existing fuel failures (i.e., the current plant configuration) appear to be outside of the design and licensing bases for these design bases events.

The effect from pre-existing fuel failures was considered, at least partially, for one design bases event. UFSAR Section 15.2.4.5.1, "Fission Product Release from Fuel," for the main steam isolation valve closure event stated:

.

While no fuel rods are damaged as a consequence of this event, fission product activity associated with normal coolant activity levels as well as that released from previously detective rods is released to the suppression pool as a consequence of SRV [safety relief valve] actuation and vessel depressurization.

The aforementioned design bases events (e.g., control rod withdrawal error at power, loss of feedwater heating, et al) are <u>not</u> bound by these results because the radioactive material is not "scrubbed" by the suppression pool water as it is in the MSIV closure event.

As detailed in UCS's April 1998 report on reactor operation with failed fuel cladding, it has not been demonstrated that the effects from design bases transients and accidents (i.e., hydrodynamic loads, fuel enthalpy changes, etc.) prevent pre-existing fuel failures from propagating. It is therefore possible that significantly more radioactive material will be released to the reactor cociant system during a transient or accident than that experienced during steady state operation. Thus, the existing design bases accident analyses for River Bend Station do not bound its current operation with known fuel cladding failures.

In addition to operating with non-bounding design bases accident analyses, it appears that the River Bend licensee is also violating its licensing basis for worker radiation protection. UFSAR Section 12.1.1, "Policy Consideration," stated:

The purpose of the ALARA [as low as is reasonably achievable] program is to maintain the radiation exposure of plant personnel as far below the regulatory limits as is reasonably achievable.

UFSAR Section 12.1.2.1, "General Design Considerations for ALARA Exposures," stated that River Bend's efforts to maintain in-plant radiation exposure as low as is reasonably achievable included:

Minimizing radiation levels in routinely occupied plant areas and in vicinity of plant equipment expected to require the attention of plant personnel.

According to NRC Information Notice No. 87-39, "Control of Hot Particle Contamination at Nuclear Plants:"

A plant operating with 0.125 percent pin-hole fuel cladding defects showed a five-fold increase in wholebody radiation exposure rates in some areas of the plant when compared to a sister plant with high-integrity fuel (<0.01 percent leakers). Around certain plant systems the degraded fuel may elevate radiation exposure rates even more.

Industry experience demonstrated that reactor operation with failed fuel cladding increased radiation exposures for plant workers. The River Bend licensee has a licensing basis requirement to maintain radiation exposures for plant workers as low as is reasonably achievable. The River Bend licensee informed the NRC about potential fuel cladding failures. It could shut down the facility and remove the failed fuel assemblies from the reactor core. Instead, it continues to operate the facility with higher radiation levels.

Since it appears that operation with one or more failed fuel assemblies is not permitted by its design and licensing bases, River Bend must be immediately shut down. The facility must remain shut down until:

□ The River Bend licensee removes the failed ... 1 assemblies from the reactor core.

- OR -

The River Bend licensee properly updates the plant's design and licensing bases to permit the plant to operate with known fuel damage.

September 25, 1998 Page 4 of 4

Basis for Requested Action

UCS is a non-profit, public-interest organization with sponsors across the United States, including Louisiana. UCS monitors performance at nuclear power plants in the United States against safety regulations promulgated by the NRC to protect the public and plant workers. When real or potential erosion of mandated safety margins is detected, as is currently indicated at this time at River Bend, UCS engages the NRC, the media, and other authorities to resolve the safety concerns.

Requested Actions

UCS petitions the NRC to require the River Bend Station to be immediately shut down and that the facility remain shut down until all of the failed fuel assemblies are removed from the reactor core. Alternatively, the plant could be restarted after its design and licensing bases were properly updated to reflect continued operation with failed fuel assemblies.


UCS respectfully requests a hearing on this petition to present new information on reactor operation with failed fuel assemblies. This new information will include, but is not limited to, a discussion of the April 1998 UCS report and the plant-specific information regarding River Bend. While our concerns apply to River Bend, we respectfully request that this hearing be held in the DC area since the issue affects all operating nuclear power plants.

Sincerely,

mico Rahlan

David A. Lochbaum Nuclear Safety Engineer

enclosure: "Potential Nuclear Safety Hazard / Reactor Operation with Failed Fuel Cladding," April 22, 1998



The Union of Concerned Scientists has identified a potential safety hazard at nuclear power plants that operate with small cracks and holes in the metal tubing, also called cladding, containing their fuel. The fuel cladding is a vital barrier between highly radioactive materials and the environment. From a review of available documentation, UCS concludes that federal regulations require this barrier to be intact during plant operation. There is a good reason for these regulations – the public cannot be harmed as long as the fuel cladding remains intact. If it is not intact, radioactivity will be released to the plant and the environment. Such a release could affect the health of plant workers and members of the public. In addition, fuel rods with degraded cladding may break apart during an accident and prevent safety equipment from functioning. Despite these potentially serious consequences, nuclear plants routinely operate with defective fuel cladding. In fact, many, if not all, nuclear plants have operated with damaged fuel cladding.

UCS recommends that the Nuclear Regulatory Commission (NRC) enforce federal regulations which prohibit nuclear plants from operating with defective fuel cladding. These regulations allow the NRC to permit nuclear plants to operate with defective fuel cladding, but only when their owners establish acceptable boundaries based on studies of both normal operating and accident conditions. Until these safety concerns are resolved, UCS considers nuclear plants operating with fuel cladding failures to be potentially unsafe and to be violating federal regulations.

Background

The following sections discuss: design and licensing bases requirements for nuclear plants; their specific application to nuclear fuel design; the use of multiple barriers in protecting the public; the role of the fuel cladding as a barrier; the experience with fuel cladding failures, and the potential safety hazards from fuel cladding failures.

Design and Licensing Bases Requirements

Design and licensing bases requirements establish safe operating boundaries which are supported by extensive safety analyses. Operating within the boundaries provides reasonable assurance that the public will be protected if there is an accident. The safety or danger of operating outside the boundaries has not been analyzed. As a result safety margins may be compromised when boundaries are crossed, increasing the risk to the public. Therefore, federal regulations do not permit plants to operate in unanalyzed conditions.

Fuel Design

Nuclear plant are powered by fuel rods which contain uranium dioxide pellets roughly the size and shape of a large pencil eraser stacked within 12 to 14 feet long metal tubes sealed at each

end with welded metal caps.¹ A simplified drawing of a fuel rod is shown in Figure 1. The fuel tubes are also called the fuel cladding. Fuel cladding is like the gas tank in a car – if the tank is breached, highly volatile gasoline can spill out to threaten the safety of its passengers and innocent bystanders, as well as degrading the environment. When fuel cladding is breached, highly radioactive material spills out to threaten the safety of plant workers and the public.

All operating US nuclear power plants use fuel assemblies containing square arrays of fuel rods. A typical fuel assembly is illustrated in Figure 2. As shown in this figure, the fuel rods must remain intact to provide the overall structural integrity of the fuel assemblies. The fuel design bases ensure that "the fuel is not damaged as a result of normal operation and anticipated operational occurrences." ² The phrase "not damaged," as used by both the NRC and nuclear plant owners, means that the fuel rods are not damaged to the point where they would fail.³ Thus, the fuel design bases includes the explicit requirement that fuel cladding remains intact during normal operation.

Defense-in-Depth Barriers

The splitting, or fissioning, of uranium atoms in the fuel rods releases energy that heats water – nuclear energy that powers the plant. Byproducts of the fission process include radioactive gases and solids. Plutonium is also produced by the nuclear reactions. These radioactive materials emit gamma rays along with alpha and beta particles which can cause damage to the human body. The fuel cladding keeps the radioactive materials contained. If the cladding is defective, radioactive materials will leak into the water which surrounds the cladding and keeps the fuel rods cooled. This water is contained within the reactor vessel and the piping connected to it, which form a second barrier to contain the radioactive materials. If the piping fails, contaminated water spills into the reactor containment building. The reactor vessel and its piping are located within a reactor containment building which forms a third barrier. Because the reactor containment building is not leak tight, it reduces, but does not eliminate, the possibility that radioactive material would escape. Figure 3 shows a simplified drawing of these three barriers.

Three barriers between the radioactive material and the environment imply that one barrier can be breached during plant operation leaving two intact barriers to protect the public. However, the safety analyses assume that all three barriers are intact prior to any accident. Let's assume the rupture of a pipe connected to the reactor vessel breaches one of the barriers. If the pipe rupture occurs when the fuel cladding is defective, then two of the barriers are breached. The remaining barrier, the reactor containment building, only reduces the amount of radioactive material released to the environment. Thus, all three barriers must be intact during plant operation for the public to be protected.

¹ Baltimore Gas & Electric Company, Calvert Cliffs Nuclear Plant Updated Final Safety Analysis Report, Section 3.3.2.1, "Fuel Rod Mechanical Design," and General Electric Company, "Licensing Topical Report / General Electric Standard Application for Reactor Fuel," NEDO-24011-A-4, January 1982.

² Nuclear Regulatory Commission, NUREG-0800, Standard Review Plan, Section 4.2, Fuel System Design.

³ Nuclear Regulatory Commission, NUREG-0800, Standard Review Plan, Section 4.2, Fuel System Design, and GPU Nuclear Corporation, Oyster Creek Nuclear Generating Station Updated Final Safety Analysis Report, Section 4.4.2, "Description of Thermal and Hydraulic Design of the Reactor Core."

The fuel cladding is the most important of the three barriers. If the fuel cladding remains intact, the other two barriers can completely fail and the public will still be protected. The intact fuel cladding contains the radioactive gases and solids and prevents them from being released to the atmosphere. The public cannot be harmed from a nuclear plant accident in which the fuel cladding remains intact. But, as the next section indicates, nuclear plants routinely operate with this vital barrier seriously degraded.

Fuel Cladding Failure Experience

Numerous fuel cladding failures from various causes have been reported over the years. For example, the water flowing through the reactor core has caused fuel rods to sway back and forth. In this situation, the fuel rods vibrate against the grid (shown in Figure 2) and damage the cladding. At other plants, debris in the reactor water, such as metal flakes from rusted piping, has lodged against the grid. The friction from the vibration of this debris damaged the cladding. Another failure mode results when fuel pellets expand faster than the fuel rod cladding (see Figure 1) as their temperatures increase. The expanding pellets stretch the cladding, sometimes until it cracks or splits. Finally, the welds holding the upper and lower end plugs to the fuel rod cladding (see Figure 1) have sometimes been defective, causing pinhole leaks or even cracks to form. Other failure modes have been experienced too. Many, if not all, nuclear plants have experienced fuel cladding failures during their lifetimes. Few plants have shut down early to remove failed fuel rods.

Leaking fuel rods are detected by increased radioactivity levels in the reactor vessel's liquid and gaseous releases.⁴ Not surprisingly, the radioactivity levels rise significantly when fuel cladding fails. The causes of fuel cladding failures cannot be determined until the plant is shut down and the leaking fuel rods examined.

The following reports illustrate recent fuel cladding failure incidents and include some serious events.

The Vermont Yankee plant recently operated with at least one failed fuel rod for many months.⁵ Its owners elected to operate with the leaker(s) until the plant's next scheduled refueling outage in the spring of 1998 rather than incur the cost of an unscheduled shut down.⁶ The Brunswick Unit 1 plant in North Carolina operated during 1997 with fuel cladding failures that its owners tolerated.⁷ The Surry plant in Virginia also operated in 1997 with failed fuel cladding.⁸ These incidents demonstrate that nuclear plants continue to operate with fuel cladding failures.

⁶ Vermont Yankee Nuclear Power Corporation, Presentation to Vermont State Nuclear Advisory Panel, December 3, 1997.

⁷ Johan Blok and Roger Asay, Centec XXI, "Pinpoint fuel leaks to improve nuclear economics," *Power*, January/February 1998.

⁴ Entergy Operations, River Bend Station Updated Final Safety Analysis Report, Section 4.2.4.2, "Online Fuel System Monitoring," and Section 11.5.2.2.1, "Main Steam Line Radiation Monitoring System."

⁵ Nuclear Regulatory Commission, Daily Event Report, DER No. 33152, October 28, 1997.

A few years ago, the owner of the Point Beach Nuclear Plant in Wisconsin reported a significant event in which "The fuel cladding was failed to the extent that fuel pellets could be seen through the hole in the clad. However, no pellets escaped from the rod." The fuel rod failure was detected when the radioactivity levels of the reactor water rose to a level that was "10 percent of that allowed by [Point Beach Nuclear Plant's operating license]."⁹ In other words, the plant's operating license would have allowed it to remain running with up to nine other similarly failed fuel rods. This event suggests that the restrictions on reactor water radioactivity levels are too high to prevent operation with gaping holes in fuel rod cladding.

At the Palisades plant in Michigan, three portions of a broken fuel rod were discovered in different parts of the reactor. One segment, nearly 5½ feet long, was missing about one-third of its fuel pellets. A second segment, 4½ feet long, and a third segment, 1½ feet long, appeared to contain all their fuel pellets.¹⁰ This event is disturbing because it highlights how fragile the cladding can become during normal operation. At Palisades, this fuel rod literally fell apart as it was being removed from the reactor core and radioactive material was lost, including highly toxic plutonium.

Fuel Cladding Failure Consequences

What is the safety threat from a nuclear plant operating with fuel cladding failures? The fact that many plants have operated for many years with failed fuel cladding could be taken to imply an acceptable safety record. However, that is not the case. That fact demonstrates, at most, that the public is protected with fuel cladding failures during normal plant operation. It does not provide any reason to believe that the public will be protected in the event of an accident. It also does not provide any reason to believe that nuclear workers will be protected during normal plant operation with failed fuel cladding.

What might happen if a nuclear plant with failed fuel cladding had an accident? A common accident scenario involves breaking a large pipe connected to the reactor vessel. Water and steam rush out of the reactor vessel through the broken pipe. The water flow in the reactor core, instead of flowing from the bottoms of the fuel assemblies to their tops, may flow across the fuel assemblies. This cross-flow 'pushes' the fuel rods to the side rather than towards the top. Cladding that is weakened may fail under this side force. The plant's response to the pipe break is to shut down. Control rods are automatically inserted into the reactor core to stop the fissioning process. Fuel rods which fail and shift out of their vertical alignment may prevent the insertion of control rods. The safety analyses assume that the control rods can be inserted and shut down the reactor. Can fuel cladding failures cause such problems during this accident scenario? No one knows. Pre-existing fuel cladding failures have not been considered in the

⁸ Nuclear Regulatory Commission, Inspection Report 50-280/97-10, December 15, 1997.

⁹ Wisconsin Electric Power Company, Licensee Event Report No. 85-002-01, "Failed Fuel Rod in Assembly H14, Point Beach Nuclear Plant Unit 1," May 19, 1986.

¹⁰ United States Nuclear Regulatory Commission, Information Notice 93-82, "Recent Fuel And Core Performance Problems In Operating Reactors," October 12, 1993.

safety analyses for this accident or any other accident. Yet, nuclear plants routinely operate with such fuel cladding failures.

What happens if fuel cladding failures increase the severity of nuclear plant accidents? Since plant safety analyses assume that fuel cladding is undamaged when accidents occur, the failures may cause more radioactivity to be released to the environment than has been previously considered. After all, a key barrier confining this highly radioactive material is already breached when the accident begins. Under no circumstances will less radioactivity be released. Thus, it is imperative from a public health standpoint that nuclear plants do not operate with fuel cladding failures unless safety analyses are performed which demonstrate that the consequence. from accidents under these conditions are acceptable.

Summary

The fuel cladding is the most important of the three barriers between highly radioactive material and the environment. As long as the fuel cladding remains intact, no nuclear plant accident can threaten public health and safety. Yet, nuclear plants routinely operate with damaged fuel cladding.

Safety analyses assume that the fuel cladding is intact when accident scenarios begin. Operation with pre-existing fuel cladding failures may mean that a nuclear accident will have more severe consequences than predicted by the invalidated safety analyses. Thus, UCS considers a nuclear plant operating with defective fuel cladding to represent an increased risk to the public.

The fuel design bases require the fuel cladding to remain intact during normal plant operation. Federal safety regulations require that plants operate within the boundaries established by their design bases. Therefore, UCS concludes that operating a nuclear plant with failed fuel cladding violates federal safety regulations.

See Attachment 1 for details of UCS's assessment of reactor operation with failed fuel cladding.

ALARA Issue

Nuclear plant owners are required by federal regulations to keep the release of radioactive materials "as low as reasonably achievable" (ALARA).¹¹ According to the NRC, "a plant operating with 0.125 percent pin-hole fuel cladding defects showed a general five-fold increase in whole-body radiation exposure rates in some areas of the plant when compared to a sister plant with high-integrity fuel (<0.01 percent leakers). Around certain plant systems the degraded fuel may elevate radiation exposure rates even more."¹² The "sister plants" were virtually identical because they were built at the same time by the same owner on the same site. The

¹¹ Title 10 of the Code of Federal Regulations, Sections 50.34a, "Design objectives for equipment to control releases of radioactive material in effluents – nuclear power reactors," and 50.36, "Technical specifications," and Title 10 of the Code of Federal Regulations, Part 50, Appendix I, "Numerical Cuides for Design Objectives and Limiting Conditions for Operation to Meet the Criterion "As Low As Reasonably Achievable" for Radioactive Material in Light-Water-Cooled Nuclear Power Reactor Effluents."

¹² United States Nuclear Regulatory Commission, Information Notice No. 87-39, "Control Of Hot Particle Contamination At Nuclear plants," August 21, 1987.

significant variation in radiation exposure rates is <u>not</u> due to thicker concrete or other design differences – it is due to the failed fuel cladding. UCS is troubled by this NRC evidence because it shows a significantly increased risk to nuclear plant workers at a facility operating with just 0.125 percent fuel cladding failures. Many plants consider it permissible to operate with eight times as many fuel cladding failures (up to 1.0% failures).

Fuel cladding defects release radioactive materials into the reactor water. The water carries them to all parts of the plant, contaminating equipment throughout the facility. Workers conducting equipment inspections and maintenance receive higher radiation exposures. Indeed, some plant workers have received radiation doses far greater than allowed by federal regulations from highly radioactive material released through fuel cladding defects.¹³

It is a well-documented fact that plant operation with defective fuel cladding significantly increases personnel exposures. Federal regulations requires nuclear plant owners to keep the release of radioactive materials as low as reasonably achievable. Therefore, it is both an illegal activity and a serious health hazard for nuclear plants to continue operating with fuel cladding damage.

Conclusions And Recommendations

Conclusions

It is UCS's considered opinion that existing design and licensing requirements do not allow plants to operate with known fuel cladding failures. In addition, federal regulations require formal NRC approval prior to any nuclear plant operating with fuel cladding failures. Such approval has neither been sought nor granted.

UCS's evaluation (see attachment 1) suggests that both the probability and consequences of postulated accidents may be increased when nuclear plants operate with pre-existing fuel cladding failures. Thus, operation with fuel cladding failures is a violation of federal regulations which represents a potential threat to public health and safety.

UCS's assessment was generic. Consequently, this conclusion does not explicitly apply to any operating plant. However, UCS's assessment identified the strong potential for operation with fuel cladding failures to be an illegal activity unless the plant's owners performed a plant-specific safety evaluation which established such operation as acroptable and the NRC has formally reviewed and approved this safety evaluation. Absent both of these conditions, it seems highly probable that any plant operating with fuel cladding failures is violating its design and licensing bases requirements, a condition not allowed by federal safety regulations. It further appears that such illegal operation may have serious safety implications. Finally, operation with fuel cladding damage also seems to violate the ALARA concept mandated by federal regulations, thus exposing plant workers to undue risk.

¹³ United States Nuclear Regulatory Commission, Information Notice No. 87-39, "Control Of Hot Particle Contamination At Nuclear plants," August 21, 1987.

UCS's research for this assessment did not locate any information which suggests that operation with failed fuel cladding has been previously evaluated pursuant to federal regulations. There is considerable documentation on fuel cladding failure events, on inspections of failed fuel rods, and on various fuel damage mechanisms. Despite extensive, focused efforts, UCS was unable to find any indication that the safety implications of plant operation with failed fuel cladding have been considered by the fuel vendors, the NRC, or nuclear plant owners. This non-existent data further reinforces UCS's conclusions that operation with failed fuel cladding has not been properly analyzed by the industry, has not been approved by the NRC, and is both potentially unsafe and illegal.

Recommendations

UCS recommends that the Nuclear Regulatory Commission take appropriate steps to prohibit nuclear power plants from operating with fuel cladding damage until the safety concerns raised in this report are resolved. These appropriate steps include, but are not limited to, the following:

- Plant owners should be required to shut down their facilities upon detection of a fuel cladding failure. The plants must not restart until the failed fuel rods are removed.
- Plant owners should be required to evaluate the safety implications of operating with failed fuel cladding in accordance with federal regulations. If these safety evaluations are unable to justify continued operation, the plants should be shut down.

For the long term resolution of the safety concerns raised in this report, UCS recommends that the Updated Final Safety Analysis Reports (UFSARs) be revised. These revisions would establish safe boundaries for operation. After these boundaries are drawn and incorporated into the UFSARs, plants could continue to operate with failed fuel cladding as long as the failures remained within the previously analyzed region. If the amount of failed fuel cladding exceeded the boundaries, then the plant should face the options recommended above.

Unreviewed Safety Question Assessment

1 .

This attachment contains UCS's evaluation for reactor operation with failed fuel cladding. Our evaluation applied federal regulations for determining when a proposed mode of operation crosses the plant's authorized boundaries and thus requires prior NRC approval. As the results clearly indicate, reactor operation with failed fuel cladding requires NRC approval. Yet, such approval has neither been sought nor granted.

The NRC issues an operating license for a nuclear power plant after reviewing its design and procedures. The plant's owners may modify the facility and revise its procedures as long as the changes do not alter the bases for the NRC's approval of the operating license. A change which alters the operating license bases is called an unreviewed safety question (USQ). For example, a proposed change that reduces the plant's safety margin is an unreviewed safety question because the NRC may have relied on the greater margin in granting the plant's operating license. Likewise, a proposed change that maintains the existing safety margin but does so by operator actions instead of automatic equipment operation is also an USQ because the NRC's approval may have relied on the automatic protective features. When a proposed change involves an USQ, NRC approval must be obtained in advance. Federal regulations specify that a proposed change involves an USQ if:

- the probability of occurrence or the consequences of an accident or malfunction of equipment important to safety previously evaluated in the safety analysis report may be increased; or
- (2) a possibility for an accident or malfunction of a different type than any evaluated previously in the safety analysis report may be created; or
- (3) the margin of safety as defined in the basis for any technical specification is reduced.¹⁴

Federal regulations require nuclear plant owners to obtain NRC permission prior to conducting any activity for which the answer to one or more of these questions is anything but "NO." As UCS's nuclear safety engineer, I reviewed publicly available documentation to determine if these criteria are satisfied for plants operating with fuel cladding failures. Prior to joining UCS, I worked in the nuclear industry for over 17 years where I developed, reviewed, and assessed literally thousands of USQ determinations.

I divided the first criterion above into the "probability" and "consequences" elements for clarity. The scope of this evaluation was limited to four types of documentation: 1) the Updated Final Safety Analysis Reports (UFSARs) for four of UCS's focus plants (the Calvert Cliffs plant in Maryland, the Oyster Creek plant in New Jersey, the River Bend plant in Louisiana, and the Millstone Unit 3 plant in Connecticut); 2) the non-proprietary version of the fuel design topical report submitted by a vendor (General Electric); 3) the standard technical specifications prepared by all four reactor manufacturers (Westinghouse, General Electric, Babcock & Wilcox, and

¹⁴ Title 10, "Energy," of the Code of Federal Regulations, Section 50.59, "Changes, tests and experiments,"

Combustion Engineering); and 4) NRC correspondence on fuel cladding failure events. The results from this evaluation follow.

• Criterion 1a: May the probability of occurrence of an accident or malfunction of equipment important to safety previously evaluated in the safety analysis report be increased by operation with failed fuel cladding?

The standard technical specifications prepared by Westinghouse, General Electric, Combustion Engineering, and Babcock & Wilcox (vendors for all of the plants operating in the United States) specify that "The fuel cladding must not sustain damage as a result of normal operation."¹⁵ The NRC considers fuel cladding to be damaged when its integrity is lost.¹⁶ The detection of fission products *outside* the fuel rods is irrefutable evidence that fuel cladding integrity has been lost.

The standard technical specifications are the templates from which individual plant operating licenses were derived. Since these specifications establish zero defects as the minimally acceptable standard, operation with fuel cladding failures increases the probability of "malfunction of equipment important to safety," namely the fuel itself, to 100%. For this reason alone, the answer to this question is <u>YES</u>.

To apply the above generic assessment to a specific plant, UCS looked at available documentation for the Oyster Creek Nuclear Generating Station in New Jersey. A design basis for Oyster Creek is "to ensure that no fuel damage will occur in normal operation or operational transients caused by reasonable expected single operator error or equipment malfunction."¹⁷ Fuel rod damage "is defined as a perforation of the cladding which would permit the release of fission product to the reactor coolant."¹⁸ Thus, the detection of failed fuel rod(s) at Oyster Creek would be an equipment malfunction placing the plant outside its design basis. Again, the answer to this question is <u>YES</u>.

A fuel cladding defect may allow gases within a fuel rod to leak out. A defect may also allow water to leak in. It appears that leakage in either direction may also increase the probability that the fuel cladding will not perform its necessary safety function.

¹⁵ Babcock & Wilcox Company, Standard Technical Specifications, Section B 2.1.1., "Reactor Core SLs," Combustion Engineering, Standard Technical Specifications, Section B 2.1.1, "Reactor Core SLs," General Electric Company, BWR/4 Standard Technical Specifications, Section B 2.1.1, "Reactor Core SLs," and Westinghouse Electric Corporation, Standard Technical Specifications, Section B 2.1.1, "Reactor Core SLs," and Westinghouse

¹⁶ Nuclear Regulatory Commission, NUREG-0800, Standard Review Plan, Section 4.2, "Fuel System Design."

¹⁷ GPU Nuclear Corporation, Oyster Creek Nuclear Generating Station Updated Final Safety Analysis Report, Section 4.4.1, "[Thermal and Hydraulic Design] Design Basis."

¹⁸ GPU Nuclear Corporation, Oyster Creek Nuclear Generating Station Updated Final Safety Analysis Report, Section 4.4.2, "Description of Thermal and Hydraulic Design of the Reactor Core."

A fuel cladding defect which allows gases to leak out of a fuel rod has at least two potentially adverse consequences. The fuel rods are pressurized with helium during their fabrication to minimize a problem called cladding creep-collapse. The pressure inside a nuclear plant ranges from 960 to ~ 100 pounds per square inch at full power. The difference between a fuel rod's external pressure and internal pressure can exert sufficient inward force to cause the cladding to fill the gaps between fuel pellets.¹⁹ The stress on the cladding can cause it to break. The leakage of helium from a fuel rod reduces its internal pressure, thus potentially increasing the probability of fuel rod damage from cladding creep-collapse.

Inadequate cooling of the fuel is another potential consequence from gases leaking out of a fuel rod. Helium is used to pressurize fuel rods because of its high thermal conductivity.²⁰ The leakage of helium through a fuel cladding defect may slow down the transfer of heat from the fuel to the water. When heat cannot be dissipated from the fuel as quickly as assumed, the fuel temperature will increase and may reach the point at which it begins to melt. The leakage of helium from a fuel rod may reduce heat transfer rates, thus potentially increasing the probability that the fuel is seriously damaged during a loss-of-coolant accident.

A fuel cladding defect which allows water to leak into a fuel rod also has at least two potentially adverse consequences. During plant operation, high fuel temperatures prevent water from leaking in through a cladding defect. However, water can enter defects when the plant is shut down and cause fuel rods to become waterlogged. If the plant increases power quickly, the rising fuel temperature may cause the water inside the fuel rods to evaporate and perhaps even boil. The water vapor and steam produced inside the fuel rods, unless it is able to leak out through the defects, increase their pressure. This pressure buildup is suspected to have caused the "bursting" of fuel rods at the Point Beach plant in Wisconsin. Sections of the cladding and several fuel pellets could not be located when the damaged assemblies were later inspected.²¹

There is another potential adverse consequence from water leaking into fuel rods. The high operating temperature dissociates the water into hydrogen and oxygen gases. The hydrogen gas interacts with the cladding to form blisters. The blisters embrittle the cladding, leading to perforations.²² To minimize the moisture content, the fuel pellets are dried p. or to being loaded

¹⁹ Baltimore Gas & Electric Company, Calvert Cliffs Nuclear Plant Updated Final Safety Analysis Report, Section 3.7.1.1.a, "Clad Creepdown/Creep-Collapse."

²⁰ Baltimore Gas & Electric Company, Calvert Cliffs Nuclear Plant Updated Final Safety Analysis Report, Section 3.3.2.1, "Fuel Rod Mechanical Design."

²¹ B. Siegel, Nuclear Regulatory Commission, "Evaluation of the Behavior of Waterlogged Fuel Rod Failures in LWRs," NUREG-0303, March 1978.

²² Baltimore Gas & Electric Company, Calvert Cliffs Nuclear Plant Updated Final Safety Analysis Report, Section 3.7.2.1, "Burnable Poison Rod Design Evaluation."

into the fuel rods.²³ Thus, water leaking into a fuel rod may increase the probability that fuel cladding suffers this type of damage, which is called hydriding.

In fact, failure propagation due to hydriding has already been identified. Recent inspections of failed fuel rods at the Salem plant in New Jersey, the Beaver Valley plant in Pennsylvania, and the Wolf Creek plant in Kansas revealed that, "In some of the affected assemblies, secondary hydriding a' o was evident."²⁴ A fuel rod at the Perry Nuclear plant in Ohio experienced a cladding crack measuring 20 inches long, or nearly 13% of the fuel rod's length, caused by secondary hydriding.²⁵ In these events, the initial fuel cladding failures were caused by other mechanisms. These failures later propagated due to hydriding.

Thus, operation with fuel cladding failures has the potential for increasing the probability that an important barrier protecting the public, namely the fuel cladding itself, fails to adequately confine radioactive materials during a postulated accident. The fuel cladding is considered "equipment important to safety." A fuel cladding failure is therefore a malfunction of equipment important to safety. For this reason, too, the answer to this criterion is <u>YES</u>.

Finally, the NRC's Standard Review Plan states that the fuel design bases ensure that "fuel damage is never so severe as to prevent control rod insertion when it is required." ²⁶ Nuclear plant operation with failed fuel cladding has caused individual fuel rods to break into segments during fuel handling evolutions. If degraded fuel cladding were to similarly break during an accident, the fuel rod segments might interfere with control rod insertion. Thus, for this additional reason, the answer to this criterion is <u>YES</u>.

• Criterion 1b: May the consequences of an accident or malfunction of equipment important to safety previously evaluated in the safety analysis report be increased by operation with failed fuel cladding?

The NRC reported that the nuclear fuel's design bases are intended to "provide assurance that the fuel system is not damaged as a result of normal operation. 'Not damaged,' as used in the above statement, means that fuel rods do not fail. Fuel rod failure is defined as the loss of fuel rod [integrity]."²⁷ Thus, the fuel system, including the fuel cladding, must remain undamaged during normal operation.

²³ Baltimore Gas & Electric Company, Calvert Cliffs Nuclear Plant Updated Final Safety Analysis Report, Section 3.3.2.1, "Fuel Rod Mechanical Design, and Nuclear Regulatory Commission, NUREG-0800, Standard Review Plan, Section 4.2, "Fuel System Design."

²⁴ United States Nuclear Regulatory Commission, Information Notice 93-82, "Recent Fuel And Core Performance Problems In Operating Reactors," October 12, 1993.

²⁵ United States Nuclear Regulatory Commission, Information Notice 93-82, "Recent Fuel And Core Performance Problems In Operating Reactors," October 12, 1993.

²⁶ Nuclear Regulatory Commission, NUREG-0800, Standard Review Plan, Section 4.2, Fuel System Design.

²⁷ Nuclear Regulatory Commission, NUREG-0800, Standard Review Plan, Section 4.2, "Fuel System Design"

The safety analysis for the recirculation flow control failure with increasing flow event²⁸ at the River Bend Station in Louisiana concluded that "An evaluation of the radiological consequences is not required for this event since no radioactive material is released from the fuel."²⁹ If this event were to occur with pre-existing fuel cladding failures, this analysis would be rendered invalid. Since this analysis assumes that the fuel cladding remains intact, its conclusions are invalidated when there are fuel cladding failures.

The safety analysis for the feedwater controller failure maximum demand event³⁰ at River Bend concludes that fuel and pressure vessel "barriers maintain their integrity and function as designed."³¹ Obviously, this analysis's conclusion is invalidated when the plant operates with pre-existing fuel cladding failures.

The safety analysis for the rod withdrawal error event³² at River Bend specifies that "An evaluation of the barrier performance was not made for this event since this is a localized event with very little change in the gross core characteristics."³³ Fuel cladding damage is a localized event. The failed fuel rod has a pinhole leak or a hairline split in its cladding or a cracked weld at its end cap. If the rod withdrawal error occurs in the vicinity of the fuel cladding defect, the big change in local characteristics could propagate that defect. Thus, this analysis's conclusion is invalidated when the plant operates with a fuel rod defect.

The safety analysis for a control element assembly ejection event³⁴ at the Calvert Cliffs Nuclear Plant concluded that "the site boundary [radiological] dose guidelines will be approached." ³⁵

³⁰ This potential accident is similar to the recirculation flow control failure with increasing flow event in that too much water to the reactor core results in an uncontrolled power increase.

³¹ Entergy Operations, River Bend Station Updated Final Safety Analysis Report, Section 15.1.2.4, "[Feedwater Controller Failure Maximum Demand] Barrier Performance."

³² This potential accident involves the inadvertent withdrawal of a control rod causing the power produced by the adjacent fuel assemblies to increase significantly.

³³ Entergy Operations, River Bend Station Updated Final Safety Analysis Report, Section 15.4.2.4, "[Rod Withdrawal Error] Barrier Performance."

³⁴ This potential accident is comparable to car engine throwing one of its pistons. The piston may break the engine casing. Likewise, the ejected control element assembly may break the reactor coolant pressure boundary and allow reactor water to leak out.

³⁵ Baltimore Gas & Electric Company, Calvert Cliffs Nuclear Plant Updated Final Safety Analysis Report, Section 14.13.2, "Sequence of Events [Control Element Assembly Ejection]."

²⁸ This potential accident is comparable to a mistake using a bellows to flame a wood fire. If too much air is supplied, the fire may blaze up out of control. Likewise, putting too much water through the River Bend reactor core can cause it to run out of control.

²⁹ Entergy Operations, River Bend Station Updated Final Safety Analysis R/ port, Section 15.4.5.5, "[Recirculation Flow Control Failure with Increasing Flow] Radiological Consequences."

The analysis found the postulated event acceptable because the plant's design features "will prevent fuel clad failure, will prevent exceeding the [reactor coolant system] Pressure Upset Limit, and will therefore limit the radiological site boundary dose [i.e., the radiation levels experienced by a member of the public at the plant's fence] to below the criteria in 10 CFR 100 guidelines." ³⁶ Since this analysis assumes that fuel cladding failures are prevented, its conclusions are invalidated when there are pre-existing fuel cladding failures.

The NRC's Standard Review Plan states that the fuel design bases ensure that "the number of fuel rod failures is not underestimated for postulated accidents." ³⁷ Yet, the previous accident analyses underestimated the number of fuel rod failures if those plants operated with fuel cladding failures. Thus, the answer to this criterion is <u>YES</u>.

The Wolf Creek plant recently experienced fuel cladding failures affecting 44 fuel rods in three fuel assemblies. According to an NRC report on the problem, "The most severely degraded fuel rod fragmented into three segments during fuel handling operations while offloading the core."³⁸ Fuel handling operations include removing a fuel assembly from the reactor core, placing it in a device called an upender, lowering the assembly to a horizontal position, transferring it through the reactor containment wall into the fuel handling building, raising the assembly to a vertical position, and moving it to a storage location in the spent fuel pool. These manipulations put dead load force (i.e., gravity) on the fuel assembly and its fuel rods. Fuel assemblies are designed to withstand the force associated with these handling evolutions, at least when their fuel cladding is undamaged. Apparently at Wolf Creek, the force of gravity was sufficient to cause the structural failure of a fuel rod with previously damaged cladding.

What if an accident occurred when the fuel assemblies with the damaged cladding still resided in the reactor core? For example, consider the hydrodynamic forces inside the reactor vessel following a break of a large pipe connected to it. The high energy water escaping through the break exerts considerable force. The side force on the fuel rods may approach, or even exceed, the dead load force during fuel handling. The weakened fuel cladding may experience structural failure as was encountered during fuel handling. Fuel rod structural failure could have very serious consequences during an accident. The dislodged fuel rod segments could interfere with the insertion of control elements attempting to shut down the reactor. Fuel assemblies are tightly packed into the reactor vessel. The clearance between fuel assemblies and control elements is fractions of an inch at most. Fuel rod segments would not have to move much in order to interfere with control elements. Thus, the consequences of previously analyzed accidents could be increased by operation with fuel cladding failures. The answer to this criterion is YES.

³⁶ Baltimore Gas & Electric Company, Calvert Cliffs Nuclear Plant Updated Final Safety Analysis Report, Section 14.13.4, "Conclusion [Control Element Assembly Ejection]."

³⁷ Nuclear Regulatory Commission, NUREG-0800, Standard Review Plan, Section 4.2, Fuel System Design.

³⁸ United States Nuclear Regulatory Commission, Information Notice 93-82, "Recent Fuel And Core Performance Problems In Operating Reactors," October 12, 1993.

• Criterion 2: May the possibility for an accident or malfunction of a different type than any evaluated previously in the safety analysis report be created by operation with failed fuel cladding?

After residing in the reactor core for one or more cycles of operation, fuel assemblies are moved to the spent fuel pools. "Spent" fuel assemblies continue to generate considerable amounts of heat and release deadly amounts of radiation for many years. The worst-case spent fuel pool accident is typically assumed to be a fuel handling event. The analysis for this event assumes that a fuel assembly is dropped onto another fuel assembly.³⁹ Fuel rods in both assemblies are assumed to fail to evaluate the radiological consequences of the event. The spent fuel pools are also analyzed for possible damage resulting from an earthquake. These analyses generally assume that no fuel damage occurs as long as the fuel storage racks remain structurally intact.

Some spent fuel pool accident analyses take credit for operation of the spent fuel building's ventilation system. This system routes the building's exhaust air through filters, thus lowering the radiological dose to the public. At many plants, the ventilation system only performs this safety function when fuel handling operations are underway.

Spent fuel assemblies with cladding failures may have those failures propagate when subjected to earthquake forces. Radioactive gases released from spent fuel assemblies following an earthquake may cause radiological consequences which exceed those for the fuel handing event if (a) the inventory from more than the fuel rods in two assemblies is released, or (b) credit is taken in the fuel handling event analysis for operation of the spent fuel building's ventilation system but the system is unavailable. Consequently, the answer to this criterion is MAYBE.

• Criterion 3: May the margin of safety as defined in the basis for any technical specification be reduced by operation with failed fuel cladding?

The standard technical specifications prepared by Westinghouse, General Electric, Combustion Engineering, and Babcock & Wilcox (vendors for <u>all</u> of the operating plants in the United States) specify that "The fuel ciadding must not sustain damage as a result of normal operation and [anticipated operational occurrences]."⁴⁰ The NRC considers fuel cladding to be damaged when its integrity is lost.⁴¹ The detection of fission products *outside* the fuel rods is irrefutable evidence that fuel cladding integrity has been lost.

³⁹ Baltimore Gas & Electric Company, Calvert Cliffs Nuclear Plant Updated Final 'Jafety Analysis Report, Section 14.18.2, "Method of Analysis [Fuel Handling Accident]."

⁴⁰ Babcock & Wilcox Company, Standard Technical Specifications, Section B 2.1.1., "Reactor Core SLs," Combustion Engineering, Standard Technical Specifications, Section B 2.1.1, "Reactor Core SLs," General Electric Company, BWR/4 Standard Technical Specifications, Section B 2.1.1, "Reactor Core SLs," and Westinghouse Electric Corporation, Standard Technical Specifications, Section B 2.1.1, "Reactor Core SLs," and Westinghouse

⁴¹ Nuclear Regulatory Commission, NUREG-0800, Standard Review Plan, Section 4.2, "Fuel Systers Design."

The standard technical specifications are the templates from which individual plant operating licenses are derived. Since these specifications establish zero defects as the minimally acceptable standard, operation with fuel cladding failures clearly represents a safety margin reduction. Consequently, the answer to this question appears is <u>YES</u>.


Conclusion

.

Federal regulations specify that an unreviewed safety question is indicated when the answer to any one of the criteria is non-negative. UCS's assessment determined that none of the answers is negative. Three of the answers are unequivocally YES and a fourth is MAYBE. Thus, nuclear power plant operation with failed fuel cladding is clearly an unreviewed safety question. NRC approval is required for a plant to continue operating with fuel cladding failures.

Performed by: ____ 04-02-98 David A. Lochbaum


Nuclear Safety Engineer




April 2, 1998

. .

...





DISTRIBUTION: Docket File PD4-1 r/f CHawes RFretz

October 29, 1998

| MEMORANDUM TO: | Rules and Directives Branch Division of Administrative Services Office of Administration | | | | | |
|----------------|------------------------------------------------------------------------------------------------|--|--|--|--|--|
| FROM: | Office of Nuclear Reactor Regulation | | | | | |
| SUBJECT: | ENTERGY OPERATIONS, INC RIVER BEND STATION | | | | | |

One signed original of the Federal Register Notice identified below is attached for your transmittal to the Office of the Federal Register for publication. Additional conformed copies (Five) of the Notice are enclosed for your use.

Notice of Receipt of Application for Construction Permit(s) and Operating License(s). Notice of Receipt of Partial Application for Construction Permit(s) and Facility License(s): Time for submission of Views on Antitrust matters. Notice of Consideration of Issuance of Amendment to Facility Operating License. (Call with 30-day insert date). Notice of Receipt of Application for Facility License(s); Notice of Availability of Applicant's Environmental Report; and Notice of Consideration of Issuance of Facility License(s) and Notice of Opportunity for Hearing. Notice of Availability of NRC Draft/Final Environmental Statement. Notice of Limited Work Authorization. Notice of Availability of Safety Evaluation Report. Notice of issuance of Construction Permit(s). Notice of Issuance of Facility Operating License(s) or Amendment(s). Order. Exemption. Notice of Granting Exemption. Environmental Assessment. Notice of Preparation of Environmental Assessment. Receipt of Petition for Director's Decision Under 10 CFR 2.206. Issuance of Final Director's Decision Under 10 CFR 2.206. Other:

DOCKET NO. 50-458

Attachment(s): As stated

Contact: R. Fretz Telephone: 415-1324

DOCUMENT NAME: RBG980502.GRN

| | y of this document, yindicate in the box: | "C" = Copy wi | thout attachment/enclo | sture "E" = Cop | y with attachment/onclosure | "N" = No copy |
|--------|-------------------------------------------|---------------|------------------------|-----------------|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| OFFICE | LA/PU4-1/ Stude | | | | | T |
| | | | | | | and the second se |
| DATE | 10/30/98 | | | | | |

OFFICIAL RECORD COPY