NRC Fornt 366								E EVE	NT RE	PORT	(LER)		U.S. NUCLEAR REQULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES 8/31/88						
FACILIT	NAME	1)	-	_	-								DOCKET NUMBER	(2)		PA	GE (3)		
	VOGT	LE		UNI	T 1								0 5 0 0	101	41214	1 OF	014		
TITLE (4							-								71617	-	1017		
100	USE	OF	IM	PRO	PER	TOOL L	EADS TO	CONTA	INMEN	T VENT	TILATI	ON ISOLA	TION						
EVI	ENT DAT	_			-	ER NUMBER		-	PORT DATE	-			FACILITIES INVO	LVED	8:				
MONTH	DAY	YE	LA	YEAR		SEQUENTIA	L REVISION	MONTH	DAY	YEAR		PACILITY NA	MES	роск	ET NUMBE	R(\$)			
						1	1						0 1	51010	101	1 1			
		l				1								_					
0 9	0 7	8	8	8	8	0, 2	6 0 0	10	0 6	8 8				0 1	5 10 10	101	1 1		
OPE	RATING			THIS	REPORT	T IS SUBMITT	ED PURSUANT	TO THE R	EQUIREME	NTS OF '0	CFR 9 10	theck one or more	of the following) it	11	-		-		
Mo	DOE (9)		1		20.4021	6)		20.406	e)		X	50.73(a)(2)(iv)			73,71(6)				
	POWER 20.408(a)(1)(i)				50.36(e)	(1)			5J.73(a)(2)(v)		73.71(e)								
(10)	(10) 11 010 20.40%(a)(1)(H)			50.38(e)(2) 50.73(e)(2)(v)						OTHER Specify in Absorber									
	· variable same	demand with			20.40614	H116m)		50.73(4)	(2)(i)			50.73(a)(2)(viii)	(A)		366A)	in Text, NR	C Form		
			1		20.406 (4	11(1)(iv).		80.73(4)	(2)(0)			50 13(a)(2)(viii)	(8)	1					
					20 406 1	(1) (1) (v)		50.73(p)	(2)(111)			50.72(a)(2/(x)							
	-	-	-		-		· ·	ICENSEE	CONTACT	FOR THIS	LER (12)								
NAME									-					TELE	PHONE NUM	RBBN			
													AREA CODE	T					
J.	E. Sw	vart	ZW	e1d	er,	Nuclea	r Safety	and	Comp1	iance	Manag	er	4 014	8	2 6 -	13 16	1118		
				-			THE RESERVE AND ADDRESS OF THE PARTY OF THE		THE RESERVE OF THE PERSON NAMED IN	CHARLESTON, WA		D IN THIS REPO	AT (13)				-		
CAUSE	CAUSE SYSTE A COMP					REPORTABLE TO NARDS			CAUSE	SYSTEM	COMPONENT	MANUFAC TURER	R E	PORTABLE O NPROS					
		-		-	-		1			_	-		-	-	-				
	1	1	1	1		1 1 1		100				1 1 7	1 1 1 1						
	-		-			-	-	-		1			-	-	-	-			
	1	1	1	1		1 1 1					1	1-1-1	1111						
		-		-	-	SUPPLEM	ENTAL REPORT	EXPECTE	D (14)	-			-	-	MONT	H DAY	YEAR		
		-		-	-	_			-	-			EXPECT SUBMISS	ION			+		
YES	111 yes c	omp#	w EX	PECTE	10 svæ	MISSION DAT	(B)		X NO				DATE	5)		1	1		

On 9/7/88, an electrician was in the process of reinstalling shorting bars into fuse holders following the completion of an electrical switch replacement. At 1257 CDT, the electrician unintentionally created a short between two 120 volt AC circuits. Various alarms and indicators actuated, including those for a Containment Ventilation Isolation (CVI). The appropriate CVI valves and dampers actuated. Control room personnel verified that no abnormal radiation condition existed by observing redundant monitors. The control room personnel and the electrician immediately notified each other and confirmed that the electrical short had initiated the CVI.

The cause of this event is the use of an improper tool by the electrician. Fuse pullers provided to the electrician would not fit between the inserted shorting bars, so he used needle-nose pliers to perform the insertions. These pliers made the electrical short by simultaneously contacting two shorting bars following one shorting bar's insertion. Appropriate personnel will be advised to avoid the use of needle-nose pliers or makeshift tools for installation of fuses or shorting bars. Also, the proper size fuse-pullers will be made available.

9810120176 881006 FDR ADOCK 05000424 FDC PDC

ABSTRACT (Limit to 1800 spaces, i.e. approximately fifteen single space typewritten lines) (18)



A. REQUIREMENT FOR REPORT

This report is required per 10 CFR 50.73(a)(2)(iv) because an unplanned actuation of an Engineered Safety Feature occurred.

B. UNIT STATUS AT TIME OF EVENT

At the time of this event, Unit 1 was in Mode 1 (power operations) at 100% rated thermal power. There was no inoperable equipment which contributed to the occurrence of this event.

C. DESCRIPTION OF EVENT

On 9/7/88, an electrician was in the process of reinstalling shorting bars into fuse holders following the completion of an electrical switch replacement. The fuse holders are located in the Balance of Plant (BOP) Safety Actuation Cabinet in the main control room. At 1257 CDT, the electrician unintentionally created a short between two 120 volt AC circuits.

This initiated various alarms:

- (1) 480 Volt Non-1E switchgear alarm
- (2) 120 volt Ac panel trouble alarm
- (3) Inverter trouble alarm
- (4) 4160 Volt 1E switchgear trouble alarm
- (5) Sequencer trouble alarm(6) Pressurizer level alarm
- (7) Radiation monitor trouble alarm
- (8) 1RE-0003 area radiation monitor high alarm
- (9) Containment Ventilation Isolation (CVI) indicating lights

The appropriate CVI valves and dampers actuated. Control room personnel verified that no abnormal radiation condition existed by observing redundant monitors. The control room personnel and electrician had previously discussed the possibility of problems created by the electrician's cramped working conditions and immediately notified each other confirming that the electrical short had initiated the CVI. Recovery from the CVI was complete at 1330 CDT. The various other indications and alarms, which were also found to be caused by the electrical short, were reset.

LICENSEE EVE	LICENSEE EVENT REPORT (LEH) TEXT CONTINUATION												
PACILITY NAME (1)	OOCKET NUMBER (2)		LE	R NUMBER (6)			*	AGE ()	30				
		YEAR		SEQUENTIAL		NEVISION NUMBER		П					
VOGTLE - UNIT 1	0 15 10 10 10 1 41 21 4	010		01216		010	01.3	OF	0.14				

TEXT IN more space is equired, use additional NIRC Form 398.4 (s) (17)

D. CAUSE OF EVENT

The direct cause of this event is the electrical short which led to a momentary loss of power to 1RE-0003, resulting in a high radiation alarm and a CVI.

0 15 10 10 10 1 41 21 4 818 - 012 16 - 010 013 OF 014

The root cause of this event is the use of an improper tool by the electrician. Fuse pullers provided to the electrician would not fit between the inserted shorting bars, so he used needle-nose pliers to perform the insertions. These pliers made the electrical short by simultaneously contacting two shorting bars following one shorting bar's insertion.

Contributing to this event were the cramped conditions surrounding the fuse holders. Although the electrician had successfully inserted three shorting bars without incident, the tight quarters which he encountered were a hindrance to the completion of his task.

E. ANALYSIS OF EVENT

No actual high radiation condition existed at the time of the event as shown by the redundant radiation monitors. The valves and dampers receiving the CVI signal actuated to their correct positions. Based on these considerations, it is concluded that there was no adverse effect on plant safety or public health and safety as a result of this event.

F. CORRECTIVE ACTIONS

- Appropriate personnel will be advised to avoid the use of needle-nose pliers or makeshift tools for installation of fuses or shorting bars and to contact their foreman if the occasion arises. They will also be instructed to exercise extreme care when working in cramped conditions. These guidance sessions are expected to be complete by 10/31/88.
- 2. Proper-size fuse pullers will be obtained and are scheduled to be available for use by 12/1/88.

(9-43)	LICENSEE EVENT REPORT (LER) TEXT CONTINUATION													APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88							
FACILITY NAME (1)		Ox	OCK E	TN	UMBE	A (2)					LE		MBER	(8)				AGE	r	_	
										YFAR		540	UENT	AL		REVISION NUMBER					
VOGTLE - UNI	T 1		0 5 0 0	0	4	2	4	8 8	_	0	121	6	- 010	014	OF	0 1	14				

EXT (If more space is required, use additional NRC Form 366A's) (17)

G. ADDITIONAL INFORMATION

1. Failed Components

None

2. Previous Similar Events

No previous ESF actuations have occurred as a result of the use of improper tools.

3. Energy Industry Identification System Code:

Containment Isolation Control System - JM

Radiation Monitoring System - IL

Reactor Coolant System - AB

4160 Volt IE Switchgear System - EB

480 Volt Non-IE Switchgear System - EC

120 volt AC power supply system - EF

Georgia Power Company 333 Piedmont Avenue Atlanta, Georgia 30108 Telephone 404 526 2526 Mailing Address: Post Office Bux 4545 Atlanta, Georgi (3)302 W. G. Hairston, III Senior Vice President Nuclear Operations

the southern electric system.

NON-00344

October 6, 1988

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D. C. 20555

> PLANT YOGTLE - UNIT 1 NRC DOCKET 50-424 OPERATING LICENSE NPF-68 LICENSEE EVENT REPORT USE OF IMPROPER TOOL LEADS TO CONTAINMENT VENTILATION ISOLATION

Gentlemen:

In accordance with the requirements of 10 CFR 50.73, Georgia Power Company hereby submits a Licensee Event Report (LER) concerning a Containment Ventilation Isolation.

Sincerely,

W. S. Hot In W. G. Hairston, III

TEW: dmh

Enclosure: LER 50-424/1988-026

c: Georgia Power Company Mr. P. D. Rice Mr. G. Bockhold, Jr Mr. M. Sheibani Mr. J. P. Kane

GC-NORMS Vogtle/NCRMS

U. S. Nuclear Regulatory Commission Dr. J. N. Grace, Regional Administrator Mr. J. B. Hopkins, Licensing Project Manager, NRR (2 copies) Mr. J. F. Rogge, Senior Resident Inspector - Operations, Vogtle