AVERAGE DAILY UNIT POWER LEVEL

Docket No. 50-272
Unit Name Salem # 1
Date April 10,1986
Telephone609-935-6000
Extension 4455

Completed by Pell White

Month	March 1986			
Day A	(MWe-NET)	Day A	verage Daily Power L (MWe-NET)	evel
1	1037	17	804	
2	1041	18	1008	
3	937	19	954	
4	1022	20	978	
5	1042	21	822	
6	1038	22	0	
7	1012	23	0	
8	1035	24	0	
9	1041	25	0	
10	1046	26	0	
11	1033	27	0	
12	1053	28	0	
13	1045	29	0	
14	1045	30	0	
15	779	31	0	
16	930			

P. 8.1-7 R1

8604170566 860331 PDR ADOCK 05000272 R PDR IE24

OPERATING DATA REPORT

Docket No.50-272
Date April 10, 1986
Telephone 935-6000
Extension 4455

Completed by Pell White

Operating Status

1. 2. 3. 4. 5. 6. 7. 8.		s MWe) 1124 MWe) 1079	Notes 3 through 7) sin N/A	nce Last
9.	Power Level to Which Restricted,	if any (Net	MWe) N/A	
10.	Reasons for Restr ctions, if any		N/A	
		This Month	Year to Date	Cumulative
11.	Hours in Reporting Period	744	2160	76729
	No. of Hrs. Reactor was Critical	502.2	1834.0	46019.4
	Reactor Reserve Shutdown Hrs.	0.0	0.0	3088.4
	Hours Generator On-Line Unit Reserve Shutdown Hours	502.0	1763.2	44268
	Gross Thermal Energy Generated (MWH)	1572262	5651424	136135453
17.	Gross Elec. Energy Generated			130103433
	(MWH)	518360	1872860	45168870
	Net Elec. Energy Generated (MWH) Unit Service Factor	494697	1790381	42895873
	Unit Availability Factor	67.5	81.6	57.7
	Unit Capacity Factor			
2	(using MDC Net) Unit Capacity Factor	61.6	76.8	51.8
	(using DER Net)	61.0	76.0	51.3
23.	Unit Forced Outage Rate	0	8.1	28.0
4.	Shutdowns scheduled over next 6 m	months (type	, date and dura	tion of each
	N/A			

26. Units in Test Status (Prior to Commercial Operation):

	Forecast	Achieved
Initial Criticality	9/30/76	12/11/76
Initial Electricity	11/1/76	12/25/76
Commercial Operation	12/20/76	6/30/77

8-1-7.R2 Page of

UNIT SHUTDOWN AND POWER REDUCTIONS REPORT MONTH MARCH 1986

Docket No.50-272 Unit Name Salem No.1 April 10,1986 Date Telephone 609-935-6000 Extension 4455

Completed by Pell White

No.	Date	Type	Duration Hours	Reason 2	Method of Shutting Down Reactor	License Event Report	System Code 4	Component Code 5	Cause and Corrective Action to Prevent Recurrence
86-278	0303	F	8.9	D	5	-	RC	ZZZZZZ	Core Tilt Restrictions
86-330	0315	F	0.3	A	5	-	НС	HTEXCH	Loss of Vacuum/High Back Pressure
86-332	0315	F	0.2	А	5		нс	HTEXCH	Loss of Vacuum/High Back Pressure
86-336	0315	F	12.5	A	5		нс	HTEXCH	Loss of Vacuum/High Back Pressure
86-348	0317	F	2.7	В	5		нс	HTEXCH	Conenser Tube Fouling
86-350	r317	F	5.7	В	5	1 2 11	нс	нтехсн	Conenser Tube Fouling
86-380	0321	S	1.0	С	5	-	RC	ZZZZZ	Core Coastdown Nuclear
86-382	0321	s	1.0	С	5	_	RC	ZZZZZ	Core Coastdown Nuclear
86-384	0321	S	1.0	С	5	-	RC	ZZZZZ	Core Coastdown Nuclear
86-386	0321	S	242.0	С	1	-	RC	ZZZZZ	Nuclear Normal Refueling

F: Forced S: Scheduled 2 Reason A-Equipment Failure-explain B-Maintenance or Test C-Refueling D-Regulatory Restriction E-Operator Training & Licensing Exam F-Administrative G-Operational Error-explain H-Other-explain

3 Method 1-Manual 2-Manual Scrain. 3-Automati Scram, tion of Data 4-Continuation of Entry Sheets Previous Outage for Licensee 5-Load Reduction 9-Other

4 Exhibit G Instructions Salem as for Prepara-Event Report (LER) File (NUREG 0161)

5 Exhibit 1 Source

MAJOR PLANT MODIFICATIONS REPORT MONTH MARCH 1986

DOCKET NO.: 50-272

UNIT NAME: Salem 1

DATE: April 10, 1986

COMPLETED BY: J. Ronafalvy

TELEPHONE: 609/339-4455

*DCR NO.	PRINCIPAL SYSTEM	SUBJECT
1EC-0675	Fuel Handling Crane	Revise limit switch protection arrangement as necessary to comply with intent of No. 2 Unit outstanding item No. 047043.
1EC-1413	Reactor Coolant	Replacement of Reactor Coolant Wide Range RTD's with environmentally qualified elements.
1EC-1533	Bldg. & Equip. Drain; Flood & Sump Pumps	Change nuclear classification of containment sump pumps from Nuclear Class III to Non-Nuclear Safety.
1EC-1565	Chilled Water System CW Expansion Tank	Install a 10 psig relief valve at the Chilled Water Expansion Tank. Inspect and repair Nitrogen pressure reducing valve (1CH-147) by removing the bonnet.
1EC-1834	RVLIS	Perform the field modification as per Westinghouse Procedure No. NSID-EIS-83-16. Scope of this change is under Section 5 of this procedure which includes environmental/seismic qualification changes and human factors modifications.
1EC-1843	Neutron Flux Monit.	Install a non-safety related source range neutron flux monitor at the remote hot shutdown panel.

^{*} DCR - Design Change Request

MAJOR PLANT MODIFICATIONS (continued) REPORT MONTH MARCH 1986

*DCR NO.	PRINCIPLE SYSTEM	SUBJECT
1EC-1849	Main Steam	Install additional steam stop valve hydraulic control bypass valve trouble light on control/console for each of four valves 11-14MS167. Recently this condition hindered plant start-up on Unit #1.
1ED-0014	Radiation Monitoring	Add a new plant vent sampling system with appropriate readouts and control functions. Three monitors - particulate, iodine, and gaseous. 1-R41A,B,C.
1SC-0690	11-12-13 Chiller Cond. Recirc. Pump	Change shaft sleeve material from (316) stainless steel to monel.
1SC-0948	Waste Gas	Install two test connections on the Waste Gas System. Add one test connection between valves 1WG6 and 1WL99 on the vent header. Add the second test connection on the H.P. header downstream of valves 11WG22 and 12WG27. Locate both test connections in the Waste Gas System Valve Room.

^{*}DCR - Design Change Request

MAJOR PLANT MODIFICATIONS REPORT MONTH MARCH 1986

DOCKET NO.: 50-272

UNIT NAME: Salem 1
DATE: April 10, 1986
COMPLETED BY: J. Ronafalvy
TELEPHONE: 609/339-4455

*DCR	SAFETY EVALUATION 10CFR 50.59
1EC-0675	Installation of the new upper limit switch and other hardware on the Fuel Handling Building Crane will not affect the safe shutdown of the reactor nor will it create a new fire hazard. This design change does not involve changes to the FSAR or the Technical Specifications. This design change complies with NUREG 0612 requirements for upgrading cranes at operating nuclear power plants. No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.
1EC-1413	This design change involved a direct replacement of existing equipment. The system functions remain unchanged. No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.
1EC-1533	The Containment Sump Pumps are not part of a safety related system and do not affect the safe shutdown of the plant. They are not required to mitigate consequences of an accident. No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.
1EC-1565	The changes implemented via this design change do not jeopardize the pressure retaining boundary nor impact the operation of the basic design criteria of the Chilled Water System. The Chilled Water System is a closed loop system and therefore no environmental impact with this design change is involved. No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.

^{*} Design Change Request

*DCR	SAFETY EVALUATION 10CFR 50.59
1EC-1834	All potential realistic failure modes have been considered but are not applicable with this design change. This change will make the RVLIS system fully operable. No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.
1EC-1843	All potential, realistic failure modes have been considered. The monitor is non-safety related, however, a safety related power source provides power for the non-safety related neutron flux monitoring system. Electronic isolation of the distribution panel is provided by the panel feeder breaker and the NIS source range monitor panel. The installation of the source range neutron flux monitor instrument at the remote shutdown panel represents an enhancement of the capability of the station to safely shut down the plant in the event of a fire emergency. No plant process or dischage is affected by this design change. No unreviewed safety or environmental questions are involved.
1EC-1849	This design change does not affect the intended function of the Main Steam System. No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.
1ED-0014	The function of plant vent radiation monitoring is not changed by this design change. This change improves the monitoring capability by deleting shared monitors. This change does not alter the production or quantity of radioactive materials. No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.

^{*} Design Change Request

*DCR	SAFETY EVALUATION 10CFR 50.59
1SC-0690	The replacement sleeves are made of upgraded materials for the Chiller Condenser Water Recirculation Pumps. The change in sleeve material does not affect any previously performed safety analysis nor does it create any new safety hazards. The Tech. Spec. basis is not affected. The new sleeve will be less subject to corrosion, pitting and wearing out as are the present sleeves. No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.
1SC-0948	The addition of two test connections to the Waste Gas System will not impact the safe operation of the plant. The connections are to be used only for system testing and are to be blind flanged during system operation. Each test line will be normally isolated with a valve and a blind flange No plant process or discharge is affected by this design change. No unreviewed safety or environmental questions are involved.

^{*} Lesign Change Request

PSE&G SALEM GENERATING STATION SAFETY RELATED WORK ORDER LOG

WO NO	UNIT	EQUIPMENT IDENTIFICA	TION
8603040222	1	1200A GE 4KV CIRCUIT BREAKER	
		FAILURE DESCRIPTION:	BREAKER FAILED TO CLOSE IN THE CUBICLE AND AT THE TEST STATION. DR SMD-IE 86-059 HAS BEEN WRITTEN AGAINST THIS BREAKER.
		CORRECTIVE ACTION:	REPLACED MICRO ST, PERFORMED M3J, ALL SAT. IN- STALLED IN 1H6D 10SITION.
0099168316	1	#12 BAT	
		FAILURE DESCRIPTION:	SENSOR FOUND OUT OF CAL DURING A SENSOR CALIBRATION PROCEDURE.
		CORRECTIVE ACTION:	REPLACE OSCILLATOR IN TRANSMITTER; CALIBRATED AND RETURNED TO SERVICE. CALIBRATED AS PER 11C-2.9.001.
0099168413	1	VCT PRESSURE	
		FAILURE DESCRIPTION:	SENSOR FOUND OUT OF CALIBRATION DURING A SENSOR CAL PROCEDURE.
		CORRECTIVE ACTION:	CALIBRATED AS PER 1IC-2.9.024.

WO NO	UNIT	EQUIPMENT IDENTIFICAT	ION
0099168413	1	VCT PRESS FAILURE DESCRIPTION:	SENSOR FOUND OUT OF CALIBRATION DURING A SENSOR CALIBRATION PROCEDURE.
		CORRECTIVE ACTION:	CALIBRATED AS PER 1IC-2.9.024
0099180090	1	STRAINER EATIURE DESCRIPTION:	STRAINER HAS A BROKEN SHEAR KEY.
		CORRECTIVE ACTION:	REPLACED STRAINERS-REPLACED SHEAR KEY AND REPLACED BARREL DISTRIBUTORS.
0099180561	1	11SW223	
		FAILURE DESCRIPTION:	11 FAN COIL UNIT FLOW CONTROL VALVE HAS A SEVERE SW LEAK WHERE VALVE BODY IS BOLTED TO PIPING. BOLTS ON FLANGE WERE TIGHT. PROCEDURE.
		CORRECTIVE ACTION:	REPLACED BOTTOM GASKET ON 11SW223.

WO NO	UNIT	EQUIPMENT IDENTIFICAT	ION	
8504110541	1	FLANGE ORIFICE/11SJ37&38		
		FAILURE DESCRIPTION:	FLONGE IS HEAVILY CORRODED WITH CRYSTALIZED BORIC ACID AND IS LEAKING.	
		CORRECTIVE ACTION:	REPLACED GASKETS.	
8510221197	1	12MS10 CONTROL VALVE		
		FAILURE DESCRIPTION:	REPACK WITH CHESTERTON PACKING ALSO VALVE LEAKS THRU.	
		CORRECTIVE ACTION:	DISASSEMBLED, INSPECTED, CLEANED, REPLACED PISTON RINGS, REPLACED GASKET, BLUE CHECKED, REASSEMBLED & REPACKED WITH CHESTERTON PACKING.	
8511010106	1	LOW TURB. LOAD		
		FAILURE DESCRIPTION:	RECEIVED "LOW LOAD TURB. TRIP REQUIRED" ALARM ON THE CONTROL ROOM BEZEL. THERE IS NO SIGNAL THAT SHOULD GIVE US THAT ALARM.	
		CORRECTIVE ACTION:	WIRE IN TP-14-1 2-2-U LIFTED LANDED 2-2-U. RE- CEIVED A GROUND ON 1-A-125V BUS, LIFTED LEAD 2-2-U AS PER SS INSTRUCTIONS.	

WO NO	UNIT	EQUIPMENT IDENTIFICA	TION
8512260181	1	#12 WGC RECIRC VALVE	
		FAILURE DESCRIPTION:	12WG22 ON #12 WASTE GAS COMPRESSOR IS NOT CONTROLLING VALVE: STAYS FAILED OPEN AND COMPRESSOR TRIPS OUT ON FIVE MINUTE TIMER FOR DISCHARGE PRESSURE BEING LESS THAN 25 PSIG.
		CORRECTIVE ACTION:	FOUND FLAPPER/NOZZLE IN CONTROLLER BADLY PITTED AND WORN. REPLACED AND REALIGNED CONTROLLER. FUNCTIONALLY CHECKED CONTROLLER/ VALVE ACTION BY VARYING SETPOINT.
8602130511	1	12 ACCUM LEVEL CHANNEL B	
		FAILURE DESCRIPTION:	THE HI/LO LEVEL ALARM IS ILLUMINATED, ALTHOUGH THE ACTUAL LEVEL IS SATISFACTORY.
		CORRECTIVE ACTION:	CHECKED TRANSMITTER VOLTAGE FOR CAPABILITY WITH INDICATION.
8602220235	1	11A & 11B STARTING	
		AIR COMPRESSOR	
		FAILURE DESCRIPTION:	THE AIR COMPRESSOR DOES NOT START IN THE AUTO MODE.
		CORRECTIVE ACTION:	REPLACED PD 6476.

WO NO	UNIT	EQUIPMENT IDENTIFICA	TION
8602261063	1	#1SW OVERPRESSURE PROTECTION	
		FAILURE DESCRIPTION:	VALVE DID NOT OPEN WITH FOUR SW PUMPS IN SERVICE AND HEADER PRESSURE AT 150#.
		CORRECTIVE ACTION:	VERIFIED OPERATION OF VALVE & POSITIONER VERIFIED CONTROLLER IS OPERATING CONNECTLY FOUND SETPOINT AT 144 PSI AND RESET AT 135 PSI. CALIBRATED TRANSMITTER.
3602261071	1	JACKET WATER HI TEMP	
		FAILURE DESCRIPTION:	WHILE RUNNING DIESEL RECIEVED THE JACKET WATER HIGH TEMPERATURE ALARM. SET POINT FOR ALARM IS 175 DEG.F, THE ACTUAL TEMPERATURE AT THAT TIME WAS 165 DEG.F.
		CORRECTIVE ACTION:	RECALIBRATED ALL OF THE ABOVE TEMP DEVICES.
8603031193	1	15 SW PUMP STRAINER	
		FAILURE DESCRIPTION:	THE 15 SERVICE WATER PUL'P STRAINER HAS A 45 LB DIFF AND THE MOTER SMELLS LIKE IT IS BURNT UP.
		CORRECTIVE ACTION:	REPLACED TRANSFORMER IN CONTROL CIRCUIT. DIFF AT 6 STAINER SHUT OFF IN AUTO AT ABOUT 4 PSI DIFF.

NO NO	UNIT	EQUIPMENT IDENTIFICA	1 LUN
8603100233	1	ROD POSITION IND. FAILURE DESCRIPTION: CORRECTIVE ACTION:	PLEASE CHECK THE CAL ON THE ROD POSITION IND. SA-I&C 490 WAS FOUND OUT OF CAL ON THE A.C. RANGE. CALIBRATED SIGNAL CONDITION MODULE AND
			POSITION INDICATOR. FOUND INSPEC.
8603100241	1	ROD POSITION IND.	
			PLEASE CHECK THE CAL ON THE ROD POSITION INDICATION SA-1&C 490 WAS OUT OF CAL ON THE AC RANGE.
		CORRECTIVE ACTION:	CALIBRATED SIGNAL CONDITION MODULE AND POSITION INDICATOR.
8603100373	1	1R13E MONITOR	
		FAILURE DESCRIPTION:	1R13E OBSERVED FAILED.
		CORRECTIVE ACTION:	FOUND CONDENSATE MOSITURE ON THE DETECTOR AND PREAMP. CLEANED ALL COMPONENTS AND REMOVED HV ARCH ON PREAMP CONNECTOR BASE. RETURNED TO SERVICE.
8603120188	1	# 1 UNIT POWER RANGE	
		FAILURE DESCRIPTION:	TWO OUT OF SPEC. READINGS FOUND WHILE DOING THE CHANNEL CAL. CHECK (1PD16.3007) THE OUT OF SPECS. WERE 1) NR41 OUT BY 2% AT THE BOTTOM. 2 LOWER FLUX OUT IN THE MIDDLE BY .012 VDC.
		CORRECTIVE ACTION:	MADE ADJUSTMENTS AND TOOK AS LEFT DATA.

O NO	UNIT	EQUIPMENT IDENTIFICA	TION
3603130124	1	11CV160 CONTROL VALVE FAILURE DESCRIPTION:	THE CAL ON THE ROD POSITION INDICATION SA-1&C 490 WAS OUT OF CAL ON THE AC RANGE.
		CORRECTIVE ACTION:	CALIBRATED SIGNAL CONDITION MODULE AND POSITION INDICATOR.
8603170134 1 #1 UNIT SPARE RECORDER		#1 UNIT SPARE RECORDE	R
		FAILURE DESCRIPTION:	#1 UNIT SPARE RMS RECORDER FOUND IN RACK #75 DOES NOT APPEAR TO BE FUNCTIONING CORRECTLY.
		CORRECTIVE ACTION:	PRINT WHEEL MISSING, FOUND WHEEL MISSING SCREW, REPLACED AND RETURNED TO SERVICE.
8603180032	1	RMS	
		FAILURE DESCRIPTION:	LOCAL RMS R-41E GOOD READING, OPERABLE. CONTROL ROOM MONITOR FAILED.
		CORRECTIVE ACTION:	CLEARED RAMS RELOADED SETPTS. VERIFIED TRAIN A&B TRIPS & VLV CLOSURE.
8603200548	1	CONT DIFF PRESS INSTE	
		FAILURE DESCRIPTION:	METER FOR CONT DIFF PRESS IS HANGING UP AT A SLIGHT POSITIVE PRESSURE. DOES NOT REDUCE WHEN PERFORMING PRESSURE RELIEF. SUSPECT TRANSMITTER PROBLEM THIS INDICATION IS NECESSARY FOR UPCOMING OUTAGE PURGES.
		CORRECTIVE ACTION:	FOUND TRANSMITTER OUTPUT SLIGHTLY HIGH FOR ACTUATOR CONTAINMENT BAROMETRIC PRESS.

WO NO	UNIT EQUIPMENT IDENTIFICATION
8603230072	1 1SA118 FAILED LRT
	FAILURE DESCRIPTION: VALVE FAILED LEAK RATE TEST.
	CORRECTIVE ACTION: DISASSEMBLED & CLEANED VALVE, BLUE CHECK 100% REASSEMBLED VALVE & REPACKED WITH JOHN CRANE 187-I PACKING (7 RINGS).

SALEM GENERATING STATION MONTHLY OPERATING SUMMARY - UNIT NO. 1 MARCH 1986

SALEM NO. 1

The Unit began the period operating at 97% power. Between 3/15/86 and 3/17/86, river grasses and debris caused a series of circulating water problems. Load reductions were performed as necessary to maintain condenser vacuum. On 3/22/86 at 2158 hours, the Unit was removed from service and commenced the sixth refueling cutage. Major work to be done this outage includes refueling, leak rate test of the Type "C" Containment Isolation Valves, 11E, 12E, and 13W MSR HP tube bundle replacement, valve replacements, valve repackings (as required), upgrade of the connectors on the Control Rod Drive mechanisms, and other miscellaneous maintenance and inspection work. The Unit remained in Mode V (Cold Shutdown), until 0715 hours, on 3/28/86, when the reactor vessel head studs were detensioned and Mode VI (Refueling), was entered. The reactor vessel head was lifted on 3/30/86. As of this report, the Unit remains in Mode VI with outage work continuing and on schedule.

REFUELING INFORMATION

COME	TELEF	NO.: 50-272 NAME: Salem 1 DATE: April 10, 1986 HONE: 609/935-6000 SION: 4455		
Mont	th March 1986			
1.	Refueling information has changed from YES NO X			
2.	Scheduled date for next refueling:M	arch 22, 1986		
3.	Scheduled date for restart following re	fueling: May 20, 1986		
4.	A) Will Technical Specification changements be required? YES NOX	es or other license		
	B) Has the reload fuel design been re Operating Review Committee? YES X NO If no, when is it schedu			
5.	Scheduled date(s) for submitting propose N/A	ed licensing action:		
6.	Important licensing considerations asso	ciated with refueling:		
7.	Number of Fuel Assemblies:			
	A) Incore B) In Spent Fuel Storage	193 296		
8.	Present licensed spent fuel storage cap	acity:1170		
	Future spent fuel storage capacity:	1170		
9.	Date of last refueling that can be discharged to spent fuel pool assuming the present licensed capacity: September 20			
	나타내다 가는 보고 있어? 네티워 보고 하게 되는 것 같아.			

8-1-7.R4



Public Service Electric and Gas Company P.O. Box E. Hancocks Bridge, New Jersey 08038

Salem Generating Station

April 10, 1986

Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

Dear Sir:

MONTHLY OPERATING REPORT SALEM NO. 1 DOCKET NO. 50-272

In compliance with Section 6.9, Reporting Requirements for the Salem Technical Specifications, 10 copies of the following monthly operating reports for the month of March 1986 are being sent to you.

Average Daily Unit Power Level
Operating Data Report
Unit Shutdowns and Power Reductions
Major Plant Modification
Safety Related Work Orders
Operating Summary
Refueling Information

Sincerely yours,

J. M. Zupko, Jr.

General Manager - Salem Operations

JR:kcb

Cc: Dr. Thomas E. Murley
Regional Administrator USNRC
Region I
631 Park Avenue
King of Prussia, PA 19406

Director, Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Enclosures 8-1-7.P4 JE24