

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) **Oconee Nuclear Station, Unit 1** DOCKET NUMBER (2) **0 5 0 0 0 2 6 9 1** PAGE (3) **1 OF 0 5**

TITLE (4) **Vent Gaseous Radiation Monitor IRIA-45 Removed From Service During Refueling Operations**

| EVENT DATE (5) | | | LER NUMBER (6) | | | REPORT DATE (7) | | | OTHER FACILITIES INVOLVED (8) | | |
|----------------|-----|------|----------------|-------------------|-----------------|-----------------|-----|------|-------------------------------|--|--|
| MONTH | DAY | YEAR | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | MONTH | DAY | YEAR | FACILITY NAMES | | |
| 03 | 14 | 86 | 86 | 005 | 00 | 04 | 14 | 86 | N/A | | |
| | | | | | | | | | DOCKET NUMBER(S) | | |
| | | | | | | | | | 0 5 0 0 0 | | |
| | | | | | | | | | N/A | | |
| | | | | | | | | | 0 5 0 0 0 | | |

OPERATING MODE (9) **6** THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)

| | | | | |
|-------------------------------|-------------------|--|---------------------|--|
| POWER LEVEL (10) 0 0 0 | 20.402(b) | 20.406(a) | 50.73(a)(2)(iv) | 73.71(b) |
| | 20.406(a)(1)(i) | 50.38(a)(1) | 50.73(a)(2)(v) | 73.71(a) |
| | 20.406(a)(1)(ii) | 50.38(a)(2) | 50.73(a)(2)(vi) | <input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 366A) |
| | 20.406(a)(1)(iii) | <input checked="" type="checkbox"/> 50.73(a)(2)(i) | 50.73(a)(2)(vii)(A) | 50.72(b)(2)(iii) |
| | 20.406(a)(1)(iv) | 50.73(a)(2)(ii) | 50.73(a)(2)(vii)(B) | |
| | 20.406(a)(1)(v) | 50.73(a)(2)(iii) | 50.73(a)(2)(ix) | |

LICENSEE CONTACT FOR THIS LER (12)

NAME **Sandy G. Godwin, Licensing** TELEPHONE NUMBER **7 1 0 4 3 7 3 1 - 2 3 6 2**

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

| CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPROS | CAUSE | SYSTEM | COMPONENT | MANUFACTURER | REPORTABLE TO NPROS |
|-------|--------|-----------|--------------|---------------------|-------|--------|-----------|--------------|---------------------|
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) NO

EXPECTED SUBMISSION DATE (15)

| MONTH | DAY | YEAR |
|-------|-----|------|
| | | |

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On March 14, 1986, with Unit 1 shut down for refueling, the Vent Gaseous Radiation Monitor (IRIA-45) was removed twice from service in conjunction with repair work on the Vent Particulate Radiation Monitor (IRIA-43). Fuel was being moved in the Reactor Building (RB) at the same time. This violated the intention of Technical Specification 3.8.10 which requires IRIA-45 and the RB Purge System to be operable during refueling operations.

The discovery of IRIA-45 being out of service occurred at 2204 hours. The immediate corrective action was to stop fuel movement. IRIA-45 was placed back in service at 2334 hours after IRIA-43 was repaired and IRIA-45 and the RB Purge System were tested. Fuel handling resumed at 2335 hours. The health and safety of the public were not affected by this incident.

This incident is classified as Personnel Error because work was done on IRIA-43 without evaluating the possibility of IRIA-45 being affected.

B604210130 B60414
PDR ADOCK 05000269
S PDR

IE 22 1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | | |
|---|--|----------------|-------------------|-----------------|----------|----|-----|
| FACILITY NAME (1) Oconee Nuclear Station, Unit 1 | DOCKET NUMBER (2) 0 5 0 0 0 2 6 9 | LER NUMBER (6) | | | PAGE (3) | | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| | | 8 6 | - 0 0 5 | - 0 0 0 | 2 | OF | 0 5 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

BACKGROUND

The Reactor Building Purge System including radiation monitor IRIA-45 which initiates the purge isolation, is required by Technical Specifications to be operable prior to refueling operations. The proper functioning of these components is desired to prevent a significant release of fission productions if a fuel handling accident occurs.

Radiation monitor IRIA-45 monitors the Unit 1 Vent (stack) for low range gaseous radioactivity. It also has interlocks which automatically terminate the Reactor Building purge and close the purge isolation valves when radiation levels in the vent get high enough to cause IRIA-45 to alarm.

IRIA-43 detects air particles by monitoring a moving filter paper with a plastic beta scintillator. The filter paper is rolled out and taken up by an advance drive mechanism.

IRIA-45 is part of a Vent Radiation Monitor cabinet, along with three other monitors. All four monitors share a common sample nozzle off the Unit 1 Vent. A dual pumping system, driven by a single motor, is provided to supply continuous air samples to the monitors. One pump supplies air samples to a particulate monitor, IRIA-43. The second pump supplies air samples to a fixed charcoal filter that is monitored for iodine by IRIA-45 and IRIA-46, for normal and high radiation ranges, respectively. The motor for the pumps is normally turned off when performing maintenance on any of the four monitors, thus all would be out of service at that same time.

DESCRIPTION OF EVENT

On March 14, 1986, with Unit 1 shut down for refueling, a "Refueling Procedure" step which states:

"The Reactor Building Purge System, including the Radiation Monitor, IRIA-45, which initiates purge isolation, shall be tested and verified to be operable within 24 hours prior to refueling operations"

was performed.

All of the reactor operators and the senior reactor operator on the shift for this night were knowledgeable about this limit in the refueling procedure and about the Vent Radiation Monitor cabinet having a dual pump motor.

During this time, a work request was being performed, which sets the flow for the sample pumps on IRIA-32, -39, -41, -43, -47 and -48 at the RIA cabinets. At approximately 2020 hours, a low flow indication for IRIA-43

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | |
|---|-------------------------------------|----------------|-------------------|-----------------|----------|----|
| FACILITY NAME (1) Oconee Nuclear Station, Unit 1 | DOCKET NUMBER (2) 0500026986 | LER NUMBER (6) | | | PAGE (3) | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | |
| | | 86 | 005 | 00 | 03 | OF |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

tested before refueling operations resumed. Involved personnel were counseled concerning the event.

Planned corrective actions are:

All licensed reactor operators will review this incident investigation report for lessons learned and for the necessity of maintaining the limitations of the refueling procedure.

The standing work requests for setting the flow for RIA sample pumps (for RIAs 32, 39, 41, 43, 44, 47, 48), will be changed to add a precaution to not turn off any radiation monitor cabinet pump without getting clearance from Operations.

Appropriate personnel are evaluating a Technical Specification interpretation for all three nuclear stations that will address removing equipment from service for brief periods of maintenance when compensatory actions would be inappropriate.

A data base search of previous Incident Investigation Report lists 104 incidents in the category of "radiological significance". Only four of them involved a RIA being out of service during a release or purge to the Vent. A review of these reports found that RIA-45 has not been out of service during refueling operations; therefore, this incident is not recurring.

There were no abnormal radiation exposures or personnel injuries as a result of this incident.

CAUSE OF EVENT

The intent of Technical Specification 3.8, "Fuel Loading and Refueling", item 3.8.10, was violated twice on March 14, 1986, once for approximately four minutes and again for approximately one hour when IRIA-45 was taken out of service during refueling operations on Unit 1. In both cases the Unit 1 Assistant Shift Supervisor was aware that the RIA supply pump could be taken out of service. The root cause of these events is a cognitive error. Clearance was given for the Vent Particulate Radiation Monitor, IRIA-43, to be repaired without inquiring about what the repair work would do to the Vent Radiation Monitor cabinet. No one was informed of any limits or precautions concerning the Vent Gaseous Radiation Monitor, IRIA-45, that are in the refueling procedure. Therefore this incident is classified as Personnel Error.

Contributing causes to the event was the lack of communication between involved personnel. If all of the appropriate people had been aware of all that was going on, the event would have been avoided.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | |
|---|-----------------------------------|----------------|-------------------|-----------------|----------|----|
| FACILITY NAME (1) Oconee Nuclear Station, Unit 1 | DOCKET NUMBER (2) 05000269 | LER NUMBER (6) | | | PAGE (3) | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | |
| | | 86 | 005 | 00 | 04 | 05 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

was observed. It was suspected that the moving filter paper was clogged, so the Vent Radiation Monitor cabinet dual pump motor was turned off and the inlet and outlet valves from the Vent were valved closed. The IRIA-43 lid was lifted briefly, long enough to determine that a solenoid mechanism on the filter paper advance drive was malfunctioning. The Vent Radiation Monitor cabinet was valved back in and the dual pump motor was turned back on at approximately 2024 hours.

Appropriate personnel were notified that IRIA-43 was malfunctioning.

At approximately 2100 hours, work was started to repair IRIA-43. The Vent Radiation Monitor cabinet was turned off and valved out. At this time, a violation of the intent of Technical Specification 3.8.10 occurred because IRIA-45 was now out of service while fuel was being handled.

It was determined that the solenoid mechanism for the filter paper drive for IRIA-43 needed replacing. While the part was being obtained, a remote particulate sampler was set up at the Vent Radiation Monitor cabinet to cover IRIA-43 being out of service. The HP Specialist noticed that the pump was off. He went to the HP office to check on the sampling requirements for IRIA-44, -45 and -46. Meanwhile, a solenoid was replaced in IRIA-43. The drive mechanism still would not function properly, so it was determined that the problem was within the rack drive mechanism.

At 2204 hours, the Unit 1 Nuclear Control Operator (NCO) was notified that a remote particulate sampler was set up and that he would also provide the necessary sampling for IRIA-44, -45 and -46, also out of service. The NCO and the Senior Reactor Operator (SRO) in the control room, realizing IRIA-45 should not be out of service during fuel movement, notified the Refueling Supervisor and had fuel movement stopped. The SRO confirmed that IRIA-45 was out of service. The SRO was told that IRIA-45 would be returned to service in about 10 minutes, but IRIA-43 was not repaired. At approximately 2210 hours, the Vent Radiation Monitor cabinet was valved back in and the dual pump motor was turned back on. IRIA-43 was repaired at 2255 hours. The Vent Radiation Monitor cabinet was returned to service, including IRIA-43, -44, -45 and -46.

The Unit 1 NCO had written a priority one work request, to perform the functional test for IRIA-45 and the RB Purge Isolation. The test was completed at 2334 hours, and fuel handling resumed at 2335 hours.

CORRECTIVE ACTION

The immediate corrective action was to stop refueling operations to prevent the possibility of a fuel accident occurring without automatic Reactor Building purge isolation. The Vent Radiation Monitor cabinet was put back in service and the Reactor Building Purge Isolation System was functionally

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

| | | | | | | |
|---|--|----------------|-------------------|-----------------|----------|----------|
| FACILITY NAME (1) Oconee Nuclear Station, Unit 1 | DOCKET NUMBER (2) 0 5 0 0 0 2 6 9 | LER NUMBER (6) | | | PAGE (3) | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | |
| | | 8 6 | - 0 0 5 | - 0 0 | 0 5 | OF 0 5 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

SAFETY ANALYSIS

This incident of IRIA-45 being out of service rendered the automatic Reactor Building Purge Isolation System inoperable. If a fuel assembly did sustain some mechanical damage during refueling operations, a subsequent release of fission products would occur. The activity would be assumed to be released as a puff from the Unit Vent, because no vent or purge isolation was possible. The ONS FSAR Section 15.11.2.1, "Single Fuel Assembly Handling Accidents", states that the result of a conservative analysis performed for a fuel handling accident within the Reactor Building indicates that a 0.5 rem whole body and a 32 rem thyroid dose at the site boundary could occur. It also states that these values are well within the limits of 10 CFR 100. No radioactivity was released during this incident.

With the procedures and experience that ONS has, mechanical damage to the fuel assemblies during refueling operations is possible but improbable.

It is concluded that the health and safety of the public were not affected by this incident.

DUKE POWER COMPANY
P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

April 14, 1986

Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555


Subject: Oconee Nuclear Station, Unit 1
Docket Nos. 269, -270, -287
LER 269/86-05

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 269/86-05 concerning vent gaseous radiation monitor IRIA-45 being removed from service during refueling operations.

This report is submitted in accordance with §50.73(a)(2)(i) and 50.72 (b)(2)(iii). This event was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

SGG:slb

Attachment

xc: Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Ms. Helen Nicolaras
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE22
11

Document Control Desk

April 14, 1986

Page Two

xc: American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, New York 10020