

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) <b>OYSTER CREEK, UNIT 1</b>	DOCKET NUMBER (2) <b>050002119</b>	PAGE (3) <b>1 OF 03</b>
--	---------------------------------------	----------------------------

TITLE (4) **CONTAINMENT PARTICULATE MONITOR SAMPLE LINE ISOLATION VALVES - POTENTIAL FAILURE TO OPERATE DUE TO DESIGN DEFICIENCY**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
05	20	88	88	063	00	06	16	88			05000

OPERATING MODE (9) **N**

POWER LEVEL (10) **11010**

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.405(e)	<input type="checkbox"/> 50.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)
<input type="checkbox"/> 20.405(a)(1)(i)	<input type="checkbox"/> 50.38(e)(1)	<input type="checkbox"/> 50.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)
<input type="checkbox"/> 20.405(a)(1)(ii)	<input type="checkbox"/> 50.38(e)(2)	<input type="checkbox"/> 50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)
<input type="checkbox"/> 20.405(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	
<input type="checkbox"/> 20.405(a)(1)(iv)	<input checked="" type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)	
<input type="checkbox"/> 20.405(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME <b>Roger B. Gayley, Operations Engineer</b>	TELEPHONE NUMBER AREA CODE: <b>610</b> NUMBER: <b>997-11-49611</b>
---	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)  NO

EXPECTED SUBMISSION DATE (15)

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single-space typewritten lines) (16)

The plant's Containment Particulate Monitor sample line isolation valves' control circuitry does not meet single failure criteria as required by 10CFR50, Appendix A, General Design Criterion. This condition was determined reportable on May 20, 1988, while the plant was operating at rated output. The apparent cause of the condition is a design deficiency which has been present since the Containment Particulate Monitor was installed in 1976. This condition is significant in that it could place the plant outside its design basis containment leak rate during a design basis accident. A conservative analysis indicates that under the design basis loss of coolant accident with this single failure present, operators would have to diagnose and take corrective action within 6.7 hours to prevent exceeding 10% of the 10CFR100 limits. Direction by means of a standing order has been provided to operators to deenergize the power supply to close these valves upon a reactor low-low water level or a high drywell pressure alarm. Corrective action will be taken in accordance with the Integrated Living Schedule for the Oyster Creek plant.

8806280027 880616  
PDR ADOCK 05000219  
S PDR

1222  
11

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Oyster Creek, Unit 1	DOCKET NUMBER (2)  0   5   0   0   0   2   1   9	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8   8	-   0   0   3	-   0   0	0   2	OF	0   3

TEXT (If more space is required, use additional NRC Form 386A's) (17)

Date of Discovery

The condition was determined to be reportable on May 20, 1988. It has, however, existed since 1976 when the Containment Particulate Monitor was installed.

Identification of Occurrence

The control circuitry for Containment Particulate Monitor sample line isolation valves (V-38-9, V-38-10, V-38-16 and V-38-17) (EIS Code IP) does not meet single failure criteria as required by Nuclear Regulatory Commission General Design Criteria 21, 24, 54, and 56. This condition is considered reportable in accordance with 10CFR50.73(a)(2)(i)(B).

Conditions Prior to Occurrence

The plant was operating at rated thermal output generating approximately 650 MWe when the condition was determined to be reportable.

Description of Occurrence

A sample line connected to the drywell air space is connected to the plant's Containment Particulate Monitor (CPM) equipment. Isolation is provided by two isolation valves in series located in the CPM inlet sample lines (V-38-9, V-38-10) and outlet sample lines (V-38-16 and V-38-17). These valves are automatically closed upon receipt of a containment isolation signal. The existing control circuitry configuration allows a single failure to occur (i.e., a short circuit between the power feed and control wires) that could render the valves remotely inoperable and stuck in the open position.

This condition was first identified during January 1988 during engineering of a CPM modification. The engineer who identified the condition initiated a "Preliminary Safety Concern and Potential Licensee Event Evaluation" (PSC). A Licensing Action Item (LAI) was initiated as a result of the PSC. A preliminary determination was made on the LAI by the end of April 1988. A final determination on reportability was made on May 20, 1988.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)  Oyster Creek, Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 2 1 9	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		8 8	0 0 3	0 0	0 3	OF 0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Apparent Cause of Occurrence

The apparent cause of this occurrence is a design deficiency. Section 6.2.4.5 of the Oyster Creek Final Safety Analysis Report (FSAR) under "Design Evaluation of Isolation Valves" indicates that isolation valves and their associated electrical systems are designed to prevent common mode failures. The existing configuration could allow a short circuit between the power feed and control wires that would render all four isolation valves inoperable and stuck in the open position. The existing configuration is therefore not in compliance with the original plant design criteria.

Analysis of Occurrence and Safety Assessment

Containment isolation is provided to contain the reactor coolant thermal energy and fission products which could be released during a Loss of Coolant Accident (LOCA). The Primary Containment design basis leak rate could be exceeded if the unlikely events listed below were to occur simultaneously:

1. A single failure as designed above
2. A LOCA
3. Significant fuel failure as a result of the LOCA

A conservative analysis indicates that under the design basis loss of coolant accident with this single failure present, operators would have to diagnose and take corrective action within 6.7 hours to prevent exceeding 10% of the 10CFR100 limits.


Corrective Action

Direction by means of a standing order has been provided to operators to deenergize the power supply to these valves to close them upon receipt of a reactor low-low level or a high drywell pressure alarm. Corrective action will be taken to correct this deficiency in accordance with the Integrated Living Schedule (ILS).

Similar Occurrences

LER 87-040 Torus Oxygen Sample Line Does Not Meet Single Failure Criteria Due to Design Deficiency

(0510A)



**GPU Nuclear Corporation**  
Post Office Box 388  
Route 9 South  
Forked River, New Jersey 08731-0388  
609 971-4000  
Writer's Direct Dial Number:

June 16, 1988

Director of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Mail Station P1-137  
Washington, DC 20555

Dear Sir:

Subject: Oyster Creek Nuclear Generating Station  
Docket No. 50-219  
Licensee Event Report

This letter forwards one (1) copy of Licensee Event Report (LER)  
No. 88-003.

Very truly yours,

E. E. Fitzpatrick  
Vice President & Director  
Oyster Creek

EEF:GB:dmd(0510A)  
Enclosures

cc: Mr. William T. Russell, Administrator  
Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Mr. Alexander W. Dromerick  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

NRC Resident Inspector  
Oyster Creek Nuclear Generating Station  
Forked River, NJ 08731

IER2  
||