

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Shoreham Nuclear Power Station Unit #1	DOCKET NUMBER (2) 05000322	PAGE (3) 1 OF 4
---	-------------------------------	--------------------

TITLE (4)  
Loss of RPS Bus "B" due to personnel error during a tagging operation

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
05	28	88	88	007	000	06	24	88			05000
											05000

OPERATING MODE (9) 4	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)									
POWER LEVEL (10) 010	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(c)	<input checked="" type="checkbox"/> 60.73(a)(2)(iv)	<input type="checkbox"/> 73.71(b)						
	<input type="checkbox"/> 20.406(a)(1)(i)	<input type="checkbox"/> 60.36(e)(1)	<input type="checkbox"/> 60.73(a)(2)(v)	<input type="checkbox"/> 73.71(e)						
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 60.36(e)(2)	<input type="checkbox"/> 60.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 365A)						
	<input type="checkbox"/> 20.406(c)(1)(iii)	<input type="checkbox"/> 60.73(a)(2)(i)	<input type="checkbox"/> 60.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 60.73(a)(2)(ii)	<input type="checkbox"/> 60.73(a)(2)(viii)(B)							
<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 60.73(a)(2)(iii)	<input type="checkbox"/> 60.73(a)(2)(x)								

LICENSEE CONTACT FOR THIS LER (12)	
NAME Robert W. Grunseich, Operational Compliance Engineer	TELEPHONE NUMBER 516929-8300

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	

SUPPLEMENTAL REPORT EXPECTED (14)	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO			

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On May 28, 1988 at 0645, unplanned ESF actuations occurred when an Equipment Operator (EO) inadvertently opened the wrong breaker during a tagging operation. The plant was in Operational Condition 4 (Cold Shutdown) with the mode switch in shutdown and all rods inserted in the core. The EO, utilizing an approved SECP (Station Equipment Clearance Permit), was in the Emergency Switchgear Room 102 to open a breaker that supplied power to the Standby Liquid Control heat tracing. However, when it was time to open the breaker, he inadvertently opened the incorrect breaker which was located below the correct one. This caused a loss of power to the RPS "B" Bus resulting in the initiation of several ESFs. The Control Room notified the EO to halt the tagging operation. Power was subsequently restored to the bus and all systems were returned to normal. Plant Management was notified of the event and the NRC was notified at 0800 per 10CFR50.72. The incident was discussed with all operators and the EO involved was counseled as to the importance of exercising care when de-energizing circuits.

IE22  
111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME IS:	DOCKET NUMBER IS:	LER NUMBER IS:			PAGE IS:	
		YEAR	SEQUENTIAL NUMBER	FILE NUMBER		
Shoreham Nuclear Power Station Unit #1	0 5 0 0 0 3 2 2	8 8	- 0 0 7	- 0 0 0 2	OF	0 4

PLANT AND SYSTEM IDENTIFICATION

General Electric - Boiling Water Reactor

Energy Industry Identification System (EIIS) codes are identified in the text as [xx].

IDENTIFICATION OF THE EVENT

Loss of RPS Bus "B" due to Equipment Operator error during a tagging operation.

Event Date: 5/28/88

Report Date: 6/24/88

CONDITIONS PRIOR TO THE EVENT

Operational Condition 4 - Cold Shutdown

Mode Switch - Shutdown

RPV Pressure = 0 psig                  RPV Temperature = 105 Degrees F

POWER LEVEL - 0

All rods inserted in the core.

DESCRIPTION OF THE EVENT

On May 28, 1988 at 0645 unplanned ESF actuations occurred when an Equipment Operator (EO) inadvertantly opened the wrong breaker during a tagging operation.

The EO (#1) was assigned by the Nuclear Station Operator (NSO) to hang a Station Equipment Clearance Permit (SECP) in preparation for a power outage to seven Motor Control Centers located throughout the plant. This was to facilitate inspections for Equipment Qualification purposes. Another EO (#2) was sent to the Reactor Building to hang a tag on a power supply to the Standby Liquid Control (SLC) heat tracing to ensure it remained operable while the redundant heat tracing was removed from service. EO #1 reported to Emergency Switchgear Room 102 to locate the breaker to be opened for the power outage. After identifying the correct breaker (1R24\*SWG112-3A) he awaited notification from EO #2 that the tag was hung for the heat tracing. Upon receiving this notification, he then walked over to the panel and opened up breaker 1R24\*SWG-112-3C which is located two breakers below the one he should have opened. This action caused a loss of power to RPS "B" and the following systems initiated:

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME:	DOCKET NUMBER:	LER NUMBER:			PAGE:	
		YEAR	SEQUENCE NUMBER	REVISION NUMBER		
		0500032288	-007	-00	03	OF 04

NOTE: IF MORE THAN ONE REPORT IS SUBMITTED FOR THIS FACILITY, THE REPORT NUMBER SHOULD BE INDICATED IN THE DOCKET NUMBER.

- 1/2 RPS "B"
- 1/2 NS4 isolation
- "B" RBSVS
- "B" CRAC
- RWCU isolation
- RBCLCW "B" split

The Control Room notified the EO of what had just occurred and instructed him to halt the tagging operation. At 0720, power was restored to RFS Bus "B", RWCU was returned to its normal configuration prior to the event and the NS4 isolation signal was cleared. The RBCLCW system was returned to its normal configuration and CRAC was reset at 0730. At 1117, RBSVS was reset and RBNVS was restored. Plant Management was notified of the event and the NRC was notified per 10CR50.73 at 0800.

CAUSE OF THE EVENT

The cause of the event was personnel error for failing to follow plant procedures. The EO was aware of the correct breaker that should have been opened, however he inadvertantly opened the incorrect breaker. The tag in his hand and the SECP he was using identified the correct breaker. The breakers were properly labeled with high visibility labels.

ANALYSIS OF THE EVENT

This event resulted in unplanned automatic actuations of ESF systems (1/2 RPS, 1/2 NS4, RBSVS/CRAC, RWCU and RBCLCW) and is reportable per 10CFR50.73 (a) (2) (iv). There is minimal safety significance to the event. All systems operated as designed. Operators carried out all required actions. Had this event occurred under a more severe set of circumstances (5% power), the safety significance would still be minimal.

CORRECTIVE ACTION

The incident was discussed with all operators. The EO involved was counseled as to the importance of exercising care when de-energizing circuits and the need to be more aware of his actions.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER IS:			PAGE IS:	
		YEAR	SIGNATURE NUMBER	EVENT NUMBER		
		088	007	00	04	OF 04

USE IF MORE THAN ONE FACILITY AND ADDRESS AS: Form 204A (11)

ADDITIONAL INFORMATION

a. Manufacturer and model number of failed component (s)

None

b. LER numbers of previous similar events

85-054



**LONG ISLAND LIGHTING COMPANY**

SHOREHAM NUCLEAR POWER STATION • P.O. BOX 628 • WADING RIVER, NEW YORK 11792

TEL. (516) 929-8300

June 24, 1988

PM-88-170

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Dear Sir:

In accordance with 10CFR50.73, enclosed is Shoreham Nuclear Power Station's Licensee Event Report LER 88-007.

Sincerely yours,

William E. Steiger, Jr.  
Plant Manager

DAS/jp

Enclosure

cc: William T. Russell, Regional Administrator  
Frank Crescenzo, Resident Inspector  
Institute of Nuclear Power Operations, Records Center  
American Nuclear Insurers

SR.A21.0200

JE22  
||