,			LICENSE	E EVENT	REPORT	(LER)			
Facility Name (1) OL Title (4) REACTO	AD-CITIES	NUCLEAR POWER STATION EANUP SYSTEM VALVE CL	. UNIT OSURE D	THO UE TO LE	GHTNIN	IG CAUS	Docket No 01 51 0 ING ELECTRIC	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0) Page (3) 2 6 5 1 0f 2 1 : IP
vent Date (5)	1	LER Number (6)	1	Repor	t Date	(7)	Other	Facilit	ies Involved (8)
th Day Yea	r Year	/// Sequential /// Re	vision. umber	Month	Day	Year	Facility	Names	Docket Number(s)
01 5 21 0 81	7 817	0 0 0 1 7 0	10	016	01 8	8 7			0 5 0 0 0 0 1
OPERATING MODE (9)		THIS REPORT IS SUBMIT (Check one or more of	TED PUR	SUANT TO	THE R	EQUIREN	MENTS OF 100	FR	
POWER LEVEL (10) 0	9 0	20.402(b) 20.405(a)(1)(1) 20.405(a)(1)(11) 20.405(a)(1)(111)	50 50 50	.405(c) .36(c)(1 .36(c)(2 .73(a)(2)))(1)	50 50 50),73(a)(2)(1),73(a)(2)(1),73(a)(2)(1),73(a)(2)(1	v) 11) 111)(A)	73.71(b) 73.71(c) Other (Specify in Abstract beld
		20.405(a)(1)(1v) 20.405(a)(1)(v)	\$0 \$0	.73(a)(2 .73(a)(2)(11))(111)	50).73(a)(2)(v).73(a)(2)(v	111)(8))	and in Text)
			CENSEE	CONTACT	FOR TH	IS LER	(12)		
Name K. J. HI	ILL, Techni	cal Staff Engineer. E	xt. 215	0			AREA 3 i	CODE 0 9	6 5 4 - 2 2 4
	COMPL	ETE ONE LINE FOR EACH	COMPON	ENT FAIL	IRE DE	SCRIBED	IN THIS RE	PORT (1)	1)
CAUSE SYSTEM	COMPONENT	MANUFAC- REPORTAB	LE ////	/// CAU	SE S	YSTEM	COMPONENT	TURES	AC- REPORTABLE
	111		- 19/1	11/1		1		11	1 111
			1111	777		_		+ + +	1 17777
Ives (If yes.	complete E	XPECTED SUBMISSION DA	Q (14) TE)		,			Submiss Date	15)

On May 20, 1987, at 0350 nours, Quad Cities Unit Two was operating in the RUN mode at approximately 90 percent core thermal power. At this time, the Reactor Water Cleanup System (RWCU) isolated (Group III) and several Group II inboard isolation valves automatically closed due to 480 VAC Feed to Bus 28 tripping. At 0405 hours, normal power to Bus 28 was restored, the RWCU System was returned to normal and the Group II isolation valves which closed were reopened.

The cause for this event is attributed to an electrical storm in the area which resulted in a lightning strike to a meteorological tower. The power surge from the lightning bolt backfed to Bus 28 causing the main breaker for that bus to trip. The relay which initiates RWCU system isolation valve closure on high water temperature lost power when Bus 28 tripped and this caused the RWCU isolation. The Group II valves that closed during this event did not close due to a valid isolation signal, but due to a loss of power to the trip logic for the valves.

The local power transformer and distribution panel circuit breakers were found damaged and were replaced. An evaluation was performed to determine if the breaker tripping sequence was proper. It was determined the breaker trip setting coordination was proper but a recommendation to trip check the associated breakers is to be performed when conditions permit. This report is submitted to comply with the requirements of 10 CFR 50-73 (a)(2)(iv).

8803090334 870608 PDR ADOCH 05000265 S BCB

IEZZ'/

FACILITY NAME (1)	DOCKET NUMBER (2)	LER 1	UMBER	(6)			P	age (11
		Year	14/1	Sequential Number	144	Revision Number			
ad Cities Unit Two	015101010121615	817	1.	0 1 0 1 7	-	0 1 0	012	QF	01

PLANT AND SYSTEM IDENTIFICATION:

General Electric - Boiling Water Reactor - 2511 MWt rated core thermal power. Energy Industry Identification System (EIIS) codes are identified in the text as [XX].

EVENT IDENTIFICATION:

The Unit Two Reactor Water Cleanup System isolation valves closed due to loss of Bus 28 during electrical scorm.

A. CONDITIONS PRIOR TO EVENT:

Unit:	Two		Event Date:	May 20, 1987	Event	Time:	0350
Reactor	Mode:	1	Mode Name:	RUN	Power	Level:	90%

This report was initiated by Deviation Report D-4-2-87-031

RUN Mode(4) - In this position the reactor system pressure is at or above 825 psig, and the reactor protection system is energized, with APRM protection and RBM interlocks in service (excluding the 15% high flux scram).

DESCRIPTION OF EVENT:

On May 20, 1987, at 0350 hours. Quad Cities Unit Two was operating in the RUN mode at approximately 90 percent core thermal power. At this time, the main 480 VAC Feed circuit breaker to 480 VAC switchgear Bus 28 [ED] tripped. Bus 28 is an Engineered Safeguards System, Division I bus. This trip was immediately followed by closure of the Group III Reactor Water Cleanup (RWCU) [CE] isolation valve [JM] 1-1201-5. The 1-1201-80 valve also closed as designed (although it is not a Group III isolation valve). The other Group III isolation valve did not close because its power supply was lost as a result of the Bus 28 trip. An alarm "Group III ISO NOT RESET" was received, and several inboard isolation valves [JM] normally associated with a Group II isolation (Pressure Suppression System [JM] and Oxygen Analyzer System [IK]) also closed. A Shift Foreman and Equipment Attendant were dispatched to Bus 28 and discovered undervoltage relays 227-1 and 227-2 had tripped. The two relays were reset and at 0405 hours, the Unit Operator successfully restored normal power to Bus 28. The "GROUP III ISO NOT RESET" alarm was reset, the Reactor Water Cleanup System (RWCU) was returned to normal, and the Group II isolation valves which closed were reopened.

C. APPARENT CAUSE OF EVENT:

This report is submitted in accordance with the Code of Federal Regulations. Title 10, Part 50.73 (a)(2)(iv), which required the reporting of "any event or condition that results in manual or automatic actuation of any Engineered Safety Feature, including the Reactor Protection System."

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUM	BER	/6)			PI	se ()	13
· . · · · · ·		Year 1	11	Sequential Number	11/1	Revision Number			
had Cities Unit Two	01510101012161	817	-	0 1 0 1 7	-	0 1 0	013	OF	01

The apparent cause of this event has been attributed to an electrical storm which was in the vicinity of the plant at the time of the event. It is suspected that a bolt of lightning hit the meteorological tower [IS] which is located approximately 1000 feet northeast of the plant. This tower is fed from Motor Control Center (MCC) 28-3, which is fed from Bus 28. The power surge from the lightning bolt backfed to Bus 28 causing the main breaker for that bus to trip.

The relay which initiates Reactor Water Cleanup (RWCU) isolation valve closure on high water temperature lost power when Bus 28 tripped. This trip is intended to prevent damage to the RWCU demineralizer resins due to high temperatures. The loss of power simulated a high temperature condition and caused isolation of the RWCU system. The valve closure then resulted in the Control Room receiving a "GROUP III ISOLATION NOT RESET" alarm. The closure of several Group II isolation valves was not caused by a Group II isolation signal, but loss of power to the trip logic for the valves.

D. SAFETY ANALYSIS OF EVENT:

The safety of the public and plant personnel was never affected during this event. Normal Group III isolation occurs upon receipt of a reactor low water level signal (+8 inches). In this situation, the RWCU system isolation was not a result of abnormal reactor operation. RWCU system isolation does not affect safe operation of the reactor but may result in increased reactor water conductivity if isolated for a prolonged length of time. The short amount of time that the system was isolated did not result in any noticeable increase in reactor water conductivity.

E. CORRECTIVE ACTIONS:

The local power transformer and distribution panel circuit breakers for the metaorological tower were found to be damaged by the lightning strike and were replaced. There was no damage to MCC 28-3 or Bus 28. The Station Electrical Engineering Department was contacted to evaluate the trip setting coordination of the main feed circuit breakers for MCC 28-3 and Bus 28 since the main feed circuit breaker for Bus 28 tripped before the main feed circuit breaker for MCC 28-3 or the feed breaker to the meteorological tower tripped. The results of their review indicated that the coordination was proper, however it was recommended that Bus 28. MCC 28-3 feed breaker, and the meteorological tower feed breaker be trip checked to verify their correct operation. This action will be scheduled for an appropriate opportunity and will be tracked under Action Item #26578087007.

F. PREVIOUS EVENTS:

There are no previous reportable events involving RWCU system isolation as a result of a breaker trip from an electrical storm.

G. COMPONENT FAILURE DATA:

Not applicable.

Commonwealth Edison	DEVIATION REPORT		
	STA UNIT YEAR	- 031 NO.	
ART 1 TITLE OF DEVIATION		OCCURRED	
ROUP III ISOLATION		5/20/87 DATE	0350 TIME
YSTEM AFFECTED PLANT STAT	US AT TIME OF EVENT		TESTING
1200 MODE RUN	, POWERIA 90	BORK REQUEST NO.	VES X
Received Group III isolatic	on and k erp. I & II. at	nd A channel scram, be	cause
Received broup in thoracter	and the set of the set of the		
Bus 28 was lost. Lightning	g is the suspected culp	rit.	1
			la companya da series de la companya
POTENTIALLY SIGNIFICANT EVE	NT PER NSO DIRECTIVE A-07	YES 🖾 NO	
CERSO, 12 NRC RED PHONE 1 HOUR		C. Bucknell	5/20/87
A HOUR DA	S DNO PERSONSID	. C. DUCKNELL	21 20101
		1 SUPERVISOR	UATE
PART 2 OPERATING ENCINEER'S COMMENT	5	L JUPERVISOR	UAT 1
The Gr. III isol. was	s a result of the loss of	of the 2ARPS bus. Thi	8
The Gr. III isol. was	s a result of the loss of water cleanup system	of the 2ARPS bus. Thi high temperature sign	8
The Gr. III isol. was caused a false reacto	s a result of the loss o or water cleanup system	of the 2ARPS bus. Thi high temperature sign	s al
The Gr. III isol. was caused a false reactor and subsequent cleans	s a result of the loss o or water cleanup system up system isolation.	of the 2ARPS bus. Thi high temperature sign	8 al
The Gr. III isol. was caused a false reactor and subsequent cleans	s a result of the loss o or water cleanup system up system isolation.	of the 2ARPS bus. Thi high temperature sign	s al
The Gr. III isol. was caused a false reactor and subsequent cleans	s a result of the loss o or water cleanup system up system isolation.	of the 2ARPS bus. Thi high temperature sign	s al
The Gr. III isol. was caused a false reactor and subsequent cleans	s a result of the loss o or water cleanup system up system isolation.	of the 2ARPS bus. Thi high temperature sign	8 al
PART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reacto and subsequent cleans	s a result of the loss o or water cleanup system up system isolation.	of the 2ARPS bus. Thi	s al
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE INCERSO.7	S a result of the loss of or water cleanup system up system isolation.	will DATE	8 al
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleanu NON REPORTABLE EVENT 30 DAY REPORTABLE INCER 50.7. (a) (2) (IV	3 NOTIFICATION - REGIO	will DATE	8 al
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE INCER 50.7 (a) (2) (IV 5 DAY REPORT PER INCERS)	S a result of the loss of or water cleanup system up system isolation.	of the 2ARPS bus. Thi high temperature sign will DATE	8 al 7.555
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleanu NON REPORTABLE EVENT 20 DAY REPORTABLE INCERSO,7 (a) (2) (IV 5 DAY REPORT PER INCERSI ANNUAL/SPECIAL REPORT REQUIRE	3 NOTIFICATION	A HIPERVISOR of the 2ARPS bus. Thi high temperature sign will DATE SO DATE IFICATION MADE	8 al 70x5
ALT 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE EVENT (a) (2) (IV 5 DAY REPORT PER INCERSI ANNUAL/SPECIAL REPORT REQUIRE A.1.R. #	S a result of the loss of or water cleanup system up system isolation.	N 111 DATE	8 al 7.5%E
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reacto and subsequent cleanu NON REPORTABLE EVENT 30 DAY REPORTABLE INCERSO,7 (a) (2) (IV 5 DAY REPORT PER INCERSI ANNUAL/SPECIAL REPORT REQUIRE A.1.6. *	3 NOTIFICATION	A DIPERVISION of the 2ARPS bus. Thi high temperature sign will DATE N 111 DATE SO DATE SO DATE PORATE OFFICER DATE	8 al 70xg 70xg
PART 2 OPERATING ENDINCER'S COMMENT The Gr. III isol. was caused a false reacto and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE EVENT 30 DAY REPORTABLE INCERSO,7 (a) (2) (IV 5 DAY REPORT PER INCERSI ANNUAL/SPECIAL REPORT REQUIRE A.I.R. *	S a result of the loss of or water cleanup system up system isolation.	N 111 DATE SO DATE PORATE OFFICER DATE	8 al 73ME 73ME
PART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reacto and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE INCERSO,7: (a) (2) (IV 5 DAY REPORT PER INCERSI ANNUAL/SPECIAL REPORT REQUIRE A.1.R. #	S a result of the loss of or water cleanup system up system isolation.	A DIPERVISION of the 2ARPS bus. Thi high temperature sign will DATE SO DATE SO DATE SO DATE SO DATE SO DATE SO DATE SO DATE SO DATE SO DATE	8 al 73ME 73ME
PART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE EVENT 30 DAY REPORTABLE INCER 50.7 (a) (2) (IV 5 DAY REPORT PER INCER2) ANNUAL/SPECIAL REPORT REQUIRE A.I.R. #	S a result of the loss of or water cleanup system up system isolation.	A DIPERVISION of the 2ARPS bus. Thi high temperature sign will DATE SO DATE OFICATION MADE ON IS PER IDEFR2) PORATE OFFICER DATE 5/20/87 CATE	8 al 73ME 73ME
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE INCERSO, 7: (a) (2) (IV 5 DAY REPORT PER INCERSI ANNUAL/SPECIAL REPORT REQUIRE A.I.R. #	A result of the loss of the lo	A DIPERVISION of the 2ARPS bus. This high temperature sign with temperature sign with temperature sign on 111 Date SO DATE	8 al 73XE 73XE
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE EVENT 30 DAY REPORTABLE INCER 50.7 (a) (2) (IV 5 DAY REPORT PER INCER2) ANNUAL SPECIAL REPORT REQUIRE A.I.R. F. LE R. *87+007 PRELIMINARY REPORT COMPLETED AND REVIEWED	S a result of the loss of or water cleanup system up system isolation.	N 111 DATE SO DATE	8 al 73XE 73XE 73XE
PART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reacto and subsequent cleans and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE INCERSO, 7: (a) (2) (IV 5 DAY REPORT PER INCERSI ANNUAL/SPECIAL REPORT REQUIRE A.I.R. *	S a result of the loss of or water cleanup system up system isolation.	A DIPERVISION of the 2ARPS bus. This high temperature sign with temperature sign N 111 Date DATE DATE DATE DATE DATE DATE DATE DATE DATE DATE DATE DATE DATE DATE DATE	8 al 73XE 73XE
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans NON REPORTABLE EVENT and DAY REPORTABLE INCER 50.7 and (2) (IV 5 DAY REPORT PER INCER2) ANNUAL SPECIAL REPORT REQUIRE ALLER *	S a result of the loss of or water cleanup system up system isolation.	A DIPERVISION of the 2ARPS bus. Thi high temperature sign will DATE SO DATE	8 al
ART 2 OPERATING ENGINEER'S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans and subsequent cleans NON REPORTABLE EVENT 30 DAY REPORTABLE EVENT (a) (2) (IV 5 DAY REPORT PER 1005R2) ANNUAL/SPECIAL REPORT REQUIRE A.1.R. # LE R. #	A result of the loss of a result of the loss	A DIPERVISION of the 2ARPS bus. This high temperature sign will DATE SO	8 al 70xg 70xg 70xg 70xg
ART 2 OPERATING ENGINEER S COMMENT The Gr. III isol. was caused a false reactor and subsequent cleans NON REPORTABLE EVENT DO DAY REPORTABLE EVENT DO DAY REPORTABLE FORT (a) (2) (IV S DAY REPORT PER INCORP.) ANNUAL SPECIAL REPORT REQUIRE ALLE R *82+007 PRELIMINARY REPORT COMPLETED AND REVIEWED - NVESTIGATION REPORT & RESOLUTION ACCEPTED BY STATION REVIEWED - NYESTIGATION REPORT & RESOLUTION ACCEPTED BY STATION REVIEWED - RESOLUTION APPROVED AND AUTHORIZED FOR DISTRIBUTION	S a result of the loss of or water cleanup system up system isolation.	A DIPERVISION of the 2ARPS bus. Thi high temperature sign will DATE SO DATE	8 al



e

Commonwealth Edison Quad Cities Nuclear Power Station 22710 206 Avenue North Cordova, Illinois 61242 Telephone 309/654-2241

RLB-87-150

June 8, 1987

-10

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Reference: Quad-Cities Nuclear Power Station Docket Number 50-265, DPR-30, Unit Two

Enclosed please find Licensee Event Report (LER) 87-007, Revision 00, for Quad-Cities Nuclear Power Station.

This report is submitted in accordance with the requirements of the Code of Federal Regulations, 7itle 10, Part 50.73(a)(2)(iv), which requires the reporting of any event or condition that results in manual or automatic actuation of any Engineered Safety Feature, including the Reactor Protection System.

Respectfully,

COMMONWEALTH EDISON COMPANY QUAD-CITIES NUCLEAR POWER STATION

8 Fran

R L. Bax Station Manager

RLB/MSK/rk

Enclosure

cc: I. Johnson R. Higgins INPO Records Center NRC Region III

0370H/0183Z