

James A. FitzPatrick  
Nuclear Power Plant  
268 Lake Road  
P.O. Box 41  
Lycoming, New York 13093  
315-342-3840



**New York Power  
Authority**

**Michael J. Colomb**  
Site Executive Officer

December 4, 1998  
JAFP-98-0386

United States Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, D.C. 20555

Subject: **Docket No. 50-333**  
**LICENSEE EVENT REPORT: LER-98-012**

**Failure to Meet Primary Containment Leakage Rate Testing Program  
Requirements**

Dear Sir:

This report is submitted in accordance with 10 CFR 50.73(a)(2)(i)(B), "Any operation or condition prohibited by the plant's Technical Specifications."

There are no commitments contained in this report.

Questions concerning this report may be addressed to Mr. Gordon Brownell at (315) 349-6360.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'M. J. Colomb'.

**MICHAEL J. COLOMB**

MJC:GB:las  
Enclosure

cc: USNRC, Region 1  
USNRC, Project Directorate  
USNRC Resident Inspector  
INPO Records Center

9812090020 981204  
PDR ADOCK 05000333  
S PDR

1/1  
Jerr

## LICENSEE EVENT REPORT (LER)

(See reverse for required number of  
digits/characters for each block)

Estimated burden per response to comply with this mandatory information collection request 50 hrs. Reported lessons learned are incorporated into the licensing process and fed back to industry. Forward comments regarding burden estimate to the Records Management Branch (T-6 F33), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, and to the Paperwork Reduction Project (3150-0104), Office of Management and Budget, Washington, DC 20503. If an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

FACILITY NAME (1)

James A. FitzPatrick Nuclear Power Plant

DOCKET NUMBER (2)

05000333

PAGE (3)

1 OF 4

TITLE (4)

Failure to Meet Primary Containment Leakage Rate Testing Program Requirements

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	04	98	98	012	00	12	04	98	N/A	05000
									N/A	05000
OPERATING MODE (9)		N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more) (11)							
POWER LEVEL (10)		0	20.2201(b)		20.2203(a)(2)(v)		X		50.73(a)(2)(i)	50.73(a)(2)(viii)
			20.2203(a)(1)		20.2203(a)(3)(i)				50.73(a)(2)(ii)	50.73(a)(2)(x)
			20.2203(a)(2)(i)		20.2203(a)(3)(ii)				50.73(a)(2)(iii)	73.71
			20.2203(a)(2)(ii)		20.2203(a)(4)				50.73(a)(2)(iv)	OTHER
			20.2203(a)(2)(iii)		50.36(c)(1)				50.73(a)(2)(v)	Specify in Abstract below or in NRC Form 366A
			20.2203(a)(2)(iv)		50.36(c)(2)				50.73(a)(2)(vii)	

## LICENSEE CONTACT FOR THIS LER (12)

NAME

Mr. Gordon Brownell, Licensing Engineer

TELEPHONE NUMBER (include Area Code)

(315) 349-6360

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

## SUPPLEMENTAL REPORT EXPECTED (14)

YES

(If yes, complete EXPECTED SUBMISSION DATE).

X

NO

EXPECTED  
SUBMISSION  
DATE (15)

MONTH

DAY

YEAR

## ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On November 04, 1998, during a review of test procedures associated with the plant's Primary Containment Leakage Rate Testing Program, it was identified that Type C local leak rate test (LLRT) procedures associated with the Reactor Water Recirculation (RWR) System's inboard mini purge line containment isolation valves contained an error. This error resulted in inaccurate leakage rate test results and failure to meet the requirements of the Testing Program. This failure is a violation of surveillance requirements of Technical Specifications (TS) Section 4.7.A.2. At the time of the discovery, the mode switch was in the REFUEL position while the plant was conducting Refuel Outage 013.

The probable cause for the deficient test procedures was less than adequate technical reviews during procedure revisions.

Corrective actions include revising the test procedures, satisfactory completion of leakage rate testing on the subject RWR System isolation valves, counseling personnel involved with the inadequate procedure technical reviews, and conducting an independent review of all LLRT procedures.



LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
James A. FitzPatrick Nuclear Power Plant	05000333	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 4
		98	012	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EIIIS Codes in [ ]

**EVENT DESCRIPTION**

On November 04, 1998, during a review of test procedures associated with the plant's Primary Containment Leakage Rate Testing Program, it was identified that Type C local leak rate test procedures ST-39B-X31Ac, "Type C Leak Test of RWR A Mini Purge line valves (IST)" and ST-39B-X31Bc, "Type C Leak Test of RWR B Mini Purge Line Valves (IST)" contained an error associated with the testing of Reactor Water Recirculation (RWR) System's [AD] inboard mini purge line containment isolation valves 02-2RWR-13A and B. The test frequency for the two valves is established by the Testing Program at 24 month intervals. The last and only test performance for the two valves, using the incorrect procedures, was during the plant's fall 1996 Refuel Outage. The procedure error resulted in incorrect leak rate tests results and failure to meet the requirements of the Primary Containment Leakage Rate Testing Program. This failure is a violation of Technical Specifications (TS) Section 4.7.A.2 surveillance requirements. At the time of the discovery, the mode switch was in the REFUEL position while the plant was conducting Refuel Outage 013.

The "A" and "B" loops of the RWR System minipurge line containment isolation piping configuration consist of an inboard (02-2RWR-13A/B) and outboard (02-2RWR-41A/B) 3/4 inch stainless steel check valve. The identified test procedure errors consisted of establishing test gas vents at incorrect locations. Specifically, test pressures were applied to the vessel side of the inboard check valves. The test configuration then required gas leakage to penetrate through both the inboard and outboard check valves with test vents established outboard of 02-2RWR-41A/B. This resulted in inaccurate and lower than actual recorded leakage flow rates for the inboard check valves. The correct position for the vent path for testing of inboard valves 02-2RWR-13A/B is located in the piping between the inboard and outboard containment isolation check valves.

**EVENT CAUSE**

The probable cause for this event was less than adequate technical reviews during surveillance test procedure revisions.

Procedures ST-39B-X31Ac and ST-39B-X31Bc were revised in 1996 following the completion of a plant modification which replaced existing power operated outboard RWR System mini purge isolation valves with the currently installed 3/4 inch piston check valves. The modification affected the inboard isolation valve. Type C leakage rate test flow path configuration; however, procedure reviews did not identify the required changes.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
James A. FitzPatrick Nuclear Power Plant	05000333	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 4
		98	012	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**ANALYSIS**

This report is being submitted in accordance with 10 CFR 50.73(a)(2)(i)(B), "Any operation or condition prohibited by the plant's Technical Specifications." TS Section 4.7.A.2.a, Surveillance requirements for Containment Systems, requires, in part, leakage rate testing of the Primary Containment in accordance with the Primary Containment Leakage Rate Testing Program.

The function of all Primary Containment isolation valves is to provide necessary isolation of the containment in the event of accidents or similar conditions when the release of containment atmosphere cannot be permitted.

This event had minimal safety significance. An operability review was conducted and determined the penetrations were operable based on acceptable testing in 1996 of the penetration's outboard isolation valves. Additionally, both inboard and outboard isolation check valves were successfully Type C leak rate tested on November 04, 1998, proving their isolation capability.

**EXTENT OF CONDITION**

This event was determined to be an isolated incident based on pre-test reviews of Local Leakage Rate Test procedures during each of the Refuel Outage 013 LLRT's. The reviews were responsible for the identification of the reported procedure error. No other similar errors were identified.

An additional independent review of all LLRT procedures is being conducted by the Operations Department and is scheduled to be completed prior to plant startup from Refuel Outage 013. This review will provide further assurance that Primary Containment Leakage Rate Testing Program requirements have been satisfied.

**CORRECTIVE ACTIONS**

1. Type C leak rate test procedures ST-39B-X31Ac and ST-39B-X31Bc were revised to provide an effective vent path for testing valves 02-2RWR-13A and 02-2RWR-13B.
2. As-found leakage rate testing was completed on the subject valves per the revised procedures. Both valves met acceptance criteria.

**LICENSEE EVENT REPORT (LER)**  
**TEXT CONTINUATION**

FACILITY NAME (1)	DOCKET (2)	LER NUMBER (6)			PAGE (3)
James A. FitzPatrick Nuclear Power Plant	05000333	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 4
		98	012	00	

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

**CORRECTIVE ACTIONS** (cont.)

3. Plant personnel involved in the 1996 development and review of two surveillance test procedure revisions were counseled by the Operations Manager on the importance of maintaining a questioning attitude and conducting rigorous evaluations of all aspects of procedure changes.
4. Operations Department is completing an independent review of all LLRT procedures to assure that similar errors do not exist.  
(Scheduled Completion Date - Prior to Plant Startup from Refuel Outage 013)

**ADDITIONAL INFORMATION**

A. Previous Similar Events:

LERs 95-002, 95-003, and 95-004 describe previous similar events in which procedure deficiencies resulted in all or part of a surveillance requirement being missed or not performed in compliance with TSs.

B. Failed Components: None