



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

511 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011 8064

DEC 18 1997

Mr. C. L. Terry
TU Electric
Group Vice President, Nuclear
ATTN: Regulatory Affairs Department
P.O. Box 1002
Glen Rose, Texas 76043

SUBJECT: SUMMARY OF DECEMBER 15, 1997, MEETING


Dear Mr. Terry:

This refers to the meeting conducted in the Region IV office on December 15, 1997. This meeting was requested by you to inform the Region IV staff of the results of your most recent refueling/outage. Your presentation included discussions of activities occurring in operations, maintenance, engineering, and plant support. The meeting was beneficial in providing TU Electric the opportunity to describe the scope of the planned activities, the successes, and identify areas where improvement is needed including corrective action issues.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,


Thomas P. Gwynn, Director
Division of Reactor Projects

Docket Nos.: 50-445; 50-446
License Nos.: NPF-87; NPF-89

Enclosures:

1. Attendance List
2. Licensee Presentation



9712230190 971218
PDR ADOCK 03000445
P PDR

TU Electric

-2-

cc w/enclosures:

Mr. Roger D. Walker
TU Electric
Regulatory Affairs Manager
P.O. Box 1002
Glen Rose, Texas 76043

Juanita Ellis
President - CASE
1426 South Polk Street
Dallas, Texas 75224

TU Electric
Bethesda Licensing
3 Metro Center, Suite 610
Bethesda, Maryland 20814

George L. Edgar, Esq.
Morgan, Lewis & Bockius
1800 M. Street, NW
Washington, D.C. 20036

G. R. Bynog, Program Manager/
Chief Inspector
Texas Department of Licensing & Regulation
Boiler Division
P.O. Box 12157, Capitol Station
Austin, Texas 78711

Honorable Dale McPherson
County Judge
P.O. Box 851
Glen Rose, Texas 76043

Texas Radiation Control Program Director
1100 West 49th Street
Austin, Texas 78756

John Howard, Director
Environmental and Natural Resources Policy
Office of the Governor
P.O. Box 12428
Austin, Texas 78711

bcc to DCD (IE45)

bcc distrib. by RIV:

Regional Administrator

DRP Director

Branch Chief (DRP/A)

Project Engineer (DRP/A)

Branch Chief (DRP/TSS)

Resident Inspector

DRS-PSB

MIS System

RIV File

DOCUMENT NAME: R:_CPSES\CP1215ms.rak

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:PE:DRP/A	C:DRP/A	D:DRP					
RAKopriva;jes	JITapia	TPGwynn					
12/17/97	12/17/97	12/17/97					

OFFICIAL RECORD COPY

bcc to DCD (IE45)

bcc distrib. by RIV:
 Regional Administrator
 DRP Director
 Branch Chief (DRP/A)
 Project Engineer (DRP/A)
 Branch Chief (DRP/TSS)

Resident Inspector
 DRS-PSB
 MIS System
 RIV File

DOCUMENT NAME: R:_CPSES\CP1215ms.rak

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

RIV:PE:DRP/A	C:DRP/A	D:DRP					
RAKopriva;jes	JITapia	TPGwynn					
12/17/97	12/18/97	12/18/97					

OFFICIAL RECORD COPY

030006

ENCLOSURE 1

ATTENDANCE AT THE TU ELECTRIC OUTAGE MEETING
ON DECEMBER 15, 1997

TU Electric

C. L. Terry, Group Vice President, Nuclear Production
J. J. Kelley, Jr., Vice President of Nuclear
Engineering and Support
D. L. Davis, Nuclear Overview Manager
D. Moore, Operations Manager
M. Lucas, Maintenance Manager
B. Bird, Nuclear Planning Manager
R. Walker, Regulatory Affairs Manager
T. Hope, Regulatory Compliance Manager
J. Seawright, Senior Engineer, Regulatory Affairs
S. Sewell, Unit Supervisor
D. Woodlan, Docket Licensing Manager
S. Sawa, Outage Manager
E. Schmidt, Public Relations Coordinator

NRC

E. W. Merschoff, Regional Administrator
K. E. Brockman, Deputy Director, Division of Reactor
Projects (DRP)
J. I. Tapia, Chief, Project Branch A, DRP
R. A. Kopriva, Senior Project Engineer, Project Branch A, DRP
H. A. Freeman, Acting Senior Resident, CPSES, DRP
C. E. Johnson, Senior Reactor Inspector
J. L. Shackelford, Senior Reactor Analyst

ENCLOSURE 2



A T e x a s U t i l i t i e s C o m p a n y™

**Comanche Peak
Steam Electric Station**

**Lance Terry
Group Vice President**




A T e x a s U t i l i t i e s C o m p a n y™

**Comanche Peak
Steam Electric Station**

**David Moore
Operations Manager**

PRESSURIZER PORV LTOP SETPOINTS



MATERIAL PROPERTY BASIS

CONTROLLING MATERIAL: LOWER SHELL PLATE R110B-1 (UNIT 1)
INTERMEDIATE SHELL PLATE R3807-2 (UNIT 2)

INITIAL RT_{NDT}: 0°F (UNIT 1), 10°F (UNIT 2)

ART AT 16 EFPY: 1/4T : 84°F (UNIT 1), 81°F (UNIT 2)
3/4T : 69°F (UNIT 1), 62°F (UNIT 2)

CURVES BOUNDING COMANCHE PEAK UNITS 1 AND 2. APPLICABLE FOR COOLDOWN RATES UP TO 100°F/HR FOR THE SERVICE PERIOD UP TO 16 EFPY. CONTAINS MARGIN OF 10°F AND 110 PSIG FOR POSSIBLE INSTRUMENTATION ERRORS.








FIGURE 3.4-3


REACTOR COOLANT SYSTEM COOLDOWN LIMITATIONS - APPLICABLE UP TO 16 EFPY
















A \MVC-023F.JPG (local)



file A \MVC-023F.JPG








Figure 2.1 Comanche Peak Unit 2, Cycle 4 Core Loading Pattern


		R	P	N	M	L	K	J	H	G	F	E	D	C	B	A																								
90°	Quad IV N41 Loop 4																DD62	FF50	FF64	DD54	FF12	FF57	DD69							1										
																		D-14	6	6	C-11	6	6	M-14							Quad I N43 Loop 1	2								
																		DD32	EE67	FF20	EE44	FF26	EE66	FF29	EE52	FF32	EE74	DD15												
																		E-15	G-10	6	K-13	6	M-13	6	F-13	6	J-10	L-15												
																		DD14	FF34	FF55	EE13	EE30	EE12	FF23	EE85	EE83	EE82	FF10	FF51	DD22										
																		A-11	6	6	C-4	F-15	G-2	6	J-2	K-15	N-4	6	6	R-11										
																		EE77	FF06	EE42	FF58	EE58	FF74	EE49	FF53	EE43	FF43	EE85	FF19	EE39										
																		F-9	6	L-2	6	L-10	6	J-15	6	E-10	6	B-5	6	K-9										
																		DD79	FF41	EE46	FF75	EE36	FF31	EE32	EE38	EE81	FF52	EE20	FF80	EE04	FF85									
																		B-12	6	M-13	6	H-11	6	E-4	H-7	L-4	6	L-8	6	D-13	6	F-12								
																		FF54	EE51	EE69	EE6	FF70	EE05	EE55	EE35	EE10	EE56	FF37	EE45	EE81	EE86	FF22								
																		6	C-6	A-10	F-5	6	P-5	M-7	G-15	D-7	E-2	6	K-5	R-10	N-8	6								
																		FF15	FF28	EE26	FF16	EE16	EE07	EE40	FF36	EE27	EE29	EE73	FF73	EE33	FF06	FF39								
																		6	6	P-9	6	M-11	J-4	N-3	6	C-3	G-4	D-11	6	B-9	6	6								
																		DD70	EE19	FF62	EE72	EE26	EE39	FF66	BB13	FF67	EE69	EE53	EE15	FF25	EE34	DD82								
																E-3	C-8	6	A-9	J-8	A-7	6	F-7	6	R-9	G-8	R-7	6	N-8	L-13										
																FF61	FF17	EE41	FF46	EE90	EE66	EE47	FF03	EE02	EE14	EE63	FF04	EE09	FF33	FF72										
																6	6	P-7	6	M-5	J-12	N-13	6	C-13	G-12	D-5	6	B-7	6	6										
																FF05	EE25	EE22	EE57	FF08	EE94	EE75	EE91	EE90	EE18	FF01	EE9	EE54	EE06	FF69										
																6	C-10	A-6	F-11	6	L-14	M-9	J-1	D-9	B-11	6	K-11	R-6	N-10	6										
																DD49	FF40	EE24	FF42	EE87	FF44	EE37	EE03	EE70	FF30	EE23	FF27	EE71	FF77	DD75										
																B-4	6	M-3	6	E-8	6	E-12	H-9	L-12	6	H-5	6	D-3	6	P-4										
																EE80	FF47	EE17	FF59	EE68	FF11	EE92	FF14	EE93	FF71	EE01	FF48	EE50												
																F-7	6	P-11	6	L-6	6	G-1	6	E-6	6	E-14	6	K-7												
																DD08	FF24	FF68	EE48	EE76	EE21	FF38	EE11	EE08	EE62	FF13	FF02	DD29												
																A-5	6	6	C-12	F-1	G-14	6	J-14	K-1	N-12	6	6	R-5												
																Quad I N44 Loop 3	DD40	EE84	FF46	EE59	FF49	EE76	FF21	EE95	FF18	EE64	DD07				Quad I N42 Loop 2	14								
																E-1	G-6	6	K-3	6	H-3	6	F-3	6	J-6	L-1														
																			DD64	FF07	FF76	DD63	FF35	FF56	DD55	ASSEMBLY ID					15									
																			D-2	6	6	N-5	6	6	M-2	CYCLE 3 LOCATION														

- BB REGION 2 (West., 2.4 w/o)
- DD REGION 4B (West., 4.0 w/o, Central Zone)
- EE REGION 5 (SPC, 4.95 w/o, Central Zone)
- FF REGION 6 (SPC, 4.4 w/o, Central Zone)
- 70 REGION 4A (West., 3.6 w/o, Central Zone)



2RFO3 Cleanup Curve





Sheet metal transition
from 2.5" outlet
to 10" exhaust trunk

Suction pressure gauge

Air ejector

Suction isolation
(2" ball valve)


Air pressure gauge


1" air hose fittings with
ball isolation valves


Vacuum fill air ejector assembly with threaded unions to allow assembly to be broken into 3 sections



OUTAGE CLEARANCE ERROR RATE







Successes

- **Chemistry and CRUD Management**
- **Mid Loop Operations**
- **Reactor Coolant System Vacuum Fill**
- **Work Window Managers**
- **Clearances and Safety Tagging**
- **MODE Changes and Power Ascension**
- **Operator (PEO and RO) Performance**
- **Just-In-Time (JIT) Training**




**Comanche Peak
Steam Electric Station**


**Mitchell Lucas
Maintenance Manager**

Maintenance

- **Challenges**
 - **Switchyard Work - Unit 1 Trip**
 - **Rod Control - Unit 2 Trip**
- **Successes**
 - **Smart Team Concept**
 - **Ownership of Equipment**
- **Lessons Learned**
 - **Integrated Leak Rate Test Preparations**
 - **Staging of Special Tools**
 - **Emergency Diesel Generators**
 - **Exposure Control (ALARA) Planning**



138 KV PRIMARY BLACK START TRANSMISSION CORRIDOR



CPSES 345 KV SWITCHYARD

138KV Black Start Corridor
(For Illustration Purposes Only)

ATTACHMENT 1B
PAGE 1 OF 1

RESPONSE TO A 138/345 KV SYSTEM MALFUNCTION

REVISION NO. 6

PAGE 178 OF 190

ABNORMAL CONDITIONS PROCEDURES MANUAL

UNIT 1 AND 2

PROCEDURE NO.
ABN-601

CPSES

Attachment 1B



Switchyard Work - Unit 1 Trip

- Trip Testing of the East Bus Lockout Relays

- Past Incident

- Interim Actions

- Lessons Learned

- Previous Switchyard Corrective Actions

Rod Control - Unit 2 Trip

- **Unit 2 ramping down for Refueling Outage #3**
- **Rod Control Alarm at 10% Reactor Power**
- **Rods Dropped When Stepped Out**
- **Manually Tripped Reactor**
- **Failed Equipment Identified**

SMART Team Concept

- **Multi-Disciplined Craft Teams**
- **System Oriented**
- **Team Ownership of Equipment**

Equipment Ownership

- Personnel Air Lock
- 7300 Power Supply Rework
- Feedpump Rework
- Turbine Controls

Equipment Ownership (cont.)

- **Emergency Diesel Generators**
- **Electrical Breaker Refurbishment**
- **Pre-Job Briefings and Walkdowns**

Design Modifications

- **Design Modification Engineering Team**
- **Multi-discipline Walkdowns**
- **Advanced Planning**

Outage Management

- **Outage Control Center Relocated**
- **Centralized Outage Functions (One Stop Shopping Concept)**
- **Operations Shift Managers Perform Outage Duty Manager Function**
- **Licensed SROs Perform Work Week Manager Function**

Lessons Learned

- **Integrated Leak Rate Test Preparations**
- **Staging of Special Tools**
- **Emergency Diesel Generator**
- **Exposure Control (ALARA) Planning**



**Comanche Peak
Steam Electric Station**

Jim Kelley
**Vice President of Nuclear
Engineering and Support**

Containment Sumps

- | | |
|----------------|--|
| November, 1989 | IN 89-77 issued on containment sumps |
| December, 1993 | IN 89-77 Supplement 1 issued on holes in containment screens |
| January, 1994 | HL&P identifies gaps in containment sump structure |
| October, 1994 | CPSES Unit 2 containment sump structure gaps are found |
| November, 1994 | Repairs performed in CPSES Unit 2 |
| April, 1995 | Repairs performed in CPSES Unit 1 |
| November, 1997 | Gaps are found in containment sump structure in CPSES Unit 2 |

Weld Summary

Unit	Train	Time Frame	Welds
2	A	2RF01 (1994)	71
2	B	2RF01 (1994)	81
1	A	1RF04 (1995)	104
1	B	1RF04 (1995)	113
2	A	2RF03 (1997)	19
2	B	2RF03 (1997)	20

Safety Synopsis

- **Debris sources identified**
- **Transport velocities characterized**
- **Debris behavior characterized**
- **Surveillance/inspections evaluated**
- **Existing plant configuration provides adequate protection of plant equipment**

Causes (preliminary)

Utilization of normal engineering and work control processes were not appropriate for this situation due to:

- Gaps were difficult to identify because gaps had indirect paths through the structure.
- Work instructions may not have provided the appropriate level of detail within the work documents.
- Ineffective coordination of a work activity identified near the end of the refueling outage.

Conclusion

- Engineering review has concluded Unit 1 and Unit 2 sumps were never in a condition which would have caused inoperable equipment.
- Unit 2 sump screens have been enhanced to meet the licensing basis.
- Unit 1 sumps will be inspected in 1RF06 to ensure that the current licensing basis is met.

CCW Motor Termination Failures

**December 7,
1989**

**CCW Motor 1-02 phase B
failed while starting**

July 27, 1997

**CCW Motor 1-02 phase A
failed while starting**

**November 30,
1997**

**CCW Motor 2-01 phase B
failed while starting**

**December 7, 1989 - CCW Motor
1-02 phase B failed while starting.**

- **Specific problem repaired. Phase B
relugged**
- **Plant Incident Report**
- **19 Motor terminations were surveyed
using thermography**

**July 27, 1997 - CCW Motor 1-02
phase A failed while starting.**

- **Specific problem repaired. Phases A & C
relugged**
- **Industry experience reviewed.**
- **CPSES work history reviewed.**
- **Conclusion - isolated condition on the 1-02
motor.**
- **Generic actions were identified to look at
similar pumps motors.**

November 30, 1997 - CCW Motor 2-01 phase B failed while starting.

- **Specific problem repaired. Phases A,B, & C relugged**
- **Determined corrective action document closed from July event with generic actions outstanding.**
- **Performed thermography on Unit 2 Life Line D motors (except RHR).**
- **Generic actions on other 1-01 CCW motor complete.**

Conclusions


- Unit 1 & 2 Life Line D motors operable.
- Vendor is doing a document search for the manufacturing records.
- Management expectations were not met on the closure of the ONE Form with generic actions outstanding.
- A Significant Personnel Error was assigned to Engineering.
- Final actions to be determined from options such as: continued periodic thermography; inspections and/or replacement of connectors.
- The final corrective actions to be determined in January, 1998.

Major Plant Improvements

- Battery Charger Replacement
- Inverter Replacement
- Diesel Generator Digital Governor
- Terry Turbine Drain Modification
- Safety Injection Check Valve Replacement
- Heater Drain Modification
- Lightning Protection
- Tavg Modification

Lessons Learned

- Review use of Spent Fuel Pool 2
- Evaluate Refueling Equipment
- Joint Engineering Team (JET) provides excellent support for outage
- Build on the success of the Mod Team
- Steam Generator Inspection



A T e x a s U t i l i t i e s C o m p a n y™

**Comanche Peak
Steam Electric Station**

**Robert Bird
Plant Support Manager**

Industrial Safety

- 2RF03 Goals
 - ≤ 2 TU OSHA recordable injuries
 - ≤ 2 Contractor OSHA recordable injuries
 - 0 TU & Contractor Lost time injuries

- 2RF03 Actual
 - 1 TU OSHA recordable injuries
 - 5 Contractor OSHA recordable injuries
 - 0 TU & Contractor Lost time injuries
 - 1 Contractor fatality (electrocution)

Fuel Handling Equipment

Problems

- Hold down latch on Fuel Building Upender delayed operation
- Take up reel brush broke halting Refueling Machine
- Fuel Building Bridge Crane guide bearings failed

Radiation Dose Control

- Challenges
 - Nuclear Instrumentation well cover leaks
 - Refueling Cavity water dose rates
 - Containment dose rates slightly elevated
 - Steam Generator secondary side work scope expanded
 - Steam Generator primary side work scope expanded
- Improvements
 - Nozzle Dam installation and removal
 - Containment toolroom relocation
 - Temporary Shielding
 - New cameras for refueling cavity monitoring
 - Radiation Worker practices

Outage Program Enhancements

- Industry Lessons Learned
- Outage Control Center relocation
- Control Room Work Reduction
- SRO Work Window Managers
- Team Training
- Scope Control
- Pre-Outage Plan Milestone Adherence
- Schedule Adherence
- Discipline Team Schedule Reviews
- Outage Optimization Workshop




**Comanche Peak
Steam Electric Station**

**Douglas Davis
Nuclear Overview Manager**


Comparison to Prior Outages

Significant Personnel Errors




Total Personnel Error Rate

Based on One Year Average



Significant Personnel Errors

Based on a One Year Average



Planned Actions

- **Formal Root Cause Analysis of each event**
- **Collective review of all significant issues**
- **Self-critique of the major tasks**
- **Summary Self-critique of the overall outage control**

Leadership in Industry Initiatives

- EPRI Leading Human Performance Indicator
- EPRI Database Analysis
- INPO Human Performance Fundamentals Course
- INPO Excellence in Human Performance document