EA 97-413

Mr. L. W. Pearce Site Vice President Quad Cities Station Commonwealth Edison Company 22710 206th Avenue North Cordova, IL 61242

SUBJECT: NRC PREDECISIONAL ENFORCEMENT CONFERENCE SUMMARY

Dear Mr. Pearce:

This refers to the Predecisic nal Enforcement Conference conducted by Mr. A. B. Beach, Regional Administrator, and other members of the Region III and Headquarters staff on November 5, 1997. The subject of this conference was the apparent violations at Quad Cities Station identified in the NRC's letter to you dated September 17, 1997, involving 10 CFR 50.9, "Completeness and Accuracy of Information."

During the conference, your staff acknowledged the violations and presented information addressing the background, conclusions, significance, and lessons learned for issues involving the operability determination, secondary containment, and coupon sample test. Also, actions taken by the site to prevent recurrence were presented. Copies of the NRC's and licensee's handouts, and the attendance list are enclosed with this summary.

You will be notified by separate correspondence of our decision regarding the enforcement action based on the information presented and discussed at the Predecisional Enforcement Conference. No response is required until you are notified of the proposed Enforcement Action.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Sincerely,

/s/ J. Jacobson for

John A. Grobe, Director Divis' n of Reactor Safety

Docket Nos. 50-254; 50-265 License Nos. DPR-29; DPR-30

Enclosures: As stated

300044

See Attached Distribution

DOCUMENT	NAME:	G:\DRS\QUA12157.DRS	

To receive a copy of this document, indicate in the box "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	RIII/DRS	N	RIII/DRP	RIII/EICS	RIII/DRS
NAME	JGavula:so		MRing	HClayton Sc	JGrobe
DATE	12/16/97		12/16/97	12/18/97	12/18/97

12300109 971218 R ADOCK 05000254 FICIAL RECORD COPY

L. W. Pearce

cc w/encls:

- O. Kingsley, Nuclear Generation Group President & Chief Nuclear Officer
- M. Wallace, Senior Vice President, Corporate Services

E. Kraft, Vice President, BWR Operations Liaison Officer, NOC-BOD

D. A. Sager, Vice President,

Generation Support

D. Farrar, Nuclear Regulatory Services Manager

I. Johnson, Licensing Operations Manager Document Control Desk - Licensing

Quad Cities Station Manager

C. C. Paterson, Regulatory Affairs Manager Richard Hubbard

Cicitaro Hobbard

Nathan Schloss, Economist, Office of the Attorney General State Liaison Officer Chairman, Illinois Commerce Commission W. D. Leech, Mana or of Nuclear, MidAmerican Energy Company

Distribution

Docket File w/encls PUBLIC IE-01 w/encls LPM, NRR w/encls DRP w/encls DRS w/encls J Lieberman, OE RIII PRR w'encis SRI, Quad Cities w/encis J. L. Caldwell, RIII w/encis A. B. Beach, RIII w/encis CAA1 w/encis J. Goldberg, OGC RIII Enf. Coordinator w/encls TSS w/encls R. A. Capra, NRR w/encls DOCDESK w/encls R. Zimmerman, NRR

2

Attendance Sheet

DATE: 11/5/97

4

4

REF. NO. EA 97-413

LICENSEE: QUAD CITIES

NAME A. B. Beach R. A. Capra J. M. Jacobson M. Dapas R. M. Pulsifer R. Landsman J. A. Gavula C. G. Miller T. Reis J. Heller B. Berson H. Walker	<u>FITLE</u> Regional Administrator Director, PDIII-2 Acting Deputy Director, DRS Acting Deputy Director, DRP Project Manager Project Engineer Chief, Engineering Spec Branch 1 Senior Resident Inspector Office of Enforcement Enforcement Coordinator Regional Counsel Senior Specialist	COMPANY NRC NRC NRC NRC NRC NRC NRC NRC NRC NRC
 E. S. Kraft, Jr. L. W. Pearce D. B. Cock S. Eldridge R. Scoville B. Rybak R. Freeman R. Gavankar J. Purkis D. Stenger B. Helfrich D. Farrar B. Fairbank B. Leech 	BWR - Vice President Site Vice President, Quad Cities Plant Manager, Quad Cities Engineering Assurance Supervisor Staff Engineer, Quad Cities Senior Licensing Administrator Dreden Chief Engineer (Mech/Structural) System Engineer Supervisor Attorney (Winston & Strawn) Senior Counsel, Nuclear Licensing Acting Site Engineer Manager Manager, Nuclear	ComEd ComEd ComEd ComEd ComEd ComEd ComEd ComEd ComEd ComEd ComEd ComEd ComEd ComEd Mid American Energy

ATTACHMENT

.

NRC HANDOUT

· your a

The apparent violation discussed at the predecisional enforcement conference is subject to further review and is subject to change prior to any resulting enforcement action

A. 10 CFR 50.9 (a) requires, in part, that information provided to the Commission by a licensee shall be complete and accurate in all material respects.

Contrary to the above, the August 25, 1996, Operability Determination Checklist, which was attached to the PORC minutes stated, "The beams and connections checked had functionality interaction coefficients (FICs) less than 1.0," was inaccurate. Specifically, supporting calculations showed FICs to be in excess of 1.0. This information was material because the correct information would likely have resulted in substantial further inquiry by the NRC.

B. 10 CFR 50.9 (a) requires, in part, that information provided to the Commission by a licensee shall be complete and accurate in all material respects.

Contrary to the above, during Quad Cities site visits on May 14 and 15, 1996, the statements made by Commonwealth Edison personnel to NRC officials, that the metal siding panels blown off the Reactor Building during high winds on May 10, 1996, had no effect on structural integrity, was inaccurate and misleading. Specifically, the panels were required for structural integrity during design basis wind load or a line break in secondary containment. This information was material because the correct information would likely have resulted in substantial further inquiry by the NRC.

The apparent violation discussed at the predecisional enforcement conference is subject to further review and is subject to change prior to any resulting enforcement action

ATTACHMENT

LICENSEE HANDOUT



Quad Cities Station Apparent Violations of 10 CFR 50.9

November 5, 1997



Opening Remarks

E. S. Kraft, Jr.

3



Agenda

- Operability Determination
- Secondary Containment Siding
- Coupon Sample Tests
- Actions Taken



Operability Determination



Öperability Determination Issue

- Operability Determination Checklist, Attachment B of PIF 95-2256, stated:
 - "The beams and connections checked had functionality interaction coefficients less than 1.0."



^{station} Operability Determination Factual Background

- Corner Room Steel Issue Identified In August 1995 -- PIF 95-2256
- Management Took Aggressive Action
 - Initiated 72-hour Operability Evaluation
 - Preparations Made for Temporary Support of RHR Heat Exchangers



Öperability Determination Factual Background

- Operability Evaluation
 - Primarily Qualitative, Based on Previous Dresden
 Operational Evaluation and Engineering Judgment
 - Preliminary Evaluations Performed for Quad Cities
 - > Based on these, Operational Evaluation stated that Functionality Interaction Coefficients for Representative Beams and Connections Were < 1.0</p>



Operability Determination Factual Background

- PORC Did Not Accept as Final Determination at 8/24/95 Meeting
 - Allowed 24 hours for Further Evaluation
 - Wanted to Bound Problem Knew More Calculations Needed
- Further Engineering Evaluation
 - Corporate Engineering Support Provided
 - Additional Sample Evaluations Purformed on Beams (ComEd) and Connections (S&L) on 8/25



Öperability Determination Factual Background

- During 8/25 Meeting, PORC Accepted and Directed:
 - Engineering to Continue Performing Formal Calculations
 - Engineering to Initiate Design for Modifications to Restore Steel to Design Basis Limits



Öperability Determination Factual Background

- Final Operability Calculations Completed 9/15/95
 - Representative Beams Showed Acceptable
 Operability Functionality Interaction
 Coefficients
 - In One Case (Beam B4) Engineering Judgment Used to Conclude Acceptable Interaction Coefficients
- Design Effort Continued



Öperability Determination Conclusions

- Operability Determination and Conclusion Were Valid:
 - Understand Source of Confusion

> Use of Term "Calculation"

>Lack of Explanation of Use of Engineering Judgment in the Operability Evaluation



Operability Determination Conclusions (Cont')

- While the Terms could Cause Confusion, there was No Intent to Mislead
 - Record of Second Set of Sample Calculations
 Performed
 - PORC Understood Operability Determination
 Evaluation was not Formal Calculation
 - Final Calculations Documented Engineering Judgment



Öperability Determination Significance

- No Safety Consequences
 - Did Not Affect Station's Actions
 - PORC Review Not Affected
 - Final Calculations Confirmed Operability Conclusion



^{station} Depending Determination Lessons Learned

- ComEd Understands Potential for Confusion
 - Use of Term "Calculation"
 - Need to Explain Bases for Judgments



Secondary Containment Siding



Secondary Containment Issue

- Verbal Statements to NRC Regarding Function of Exterior Siding Panels on Secondary Containment
- Reflected Station's Understanding at Time Based on Inadequate Engineering Evaluation



- Friday, May 10, 1996
 - High Winds Hit Station
 - > Damaged Exterior Siding Panels
 - > Other Damage to Site Facilities
 - Secondary Containment Declared Inoperable
 - Unit 2 Promptly Shut Down
 - Unit 1 Already Shutdown, in Refueling



- Immediate Concerns Addressed by Engineering and Station Management
 - Personnel and Plant Safety
 - Stabilization of Secondary Containment Envelope
 - System Restoration



• May 12, 1996

 Operations Verified Standby Gas Treatment System Maintaining Negative 0.25 Inches Water Pressure in Secondary Containment

> Technical Specification Requirement

 Secondary Containment Not Declared Operable



- Engineering Reviewing Function of Exterior Siding -- Mistakenly Believed Siding Not Required for Integrity
 - Vendor Information Was Not Questioned
 - Inadequate Review of Design Bases



- May 10-15, Efforts t .estore Plant & Site
 - Secondary Containment Blowout Panel Repair
 - Secondary Containment Siding Stabilization
 - SBO Dieseis Gut of Service due to Cable Damage
 - Liquid Nitrogen Storage System Damage
 - Meteorology Tower Damage
 - Waste Oil Building Destroyed
 - Mixed Waste Building Damage
 - Corner Room Steel & Other Issue Resolution
 - Unit 1 Outage In Progress



- May 15, 1996
 - Major Engineering Efforts Still Underway
 - Engineering Discussions with NRC
 - >Indicated Siding Not Needed for Secondary Containment
 - >Based on Belief of Vendor Input, Compliance with Technical Specification D/P Requirements, and Characteristics of Siding



- May 15, 1996 (Cont')
 - NRC Senior Management Site Visit
 - > Primary Focus on SBO Cables
 - > ComEd Provided Understanding that Secondary Containment Operable without Siding and that ComEd Personnel had Verified with Vendor
 - As of May 15, 1-inch Line Break Scenario Not Identified



- May 18-24, 1996
 - Management Decision to Keep Both Units
 Shutdown to Resolve Other Issues
- May 19, Secondary Containment Declared Operable and FSAR Change Started
- May 22, NRC Questioned Basis
- May 29, Secondary Containment Declared Inoperable



Secondary Containment Conclusions

- Statements Inaccurate Based on Information Later Developed, But Reflected Station's Understanding After Significant Event
 - Incorrect Initial Assessment Due to Lack of Questioning Attitude
 - Secondary Containment Met Technical Specification
 Surveillance Requirement
 - Characteristics of Siding Suggested Only Needed for Weather Protection



Secondary Containment Conclusions (Cont')

Not Intentional

 Real Time Oral Communication to NRC of What ComEd Believed Subsequent to Crisis



Secondary Containment Significance

- No Safety Consequences
 - Until Siding Repaired, Both Units Remained in Cold Shutdown
 - Seven Inch Internal Pressure from One Inch Instrument Line Break Is Not Possible During Cold Shutdown
 - Other Repairs Prevented Startup



Secondary Containment Lessons Learned

- ComEd Understands Potential Significance of Incorrect Information
- To Avoid Inadvertent Errors in Verbal Communications, Need Greater Effort to Clearly Convey Bases for Conclusions



Coupon Sample Tests



Coupon Sample Tests Issue

 Failure to Inform NRC of Coupon Sample Test Results on Corner Room Steel at April 11, 1996 Technical Meeting



- NRC Reviewing Dresden Operability Evaluation for Corner Foom Steel
- March 28, 1996 Phone Call with NRC Regarding Operability of Quad Cities Steel
 - NRC Requested Information on Several Issues, Including 10 % Overstress Factor
- April 1, 1996 Quad Cities Letter
 - Responded to Staff Questions -- Provided Analytical Basis and Stated Commitment to Repair Steel



- March 29, 1996 -- Station Management
 Decided to Obtain Test Samples of Existing
 Structural Steel
 - Only Existing Samples were from Dresden
 - Small Group of Samples Taken at Quad Cities
 - Purpose of Testing was to Confirm Same Batch of Material Type (A-36) as Dresden, Not to Justify 10% Overstress



- April 1 and 2, 1996 Test Results Received
 Confirmed A-36 Steel
- Test Results Not Considered Material
 - Not Statistically Valid Sample
 - Results In Line with Expentations -- Not
 Considered to Contradict April 1 Letter
 - Other Conservatisms Remained Valid to Justify 10% Overstress




- April 11, 1996 Technical Meeting
 - Many Technical Issues Discussed, Including
 Operability Calculations, Basis for Calculations



Coupon Sample Tests Lessons Learned

 Greater Sensitivity to the Need to Provide Bases for Conclusions to NRC





Actions Taken

- Vendor Information -- Documentation and Verification
- Third-party Review of 10 CFR 50.59 Evaluations
- Establishment of Engineering Assurance Group
- Formal Review of Written Correspondence with NRC



Actions Taken (Cont')

- Training Completed
 - Engineering Secondary Containment Enforcement Issues
 - Station Supervisors Briefed on Need for "Complete and Accurate" Information
 - Regulatory Affairs Regulatory Interface Training



Future Actions

• Training on 10 CFR 50.9 for selected personnel who interact with the NRC.



Concluding Remarks

E. S. Kraft, Jr.

1