IRC FORM 4-95)	5) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)							AISSION	DN APPROVED BY OME NO. 3150-0104 EXPIRES 04/30/98 ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATO INFORMATION COLLECTION REQUEST: 50.0 HHS. REPORTED LESSO LEARNED ARE INCORPORATED INTO THE LICENSING PROCESS AND F BACK TO INDUSTRY. FORWARD COMMENTS REGARDING BURD ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH 6 F33, U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, J 20555-0001, AND TO THE PAPERWORK REDUCTION PHOLICET (3150-01D DFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20%C3.									
FACILITY NAME (1) Millstone Nuclear Power Station Unit 3											DOCKET NUMB	ER (2)	PAGE (3) 1 of 4					
											000004	20						
TITLE (4)	'A" En	nergeno	by Di	esel G	enerat	or In	operable	Due To V	/entilat	tion Ali	gnmer	nt Prohibila	ng Tornado	o Rec	overy			
EVENT DATE (5) LEB NUMBER (6) REPORT DATE (7)								OTHER FACILITIES INVOLVED (8)										
MONTH	DAY	YEAR	YEA	R SE		AL	REVISION	MONTH	DAY	YEAR	FACILIT	Y NAME		DOCKET NUMBER				
11	13	97	97	7	057		00	12	18	97	FACILIT	Y NAME		DOCKET NUMBER				
OPERA	TING	5	THIS	S REPOR	T IS SU	BMIT	TED PURSU	ANT TO TH	HE REQU	IREMEN	TSOF	10 CFR 5: (C	heck one or i	more)	(11)			
MODE	(9)		T	20.220	11.)			20.2203	a)(2)(v)		D	50.73(a)()	2)(i)	5	0.73(a)(2)(v	viii)		
POWER		000	20.2203(a)(1)				20.2203	(a)(3)(i)			50.73(a)(2)(ii)	50.73(a)(2)(x)					
LEVEL	LEVEL (10)		-	20.220	3(a)(2)(i)		20.2203	(a)(3)(ii)		50.73(a)		2)(iii) 7		3.71			
			-	20.220	3(a)(2)(i	ii)		20.2203	(a)(4)			50.73(a)(2)(iv)	0	THER			
		20.2203(a)(2)(iii)				50.36(c)(1)				50.73(a)(2)(v)	Specif	y in Abstract	ct below				
			20.2203(a)(2)(iv)				60.36(c)(2)				50.73(a)(2)(vii)	or in NHC Form 500A					
			ik make				LICENSEE	CONTACT	FOR TH	HIS LER	12)							
NAME	C	avid A	. Sm	ith, M	P3 Nu	clea	r Licensing	g Manage	ər		T	ELEPHONE NUM	3ER (Include Are (860)43	a Code) 7-534	40			
		COMP	LETE	ONE	LINE F	OR	EACH CO	NPONEN	IT FAIL	URE D	ESCR	BED IN TH	IIS REPOR	T (13)			
CAUSE	SYS	TEM CO	MPON	ENT MA	NUFACTI	JRER	REPORTABL TO NPRDS	E Constant	CAUS	SE S'	STEM	COMPONENT	MANUFACTI	JAER	TO NPF	ABLE		
		SUP	PLEM	ENTAL	REPORT	EXP	ECTED (14)				EXPE	CTED	MONTH		DAY	YEA		
YES		Loto E V DI	CTE	CUDA	ISSION	DATE	3)		SUBMI	SSION (15)						

On November 13, 1997, with the unit in Mode 5, it was identified that the "A" Emergency Diesel Generator (EDG) may have been inoperable from October 11, 1997. On October 11, 1997, the air intake damper for the Emergency Vertualation System serving the "A" EDG cubicle failed open. The exhaust dampers had been failed in the full open position as part of temporary modifications to provide cooling to support EDG operation in the event of an emergency because replacement parts could not be readily obtained. A review on November 13, 1997, of the associated safety and engineering evaluations, identified that credit had been taken for placing the EDG Emergency Ventilation System in full recirculation in order to be able to re-open the exhaust tornado dampers. This condition was determined reportable on November 18, 1997.

The cause of this event was an inadequate development and review of the safety and technical evaluations associated with a temporary modification to fail open the 'A' EDG Cubicle ventilation dampers. Actions to alert personnel that a failure of the air intake damper could result in invalidating the tornado recovery actions specified within AOP 3569 'Severe Weather Conditions' were not explicitly identified and compensatory actions were not put in place.

The ability of the EDG to provide emergency power in order to mitigate the consequences of an accident was not challenged during this time period. There were no safety consequences as result of this condition. However, the failure to recognize and prevent the circumstances leading to this degraded condition is safety significant. The actuator for the "A" Emergency Ventilation System air intake damper has been replaced with a functional actuator.

712310359 9712

PDR

ADOCK 05000423

PDR

NRC FORM 366A (4-95) LICENSE TE	E EVENT REPORT (LER)	J.S.	NUCLE	AR RE	GULATORY	COMMISSION		
FACILITY NAME (1)	DOCKET NUMBER (2)				LER NUMBER (6)				
Millstone Nuclear Power Station Unit 3	05000423	YEAR	SEQUENTIAL NUMBER			REVISION NUMBER	2 of 4		
Anistone Houldar Power Station Onit's	00000420	97		057		00	2014		

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

I. Description of Event

On November 13, 1997, with the unit in Mode 5, it was identified that the "A" Emergency Diesel Generator (EDG) may have been inoperable from October 11, 1997. On October 11, 1997, the air intake damper for the Emergency Ventilation System serving the "A" EDG cubicle failed open. The exhaust dampers had been failed in the full open position as part of temporary modifications to provide the necessary cooling to support EDG operation in the event of an emergency because replacement parts (replacement actuators / Hydromotors) could not be obtained from the vendor (or rebuilt) in a ready fashion. A review on November 13, 1997, of the safety and engineering evaluations associated with these temporary modifications, identified that credit had been taken for placing the EDG Emergency Ventilation System in full recirculation in order to be able to re-open the exhaust tornado dampers. These tornado recovery steps were included in Abnormal Operating Procedure (AOP) 3569 "Severe Weather Conditions." This condition was determined reportable on November 18, 1997.

Technical Specification (TS) 3.8.1.2, "Electrical Power Systems, A. C. Sources - Shutdown," requires that two "... A. C. electrical power sources shall be OPERABLE ... One [of which is a] diesel generator..." The definition of OPERABLE states, "A system, subsystem, train, component or device shall be OPERABLE or have OPERABILITY when it is capable of performing its specified function(s) and when all necessary attendant ... auxiliary equipment that are required ... to perform its function(s) are also capable of performing their related support function(s)." The "A" EDG was inoperable because its Emergency Ventilation System intake ventilation damper failed in the full open position. This failure, coupled with the temporary modifications which repositioned the exhaust dampers to the fully open position, would have prevented the reopening of the exhaust tornado dampers had they been closed due to a tornado. Additionally, due to the pressure buildup within the EDG cubicle with the Emergency Ventilation System running, access to the fan breakers located within the cubicle would have been restricted since it is highly unlikely the doors could be opened. Consequently, this may have inhibited the capability to provide adequate cooling to the "A" EDG, thereby resulting in the EDG not being able to perform its safety function.

On November 13, 1997, the "A" EDG was declared inoperable until a fully functional actuator could be installed at the intake damper assembly. A temporary modification was prepared to remove a functional actuator from one of the two exhaust path dampers and install it at the intake damper assembly (the exhaust dampers were gagged open pending completion of installation of other rebuilt actuators).

This event is reportable pursuant to 10 CFR 50.73(a)(2)(ii)(B), as a condition outside the units design basis. This condition was identified and documented in accordance with the Millstone Corrective Action Program.

II. Cause of Event

The cause of this event was an inadequate development and review of the safety and technical evaluations associated with installation of Temporary Modification 3-97-049 "Fail Open 'A' EDG Cubicle Ventilation Dampers 3HVP*MOD20A/C." The safety evaluation for the temporary modification recognized that there existed a reliance on being able to re-open the exhaust tornado dampers by putting the system into the recirculation mode. However, actions to alert personnel that a failure of the air intake damper could result in invalidating the tornado recovery actions specified within AOP 3569 'Severe Weather Conditions' were not explicitly identified and compensatory actions were not put in place.

A contributing factor is that the tornado recovery actions referenced in the AOP have never been used by plant personnel during normal work activities. The effect that temporary modification had on these procedure steps was therefore not given adequate review when the modification was implemented.

NRC FORM 366A (4-95)

NRC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)		PAGE (3)				
Millstone Nuclear Power Station Linit 3	05000423	YEAR	SEQUENTIAL NUMBER			REVISION NUMBER	3 of 4
Milistone Nuclear Power Station Onit 5	00000420	97		057		00	0014

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

III. Analysis of Event

Because the unit has not experienced a Loss of Offsite Power (or other event requiring operation of the diese!) coincident with a tornado during the time period when the dampers were inoperable, the need to access the EDG building was not necessary and the ability of the equipment to provide emergency power in order to mitigate the consequences of an accident was not challenged. Consequently, there were no safety consequences as result of this condition. However, the failure to recognize and prevent the circumstances leading to this degraded condition is safety significant.

IV. Corrective Action

The following corrective action has been completed:

 The actuator for the "A" Emergency Ventilation System air intake damper has been replaced with a functional actuator.

The following corrective actions will be completed:

- Safety evaluation procedures and training are being revised to improve the quality and detail within the Safety Evaluations. This will be completed by March 1, 1998.
- 2. A briefing will be provided to Technical Support personnel on this event by January 31, 1998.

V. Additional Information

None

Similar Events

Listed below are other historical LERs which reported a potential loss of safety function and/or conditions outside of the design basis of the unit. A majority of these events were identified as a result of the Configuration Management Review Process.

LER 96-026-02Non-Conservative Primary Grade Water Flow Rates Used in Boron Dilution Safety AnalysisLER 97-031-00RHR Valve Low Pressure Open Permissive Bistable Setting Set Non-ConservativelyLER 97-041-00Voluntary Report: Operation of Service Water System With Only One Pump OperableLER 97-046-00Containment Recirculation Spray System Cubicle Flood PotentialLER 97-048-00Oversized PGS Impeller Could Potentially Result in Non-Conservative Boron Dilution Event

NRC FORM 3R6A			U.S.	NUCLE	ARR	EGULATORY	COMMISSIO
(4-95)	E EVENT DEDORT	ED					
LIVENSE	T CONTINUE TION	LEN/					
TE	XI CONTINUATION						
FACILITY NAME (1)	05000423		PAGE (3)				
Millstone Nuclear Power Station Unit 3		YEAR SEQUENTIAL			REVISION NUMBER	4 of 4	
				057		00	
TEXT (If more space is required, use additional copies of NHC Forn	n 366A) (17)			decree scener	Box, our		Bend Ballin and Ballin Linker, Landson
Manufacturer Data							
EIIS System Code							
Emergency Onsite Power Supply Building	VJ						
Emergency Onsite Power Supply Building	NB						
Emergency Onsite Power Supply System	EK						
EIIS Component Code							
Damper	DMP						
Damper, Control	CDMP						